# Table 5C-36 DAILY WATER ANALYSIS REPORT REGARDING TO HOUSE SERVICE CLOSED CYCLE (Malaya Plant)

	Unit		M	alaya	a 1				М	alay	a 2		
	Date	8/8	T	8/22	1	9/4	9/13	8/8	8/15	8/22	8/29	9/4	T
P-Alkalintiy	ppm CaCO3	2	2	2	2	2	2	2	2	2	3	2	
M.OAlkalinity	ppm CaCO3	7	7	7	7	7	7	- × 45 - × 45 - × 7.	7	9	7	7	
Chloride	ppm NaCl	0	0	0	0	0	0	0	0	0	0	0	ſ
Sulfate	ppm Na2SO4												Í
Total Hardness	ppm CaCO3												
Ca Hardness	ppm CaCO3												ſ
Mg Hardness	ppm CaCO3												
Silica	ppm	0.02	0.02	0.02	0.02	0,02	0.02						
Water Temp.	°C												T
Sodium Chromite	ppm NaCrO4												ĺ
pCa													
p-Alkalinity													Ī
C at Tu													I
pHs													
Acutal PH		9.2	9.2	9.2	9.2	9.2	9.2	9.2	9.2	9.2	9.2	9.2	
PH-pHs (SI)													
Conductivity	uS/cm											1 : ( <b>1</b> : ( 1	
Turbidity	ppm												
Total Solids	ppm												ſ

Table 5C-37 ANALYSIS DATA OF HOUSE SERVICE COOLING SYSTEM REQUESTED BY JICA TEAM ( GSTP ) 

September 9, 1982

ITEM	Unit	Gardner 1	Snyder 1	Snyder 2
Conductivity	at 25 <sup>0</sup> C	4.5	10	10
рн		9.0	9.6	9.5
Turbidity	ppm	Z	Z	Z
Hydrazine	ppb	8	5	5
Silica	ppm	0.018	0,012	0,018
Dissolved Oxygen	ppb	very high 60	60	60

#### b. Condenser Cooling Water

Gardner/Snyder and Malaya Thermal Plants utilize Laguna lake water as a cooling medium of the condenser while Tegen Thermal Plant make use of the Pasig River. It will be observed in the attached 1980 data, the water quality varies from rainy to dry season. During rainy season, the salt concentration and turbidity are high. The turbidity is about 40 ppm.

The attached sheet showed the material, protection method and actual plugged ratio of the main condensers of Gardner/Snyder and Malaya Thermal Plants.

Gardner-1 was initially operated with admiralty tube in the main condenser. All tubes were replaced with cupro-nickel material in 1979 when the main condenser reached 10% ratio of the tube plugged.

Gardner-2, Snyder-1 and -2, Malaya-1 and -2, have current cathodic protection in its main condenser. Only the cathodic protection of Malaya-1 and -2 are working. The ball cleaning device of Malaya-2 was under water.

The current cathodic protection is operated based on the conductivity of the cooling water. The chemical group was the one maintaining it before the management of its data was transferred to the maintenance group.

	(January - December 1980)	380)					
Apr	May	- nuc	Jul	lg Sept.	0 ct	Nov.	Dec.
0	0	0	0	0 0	0	0	0
85 0	87	84	71 65	5 62	75	42	52
0 260	263	614   6			- 29 <u>5</u>	210	220
3 50	51	50	2		49	48	53
0 98	211	214 2			195	85	80
4 30	32	50	60		62	39	33
68	80	164			133	46	57
0.38	0.4			944	0 0.35	0.35	0,35
5 7.5	7.5			. 7.5	7.6	7.5	۲.۲
	mar Apr 0 0 0 80 85 270 260 53 50 34 30 34 30 66 68 66 68 7.5 7.5	Apr         May           0         0         0           1         85         87           260         263         1           50         51         1           98         112         1           98         112         1           98         0.32         32           90.38         0.4         0.4           7.5         7.5         7.5	Apr         May         Jun           0         0         0         0           1         85         87         84           260         263         614         6           50         51         50         50           98         112         214         6           90         32         50         6         6           61         50         112         214         6           98         112         214         6         6           90         32         50         6         6           90         32         50         6         6           91         30         32         50         6           91         30         32         50         6           91         0.33         0.4         0.39         0           1         7.5         7.5         7.5         7.5	Apr         may         Jun         Jun <td>Apr         May         Jun         Jun         Aug           0         0         0         0         0         0           85         87         84         71         65           260         263         614         625         587           50         51         50         51         45           98         112         214         210         55           30         32         50         61         60         55           30         32         50         61         214         200           98         112         214         214         200         55           30         32         50         60         55         55           68         80         164         157         145         55           0.38         0.34         0.39         0.44         0.30         55</td> <td>Apr         May         Jun         Jun         Jun         Sept.           0         0         0         0         0         0         0           1         85         87         84         71         65         62           260         263         614         625         587         578           50         51         50         51         45         .45           50         51         50         51         45         .45           98         112         214         200         198         .45           98         112         214         200         198         .45           98         112         214         200         198         .45           90         30         32         50         56         .45           91         30         32         50         60         .45         .45           7         30         32         50         60         .45         .45           63         0.38         0.44         0.30         0.30         0.30         .56           7         7.5         7.5         7.5</td> <td>Apr         May         Jun         Jun</td>	Apr         May         Jun         Jun         Aug           0         0         0         0         0         0           85         87         84         71         65           260         263         614         625         587           50         51         50         51         45           98         112         214         210         55           30         32         50         61         60         55           30         32         50         61         214         200           98         112         214         214         200         55           30         32         50         60         55         55           68         80         164         157         145         55           0.38         0.34         0.39         0.44         0.30         55	Apr         May         Jun         Jun         Jun         Sept.           0         0         0         0         0         0         0           1         85         87         84         71         65         62           260         263         614         625         587         578           50         51         50         51         45         .45           50         51         50         51         45         .45           98         112         214         200         198         .45           98         112         214         200         198         .45           98         112         214         200         198         .45           90         30         32         50         56         .45           91         30         32         50         60         .45         .45           7         30         32         50         60         .45         .45           63         0.38         0.44         0.30         0.30         0.30         .56           7         7.5         7.5         7.5	Apr         May         Jun         Jun

			Table 50-39	CONDENSER COOLING WATER TREATMENT	LING WATER TREA	<b>TMENT</b>		
			GARDNER-1	GARDNER-2	SNYDER-1	SNYDER-2	MALAYA-1	MALAYA-2
Material of cooling tube	oo1ing	tube	Cupro-Nickel	Admiralty Metal	Admiralty Metal	Al-Brass	Al-Brass 90-10 Cupro-Nickel (Air Cooling Zone)	SVS - 316
Protect Method	thod		Sacrificial Anode	Impressed Impressed Current Current Cathodic Cathodic Protection (Not working)	Impressed Current Cathodic Protection (Not working)	Impressed Current Cathodic Protection (Not working)	Impressed Current Cathodic Protection	Impressed Current Catho dic Protection Ball.cleaning (Not working)
	Date	1	August 1982	August 1982	July 1982	June 1982	August 1982	Sept. 1982
		No. of Plug:					517	3177
	≺						3.01	31.52
Plugged Tube		No of Plug					231	1495
Kat 10							3.05	14.8
		No.of Plug	O	266	255	58	1048	4672
	Total	26	0	1.09	1.05	0.17	3.01	23.13
		No.of Total	14748	24400	24400	34800	34.800	20160

Total Tube

5 - 566

Malaya-2 ball cleaning device was operated for about 6 months since the units initial operation. During the process of its operation, the ratio of ball recovery was low and there was no spare ball available.

Malaya-2 main condenser has 316 SS tube materials. At present the number of tubes plugged was about 23%. The unit experienced frequent condenser leakage. It might be due to the presence of scale in between the tube and high concentration of chloride which causes service corrosion of the tube.

Malaya-2 main condenser will be retube using Al-Brass materials in the next overhauling. In 1979 Gardner-1 was retubed changing the materials from Al-Brass to cupronickel. JICA team is wondering why Malaya 2 main condenser tube is to be replaced with Al-Brass materials instead of the cupro-nickel type which is resistant to Laguna Lake water corrosion.

#### Leak Test with Half Condenser Operation

On August 25, 1982, during start-up of Malaya-2 there was an indication of condenser leakage so that on September 3, 1982, half condenser operation was performed and subsequently leak test was done on one side of the condenser. NAPOCOR utilized the soap sud method in finding the leaky tubes. JICA team recommends the use of the vinyl sheet method in finding the leaky tubes. In the case of Malaya-2 main condenser vinyl shut method is not applicable because of the following.

- 1) There were plenty of tube plugged on both side of the condenser. The vinyl sheet will not stick since the plug protrude for about 1 to 1.5 cm.
- 2) The vinyl sheet available at the plant is too thick.
- 3) No good connection between two compartment of the condenser.
- 4) The person who will erform the said method will lose interest due to hot condition inside the condenser. During the soap sud test of Malaya-2 main condenser,
  200 tubes were found to be leaking at side B main condenser side A was not checked. All leaky tubes were plugged.

The preparation for determining the leaky tubes was observed to consume more time. Like for instance, the preparation of scaffolding to be used for inspection, it took them 12 hours to complete the work.

#### Recommendation

Cooling water management is directly related to Plant efficiency which will result on condenser low vacuum. Improper treatment of cooling water will cause condenser tube corrosion and ultimately will contaminate the feedwater system. The current cathodic protection and the ball cleaning device should be repaired immediately and placed on operation.

In the determination of leaky tubes by soap sud method, the process just cover only one side which is less effective. Like in the case of the heat exchanger, the reliability of the said method is very low.

The vinyl sheet method is very effective and covers wide area of the condenser. In order that the said process could be applied to NAPOCOR's Thermal Plants main condenser, the following should be implemented.

- 1) The plug should protrude to the tube plate for at least 2 to 5 mm.
- 2) Vinyl sheet should have a thickness of below 0.1 mm. The material should be vinyl coated.

All scaffoldings needed for the inspection of the main condenser should always be placed near its side. In this manner, preparation time during condenser leakage determination will be shorter.

The method being used in Japan for the determination of condenser leakage, is based on the conductivity reading often passing thru cation resin. During half condenser operation, the corresponding conductivity is taken and compared it with the result on the other side. The side with the higher reading is the one to be checked.

During inspection of main condenser always use low voltage source of lighting.

# 10) Disposition of Abnormality in Feedwater

#### Unit Start-up a .

During start-up of drum and once-through type boilers, the water quality limits recommended by the boiler maker should always be followed. Below are the water quality limits recommended by boiler manufacturer.

Feedwater Quality Limit During Start-up

#### (G-2, S-1, S-2 and M-1)

	Process	N	2 <sup>H</sup> 4 Fe	Cu SiO	2 micro	S/cm
		a shekara shekara Sana sa shekara	pb ppb	oph oph	(After	Cation)
·				FFF FFF		<u></u>

#### Fire Boiler:

Raise Temp. up

to	370°F,(177°	C) 10-70	200	
Ra	ise Temp.			
40	0°F (204°C)	10-70	100	
50	00°F (260°C)		100	
68	80°F (360°C)		100	80
Turbine	<u>Rolling</u>		100 10	40
On Load			60 5	30

In the start-up of once-through units at Gardner/ Snyder Themal Plant, it was observed that the Plant experience problem in the supply of demineralized water. On September 2, 1982, during start-up of Snyder-1, the water quality items being analyzed were iron (Fe), silica (SiO<sub>2</sub>) and chloride (C1) only. In the analysis of water quality, pH, hydrogine, dissolved oxygen and conductivity (often passing thru cation resin) should be included.

5 - 570

In addition, during the start-up of the above unit, the iron was being analyzed utilizing the millipore filter. As recommended by UTL team, iron should be analyzed utilizing the TPTZ method. The said method will give the true value of iron. Likewise, dissolved oxygen should always be analyzed. As reported by UTL team, they observed that high concentration of dissolved oxygen excess during start-up of once-through units. To minimize presence of dissolved oxygen, an additional dosage of hydrazine is needed.

In the start-up of once-through units, it was observed that the corrosion products from the boiler were all being removed by the condensate polisher. In the presence of high concentration of iron in the system, blowdown could not be done due to lack of demineralized water.

Moreover, during start-up, the condensate polisher was being operated not H-OH type. All impurities were absorbed by the polishers causing its overloading. Recommendation


During start-up of once-through units, it was observed that presence of high concentration of dissolved oxygen excess. JICA team recommends frequent analysis of dissolved oxygen should be done so that right treatment should be implemented. The presence of high concentration of corrosion product in the condensate and feedwater system should be avoided in order to minimize its deposition to the boiler system and turbine blade. If the corrosion products are carried over to the boiler and turbine, during stoppage of the units the deposits will go into the feedwater system during start-up.


In case that the presence of corrosion products could not be avoided in the condensate and feedwater system, JICA team recommends that blowdown should be done so that the condensate polisher will not be overloaded. The condensate polisher should be operated H-OH type.


The dissolved oxygen should be controlled with the addition of the right concentration of hydrazine.


For rapidity of analysis, iron should be analyzed utilizing millipore filter if the iron concentration is more than 500 ppb. If the iron is below 500 ppb, iron analysis should be done using TPTZ method.

In Japan, the start-up of the unit is based on the attached start-up data. To facilitate start-up of oncethrough unit, JICA team recommends installation of blowing pipe at the condensate pump discharge.











5 - 575



# Low Pressure Clean-Up


- 1. Start deaerator vacuum up (LP Htr: Bypass, Blow off) NH40H injection (pH 9.3 - 9.5)
- LP Htr. in service Deaerator inlet turbidity < 3 ppm CBP discharge 0<sub>2</sub> < 100 ppb</li>
   After LP 1.2 Htr. in service, when upper water quality is kept, LP
  - 3.4 Htr. becomes available.
- 3. Recirculation
  - Deaerator tank turbidity < 3 ppm CBP dsicharge 0<sub>2</sub> < 100 ppb
- 4. For next step
  - Deaerator tank outlet turbidity < 1 ppm (Target Fe < 100 ppb)
    - $0_{2} < 10 \text{ ppb}$
    - $(pH 9.3 9.5, N_2H_4 > 200 ppb)$



# PRE BOILER Clean-up

- Water filling → Blow off without HPHtr (Max 255T/H. Design 128T/H)
- 2. A-HPHtr  $\rightarrow$  B-HPHtr
  - → A, B HPHtr ---> recirculation for each steps =>
  - Turbidity in blowdown water < 3 ppm
  - Deaerator 0<sub>2</sub> < 10 ppb
- 3. for next step
  - HPHtr outlet = Fe < 50 ppb, Gu < 20 ppb, SiO<sub>2</sub> < 30 ppb
    - Cation conductivity < luS/cm
  - Deaerator tank outlet 0<sub>2</sub> < 10 ppb pH 9.3 - 9.6 , oil < 1 ppm (at initial clean-up only)
    - N<sub>2</sub>H<sub>4</sub> 200 300 ppb
  - Feedwater flow Max 508 T/H Feedwater temp. > 80°C

# 5 - 576



# Boiler Cold Clean-up

- To boiler at about 10% MCR Feed water flow rate
- 2. Blow off  $\Rightarrow$  recirculation
- Start-up separator turbidity < 3 ppm
- 3. for next step Eco inlet Fe < 50 ppb, Cu < 20 ppb Si0 $_2$  < 30 ppb,
  - cation conductivity < 1 uS/cm
  - Deaerator tank  $0_2 < 10$  ppb
  - Water-wall outlet Fe < 200 ppb (Target Fe < 100)

# Boiler Hot Clean-Up

- I. Boiler firing after pressure increase at 5% MCR\_feedwater flow rate and 246 kg/cm<sup>2</sup> (WW outlet)
- 2. WW outlet temperature 170°C
- 3. Eco inlet Fe < 50 ppb, Cu < 20 ppb . SiO<sub>2</sub> < 30 ppb
  - cation conductivity < 1 uS/cm Deaerator tank outlet 0<sub>2</sub> < 10 ppb
  - WW outlet Fe < 100 ppb (Target < 50 ppb)

# Table 5C-40 EXAMPLE OF WATER QUALITY ANALYSIS DATA DURING UNIT START-UP

(In case of Kyushu Electric Power Co.)

- 1. Outage period 21 days
- 2. System Lay up
  - (1) Deaerator: Water flooding with 50 ppm as  $\mathrm{N_2H_4}$
  - (2) Boiler water wall: Water flooding with 50 ppm as  $\mathrm{N_2H_4}$
  - (3) LP Heater, HP Heater cell side:  $N_2$  seal
  - (4) Condenser: Not treating

3. Start up schedule

April 3 - 0:44	pm -	1:50 pm Condenser Hotwell Flushing
<b>6:4</b> 8	pm -	Condensate water circulation
7:23		Vacuum up
April 4 - 7:30	am –	Low pressure clean up
1:15	pm -	High pressure clean up
6:00		Boiler cold clean up
April 5 - 1:59	am -	Fired boiler
2:30	-	Temperature raise up, Step l
5:49	-	Temperature raise up, Step 2
10:00		Turbine rolling
0:45	pm -	On line
4. Consumption of	Demine	ralized Water 680 m <sup>3</sup>

문제 물법에 가을 빌려 주는 것이다.

(179,000 gals)

T.	able 5C	-40 EXAN	IPLE	OF 1	JATE]	R QUA	LITY	AN	ALYSI	S DATA
Start up Procedure	Date Time	Sample	РН	MS/cm	Si O <sub>2</sub> ppb	N2H4 ppb	Fe ppb	0 <sub>2</sub> ррь	Turb. ppm	REMARKS
Hotwell Flushing	April 3 1:50 pm	CP out				3800			3.2	April 3, 0:44 pm 1:50 pm Condenser Hotwell
Clean up around condenser	April 4 7:00 am	CP out						170	0.3	Flüshing 7:23 pm Vac. up
	7:30	CP out CBP out CP out	8.7 9.0	ia di Metala	9	600 1000	70 19 60	170 170 170	100 A.	April 4 7:30 am Low pressure clean up
ssure Clean-up	11:00	Dea inlet Dea tank CP out Dea inlet	9.1 9.1 9.3 9.3	3.0 3.8 4.5 3.8	8	1380 1100	50 50	200 200 170 170		
Low Pressure	<ul> <li>A state of the state</li> </ul>	Dea tank CP out Dea inlet Dea tank	9.3 9.4 9.4 9.4	3.9 6.2 6.4 6.3	8 6 6	150 900 700	65 25 25	120 90 5 0		1:15 pm High Pressure Clea up
Pressure Clean-up	2:30 5:30	CP out Dea inlet Dea tank <sup>#</sup> Shr out CP out	9.4 9.4 9.4 9,4 9,4	4.5 5.5 5.3	6 6 6	1100	150 50 50 70 80	170 170 90		
High Pressu		Dea inlet Dea tank <sup>#</sup> 8hr out	9.4 9.4 9.4	4.9 5.2	6 6	850	45 50 40	120		
	8:00	CP out Dea inlet Dea tank Eco inlet	9.4	5.0 6.1		1375 925	20		5	6:00 Boiler Cold Cléan 6:00 - 7:00 up Blowing
Cold Clean-up		Waterwall out Starting Separator +Dr.	9.5				490 860			
Boiler	10:00	CP out Dea inlet Eco inlet	1.11.21			1050 900	18124			

Table 5C-40	EXAMPLE C	F WATER	QUALITY	ANALYSIS	DATA

				-	- 580						
				1997) 1997 - 1997 1997 - 1997							
	Table 5C	-40 EXAN	1PLE	OF	WATE	r qu <i>i</i>	<b>ALIT</b> Y	( AN	ALYSI	S DATA	
Start u	Date			MS/a	[si 0 <sub>2</sub>	N <sub>a</sub> H <sub>a</sub>	Fe	02	Turb		
Proceduri	1	Sample	РН	/ a	h ppb	2 4 ppb	ppb	د ppb	ррт	REMARKS	
		Waterwall									
		out Starting					75				
		DV	9.5	8.0			115				
	April 5 0:00am	CP out			8		100	170			
		Dea inlet	9.4	6.4	6	1050		60			
		Eco inlet	9.4	5.9	6	920	36	0			
		Water well out	9.4	6.1	7		43				
	2:00	CP out Dea inlet	95	7.2		570	135 31	170 40		April 5 1:59 am	
		Eco inlet	1.1.1.1.1.1.1	7.2		340	1.1.1.1	0		ired Boiler	
		W.W out					32				
	4:00	CP out					140			2:30	
		Dea inlet	1.4 1.5 1.4	8.3		570				Temperature raise	
		Eco inlet W.W out	9.5	7.4		490	13 16		en de Boald	3:30 - 8:10	
	7:00	CP out					340	140		Turbine warming	
		Dea inlet		1.1	÷	1.	8	50		5:49 Temperature raise	an an an Anna An An Anna An Anna Anna
		Eco inlet W.W out	9.5	8.2		250	16 5	0			
	9:30	CP out			8		150	60			
	1.30	Dea inlet	9.5	6.7		91	1 5 6 6	5			
		Eco inlet	9.5	7.1	8	77	7	Ö			
		W.W out SH out			8		10 3				
		Sn out			0						
	11:30	CP out					700	40		10:00 Turbine start	
		Dea inlet	1.1			67		10		lurone start	
		Eco inlet W.W out	9.5	) /.3		57	8	0		0:45 pm	
	2:30	CP out					1060	- E - E - E - E - E - E - E - E - E - E		on line	
	pm	Dea inlet		9 (N. 1997)	1.22 - 1	75	1.5		1 1 <sup>1</sup> 1 1 1		
		Eco inlet W.W out	9.9	5 7.0		47	21 7			1:00 LP Heater in	
		R.R. UUL								Service	
									1		

	Table 5C-	40 EXAM	PLE	OF W.	ATER	QUA	LITY	ANA	LYSI	S DATA
Start ( Procedu)		Sample	РН	MS/ <sub>CR</sub>	Si O <sub>2</sub> ppb	N <sub>2</sub> H <sub>4</sub> ppb	Fe ppb	-	Tùrb. ppm	REMARKS
	3:30	CP out Dea inlet				24	1100 140	1.0.0		2:10 LP heater in Service
		Eco inlet W.W out LP Hr				15	60 28			4:30 LP Heater Drain in System
		Drain HP Hr Drain			13 15		1100 10			
	4:30 pm	CP out Dea inlet	9.5	8.1		18	120			5:00 HP Heater Drain in system
		Eco inlet W.N out LP Hr.Dr	9.5 9.5	8.1		12	60 850			
	6:00	HP Hr Dr LP Hr Dr	9.5	7.0			17 70	0		
		HP Hr Dr					15			

# b. Condenser in Leakage

JICA team found out on their survey that the cause of deterioration of all units were due to condenser in leakage and improper water treatment. It was observed that condenser in leakage is not properly detected due to the absence of continuous conductivity monitoring instruments. The detection of condenser in leakage is only done analytically.

The method of chloride analysis being used by Malaya and Gardner/Snyder Thermal Plants was observed to be less accurate. Like in the case of Gardner/Snyder Thermal Plant, the detection limit of chloride is about 0.15 ppm while Malaya is about 0.1 ppm. JICA team attributed it to the type of cell being used in the analysis. Both Thermal Plants are using a shorter cell in chloride analysis which is not so accurate.

Comparing the minimum detection limits of chloride to the attached graph, it will be noted that the 0.1 ppm chloride has an equivalent of 1.2 micro S/cm while the 0.15 ppm chloride has an equivalent of 1.8 micro S/cm. The equivalent conductivity of the minimum detection limit of chloride is way beyond the maximum limit value of feedwater conductivity of 0.3 micro S/cm.

Likewise, it was observed that the condensate polisher is being operated as NH<sub>4</sub> type. Since chloride analysis is not so accurate a detection limit is high, the whole feedwater system is already contaminated before the chemical section will realize the presence of chloride. Continuous sodium monitoring instruments were installed at the condensate pump discharge and condensate polisher outlet of Gardner/Snyder once-through units. The said instruments properly monitored any abnormality in the feedwater system. Last August 16, 1982, Snyder-1 experienced condenser in leakage. It was noted that the sodium concentration at the condensate pump discharge keeps on increasing. JICA team monitored its corresponding conductivity often passing thru cation resin. With the increase in sodium concentration, the conductivity also increased. The maximum chloride was about 0.1 ppm, 20 ppb sodium and 2.4 micro S/cm conductivity often passing cation resin. Sawdust was poured in the tunnel and the chloride concentration gradually decreased.

Gardner-1 and Malaya-2 drum type boilers have no sodium monitoring instruments. The conductivity monitoring instruments are not working. In the detection of condenser in leakage, chloride analysis is just being done. The disposition of condenser in leakage of all oncethrough units is taking care of by the condensate polishers while the drum type boilers are being protected by blowing down and by injection of disodium and trisodium phosphate. The condensate polishers should be operated H-OH type in case of condenser in leakage. It was observed that it is not being operated as such. Last August 25, 1982 at Malaya-2, JICA team observed that said unit experienced condenser in leakage. In order to minimize concentration of chloride in the boiler saline, blow down and injection of disodium and trisodium phosphate were done. Continuously blow down was intermittened due to lack of demineralized water. The chloride at the boiler drum reached up to 6 ppm. Half condenser operation could not be performed due to great power demand. Half condenser inspection was done on September 3, 1982 and the leaky tubes were plugged. Recommendation

- 1) Condenser tube leak should be treated at early stage.
- All units should be provided with continuous conductivity monitoring instruments.
- Maintenance of the sodium analyzer should be done once a month to make it always reliable.
- Improvement of chloride analysis in order to increase its detection limit.
- 5) During condenser leakage the following procedure should be implemented so that contamination of the boiler system will be avoided.

In case of once-through boiler, the following steps should be followed:

a) Condensate polisher should be operated H-OH type.

For the drum type boiler with a drum pressure of 170 kg/cm<sup>2</sup>. The following standard treatment are needed.
Boiler water conductivity after passing thru cation resin should be maintained below 5 micro S/cm. Conductivity beyond 5 micro S/cm, blowing down of the boiler saline should be done.

In case that the boiler saline conductivity, after passing cation resin of 5 micro S/cm cannot be controlled, injection of disodium and trisodium phosphate should be done. the molar ratio of 2.5 -2.6 sodium phosphate and 1.0 ppm phosphate residual should be maintained.

b)

# 11) Overhauling

#### a. Inspection

During overhauling of Gardner-2, JICA team inspected the condenser, deaerator, etc. Below is the result of inspection:

#### Condenser (steam side) and Hotwell

Condenser tube surfaces is reddish brown color, of terrix oxide. The upper tubes were damaged due to turbine blade breakage. The hotwell accumulated plenty of sludge deposits.

#### Deaerator Tank and Flash Tank

The wall of the deaerator was coated with black magnitite and the bottom position with little reddish brown coating.

The manhole of the deaerator and flash tank were noted to be opened for quite sometime. Plenty of dust particle accumulated inside the manhole.

# Recommendation

During unit overhauling, inspection of condenser, deaerator, flash tank, etc. should be done in order to determine the effectiveness of chemical management. The record of the past inspection should always be kept and used for comparison purposes. Once the unit is uncovered for overhauling, inspection should be done as early as possible. All deposits and sludge should be taken, weighed and analyzed to be used as reference for the next overhauling, On this manner effectiveness of chemical treatment could easily be determined.

		01010011100
Raw water tank clean well	Volume and distribution of deposites, Growth of duchweed, living things,	Cleaning
Demineralized Water Tank	lyning and point	
Condenser Water Tank		
Demineralizer Plant,	Inside of Resin Tower, etc. (See. 5.3.3 - 3.4	Makeup of Resin, etc.
Condensate Polisher	Demineralizer, Condensate Polisher)	ACS111, EUL.
Condenser (Steam Side)	Corrosion, mechanical destoration of condenser tube, volume and	Cleaning
	distribution of deposite in hotwell.	
Feedwater Water Deaerator heater	Corrosion of tube plate, tube, volume and distribution of sludge in water chamber.	Ditto
Deaerator	Protective film inside deaerator Volume and distribution of mud	Ditto

Table 5C-41 ITEM FOR INSPECTION DURING OVERHAULING

ITEMS FOR INSPECTION

DISPOSITION

Ditto

**EQUIPMENT** 

Boiler Header

Volume and distribution of mud

(Cut the inspection hole)

Corrosion

	Color, volume and distribution of	
Turbine	scale on blade. Erosion of blade with drain.	Ditto
Condenser (cooling water side)	Number of clogging tube with shell or other things. Scale of tube.	
Heat exchanger (cooling water side)	Corrosion of tube plate and tube. Situation of Zinc plate, or cathodic	Ditto

e da înita • Marine da Araba • Marine da Araba

#### b. Boiler and Auxillaries Preservation Treatment

At present, Gardner/Snyder and Malaya Thermal Plants have no actual standard preservation treatment being implemented during unit's shutdown. Wet storage of the boiler often chemical cleaning is done with 500 ppm  $N_2H_4$ being maintained in the system. In the case of Gardner 2 it was wet stored for two weeks with the above concentration of Hydrazine.

Last August 29, 1982 Snyder-1 tripped and was started on September 3, 1982. JICA team advised the chemical section to treat the deaerator and boiler system with 10 ppm  $N_2H_4$  during the shutdown period.

#### Recommendation

During outage of the unit, entry of oxygen in the system could not be avoided without proper treatment. Presence of dissolved oxygen in the system will cause corrosion of the tube metal surfaces. The best method of treatment are with the use of oxygen scavenger and pH control chemicals. The boiler and its auxiliaries could be preserved by floating them with the right concentration of chemicals and pressurizing with  $0.3 - 0.5 \text{ kg/cm}^2$  Nitrogen gas to prevent entry of oxygen.

The other type of treatment process are the steam sealing and dry treatment.

a) Outage period

b) System material, equipment

c) Standard of treatment

In case of Japan, attached is the procedure on the

preservation treatment.

HEATER SHELL SIDE	steam sealing (condenser: under vacuum Low Pressure Side: Vacuum keep steam sealing		steam sealing or nitrogen blanket	Nitrogen blanket or water flooding with N <sub>2</sub> H <sub>4</sub> 50ppm NH <sub>4</sub> 5ppm		or nitrogen Dialiket
DEAERATOR	the second s	partially filled deaera- tor with water is stored as follows: Nitrogen blanket $N_2H_4$ 5~10ppm	steam sealing or nitrogen s blanket N <sub>2</sub> H <sub>4</sub> 10~20ppm	Nitrogen blanket N <sub>2</sub> H <sub>4</sub> 50pm NH <sub>4</sub> 5ppm	nitrogen blanket N <sub>2</sub> H <sub>4</sub> 100ppm NH <sub>4</sub> 5ppm	or dry lay-up
B 0 I L E R CONDENSATE FEEDWATER SYSTEM	<pre>heater made of steel No treatment (the same as operation condition) water full filling, N<sub>2</sub>H<sub>4</sub> 5~10ppm (hlr. full filling and nitrogen blanket.</pre>	ly nitrogen wing	water flooding of unit with chemical conc. of $N_2 H_4 \ 10 \sim 20 ppm$	water flooding of unit with chemical conc. of N <sub>2</sub> H <sub>4</sub> 50ppm (pH>10) NA <sub>4</sub> 5ppm (pH>10)	water flooding of unit with chemical conc. of $N_2H_4$ 100ppm $N_4$ 5ppm or nitrogen blanket	
System Outage Period	oiler Banking <<100 Hrs		<-10 -days	<li>4 month</li>	▲1 month	

HEATER SHELL SIDE	heater made of steel. based on unit with heater made of steel. In case of water flooding, $N_2H_4$ should be kept at 20-30 ppm. In case of without and water filling equipment and water filling equip- ment, water should be drained out at high temperature and it should be kept at dry condition.						water tilling equip- ment, water should be drained out at high temperature and it should be kept at dry condition. less than ntration is less than 4 500ppm, NH <sub>4</sub> free.		
CONDENSER FEEDWATER SYSTEM D E A E R A T O R	<mark>al 100</mark> /	<pre>based on unit with heater made of steel, no treatment (the same as operation condition)</pre>	N2H4 5 ~ 10 ppm	$N_{\rm L}^{2}H_{4}$ 10 $\sim$ 20 ppm		N <sub>2</sub> H <sub>4</sub> 20 ~ 30ppm	is suppressed by the environmental aspects, if $N_2H_4$ concentration is less specification valve, additional injection is possible. Intration is possible to be increased conservatively to $N_2H_4$ 500ppm, $NH_4$ function is possible to be increased conservatively to $N_2H_4$ 500ppm, $NH_4$ function is possible to be increased conservatively to $N_2H_4$ 500ppm, $NH_4$ for the increased conservatively to $N_2H_4$ 500 ppm.		
8 0 1 L E R	"Unit with heater made of copper alloy	based on unit with heate (the same as operation c			N2H4 50ppm	N2 <sup>4</sup> 4, 100 ppm	<ul> <li>* In JPN, N<sub>2</sub>H<sub>4</sub> concentration is suppressed by the specification valve, In case of NPC, N<sub>2</sub>H<sub>4</sub> concentration is possible</li> </ul>		
System Outage Period	<sup>o</sup> Unit wi	Boiler Banking	<100 Hrs	< 10 days	<1 month	×1 month	Notes: In JP In ca		

# 12) Boiler Chemical Cleaning

Post operational chemical cleaning of NAPOCOR boilers is done depending on the density of deposits on the tube. During overhauling, water wall tube samples are taken from the hottest side to determine whether there is a need to chemically clean the boiler. In the case of Gardner-2, the density of deposits on the water wall tube was more than the allowable limits of 30 mg/cm<sup>2</sup>. The Quality Assurance Group, the Plant Management and the Region Technical Services Division decided that there is a need for chemical cleaning.

The chemical section of the plant prepared the corresponding procedure, management during the chemical cleaning process, analysis and take charge of the chemical cleaning. The operation group supervised the operation of the system.

Actually the chemical cleaning was delayed by five days from the original schedule due to the lack of the secondary superheater valves. The whole chemical cleaning process was successful as shown in the result of inspection. The quantity of scale removed during the process was about 3150 kgs  $Fe_3^{0}_4$ . The flash tank and boiler heater were inspected and found to be coated with thin film of magnitite.

- Aug. 12 Temporary piping flushing
  - 13 19 Pump and valves repair
    - 20 Secondary superheater flushing
      - Boiler filling and raising of temperature

and the state

- Preparation of chemicals
- 21 Acid cleaning
  - Displacement
- 22 Passivation
- 23 Inspection of Flash Tank
- 24 Inspection of heater and sampling tube
- Sept. 5 Wet storage (boiler fill)
- b. Summary of Chemical Cleaning

(a) Temporary piping, boiler, SH flushing

Flushing of the temporary piping finished early. During the boiler and secondary superheater flushing, leak developed at the main stop valve, MV-4, MV-5, and CV-104. Likewise, the chemical cleaning pump broke down. The repair of leaky valves and pump took 5 days. In the meantime that the valves were being repaired, JICA team advised to relocate the chemical injection point.

# (b) Acid Cleaning

During the acid cleaning process, the initial plan was to heat the system to about  $195^{\circ}F$  ( $90^{\circ}C$ ) -  $200^{\circ}F$ ( $93^{\circ}C$ ) but JICA team recommends to initially heat the system to  $200^{\circ}F$  ( $93^{\circ}C$ ) -  $210^{\circ}F$  ( $99^{\circ}C$ ) because during the chemical injection the temperature will drop. In addition, they recommend to drain the flash tank and prepare the acid solution with the same volume as of the flash tank.

The chemical injection was finished within 45 minutes. The normal flow was done in 3 hours and the reverse flow in 3 hours. After 4 hours of acid recirculation, the maximum iron concentration was about 15600 ppm which is the saturation point.

# (c) Displacement

The flash tank was drained under nitrogen blanket. The filling and draining were done in 14 hours. The demineralized water used during displacement contained  $30-20 \text{ ppm N}_2\text{H}_4$ . In the displacement process the target value of turbidity is 10 ppm. The actual analysis of the displaced water was 6 ppm turbidity and 5 ppm iron. Then passivation phase follows. The total volume of demineralized water consumed during displacement was 1080 m<sup>3</sup>.

. (1994) - (1

물 같아. 나는 것이 않아. 나는 것이 않아. 나는 것이 않아. 나는 것이 않아.

# (d) Passivation

The circulating water was heated to 200°F (93°C). Once the temperature equilibrium was reached, the passivating chemicals were injected.  $(N_2H_4$  and NH<sub>4</sub>OH). Once the pH of 10 was attained the solution was recirculated for 6 hours, thereafter the system was completely drained.

#### c. Inspection

#### (a) Test Plate

The test plate was installed in the heater discharge main line. It was made of the same material as of the waterwall tube. After the acid cleaning, the test plate surfaces has no pitting corrosion. There was a considerable lost in weight but the corrosion rate could not be computed due to the irregularity of the shape of the test plate.

(b) Flash Tank

The scale at the flash tank was completely removed. The sludge accumulated at its bottom was about 2 cm.

#### (c) Boiler Water Wall Header

The scale at the boiler water wall tube was completely removed and it was properly passivated. At the bottom header, there was an accumulation of about 1 cm thick of sludge. JICA team advised to remove all of them. In addition, it was observed that the water wall header surfaces was wet and it might be due to incomplete draining.

# (d) Water Wall Sample Tube

The inside of the water wall tube sample showed clean surfaces which was indicative of effective passivation.

	Concentra	PROC				
	tion in the cycle	Acid Cleaning	Passiva- tion	Wet Storage	Total	
Hydroxy Acetic Acid (70% as CH <sub>2</sub> 00H)	2%	1145 Gals (4.35 m <sup>3</sup> )			1145 Gals (4.35 m <sup>3</sup> )	
Formic Acid (85% as HCOOH	1%	480 Gals (1.8 m <sup>3</sup> )	-		480 Gals (1.8 m <sup>3</sup> )	
Rodine 31A		195 Gals (0.7 m <sup>3</sup> )			195 Gals (0.7 m <sup>3</sup> )	
Hydrozine (35% as N <sub>2</sub> H <sub>4</sub> )	500ppm		70 Gals (0.27m <sup>3</sup> )	70 Gals (0.27m <sup>3</sup> )	140 Gals (0.54m <sup>3</sup> )	
Ammonium Hydroxide (28% as NH <sub>4</sub> OH)	10 ppm as NH <sub>3</sub>		10 Gals (0.04 m <sup>3</sup> )	10 Gals (0.04 m <sup>3</sup> )	20 Gals (0.08 m <sup>3</sup> )	
Nitrogen Gas (100% N <sub>2</sub> )	2-5psig	10 Bottles			10 Bottles	
Demineralized Water (estimate)		200 m <sup>3</sup>	1100 m <sup>3</sup>	200 m <sup>3</sup>	1500 m <sup>3</sup>	

						•				5	• •••	59	9								
			• • • • •	- 			ini National Ragenti			-											
			e.	D	ata	of	Wa	ate	r (	)ua	Lit	v o	f (	Chei	nic	a1	<b>C</b> 1	ean	ing	ς Ο:	£G-
andra an Anglas an Anglas anglas Anglas anglas Anglas anglas										••••••••••••••••••••••••••••••••••••••											
														i E G							
	Tal	ole	5C-	44	DA	TA	OF	WA	TE	R Q	UAL	ITY	' A'	гс	HEM	IC	<b>AL</b>	CLF	AN	ENG	OF
	rks																				
	Remarks																				
	sure <sup>0</sup> F			175		195	195	195	183	182											
	Temperature After   c+			~		8			œ			*						200	195	210	210
	Tem Aft	йн Н		2		198	195	195	198	061								2	~	2	5
	C1		0.3																		
	CHN BHJ		4.2											1.5				3133	5100	2744	2439
				;											55	58	66	0	0	0	2
															ъ Ч	ۍ ا	9	1440	1440	1120	1.042
	Turbi- dity		0.01								161	104	70	44	36	10	9				
		uid d		0	0	0	0	0	0	0									1. No. 1.		
								3					7			<u>م</u>					
		ed d		6200	5065	13632	12422	15678	14598	13512			97	121							
	Conductivity	Micro S/Cm	20.5					15678													
	Conduc	Micro						-		an a											
	Acid			6	2.4	2.3	2.0	1.6	1.6	1.6											
	Hd		0.0			2.9	3.8	3.7	1.1.1	3.4	3.4	4.2	5.2	7.6	7.8	7.5	8.1	10.0	10.0	10.1	10.0
		- -							2			 ≥		L							-
	Time	Aug. 20	9:00 P	Aug. 21 5-50 A M	6:40	7:40	8:15	00-6	10:00	11:00	2:00	1:00 P.M	6:30	8:00	Aug. 22 1:15 A.M.	1:45	2:15	1:00	12:30	3:00 P.M.	3:30
			Heating 1				n sə l					1	<b>.</b>	ອແອວ					its	<b>.</b>	

Table 5C-45 BOILER CHEMICAL CLEANING PROCEDURE

Temp. 190-200°F Temp.120-130°F T-Fe 100 ppm Inspection of is constant, Temp 100 °F [End Point] pH 9.0 Iron content Reverse 3 Hr [End Point] pH 5.0 [End Point] Temp 195 °F Circulation Temp. 100°F Normal 3 Hr [End Point] Test Tube. 1 Hr Remarks Analysis Item е --1 - Fe Fe<sup>2+</sup> ي ب ا те <del>3</del> Hd Hd Hd Hd. Hd 3 In case of Japan N2H4 500 ppm Organic Acid Chemicals NH3 0.08% Acid Inhibitor Reducing Critical agent 0 1% ž Neutralization (Filling and Passivation (2 Hr) ( 1 Hr ) Schedule Blowing) Cleaning Rinsing ( 1 Hr. ) ( 8 hr) Washing Acid (6 Hr) Temp 195 - 200°H Acid Concen-Temp. 195-200°F Iron content is Reverse 3 Hr Circulation [End Point] [End Point] constant. Temperature Normal 3 Hr Remarks Turbidity Analysis Item Turbidity tration Boller N2H4 Hđ 1-Fe ਸ਼ੁਰ 3 #2 NH<sub>3</sub> 10 ppm 10 - 20 ppm N2H4 500 ppm CH200H 2% Rodine 31A Chemicals HC00H 1% Gardner N2H4 Displacement Passivation ( 6 Hr ) Schedule Cleaning Acid (6 hr) (13 Hr)

5 - 600

Total volume of boiler water wall  $152 \text{ m}^3$  (40,000 gal)

 $15600 \text{ ppm x } 152 \text{ m}^3 = 2371 \text{ kg as Fe}$ 

= 3272 kg as  $Fe_{3}O_{4}$ 

g. Deposit Volume of Sample Tube

	Before Cleaning	After Cleaning
Fire Side	66.37 mg/cm <sup>2</sup>	9.96 mg/cm <sup>2</sup>
Rear Side	44.84 mg/cm <sup>2</sup>	1.57 mg/cm <sup>2</sup>
Analysis of Scale		
34	Component 8% as NaCl	
SiO none	0% as NaU1	

Si0<sub>2</sub> none

h. Test Plate Analysis

사람이 눈 가는 것이 잘 주었다. 나라 가지 않는 것 같은 것 같이 많이 많이 많이 많이 했다.	
$(\mathbf{gr})$	(gr) (gr)
#1 55.01610 54	.91750 0.09860
#2 57.01720 56	.91155 0.10565

Surface Area unknown

## i. Recommendation

(a) Schedule of Chemical Cleaning

Gardner-2 boiler acid cleaning was scheduled at the middle of the overhauling period. The acid cleaning finished on August 22 and wet storage of the boiler was done on September 5, 1982. The protection film created during passivation is effective only for one week. In Japan, the chemical cleaning is done 7 to 10 days before the unit start. In this case the boiler feed pump can be used in filling the boiler circuit. In using the boiler feed pump, the preboiler and heater are simultaneously being flushed.

In this regard, JICA team strongly recommend that chemical cleaning should be done 7 - 10 days before the start of the unit.

(b) Preparation before Acid Cleaning

i. Boiler Hydrostatic Test

ii,

Prior to chemical cleaning, the boiler circuit should be hydrostatic tested to avoid unnecessary delay. Like in the case of Gardner-2, the acid cleaning was delayed by 5 days due to the leaking secondary superheater valves. Operation of Circulating Water Pump (CWP)

During chemical cleaning the circulating water pump should be placed in operation to cool the high temperature drain which leak to the condenser hot well.

iii. Scale removal test of sample tube

The quality of scale deposits inside the water wall tube depends on the condition of operation periods. High heat rate could not remove the scale deposited. In this regard, proper chemical cleaning is needed to restore the effectiveness of the water wall tube. Prior to the chemical cleaning, scale from the water wall tube should be analyzed to determine the effective chemicals or kind of acid needed for

its proper removal.

(c) Chemical Cleaning Procedure


i. Test Tube and Plate

To determine the effectiveness of the chemical cleaning process, JICA team recommends installation of the test tube and plate during acid cleaning. The operating condition where the test materials are installed should be the same as that of the waterwall tube.

In case of Japan, the loss in weight of the test tube is limited within 3 to 5 mg/cm<sup>2</sup> during total washing hours.

JICA team observed that the test plate was installed after the mixing heater. Its condition was different from the water wall tube so that the effect is not conclusive. JICA team recommends test plate and tube should be installed before the mixing heater with corresponding flowmeter so that velocity is the same as that of the water wall tube.

## Please refer to the diagram shown below:



Test Plate Test Tube <u>Recommendation</u>

In case of Gardner-2, the test plate was installed after the mixing heater. In this case, the test plate was exposed to a fast velocity wherein corrosion rate is high. Procedure for Mixing the Chemicals


## (1) Hydrazine Mixing

ii.

JICA team observed that hydrazine was directly mixed in the condensate storage tank during chemical cleaning process. JICA team recommends that a separate hydrazine tank with corresponding injection pump be provided for every chemical cleaning. In this way, contamination of the boiler make-up water will be avoided. It was noted last September 9, 1982, the makeup water to the boiler was contaminated with the chemicals at the condensate storage tank. The feedwater pH and  $N_2H_4$  concentration tremendously increased.

## (ii) Acid Mixing

During the preparation of the acid cleaning chemicals, JICA team observed that 55 gals drums were individually being lifted with the use of a chain block. the procedure was dangerous, we are recommending that 250 gals rubber lined tank and transfer pump be used in mixing the chemicals. Please refer to the diagram below:



## iii. Procedure of Cleaning

## (i) Displacement

JICA team observed that the NAPOCOR displacement process during chemical cleaning was continuous filling and draining. The process was observed to be time consuming and consumed plenty of demineralized water. JICA team recommends that during the displacement process filling method should be used. In Japan, the said method will take only about 8 hours and will consume only 2 times of the boiler volume. In case of Gardner-2 the displacement was about 14 hours and consumed 1100 m<sup>3</sup> or 290,000 gals of demineralized water which is equivalent to about 7.2 times of the volume of the boiler.

## (ii) Rinsing

JICA team recommends that after acid cleaning, the rinsing water should contain 0.1% citric acid.

## (iii) Fe<sup>+3</sup> Analysis During Acid Cleaning

During the acid cleaning process,  $Fe^{+3}$ should be analyzed. Excess of  $Fe^{+3}$  is indicative of metal corrosion. In this respect,  $Fe^{+2}$  and  $Fe^{+3}$  should separately be analyzed. If the  $Fe^{+3}$  exceeds 500 ppm, hydrazine or reducing agent should be injected into the system.

## (iv) Check of System Flow Rate

In chemical cleaning using organic acid, maintenance of the right velocity and temperature of the system is important. In case of once-through boiler, there is a difficulty to maintain the right velocity in the system so that proper checking of vents should be done to have a laminar flow. Likewise, checking of the temperature in all side of the boiler should be done.

# Reference - 10 Test Method for Iron (Fe<sup>3+</sup>/Fe<sup>2+</sup>) (for Chemical Cleaning)

1. Summary of Method

 $Fe^{3+}$  (ferric ion) in sample forms a red-violet complex with sulfosalicylic acid at a pH of about 2. By the titration of this solution with EDTA solution, yellow complex is formed. Accordingly,  $Fe^{3+}$  can be determined first and  $Fe^{2+}$  can be titrated after oxidation to  $Fe^{3+}$ .

2. Reagents

d)

- a) pH Buffer Solution Dissolve 10.7 g of ammonium chloride (NH<sub>4</sub>Cl) and 20 ml of acetic acid (CH<sub>3</sub>COOH) in water and dilute to 100 ml.
- b) 10% Sulfosalicylic Acid Dissolve 10 g of sulfosalicylic acid ~C<sub>7</sub>H<sub>5</sub>O<sub>3</sub> (So<sub>2</sub>NH<sub>2</sub>)" in water and dilute to 100 ml.
   c) Ammonium Persulfate
  - 0.09M EDTA Solution Dissolve 33.5 g of disodium ethylenediamine-tetraacetate dihydrate  $[(CH_2COO)_2 NCH_2CH_2N(CH_2COO)_2.H_2.Na_2.2H_2O]$  in water and dilute to 1000 ml. The factor of this solution is determined as follows. Take 50 ml of iron standard solution (1 mg Fe<sup>2+</sup>/1 ml) into a beaker and add 20 ml of pH buffer solution and about 2 ml of 10% sulfosalicylic acid and heat to 40 - 50°C. After adding about 2g of ammonium persulfate, titrate the solution with 0.09M EDTA solution until the color changes to light-yellow from red-violet. From ml(x) volume of EDTA solution required to titrate, calculate the factor (F) as follows.

 $\mathbf{F} = \frac{25}{\mathbf{X}}$ 

## 3. Procedure

a) Fe<sup>3+</sup>

Take 5 ml of filtered sample into a beaker. Add 20 ml of pH buffer solution and 2 ml of 10% sulfocalicylic acid. If ferric ion (Fe<sup>3+</sup>) is present, red-violet color develops. Titrate the solution with 0.09M EDTA solution until a yellow color, after heating to 50 - 60°C. From ml (a) volume of EDTA solution required to titrate, calculate the concentration of ferric ion (Fe<sup>3+</sup>) as follows:

 $Fe^{3+}$  (ppm) = a x 1000 x F

b) Fe<sup>2+</sup>

After testing ferric ion, add about 2 g of ammonium persulfate into the same solution for the oxidation of Fe<sup>2+</sup>. Titrate the solution with 0.09M EDTA solution until a yellow color. From ml (b) volume of EDTA solution required to titrate, calculate the concentration of ferrous ion (Fe<sup>2+</sup>) as follows:

 $Fe^{2+}$  (ppm) = b x 1000 x F

where, F = the factor of 0.09M EDTA solution

### Remarks

- If pH of the sample is not adjusted at 2 2.5, the end point is not clear.
- When copper and nickel concentration is more than 500 ppm, the end point is not clear and gives higher value.
- Solution temperature should be kept at 50 60°C, for the slower reaction of room temperature. Titration should be done slowly near the end point to prevent getting of higher value.

If an accelerant (flouride such as NH4HF2) exists in the sample, it is difficult to titrate for the formation of Fe
F Chelate, but possible to titrate by adding 20% aluminum sulfate as follows.

In case of testing at room temperature - - - -

Add 2 ml of 20% aluminum sulfate solution in 2 ml of the sample and wait for 2 minutes. The following procedure is the same as the text.

In case of testing at 50 - 60°C

Concentration (%)	Addition Volume (ml)
of Accelerant	_of 20% Al <sub>2</sub> (SO <sub>4</sub> )3
0,3	0.3
0.3	0.4
0.5	0.5
1.0	1.0

동화 (第1948년 2월 - 2019년 4월 - 2017년 2월 - 2019년 4월

· 사실 문화 제품은 문화 같은 문화 같은 것이라.

· 동물은 특별 이 동문을 알려도 가슴을 써 아이들 것 같은 동물이었는 것을 것

是推动的问题的,我们的问题,我们就是我们的问题。 网络拉马拉

### 13) Corrosion Protection in Furnace Side

Gardner/Snyder and Malaya Thermal Plant used high sulfur fuel oil in the boiler. Below is the corrosive components of the said oil:

% Sulfur --- 2.9 - 4.5

ppm Sodium --- 8 - 19

ppm Vanadium ---- 13 - 54

The presence of corrosive components in the fuel oil will cause low and high temperature corrosion in the boller system. Like in the case of Malaya Thermal Plant, its air heater always being clogged up. Improvement of the unit's efficiency is always a problem.

Inspection of Gardner-2 indicated corrosion on the furnace side of water wall tube and secondary superheater.

Gardner/Snyder and Malaya units are always being operated not on the rated capacity. Thus their corresponding heat rates are very high. If the abnormality in the boiler is repaired and the unit is operated full load, there will be high temperature corrosion and ultimately will cause tube failure. In this regard, it is necessary to protect the furnace side.

Snyder-1 and -2 and Malaya-2 gas ducts are being corroded by the furnace gas caused by low temperature corrosion. In the said units there were so many gas leaks and even in the control room odor of  $SO_2$  gas could be felt. The concentration of  $SO_2$  gas is way beyond the environmental limit of 0.1 ppm  $SO_2$ . Malaya-2 air heater differential pressure increases due to clogging of elements. The effect will cause the reduction of the unit load.

Snyder-2 at present is using fuel oil additive. The result is not yet known.

All units have no protection from low temperature corrosion. In this matter, the air heater is being damaged due to defective steam coil heater. Recommendation

Below is the effect of high sulfur fuel in the boiler.




Table 5C-46 EFFECT OF HIGH SULFUR OIL

High temperature corrosion is due to the presence of sodium sulfate which causes sulfidation attack on the tube surfaces. It could be protected by following the protection method stated below. But in spite of implementing the necessary protection method, the system could not be protected completely if there is no careful inspection during overhauling and advance maintenance.

Disposition of High Temperature Corrosion

- (1) Prevention of gas inclination and cancellation of high temperature area
- (2) Protection of local high temperature area with refractory material
- (3) Injection of fuel oil additive to raise the melting point
- (4) Water washing of the furnace
- (5) Changing of tube material, for instance SUS 316, SUS 321 to SUS 347 and STBA 24 to HCM9M

For sodium corrosion, the best additive are magnesium compound, aluminum and manganese compound.

Using wrong type of fuel oil additive, the evaluation is very difficult and the price is very expensive. In Japan recently, the use of fuel oil additive is discontinued because the cost of boiler tube is lower compared to the cost of fuel additive.

Low temperature corrosion is caused by oxidation of  $SO_2$  to SO<sub>3</sub> and ultimately formation of  $H_2SO_4$ . With the increase in SO<sub>3</sub> concentration, the corresponding dew paint decreases, thus  $H_2SO_4$  is produced which caused corrosion of air heater, gas duct and stack. The  $H_2SO_4$  condensation will cause presence of sticky ash. Below is the protection of low temperature corrosion.

## Protection of Low Temperature Corrosion

- (1) Low excess air operation should always be maintained.
- (2) Control of exhaust gas temperature
- (3) Injection of ammonia gas after multicyclone
- (4) Anti-corrosion material should be used, for instance corten steel
- (5) Steam coil air heater should be used to increase the metal temperature of the air heater.

JICA team recommends measurement of  $SO_2$ ,  $SO_3$  analysis and the corresponding dew point, so that proper treatment could be done. In this regard JICA team recommends implementation of Items (2) and (5) of the protection method.

a she wate Mar

的复数建筑者 医马克勒氏试验检尿道检尿

S. 2012 - 201