

APPENDICES FOR CHAPTER 9

9 - 1	Development Strategies and Major Projects By Region - - - - -	183
9 - 2	Future Planning Framework - - - - -	193



# APPENDIX 9-1 Development Strategies and Major Projects by Region

## APPENDIX 9.1-1 REGIONAL STRATEGIES BY SECTOR AND SELECTED MAJOR ON-GOING PROJECT, REGION I, II AND VIII

Region	Agriculture	Industry	Social Services	Infrastructure	Selected Major On-Going Projects
Iloocos (I)	<ul style="list-style-type: none"> <li>* improvement of the technological, financial and marketing components of the different agricultural programs together with specialization in and intensification of the production of a number of high-value cash crops while exercising care that production does not conflict with ecological objectives</li> </ul>	<ul style="list-style-type: none"> <li>* expansion of manufacturing and other industrial employment generating activities in the urban centers, and household-based or small industries in the rural areas</li> <li>* further boost to tourism sector through the continuous development of tourists attractions</li> </ul>	<ul style="list-style-type: none"> <li>* strengthening of expanded rural health services and nutrition program</li> <li>* expansion of non-formal training of unemployed adults and out-of-school youth</li> </ul>	<ul style="list-style-type: none"> <li>* expansion of irrigation facilities</li> <li>* improvement of critical trunkline roads in depressed areas and existing road linkages to neighboring regions</li> <li>* development of railways as an alternate mode of land transport</li> <li>* vigorous pursuance of electrification program and tapping of other sources of energy (geothermal energy)</li> </ul>	<ol style="list-style-type: none"> <li>1. Philippine Rural Infrastructure Project (PRIP)</li> <li>2. National Irrigation System Improvement I</li> <li>3. Philippine-Japan Highway Loan Project - Phase II</li> <li>4. Manila North Road Improvement Project</li> </ol>
Cagayan Valley (II)	<ul style="list-style-type: none"> <li>* attainment of the nutrition, export substitution and import substitution and energy development</li> <li>* priority for classification of public forest land to help establish an appropriate land use pattern</li> </ul>	<ul style="list-style-type: none"> <li>* promotion of cottage and small industries, and secondarily, on selected medium industries</li> </ul>	<ul style="list-style-type: none"> <li>* additional social infrastructure support in underserved areas</li> </ul>	<ul style="list-style-type: none"> <li>* construction of farm-to-market roads</li> </ul>	<ol style="list-style-type: none"> <li>1. Philippine-Japan Highway Loan Project, Phase II</li> <li>2. Magat River Multi-Purpose Project (Power Phase)</li> <li>3. Cagayan Integrated Agricultural Development Project</li> <li>4. Philippine Rural Infrastructure Project</li> <li>5. Chico River Irrigation Project</li> <li>6. Magat River Multi-Purpose Project (Irrigation)</li> <li>7. National Irrigation Systems Improvement Project I</li> </ol>
Eastern Visayas (VIII)	<ul style="list-style-type: none"> <li>* tapping of prime arable lands for expanded production and by developing new technologies for upland and marginal farms</li> </ul>	<ul style="list-style-type: none"> <li>* complement Metro Manila and Cebu in the promotion of new industrial ventures</li> <li>* operation of Tongonan Geothermal Project to provide energy requirement of the Copper Smelter and Phosphatic Fertilizer Plant and Industrial Estate in Isabel Leyte.</li> </ul>	<ul style="list-style-type: none"> <li>* realignment of new technologies and expertise on manpower development facilities</li> </ul>	<ul style="list-style-type: none"> <li>* construction of road, bridges, ports and telecommunication facilities</li> </ul>	<ol style="list-style-type: none"> <li>1. West Leyte Road Improvement</li> <li>2. Philippine-Japan Friendship Highway-Project</li> <li>3. Samar Integrated Rural Development Project</li> <li>4. Copper and Melter, Isabel, Leyte</li> <li>5. Phosphatic Fertilizer, Isabel, Leyte</li> <li>6. Tongonan Geothermal Power Project</li> <li>7. Leyte-Samar Project</li> <li>8. National Irrigation Systems Improvement Project I</li> </ol>

APPENDIX 9.1-2 (I) PROJECT LIST ON SELECTED ON GOING MAJOR PROJECTS  
(AS OF DECEMBER 1982)

SECTOR / PROJECT NAME	REGION	PROJECT LOCATION	PROJECT COST (MILLION PESOS) (\$1 = P7.50)	PROJECT DESCRIPTION
<b>I INFRASTRUCTURE</b>				
<b>A. Road</b>				
1. Philippine - Japan Highway Loan Project, Phase II	I and II	Laoag - Allacapan	363.35	Upgrading of selected portions of the Manila North Road (Road No. 3) beginning at Laoag City in Ilocos Sur North until Allacapan, Cagayan Province (Road No. 5)
2. Manila - North Road Improvement Project	I	Rosario - Laoag	544.913	Improvement of about 225 kms. from Rosario, Pangasinan to Laoag, Ilocos Norte.
3. West Leyte Road Improvement	VIII	West Leyte	18.109	Improvement of existing road sections of about 296 kms. to acceptable levels of service.
4. 3rd IBRD Highway Package	V, VI, VII and X	Not Specified	1,576.8	This project package includes 577 kms. of national roads and 230 kms. of minor roads.
5. Philippine - Japan Friendship Highway - Ferry Service Project	V, VIII and X	Sorsogon - Samar, Leyte - Surigao	247.47	It will serve as final link for the Daang Maharlika from Allacapan in Cagayan to Davao City.
<b>B. Ports</b>				
1. Fishing Port Package I Project	I, IV, V, VI, IX	Sual, Lucena, Camaligan and Zamboanga	854.297	The project involve the construction of fishing port complexes for efficient handling operations and improve shelter, maintenance and repair of fishing vessels.
<b>C. Rail</b>				
1. Main Line South Rehabilitation Project	V	Manila - Legaspi	476.9	Rehabilitation of the tracks, bridges and communication system in the southern line of the Phil. National Railways (PNR) between Manila and Legaspi
<b>D. Power and Electrification</b>				
1. Magat River Multi - Purpose Project (Power Phase)	II	Ramon, Isabela	672.14	Construction and development of hydroelectric power plant at the Magat River multi-purpose project with an initial capacity of 360 megawatts (MW), consisting of four (4) generating units at 90 MW each.
2. Kalayaan Pumped Storage Power Project (Stage I)	IV	Laguna	1,930.51	Construction of a pumped storage hydroelectric power plant with an aggregate installed capacity of 300 MW consisting of 2 generating capacity of 300 (MW) each. Basically operating as hydraulic accumulator system, the plant will supplement electric power in the Luzon Grid, specially during periods of off peak power demand.

APPENDIX 9.1 - 2 (2) PROJECT LIST ON SELECTED ON GOING MAJOR PROJECTS  
( AS OF DECEMBER 1982 )


SECTOR / PROJECT NAME	REGION	PROJECT LOCATION	PROJECT COST (MILLION PESOS)	PROJECT DESCRIPTION
3. Makiling - Banahaw Geothermal Power Project (Units 5 and 6)	IV	Calauan, Laguna	993.04	Involves the exploration and exploitation of geothermal resources in the Makiling - Banahaw areas in the Southern Tagalog region and the construction of power generation facilities for the third Mak - Ban Geothermal Power Plant including the supply and erection of the electromechanical equipment.
4. Tiwi Geothermal Power Project (Units 5 and 6)	V	Tiwi, Albay	790.32	Construction of power generation facilities with a total capacity of 110 (MW), consisting of 2 generating units at 55 MW each.
5. Tongonan Geothermal Power Project	VIII	Tongonan, Leyte	490.99	Involves the generation of electric power, estimated to have a total generating capacity of 112.5 (MW), utilizing the geothermal resource potential of the Tongonan and Burawen Geothermal Field.
6. Leyte - Samar Circuit	VIII	Leyte and Samar	254.62	Involves the installation of transmission lines (192 kms. of 138 KV and 45.5 kms. of 69 KV) and construction of two substation facilities.
E. Irrigation and Related Water Resources Project				
1. Chico River Irrigation Project	II	Cagayan and Kalinga - Apayao	548.0	Upgrading and rehabilitation of existing irrigation system in the project area and extend irrigation to about 19,700 has. of rainfed rice land.
2. Magat River Multi - Purpose Project	II	Isabela	681.206	The project seeks to accelerate the development of the Cagayan Valley through irrigation, flood control and provision of electric power. It is also aims to establish adequate system of domestic water supply, recreation and fish conservation.
3. National Irrigation Systems Improvement Project I	I, II, and VIII IV, V, VI IX, X, XI and XII	Not Specified	1,844.010	Rehabilitation of existing irrigation and drainage system as well as constructing new irrigation facilities to allow year - round cultivation.
4. Central Luzon Ground - water Irrigation Project	III	Not Specified	221.351	The project involves the installation of 240 deep wells and related equipment to supplement water supply for irrigating an additional 12,000 has. in areas where surface water is inadequate.

APPENDIX 9.1-2 (3) PROJECT LIST ON SELECTED ON GOING MAJOR PROJECTS  
(AS OF DECEMBER 1982)









SECTOR / PROJECT NAME	REGION	PROJECT LOCATION	PROJECT COST (MILLION PESOS)	PROJECT DESCRIPTION
II Integrated Area Development Project				
1. Libmanan Cabusao Integrated Area Development Project	V	Libmanan and Cabusao, Camarines Sur	78.91	Involves the construction of irrigation and drainage facilities, flood and salinity control structures, roads and social/institutional services in around 3,927 hectares.
2. Bicol Secondary and Feeder Roads Project	V	Camarines Sur and Albay	404.0	Involves the construction of 189.96 kms. of secondary roads, 252.34 kms. of feeder roads and 61 bridges.
3. Bicol River Basin Irrigation Development Project	V	Naga, Calabanga and Rinconada, Camarines Sur	612.6	Involves the implementation of 2 integrated area development projects, namely, Naga - Calabanga and Reconada IDA's. It has 6 components irrigation and irrigation and related works, flood control; agricultural and institutional development; farm to market roads; rural waterworks development and watershed development.
4. Rinconada - Buhi/Lao	V	Buhi, Baao, Nabua and Iriga City, Camarines Sur	75.26	Rehabilitation and extension of the existing Lalo Irrigation system to about 1,000 hectares; development of Lake Buhi as water source of irrigation, construct 21 Km. of service roads, develop watershed/agroforestation in 1,350 has. farmed by 900 small scale upland farmers.
5. Integrated Health, Nutrition and Population Project	V	Camarines Sur, and Albay	58.4	Involves the provision of health facilities to 400 barangays in Camarines Sur and Albay, upgrading of the laboratory facilities of the 2 provincial hospitals; training of health aides and construction of health stations.
6. Bula - Minalabac	V	Camarines Sur	69.0	Covers 2,423 hectares with 1,230 farmers as beneficiaries; it will provide farm lots of manageable sizes ranging from 500 to 2,000 square meter complete with irrigation and road facilities and the provision of settlement facilities to barangays in the area.
7. Cagayan Integrated Agricultural Development Project	II	Cagayan Province	501.98	Targeted to complete in 1983, the project includes agricultural development, provision of irrigation, electrification, construction of barangays roads and flood control facilities and other developmental projects.
8. Philippine Rural Infrastructure Project (PRIP)	I, II, VI, VII	Abra, Kalinga - Apayao, Aklan, Antique, Capiz and Bohol.	531.0	Construction and rehabilitation of 51 communal irrigation facilities; 1,172 kms. of barangays roads and access roads; 3 ports in Panay; 60 barangay health stations and provision of 418 wells for residents water supply.

APPENDIX 9.1-2 (4) PROJECT LIST ON SELECTED ON GOING MAJOR PROJECTS  
(AS OF DECEMBER 1982)


SECTOR / PROJECT NAME	REGION	PROJECT LOCATION	PROJECT COST (MILLION PESOS)	PROJECT DESCRIPTION
9. Samar Integrated Rural Development Project.	VIII	Samar Island	599.69	<p>IBRD Improvement of about 230 kms. of national roads in Eastern Samar; rehabilitation of Port Catbalogan; construction and improvement of about 2,000 wells and 100 spring in small rural communities throughout the island; construction of 3 schistosomiasis control field laboratories and a mass chemotherapy campaign and provision of consulting services to assist in carrying out F/S for Catubig valley in Northern Samar.</p> <p>ADAB Construction of approx. 160 kms. of national secondary roads and around 80 bridges; 260 kms. of agricultural feeder roads, water supply systems, development of power distribution system (240 kms.) and agricultural development.</p>
III Industry 1. Copper Smelter	VIII	Isabela, Leyte	\$343 M.	<p>Establishment of a copper smelting and refining facilities designed to process locally manufactured copper concentrates into refined copper; the plant targeted to operate in mid-1983, have a production capacity of 138,000 MTPY copper cathodes; 442,000 MTPY sulfuric acid.</p>
2. Phosphatic Fertilizer	VIII	Isabela, Leyte	\$484 M.	<p>Targeted to operate during mid-1984 the project, with an annual production capacity of 153,000 MT ammonium sulfate; 253,000 MT of AP/NPK; 512,000 MT of DAP and 170,000 MT of MAP, will utilize the sulfuric acid output of the copper smelter project.</p>
<p>SOURCE: 1. Profiles of Major On-going Foreign Assisted Projects as of 31 December 1982 NEDA, March 1983 2. Five-year Phil. Development Plan, 1983-87 NEDA</p>				



APPENDIX 9.1 - 3  
 MAJOR ON-GOING PROJECTS (ROADS, PORTS & RAILWAYS)


LEGEND:	
	Second ADB Improvement Project (Philippine Islands Road Improvement).
	Third IBRD Highway Package
	Luzon Road Improvement Project
	Ilocos Norte Rural Road Improvement Project
	Mindanao Secondary & Feeder Roads Project
	First OPEC - Assisted Road Project
	Fishing Ports Package I Project
	Third IBRD Ports Package






APPENDIX 9.1-4  
MAJOR ON-GOING PROJECTS (POWER & ELECTRIFICATION)


Legend:	
(N)	Nuclear
(H)	Hydrothermal
(G)	Geothermal
(C)	Coal





APPENDIX 9.1-5 MAJOR ON-GOING PROJECTS (IRRIGATION)


LEGEND:  NATIONAL IRRIGATION SYSTEM IMPROVEMENT PROJECT I & II

<p>LEGEND:  NATIONAL IRRIGATION SYSTEM IMPROVEMENT PROJECT I &amp; II</p>	



APPENDIX 9.1-6 ON-GOING AREA INTEGRATED DEVELOPMENT PROJECT

LEGEND:	
	PHILIPPINE RURAL INFRASTRUCTURE PROJECT (PRIP)
	SECOND RURAL DEVELOPMENT LAND SETTLEMENT PROJECT



APPENDIX 9.1-7 MAJOR INDUSTRIAL PROJECTS

	SOURCE: 1983-87 Dev. Plan, NEDA

## APPENDIX 9-2 Future Planning Framework

### APPENDIX 9.2-1. POPULATION IN THE PROJECT AREA BY PROVINCE

	Population				Growth Rates		
	1980	1990	2000	2010	1980-1990	1990-2000	2000-2010
<u>Region I</u>	<u>3,540,893</u>	<u>4,086,000</u>	<u>4,422,000</u>	<u>4,659,000</u>	1.4	0.8	0.5
Abra	160,198	181,000	195,000	205,000	1.2	0.8	0.5
Benquet	354,751	455,000	538,000	566,000	2.5	1.7	0.5
Ilocos Norte	390,666	434,000	451,000	475,000	1.1	0.4	0.5
Ilocos Sur	443,591	501,000	536,000	565,000	1.2	0.7	0.5
La Union	452,578	536,000	591,000	624,000	1.7	1.0	1.2
Mt. Province	103,052	120,000	132,000	139,000	1.5	1.0	0.5
Pangasinan	1,636,057	1,859,000	1,979,000	2,085,000	1.3	0.6	0.5
<u>Region II</u>	<u>2,215,522</u>	<u>2,784,000</u>	<u>3,273,000</u>	<u>3,740,000</u>	2.3	1.6	1.3
Batanes	12,091	14,000	16,000	19,000	1.5	1.3	1.7
Cagayan	711,476	873,000	1,003,000	1,146,000	2.1	1.4	1.3
Ifugao	111,368	136,000	156,000	178,000	2.0	1.4	1.3
Isabela	670,604	1,093,000	1,284,000	1,467,000	2.3	1.6	1.3
Kalinga-Apayao	185,063	238,000	285,000	326,000	2.6	1.8	1.3
Nueva Vizcaya	241,690	315,000	382,000	457,000	2.7	2.0	1.3
Quirino	83,230	115,000	147,000	167,000	3.3	2.5	1.3
<u>Region III</u>	<u>4,802,793</u>	<u>5,988,000</u>	<u>6,964,000</u>	<u>7,875,000</u>	2.2	1.5	1.2
Bataan	323,254	446,000	564,000	639,000	3.3	2.4	1.3
Bulacan	1,096,046	1,394,000	1,633,000	1,846,000	2.4	1.6	1.2
Nueva Ecija	1,069,409	1,517,000	1,512,000	1,710,000	2.1	1.4	1.2
Pampanga	1,181,590	1,442,000	1,667,000	1,884,000	2.0	1.5	1.2
Tarlac	688,457	836,000	950,000	1,075,000	2.0	1.3	1.2
Zambales	444,037	553,000	638,000	721,000	2.2	1.4	1.2
<u>Region VIII</u>	<u>2,799,534</u>	<u>3,358,000</u>	<u>3,763,000</u>	<u>4,054,000</u>	1.8	1.2	0.7
Eastern Samar	320,637	405,000	479,000	516,000	2.4	1.7	0.7
Leyte	1,302,648	1,541,000	1,690,000	1,821,000	1.7	0.9	0.7
Northern Samar	378,516	465,000	537,000	578,000	2.1	1.5	0.7
Southern Leyte	296,294	356,000	397,000	428,000	1.9	1.1	0.7
Western Samar	501,439	591,000	660,000	711,000	1.7	1.1	0.7


APPENDIX 9.2-2 EXPECTED GROWTH OF AGRICULTURAL OUTPUT  
BY REGION, 1982-87

	Philippines	REGION		
		I	II	VIII
Food Crop	4.9	-	-	-
Palay	3.6	4.8	6.3	1.3
Corn	11.9	4.8	6.0	1.3
Vegetables	-	4.8	16.4	-
Fruits	-	4.8	5.5	-
Commercial Crop				
Tobacco	-	4.8	5.5	-
Sugar	5.6	-	7.1	1.2
Coconut (Copra)	0.9	-	4.1	6.9
Fish	6.2	4.7	5.4	4.5
Meat	7.3	4.8	4.6	1.3
Forestry	1.7	5.3	2.2	
Mining	10.1	11.7	-	-
G R D P	6.3	7.2	7.4	7.6

APPENDICES FOR CHAPTER 10

10 - 1	Summary of Geological Survey- - - - -	195
10 - 2	Realignment of Critical Sections - - - - -	213
10 - 3	Stability Calculations - - - - -	219
10 - 4	Condition of Disaster and Selected Countermeasures - - - - -	227



Appendix 10-1 Summary of Geological Survey








BORING LOGS (MAHAPLAG-SOGOD SECTION) (2)



BORING LOGS (MAHAFLAG-SOGOD SECTION) (3)






# APPENDIX 10.1-4 UNCOFINED COMPRESSION TEST

PROJECT : ROAD DISASTER PREVENTION PROJECT  
 LOCATION : SOGOD-MAHAPLAG ROAD MAHARLIKA HIGHWAY  
 BOREHOLE NO. : BH-2 SAMPLE NO. : C-4

DATE : 12-21-83  
 DEPTH : 10.00-10.50 M.



APPENDIX 10.1-5 SUMMARY OF SEISMIC REFRACTION (MAHAPLAG-SOGOD SECTION) (1)

SPOT NO.	Results of seismic refraction Scale Hor. 1:200 m Vert. 1:100 m All velocities in M/sec.	Description
VIII-75		Montle soil covering and highly to moderately weathered and fractured ANDESITE
VIII-77		Same as VIII-75 however, overburden thickness is smaller in VIII-75
VIII-87		Reddish brown soil cover underlain by moderately to highly weathered AGGLOMERATES

SUMMARY OF SEISMIC REFRACTION (MAHAPLAG - SOGOD SECTION) (2)


SPOT NO.	<p>Results of seismic refraction survey</p> <p>Scale Hor. 1:200m Vert. 1:100m</p> <p>All velocities in M/sec</p>	Description
VIII-90		Brownish soils cover underlain by highly to moderately weathered AGGLOMERATES
VIII-100		Topsoil is underlain by ANDESITES of various weathering grades
VIII-103		Same as VIII-100, but jointing and weathering is more intense

SUMMARY OF SEISMIC REFRACTION (MAHAPLAG-SOGOD SECTION) (3)





SPOT NO.	Results of seismic refraction survey Scale Hor. 1:200m Vert. 1:100m All velocities in M/sec	Description
VIII-104		Totally weathered ANDESITE
VIII-107		Totally weathered AGGLOMERATES with highly jointed section



KEY MAP KENNON ROAD-BAGUIO CITY





HALF REDUCED COPY




APPENDIX 10.1-6 SUMMARY OF SEISMIC EXPLORATION AND BORINGS IN KENNON ROAD

APPENDIX 10.1-7 BORING LOGS (KENNON ROAD) (1)



BORING LOGS (KENNON ROAD) (2)



APPENDIX IO.1-B SUMMARY OF LABORATORY TEST RESULTS (KENNON ROAD)

PROJECT: ROAD DISASTER PREVENTION PROJECT  
LOCATION: KENNON ROAD, BAGUIO CITY

PROJECT: ROAD DISASTER PREVENTION PROJECT  
LOCATION: KENNON ROAD, BAGUIO CITY

SUMMARY OF LABORATORY TEST RESULTS

BORE-SAM- HOLE NO.	DEPTH (M)	NMC	ATTEBERG LIMIT					SIEVE ANALYSIS, (% FINER)					SIEVE NO.	REMARK	
			LL	PL	PI	1	3/4	4	10	20	40	60			140
BR-1															
1	0.55-1.00	41	73	33	40				100	96	89	81	72	65	58
2	1.55-2.00	43	60	26	34				100	94	81	65	56	50	40
3	2.55-3.00	33	48	28	20				100	94	82	66	56	45	40
4	3.55-4.00	37	53	24	29				100	86	68	52	41	37	30
5	4.55-5.00	48	74	32	44				100	93	86	74	62	54	51
6	5.55-6.00	44	61	27	34				100	96	90	80	68	62	53
7	6.55-7.00	50	72	30	42				100	99	99	96	91	79	74
8	7.55-8.00	51	73	30	43				100	99	99	96	91	79	77
9	8.55-9.00	16							100	87	71	50	38	34	28
10	9.55-10.00	28	62	32	30				100	97	94	89	79	65	61
11	10.55-11.00	32							100	88	71	58	54	42	33
12	11.55-12.00	24							100	77	54	41	36	27	24
13	12.55-13.00	20							100	88	71	55	44	36	28
14	13.00-13.45	46	52	27	25				100	99	95	90	80	71	69
15	14.00-14.45	32	57	26	31				100	99	93	82	73	65	59
16	14.45-14.90	34	74	32	42				100	92	89	87	71	62	61
17	15.00-15.45	30	62	30	32				100	94	81	64	51	41	32
18	15.55-16.00	17							100	88	74	54	40	27	17
19	16.00-16.45	9							100	97	83	62	44	24	15
20	16.55-17.00	10							100	96	86	68	53	45	34
21	17.00-17.45	3							100	67	53	40	26	17	9
22	17.55-18.00	11							100	60	42	37	30	14	10
23	18.00-18.45	21	45	33	12				100	99	96	82	53	34	32
24	18.55-19.00	21	46	32	14				100	90	86	83	72	53	27
25	19.00-19.45	6	44	32	12				100	95	91	82	65	48	36
26	19.55-20.00	11							100	93	83	71	59	49	39
27	20.00-20.45	3							100	93	91	79	65	45	37
28	21.00-21.45	6							100	86	54	41	22	20	16
29	21.45-21.55	10							100	84	68	57	42	38	31
30	22.55-23.00	7							100	82	71	54	45	33	26
31	23.00-23.45	10							100	94	58	53	48	43	33
32	23.55-24.00	13							100	91	62	56	43	40	33
33	24.55-25.00	11							100	90	79	58	43	34	27
34	25.55-26.00	12							100	89	76	59	48	36	28

SUMMARY OF LABORATORY TEST RESULTS

BORE-SAM- HOLE NO.	DEPTH (M)	NMC	ATTEBERG LIMIT					SIEVE ANALYSIS, (% FINER)					SIEVE NO.	REMARK	
			LL	PL	PI	1	3/4	4	10	20	40	60			140
BIL-2															
1	0.55-1.00	21	57	25	32										
2	1.55-2.00	33	59	32	37				100	97	93	87	81	76	70
3	2.55-3.00	37	75	34	41				100	99	97	91	86	80	77
4	3.55-4.00	28	71	30	41				100	95	92	87	76	68	60
5	4.55-5.00	25	45	33	12				100	92	89	80	67	51	46
6	5.55-6.00	30	46	34	12				100	95	87	70	55	49	45
7	6.55-7.00	30							100	92	79	62	45	38	27
8	7.55-8.00	25	54	24	30				100	91	84	76	68	51	42
9	8.55-9.00	24	54	25	29				100	85	76	59	47	37	23
10	9.55-10.00	13							100	96	93	82	69	61	53
11	10.55-11.00	30	64	28	36				100	94	83	72	63	55	49
12	11.55-12.00	22	71	29	42				100	92	83	72	61	52	44
13	12.55-13.00	22	69	30	39				100	99	87	68	53	46	38
14	13.55-14.00	29	61	27	34				100	99	87	68	53	46	38
15	14.55-15.00	22	74	32	42				100	95	92	84	69	59	48
16	15.55-16.00	9	67	31	36				100	97	87	81	79	76	
17	16.00-16.45	36	72	32	40				100	95	82	61	50	43	
18	16.55-17.00	27	69	32	37				100	96	86	78	68	63	
19	17.00-17.45	47	71	32	39				100	96	86	78	68	63	
20	17.55-18.00	51	75	32	43				100	97	91	71	58	51	
21	18.00-18.45	47	72	30	42				100	93	82	74	68	63	
22	18.55-19.00	49	67	30	37				100	93	82	74	68	63	
23	19.00-19.45	42	72	32	40				100	95	84	74	68	63	
24	19.55-20.00	56	77	35	42				100	95	83	73	71		
25	20.00-20.45	47	73	33	40				100	91	87	80	72		
26	20.55-21.00	56	67	31	36				100	97	93	81	74	66	
27	21.00-21.45	36	68	30	38				100	81	68	66	57	49	
28	21.55-22.00	46							100	86	84	66	47	36	



APPENDIX 10.1-9 SUMMARY OF SEISMIC REFRACTION (KENNON ROAD) (!)

SPOT NO.	Results of seismic refraction survey Scale Hor. 1:200m Vert. 1:100m All velocities in M/sec	Description
IK-6		Slightly weathered and fractured Conglomeratic, Metavolcanics, Limestones, Diorites and Andesites
IK-10		Moderately to highly weathered fossiliferous LIMESTONE
IK-12		Moderately to highly weathered ANDESITE
IK-19		Moderately weathered, slightly jointed ANDESITE

SUMMARY OF SEISMIC REFRACTION (KENNON ROAD) (2)

SPOT NO.	Results of seismic refraction survey Scale Hor. 1:200 m Vert. 1:100 m All velocities in M/sec.	Description
IK-21	<p>ELEV 100 --                      118 -- 530                      110 --                      107 -- 1300                      104 --                      103 -- 3000                      102 --                      101 -- 3000                      100 -- 3000                      ASSUME ELEV. = 100 M.</p>	Moderately weathered, highly jointed, a livegray DIORITE
IK-23	<p>ELEV 1245 --                      1244 -- 200                      1243 -- 2150                      1242 -- 2150</p>	Slightly to moderately weathered DIORITE
IK-29	<p>ELEV 857 --                      856 -- 350                      855 -- 750                      854 -- 1200                      853 -- 3000                      852 -- 1020                      851 -- 2750                      850 -- 3000                      848 -- 3000</p>	Highly weathered, highly jointed ANDESITE
IK-34	<p>ELEV 1090 --                      1089 -- 250                      1088 -- 350                      1087 -- 1100                      1086 -- 2740                      1085 -- 1250                      1084 -- 2400</p>	Highly to moderately weathered, highly jointed ANDESITE

SUMMARY OF SEISMIC REFRACTION (KENNON ROAD) (3)

SPOT NO.	Results of seismic refraction survey	Description
IK-38	<p>Scale Hor. 1:200 m Vert. 1:100 m</p> <p>All velocities in M/sec</p> 	Highly jointed, slightly weathered Sedimentary Facies
IK-41	 <p>ASSUME ELEV. = 100 M.</p>	Slightly weathered to moderately weathered ANDESITE

Appendix 10-2 Realignment of Critical Sections

1. Km. 1,010 + 700 in Mahaplag-Sogod Section, Mahalika Highway


A short section at Km. 1,010 + 700 (spots VIII-80 and 81) in Mahaplag-Sogod Section is subjected to the largest scale of cut slope failure and embankment slope failure.


Two (2) alternative plans were studied to come up with the optimum solution on this special section: one is to provide slope protection work on the existing slopes, thus increasing stability of the existing slopes and the other is to realign a road center line to avoid disaster potential spots. In the latter plan, the road center line was shifted towards valley side and the valley was spanned by a bridge (see Figure on next page). Rough construction costs of two plans were estimated as follows;

		Unit : Million Pesos	
Plan-1		Plan-2	
Slope Protection of Existing Slopes		Realignment	
Embankment	8.8	Superstructure	38.0
Vegetation on embankment slopes	0.8	Substructure	15.0
Re-cutting (gravel)	7.1	Approach	1.2
Re-cutting (soft rock)	5.7		
Vegetation on cut slopes	1.1		
Underground drainage	1.4		
Others	2.2		
<b>Total</b>	<b>27.1</b>		<b>54.2</b>

As Plan-2 requires a bridge of 270 meters in length with piers of 70 meters in height, construction cost of Plan-2 is more expensive by about double than Plan-1. Plan-1 which is slope protection of existing slopes was recommended for adoption to the preliminary design.








2. Section between Km. 239 + 830 and Km. 240 + 240, Kennon Road

Quite steep and high cut slopes continue along this section which contains four (4) disaster spots of IK-39, 40, 41 and 42. In addition to a plan to provide slope protection works on the existing slopes, a route realignment plan was considered. New alignment was selected on the opposite side of the Bued River. New alignment has length of 343 meters which is shorter by about 70 meters than the existing route, however, new alignment has to cross the Bued River twice requiring two bridges. It also requires high cut slopes of about 25 meters in height (see Figure on next page).


Construction costs of two plans were roughly estimated as follows;

		Unit : Million Pesos	
Plan-1		Plan-2	
Slope Protection of Existing Slopes		Realignment	
IK-39	1.0	Two bridges (L = 74 meters)	
IK-40	0.3	Superstructure	3.5
IK-41	0.8	Substructure	1.8
IK-42	0.2	New road (L = 269 meters)	1.9
Total	2.3		7.2

Plan-2, realignment plan is more expensive by about 3 times than Plan-1. Plan-1, slope protection of existing slopes was recommended.



PLAN SCALE 1:100



NOTE : ALL DIMENSIONS ARE IN MILLIMETER

ELEVATION

APPENDIX 10-3  
STABILITY CALCULATIONS

A) Stability Calculation for Slope failure at Disaster

Spot No. VIII - 80/81 (Mahaplag - Sogod Section  
Leyte)


Computed by Micro-Computer

B) Stability Calculation for Landslide at Disaster

Spot No. IK- 48 (Kennon Road)

1. Dimension of Slope
2. Computation of Stability
3. Acting Force on Pile
- 4 Design of Pile

A) STABILITY CALCULATION (Disaster Spot No. VII - 80/81)



1 Case 1

$R = 500$

$F.S = 1.0 \longrightarrow \tan \phi = 1.41 \text{ and } c = 0.0 \text{ t/m}^2 \text{ or}$   
 $\tan \phi = 0.00 \text{ and } c = 13.16 \text{ t/m}^2$

2 Case 2

$R = 500$

$\left. \begin{matrix} \tan \phi = 0.87 \\ c = 5.00 \text{ t/m}^2 \end{matrix} \right\} \longrightarrow F.S = 1.0$

3 Case 3


$R = 300$

$\left. \begin{matrix} \tan \phi = 0.87 \\ c = 5.00 \text{ t/m}^2 \end{matrix} \right\} \longrightarrow F.S = 0.95$

4 Case 4

$R = 300$

$F.S = 1 \longrightarrow \tan \phi = 1.64 \text{ and } c = 0.00 \text{ t/m}^2$   
 $\tan \phi = 0.00 \text{ and } c = 11.75 \text{ t/m}^2$



4 Case 5

$R = 300$

After Removal

$\left. \begin{matrix} \tan \phi = 1.29 \\ c = 2.5 \text{ t/m}^2 \end{matrix} \right\} \longrightarrow F.S = 1.14 > 1.1$



TITLE:LEYTE CASE - 1

WATER LEVEL 1

FAILURE CIRCLE			FORCES			FACTOR OF SAFETY		
X0 (M)	Y0 (M)	RADIUS (M)	COHESION (T*M)	FRICTION (T*M)	DRIVING (T*M)	SAFETY	TAN(F)	C (T/M**2)
28.00	533.00	500.00	0.00	X1918586.00	X1918586.00	1.00		1.41 0.00
28.00	533.00	500.00	X1918586.00	0.00	X1918586.00	1.00		0.00 13.16

TITLE:LEYTE CASE - 2

COORDINATES OF GRAND SURFACE

(100.0, 0.0) (151.0, 48.0) (178.0, 57.0) (214.0, 86.0) (237.0, 98.0)  
 (258.0, 122.0) (294.0, 120.0) (302.0, 132.0) (321.0, 148.0) (344.0, 174.0)  
 (400.0, 200.0) (550.0, 200.0)

COORDINATES OF LAYER BOUNDARY

( 0.0, X-100.0) (550.0, X-100.0) DEN(T/M\*\*3) 1.30 COH(T/M\*\*2) 5.00 FRI(DES) 0.87

GRAND OF WATER LEVEL 1

FAILURE CIRCLE			FORCES			FACTOR OF SAFETY		
X0 (M)	Y0 (M)	RADIUS (M)	COHESION (T*M)	FRICTION (T*M)	DRIVING (T*M)	SAFETY	TAN(F)	C (T/M**2)
28.00	533.00	500.00	729041.30	X1182859.00	X1918586.00	1.00		

TITLE:LEYTE CASE - 3

COORDINATES OF GRAND SURFACE

(100.0, 0.0) (294.0, 120.0) (302.0, 132.0) (321.0, 148.0) (344.0, 174.0)  
 (400.0, 200.0) (550.0, 200.0)

COORDINATES OF LAYER BOUNDARY

( 0.0, X-100.0) (550.0, X-100.0) DEN(T/M\*\*3) 1.50 COH(T/M\*\*2) 5.00 FRI(DES) 0.87

GRAND OF WATER LEVEL 1

FAILURE CIRCLE			FORCES			FACTOR OF SAFETY		
X0 (M)	Y0 (M)	RADIUS (M)	COHESION (T*M)	FRICTION (T*M)	DRIVING (T*M)	SAFETY	TAN(F)	C (T/M**2)
171.00	392.00	298.00	185161.80	242850.50	458663.20	0.95		

TITLE:LEYTE CASE 4

WATER LEVEL 1

FAILURE CIRCLE			FORCES			FACTOR OF SAFETY		
X0 (M)	Y0 (M)	RADIUS (M)	COHESION (T*M)	FRICTION (T*M)	DRIVING (T*M)	SAFETY	TAN(F)	C (T/M**2)
171.00	392.00	298.00	0.00	458663.20	458663.20	1.00		1.64 0.00
171.00	392.00	298.00	458663.20	0.00	458663.20	1.00		0.00 11.75

TITLE:LEYTE 8/80/81 CASE 5

COORDINATES OF GRAND SURFACE

(100.0, 0.0) (294.0, 120.0) (302.0, 132.0) (321.0, 148.0) (344.0, 174.0)  
 (374.0, 174.0) (400.0, 200.0) (550.0, 200.0)

COORDINATES OF LAYER BOUNDARY


( 0.0, X-100.0) (550.0, X-100.0) DEN(T/M\*\*3) 1.80 COH(T/M\*\*2) 2.50 FRI(DES) 1.29

GRAND OF WATER LEVEL 1

FAILURE CIRCLE			FORCES			FACTOR OF SAFETY		
X0 (M)	Y0 (M)	RADIUS (M)	COHESION (T*M)	FRICTION (T*M)	DRIVING (T*M)	SAFETY	TAN(F)	C (T/M**2)
171.00	392.00	298.00	89557.37	272872.20	318703.50	1.14		


B) STABILITY CALCULATION (Disaster Spot No. IK-48)

Dimension of Slope



## 2. Computation of Stability

Computation Table of Stability Check



Slice No.	Area of Trapezium A (m <sup>2</sup> )	Unit Weight of soil γ <sub>s</sub> (t/m <sup>3</sup> )	Weight of Slices W (t/m)	Degree θ	W · Sin θ (t/m)	W · Cos θ (t/m)	l (m)
1	1/2 (0.0+14.0) X 15.0	1.7	178.5	47.5	131.6	120.6	20.5
2	1/2 X (14.0+14.5) X 9.5	1.7	230.1	5.0°	20.1	229.2	9.54
3	1/2 X (10.0+13.5) X 28.5	1.7	569.3	5.0°	49.6	567.1	28.6
4	1/2 X (13.5+7.8) X 36.5	1.7	660.8	5.0	57.6	658.3	36.6
5	1/2 X (7.8+8.0) X 31.5	1.7	423.0	5.0°	36.9	421.4	31.6
6	1/2 X (8.0+9.0) X 16.5	1.7	238.4	5.0°	20.8	239.5	16.6
7	1/2 X (9.0+7.0) X 34.0	1.7	462.4	5.0°	40.3	460.6	34.1
8	1/2 X (7.0+5.2) X 16.5	1.7	171.1	5.0°	14.9	170.4	16.6
9	1/2 X (5.2+0.0) X 10.5	1.7	46.4	5.0°	4.0	46.2	10.5
Total					375.8	2911.3	204.9

If Factor of Safety = 1.0

$$F.S = \frac{C \times \sum l + \tan \phi \times W \cdot \cos \theta}{W \cdot \sin \theta}$$

C: Cohesion of Soil (t/m<sup>2</sup>)


φ: Angle of Internal friction (degree)

$$F.S = 1$$

$$1 = \frac{C \times 204.9 + \tan \phi \times 2911.3}{375.8}$$

$$C = 0 \rightarrow \tan \phi = 0.129 \quad (\phi = 7.4^\circ)$$

$$\tan \phi = 0 \rightarrow C = 1.834 \text{ t/m}^2$$



$$C = 1.20 \text{ t/m}^2 \rightarrow \tan \phi = 0.045 \quad (\phi = 2.56^\circ)$$

### 3 Acting Force on Pile

$$F.S_{(p)} = \frac{C \times \Sigma l + \tan \phi \times W \cdot \cos \theta + P}{W \cdot \sin \theta}$$

P; Acting Force on Pile (t/m)

F.S<sub>(p)</sub>; Proposed Factor of Safety (1.1)

$$C = 1.1 \text{ t/m}^2$$

$$\tan \phi = 0.045$$

$$\Sigma l = \text{Slices } \textcircled{1} + \textcircled{2} + \textcircled{3} = 58.94$$

$$W \cdot \cos \theta = \text{Slices } \textcircled{1} + \textcircled{2} + \textcircled{3} = 916.9$$

$$W \cdot \sin \theta = \text{Slices } \textcircled{1} + \textcircled{2} + \textcircled{3} = 201.3$$

$$1.1 = \frac{1.20 \times 58.94 + 0.045 \times 916.9 + P}{201.3}$$


$$P = 129.6 \text{ t/m}$$

Interval of Piles 4.0 meters

$$P = 129.6 \text{ t/m} \times 4 \text{ m} = 518.3 \text{ t/pile}$$

P; Acting Force on One Pile

### 4 Design of Pile



Acting Force on Pile

$$P = 518.3 \text{ ton}$$

Use Chang's Formula

Co-efficient of Horizontal Subgrade

reaction Kh

$$K_h = \alpha \cdot E_o \cdot D^{-\frac{3}{4}}$$

$\alpha$ ; Constance (= 0.2)

$$E_o = 28 \cdot N \text{ (kg/cm}^2\text{)}$$

N; No. of Blows by S.P.T. (= 40)

D; Diameter of Pile (240cm)

$$K_h = 0.2 \times 28 \times 40 \times 240^{-\frac{3}{4}} = 3.7 \text{ kg/cm}^3$$

E; Young Modulus of Pile  $2.8 \times 10^5 \text{ kg/cm}^2$

I; Inertia of Pile

$$I = \frac{1}{64} \times \pi \times D^4 = \frac{1}{64} \times \pi \times 240^4 = 1.63 \times 10^8 \text{ cm}^4$$

$$B = \sqrt[4]{\frac{K \cdot D}{4 EI}}$$

$$= \sqrt[4]{\frac{3.7 \times 240}{4 \times 2.8 \times 10^5 \times 1.63 \times 10^8}} = 0.001485 \text{ cm}^{-1}$$

Embedment length under Sliding Surface

$$l \geq 2.5/\beta$$

$$= 2.5/0.001485 = 1684 \text{ cm} = 16.8 \text{ m}$$

Total pile length  $13.5 + 16.8 \approx 30 \text{ meter}$

Sectional force due to Acting force on pile

$$M_{\max} = \frac{\sqrt{(1+2\beta h_0)^2 + 1}}{2\beta h_0} \exp\left[-\tan^{-1} \frac{1}{1+2\beta h_0}\right] \times M_0$$

$M_{\max}$ ; Max. Moment

$M_0$ ; Bending Moment at Sliding Surface

$h_0$ ; Height from Sliding Surface to point of Acting Force

$$M_0 = 518.3 \text{ ton} \times 4.5 \text{ meters} = 2332.4 \text{ t}\cdot\text{m}$$

$$M_{\max} = 2958 \text{ t}\cdot\text{m}$$

$$S = 518.3 \text{ ton}$$

$S$ ; Shearing Force

Computation of Sectional Stresses

Diameter of Pile 240 cm

Covering of Reinforcement 15 cm

Steel Reinforcement Used

$$A_s = 3\text{-D32-@ 15cm}$$

$$= 3 \times 7.942 \times 44 = 1048.3 \text{ cm}^2$$

( $n = E_s/E_c = 15$ )

$$np = n \times \frac{A_s}{\pi \cdot y^2} = 15 \times \frac{1048.3}{\pi \times 240^2} = 0.09$$

$$\begin{aligned} \rightarrow S = 6.5 \\ C = 2.5 \\ z = 0.43 \end{aligned} \left. \begin{array}{l} \text{Refer to} \\ \text{Reinforced Concrete} \\ \text{homogram} \end{array} \right\}$$

$$\begin{aligned} \sigma_c &= \frac{M}{I} \times C \\ &= \frac{2958 \times 10^5}{240^3} \times 2.5 = 53 \text{ kg/cm}^2 < 70 \text{ kg/cm}^2 \\ &\quad \times 1.5 = 105 \text{ kg/cm}^2 \end{aligned}$$

$$\begin{aligned} \sigma_s &= \frac{M}{I} \times S \times n \\ &= \frac{2958 \times 10^5}{240^3} \times 6.5 \times 15 = 2086 \text{ kg/cm}^2 \\ &\quad < 1800 \times 1.5 = 2700 \text{ kg/cm}^2 \end{aligned}$$

$$\begin{aligned} \tau &= \frac{S}{I} \times z \\ &= \frac{518.3}{240} \times 0.43 = 3.9 \text{ kg/cm}^2 \\ &\quad < 6.0 \times 1.5 = 9.0 \text{ kg/cm}^2 \end{aligned}$$

APPENDIX 10-4 Condition of Disaster and Selected Countermeasures DALTON PASS SECTION (1)

No.	Disaster Spot No.	Km Type of Disaster	Existing Slope Condition			Factor for selection of countermeasure	Countermeasure	Remarks
			Dimension of slope	Geological Condition	Water Condition			
1	III-4(a)	167+300 E-DF	<p>W = 50 m.</p>	<ul style="list-style-type: none"> <li>Embankment material</li> </ul>	<ul style="list-style-type: none"> <li>Concentration of road surface water</li> </ul>	<ul style="list-style-type: none"> <li>Re-filling should be done</li> <li>Surface water flows on the slope.</li> <li>Slope is steep and new side ditch should be placed.</li> </ul>	<ul style="list-style-type: none"> <li>Re-filling</li> <li>Stone masonry</li> <li>Side ditch</li> </ul>	<ul style="list-style-type: none"> <li>Existing stone masonry was destroyed due to road surface water</li> </ul>
2	III-4(b)	167+400 C-F	<p>W = 280 m.</p>	<ul style="list-style-type: none"> <li>Diorite</li> <li>Slightly weathered.</li> <li>Developed crack</li> </ul>	<ul style="list-style-type: none"> <li>No surface water concentration.</li> </ul>	<ul style="list-style-type: none"> <li>Some detached rocks exist on the slope.</li> <li>Cracked rocks.</li> <li>Progress of weathering is anticipated.</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Concrete spraying (I=10)</li> </ul>	
3	III-4(c)	167+600 C-F	<p>W = 180 m.</p>	<ul style="list-style-type: none"> <li>Diorite</li> <li>Slightly weathered</li> <li>Highly developed cracks</li> </ul>	<ul style="list-style-type: none"> <li>No surface water concentration</li> </ul>	<ul style="list-style-type: none"> <li>Detached rocks exist on the slope.</li> <li>Progress of weathering is anticipated.</li> <li>Many cracks and joints</li> <li>More developed cracks than the cracks of spot III-4(b).</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Concrete spraying (I=15)</li> </ul>	
4	III-5	167+850 E-DF	<p>W = 20 m.</p>	<ul style="list-style-type: none"> <li>Embankment material</li> </ul>	<ul style="list-style-type: none"> <li>Existing pipe culvert.</li> </ul>	<ul style="list-style-type: none"> <li>Apron, headwall and wingwall of pipe culvert outlet were destroyed.</li> <li>No restoration work was implemented.</li> </ul>	<ul style="list-style-type: none"> <li>Re-filling of Pipe culvert</li> <li>Apron for culvert</li> <li>Stone masonry</li> <li>Vertical ditch</li> </ul>	<ul style="list-style-type: none"> <li>Only a half lane of the roadway is passable.</li> </ul>

DALTON PASS SECTION (2)

CONDITION OF DISASTER AND SELECTED COUNTERMEASURES

No.	Disaster Spot No.	Km Type of Disaster	Existing Slope Condition		Water Condition	Factor for selection of countermeasure	Countermeasure	Remarks
			Dimension of slope	Geological Condition				
5	III-6	167+900 C-SF	<p style="text-align: center;">W = 50 m.</p>	<ul style="list-style-type: none"> <li>Diorite</li> <li>Highly and totally weathered in some parts of the slope</li> <li>Highly developed crack</li> </ul>	<ul style="list-style-type: none"> <li>Slope surface water flows on the slope and a little concentration of surface water exists.</li> </ul>	<ul style="list-style-type: none"> <li>Some unstable materials shall be removed due to local weathering in some parts of the slope.</li> <li>Slope gradient is not so steep.</li> <li>Scouring of slope surface water and progress of weathering is anticipated.</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Concrete spraying (t=15 cm)</li> </ul>	<ul style="list-style-type: none"> <li>The bottom of the slope is in the toe of the ridge.</li> <li>It is useless to provide top slope ditch.</li> </ul>
6	III-7	168+100 C-SF	<p style="text-align: center;">W = 140 m.</p>	<ul style="list-style-type: none"> <li>Andesite</li> <li>Highly to moderately weathered rock.</li> <li>Highly developed cracks</li> </ul>	<ul style="list-style-type: none"> <li>Slope surface water flows on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>Some totally weathered rocks should be removed.</li> <li>Slope gradient is nearly optimum.</li> <li>Scouring of surface water and progress of weathering is anticipated.</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Concrete spraying (t=10 cm)</li> </ul>	
7	III-10	170+400 D.F	<p style="text-align: center;">W = 140 m.</p>	<ul style="list-style-type: none"> <li>Sandstone</li> <li>Slightly weathered</li> </ul>	<ul style="list-style-type: none"> <li>Water from hinterland runs at a hollow on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>The amount of debris is less than 50 cu.m.</li> <li>Debris flows out from the hollow of the slope during rainy days.</li> </ul>	<ul style="list-style-type: none"> <li>Small Sabo-dam</li> <li>Waterway</li> </ul>	
8	III-11	170+700 E-D.F	<p style="text-align: center;">W = 11 m.</p>	<ul style="list-style-type: none"> <li>Embankment materials</li> </ul>	<ul style="list-style-type: none"> <li>Concentration of road surface water</li> <li>Road surface water saturates into the embankment materials</li> </ul>	<ul style="list-style-type: none"> <li>Embankment slope shall be protected by the structures.</li> <li>Poor drainage facilities on the roadway</li> </ul>	<ul style="list-style-type: none"> <li>Re-filling</li> <li>Stone pitching</li> <li>Side ditch</li> </ul>	<ul style="list-style-type: none"> <li>Grouted riprap was destroyed due to road surface water.</li> </ul>

DALTON PASS SECTION (3)

CONDITION OF DISASTER AND SELECTED COUNTERMEASURES

No.	Disaster Spot No.	Km Type of Disaster	Existing Slope Condition			Water Condition	Factor for selection of countermeasure	Countermeasure	Remarks
			Dimension of slope	Geological Condition	Water Condition				
9	III-12	170+750 C-F	<p>Anchor wire net 67° W = 158 m.</p>	<ul style="list-style-type: none"> <li>Andesite</li> <li>Moderately weathered</li> <li>Many jointed and cracked rocks</li> </ul>	<ul style="list-style-type: none"> <li>A little influence of slope surface water on the spot.</li> </ul>	<ul style="list-style-type: none"> <li>Some detached rocks exist on the slope.</li> <li>Size of falling rocks is like a cobble stone.</li> <li>A little progress of weathering is due to the small influence of surface water.</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Anchor wire net</li> </ul>	<ul style="list-style-type: none"> <li>Catch fence can not be applied due to an anticipated big falling rocks.</li> </ul>	
10	III-14	171+200 C-S.F	<p>Sprayed concrete crib 45° W = 119 m.</p>	<ul style="list-style-type: none"> <li>Schist/Andesite</li> <li>Highly and totally weathered in some parts of the slope</li> <li>Highly cracked</li> </ul>	<ul style="list-style-type: none"> <li>Some seepage of water occurs when surface water flows on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>Some unstable materials exist on the slope.</li> <li>Progress of weathering is anticipated due to slope surface water.</li> <li>Scouring is caused by slope surface water.</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Sprayed concrete crib with boulders and with concrete wall.</li> </ul>		
11	III-15	172+500 D.F	<p>Concrete sabo-dam Stone pitching water way 25° W = 20m + 10m.</p>	<ul style="list-style-type: none"> <li>Andesite</li> <li>Moderately weathered</li> </ul>	<ul style="list-style-type: none"> <li>Water from hilted runs at the two hollows on the slope.</li> <li>Slope surface water concentrates at upper part of the two hollows</li> </ul>	<ul style="list-style-type: none"> <li>Some debris flows out from two hollows during rainy days.</li> </ul>	<ul style="list-style-type: none"> <li>Small Sabo - Dam</li> <li>Water way</li> <li>Pipe culvert</li> </ul>		
12	III-18	173+450 D.F	<p>Concrete sabo-dam Stone pitching water way 20° W = 10 m.</p>	<ul style="list-style-type: none"> <li>Volcaniclastites</li> </ul>	<ul style="list-style-type: none"> <li>Slope surface water concentrates at one hollow on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>Some debris composed of gravel and sand flows out during rainy days.</li> <li>Amount of debris flow is about 100 cu.m.</li> </ul>	<ul style="list-style-type: none"> <li>Small Sabo-Dam</li> <li>Water way</li> </ul>		



CONDITION OF DISASTER AND SELECTED COUNTERMEASURES

DALTON PASS SECTION (4)

No.	Disaster Spot No.	Km Type of Disaster	Existing Slope Condition			Factor for selection of countermeasure	Countermeasure	Remarks
			Dimension of slope	Geological Condition	Water Condition			
13	III-19	173+650 C-S.F	<p>Concrete spraying 55° 40° W = 20 m</p>	<ul style="list-style-type: none"> <li>• Volcaniclastics</li> <li>• Moderately weathered</li> </ul>	<ul style="list-style-type: none"> <li>• A little influence exists due to slope surface water.</li> </ul>	<ul style="list-style-type: none"> <li>• Progress of weathering is anticipated.</li> <li>• Slope surface failure occurs due to some unstable materials on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>• Removal.</li> <li>• Concrete spraying (t=10cm)</li> </ul>	
14	III-22(a)	185+450 C-S.F	<p>Vegetation on Re-cutting 60° 45° No protection W = 40 m</p>	<ul style="list-style-type: none"> <li>• Highly weathered DIORITE.</li> <li>• Terrace Deposit (Sand and gravel)</li> </ul>	<ul style="list-style-type: none"> <li>• Water from hinterland flows on the slope and a concentration of slope surface water occurs.</li> </ul>	<ul style="list-style-type: none"> <li>• Upper layer of the slope is Terrace deposit.</li> <li>• No drainage facilities on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>• Re-cutting.</li> <li>• Berm and Vertical ditch.</li> <li>• Vegetation.</li> </ul>	
15	III-22(b)	185+500 C-S.F	<p>Re-cutting Re-filling Gabion Retaining Wall 35° W = 75 m</p>	<ul style="list-style-type: none"> <li>• Totally weathered DIORITE (Nearly soil)</li> </ul>	<ul style="list-style-type: none"> <li>• Water from hinterland flows on the slope.</li> <li>• Slope surface water saturates into the slope.</li> <li>• The ground water level is high.</li> </ul>	<ul style="list-style-type: none"> <li>• No existing slope protection.</li> <li>• No drainage facility on the slope</li> <li>• Nearly soil</li> <li>• High ground level</li> </ul>	<ul style="list-style-type: none"> <li>• Re-cutting and Re-filling.</li> <li>• Vegetation</li> <li>• Berm and vertical ditch</li> <li>• Gabion Retaining wall</li> </ul>	
16	III-23	195+900 C-S.F	<p>Removal and Concrete spraying 60° 44° Concrete spraying W = 40 m</p>	<ul style="list-style-type: none"> <li>• Moderately to highly weathered DIORITE rocks with developed cracks.</li> </ul>	<ul style="list-style-type: none"> <li>• Slope surface water flows on the slope and a concentration of slope surface water occurs.</li> </ul>	<ul style="list-style-type: none"> <li>• Some unstable materials exist on the slope.</li> <li>• Progress of weathering is anticipated due to slope surface water</li> </ul>	<ul style="list-style-type: none"> <li>• Removal</li> <li>• Concrete spraying (t=10cm)</li> <li>• Top slope ditch</li> </ul>	

DALTON PASS SECTION (5)

CONDITION OF DISASTER AND SELECTED COUNTERMEASURES

No.	Disaster Spot No.	Km Type of Disaster	Existing Slope Condition			Factor for selection of countermeasure	Countermeasure	Remarks
			Dimension of slope	Geological Condition	Water Condition			
17	III-24	186+400 E-D.F	<p>Re-filling and vegs 2m 17m 30° W=70m</p>	<ul style="list-style-type: none"> <li>Embankment materials</li> </ul>	<ul style="list-style-type: none"> <li>Concentration of slope surface water exist</li> <li>Road surface water also saturates into the embankment materials.</li> </ul>	<ul style="list-style-type: none"> <li>Re-filling</li> <li>Vegetation</li> <li>Stone masonry</li> <li>Berm ditch</li> <li>Side ditch</li> </ul>		
18	III-25(a)	186+400 D-F	<p>Concret. Sabb-dam Stone pitching water way 10m 20° W=10m</p>	<ul style="list-style-type: none"> <li>Highly weathered DIORITE</li> </ul>	<ul style="list-style-type: none"> <li>Water from hinterland flows at one hollow on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>Concrete sabb dam</li> <li>Water way</li> </ul>		
19	III-25(b)	186+400 C-F	<p>Anchor wire net 50m 70° W=50m</p>	<ul style="list-style-type: none"> <li>Slightly to moderately weathered DACITE rock with regular cracks.</li> </ul>	<ul style="list-style-type: none"> <li>There is a little influence of slope surface water on the spot.</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Anchor wire net</li> </ul>		
20	III-26	186+600 D.F	<p>Concrete sabb-dam Stone pitching water way 30m 30° W=30m</p>	<ul style="list-style-type: none"> <li>Slightly weathered DIORITE.</li> </ul>	<ul style="list-style-type: none"> <li>Water from hinterland flows at one hollow on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>Concrete sabb dam</li> <li>Water way</li> </ul>		

DALTON PASS SECTION (6)

CONDITION OF DISASTER AND SELECTED COUNTERMEASURES

No.	Disaster Spot No.	Km Type of Disaster	Existing Slope Condition			Factor for selection of countermeasure	Countermeasure	Remarks
			Dimension of slope	Geological Condition	Water Condition			
21	III-28	187+300 C-S.F	<p>Re-cutting and vegetation Removal Repair work 50° 41° W=90 m.</p>	Slightly weathered DACITE rocks with sparse cracks	Slope surface water flows on the slope.	<ul style="list-style-type: none"> <li>Some unstable materials on the slope.</li> <li>No progress of weathering is anticipated for hard stable rocks.</li> <li>Soils overlie on the rocks at the top of the slope.</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Berm ditch</li> <li>Re-cutting</li> <li>Vegetation</li> <li>Top slope ditch</li> </ul>	<ul style="list-style-type: none"> <li>No slope protection required for the rock.</li> </ul>
22	III-30	187+800 C-S.F	<p>Re-cutting and vegetation Concrete spraying 50° 42° W=80 m.</p>	Moderately weathered DACITE rocks with developed cracks.	Slope surface water flows on the slope and a little concentration of slope surface water occurs.	<ul style="list-style-type: none"> <li>Progress of weathering is anticipated.</li> <li>Some unstable materials exist on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Concrete spraying (t=10 cm)</li> <li>Berm ditch</li> <li>Re-cutting</li> <li>Vegetation</li> </ul>	
23	III-31	188+000 C-S.F	<p>Re-cutting and vegetation Concrete spraying 54° 48° W=230 m.</p>	Moderately to highly weathered DACITE rocks with highly developed cracks.	A little concentration of surface water exist	<ul style="list-style-type: none"> <li>Weaker rocks than the rocks of spot III-30</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Concrete spraying (t=15 cm)</li> <li>Berm ditch</li> <li>Re-cutting</li> <li>Vegetation</li> </ul>	
24	III-32	188+100 E-D.F	<p>Re-filling Cast-in-place concrete crib Stone pitching 50° 35° W=35 m.</p>	Embankment materials	<ul style="list-style-type: none"> <li>Concentration of road surface water exists.</li> <li>Road surface water saturates into the embankment materials.</li> </ul>	<ul style="list-style-type: none"> <li>Poor drainage facilities exist</li> <li>No existing slope protection.</li> <li>Too steep and high slope</li> </ul>	<ul style="list-style-type: none"> <li>Re-filling</li> <li>Cast-in-place concrete crib with grass</li> <li>Stone pitching</li> <li>Gabion foot protection</li> </ul>	

DALTON PASS SECTION (7)

CONDITION OF DISASTER AND SELECTED COUNTERMEASURES

No.	Disaster Spot No.	Km Type of Disaster	Existing Slope Condition			Factor for selection of countermeasure	Countermeasure	Remarks	
			Dimension of slope	Geological Condition	Water Condition				
25	III-36	188+700 D.F	<p>Concrete scale-dam Stone pitching water way 40° W=10m.</p>	<ul style="list-style-type: none"> <li>Slightly weathered DIORITE.</li> </ul>	<ul style="list-style-type: none"> <li>Water from hinterland flows at a hollow on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>Concrete Saba-Dam.</li> <li>Waterway.</li> </ul>			
26	III-37	189+900 C-F	<p>Anchor wire net 53° 75° W=117m.</p>	<ul style="list-style-type: none"> <li>Moderately weathered DIORITE with highly developed cracks.</li> </ul>	<ul style="list-style-type: none"> <li>A little influence of slope surface water exists.</li> </ul>	<ul style="list-style-type: none"> <li>Slope is steep with stable rocks.</li> <li>Only falling rocks are anticipated.</li> </ul>	<ul style="list-style-type: none"> <li>Anchored wire net.</li> </ul>		
27	III-38(a)	190+000 C-S.F	<p>Concrete spraying 43° W=67m.</p>	<ul style="list-style-type: none"> <li>Highly weathered DIORITE rocks with highly developed cracks.</li> </ul>	<ul style="list-style-type: none"> <li>Slope surface water flows on the slope and a concentration of slope surface water occurs.</li> </ul>	<ul style="list-style-type: none"> <li>A little unstable soil is on the slope.</li> <li>A little progress of weathering occurs.</li> </ul>	<ul style="list-style-type: none"> <li>Concrete spraying (t = 10 cm.)</li> </ul>		
28	III-36(b)	190+050 D.F	<p>Stone pitching water way 20° W=10m.</p>	<ul style="list-style-type: none"> <li>Slightly weathered DIORITE.</li> </ul>	<ul style="list-style-type: none"> <li>Concentration of slope surface water exists.</li> <li>Water from hinterland flows at a hollow on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>Slope is stable and covered by trees and grasses.</li> </ul>	<ul style="list-style-type: none"> <li>Waterway.</li> </ul>		

DALTON PASS SECTION (8)

CONDITION OF DISASTER AND SELECTED COUNTERMEASURES

No.	Disaster Spot No.	Km. Type of Disaster	Existing Slope Condition			Factor for selection of countermeasure	Countermeasure	Remarks
			Dimension of slope	Geological Condition	Water Condition			
29	III-39	190+400 C-S.F	<p>Concrete spraying W = 50 m.</p>	<p>Highly weathered DIORITE rocks with regular cracks.</p>	<p>A little concentration of slope surface water exists.</p>	<p>Removal Concrete spraying (t = 10 cm.)</p>		
30	III-41	190+750 C-S.F	<p>Concrete spraying W = 70 m.</p>	<p>Highly weathered DIORITE rocks with highly developed cracks</p>	<p>Water from hinterland flows at two hollows on the slope. There is much concentration of slope surface water.</p>	<p>Removal Concrete spraying (t = 15 cm.) Top slope and Vertical ditch</p>		
31	III-42	190+850 D.F	<p>Concrete Sabo-dam stone pitching waterway W = 10 m.</p>	<p>DIORITE</p>	<p>Water from hinterland flows at a hollow on the slope.</p>	<p>Concrete Sabo-Dam Water way Box culvert</p>		
32	III-43	190+900 C-S.F	<p>Concrete spraying W = 70 m.</p>	<p>Highly weathered DIORITE rocks with highly developed cracks</p>	<p>Water from hinterland flows on the slope.</p>	<p>Concrete spraying (t = 15 cm.) Top slope and vertical ditch</p>		





CONDITION OF DISASTER AND SELECTED COUNTERMEASURES

DALTON PASS SECTION (3)

No.	Disaster Spot No.	Km Type of Disaster	Existing Slope Condition			Factor for selection of countermeasure	Countermeasure	Remarks
			Dimension of slope	Geological Condition	Water Condition			
33	III-46	192+700 C-S-F	<p>W=120 m.</p>	Highly weathered DACITE rocks with highly developed cracks and fractures.	Water from hinterland flows on the slope.	<ul style="list-style-type: none"> <li>Removal</li> <li>Sprayed concrete crib with concrete wall.</li> <li>Re-cutting</li> <li>Vegetation</li> <li>Top slope ditch.</li> </ul>		
34	III-47(a)	192+850 C-S-F	<p>W=50 m.</p>	Slightly weathered DACITE rocks with developed cracks.	Water from hinterland flows on the slope.	<ul style="list-style-type: none"> <li>Removal</li> <li>Top slope ditch.</li> <li>Re-cutting</li> <li>Vegetation</li> </ul>	No slope protection is required for rocks on the slope.	
35	III-47(b)	193+000 C-S-F	<p>W=85 m.</p>	Highly weathered DACITE rocks with highly developed cracks and fractures.	A little concentration of slope surface water exists.	<ul style="list-style-type: none"> <li>Removal</li> <li>Sprayed concrete crib with concrete wall.</li> <li>Berm ditch.</li> <li>Re-cutting</li> <li>Vegetation</li> </ul>		
36	III-48	193+300 E-D-F	<p>W=10 m.</p>	Embankment materials.	Scouring is caused by water coming from the outlet of pipe culvert. River was scoured at the toe of the slope.	<ul style="list-style-type: none"> <li>Stone masonry.</li> <li>Gabion foot protection.</li> </ul>		

DALTON PASS SECTION (10)

CONDITION OF DISASTER AND SELECTED COUNTERMEASURES

No.	Disaster Spot No.	Km Type of Disaster	Existing Slope Condition			Factor for selection of countermeasure	Countermeasure	Remarks
			Dimension of slope	Geological Condition	Water Condition			
37	III-50	194+400 D.F	 <p>Stone pitching water way and gravity type retaining wall.</p> <p>W=100 m.</p>	<ul style="list-style-type: none"> <li>Colluvial soil (Debris)</li> </ul>	<ul style="list-style-type: none"> <li>Water from hinterland flows at several hollows on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>No drainage facilities on the slope.</li> <li>The slope is covered by trees and grasses and can be seen stable.</li> </ul>	<ul style="list-style-type: none"> <li>Water way</li> <li>Gravity type retaining wall.</li> </ul>	
38	III-51	195+600 C-F	 <p>W=80 m.</p>	<ul style="list-style-type: none"> <li>Moderately to highly weathered DACITE rocks with highly developed cracks.</li> </ul>	<ul style="list-style-type: none"> <li>A little influence exist due to slope surface water.</li> </ul>	<ul style="list-style-type: none"> <li>Progress of weathering is anticipated.</li> <li>Slope is just an optimum gradient.</li> <li>Some detached rocks exist on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Concrete spraying (t = 15 cm.)</li> </ul>	
39	III-53	195+850 D.F	 <p>Concrete sabo-dam</p> <p>Stone pitching water way</p> <p>W=20 m.</p>	<ul style="list-style-type: none"> <li>Slightly weathered DIORITE.</li> </ul>	<ul style="list-style-type: none"> <li>Water from hinterland flows at a hollow on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>Some debris exist on the slope.</li> <li>No drainage structure crosses the roadway.</li> </ul>	<ul style="list-style-type: none"> <li>Concrete Sabo-Dam.</li> <li>Water way</li> <li>Concrete box culvert.</li> </ul>	
40	III-54	195+900 C-S.F	 <p>Re-cutting and vegetation</p> <p>W=50 m.</p>	<ul style="list-style-type: none"> <li>Totally weathered DIORITE (nearly soil)</li> </ul>	<ul style="list-style-type: none"> <li>Slope surface water saturate into the ground.</li> </ul>	<ul style="list-style-type: none"> <li>Slope gradient is steeper than the optimum.</li> <li>No drainage on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>Re-cutting.</li> <li>Vegetation.</li> <li>Berm ditch.</li> </ul>	

CONDITION OF DISASTER AND SELECTED COUNTERMEASURES

DALTON PASS SECTION (II)





No.	Disaster Spot No.	Km. Type of Disaster	Existing Slope Condition			Factor for selection of countermeasure	Countermeasure	Remarks *
			Dimension of slope	Geological Condition	Water Condition			
41	III-55	196+050 C-S.F	<p>W = 100 m.</p>	<ul style="list-style-type: none"> <li>Totally weathered DIORITE (Nearly soil)</li> </ul>	<ul style="list-style-type: none"> <li>Water from hinterland flows on the slope and a little concentration of water occurs.</li> </ul>	<ul style="list-style-type: none"> <li>Slope gradient is not optimum.</li> <li>Slope failure exist due to the absence of slope protection.</li> </ul>	<ul style="list-style-type: none"> <li>Re-cutting</li> <li>Vegetation</li> <li>Top slope ditch and berm ditch.</li> </ul>	
42	III-56	196+100 C-D.F	<p>W = 120 m.</p>	<ul style="list-style-type: none"> <li>Totally weathered DIORITE (Nearly Soil)</li> </ul>	<ul style="list-style-type: none"> <li>Concentration of slope surface water exists.</li> </ul>	<ul style="list-style-type: none"> <li>Slope gradient is a little bit steeper than the optimum</li> <li>Slope deep failure exists due to the concentration of surface water.</li> </ul>	<ul style="list-style-type: none"> <li>Re-cutting</li> <li>Vegetation</li> <li>Top slope ditch and vertical ditch</li> </ul>	
43	III-61	197+700 O.F	<p>Concrete box culvert</p>	<ul style="list-style-type: none"> <li>Embankment materials</li> </ul>	<ul style="list-style-type: none"> <li>Water from hinterland concentrates at this place.</li> </ul>	<ul style="list-style-type: none"> <li>Lock of drainage facilities causes the water to cross over the roadway.</li> </ul>	<ul style="list-style-type: none"> <li>Concrete Box culvert (double barrel)</li> </ul>	
44	III-65	203+450 C-S.F	<p>W = 65 m.</p>	<ul style="list-style-type: none"> <li>Highly weathered ANDESITE</li> <li>Fractured and highly developed cracks</li> </ul>	<ul style="list-style-type: none"> <li>Surface water flows on the slope and a little seepage of water occurs.</li> </ul>	<ul style="list-style-type: none"> <li>Very weak soft rock</li> <li>Much progress of weathering occurs due to surface water and seepage of water.</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Sprayed concrete crib with boulders</li> <li>Berm ditch</li> </ul>	<ul style="list-style-type: none"> <li>The proposed Dalton Pass Tunnel Project starts from this spot</li> <li>Same countermeasures shown in left column.</li> </ul>

\* Countermeasures shown in Remarks are to be considered as countermeasures in long term.



DALTON PASS SECTION (12)

CONDITION OF DISASTER AND SELECTED COUNTERMEASURES

No.	Disaster Spot No.	Km Type of Disaster	Existing Slope Condition			Factor for selection of countermeasure	Countermeasure	Remarks*
			Dimension of slope	Geological Condition	Water Condition			
45	III-66(a)	203+550 C-S.F	 <p>W = 40 m.</p>	<ul style="list-style-type: none"> <li>Highly and totally weathered ANDESITE with developed cracks in some parts of the slope. (Nearly soil)</li> </ul>	<ul style="list-style-type: none"> <li>A little concentration of slope surface water exists.</li> </ul>	<ul style="list-style-type: none"> <li>Re-cutting</li> <li>Vegetation</li> <li>Berm ditch</li> </ul>	<ul style="list-style-type: none"> <li>Re-cutting</li> <li>Concrete spraying (t=10cm)</li> <li>Berm ditch</li> </ul>	
46	III-66(b)	203+850 D.F	 <p>W = 20 m.</p>	<ul style="list-style-type: none"> <li>River deposit</li> </ul>	<ul style="list-style-type: none"> <li>Small creek is approximately about 5.0 meters in width.</li> </ul>	<ul style="list-style-type: none"> <li>Water way</li> <li>Concrete sabo dam</li> </ul>	<ul style="list-style-type: none"> <li>Some countermeasures shown in left column</li> </ul>	
47	III-68	204+250 C-D.F	 <p>W = 95 m.</p>	<ul style="list-style-type: none"> <li>Highly to totally weathered DIABASE rocks in some parts of the slope. (Nearly soil)</li> </ul>	<ul style="list-style-type: none"> <li>Concentration of slope surface water exists.</li> </ul>	<ul style="list-style-type: none"> <li>Re-cutting</li> <li>Vegetation</li> <li>Berm ditch</li> </ul>	<ul style="list-style-type: none"> <li>Re-cutting</li> <li>Concrete spraying (t=10cm)</li> <li>Berm ditch</li> </ul>	
48	III-70	204+400 C-S.F	 <p>W = 50 m.</p>	<ul style="list-style-type: none"> <li>The slope is covered by soil with highly weathered DIABASE rocks.</li> </ul>	<ul style="list-style-type: none"> <li>Water from hinterland flows at a hollow on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>Top slope ditch</li> <li>Vertical ditch</li> </ul>	<ul style="list-style-type: none"> <li>Re-cutting</li> <li>Vegetation</li> <li>Berm ditch</li> </ul>	

\* Countermeasures shown in remarks are to be considered as countermeasures in long term.

DALTON PASS SECTION (13)

CONDITION OF DISASTER AND SELECTED COUNTERMEASURES

No.	Disaster Spot No.	Km Type of Disaster	Existing Slope Condition			Factor for selection of countermeasure	Countermeasure	Remarks
			Dimension of slope	Geological Condition	Water Condition			
49	III-72	204+800 C-S.F	<p style="text-align: center;">W = 70 m.</p>	<ul style="list-style-type: none"> <li>Highly to totally weathered DIABASE rocks in some parts of the slope. (Nearly soil)</li> </ul>	<ul style="list-style-type: none"> <li>A little concentration of slope surface water exists.</li> </ul>	<ul style="list-style-type: none"> <li>Sleep slope</li> <li>Totally weathered rocks are considered as soils.</li> </ul>	<ul style="list-style-type: none"> <li>Re-cutting</li> <li>Vegetation</li> <li>Berm ditch</li> </ul>	<ul style="list-style-type: none"> <li>Re-cutting</li> <li>Concrete spraying (t=10cm)</li> <li>Berm ditch</li> </ul>
50	III-73	205+000 C-S.F	<p style="text-align: center;">W = 50 m.</p>	<ul style="list-style-type: none"> <li>Highly and totally weathered ANDESITE rocks exist in some parts of the slope</li> </ul>	<ul style="list-style-type: none"> <li>A little concentration of slope surface water.</li> </ul>	<ul style="list-style-type: none"> <li>Slope gradient is gentle.</li> <li>Very weak rocks covered the slope. (nearly soil)</li> </ul>	<ul style="list-style-type: none"> <li>Re-cutting</li> <li>Vegetation</li> <li>Berm ditch</li> </ul>	<ul style="list-style-type: none"> <li>Re-cutting</li> <li>Concrete spraying (t=10cm)</li> <li>Berm ditch</li> </ul>
51	III-75	205+900 C-D.F	<p style="text-align: center;">W = 90 m.</p>	<ul style="list-style-type: none"> <li>Highly weathered DIABASE</li> <li>Highly jointed and developed cracks</li> </ul>	<ul style="list-style-type: none"> <li>A little influence due to surface water</li> </ul>	<ul style="list-style-type: none"> <li>Slope gradient is optimum</li> <li>Progress of weathering is anticipated.</li> </ul>	<ul style="list-style-type: none"> <li>Concrete spraying (t = 10 cm)</li> </ul>	<ul style="list-style-type: none"> <li>Concrete spraying (t = 15 cm)</li> </ul>
52	III-76	206+000 C-D.F	<p style="text-align: center;">W = 160 m.</p>	<ul style="list-style-type: none"> <li>Highly to totally weathered DIABASE</li> </ul>	<ul style="list-style-type: none"> <li>Water from hinterland flows on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>Berms exist on the slope but no ditches on the berm.</li> <li>Cut slope gradient is optimum</li> <li>No slope protection</li> </ul>	<ul style="list-style-type: none"> <li>Vegetation</li> <li>Berm ditch</li> <li>Stone masonry</li> </ul>	<ul style="list-style-type: none"> <li>Concrete spraying (t = 10cm)</li> <li>Berm ditch</li> <li>Slope masonry</li> </ul>

\* Countermeasures shown in Remarks are to be considered as countermeasures in long term.

CONDITION OF DISASTER AND SELECTED COUNTERMEASURES

DALTON PASS SECTION (14)

No.	Disaster Spot No.	Km Type of Disaster	Existing Slope Condition:			Factor for selection of countermeasure	Countermeasure	Remarks
			Dimension of slope	Geological Condition	Water Condition			
53	III-77	206+250 C-DF	<p>W = 87 m.</p>	<ul style="list-style-type: none"> <li>Moderately to highly weathered DIABASE with highly developed cracks.</li> </ul>	<ul style="list-style-type: none"> <li>A little concentration of slope surface water exists.</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Concrete spraying (1=15cm)</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Cast in place concrete crib</li> </ul>	
54	III-78	206+350 C-SF	<p>W = 80 m.</p>	<ul style="list-style-type: none"> <li>Moderately to highly weathered DIABASE with highly developed cracks.</li> </ul>	<ul style="list-style-type: none"> <li>A little concentration of slope surface water exists.</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Concrete spraying (1=15cm)</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Cast-in-place concrete crib</li> </ul>	
55	III-79	206+600 E-DF	<p>W = 70 m.</p>	<ul style="list-style-type: none"> <li>Embankment materials and highly weathered DIABASE</li> </ul>	<ul style="list-style-type: none"> <li>Much concentration of road surface water causes the road surface water to saturate into the ground.</li> </ul>	<ul style="list-style-type: none"> <li>Re-filling</li> <li>Cast-in-place concrete crib with grass</li> <li>Stone pitching</li> <li>Gabion foot protection</li> <li>Berm ditch and vertical ditch</li> </ul>	<ul style="list-style-type: none"> <li>Same countermeasures shown in left column</li> </ul>	
56	III-80	206+600 C-SF	<p>W = 240 m.</p>	<ul style="list-style-type: none"> <li>Highly weathered DIABASE</li> <li>Highly developed cracks and fractured in some parts of the slope</li> </ul>	<ul style="list-style-type: none"> <li>Water from hinterland flows on the slope and a little concentration of water occurs.</li> </ul>	<ul style="list-style-type: none"> <li>Vegetation</li> <li>Berm ditch and vertical ditch</li> <li>Stone masonry</li> </ul>	<ul style="list-style-type: none"> <li>Concrete Spraying</li> <li>Berm ditch and vertical ditch</li> <li>Stone masonry</li> </ul>	

\* Countermeasures shown in Remarks are to be considered as countermeasures in long term

CONDITION OF DISASTER AND SELECTED COUNTERMEASURES

DALTON PASS SECTION (15)

No.	Disaster Spot No.	Km Type of Disaster	Existing Slope Condition			Factor for selection of countermeasure	Countermeasure	Remarks *
			Dimension of slope	Geological Condition	Water Condition			
57	III-81	206+800 E-D.F	<p>W = 18m + 20m + 45m.</p>	<ul style="list-style-type: none"> <li>• Embankment materials</li> </ul>	<ul style="list-style-type: none"> <li>• Concentrated road surface water saturates into the ground.</li> </ul>	<ul style="list-style-type: none"> <li>• Re-filling</li> <li>• Supported type Retaining wall</li> <li>• Vertical ditch</li> <li>• Stone pitching</li> </ul>	<ul style="list-style-type: none"> <li>• Same countermeasures shown in left column</li> </ul>	
58	III-82	207+150 C-S.F	<p>W = 96m.</p>	<ul style="list-style-type: none"> <li>• Highly and totally weathered DIABASE in some parts of the slope. (Nearly soil)</li> </ul>	<ul style="list-style-type: none"> <li>• Concentration of the slope surface water exists.</li> </ul>	<ul style="list-style-type: none"> <li>• Re-cutting</li> <li>• Vegetation</li> <li>• Berm ditch and Vertical ditch</li> </ul>	<ul style="list-style-type: none"> <li>• Re-cutting</li> <li>• Concrete spraying (t=10cm)</li> <li>• Berm ditch and Vertical ditch</li> </ul>	
59	III-83	207+300 C-S.F	<p>W = 65m.</p>	<ul style="list-style-type: none"> <li>• Highly and totally weathered DIABASE in some parts of the slope (Nearly soil)</li> </ul>	<ul style="list-style-type: none"> <li>• A little concentration of slope surface water exists.</li> </ul>	<ul style="list-style-type: none"> <li>• Re-cutting.</li> <li>• Vegetation</li> <li>• Berm ditch</li> </ul>	<ul style="list-style-type: none"> <li>• Re-cutting</li> <li>• Concrete spraying (t=10cm)</li> <li>• Berm ditch</li> </ul>	
60	III-84	207+550 C-S.F	<p>W = 120m.</p>	<ul style="list-style-type: none"> <li>• Highly and totally weathered DIABASE in some parts of the slope. (Nearly soil)</li> </ul>	<ul style="list-style-type: none"> <li>• Concentration of slope surface water exists.</li> </ul>	<ul style="list-style-type: none"> <li>• Re-cutting</li> <li>• Vegetation</li> <li>• Berm ditch and vertical ditch</li> </ul>	<ul style="list-style-type: none"> <li>• The proposed Dalton Pass Tunnel Project ends up to this spot.</li> <li>• Re-cutting</li> <li>• Concrete Spraying (t=10cm)</li> <li>• Berm ditch and vertical ditch.</li> </ul>	

\* Countermeasures shown in Remarks are to be considered as countermeasures in long term





DALTON PASS SECTION (16)

CONDITION OF DISASTER AND SELECTED COUNTERMEASURES

No.	Disaster Spot No.	Km Type of Disaster	Existing Slope Condition			Factor for selection of countermeasure	Countermeasure	Remarks
			Dimension of slope	Geological Condition	Water Condition			
61	II-4	216+900 E-DF	<p>W = 170m</p>	<ul style="list-style-type: none"> <li>Embankment material</li> </ul>	<ul style="list-style-type: none"> <li>Scouring is caused by high velocity of river current.</li> <li>Concentration of road surface water exist.</li> </ul>	<ul style="list-style-type: none"> <li>Re-filling</li> <li>Stone pitching</li> <li>Vegetation</li> <li>Gabion foot protection</li> </ul>		
62	II-5	217+350 C-D.F	<p>W = 80m</p>	<ul style="list-style-type: none"> <li>Highly to totally weathered DIABASE rocks with highly developed cracks and fractures.</li> </ul>	<ul style="list-style-type: none"> <li>Slope is not steep but rocks are very weak.</li> <li>Progress of weathering is anticipated.</li> <li>Erosion by slope surface water is anticipated.</li> </ul>	<ul style="list-style-type: none"> <li>Re-cutting</li> <li>Sprayed concrete crib with grass.</li> <li>Vegetation</li> <li>Top slope ditch and berm ditch.</li> </ul>		
63	II-7	219+500 C-S.F	<p>W = 50m</p>	<ul style="list-style-type: none"> <li>Highly to totally weathered DIABASE.</li> <li>Highly fractured rock.</li> </ul>	<ul style="list-style-type: none"> <li>Slope is very high. Re-cutting work cannot be applied.</li> <li>Slope gradient is a little bit steeper than the optimum.</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Sprayed concrete crib with grass.</li> <li>Concrete spraying (t = 15cm.)</li> <li>Top slope ditch.</li> </ul>		
64	II-8	219+600 C-S.F	<p>W = 30m</p>	<ul style="list-style-type: none"> <li>Moderately to highly weathered DIABASE rocks with highly developed cracks.</li> </ul>	<ul style="list-style-type: none"> <li>Unstable and detached rocks.</li> <li>Slope gradient is not so steep.</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Concrete spraying (t = 15cm.)</li> </ul>		

DALTON PASS SECTION (17)

CONDITION OF DISASTER AND SELECTED COUNTERMEASURES

No.	Disaster Spot No.	Km Type of Disaster	Existing Slope Condition			Factor for selection of countermeasure	Countermeasure	Remarks	
			Dimension of slope	Geological Condition	Water Condition				
65	II-9	220+100 C-S.F	 <p>W = 90 m.</p>	<ul style="list-style-type: none"> <li>Highly weathered DIABASE rock with highly developed cracks.</li> </ul>	<ul style="list-style-type: none"> <li>A little concentration of slope surface water exists.</li> </ul>	<ul style="list-style-type: none"> <li>Concrete spraying (I = 15cm.)</li> <li>Slope is stable.</li> </ul>			
66	II-11(a)	221+250 D.F	 <p>W = 120 m.</p>	<ul style="list-style-type: none"> <li>River deposit (Debris)</li> </ul>	<ul style="list-style-type: none"> <li>During heavy rain, a big concentration of water from hinterland is anticipated.</li> </ul>	<ul style="list-style-type: none"> <li>Gravity type retaining wall.</li> <li>Concrete box culvert.</li> <li>Catch space. (Excavation)</li> </ul>	<ul style="list-style-type: none"> <li>Generally speaking, Sabo Project will be required at this site.</li> </ul>		
67	II-11(b)	222+050 D.F	 <p>W = 50 m.</p>	<ul style="list-style-type: none"> <li>River deposit (Debris)</li> </ul>	<ul style="list-style-type: none"> <li>Scouring of river bed is anticipated.</li> <li>Current velocity of the river is very high during rainy season.</li> </ul>	<ul style="list-style-type: none"> <li>Concrete Sabo-Dam.</li> <li>Waterway</li> <li>Gabion foot protection.</li> </ul>			
68	II-13	223+150 D.F	 <p>W = 10 m.</p>	<ul style="list-style-type: none"> <li>Slightly weathered DIABASE.</li> </ul>	<ul style="list-style-type: none"> <li>Water from hinterland flows at a hollow on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>Waterway</li> <li>Concrete Sabo-Dam.</li> </ul>	<ul style="list-style-type: none"> <li>Some debris exist on the hollow.</li> <li>Slope gradient is stable and the slope is covered by trees and grasses.</li> </ul>		

DALTON PASS SECTION (18)

CONDITION OF DISASTER AND SELECTED COUNTERMEASURES

No.	Disaster Spot No.	Km Type of Disaster	Existing Slope Condition			Factor for selection of countermeasure	Countermeasure	Remarks
			Dimension of slope	Geological Condition	Water Condition			
69	II-14	223+500 E-D.F	<p>W = 100 m.</p>	<ul style="list-style-type: none"> <li>Embankment material.</li> </ul>	<ul style="list-style-type: none"> <li>Current velocity of the river is very high.</li> <li>Road surface water concentration exist.</li> </ul>	<ul style="list-style-type: none"> <li>Re-filling.</li> <li>Stone pitching.</li> <li>Gabion retaining wall.</li> </ul>		
70	II-15	223+600 C-D.F	<p>W = 150 m.</p>	<ul style="list-style-type: none"> <li>Highly to totally weathered DIORITE.</li> <li>Fractured.</li> <li>Very weak soft rock.</li> </ul>	<ul style="list-style-type: none"> <li>Water from hinterland flows on the slope and concentrates at two hollows on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>Removal.</li> <li>Sprenged concrete crib with concrete wall.</li> <li>Top slope ditch.</li> <li>Vertical ditch.</li> </ul>		
71	II-18(a)	224+400 E-D.F	<p>W = 350 m.</p>	<ul style="list-style-type: none"> <li>Embankment material.</li> </ul>	<ul style="list-style-type: none"> <li>Current velocity of the river is very high.</li> </ul>	<ul style="list-style-type: none"> <li>Re-filling.</li> <li>Stone pitching.</li> <li>Gabion foot protection.</li> </ul>		
72	II-18(b)	225+000 E-D.F	<p>W = 350 m.</p>	<ul style="list-style-type: none"> <li>Embankment material.</li> </ul>	<ul style="list-style-type: none"> <li>Current velocity of the river is very high.</li> </ul>	<ul style="list-style-type: none"> <li>Re-filling.</li> <li>Stone pitching.</li> <li>Gabion foot protection.</li> </ul>		

DALTON PASS SECTION (19)






CONDITION OF DISASTER AND SELECTED COUNTERMEASURES

No.	Disaster Spot No.	Km Type of Disaster	Existing Slope Condition			Factor for selection of countermeasure	Countermeasure	Remarks
			Dimension of slope	Geological Condition	Water Condition			
73	II-19	225+700 E-D.F	<p>Embankment material.</p> <p>High velocity of river current.</p> <p>Scouring by the river is anticipated.</p> <p>Stone pitching</p> <p>Gabion foot protection</p> <p>W = 200 m.</p>	<ul style="list-style-type: none"> <li>Embankment material.</li> </ul>	<ul style="list-style-type: none"> <li>High velocity of river current.</li> <li>Scouring by the river is anticipated.</li> </ul>	<ul style="list-style-type: none"> <li>Existing grouted riprap is almost destroyed.</li> <li>Scouring caused by the river current needs protection.</li> </ul>	<ul style="list-style-type: none"> <li>Stone pitching.</li> <li>Gabion foot protection.</li> </ul>	



MAHAFLAG - SOGOD SECTION (I)

APPENDIX 10.3-2 CONDITION OF DISASTER AND SELECTED COUNTERMEASURES

No.	Disaster Spot No.	Km Type of Disaster	Existing Slope Condition			Water Condition	Factor for selection of countermeasure	Countermeasure	Remarks
			Dimension of slope	Geological Condition					
1	VIII-6(a)	990+500 E-D.F	 <p>Side ditch Vegetation 2.0m Re-filling W=30m</p>	<ul style="list-style-type: none"> <li>Embankment material</li> </ul>	<ul style="list-style-type: none"> <li>Concentration of road surface water</li> </ul>	<ul style="list-style-type: none"> <li>Inadequate embankment</li> <li>Poor drainage facilities exist on the roadway.</li> </ul>	<ul style="list-style-type: none"> <li>Re-filling</li> <li>Vegetation</li> <li>Side ditch</li> </ul>	<ul style="list-style-type: none"> <li>A half lane of the existing concrete pavement was destroyed.</li> </ul>	
2	VIII-66	1000+730 E-D.F	 <p>Temporary Bridge Stone masonry Supported type retaining wall W=10m</p>	<ul style="list-style-type: none"> <li>Sand and gravel</li> <li>Filling material</li> </ul>	<ul style="list-style-type: none"> <li>Bridge abutment was scoured by the river.</li> </ul>	<ul style="list-style-type: none"> <li>1st approach abutment encroached to the river</li> </ul>	<ul style="list-style-type: none"> <li>Extension of bridge length</li> <li>Revetment</li> </ul>	<ul style="list-style-type: none"> <li>Existing graded riprap was destroyed.</li> </ul> 	
3	VIII-67	1002+350 E-D.F	 <p>Vegetation Re-filling Berm W=27m</p>	<ul style="list-style-type: none"> <li>Embankment material</li> </ul>	<ul style="list-style-type: none"> <li>Concentration of road surface water</li> </ul>	<ul style="list-style-type: none"> <li>Inadequate embankment</li> <li>Poor drainage facilities exist on the roadway.</li> </ul>	<ul style="list-style-type: none"> <li>Re-filling</li> <li>Vegetation</li> <li>Side ditch</li> </ul>		
4	VIII-68	1003+060 E-D.F	 <p>Vegetation Re-filling Berm W=35m</p>	<ul style="list-style-type: none"> <li>Embankment material</li> </ul>	<ul style="list-style-type: none"> <li>Concentration of road surface water</li> <li>Embankment material is saturated by road surface water.</li> </ul>	<ul style="list-style-type: none"> <li>Poor drainage facilities exist on the roadway.</li> </ul>	<ul style="list-style-type: none"> <li>Re-filling</li> <li>Vegetation</li> <li>Side ditch</li> </ul>		

MAHAPLAG - SOGOD SECTION (2)

CONDITION OF DISASTER AND SELECTED COUNTERMEASURES

No.	Disaster Spot No.	Km Type of Disaster	Existing Slope Condition			Factor for selection of countermeasure	Countermeasure	Remarks
			Dimension of slope	Geological Condition	Water Condition			
5	XIII-71	1004+950 L.S	<p>W = 120 m</p>	<ul style="list-style-type: none"> <li>Highly weathered Sedimentary Rock (= Nearly Soil)</li> </ul>	<ul style="list-style-type: none"> <li>Spring in the slope</li> </ul>	<ul style="list-style-type: none"> <li>Re-cutting</li> <li>Horizontal drain holes</li> <li>Vegetation</li> <li>Gablon Retaining wall</li> </ul>		
6	XIII-73	1006+580 C-S.F	<p>W = 60 m</p>	<ul style="list-style-type: none"> <li>Totally weathered TUFF</li> <li>Almost soil</li> </ul>	<ul style="list-style-type: none"> <li>Concentration of surface water on the slope</li> </ul>	<ul style="list-style-type: none"> <li>Re-cutting</li> <li>Vegetation</li> <li>Top slope ditch</li> <li>Barr and vertical ditch</li> </ul>		
7	XIII-74	1009+020 E-D.F	<p>W = 20 m</p>	<ul style="list-style-type: none"> <li>Embankment material</li> </ul>	<ul style="list-style-type: none"> <li>Concentration of road surface water</li> </ul>	<ul style="list-style-type: none"> <li>Re-filling</li> <li>Vegetation</li> <li>Vertical ditch</li> <li>Side ditch</li> </ul>		
8	XIII-75	1009+050 C-S.F	<p>W = 35 m</p>	<ul style="list-style-type: none"> <li>Highly weathered TUFF</li> <li>Totally weathered in parts of slope</li> </ul>	<ul style="list-style-type: none"> <li>Concentration of slope surface water</li> <li>Water concentrated from hinterland</li> </ul>	<ul style="list-style-type: none"> <li>Re-cutting</li> <li>Vegetation</li> <li>Vertical drain</li> </ul>		





MAHAPLAG - SOGOD SECTION (3)

CONDITION OF DISASTER AND SELECTED COUNTERMEASURES

No.	Disaster Spot No.	Km Type of Disaster	Existing Slope Condition			Factor for selection of countermeasure	Countermeasure	Remarks
			Dimension of slope	Geological Condition	Water Condition			
9	VIII-76	1009+680 E-D.F		<ul style="list-style-type: none"> <li>Embankment material</li> </ul>	<ul style="list-style-type: none"> <li>Concentration of road surface water</li> </ul>	<ul style="list-style-type: none"> <li>Poor drainage facilities exist on the roadway.</li> <li>Steep embankment slope</li> </ul>	<ul style="list-style-type: none"> <li>Re-filling</li> <li>Vegetation</li> <li>Side ditch</li> <li>Vertical ditch</li> </ul>	
10	VIII-77	1009+700 C-S.F		<ul style="list-style-type: none"> <li>TUFF</li> <li>Slightly weathered and soft rock</li> <li>High developed cracks</li> </ul>	<ul style="list-style-type: none"> <li>Scoured by slope surface water</li> </ul>	<ul style="list-style-type: none"> <li>No existing slope protection</li> <li>Slope is steep and high</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Concrete spraying (t = 15 cm)</li> </ul>	
11	VIII-78	1009+720 E-D.F		<ul style="list-style-type: none"> <li>Embankment material</li> </ul>	<ul style="list-style-type: none"> <li>Concentration of road surface water</li> </ul>	<ul style="list-style-type: none"> <li>Poor drainage facilities exist on the roadway.</li> <li>Steep embankment slope</li> </ul>	<ul style="list-style-type: none"> <li>Re-filling</li> <li>Vegetation</li> <li>Side ditch</li> <li>Vertical ditch</li> </ul>	
12	VIII-79	1010+200 C-S.F		<ul style="list-style-type: none"> <li>Slightly weathered</li> <li>TUFF</li> <li>Soft rock</li> <li>High developed cracks</li> </ul>	<ul style="list-style-type: none"> <li>Scoured by slope surface water</li> </ul>	<ul style="list-style-type: none"> <li>No existing slope protection</li> <li>Slope is steep and high.</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Concrete spraying (t = 15 cm)</li> </ul>	

MAHAPLAG - SOGOD SECTION (4)

CONDITION OF DISASTER AND SELECTED COUNTERMEASURES

No.	Disaster Spot No.	Km Type of Disaster	Existing Slope Condition		Water Condition	Factor for selection of countermeasure	Countermeasure	Remarks
			Dimension of slope	Geological Condition				
13	XIII-80	1010+650 E-D.F	 <p>W = 60m + 30m</p>	<ul style="list-style-type: none"> <li>Embankment material</li> </ul>	<ul style="list-style-type: none"> <li>Concentration of surface water</li> </ul>	<ul style="list-style-type: none"> <li>No existing drainage facilities</li> <li>Scoured by the slope surface water and road surface water</li> <li>Slope is very high but not so steep</li> </ul>	<ul style="list-style-type: none"> <li>Re-filling</li> <li>Vegetation</li> <li>Subsurface drainage</li> <li>Side ditch</li> </ul>	<ul style="list-style-type: none"> <li>Opposite side of Spot No. XIII-81</li> </ul>
14	XIII-81	1010+700 C-D.F	 <p>W = 270m</p>	<ul style="list-style-type: none"> <li>Tuffaceous SAND - STONE</li> <li>Highly weathered</li> <li>Totally weathered in some parts of the slope (almost sand and gravel)</li> </ul>	<ul style="list-style-type: none"> <li>Concentration of slope surface water</li> <li>Concentration of water from hinterland</li> <li>Abundant seepage of water</li> </ul>	<ul style="list-style-type: none"> <li>No existing slope protection</li> <li>Progress of weathering is anticipated</li> <li>Very long slope length</li> </ul>	<ul style="list-style-type: none"> <li>Re-cutting</li> <li>Vegetation</li> <li>Berm and vertical ditch</li> <li>Horizontal drain holes</li> </ul>	<ul style="list-style-type: none"> <li>The biggest slope failure in Mahaplag-Sogod Section.</li> </ul>
15	XIII-83(b)	1012+040 E-D.F	 <p>W = 7.0 m</p>	<ul style="list-style-type: none"> <li>Embankment material</li> </ul>	<ul style="list-style-type: none"> <li>Concentration of road surface water</li> </ul>	<ul style="list-style-type: none"> <li>Poor drainage facilities exist on the roadway</li> <li>Not so steep and high embankment</li> </ul>	<ul style="list-style-type: none"> <li>Pipe culvert</li> <li>Re-filling</li> <li>Vegetation</li> <li>Vertical drain</li> </ul>	<ul style="list-style-type: none"> <li>Outlet of pipe culvert, headwall and apron was washed out.</li> </ul>
16	XIII-83(c)	1012+550 D.F	 <p>W = 7.0 m</p>	<ul style="list-style-type: none"> <li>Totally weathered</li> <li>TUFF</li> <li>Nearly soil</li> </ul>	<ul style="list-style-type: none"> <li>Concentration of slope surface water</li> </ul>	<ul style="list-style-type: none"> <li>No existing drainage facilities on the slope</li> </ul>	<ul style="list-style-type: none"> <li>Waterway</li> <li>Catch Basin</li> </ul>	

MAHAPLAG - SOGOD SECTION (5)

CONDITION OF DISASTER AND SELECTED COUNTERMEASURES

No.	Disaster Spot No.	Km Type of Disaster	Existing Slope Condition			Factor for selection of countermeasure	Countermeasure	Remarks
			Dimension of slope	Geological Condition	Water Condition			
17	VIII-85	1013+950 E-D.F	<p>W=49m</p>	<ul style="list-style-type: none"> <li>Embankment material</li> </ul>	<ul style="list-style-type: none"> <li>Concentration of road surface water</li> </ul>	<ul style="list-style-type: none"> <li>Re-filling</li> <li>Cast-in-place concrete crib with grass</li> <li>Gabion retaining wall</li> <li>Vertical ditch</li> <li>Slide ditch</li> </ul>		
18	VIII-86	1013+980 C-S.F	<p>W=150m</p>	<ul style="list-style-type: none"> <li>Highly weathered SANDSTONE</li> <li>Totally weathered in some parts of the slope</li> <li>High developed cracks</li> </ul>	<ul style="list-style-type: none"> <li>Slope-surface water flows on the slope</li> <li>Surface water from hinterland drops on the slope</li> </ul>	<ul style="list-style-type: none"> <li>Re-cutting</li> <li>Concrete spraying (thickness 15cm)</li> <li>Vertical drain</li> <li>Stone masonry</li> </ul>		
19	VIII-87(a)	1014+500 C-D.F	<p>W=20m</p>	<ul style="list-style-type: none"> <li>Highly weathered ANDESITE</li> <li>High developed cracks</li> </ul>	<ul style="list-style-type: none"> <li>Concentration of slope surface water</li> <li>A little seepage of water</li> </ul>	<ul style="list-style-type: none"> <li>Re-cutting</li> <li>Sprayed concrete crib with grass</li> <li>Vegetation</li> <li>Vertical drain</li> <li>Stone masonry</li> </ul>		
20	VIII-87(b)	1015+100 O.F	<p>W=100m</p>	<ul style="list-style-type: none"> <li>Embankment material</li> </ul>	<ul style="list-style-type: none"> <li>Small creek crosses the roadway and water overflows on it.</li> </ul>	<ul style="list-style-type: none"> <li>Pipe culvert</li> <li>Stone masonry</li> </ul>		

MAHAPLAG - SOGOD SECTION (S)

CONDITION OF DISASTER AND SELECTED COUNTERMEASURES

No.	Disaster Spot No.	K.m Type of Disaster	Existing Slope Condition			Factor for selection of countermeasure	Countermeasure	Remarks
			Dimension of slope	Geological Condition	Water Condition			
21	XVII-88	1015 + 150 C-D.F	<p>W=39m</p>	<ul style="list-style-type: none"> <li>Totally weathered TUFF</li> <li>Nearly soil</li> <li>Loose soil</li> </ul>	<ul style="list-style-type: none"> <li>Surface water from hinterland drops on the slope.</li> <li>Scoured by concentration of slope surface water</li> </ul>	<ul style="list-style-type: none"> <li>Progress weathering is fast.</li> <li>Slope gradient is not so steep.</li> <li>Vegetation should be applied.</li> <li>Concentration of surface water</li> </ul>	<ul style="list-style-type: none"> <li>Re-cutting</li> <li>Vegetation</li> <li>Vertical drain</li> </ul>	
22	XVIII-89	1015 + 560 E-D.F	<p>W=90m</p>	<ul style="list-style-type: none"> <li>Embankment materials</li> </ul>	<ul style="list-style-type: none"> <li>Concentration of road surface water</li> <li>Existing culvert crosses the roadway.</li> </ul>	<ul style="list-style-type: none"> <li>Poor drainage facilities exist on the roadway.</li> <li>Slope is very high and not so steep.</li> <li>No slope protection nor opens of pipe culverts</li> <li>A little seepage of water occurs.</li> </ul>	<ul style="list-style-type: none"> <li>Re-filling</li> <li>Cast-in-place concrete crib with grass</li> <li>Vertical ditch</li> <li>Gobion closed conduit</li> <li>Stone pitching</li> <li>Gobion Retaining Wall</li> </ul>	
23	XIII-90(a)	1015 + 510 C-S.F	<p>W=20m</p>	<ul style="list-style-type: none"> <li>Highly weathered SANDSTONE</li> <li>Highly developed cracks</li> </ul>	<ul style="list-style-type: none"> <li>Concentration of slope surface water</li> </ul>	<ul style="list-style-type: none"> <li>More stable than the rock of Spot No. XIII-90(b)</li> <li>No drainage facilities exist on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>Re-cutting</li> <li>Concrete spraying (thickness 10cm)</li> <li>Vertical drain</li> </ul>	
24	XIII-90(b)	1015 + 560 C-SF	<p>W=40m</p>	<ul style="list-style-type: none"> <li>Highly weathered SANDSTONE</li> <li>In some parts of the slope, hard SANDSTONE exists.</li> <li>Highly developed cracks</li> </ul>	<ul style="list-style-type: none"> <li>Water from hinterland drops on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>Very weak rocks</li> <li>Slope is steep and very high.</li> <li>The berms exist on the slope, but there is no berm ditch.</li> <li>Re-cutting can not be applied.</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Sprayed concrete crib with concrete wall</li> <li>Rock Bolt</li> <li>Anchor wire net</li> </ul>	<p>There are 2 kinds of Rock-hardness on the slope</p>

MAHAFLAG - SOGOD SECTION (7)

CONDITION OF DISASTER AND SELECTED COUNTERMEASURES

No.	Disaster Spot No.	Km Type of Disaster	Existing Slope Condition			Water Condition	Factor for selection of countermeasure	Countermeasure	Remarks
			Dimension of slope	Geological Condition	Geological Condition				
25	VIII-91	1016 + 600 E-D.F	<p>W = 15m</p>	<ul style="list-style-type: none"> <li>Embankment materials</li> </ul>	<ul style="list-style-type: none"> <li>Concentration of road surface water</li> <li>Embankment material is saturated by the road surface water.</li> </ul>	<ul style="list-style-type: none"> <li>Poor drainage facilities exist on the roadway.</li> <li>Slope gradient is gentle.</li> </ul>	<ul style="list-style-type: none"> <li>Re-filling</li> <li>Vegetation</li> <li>Side ditch</li> <li>Gablon Retaining Wall</li> </ul>		
26	VIII-92	1016 + 750 C-S.F	<p>W = 60 m</p>	<ul style="list-style-type: none"> <li>VOLCANICLASTICS</li> <li>Totally weathered (Nearly Soil)</li> <li>Very loose</li> </ul>	<ul style="list-style-type: none"> <li>Seepage of water occurs</li> <li>Slope surface water flows on the slope</li> </ul>	<ul style="list-style-type: none"> <li>No slope protection</li> <li>No drainage facilities exist on the slope</li> </ul>	<ul style="list-style-type: none"> <li>Re-cutting</li> <li>Vegetation</li> <li>Berm and vertical ditch</li> </ul>		
27	VIII-93	1016 + 850 E-D.F	<p>W = 44.5 m</p>	<ul style="list-style-type: none"> <li>Embankment material</li> </ul>	<ul style="list-style-type: none"> <li>Concentration of road surface water</li> <li>Embankment material is saturated by the road surface water.</li> </ul>	<ul style="list-style-type: none"> <li>Poor drainage facilities</li> <li>Slope gradient is gentle.</li> <li>A little seepage of water on the slope occurs</li> </ul>	<ul style="list-style-type: none"> <li>Re-filling</li> <li>Vegetation</li> <li>Gablon closed conduit</li> <li>Vertical ditch</li> <li>Side ditch</li> <li>Gablon Retaining Wall</li> </ul>	<ul style="list-style-type: none"> <li>Half lane of the concrete pavement was destroyed.</li> </ul>	
28	VIII-94	1017 + 400 C-D.F	<p>W = 10.5 m</p>	<ul style="list-style-type: none"> <li>VOLCANICLASTICS</li> <li>Totally weathered (Nearly Soil)</li> </ul>	<ul style="list-style-type: none"> <li>Slope surface water flows on the slope.</li> <li>A little seepage of water occurs.</li> </ul>	<ul style="list-style-type: none"> <li>No protection on the slope</li> <li>Slope gradient is very gentle.</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Vegetation</li> <li>Top slope ditch</li> </ul>		

MAHALAG - SOGOD SECTION (8)

CONDITION OF DISASTER AND SELECTED COUNTERMEASURES

No.	Disaster Spot No.	Km Type of Disaster	Existing Slope Condition			Factor for selection of countermeasure	Countermeasure	Remarks
			Dimension of slope	Geological Condition	Water Condition			
29	XIII-96	1018 + 280 E-D.F	<p>W = 50 m</p>	<ul style="list-style-type: none"> <li>Embankment materials</li> </ul>	<ul style="list-style-type: none"> <li>Concentration of road surface water</li> <li>Embankment material is saturated by the road surface water.</li> </ul>	<ul style="list-style-type: none"> <li>Poor drainage facilities exist on the roadway.</li> <li>A little seepage of water on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>Re-filling</li> <li>Vegetation</li> <li>Gabion closed conduit</li> <li>Vertical ditch</li> <li>Side ditch</li> <li>Gabion Retaining Wall.</li> </ul>	<ul style="list-style-type: none"> <li>Concrete pavement was destroyed.</li> </ul>
30	XIII-97	1018 + 800 C-S.F	<p>W = 70 m</p>	<ul style="list-style-type: none"> <li>Highly weathered ANDESITE (Soft rock)</li> <li>Highly jointed and developed cracks</li> </ul>	<ul style="list-style-type: none"> <li>Slope surface water flows on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>No protection on the slope and the slope gradient is not optimum.</li> <li>Progress of weathering is anticipated.</li> </ul>	<ul style="list-style-type: none"> <li>Re-cutting</li> <li>Concrete spraying (t = 10cm)</li> </ul>	
31	XIII-99	1019 + 360	<p>W = 120 m</p>	<ul style="list-style-type: none"> <li>ANDESITE</li> <li>Slightly weathered</li> <li>Developed cracks</li> </ul>	<ul style="list-style-type: none"> <li>Slope surface water flows on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>No protection on the slope</li> <li>Some detached soils exist on the slope.</li> <li>Slope gradient is steep.</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Re-cutting</li> <li>Concrete spraying (t = 15cm)</li> <li>Vertical ditch</li> <li>Top slope ditch</li> </ul>	
32	XIII-100	1019 + 690 G-D.F	<p>W = 60 m</p>	<ul style="list-style-type: none"> <li>ANDESITE</li> <li>Highly weathered and developed cracks</li> </ul>	<ul style="list-style-type: none"> <li>Concentration of slope surface water</li> <li>A little seepage of water occurs.</li> </ul>	<ul style="list-style-type: none"> <li>Deep scouring due to concentration of slope surface water</li> <li>Debris exist on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Water way</li> <li>Gravity type retaining wall</li> <li>Concrete spraying (t = 10cm)</li> <li>Vegetation</li> </ul>	



MAHALPLAG - SOGOD SECTION (9)

CONDITION OF DISASTER AND SELECTED COUNTERMEASURES

No.	Disaster Spot No.	Km Type of Disaster	Existing Slope Condition			Factor for selection of countermeasure	Countermeasure	Remarks
			Dimension of slope	Geological Condition	Water Condition			
33	VIII-101	1019+890 C-S.F	<p>W=70m</p>	<ul style="list-style-type: none"> <li>Slightly weathered ANDESITE</li> <li>Highly developed cracks</li> </ul>	<ul style="list-style-type: none"> <li>Less concentration of slope surface water</li> </ul>	<ul style="list-style-type: none"> <li>No slope protection was implemented.</li> <li>Progress of weathering is anticipated.</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Concrete spraying (1=10 cm)</li> </ul>	
34	VIII-102	1020+000 C-S.F	<p>W=23m</p>	<ul style="list-style-type: none"> <li>Highly weathered ANDESITE</li> <li>Totally weathered in some parts of the slope (Nearly soil)</li> </ul>	<ul style="list-style-type: none"> <li>Concentration of slope surface water</li> </ul>	<ul style="list-style-type: none"> <li>No slope protection was implemented</li> <li>Scoured by concentration of slope surface water</li> <li>Nearly soil</li> </ul>	<ul style="list-style-type: none"> <li>Re-culturing</li> <li>Vegetation</li> <li>Vertical ditch</li> </ul>	
35	VIII-103	1020+670 C-F	<p>W=20m</p>	<ul style="list-style-type: none"> <li>Highly weathered ANDESITE</li> <li>Hard Rock</li> <li>Developed cracks</li> </ul>	<ul style="list-style-type: none"> <li>Less damages due to slope surface water</li> </ul>	<ul style="list-style-type: none"> <li>Progress of weathering is minimal.</li> <li>Detached rocks exist on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Anchor wire net</li> </ul>	
36	VIII-104	1020+800 C-F	<p>W=90m</p>	<ul style="list-style-type: none"> <li>Highly weathered ANDESITE</li> <li>Hard Rock</li> <li>Developed cracks</li> </ul>	<ul style="list-style-type: none"> <li>Less damages due to slope water surface</li> </ul>	<ul style="list-style-type: none"> <li>Soft rock and soils exist in some parts of the slope.</li> <li>Progress of weathering is minimal.</li> <li>Slope gradient is steeper than optimum gradient.</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Re-culturing</li> <li>Anchor wire net</li> </ul>	

MAHAPLAG - SOGOD SECTION (10)

CONDITION OF DISASTER AND SELECTED COUNTERMEASURES

No.	Disaster Spot No.	Km Type of Disaster	Existing Slope Condition		Water Condition	Factor for selection of countermeasure	Countermeasure	Remarks
			Dimension of slope	Geological Condition				
37	VIII-105	1021+050 L.S	<p>Horizontal drain holes W=80m</p>	<ul style="list-style-type: none"> <li>Moderately weathered SEDIMENTARY ROCK</li> </ul>	<ul style="list-style-type: none"> <li>High underground level</li> <li>A little seepage of water occurs.</li> </ul>	<ul style="list-style-type: none"> <li>The slope is covered by grasses and trees.</li> <li>The slope gradient is not steep and the slope is unstable in dry season.</li> </ul>	<ul style="list-style-type: none"> <li>Horizontal drain holes</li> </ul>	
38	VIII-106	1022+260 C-S.F	<p>Vegetation Re-cutting W=55m</p>	<ul style="list-style-type: none"> <li>Slightly weathered TUFF</li> <li>Bedding planes inclined towards slope surface</li> </ul>	<ul style="list-style-type: none"> <li>Slope surface water flows on the slope and saturate to the ground.</li> </ul>	<ul style="list-style-type: none"> <li>Transitional slide is anticipated.</li> <li>Structural weakness of slope such as bedding planes between firm bed rocks and overlying detritus.</li> </ul>	<ul style="list-style-type: none"> <li>Re cutting</li> <li>Vegetation</li> <li>Top slope ditch</li> </ul>	
39	VIII-107	1022 + 550 C-S.F	<p>Only ditches W=80m</p>	<ul style="list-style-type: none"> <li>Moderately weathered TUFF</li> <li>Developed cracks.</li> </ul>	<ul style="list-style-type: none"> <li>Water from hinterland runs at two hollows of the slope.</li> </ul>	<ul style="list-style-type: none"> <li>The slope is covered by grasses and trees.</li> <li>Concentration of slope surface water</li> </ul>	<ul style="list-style-type: none"> <li>Vertical ditch</li> <li>Top slope ditch</li> </ul>	
40	VIII-108	1023 + 220 L.S	<p>Re-cutting and vegetation Gabion retaining wall Gibion retaining wall W=320m</p>	<ul style="list-style-type: none"> <li>Highly weathered SEDIMENTARY ROCK (Nearly Soil)</li> </ul>	<ul style="list-style-type: none"> <li>Slope surface water saturates to the ground.</li> <li>Ground water level is not so high.</li> </ul>	<ul style="list-style-type: none"> <li>Slope gradient is not steep and height of slope is low.</li> <li>Width of shoulder is more than 3.0 meters.</li> </ul>	<ul style="list-style-type: none"> <li>Re-cutting</li> <li>Counter fill</li> <li>Gabion Retaining Wall</li> <li>Berm and vertical ditch</li> <li>Vegetation</li> </ul>	

KENNON ROAD (1)

APPENDIX 10.3-3. CONDITION OF DISASTER AND SELECTED COUNTERMEASURES

No.	Disaster Spot No.	Km Type of Disaster	Existing Slope Condition		Water Condition	Factor for selection of countermeasure	Countermeasure	Remarks
			Dimension of slope	Geological Condition				
1	1K-3	216+000 C-F	<p>W = 140M (W: Width of slope)</p>	<ul style="list-style-type: none"> <li>• Conglomerate</li> <li>• Hard and fresh rock with sparse cracks.</li> </ul>	<ul style="list-style-type: none"> <li>• Less concentration of slope surface water.</li> <li>• A little seepage of water.</li> </ul>	<ul style="list-style-type: none"> <li>• Overhang formed</li> <li>• Water from hinterland concentrated at one place and falls to road surface.</li> <li>• Progress of weathering is minimal.</li> </ul>	<ul style="list-style-type: none"> <li>• Re-cutting</li> <li>• Anchor wire net</li> <li>• Vertical ditch</li> </ul>	<ul style="list-style-type: none"> <li>• Road widening towards river side is difficult due to deep valley.</li> </ul>
2	1K-4	219+300 C-F	<p>W = 250M</p>	<ul style="list-style-type: none"> <li>• Conglomerate</li> <li>• Hard and fresh rock with sparse cracks.</li> </ul>	<ul style="list-style-type: none"> <li>• A little seepage of water.</li> <li>• Water from hinterland runs at two hollows of the slope.</li> </ul>	<ul style="list-style-type: none"> <li>• Overhang formed</li> <li>• Rock is stable though with slight cracks.</li> <li>• Water from hinterland concentrated at two places and fall to road surface.</li> </ul>	<ul style="list-style-type: none"> <li>• Re-cutting</li> <li>• Anchor wire net</li> <li>• Vertical ditch</li> </ul>	<ul style="list-style-type: none"> <li>• do -</li> </ul>
3	1K-6	223+200 C-F	<p>W = 150M</p>	<ul style="list-style-type: none"> <li>• Conglomerate</li> <li>• Fresh rock with regular cracks.</li> </ul>	<ul style="list-style-type: none"> <li>• No water seepage nor concentration of slope surface water.</li> </ul>	<ul style="list-style-type: none"> <li>• Overhang formed</li> <li>• More stable than rock of 1K-4.</li> </ul>	<ul style="list-style-type: none"> <li>• Re-cutting</li> <li>• Anchor wire net</li> </ul>	<ul style="list-style-type: none"> <li>• do -</li> </ul>
4	1K-7(a)	224+850 C-F	<p>W = 138M</p>	<ul style="list-style-type: none"> <li>• Conglomerate</li> <li>• Slightly weathered rock with regular cracks.</li> </ul>	<ul style="list-style-type: none"> <li>• No concentration of slope surface water.</li> </ul>	<ul style="list-style-type: none"> <li>• Overhang formed</li> <li>• Some joints exist. Less weak than rock of 1K-3, 4 and 6.</li> </ul>	<ul style="list-style-type: none"> <li>• Re-cutting</li> <li>• Anchor wire net</li> </ul>	<ul style="list-style-type: none"> <li>• do -</li> </ul>

CONDITION OF DISASTER AND SELECTED COUNTERMEASURE

KENNON ROAD (2)

No.	Disaster Spot No.	Km Type of Disaster	Existing Slope Condition			Factor for selection of countermeasure	Countermeasure	Remarks
			Dimension of slope	Geological Condition	Water Condition			
5	IK-7(b)	224+850 E-D.F	<p>Existing Stone Masonry W=21m</p>	<ul style="list-style-type: none"> <li>Embankment materials (sand and gravel)</li> <li>HARD CONGLOMERATE</li> </ul>	<ul style="list-style-type: none"> <li>Concentration of road surface water exists.</li> <li>Embankment materials were saturated by road surface water.</li> </ul>	<ul style="list-style-type: none"> <li>Supported type retaining wall.</li> <li>Stone masonry retaining wall</li> <li>Side ditch.</li> </ul>		
6	IK-9	226+100 C-F	<p>Re-cutting Sprayed concrete crib W=196m</p>	<ul style="list-style-type: none"> <li>LIMESTONE</li> <li>Weathered rock with developed cracks.</li> </ul>	<ul style="list-style-type: none"> <li>Less concentration of slope surface water.</li> <li>Slope surface water flows on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Re-cutting</li> <li>Sprayed concrete crib with grass and with concrete wall</li> </ul>	<ul style="list-style-type: none"> <li>Catch fence can not be applied due to the heavier weight of the falling rocks.</li> </ul>	
7	IK-10(a)	226+350 C-F	<p>Sprayed concrete crib Re-cutting W=20m</p>	<ul style="list-style-type: none"> <li>LIMESTONE</li> <li>Weathered rock with developed cracks.</li> </ul>	<ul style="list-style-type: none"> <li>A little influence due to the slope surface water.</li> </ul>	<ul style="list-style-type: none"> <li>Re-cutting</li> <li>Sprayed concrete crib with grass and with concrete wall</li> </ul>	<ul style="list-style-type: none"> <li>Very big slope failure occurs at the opposite side of the river.</li> </ul>	
8	IK-10(b)	227+250 E-D.F	<p>Re-filling Cast-in-place concrete crib P.C. Anchor Horizontal drain hole W=60m</p>	<ul style="list-style-type: none"> <li>Embankment materials (sand and gravel)</li> </ul>	<ul style="list-style-type: none"> <li>Seepage of water on the slope occurs.</li> <li>Road surface water saturates into the embankment materials.</li> </ul>	<ul style="list-style-type: none"> <li>Re-filling of common materials</li> <li>Horizontal drain hole</li> <li>Cast-in place concrete crib with concrete wall</li> <li>P.C. Anchor</li> <li>Concrete pavement</li> </ul>		

KENNON ROAD (3)

CONDITION OF DISASTER AND SELECTED COUNTERMEASURES

No.	Disaster Spot No.	Km Type of Disaster	Existing Slope Condition			Factor for selection of countermeasure	Countermeasure	Remarks
			Dimension of slope	Geological Condition	Water Condition			
9	IK-11	229+050 C-F	<p>W=39m</p>	<ul style="list-style-type: none"> <li>Andesite rocks</li> <li>Fresh rock with regular cracks.</li> </ul>	<ul style="list-style-type: none"> <li>No water concentration exist on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>Rock fall</li> <li>Progress of weathering is minimal.</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Anchor wire net</li> </ul>	<ul style="list-style-type: none"> <li>There is a small creek between slope of IK-11 and IK-12.</li> </ul>
10	IK-12	229+150 C-F	<p>W=24m</p>	<ul style="list-style-type: none"> <li>Fresh ANDESITE</li> <li>Regular cracks.</li> </ul>	<ul style="list-style-type: none"> <li>No water concentration exist on the slope</li> </ul>	<ul style="list-style-type: none"> <li>Rock fall</li> <li>Progress of weathering is minimal.</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Anchor wire net</li> </ul>	
11	IK-13	229+930 C-F	<p>W=30m</p>	<ul style="list-style-type: none"> <li>Fresh ANDESITE</li> <li>Regular cracks</li> </ul>	<ul style="list-style-type: none"> <li>No water concentration exist on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>No protection facilities for rock fall</li> <li>Progress of weathering is minimal.</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Anchor wire net.</li> </ul>	
12	IK-15	230+700 C-F	<p>W=26.5m</p>	<ul style="list-style-type: none"> <li>Fresh DIORITE</li> <li>Moderately jointed</li> </ul>	<ul style="list-style-type: none"> <li>No water concentration exist on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>No protection facilities for rock fall.</li> <li>Progress of weathering is minimal.</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Anchor wire net</li> </ul>	

KENNON ROAD (4)

CONDITION OF DISASTER AND SELECTED COUNTERMEASURES

No.	Disaster Spot No.	Km Type of Disaster	Existing Slope Condition			Factor for selection of countermeasure	Countermeasure	Remarks
			Dimension at slope	Geological Condition	Water Condition			
13	IK-19	234+300 C-F	<p>W=56 m</p>	<ul style="list-style-type: none"> <li>Highly weathered ANDESITE rocks</li> <li>Slightly to moderately weathered rocks in some parts of the slope.</li> </ul>	<ul style="list-style-type: none"> <li>Water from hinterland flows at the hollow on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>No protection facilities on the slope.</li> <li>Slope gradient is steeper than the optimum.</li> <li>There are two kinds of hardness of rocks on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>Re-curling</li> <li>Concrete spraying (t=15 cm)</li> <li>Sprayed concrete cap</li> <li>Vertical drain</li> </ul>	
14	IK-20	234+400 C-F	<p>W=59 m</p>	<ul style="list-style-type: none"> <li>Moderately weathered ANDESITE with developed cracks</li> </ul>	<ul style="list-style-type: none"> <li>No water concentration exists on the slope.</li> <li>Surface water flows on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>No protection on the slope</li> <li>Progress of weathering</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Concrete spraying (t=10 cm)</li> </ul>	
15	IK-21	234+700 C-F	<p>W=43 m.</p>	<ul style="list-style-type: none"> <li>Slightly weathered and moderately jointed GRANITE</li> </ul>	<ul style="list-style-type: none"> <li>Water from hinterland is concentrated at one hollow on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>No protection facilities for rock fall.</li> <li>No progress of weathering is anticipated.</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Anchor wire net</li> <li>Vertical drain and pipe culvert.</li> </ul>	
16	IK-22 (U)	234+900 C-F	<p>W=278 m</p>	<ul style="list-style-type: none"> <li>Slightly to moderately weathered and slightly jointed DIORITE</li> </ul>	<ul style="list-style-type: none"> <li>Water from hinterland flows at a hollow on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>No existing slope protection for rock fall.</li> <li>No progress of weathering is anticipated.</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Anchor wire net</li> <li>Vertical drain</li> </ul>	

KENNON ROAD (5)

CONDITION OF DISASTER AND SELECTED COUNTERMEASURE

No.	Disaster Spot No.	Km Type of Disaster	Existing Slope Condition			Factor for selection of countermeasure	Countermeasure	Remarks
			Dimension of slope	Geological Condition	Water Condition			
17	IK-22(b)	234+900 E-D.F	<p>W=15m</p>	<ul style="list-style-type: none"> <li>Embankment materials (Sand and gravel)</li> </ul>	<ul style="list-style-type: none"> <li>Concentration of road surface water exists.</li> </ul>	<ul style="list-style-type: none"> <li>Re-filling</li> <li>Cast-in place concrete crib with concrete wall</li> <li>P.C Anchor</li> <li>Side ditch</li> </ul>		
18	IK-23	235+050 C-F	<p>W=72m</p>	<ul style="list-style-type: none"> <li>Moderately to highly weathered DIORITE rocks.</li> <li>Developed cracks.</li> <li>Soft rock.</li> </ul>	<ul style="list-style-type: none"> <li>No water concentration on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>Re-cutting</li> <li>Concrete spraying (1=15cm)</li> </ul>		
19	IK-24(a)	235+700 C-F	<p>W=110m</p>	<ul style="list-style-type: none"> <li>Highly weathered DIORITE rocks.</li> <li>Highly jointed and developed cracks.</li> </ul>	<ul style="list-style-type: none"> <li>Water from hinterland flows on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>Removal and Re-cutting</li> <li>Sprayed concrete crib with grass</li> <li>Supported type Retaining wall.</li> </ul>		
20	IK-24(b)	235+700 E-D.F	<p>W=80m</p>	<ul style="list-style-type: none"> <li>Fresh DIORITE</li> </ul>	<ul style="list-style-type: none"> <li>High velocity of river current.</li> </ul>	<ul style="list-style-type: none"> <li>Gravity type Retaining wall.</li> </ul>		

KENNON ROAD (6)

CONDITION OF DISASTER AND SELECTED COUNTERMEASURE

No.	Disaster Spot No.	Km Type of Disaster	Existing Slope Condition			Factor for selection of countermeasure	Countermeasure	Remarks
			Dimension of slope	Geological Condition	Water Condition			
21	IK-25	236+100 C-F	<p>W = 3.4</p>	<ul style="list-style-type: none"> <li>Highly weathered DIORITE with highly developed cracks and joints.</li> </ul>	<ul style="list-style-type: none"> <li>Water from hinterland flows on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>Removal and Re-cutting</li> <li>Concrete spraying (t = 10 cm)</li> <li>Anchor wire net.</li> </ul>		
22	IK-26	236+500 C-F	<p>W = 8 m</p>	<ul style="list-style-type: none"> <li>Moderately to highly weathered DIORITE with developed cracks.</li> </ul>	<ul style="list-style-type: none"> <li>No water concentration on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>Re-cutting.</li> <li>Anchor wire net.</li> </ul>		
23	IK-27	236+600 C-F	<p>W = 20 m</p>	<ul style="list-style-type: none"> <li>Slightly to moderately weathered DIORITE with developed cracks.</li> </ul>	<ul style="list-style-type: none"> <li>No water concentration on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>Re-cutting</li> <li>Anchor wire net</li> </ul>		
24	IK-28	236+700 C-F	<p>W = 119 m</p>	<ul style="list-style-type: none"> <li>Slightly to moderately weathered DIORITE with developed cracks.</li> </ul>	<ul style="list-style-type: none"> <li>No slope surface water concentration.</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Anchor wire net</li> </ul>		



KENNON ROAD (7)

CONDITION OF DISASTER AND SELECTED COUNTERMEASURE

No.	Disaster Spot No.	Km. Type of Disaster	Existing Slope Condition			Countermeasure	Remarks
			Dimension of slope	Geological Condition	Water Condition		
25	IK-29	236+800 C-F	<p>W = 60 m</p>	Slightly weathered ANDESITE with regular cracks.	<ul style="list-style-type: none"> <li>Very little influence exists due to slope surface water.</li> </ul>	<ul style="list-style-type: none"> <li>Re-moval</li> <li>Anchor wire net</li> </ul>	
26	IK-30(a)	236+900 C-F	<p>W = 60 m</p>	Highly weathered ANDESITE with highly jointed and developed cracks.	<ul style="list-style-type: none"> <li>Surface water flows on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>Re-cutting</li> <li>Concrete spraying (± 10m)</li> </ul>	The opposite side of this spot is spot no. IK-30(b).
27	IK-30(b)	236+900 E-D.F	<p>W = 30 m</p>	Embankment materials. (Sand and gravel)	<ul style="list-style-type: none"> <li>Concentration of road surface water exists.</li> </ul>	<ul style="list-style-type: none"> <li>Re-filling</li> <li>Cast-in-place concrete crib</li> <li>Gabion retaining wall</li> <li>Side ditch</li> </ul>	
28	IK-32	237+130 E-D.F	<p>W = 60 m</p>	Fresh ANDESITE	<ul style="list-style-type: none"> <li>High velocity of river current.</li> </ul>	<ul style="list-style-type: none"> <li>Gravity type Retaining wall</li> </ul>	

KENNON ROAD (8)

CONDITION OF DISASTER AND SELECTED COUNTERMEASURE

No.	Disaster Spot No.	Km Type of Disaster	Existing Slope Condition		Factor for selection of countermeasure	Countermeasure	Remarks
			Dimension of slope	Water Condition			
29	IK-33	237+200 C-S.F	<p>W=97m</p>	<ul style="list-style-type: none"> <li>Surface water from hinterland flows on the slope but with less concentration of the surface water.</li> </ul>	<ul style="list-style-type: none"> <li>Some unstable materials and detached rocks exist on the slope.</li> <li>Slope is not steep but very high.</li> <li>No slope protection on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Sprayed concrete crib.</li> </ul>	
30	IK-34	237+300 C-F	<p>W=71m</p>	<ul style="list-style-type: none"> <li>Moderately to highly weathered ANDESITE rocks with highly developed cracks and joints.</li> </ul>	<ul style="list-style-type: none"> <li>A little influence exists due to the slope surface water.</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Concrete spraying (t=15cm.)</li> <li>Anchor wire net.</li> </ul>	
31	IK-35	237+400 C-S.F	<p>W=120m</p>	<ul style="list-style-type: none"> <li>Highly weathered DIORITE rocks with highly jointed and developed cracks.</li> </ul>	<ul style="list-style-type: none"> <li>Less concentration of the slope surface water.</li> </ul>	<ul style="list-style-type: none"> <li>Re-cutting</li> <li>Vegetation</li> <li>Concrete spraying (t=10cm)</li> </ul>	
32	IK-36	237+900 C-S.F	<p>W=80m</p>	<ul style="list-style-type: none"> <li>Moderately to highly weathered DIORITE and ANDESITE rocks with highly developed cracks.</li> </ul>	<ul style="list-style-type: none"> <li>Slope gradient is optimum.</li> <li>No slope protection.</li> <li>A little unstable materials,</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Concrete spraying (t=10 cm)</li> </ul>	





KENNON ROAD (9)

CONDITION OF DISASTER AND SELECTED COUNTERMEASURE

No.	Disaster Spot No.	Km Type of Disaster	Existing Slope Condition			Factor for selection of countermeasure	Countermeasure	Remarks
			Dimension of slope	Geological Condition	Water Condition			
33	IK-37(a)	238+120 E-D.F	<p>Stone masonry Supported type retaining wall Gabion foot protection Re-filling W = 177 m</p>	<ul style="list-style-type: none"> <li>Embankment materials</li> </ul>	<ul style="list-style-type: none"> <li>Concentration of road surface water exists.</li> <li>High velocity of the river current.</li> </ul>	<ul style="list-style-type: none"> <li>Re-filling</li> <li>Stone masonry</li> <li>Supported type Retaining wall.</li> <li>Gabion foot protection</li> <li>Side ditch</li> </ul>		
34	IK-37(b)	238+300 C-S.F	<p>Sprayed concrete crib Removal 56° W = 62 m</p>	<ul style="list-style-type: none"> <li>Highly weathered DIORITE rock with highly jointed and developed cracks</li> </ul>	<ul style="list-style-type: none"> <li>Slope surface water flow on the slope but less concentration of the surface water.</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Sprayed concrete crib with grass.</li> </ul>		
35	IK-38	238+600 C-F	<p>Concrete spraying 70 m 75° W = 235 m</p>	<ul style="list-style-type: none"> <li>Moderately to highly weathered DIORITE rocks with highly developed cracks.</li> </ul>	<ul style="list-style-type: none"> <li>Slope gradient is not so steep.</li> <li>Very weak soft rock.</li> <li>Some unstable materials are on the slope.</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Concrete spraying (1 = 10cm and 1 = 15cm)</li> <li>Catch Fence</li> </ul>		
36	IK-39	239+900 C-F	<p>Concrete spraying 75° 90 m W = 90 m</p>	<ul style="list-style-type: none"> <li>Moderately to highly weathered ANDESITE rocks with highly developed cracks.</li> </ul>	<ul style="list-style-type: none"> <li>Slope gradient is not so steep.</li> <li>Two different kinds of weakness in rocks exist on the slope.</li> <li>Wide shoulder exists in some parts of the roadway.</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Concrete spraying (1 = 10cm)</li> </ul>		

KENNON ROAD (10)

CONDITION OF DISASTER AND SELECTED COUNTERMEASURE

No.	Disaster Spot No.	Km Type of Disaster	Existing Slope Condition		Water Condition	Factor for selection of countermeasure	Countermeasure	Remarks
			Dimension of slope	Geological Condition				
37	IK-40	240+100 E-D, F		<p>• Fresh ANDESITE</p>	<p>• High velocity of the river current.</p>	<p>• The existing grouted riprap are hanging.</p> <p>• Foundation of riprap was washed out.</p>	<p>• Gravity type Retaining wall.</p>	
38	IK-41	240+150 C-F		<p>• Highly jointed with developed cracks ANDESITE are slightly weathered.</p>	<p>• Slope surface water flows on the slope.</p>	<p>• Slope gradient is not so steep but almost optimum with very high slope.</p> <p>• Falling of rocks are expected in some parts of the slope.</p> <p>• Wide shoulder width.</p>	<p>• Removal</p> <p>• Anchor wire net (in some parts of the slope)</p> <p>• Catch Fence</p>	
39	IK-42	240+230 C-F		<p>• Slightly to moderately weathered ANDESITE rocks are highly jointed.</p>	<p>• Very little influence exists due to surface water.</p>	<p>• Not steep nor high slope.</p> <p>• Some detached rocks are on the slope.</p>	<p>• Removal</p> <p>• Anchor wire net</p>	
40	IK-43	240+350 C-F		<p>• Slightly to moderately weathered ANDESITE rocks are highly jointed.</p>	<p>• Very little influence due to surface water.</p> <p>• No water concentration on the slope.</p>	<p>• A little bit steeper slope, but slope is almost stable.</p> <p>• Some detached rocks are on the slope.</p>	<p>• Removal</p> <p>• Anchor wire net.</p>	

KENNON ROAD (II)

CONDITION OF DISASTER AND SELECTED COUNTERMEASURE

No.	Disaster Spot No.	Km Type of Disaster	Existing Slope Condition			Factor for selection of countermeasure	Countermeasure	Remarks
			Dimension of slope	Geological Condition	Water Condition			
41	IK-44	240+400 C-SF	<p>Concrete spraying W = 48 m</p>	<ul style="list-style-type: none"> <li>Moderately to highly weathered DIORITE rocks with highly developed cracks.</li> </ul>	<ul style="list-style-type: none"> <li>A little concentration of slope surface water exists.</li> </ul>	<ul style="list-style-type: none"> <li>Re-cutting</li> <li>Concrete spraying (t=10 cm)</li> </ul>		
42	IK-45(a)	240+500 C-F	<p>Concrete spraying W = 31</p>	<ul style="list-style-type: none"> <li>Moderately to highly weathered DIORITE rocks with highly developed cracks.</li> </ul>	<ul style="list-style-type: none"> <li>Very little influence of surface water on the spot.</li> </ul>	<ul style="list-style-type: none"> <li>Removal</li> <li>Concrete spraying (t=10)</li> <li>Anchor wire net.</li> </ul>		
43	IK-45(b)	240+500 E-D.F	<p>Concrete spraying Stone masonry W = 15</p>	<ul style="list-style-type: none"> <li>Embankment materials.</li> </ul>	<ul style="list-style-type: none"> <li>Concentration of road surface water exists.</li> <li>Embankment materials destroyed due to the concentration of road surface water.</li> </ul>	<ul style="list-style-type: none"> <li>Poor drainage facilities</li> <li>Existing grouted riprap was destroyed due to the concentration of road surface water.</li> </ul>	<ul style="list-style-type: none"> <li>Re-filling</li> <li>Stone masonry</li> <li>Side ditch</li> </ul>	
44	IK-46(a)	240+600 C-F	<p>Concrete spraying Re-cutting Almost vertical W = 28</p>	<ul style="list-style-type: none"> <li>Moderately to highly weathered DIORITE rocks with highly developed cracks.</li> </ul>	<ul style="list-style-type: none"> <li>Very little influence exists due to slope surface water.</li> </ul>	<ul style="list-style-type: none"> <li>Slope is not high but steep.</li> <li>There is a little progress of weathering.</li> </ul>	<ul style="list-style-type: none"> <li>Re-cutting.</li> <li>Concrete spraying (t=10 cm)</li> </ul>	



