



Drawings

Title	Drawing No.
<u>San Cancio</u>	
General Plan and Profile	SC-C-01
Diversion Weir and Intake	SC-C-02
Desilting Basin and Head Tank	SC-C-03
Powerhouse and Tailrace	SC-C-04
Duration Curves	SC-H-01
Geological Plan	SC-G-01
One Line Diagram	SC-E-01
<u>Intermedia</u>	
General Plan and Profile	IN-C-01
Powerhouse and Tailrace	IN-C-02
Duration Curves	IN-H-01
Geological Plan	IN-G-01
One Line Diagram	IN-E-01
<u>Municipal</u>	
General Plan and Profile	MU-C-01
Diversion Weir and Intake	MU-C-02
Desilting Basin	MU-C-03
Head Tank	MU-C-04
Powerhouse and Tailrace	MU-C-05
Duration Curves	MU-H-01
Geological Plan	MU-G-01
One Line Diagram	MU-E-01


GENERAL PLAN (S = 1/4000)



PROFILE (H = 1/4000 V = 1/400)



SECTION OF CHANNEL (S = 1/100)






JAPAN INTERNATIONAL COOPERATION AGENCY (JICA)
 INSTITUTO COLOMBIANO DE ENERGIA ELECTRICA (ICEL)
 FEASIBILITY STUDY ON SMALL-SCALE POWER PLANTS
 REHABILITATION PROJECT IN THE REPUBLIC OF COLOMBIA

GENERAL PLAN AND PROFILE


DRAWING NO.	SC-C-01
SCALE	1/4000
DATE	

DIVERSION WEIR & INTAKE


PLAN (s=1/200)



B - B



C - C



A - A


JAPAN INTERNATIONAL COOPERATION AGENCY (JICA)
 INSTITUTO COLOMBIANO DE ENERGIA ELECTRICA (ICEL)
 FEASIBILITY STUDY ON SMALL-SCALE POWER PLANTS
 REHABILITATION PROJECT IN THE REPUBLIC OF COLOMBIA

DIVERSION WEIR AND INTAKE


DRAWING NO. SC-C-02

SCALE 1/200 DATE


MODIFICATION OF DESILTING BASIN



DETAIL 'a' (S=1/50)







DETAIL 'b' (S=1/50)



RECONSTRUCTION OF HEAD TANK




PLAN (S=1/200)



JAPAN INTERNATIONAL COOPERATION AGENCY (JICA)			
INSTITUTO COLOMBIANO DE ENERGIA ELECTRICA (ICEL)			
FEASIBILITY STUDY ON SMALL-SCALE POWER PLANTS			
REHABILITATION PROJECT IN THE REPUBLIC OF COLOMBIA			
DESILTING BASIN AND HEAD TANK			
DRAWING NO.		SC - C - 03	
SCALE	1/200	DATE	


POWERHOUSE & TAIL RACE

PLAN (S-1/150)




JAPAN INTERNATIONAL COOPERATION AGENCY (JICA)			
INSTITUTO COLOMBIANO DE ENERGIA ELECTRICA (ICEL)			
FEASIBILITY STUDY ON SMALL-SCALE POWER PLANTS REHABILITATION PROJECT IN THE REPUBLIC OF COLOMBIA			
POWERHOUSE AND TAILRACE			
DRAWING NO.		SC - C - 04	
SCALE	1/150	DATE	

(1) MONTHLY MEAN VALUE OF DAILY AVERAGE FLOW AT G.S. SITE




(3) FLOW DURATION CURVE AT GAUGING STATION SITE




Data of Hydrological Gauging Station

No. of Station	6 - 939
Name of Station	Bocatoma
River	Chinchina
Management	CHEC
Installation Year - Month	---
Coordinates (Deg. - Min.)	---
Latitude	---
Longitude	---
Above Sea Level s.n.m. (m)	---
Long River (km)	---
Catchment Area (km ²)	---
Water Shed (m)	---
Observation Period	1979 - 1987


(2) MONTHLY MEAN VALUE OF DAILY AVERAGE FLOW AT INTAKE SITE



(4) TYPICAL FLOW DURATION CURVE AT INTAKE SITE





(5) UTILIZATION & CAPACITY FACTOR











JAPAN INTERNATIONAL COOPERATION AGENCY (JICA)
 INSTITUTO COLOMBIANO DE ENERGIA ELECTRICA (ICEL)
 FEASIBILITY STUDY ON SMALL-SCALE POWER PLANTS
 REHABILITATION PROJECT IN THE REPUBLIC OF COLOMBIA

DURATION CURVES


DRAWING NO.	SC - H - C 1
SCALE	DATE




LEGEND

-  River bed deposits
-  Talus deposits
-  Terrace deposits
-  Old debris flow deposits
-  Andesite lava
-  Crystalline schist
-  Geological boundary
-  Collapse




JAPAN INTERNATIONAL COOPERATION AGENCY (JICA)			
INSTITUTO COLOMBIANO DE ENERGIA ELECTRICA (ICEE)			
FEASIBILITY STUDY ON SMALL-SCALE POWER PLANTS REHABILITATION PROJECT IN THE REPUBLIC OF COLOMBIA			
Geological Plan San Cascio			
DRAWING NO.		SC-G-01	
SCALE	1/9,300	DATE	





JAPAN INTERNATIONAL COOPERATION AGENCY (JICA)	
INSTITUTO COLOMBIANO DE ENERGIA ELECTRICA (ICEL)	
FEASIBILITY STUDY ON SMALL-SCALE POWER PLANTS REHABILITATION PROJECT IN THE REPUBLIC OF COLOMBIA	
ONE LINE DIAGRAM <i>San Cancio</i>	
DRAWING NO.	SC-E-01
SCALE	DATE

POWERHOUSE & TAIL RACE
PLAN (S=1/100)







JAPAN INTERNATIONAL COOPERATION AGENCY (JICA)
 INSTITUTO COLOMBIANO DE ENERGIA ELECTRICA (ICEL)
 FEASIBILITY STUDY ON SMALL-SCALE POWER PLANTS
 REHABILITATION PROJECT IN THE REPUBLIC OF COLOMBIA

POWERHOUSE AND TAILRACE

DRAWING NO. IN-C-02


SCALE 1/100 DATE

12-8





Data of Hydrological Gauging Station








No. of Station	6 - 939
Name of Station	Bocatoma
River	Chinchina
Management	CHEC
Installation Year - Month	---
Coordinates (Deg. - Min.)	---
Latitude	---
Longitude	---
Above Sea Level s.n.m. (m)	---
Long River (km)	---
Catchment Area (km ²)	---
Water Shed (m)	---
Observation Period	1979 - 1987



12-70




LEGEND

-  River bed deposits
-  Detritus
-  Talus deposits
-  Terrace deposits
-  Old debris flow deposits
-  Geological boundary
-  Collapse

JAPAN INTERNATIONAL COOPERATION AGENCY (JICA) INSTITUTO COLOMBIANO DE ENERGIA ELECTRICA (ICE) FEASIBILITY STUDY ON SMALL-SCALE POWER PLANTS REHABILITATION PROJECT IN THE REPUBLIC OF COLOMBIA		
Geological Plan Intermedia		
DRAWING NO.	IN-G-01	
SCALE	1/9,300	DATE







JAPAN INTERNATIONAL COOPERATION AGENCY (JICA)			
INSTITUTO COLOMBIANO DE ENERGIA ELECTRICA (ICEL)			
FEASIBILITY STUDY ON SMALL-SCALE POWER PLANTS			
REHABILITATION PROJECT IN THE REPUBLIC OF COLOMBIA			
ONE LINE DIAGRAM			
<i>Intermedia</i>			
DRAWING NO.		IN-E-01	
SCALE	---	DATE	

12-11

GENERAL PLAN (S=1/4000)





PROFILE (H=1/4000, V=1/400)



LEFT BANK LEVEL	1780.56	1780.20	1780.01	1779.80	1779.60	1779.79	1779.65	1779.77	1779.22	1779.19	1779.06	1778.94	1778.92	1778.89	1778.98	1778.24	1778.09	1777.93	1777.89	1777.69	1777.55	1777.46	1777.28	1776.99	1776.92	
FORMATION LEVEL	1778.69			1778.25	1778.25																					1775.33
ACCUMULATED DISTANCE	0	100.0	200.0	280.0	300.0	400.0	500.0	600.0	700.0	800.0	900.0	1000.0	1100.0	1200.0	1300.0	1400.0	1500.0	1600.0	1700.0	1800.0	1900.0	2000.0	2100.0	2200.0	2300.0	2390.0
DISTANCE	0	100.0	100.0	80.0	20.0	100.0	100.0	100.0	100.0	100.0	100.0	100.0	100.0	100.0	100.0	100.0	100.0	100.0	100.0	100.0	100.0	100.0	100.0	100.0	100.0	90.0
STATION	0+0	0+100	0+200	0+300	0+300	0+400	0+500	0+600	0+700	0+800	0+900	1+0	1+100	1+200	1+300	1+400	1+500	1+600	1+700	1+800	1+900	2+0	2+100	2+200	2+300	2+390


SECTION OF CHANNEL (S=1/100)





JAPAN INTERNATIONAL COOPERATION AGENCY (JICA)	
INSTITUTO COLOMBIANO DE ENERGIA ELECTRICA (ICEL)	
FEASIBILITY STUDY ON SMALL-SCALE POWER PLANTS REHABILITATION PROJECT IN THE REPUBLIC OF COLOMBIA	
GENERAL PLAN AND PROFILE (ALT-2)	
DRAWING NO.	MU-C-01
SCALE	1/4000
DATE	

12-73


DIVERSION WEIR & INTAKE PLAN (S=1/100)



LOCATION OF RECONSTRUCTION AREA (S=1/250)



A - A



B - B



JAPAN INTERNATIONAL COOPERATION AGENCY (JICA)
 INSTITUTO COLOMBIANO DE ENERGIA ELECTRICA (ICEL)
 FEASIBILITY STUDY ON SMALL-SCALE POWER PLANTS
 REHABILITATION PROJECT IN THE REPUBLIC OF COLOMBIA

DIVERSION WEIR AND INTAKE (ALT-2)


DRAWING NO.		MU-C-02	
SCALE	1/100	DATE	

12-14

DESILTING BASIN
PLAN (S=1/150)



WITH CONCRETE RAISED



JAPAN INTERNATIONAL COOPERATION AGENCY (JICA)
INSTITUTO COLOMBIANO DE ENERGIA ELECTRICA (ICEL)
FEASIBILITY STUDY ON SMALL-SCALE POWER PLANTS
REHABILITATION PROJECT IN THE REPUBLIC OF COLOMBIA


DESILTING BASIN (ALT-2)

DRAWING NO. MU-C-03

SCALE 1/150 DATE

1275




HEAD TANK PLAN (S-1/100)



JAPAN INTERNATIONAL COOPERATION AGENCY (JICA)			
INSTITUTO COLOMBIANO DE ENERGIA ELECTRICA (ICEL)			
FEASIBILITY STUDY ON SMALL-SCALE POWER PLANTS REHABILITATION PROJECT IN THE REPUBLIC OF COLOMBIA			
HEAD TANK (ALT-2)			
DRAWING NO.		MU-C-04	
SCALE	1/100	DATE	

12-16

POWERHOUSE & TAILRACE
PLAN (S-1/150)



A - A


JAPAN INTERNATIONAL COOPERATION AGENCY (JICA)
INSTITUTO COLOMBIANO DE ENERGIA ELECTRICA (ICEL)
FEASIBILITY STUDY ON SMALL-SCALE POWER PLANTS
REHABILITATION PROJECT IN THE REPUBLIC OF COLOMBIA

POWERHOUSE AND TAILRACE (ALT-2)


DRAWING NO. MU-C-05

SCALE 1/150 DATE

(1)
MONTHLY MEAN VALUE OF DAILY AVERAGE FLOW AT G.S. SITE




(3)
FLOW DURATION CURVE AT GAUGING STATION SITE




Data of Hydrological Gauging Station

No. of Station	6 - 939
Name of Station	Bocatoma
River	Chinchina
Management	CHEC
Installation Year - Month	---
Coordinates (Deg. - Min.)	
Latitude	---
Longitude	---
Above Sea Level s.n.m. (m)	---
Long River (km)	---
Catchment Area (km ²)	---
Water Shed (m)	---
Observation Period	1979 - 1987


(2)
MONTHLY MEAN VALUE OF DAILY AVERAGE FLOW AT INTAKE SITE



(4)
TYPICAL FLOW DURATION CURVE AT INTAKE SITE



(5)
UTILIZATION & CAPACITY FACTOR





JAPAN INTERNATIONAL COOPERATION AGENCY (JICA)
INSTITUTO COLOMBIANO DE ENERGIA ELECTRICA (ICEL)
FEASIBILITY STUDY ON SMALL-SCALE POWER PLANTS
REHABILITATION PROJECT IN THE REPUBLIC OF COLOMBIA










DURATION CURVES

DRAWING NO.	MU - H - 01
SCALE	---
DATE	---


12-118



LEGEND

-  River bed deposits
-  Detritus
-  Talus deposits
-  Terrace deposits
-  Old debris flow deposits
-  Sandstone
-  Crystalline schist
-  Geological boundary
-  Collapse

JAPAN INTERNATIONAL COOPERATION AGENCY (JICA) INSTITUTO COLOMBIANO DE ENERGIA ELECTRICA (ICEL) FEASIBILITY STUDY ON SMALL-SCALE POWER PLANTS REHABILITATION PROJECT IN THE REPUBLIC OF COLOMBIA			
Geological Plan Municipal			
DRAWING NO.		MU-G-01	
SCALE	1/9,300	DATE	



JAPAN INTERNATIONAL COOPERATION AGENCY (JICA)			
INSTITUTO COLOMBIANO DE ENERGIA ELECTRICA (ICEL)			
FEASIBILITY STUDY ON SMALL-SCALE POWER PLANTS			
REHABILITATION PROJECT IN THE REPUBLIC OF COLOMBIA			
ONE LINE DIAGRAM			
<i>Municipal (ALT-2)</i>			
DRAWING NO.		MU-E-01	
SCALE	—	DATE	

Attached Data

1. Facility Register for the Existing Power Plant
2. Survey Record

Facility Register for the Existing Power Plant

Power Plant	San Cancio
Electric Power Company	CHEC
Location	Manizales/Caldas
River	Chinchina
Generating Method	Run-of-River
Year Installed	1929/1947
Years in Service	
Installed Capacity	2,320 kW
Available Capacity	1,750 kW

Civil

Item	Data	
1. Dam		
1) Type	<i>concrete, gravity</i>	
2) Height (m)	<i>1912.06 ~ 1908.51 3.55</i>	
3) Crest length (m)	<i>17.7</i>	
4) Height of overflowing crest (m)	<i>1912.06</i>	
5) Width of overflowing crest (m)	<i>9.8</i>	
6) Depth of overflowing crest (m)	<i>no data available</i>	
2. Intake Gate		
1) Type	<i>sluice</i>	
2) Number of gates	<i>2</i>	
3) Dimensions (W x H)(m)	<i>no data available</i>	
3. Intake		
1) Intake sill height (m)	<i>1910.02</i>	
2) Number of intake	<i>2</i>	
3) Dimensions (W x H)(m)	<i>1.9 x 1.3 3.4 x 2.4</i>	
4. Desilting Basin	<i>No.1</i>	<i>No.2</i>
1) Dimensions (W x L x H)(m)	<i>9.9 x 43.1 x 2.7</i>	<i>14.2 x 21.8 x 5.1</i>
5. Sand Trap Gate		
1) Type	<i>sluice</i>	<i>sluice</i>
2) Number of gates	<i>1</i>	<i>1</i>
3) Dimensions (W x H)(m)	<i>1.2 x 1.2</i>	<i>1.6 x 1.2</i>
6. Headrace		
1) Type	<i>open channel</i>	
2) Dimensions (W x H)(m)	<i>average 1.6 x 1.7</i>	
3) Length (m)	<i>2.363</i>	

Civil

Item	Data
7. Reservoir Tank	
1) Dimensions (W x L x H)(m)	4.8 x 29.8 x 5.8
8. Forebay	
1) Dimensions (W x H)(m)	no data available
9. Penstock	
1) Number of lines	1
2) Penstock diameter (d)(m)	12.4
3) Penstock length (L)(m)	231.209
10. Tailrace	
1) Dimensions (W x H)(m)	no data available

Equipment

Item	Data	
	# 2	# 1
1. Water Turbine		
1) Manufacturer's name	Leffel	Voith
2) Year manufactured	1947	1929
3) Type	Francis	Pelton
4) Output (kW)	1,800FHP	1,609 HP
5) Revolution (rpm)	600	257
6) Ancillary equipment		
a) Type of governor	Mechanical Hydraulic	Mechanical Hydraulic
b) Inlet valve		
- Type	Gate	Gate
- Diameter (mm)	1,240	1,240
2. Generator and Exciter		
1) Manufacturer's name	GE	Siemens
2) Year manufactured	1947	1929
3) Type	Synchro.	Synchro.
4) Capacity (kVA)	1,500	1,400
5) Power factor (%)	80	80
6) Voltage (V)	4,160	4,000
7) Frequency (Hz)	60	60
8) Revolution (rpm)	600	257
9) Method of neutral earthing	direct	direct
10) Type of exciter	<i>no data available</i>	

Equipment

Item	Data
3. Transformer	
1) Manufacturer's name	N/A
2) Year manufactured	
3) Type	
4) Capacity (kVA)	
5) Primary voltage (kV)	
6) Secondary voltage (kV)	
7) Number of unit	
8) Vector-group symbol	
9) Impedance (%)	
10) Purpose for use	
4. Circuit Breaker	
1) Manufacturer's name	<i>no data available</i>
2) Year manufactured	
3) Type	
4) Voltage (kV)	
5) Rated current (A)	
6) Rupturing capacity (kA)	
7) Purpose for use	
5. Transmission Line	
1) Destination	Marmato S/S
2) Length (m)	<i>no data available</i>
3) Voltage (kV)	4.16
4) Number of circuit	1
5) Number of pylons	<i>no data available</i>
6) Size of conductors	,"
7) Materials of conductors	,"

Equipment

Item	Data
6. Battery	N/A
1) Manufacturer's name	
2) Year manufactured	
3) Capacity (AH/HR)	
4) DC voltage (V)	
5) Type	
7. Battery Charger	N/A
1) Manufacturer's name	
2) Year manufactured	
3) Capacity	
4) Incoming voltage (V)	
8. Overhead Crane	
1) Weight (ton)	15
2) Method of operation	Manual
3) Span (m)	<i>no data available</i>

Facility Register for the Existing Power Plant

Power Plant	Intermedia
Electric Power Company	CHEC
Location	Manizales/Caldas
River	Chinchina
Generating Method	Run-of-River
Year Installed	1947
Years in Service	1947
Installed Capacity	1,120 kW
Available Capacity	900 kW

Civil

Item	Data
1. Dam	N/A
1) Type	
2) Height (m)	
3) Crest length (m)	
4) Height of overflowing crest (m)	
5) Width of overflowing crest (m)	
6) Depth of overflowing crest (m)	
2. Intake Gate	N/A
1) Type	
2) Number of gates	
3) Dimensions (W x H)(m)	
3. Intake	N/A
1) Intake sill height (m)	
2) Number of intake	
3) Dimensions (W x H)(m)	
4. Desilting Basin	N/A
1) Dimensions (W x L x H)(m)	
5. Sand Trap Gate	N/A
1) Type	
2) Number of gates	
3) Dimensions (W x H)(m)	
6. Headrace	
1) Type	<i>open ditch (no lining)</i>
2) Dimensions (W x H)(m)	<i>average 2.80 x 1.60</i>
3) Length (m)	<i>3140</i>

Civil

Item	Data
7. Reservoir Tank	
1) Dimensions (W x L x H)(m)	7.9 x 72.1 x 4.5
8. Forebay	
1) Dimensions (W x H)(m)	N/A
9. Penstock	
1) Number of lines	1
2) Penstock diameter (d)(m)	1.24
3) Penstock length (L)(m)	153.533
10. Tailrace	
1) Dimensions (W x H)(m)	N/A

Equipment	
Item	Data
1. Water Turbine	
1) Manufacturer's name	Voith
2) Year manufactured	1935
3) Type	Pelton
4) Output (kW)	1,120
5) Revolution (rpm)	257
6) Ancillary equipment	
a) Type of governor	Mechanical Hydraulic
b) Inlet valve	
- Type	Gate
- Diameter (mm)	1,240
2. Generator and Exciter	
1) Manufacturer's name	Siemens
2) Year manufactured	1935
3) Type	Synchro.
4) Capacity (kVA)	1,400
5) Power factor (%)	80
6) Voltage (V)	4,000
7) Frequency (Hz)	60
8) Revolution (rpm)	257
9) Method of neutral earthing	direct
10) Type of exciter	no data available

Equipment

Item	Data
3. Transformer	N/A
1) Manufacturer's name	
2) Year manufactured	
3) Type	
4) Capacity (kVA)	
5) Primary voltage (kV)	
6) Secondary voltage (kV)	
7) Number of unit	
8) Vector-group symbol	
9) Impedance (%)	
10) Purpose for use	
4. Circuit Breaker	<i>no data available</i>
1) Manufacturer's name	
2) Year manufactured	
3) Type	
4) Voltage (kV)	
5) Rated current (A)	
6) Rupturing capacity (kA)	
7) Purpose for use	
5. Transmission Line	
1) Destination	Marmato S/S
2) Length (m)	<i>no data available</i>
3) Voltage (kV)	4.16
4) Number of circuit	1
5) Number of pylons	<i>no data available</i>
6) Size of conductors	
7) Materials of conductors	

Equipment

Item	Data
6. Battery	N/A
1) Manufacturer's name	
2) Year manufactured	
3) Capacity (AH/HR)	
4) DC voltage (V)	
5) Type	
7. Battery Charger	N/A
1) Manufacturer's name	
2) Year manufactured	
3) Capacity	
4) Incoming voltage (V)	
8. Overhead Crane	
1) Weight (ton)	15
2) Method of operation	Manual
3) Span (m)	<i>no data available</i>

Facility Register for the Existing Power Plant

Power Plant	Municipal
Electric Power Company	CHEG
Location	Manizales/Caldas
River	Chinchina
Generating Method	Run-of-River
Year Installed	1945
Years in Service	1945
Installed Capacity	2,112 kW
Available Capacity	1,400 kW

Civil

Item	Data
1. Dam	
1) Type	<i>concrete, gravity</i>
2) Height (m)	<i>2.5</i>
3) Crest length (m)	<i>34.0</i>
4) Height of overflowing crest (m)	<i>1781.798</i>
5) Width of overflowing crest (m)	<i>21.25</i>
6) Depth of overflowing crest (m)	<i>no data available</i>
2. Intake Gate	<i>N/A</i>
1) Type	
2) Number of gates	
3) Dimensions (W x H)(m)	
3. Intake	
1) Intake sill height (m)	<i>1779.548</i>
2) Number of intake	<i>2</i>
3) Dimensions (W x H)(m)	<i>5.4 x 2.8 2.3 x 1.7</i>
4. Desilting Basin	
1) Dimensions (W x L x H)(m)	<i>17.6 x 30.6 x 4.6</i>
5. Sand Trap Gate	
1) Type	<i>sluice</i>
2) Number of gates	<i>1</i>
3) Dimensions (W x H)(m)	<i>1.2 x 1.2</i>
6. Headrace	
1) Type	<i>open channel</i>
2) Dimensions (W x H)(m)	<i>2.20 x 1.70</i>
3) Length (m)	<i>2,390</i>

Civil

Item	Data
7. Reservoir Tank	
1) Dimensions (W x L x H)(m)	10 x 23 x 2.6
8. Forebay	N/A
1) Dimensions (W x H)(m)	
9. Penstock	
1) Number of lines	1
2) Penstock diameter (d)(m)	1.52
3) Penstock length (L)(m)	157.83
10. Tailrace	
1) Dimensions (W x H)(m)	no data available

Equipment

Item	Data	
	#1	#2
1. Water Turbine		
1) Manufacturer's name	<i>no data available</i>	
2) Year manufactured	1935	1935
3) Type	Pelton	Pelton
4) Output (kW)	1,769 HP	1,769 HP
5) Revolution (rpm)	360	360
6) Ancillary equipment		
a) Type of governor	Mechanical Hydraulic	Mechanical Hydraulic
b) Inlet valve		
- Type	Gate	Gate
- Diameter (mm)	1,520	1,520
2. Generator and Exciter		
1) Manufacturer's name	ASEA	ASEA
2) Year manufactured	1935	1935
3) Type	Synchro.	Synchro.
4) Capacity (kVA)	1,320	1,320
5) Power factor (%)	80	80
6) Voltage (V)	4,300	4,300
7) Frequency (Hz)	60	60
8) Revolution (rpm)	360	360
9) Method of neutral earthing	direct	direct
10) Type of exciter	<i>no data available</i>	

Equipment

Item	Data
3. Transformer	
1) Manufacturer's name	ASEA
2) Year manufactured	1945
3) Type	Outdoor, ONAN
4) Capacity (kVA)	900 x 3
5) Primary voltage (kV)	4.3
6) Secondary voltage (kV)	13.2
7) Number of unit	1
8) Vector-group symbol	D/Y
9) Impedance (%)	<i>no data available</i>
10) Purpose for use	Step-up
4. Circuit Breaker	
1) Manufacturer's name	ASEA
2) Year manufactured	
3) Type	OCB
4) Voltage (kV)	13.2
5) Rated current (A)	<i>no data available</i>
6) Rupturing capacity (kA)	"
7) Purpose for use	transmission line
5. Transmission Line	
1) Destination	Marmato S/S
2) Length (m)	<i>no data available</i>
3) Voltage (kV)	13.2
4) Number of circuit	2
5) Number of pylons	<i>no data available</i>
6) Size of conductors	"
7) Materials of conductors	"

Equipment

Item	Data
6. Battery	N/A
1) Manufacturer's name	
2) Year manufactured	
3) Capacity (AH/HR)	
4) DC voltage (V)	
5) Type	
7. Battery Charger	N/A
1) Manufacturer's name	
2) Year manufactured	
3) Capacity	
4) Incoming voltage (V)	
8. Overhead Crane	
1) Weight (ton)	10
2) Method of operation	Manual
3) Span (m)	<i>no data available</i>

Survey Records

San Cancio Hydroelectric Power Plant

Date of Survey : 13~14 Feb. 1989

I. RECORDS BY VISUAL INSPECTION AND HEARING SURVEY

Unit No.: 1
 Type of Turbine: Pelton

Generating Facilities	Check item by visual inspection and hearing	Results
Pelton Turbine	1) Presence of vibration 1) Existence of corrosion 1) Shaking of shaft axis 1) Oil shortage on bearing surface 2) Lack of oil viscosity 1) Control by belt-driven type 2) Speed detection device 3) Speed regulation system 4) Installation of load limiter 5) Accuracy of governor speed regulation	1) Normal 1) Corrosion: not existing Abrasion: existing 1) No objection 1) " " " " 2) " " " " 1) Belt driven 2) Speeder 3) Manual 4) N/A 5) Poor accuracy (low response)

Generating Facilities	Check item by visual inspection and hearing	Results
Pelton Turbine	Oil pressure equipment	1) Existence of oil leakage 2) Application of oil pressure pumping system
	Inlet valve	1) Operation method 2) Locking condition 3) Smoothness of pressurized oil operation
	Nozzle and Needle	1) Existence of corrosion 2) Presence of water leakage from nozzle pipe when needle is closed
	Deflector	1) Smoothness of control
	Jet Brake	1) Smoothness of control

Unit No. 7

Generating Facilities	Check item by visual inspection and hearing	Results
Rotor	1) Discoloration of winding surface due to heat 2) Existence of erosion for core 3) Fitness of between rotor and shaft	1) No objection 2) " 3) "
Stator winding	1) Frequency of burning trouble or repair 2) Reduction of insulation resistance 3) Rust and erosion of core	1) " 2) Reducing due to being advanced in year 3) No objection
Bearing	1) Occurrence of deformation on metal surface 2) Lack of oil lubrication 3) Occurrence of temperature rise	1) Repair work has been done every 2 years 2) No objection 3) "
Exciter	1) Exchange frequency of brushes worn out 2) Sufficient stock of spare brush	1) Every 2 months 2) Sufficient
Voltage regulator	1) Operation method of voltage regulator 2) Response of voltage detection for load variation	1) Manual (control panel) 2) Voltage is always regulated by operator

Generator for Pelton

Unit No.: 2

Type of Turbine: Francis

Generating Facilities	Check item by visual inspection and hearing	Results
Casing	1) Existence of corrosion 2) Wear in thickness 3) Presence of vibration	1) No objection (interior was painted) 2) " 3) "
Runner	1) Existence of corrosion 2) Occurrence of porosity by sand pitting	1) a little (due to cavitation) 2) "
Shaft	1) Shaking of shaft axis	1) No objection
Bearing	1) Oil shortage on bearing surface 2) Lack of oil viscosity	1) " 2) "
Governor control	1) Control by belt-driven type 2) Speed detection device 3) Speed regulation system 4) Installation of load limiter 5) Accuracy of governor speed regulation	1) motor 2) speeder 3) automatic 4) N/A 5) not so good (low response)

Francis Turbine

Generating Facilities	Check item by visual inspection and hearing	Results
Francis Turbine	Oil pressure equipment	1) A little, but no objection to operation 2) Shaft driven for lubrication and cooling Motor driven for Governor (A.C. 220V, 2HP)
	Inlet valve	1) Manual and motor 2) No objection 3) N/A
	Guide vanes	1) No objection 2) A little, but no objection to operation 3) 3 or 4 per Year
	Sealing device	1) N/A 2) Sufficient (material: Teflon)

Unit No.

Z

Generating Facilities	Check item by visual inspection and hearing	Results
Generator for Francis	Rotor Stator winding Bearing Exciter	1) No objection 2) " 3) " 1) " 2) Reducing due to being advanced in years. 3) No objection 1) Repair work has been done every 2 years 2) No objection 3) " 1) Every 2 months 2) Sufficient
Voltage regulator	1) Operation method of voltage regulator 2) Response of voltage detection for load variation	1) Manual (control panel) 2) Voltage is always regulated by operator

Generating Facilities	Check item by visual inspection and hearing	Results
Metering equipment	1) Sufficiency of accuracy for instruments 2) Lack of necessary instruments 3) Items constantly recorded	It is necessary to calibrate due to being 1) advanced in years. 2) Sufficient 3) Gen.: A, V, W, Wh, Hz, Casp, Ex.: A, V Turbine Pressure, rpm
Protection equipment	1) Lack of relays to be installed 2) Operation method in case of accident in transmission lines	1) Sufficient 2) 52G is tripped by 50/51
Remote control equipment	1) Control method for turbine and generator operation 2) Control method for voltage and speed control 3) Operation method of synchronized switching	Remote control panel is not provided. 1) Voltage: manual (local control panel) Speed: Francis - motor or manual 3) Manual
Power system	1) Power supply voltage (kV) after rehabilitation work	1) 4.16 kV

Control Board

Generating Facilities	Check item by visual inspection and hearing	Results
Indoor Switchgear	<ul style="list-style-type: none"> 1) Sufficiency of insulation level 2) Unification of insulation level 3) Reduction of insulation resistance_s 1) Accessibility to high voltage devices 2) Sufficiency of protection for high voltage cable terminals 3) Method and reliability of operation for synchronizing circuit breaker 	<ul style="list-style-type: none"> 1) Sufficient (4.16kv) 2) Unified (4.16kv) 3) No objection 1) Safety 2) Sufficient 3) Manual It is reliable.

Generating Facilities	Check item by visual inspection and hearing	Results
Transformer	1) Presence of over load operation	1) N/A
Circuit breaker	1) Situation of trip for outgoing feeder breaker in case of accident on transmission line 2) Fitness of maintenance in case of oil circuit breaker	1) " 2) "
Line switch	1) Operation method 2) Reliability of operation	1) Manual 2) It is not reliable.
Insulator	1) Presence of damage and dusts	1) No objection
Structural steel	1) Occurrence of erosion due to rust 2) Presence of injury	1) " 2) "
Line protection	1) Existence of adequate protection relays to connect to RED	1) 50/51

Outdoor Equipment

III. REPAIR RECORDS

No.	Study Item	Results
	<p>The past records concerning the following items shall be obtained to evaluate reliability of generating facilities.</p> <ol style="list-style-type: none"> 1) Repaired locations and method for repairing 2) Causes for damage/defect 3) Duration of repairing and power supply stoppage 4) Repaired by; <ol style="list-style-type: none"> a) staff in Power Plant b) manufacturer c) other 5) Repair cost 6) Operation life after the completion of repairing work 	<p><i>Without available informations</i></p>

IV . SITUATION OF STOCK SPARE PARTS

No.	Study Item	Results
	<p>Data on the situation of stock spare parts shall be obtained to evaluate maintainability of generating facilities.</p>	<p>1) Following spare parts have been made in CHEC's repair shop.</p> <ul style="list-style-type: none"> a. Bucket for Pelton b. Needle " c. Nozzle " d. Sealing for Valves e. Guide vane for Francis f. Bolts and nuts

V. CHEC'S INTENTION FOR REHABILITATION

No.	Study Item	Results		
	Make with/ in pertinent columns.			
-	Inlet valve	✓		*-1 Change to
-	Turbine, governor, auxiliary equipment			
-	Generator, exciter			
-	Control panel	✓		Pelton: V. (change to Francis) efficiency machi
-	Switchgear			*-2
-	Transformer			Good condition
-	Substation equipment (Circuit breaker, Isolator, etc.)			
-	Transmission tower, conductor and insulator	✓		Good condition
-	Power House	✓		Depend on F/S
-	Penstock	✓		Already char 5 years ago.
		*-1 : Change to full automatic (52G trip and Inlet Valve is closed automatically.)		
		*-2 : Generator Francis Stator winding should be change Pelton Replace Exciter Leaving as it is Replace		

Survey Records

Intermedia Hydroelectric Power Plant

Date of Survey : 13 ~ 14 Feb. 1989

I. RECORDS BY VISUAL INSPECTION AND HEARING SURVEY

Unit No.:
 Type of Turbine: Pelton

Generating Facilities	Check item by visual inspection and hearing	Results
Pelton Turbine	1) Presence of vibration 1) Existence of corrosion 1) Shaking of shaft axis 1) Oil shortage on bearing surface 2) Lack of oil viscosity 1) Control by belt-driven type 2) Speed detection device 3) Speed regulation system 4) Installation of load limiter 5) Accuracy of governor speed regulation	1) Normal 1) Corrosion: not existing Abrasion: a little existing 1) No objection 1) " 2) " 1) Belt driven 2) Speeder 3) Manual 4) N/A 5) poor accuracy (low response)

Generating Facilities	Check item by visual inspection and hearing	Results	
Pelton Turbine	Oil pressure equipment	1) Existence of oil leakage 2) Application of oil pressure pumping system	1) A little, but no objection to operation. 2) Shaft driven
	Inlet valve	1) Operation method 2) Locking condition 3) Smoothness of pressurized oil operation	Motor (A.C. 220V, 2.3kw), control from local control panel 2) No objection 3) N/A
	Nozzle and Needle	1) Existence of corrosion 2) Presence of water leakage from nozzle pipe when needle is closed	Corrosion: not existing 1) Abrasion: a little 2) No objection
	Deflector	1) Smoothness of control	1) No objection
	Jet Brake	1) Smoothness of control	1) N/A

Unit No. /

Generating Facilities	Check item by visual inspection and hearing	Results
Generator	Rotor	1) No objection 2) " 3) "
	Stator winding	1) " 2) Reducing due to being advanced in year. 3) No objection
	Bearing	1) Deformation is existing. 2) No objection 3) "
	Exciter	1) Every 2 months 2) Sufficient
	Voltage regulator	1) Manual 2) Voltage is always regulated by operator.

Generating Facilities	Check item by visual inspection and hearing	Results
Metering equipment	1) Sufficiency of accuracy for instruments 2) Lack of necessary instruments 3) Items constantly recorded	1) Not so good 2) Sufficient 3) Gen.: A, V, W, Wh, Hz, cosφ Ex.: A, V Turbine speed, rpm
Protection equipment	1) Lack of relays to be installed 2) Operation method in case of accident in transmission lines	1) Sufficient 2) 52 G is tripped by 50/51
Remote control equipment	1) Control method for turbine and generator operation 2) Control method for voltage and speed control 3) Operation method of synchronized switching	1) Remote control panel is not provided. 2) Voltage = manual (local control panel) Speed = manual 3) Manual
Power system	1) Power supply voltage (kV) after rehabilitation work	1) 4.16 kV

Control Board

Generating Facilities	Check item by visual inspection and hearing	Results
Indoor Switchgear	<p>1) Sufficiency of insulation level</p> <p>2) Unification of insulation level</p> <p>3) Reduction of insulation resistance</p> <p>1) Accessibility to high voltage devices</p> <p>2) Sufficiency of protection for high voltage cable terminals</p> <p>3) Method and reliability of operation for synchronizing circuit breaker</p>	<p>1) Sufficient</p> <p>2) Unified</p> <p>3) No objection</p> <p>1) Safety</p> <p>2) Sufficient</p> <p>3) Manual It is reliable.</p>

Generating Facilities	Check item by visual inspection and hearing	Results
Outdoor Equipment	Transformer	1) N/A
	Circuit breaker	1) / 2) /
	Line switch	1) Manual 2) It is not reliable
	Insulator	1) No objection
	Structural steel	1) / 2) "
	Line protection	1) Existence of adequate protection relays to connect to RED 2) 50/51

III. REPAIR RECORDS

No.	Study Item	Results
	<p>The past records concerning the following items shall be obtained to evaluate reliability of generating facilities.</p> <ol style="list-style-type: none"> 1) Repaired locations and method for repairing 2) Causes for damage/defect 3) Duration of repairing and power supply stoppage 4) Repaired by; <ol style="list-style-type: none"> a) staff in Power Plant b) manufacturer c) other 5) Repair cost 6) Operation life after the completion of repairing work 	<p><i>without available informations</i></p>

IV . SITUATION OF STOCK SPARE PARTS

No.	Study Item	Results
	<p>Data on the situation of stock spare parts shall be obtained to evaluate maintainability of generating facilities.</p> <p>ditto 1-</p>	<p>1) Following spare parts have been made in CHEC's repair shop.</p> <ul style="list-style-type: none"> a. Bucket for Pelton b. Needle " " c. Nozzle " " d. Sealing for valve e. Bolts and nuts

V. CHEC's INTENTION FOR REHABILITATION

No.	Study Item	Results			
		<u>Leaving as it is</u>	<u>Repair work</u>	<u>Replacement</u>	<u>Notes</u>
	Mark with ✓ in pertinent columns.				
	- Inlet valve		✓		*-1 Change to high efficiency machine
	- Turbine, governor, auxiliary equipment			✓	(change to Francis) efficiency machine
	- Generator, exciter		✓		change to stator winding
	- Control panel		✓		only Calibration
	- Switchgear	✓			Good condition
	- Transformer	N/A			
	- Substation equipment (Circuit breaker, Isolator, etc.)	N/A			
	- Transmission tower, conductor and insulator	✓			Good condition
	- Power House		✓		Depend on F/s
	- Penstock	✓			Already change 5 years ago.
					*-1: Change to full automatic (52 G trip and Inlet valve closed automatically.)

Survey Records


Municipal Hydroelectric Power Plant

Date of Survey : 13~14 Feb. 1989

I. RECORDS BY VISUAL INSPECTION AND HEARING SURVEY

Unit No.: _____ / _____

Type of Turbine: Pelton



Generating Facilities	Check item by visual inspection and hearing	Results
Pelton Turbine	Cover	1) A little, but no objection to operation
	Bucket	1) Corrosion : not existing 1) Abrasion : a little existing
	Shaft	1) No objection
	Bearing	1) " " 2) " "
	Governor control	1) } Not existing due to broken 2) } 3) }
		4) N/A
		5) can't regulate due to not existing

Generating Facilities	Check item by visual inspection and hearing	Results	
Pelton Turbine	Oil pressure equipment	1) Existence of oil leakage 2) Application of oil pressure pumping system	1) N/A 2) N/A
	Inlet valve	1) Operation method 2) Locking condition 3) Smoothness of pressurized oil operation	1) Manual 2) No objection 3) N/A
	Nozzle and Needle	1) Existence of corrosion 2) Presence of water leakage from nozzle pipe when needle is closed	Corrosion : not existing 1) Abrasion : a little existing 2) Runner is rotating when needle is closed.
	Deflector	1) Smoothness of control	1) not provided
	Jet Brake	1) Smoothness of control	1) N/A

Unit No. /

Generating Facilities	Check item by visual inspection and hearing	Results
Rotor	1) Discoloration of winding surface due to heat 2) Existence of erosion for core 3) Fitness of between rotor and shaft	1) No objection 2) " 3) "
Stator winding	1) Frequency of burning trouble or repair 2) Reduction of insulation resistance 3) Rust and erosion of core	1) " It is about the time to change to the new one due to reduction. 2) No objection
Bearing	1) Occurrence of deformation on metal surface 2) Lack of oil lubrication 3) Occurrence of temperature rise	1) Repair work has been done every 2 years 2) No objection 3) Occurred several times
Exciter	1) Exchange frequency of brushes worn out 2) Sufficient stock of spare brush	1) Every 2 months 2) Sufficient
Voltage regulator	1) Operation method of voltage regulator 2) Response of voltage detection for load variation	1) Manual 2) Voltage is always regulated by operator.

Generator

Unit No.: 2
 Type of Turbine: Pelton

Generating Facilities	Check item by visual inspection and hearing	Results
Pelton Turbine	Cover	1) A little existing
	Bucket	Corrosion: not existing 1) Abrasion: a little existing
	Shaft	1) No objection
	Bearing	1) \approx 2) \approx
	Governor control	1) Control by belt-driven type 2) Speed detection device 3) Speed regulation system 4) Installation of load limiter 5) Accuracy of governor speed regulation

Generating Facilities	Check item by visual inspection and hearing	Results
Pelton Turbine	Oil pressure equipment 1) Existence of oil leakage 2) Application of oil pressure pumping system	1) N/A 2) N/A
	Inlet valve 1) Operation method 2) Locking condition 3) Smoothness of pressurized oil operation	1) Manual 2) No objection 3) N/A
	Nozzle and Needle 1) Existence of corrosion 2) Presence of water leakage from nozzle pipe when needle is closed	Corrosion : not existing 1) Abrasion : a little existing 2) Runner is rotating when needle is closed.
	Deflector 1) Smoothness of control	1) not provided
	Jet Brake 1) Smoothness of control	1) N/A

Generating Facilities	Check item by visual inspection and hearing	Results
Indoor Switchgear	<p>1) Sufficiency of insulation level</p> <p>2) Unification of insulation level</p> <p>3) Reduction of insulation resistance</p> <p>1) Accessibility to high voltage devices</p> <p>2) Sufficiency of protection for high voltage cable terminals</p> <p>3) Method and reliability of operation for synchronizing circuit breaker</p>	<p>1) <i>Sufficient</i></p> <p>2) <i>Unified</i></p> <p>3) <i>Reducing</i></p> <p>1) <i>Safety</i></p> <p>2) <i>Sufficient</i></p> <p>3) <i>Manual.</i> <i>It is reliable</i></p>

Generating Facilities	Check item by visual inspection and hearing	Results
Transformer	1) Presence of over load operation	1) No objection
Circuit breaker	1) Situation of trip for outgoing feeder breaker in case of accident on transmission line 2) Fitness of maintenance in case of oil circuit breaker	1) Automatically tripped 2) Oil has been changed every 4 years.
Line switch	1) Operation method 2) Reliability of operation	1) Manual 2) It is not reliable and dangerous to operation.
Insulator	1) Presence of damage and dusts	1) No objection
Structural steel	1) Occurrence of erosion due to rust 2) Presence of injury	1) existing 2) No objection
Line protection	1) Existence of adequate protection relays to connect to RED	1) 50/51

Outdoor Equipment

Unit No. Z

Generating Facilities	Check item by visual inspection and hearing	Results
Generator	Rotor	1) No objection 2) " 3) "
	Stator winding	1) Winding had been changed 3 years ago It is about the time to change to the new one due to reduction. 2) No objection 3) Repair work has been done every 2 years.
	Bearing	1) No objection 2) Occurred several times 3) Every 2 months
	Exciter	1) Manual 2) Voltage is always regulated by operator.
	Voltage regulator	1) Discoloration of winding surface due to heat 2) Existence of erosion for core 3) Fitness of between rotor and shaft 1) Frequency of burning trouble or repair 2) Reduction of insulation resistance 3) Rust and erosion of core 1) Occurrence of deformation on metal surface 2) Lack of oil lubrication 3) Occurrence of temperature rise 1) Exchange frequency of brushes worn out 2) Sufficient stock of spare brush 1) Operation method of voltage regulator 2) Response of voltage detection for load variation

Generating Facilities	Check item by visual inspection and hearing	Results
Metering equipment	1) Sufficiency of accuracy for instruments 2) Lack of necessary instruments 3) Items constantly recorded	1) Bad condition due to old. <i>Sufficient, but there are no functional instruments.</i> 2) <i>Gen. : A. V. W, wh, Hz, casp</i> <i>Ex. : A. V</i> <i>Turbine pressure, rpm</i> 3) 87 G 2) 52 G is tripped by 50/51
Protection equipment	1) Lack of relays to be installed 2) Operation method in case of accident in transmission lines	1) Remote control panel is not provided. 2) Voltage : manual (local control panel) 3) Speed : manual 3) Manual
Remote control equipment	1) Control method for turbine and generator operation 2) Control method for voltage and speed control 3) Operation method of synchronized switching	1) Gen. Voltage : 4.16 or 13.2 kV Transmission : 13.2 kV
Power system	1) Power supply voltage (kV) after rehabilitation work	

Control Board

III. REPAIR RECORDS

No.	Study Item	Results
	<p>The past records concerning the following items shall be obtained to evaluate reliability of generating facilities.</p> <ol style="list-style-type: none"> 1) Repaired locations and method for repairing 2) Causes for damage/defect 3) Duration of repairing and power supply stoppage 4) Repaired by; <ol style="list-style-type: none"> a) staff in Power Plant b) manufacturer c) other 5) Repair cost 6) Operation life after the completion of repairing work 	<p>Without available informations</p>

IV . SITUATION OF STOCK SPARE PARTS

No.	Study Item	Results
	<p>Data on the situation of stock spare parts shall be obtained to evaluate maintainability of generating facilities.</p>	<p>1) Following spare parts have been made in CHEC's repair shop.</p> <ul style="list-style-type: none"> a. Bracket for Pelton. b. Needle " " c. Nozzle " " d. Sealing for valves e. Bolts and nuts

V. CHEC'S INTENTION FOR REHABILITATION

No.	Study Item	Results			
		<u>Leaving as it is</u>	<u>Repair work</u>	<u>Replacement</u>	<u>Notes</u>
	Mark with ✓ in pertinent columns.				
	- Inlet valve		✓		✓-1 (Change to Francis) Change to Stator winding
	- Turbine, governor, auxiliary equipment				Change to efficiency machine
	- Generator, exciter		✓		
	- Control panel			✓	many trouble
	- Switchgear			✓	
	- Transformer	✓			
	- Substation equipment (Circuit breaker, Isolator, etc.)			✓	
	- Transmission tower, conductor and insulator	✓			
	- Power House		✓		depend on F/S Already changed
	- Penstock	✓			5 years ago.
					✓-1 : Change to full automatic (52G trip and Inlet valve is closed automatically.)

