



IN PENANG ISLAND PROPOSED LONGITUDINAL PROFILE AND CROSS SECTION OF SG. TELUK BAHANG 0=32m}s 000.17 00017766 000.001 000.0068 000.001 000,066 000.001 000.0076 000.001 00010096 0001001 000 ° 0058 0001001 000.00%8 000.001 000,0068 000.001 3500.000 0=48 m/s STUDY ON FLOOD MITIGATION AND DRAINAGE 000.001 00010018 000.001 00010006 0001001 000.00eS 000.001 000.0062 0001003 000°002Z 0001003 00010092 000,001 000°0052 0001001 00010072 000.001 000.006S 0001001 000.0055 000.001 2100,000 000.001 2000-0002 000.001 000 ° 006 I 000.001 00010001 0001001 000.0071 0001003 00010091 000.001 00010051 0001001 = 52 m/s 00010091 0001001 000.0061 0001001 1500.000 000.0ES 000.0011 ď 0001003 000100\* 0001001 000°00E D00.001 500-002 000.001 0001001 000.0 000.0 H-20-2 DISTANCE CHRINGCE THE FIG.





Ð


(GRADE B)


O SC. TELUK BAHANC


















н--76





THE STUDY ON FLOOD MITIGATION AND DRAINAGE IN PENANG ISLAND PROPOSED LONGITUDINAL PROFILE AND CROSS SECTION OF SG. FETTES 1'9' 5'6~ 0.6 9'| 0.6 6. C - CH1250 ი ი 06 HO **S**'I ດ. ບ 6.0 CH 0.0 --6.0 ъ. ₹ CH 30 CH 600 4 ø D 네 b <u>з.</u>0 O 3.0 ന് HEIGHT OF LEFT BANK HEIGHT OF RIGHT BANK 669.9 661.01 861.11 863.11 000105 0001001 15201000 15001000 EE2 21 Ð FIG. H-20-9 0=16月5\_\_\_ EE7.01 000.001 00010011 EE9.B ££1.01 ££9°L 661.9 ££7.9 000.001 000.0001 EE7.B 000.001 ££9.3 EE1.8 000.006 LEGEND (1) SC.FETTES EE9'S 661.7 EET.T 000.001 000,008 ٩ Ð 661.9 551.3 4.733 6,733 6,733 6,733 6,733 6,733 ££9'\$ 000.001 4 Đ 04 0001004 872.5 5.133 872.5 003.001 0001009 000.001 841.3 000.005 sso.s 329.E 4°555 000-001 0001001 6 Ð 788.E 000.001 4981 730.E 000.006 116'0 115°Z 111.6 1101000 500°000 0=280/5 006.1 5°200 000.06 000.06 00E 10 000.0 009.1 2°500 0001001 00010 -0.200 009.1 5°500 000.001 0001001 009.1 2.200 0001001 00710-200.002 009.0 009.1 s.200 000-001 500 000-006 009.1 000.001 008.0-2°500 000.001 000.1-009' 1 2'500 0001051 0001005-006.1 609. I 2,200 0001059 0001059 16.0 14.0 12.0 10.0 о. 0 о. О 0. V 0.2 0.0 -2.0 PROPOSED BRNK LEVEL PROPOSED BED LEVEL CHAINACE DISTRNCE DESIGN H.E.L m (.0.8.1)36AT8





















ふ 型











IIIGEN







































Phase			I (Urgent Project)					II (Mid-Term Plan)					III (Long-Term Plan)										
Rivers	Year	'91	'92	'93	'94	'95	'96	'97	'98	'99	2000	'01	'02	'03	'04	'05	'06	'07	'08	'09	201		
(Rivers)	· ·																						
1. Sg. Pinang,	3.15 km	Winst State	5.0-10-T																				
2. Sg. Jelutong,	2.14 km	-				<b>19</b> 10-1911															[		
3. Sg. Air Itam,	3.00 km		-																				
4. Sg. Dondang,	5.30 km	-					-																
- Air Terjun diversion,	1.74 km	-																					
- Dondang retention ponds	8.4 ha			-													ŀ .						
5. Sg. Keluang	3.38 km																						
6. Sg. Ara	1.87km				60 M	_													Ì				
- Relau diversion channel	1.53 km			_		_	i																
7. Sg. Air Terjun	2.20 km																						
8. Sg. Gelugor	2.10km					_																	
9. Sg. Dua Besar	3.30 km				_				-		<u> </u>												
10. Sg. Fettes	0.60 km																						
11. Sg. Bayan Lepas	2.40 km				l														ĺ				
12. Sg. Tcluk Bahang	3.13 km							-											ľ				
13. Sg. Teluk Awak	2.10 km					Ì																	
	0.60 km									-													
15. Sg. Bagan Jermal	0.30 km																						
16. Sg. Nibong Besar	1.05 km											<b>Erfictor</b>											
17. Sg. Nibong Kecil	0.90 km										are some												
18. Sg. Kampung Masjid	0.60 km													Same	in an								
19. Sg. Nipah	1.90 km												-										
20. Sg. Batu Ferringghi	0.40 km											_											
21. Sg. Satu	0.50 km											-											
22. Sg. Kecil	0.70 km																						
23. Sg. Kelian	2.80 km												100 000										
24. Sg. Balik batu	0.50 km															*****							
25. Sg. Babi	1.00 km															l		-					
26. Sg. Ikan Mati	0.15 km																ł		ľ	-			
27. Sg. Batu	1.00 km																	ŀ					
28. Sg. Mati	0.80 km																			-			
29. Sg. Teluk Kumbar	1.70 km					ł										1			-				

## Fig. H-23 IMPLEMENTATION SCHEDULE FOR FLOOD MITIGATION MASTER PLAN

## APPENDIX I

## FORMULATION OF DRAINAGE MASTER PLAN



APPENDIX I FORMULATION OF DRAINAGE MASTER PLAN

# TABLE OF CONTENTS

1.	INTRO	DUCTION	I-1
2.	EXIST	ING DRAINAGE SYSTEM	I-1
	2.1 2.2 2.3	Existing Conditions of The Main Drains in Georgetown Area Existing Flow Capacity of Main Drains in Georgetown Area Drainage Problems in the Areas Outside Georgetown .	1-1 1-4 1-4
3.	REVIE	W OF THE PREVIOUS STUDIES	I5
	3.1 3.2 3.3	Findings and Main Issues Proposed Plans by MPPP Review of the Previous Studies	1-5 1-6 1-6
4.	στ.δην	ING CONCEPT AND CONDITIONS FOR	
ч.		IAGE MASTER PLAN	<b>I-</b> 7
	4.1 4.2 4.3	Planning Concept Run-off Analysis Flood Protection level	1-7 1-8 1-9
5.	FORMU	LATION OF MASTER PLAN	I9
	5.1 5.2	Drainage Plan in Georgetown Area Drainage Plan in the Areas Outside Georgetown	I-9 I-17

# LIST OF TABLES

Table	I-1-1	Characteristics of Existing Outfalls in North Channel	1-28
Table	I-1-2	Characteristics of Existing Outfalls in South Channel	1-29
Table	I-2	Existing Discharge Capacity of Main Drain and Outfall in North and South Channels	1-30
Table	I-3	Drain Reserve	I-31
Table	I-4	Run-off Coefficients for Urban Centre	I-31
Table	15	Probable Flood Discharge of Drainage Basin in North and South Channels	I-32
Table	1-6-1	10 Year Flood Discharge at Existing Outfall in the North Channel	I-33
Table	I-6 <b>-</b> 2	10 Year Flood Discharge at Existing Outfall in the South Channel	1-34
Table	I- <b>7</b> -1	Required Improvement Works of Drains in the North Channel	<b>1-35</b>
Table	I-7-2	Required Improvement Works of Drains in the South Channel	1-36
Table	I-8	Features of Lowlying Areas in Penang Island	I-37
Table	I-9	Causes of Inundation and Countermeasures in the Areas Outside Georgetown	I-38
Table	I-10	Features of Proposed Drainage Facilities in the Area Outside Georgetown	I-39
Table	1-11	Financial Cost of Georgetown Drainage Master Plan .	I-40
Table	1-12	Bill of Quantity for Georgetown Drainage Master Plan	I-41
Table	-	Breakdown of Construction Cost for Georgetown Drainage Master Plan	1-42

5

.

# LIST OF FIGURES

FIG. I-1	EXISTING OUTFALLS ALONG NORTH AND SOUTH CHANNELS	I~43
FIG. 1-2	COMMONLY FLOODED AREAS IN PENANG ISLAND	1-44
FIG. 1-3	PROPOSED DRAINAGE OUTFALLS BY MPPP	I-45
FIG. I-4	RAINFALL INTENSITY CURVE	I-46
FIG. I-5	RELATIONSHIP AMONG THE NECESSARY VOLUME, CATCHMENT AREA AND RAINFALL	1-47
FIG. I-6	PROPOSED WATERWAY IN FUTURE RECLAMATION AREA IN SOUTH CHANNEL	<b>I-4</b> 8
FIG. I-7	TYPICAL CROSS SECTION OF THE EXISTING JELUTONG DIVERSION CHANNEL	<b>I-4</b> 9
FIG. I-8	PROPOSED ALIGNMENT OF JELUTONG DIVERSION CHANNEL	I-50
FIG. I-9	LONGITUDINAL PROFILE OF FUTURE EXTENSION OF JELUTONG DIVERSION CHANNEL	I-51
FIG. I-10	PROPOSED DRAINAGE OUTFALLS IN GEORGETOWN	<b>1-</b> 52
FIGI-11	INUNDATION AREA IN SG. GELUGOR BASIN	I-53
FIG. 1-12	PROPOSED ROUTE OF NEW DRAIN IN BRAWN GARDEN AREA	I-54
FIG. I-13	PROPOSED CROSS SECTION OF ORIGINAL SG. GELUGOR DOWNSTREAM STRETCH	1-55
FIG.I-14	PROPOSED LONGITUDINAL PROFILE AND CROSS SECTION OF DRAIN IN MINDEN HEIGHTS AREA	I-56
FIG I-15	INUNDATION AREA IN SG. DUA BESAR BASIN	<b>1-</b> 57
FIG.I-16	PLAN OF PROPOSED DRAINAGE SYSTEM IN LOWLYING AREA ALONG SG. DUA BESAR	1-58
FIG.I-17	PROPOSED LONGITUDINAL PROFILE AND CROSS SECTION OF DIVERSION CHANNEL FROM SG. DUA KECIL CATCHMENT	I-59
FIG.I-18	INUNDATION AREA IN SG. NIBONG BASIN	<b>1-60</b>
FIG.1-19	PROPOSED DRAIN ROUTE ALONG JLN. RELAU	1-61
FIG.1-20	PROPOSED LONGITUDINAL PROFILE AND CROSS SECTION OF DRAIN ALONG JLN. RELAU	I-62
FIG I-21	PROPOSED DRAIN ROUTE AND CROSS SECTION OF DRAIN FROM BUKIT JAMBUL TO SG. RELAU	I-63
FIG.1-22	INUNDATION AREA IN SG. RELAU AND SG. ARA BASINS	I-64

< APPENDIX I >

FIG.1-23	EXISTING CONDITIONS OF SG. NIPAH AND SG. KANPUMG MASJID BASINS	I-65
FIG.I-24	EXISTING CROSS SECTIONS OF DRAINS IN KG. MAJID AREA	1-66
FIG.1-25	EXISTING CROSS SECTIONS OF DRAINS IN KG. MASJID AREA	1-67
FIG.1-26	GENERAL PLAN OF EXISTING CONDITION OF SG. KG. SERONOK	I-68
FIG.1-27	PROPOSED ALIGNMENT OF SG. KG. SERONOK DOWNSTREAM STRETCH	I-69
FIG.1-28	PROPOSED LONGITUDINAL PROFILE AND CROSS SECTIONS OF SG. KG. SERONOK	I-70

· 9

### APPENDIX I FORMULATION OF DRAINAGE MASTER PLAN

#### 1. INTRODUCTION

The Drainage Master Plan Study for Penang Island was carried out by MPPP in 1985, and the results of the study were compiled as technical report No. 14 of Penang Island Structure Plan.

This Master Plan mainly covers the drainage systems in Georgetown which discharge via 45 man-made outfalls to the North and South channels or directly to the rivers. (see Fig. I-1)

Among these main drains, N-20 (Sg. Babi), N-21 (Sg. Bagan Jermal and S-23 (Sg. Jelutong Diversion) were treated as a river.

The reasons for reviewing the previous Drainage Master Plan are as follows:

- i) For the drainage outfalls in the North channel, future extension of main drains due to the proposed Outer Ring Road should be considered.
- ii) The layout of the outfalls in the land reclamation area in the South Channel should be reviewed based on the latest information.
- iii) S-10 and S-18 drains which have lowlying area should be planned taking into account the combination of pump facility and retention pond.
- iv) Drainage problems of the main drains in the areas outside Georgetown were not included in the previous Drainage Master Plan. Hence, for the areas where inner water problem still remains after completion of river improvement works, it is necessary to propose some countermeasures.

while, in the areas outside Georgetown, drainage study was carried out for the commonly flooded areas with some flood damage and the future flood prone areas with anticipated inner water problem.

All existing outfalls of the main drains in the areas outside Georgetown discharge into the river or its tributary.

### 2. EXISTING DRAINAGE SYSTEM

2.1 Existing Conditions of the Main Drains in Georgetown Area.

The field reconnaissance survey for 45 main drains in Georgetown was carried out. Main items of the survey are as follows:

- Types of main drain and outfall
- Conditions of main drain and outfall
- Land use of catchment area
- Screen (or garbage traps)
- Garbage
- Siltation
- Tidal effects

The summary of characteristics of existing outfalls in the North and South Channels is shown in Tables I-1-1 and I-1-2.

The catchment area for each urban drainage system in Georgetown is ranging from 2 to 160 ha. 90% of total urban drainage systems are having the catchment area less than 50 ha. And 70 % of total urban drainage systems are less than 10 ha in area.

### 2.1.1 Types of Main Drains and Outfalls

Almost all the main drains in North and South Channels are channelized mostly with open drains with the exception of the earth drains, such as S-11, S-12, S-13, S-14, S-19 and S-24.

The type of outfall depends on its location and condition, and remarkably there are some outlets damaged or silted.

North Channel	-	N-5	(The slabs on the outlet
			are fallen. They disturb
			the flow.)

- N-9 (The slabs are partly damaged.)
- N-10 (Totally silted, Unusable) (One of the two pipe culverts is totally silted. Outlet is heavily damaged.)
- N-15 (Pipe culvert is heavily damaged.)
- N-17 (Pipe culvert is heavily damaged.)

South Channel

S-11 (No outlet exists)

### 2.1.2 Screen

Several screens by wire gauge to screen out the garbage are installed at the following outfalls:

- North Channel N-1 (One screen is installed at the exit of outfall. But it is slightly damaged.) N-4 (One screen is installed at
  - the exit of outfall and two screen are installed at the entrance of outlet.)
  - N-8 (One screen is installed at the middle of main drain.)
  - N-20 (One screen is installed at the entrance of outlet.)
  - S-10 (Two screens are installed in front of the pumping station.)
  - S-16 (One screen is installed in the secondary drain.)

### 2.1.3 Garbage

South Channel

The garbage is seen in most of the open drains and outlets both in the North and South Channels. Among them, the following outfalls are under relatively worse condition than others:

- S-10 (Excessive rubbish at pumping station)
  - S-16 (Excessive rubbish along the main drain)
  - S-22 (Excessive rubbish along the main drain)

### 2.1.4 Siltation

.

The outlets which situations are aggravated by blockage of drain by siltation are as follows:

•	North Channel	-	N-10 N-12
			N-12 N-13
			N-20
			N-21
•	South Channel		S-22

### 2.1.5 Tidal Effects

It is observed that most of the existing outlets are subjected to high tides, as shown in Tables I-1-1 and I-1-2.

The general views were envisaged after the review of the previous urban drainage study and field survey of the existing urban drainage system in the city of Georgetown as follows:

- Rehabilitation of the existing drainage outlets should be urgently necessary to regain the original capacity.
- Regular maintenance and operation shall be needed for any blockage by rubbish and by siltation.

In Georgetown, the major cause of flood along the drains is mostly its undersized facility such as main drain and outlet.

I - 3

Among those drainage basins in problem, the drain such as S-10 and S-18 needs to have a pumping facility in order to pump up the expected flood water from its internal drainage catchment during the storm, because the drainage catchment has lowlying area which is  $\pm 1.40$  m in elevation.

The only existing pumping station is situated at S-10 drainage outlet of which capacity is about 7.6  $m^3/s$ .

# 2.2 Existing Flow Capacity of Main Drains in Georgetown Area.

The existing flow capacities of the main drains estimated by previous study are shown in Table I-2.

Based on the flow capacity, 45 main drains are categorized as follows;

Return period of flow capacity of the main drain	No. of the main drain	8
a. $Qmax > 1/10$ b. $1/10 \ge Qmax > 1/5$ c. $1/5 \ge Qmax > 1/2$ d. $1/2 \ge Qmax$	16 3 0 18+8	35 7 0 58
Total	45	100

These probable flood discharges were estimated for each revised catchment area as shown in Table I-5.

### 2.3 Drainage Problems in the Areas Outside Georgetown

Drainage problems in the areas outside Georgetown was recognized in the present and future flood prone areas.

In the 25 river basins outside Georgetown, the following areas are known to be commonly flooded. Fig.I-2 shows the location of these areas.

River Name	Location
13. Sg. Gelugor	- Brown Garden - Minden Heights
14. Sg. Dua Besar	<ul> <li>Pesta Parking Lot and Road</li> <li>Jalan Pantai Jerjak</li> </ul>
15. 16. Sg. Nibong	- Jalan Sungai Nibong - Jalan Mahsuri
17. Sg. Keluang Sg. Relau Sg. Ara Ditch-X	- PDC Housing area - Jalan Tun Dr. Awang - Jalan Bayan Lepas
18. Sg. Nipah	- Lowlying Area (River Mouth)
19. Sg. Kampung Masjid	<ul> <li>Lowlying Area</li> <li>(River Mouth)</li> </ul>

### 21. Sg. Kampung Seronok - Permatang Damar Laut Area (Sg. Bayan Lepas)

Since the return period for the maximum floods experienced throughout the Island is greater than 10 years, as determined from rainfall records, these locations cover all areas which have inundation problem in the present drainage design scale (i.e. 10 year return period)

Almost all these areas are located along the main stream or tributaries and the causes of flooding are mainly due to the inadequate flow capacity of main stream.

Hence, these drainage problems should be basically solved by flood mitigation measures of main stream.

However, it should also be considered that the new drainage problem may be created by future development especially in lowlying area.

Lowlying area are generally defined as these areas which are affected by high tide, or have low ground levels compared with surrounding areas or high river water levels.

For the 25 river basins outside Georgetown, lowlying areas were determined based on the river survey maps, urban planning maps, etc.

Table I-8 shows the features of the existing lowlying areas.

As a basic concept for solving the drainage problems in these lowlying areas, the high water level of the rivers should be lowered as much as possible.

For lowlying areas affected by high tide near the river mouth, the basic strategy is to fill the area to a ground level high enough to permit future development, instead of installing pumping facilities.

#### 3. REVIEW OF THE PREVIOUS STUDIES

The survey and study for the Penang Island Structure Plan were carried out by MPPP in 1985, covering all aspects including infrastructure matters of Penang Island and the implementation and implications of the plan. As one of the infrastructure studies, public utilities study was carried out, including such matters as water supply, electricity supply, telecommunication, sewerage, solid waste disposal and management and drainage. The results of the study were compiled as technical report No.14 of Penang Island Structure Plan.

Findings and main issues which were elucidated by this study concerning drainage can be summarized as follows:

### 3.1 Findings and Main Issues

### 3.1.1 Findings

The existing drainage system in Georgetown consists of a network of drains which discharge via 45 man-made outfalls to

the North and South Channels or directly to rivers and streams. Outside Georgetown all drainage outlets are natural rivers. Fig.I-2 shows the existing outfalls and their respective catchment areas.

### 3.1.2 Main Issues

- There have been high occurrences of indiscriminate dumping of garbage into open drains, streams, vacant lands and the sea by the general populace.
- There are at present many government departments responsible for drainage in the island working without sufficient coordination and cooperation.
- The existing man-made as well as natural drainage outlets in many areas are inadequate to cater for the drainage. The situation is aggravated by blockage of the drains by garbage and siltation, by high tides and by the faster runoff caused by excessive land-cutting.
- Drainage improvement measures would require tremendous amount of funds.
- Some structural measures were planned and recommended by MPPP in order to alleviate the flooding caused by inadequate urban drainage system.

### 3.2 Proposed Plans by MPPP

Since almost all the drainage outlets are subjected to tidal inundation, the provision of a drainage system with tide controlled flap gate outlets is warranted. If necessary, pumping facilities should be installed at the outlets. The construction of pumping station and installation of pumps and a new tide gate were proposed at the existing Brick Kiln road outfall (S-18). Also the installation new pumps to replace the present ones were proposed at Prangin Canal outlet (S-10).

To improve the drainage system of the City of Georgetown and alleviation of flooding, a reorganization of the existing outfalls and catchment areas along the north and south channels is necessary.

Fig. I-3 shows the previously proposed outfalls.

Adequate drainage access reserve must be provided to all drainage outlets to regularly maintain the outlets.

### 3.3 Review of the Previous Studies

The Drainage Master Plan prepared by MPPP was reviewed taking into account the present land use and future land use conditions (especially, Land Reclamation Plan by PDC in the South Channel and Outer Ring Road Plan in the North Channel), and the following items will be necessary to be changed.

a) N-20 (Sg. Babi), N-21 (Sg. Bagan Jermal) and S-23 (Jelutong Diversion Channel) should be treated as a river and planned for the 50 year design discharge.

ł,

- b) The outfalls along the Gurney Drive in the North Channel will be reorganized after taking into consideration landscape, environment and maintenance.
- c) S-11, S-12 and S-13 drains will be connected to S-10 drain because of their low ground levels. S-14 drain will be extended directly into the sea.
- d) S-18 drain will be extended up to proposed Coastal Road without discharging into Sg. Pinang, and discharge via retention pond or pump facility into the sea.
- e) For the drainage in S-10 and S-18 catchment, the combination of pumping and retention pond will be adopted.
- f) The extension of existing drains of S-19 S-22 and S-24 will be quite difficult due to their low ground level in the catchments. Hence, the open waterway will be planned near the existing outfalls.
- g) S-23 drains (Sg. Jelutong Diversion Channel) will be planned for 50 year design discharge and extended to the new coastal line in box culvert or concrete open channel.
- h) In the areas outside Georgetown, previous Master Plan for drainage by MPPP covers only main stream of the river. Hence, in this study, drainage problems in commonly flooding areas and lowlying areas will be studied.

### 4. PLANNING CONCEPT AND CONDITIONS FOR DRAINAGE MASTER PLAN

### 4.1 Planning Concept

The following concept was contemplated for planning the drainage master plan.

- Considering the fact that the flow capacity of the river in Georgetown is relatively small, the distance from main drain to the sea is short and the availability of relatively steep slope of the main drain, it is presumed to be reasonable that the outlets be located towards the sea as much as possible.
- The flap gate or the pumping station will be considered for the drainage basins with a lowlying area or high tide level, where the drainage by gravity is physically impossible.
- It is presumed that the drainage problem along the Sg. Dondang at upstream of Sg. Pinang will be solved by lowlying the design water level of the main stream of Sg. Dondang.
- Number of the outlet of main drains along the Gurney Drive in the North Channel will be reduced by means of reorganization after taking into consideration the

and their and environmental aspects, landscaping maintenance.

In the South Channel area of Georgetown, the extension of the existing drain in land reclamation area is seemed to be extremely difficult.

Hence, the existing outfalls will be connected to new waterway.

- For drainage in S-10 and S-18 catchments combination of pumping facility and retention pond will be contemplated.
- For the undeveloped lowlying areas near the river mouth, the basic strategy will be to fill up the area with a ground level suitable for future development instead of installing any pumping facility.
- The drain reserve shown in Table I-3 should be kept taking into account access requirement for maintenance works.

#### 4.2 Run-off Analysis

The run-off formula adopted for the study is explained below:

Q = 1/360 Cs.C I A

where,

Q = the peak discharge (m3/s) I = the average intensity of rainfall (mm) A = the catchment area (ha) C = a run-off coefficient Cs = a storage coefficient Cs = 2tc/(2tc + td)where, tc = the time of concentration td = the time of flow in the main drain

The application of a run-off formula modified by a storage coefficient is preferable in the project area which is totally flat and lowlying.

The relationship between Cs, tc and td in Malaysian Standard is designed on the basis of the theory acceptable internationally, and the result of its practical application on some drainage basins in Kuala Lumpur (KL) coincide with those obtained by the more elaborate routing procedure by way of computer calculation. The derivation of Cs as a function of tc and td is explained in "Flood Procedure No. 16", published by Ministry of Agriculture and Rural Development, Malaysia. With the background above, "Rational Method" with storage coefficient Cs, i.e., Q=1/360 Cs C I A is adopted for the Project.

A run-off coefficient C adopted in this drainage plan is shown in Table I-4. The rainfall intensity curve is shown in Fig.I-4.

The Tables I-5 and I-6 show the result of run-off calculation for probable floods.

#### 4.3 Flood Protection Level

The design flood protection level of 10-year return period, which is the same value adopted for the Master Structure Plan MPPP, was adopted based on the following reasons:

- i. The catchment area of the drainage basin is comparative small and duration of peak discharge is quite short.
- ii. Generally, as a design scale of drainage plan, 5 to 10 year return period flood is adopted.
- iii. Construction of drainage facilities in the built-up urban area is quite costly and adoption of large scale of protection level is not feasible.

### 5. FORMULATION OF MASTER PLAN

### 5.1 Drainage Plan in Georgetown Area

### 5.1.1 Drainage Plan in the Coastal Zone

In the coastal zone of Georgetown, there are proposed projects of Outer Ring Roads, Coastal Roads and land reclamation. By these projects many of the existing drainage outfalls will be affected.

In the coastal zone of the North Channel, the only proposed project is the Outer Ring Road.

The required extension length of the existing drain is expected to be about 40 - 100 m.

In the South Channel, a large scale land reclamation project is now under consideration. The maximum length of drains to be extended would be 685 m. However, it may be rather difficult to construct such a long extension drain without any technical or hydraulic problem.

Hence, the following two cases were contemplated.

CASE - 1 Filling without any waterway in reclaimed area. CASE - 2 Filling leaving some portion to keep the waterway in reclaimed area.

1). Comparison of Drainage Plan in Reclaimed Area in Case of With and Without Waterway.

### (1) CASE-1 Without waterway

In this case, all the drains located in the land reclamation area would have to be extended from 450 m to 685 m, with or without realignment. The type of drain would be closed channel which would be installed under a roadway in the future reclaimed area.

The maintenance of such a drain extension would be very difficult because it would have a very flat slope and be affected by high tide resulting in clogging by sedimentation.

Construction cost would be costly because of poor foundation conditions.

The major problem would be inundation in inland areas during floods exceeding the 10 year design flood.

### (2) CASE-2 With waterway

In this case, by installing the waterway in the reclaimed area, the hydraulic effect for the existing outfalls due to land reclamation would probably be negligible.

The waterway will be composed of a waterway along the existing coastal line and one connecting to the sea.

These waterways serve as a retention pond for storing flood waters even if the sea water level rises due to the effects of global warming in future.

To use such a waterway as a retention pond, a tidal gate is necessary at the new outfall.

Installation of a pumping station may reduce the necessary retention pond capacity.

CASE 2 has considerable merit as compared to CASE 1 and is recommended as the drainage plan for reclaimed areas.

Regarding internal drains in the reclaimed area, those outfalls should discharge directly to the sea without flowing into the waterway.

# 2). Basic concept of proposed waterway

The proposed waterway was planned based on the following conditions;

- The cross section of waterway should have sufficient capacity so that the backwater effect would be negligible.
- The waterway should have enough capacity to storage the 50 year flood discharge for 6 hours.

Fig.I-5 shows the relationship between the necessary volume of channel, (length and width), catchment area and accumulated rainfall.

The proposed waterways in the South Channel are shown in Fig. I-6. These two waterway systems have a minimum necessary volume and it is desirable to keep the larger volume.

The continuous waterway connecting  $W_1$  waterway with  $W_2$  waterway was considered for the purpose of navigation use and improvement of water stagnation in the waterway.

Tentatively, it is possible to make the continuous waterway.

However, there exist the outfall of the Jelutong Diversion Channel and sewage outfall between proposed  $W_1$  and  $W_2$  waterways.

Especially, the outfall of diversion channel will be major obstruction in the future.

Because the level of the existing outfall of the diversion channel is high enough to discharge directly to the sea by gravity even with long extension of the channel in the reclaimed area and this diversion channel does not need any retention pond nor pump facility for drainage even if the sea water level rises in the future.

Since the catchment area of this diversion channel is rather big (490 ha), about 900,000  $m^3$  of additional storage capacity will be required in the waterway (i.e. 30 m in width and 16 km in length), when the run-off discharge from the diversion channel catchment flows into the continuous waterway.

Hence, for the outfall of the Jelutong Diversion Channel, it is recommended to construct separately the water channel from the proposed  $W_1$  and  $W_2$  waterways.

# 5.1.2 Layout of Outfalls of Main Drains in Georgetown

The outfalls of main drains in Georgetown area are divided into several groups according to the future land use plan of coastal zone.

#### (1) North Channel

In the North Channel, there is an Outer Ring Road project for which a study was carried out by JICA in 1981.

This proposed road runs along the existing coastal line and was planned to have the same formation level as the existing road except at the river mouth of Sg. Babi where the road crosses the river by means of a bridge.

### (i) Outfalls N-1 to N-11

For the outfalls N-1 and N-2 there has been no consideration for future extension.

The outfalls of N-3  $\sim$  N-11 will be extended straight up to new coastal line outside the proposed Outer Ring Road.

The required extension length will be as follows.

Origina l No.	Original Catchmen t Area (ha)	Increase / decrease of Area by Re- organization (ha)	Additional Catchment Area by Land Reclamation	Proposed Catchment Area (ha)	Extension Length (m)	Proposed outfall No.
N-3	1.5	0.0	1.2	2.7	45	pn3
N-4	1,4	0.0	1.6	3.0	70	PN4
N-5	20.5	0.0	5.0	25.5	150	PN5
N-6	34.1	0.0	5.3	39.4	9,0	PN6
N-7	4.8	0.0	1.8	6.6	90	PN7
N8	10.4	+5.0	1.9	17.3	95	PN8
N-9 )	54.2	-11.7	1.2	43.7	75	PN9
N-10	3.3	-5.0	1.7	0.0	80	
N-11	12.0	+11.7	2.1	25.8	60	PN10

### (ii) Outfalls of N-12 to N-19

For the section of Gurney Drive, realignment reducing the number of outfalls is expected after taking into consideration the maintenance and environmental aspects.

However, this Ring Road project is not definitive nor has it been authorized. The distance between the new road and existing one is still flexible.

Hence, at this stage, only the layout of the realignment will be considered.

The realignment of outfalls of the Gurney Drive section in the North Channel is as follows;

N-19 7	$\frac{N-15}{N-14}$ PN12
N-19 N-18 N-17	N-14 -
N-17 -	N-13 - PN11
N-16 J PN-13	N-12

### (2) South Channel

In the South Channel, about 210 ha of coastal area along Prangin Street Ghaut and Penang Bridge is proposed for reclamation, and a coastal road is proposed along the same stretch. This coastal road will run almost parallel to the existing coastal line about 500 m offshore.

Also, about 25 ha of coastal area along Market Street Ghaut and Prangin Street Ghaut is proposed for reclamation.

Nineteen outfalls, from S-6 to S-24, will be affected by this land reclamation project.

(i) S-1 - S-9 Outfalls

S-1 to S-5 outfalls are not affected by land reclamation and will remain at the existing sites.

S-6, S-7, S-8 and S-9 will be extended due to land reclamation as follows.

Origi- nal No.	Original Catchment Area (ha)	Additional Catchment Area by Land Reclamation	Proposed Catchment Area (ha)	Extension Length (m)	Propose d Outfall No.
S-6	5.1	3.9	9.0	160	PS6
S-7	7.3	4.9	12.2	220	PS7
S-8	4.7	4.5	9.2	280	PS8
S-9	7.6	9.0	16.6	130	PS9

#### (ii) S-10 - S-18 Outfalls

S-10 will be extended up to new retention pond which is planned outside proposed coastal road.

S-11, S-12 and S-13 will be connected to S-10 outfall because their existing ground level is not high enough to extend directly those drains up to the future outfalls outside the proposed coastal road.

S-14 drain will be solely extended to the new coastal line.

S-15 and S-16 drains will be reorganized and discharged directly to the sea.

The outfall of S-17 will remain at the existing site.

S-18 drain, which flows into the Sg.Pinang at present, will be extended and connected to the retention pond located outside coastal road.

The proposed catchment areas and extension length of each outfall are as follows:

Original No.	Original Catch- ment Area (ha)	Additional Catchment Area by Land Reclama- tion	Proposed Catch- ment Area (ha)	Extension Length (m)	Proposed Outfall No.
S-10	120.0	0.0	120.0	0.0	PS10
S-11	0.0	0.0	0.0	0.0	-
S-12	1.6	0.0	1.6	240	-
لر s-13	4.7	0.0	4.7	143	
S-14	5.3	2.7	8.0	300	PS11
Տ−15 ๅ	6.6	0.0	6.6	32.0	-
<sub>S-16</sub> J	12.0	6.7	18.7	150.0	PS12
S-17	6.8	0.0	6.8	0.0	PS13
S-18	104.0	0.0	104.0	0.0	PS14

### (iii) S-19 - S-22 outfalls

These outfalls will be treated as the third group to be surrounded by Sg. Pinang, the coastal road and the extended Jelutong diversion channel.

The total catchment area of these drains is 44.7 ha. The minimum required capacity of waterway will be about 80,500

 $m^3$ , with a length of 1,150 m, width of 35 m and effective depth of 2 m. However, taking into account the future demand for retention volume, 1,450 m of waterway having a capacity of 101,500  $m^3$  as shown in Fig. I-6 is recommended.

### (iv) S-23 outfalls (Jelutong Diversion Channel)

The existing diversion channel has enough capacity to handle the discharge of a flood with a 50 year return period. And it has adequate design water level to discharge by gravity flow to the future extended outfall.

Hence, this outfall should be extended straight to the outside of the Coastal Road.

(v) S-24 outfall

This outfall has a catchment area of 42.2 ha; the necessary volume of waterway will be 75,960 m<sup>3</sup>, with a length of 1,100 m, width of 35 m and effective depth of 2 m. However, for the same reason of S-19 - S-22 outfalls, 1,550 m waterway having a capacity of 108,500 m<sup>3</sup> is proposed. The alignment of the waterway is shown in Fig. I-6.

### 3) Future extension plan of Jelutong Diversion Channel

### (1) Verification of existing flow capacity of Jelutong Diversion Channel

This diversion channel is one of tributary of Sg. Pinang and should be planned for 50 year flood as a river.

The Jelutong Diversion Channel was completed in 1976 for the purpose of diverting the discharge from the 74% of the catchment area  $(4.9 \text{km}^2)$  of the whole basin of Sg. Jelutong to South Channel.

This diversion channel consists of a rectangular reinforced concrete channel with a width ranging from 8.22 to 9.52 m, an average depth of 3.05 m and a gradient of 1 in 833.33.

Fig.I-7 shows a typical cross section of the channel.

An estimation of run-off discharge using formula shown in Hydrological Procedure No. 16 was carried out under the projected land use conditions in 2010 to evaluate the existing flow capacity.

### Existing Flow Capacity,

Using Manning's Formula	· · · · · · · · · · · · · · · · · · ·
$Q = 1/n R^{2/3} I^{1/2} A$	N = 0.014 :concrete culvert
	$I^{1/2} = (1/833.33)^{1/2} = 0.0346$
	A (m <sup>2</sup> )
	out any freeboard L. is the bottom of beam)

 $A = 22.16 \text{ m}^2$ , R = 1.682,  $R^{2/3} = 1.414$ 

$$Q = 77.4 \text{ m}^3/\text{s}$$

b) Case II

with 15% of the sectional area as a necessary clearance under the bottom of top slab (H.W.L. is 0.489m below the bottom of top slab

i.e. 0.083m below the bottom of beam)

A = 21.52 m<sup>2</sup>, R = 1.654,  $R^{2/3} = 1.399$ Q = 74.3 m<sup>3</sup>/s

c) Case III

with 15% of the sectional area as a necessary clearance below the bottom of beam (H.W.L. is 0.428m under the bottom of beam) A = 18.84 m<sup>2</sup>, R = 1.53, R<sup>2/3</sup> = 1.328

 $Q = 61.8 \text{ m}^3/\text{s}$ 

d) Case IV with 0.6m freeboard under the bottom of beam

$$A = 17.50m^2$$
,  $R = 1.462$ ,  $R^{2/3} = 1.288$   
 $O = 55.7 m^3/s$ 

50 year discharge estimated by specific discharge of Storage Function Model

The design discharge was estimated by Storage function Model as one of Tributary of Sg. Pinang System.

 $Q = 10 \times 4.9 = 50 \text{ m}^3/\text{s}$ 

For refevence, the run-off discharges for 50 year and 100 year floods were estimated by Retional Method.

50 year discharge by Rational Method

a) Areal average run-off coefficient

f = 0.308 = 0.31 (see Table I-6.)

b) Run-off discharge

 $Q = 1/3.6.f.I_{1/50}$ , A Time of concentration: to + td = 15 + 32 (min.)  $I_{1/50} = 125$  mm/hr

 $Q = 1/3.6 \times 0.31 \times 125 \times 4.90 = 52.7 \text{ m}^3/\text{s}$ 

100 year discharge by Rational Method

 $I_{1/100} = 136 \text{ mm/hr}$ Q = 1/3.6 x 0.31 x 136 x 4.9 = 57.4 m<sup>3</sup>/s

#### Conclusion

The diversion channel section with a 0.6 m freeboard under the bottom of beam can handle the 50 year discharge.  $Q_{50}$  52.7 m<sup>3</sup>/s < 55.7 m<sup>3</sup>/s CASE IV

The diversion channel section with 15% of the sectional area as the basis for the necessary clearance under the bottom of the top slab can handle 130% of the 50 year discharge.

$$1.3.Q_{50}$$
 68.5 m<sup>3</sup>/s < 74.3 m<sup>3</sup>/s CASE II

The diversion channel section without any freeboard under the bottom of beam can handle the 100 year discharge.

 $Q_{100}$  57.4 m<sup>3</sup>/s < 77.4 m<sup>3</sup>/s CASE I

Finally, the Jelutong Diversion Channel flow capacity is adequate to handle the run-off discharge for 50 year flood of Sg. Jelutong under the projected land use conditions in the year 2010.

### (2) Future extension plan for Jelutong Diversion Channel

Due to land reclamation the extension of existing Jelutong Diversion Channel will be necessary. The length of the extension is expected to be about 510 m.

The alignment shown in Fig.I-8 is proposed. At present there are no definitive land use plans or constraints related to the reclaimed area. The gradient and cross section of the proposed channel will be the same as for the existing one.

The design discharge was set to be 65  $m^3/s$  (1.3 x 50  $m^3/s$ ).

The invert level and design high water level at the new outfall will be -0.692 and 1.99 m, respectively: (see Fig.I-9)

The design H.W.L. would not be affected even by the E.H.W.S. (+1.60 m).

The existing 1.2 m diameter water supply pipe line about 200 m off shore should be reconstructed because it is a major obstruction crossing the route of the proposed diversion channel.

### 5.1.3 Proposed Drainage Plan in Georgetown Area

Based on the above mentioned planning concept and conditions, proposed drainage facilities were studied. The major components of the drainage master plan in Georgetown consist of realignment of the existing main drains including extension of the outfall in the future reclamation area, reorganization of drainage catchment of existing drains and pump drainage plan for lowlying area.

I - 16

Fig I-10 shows the proposed outfall and catchment areas in Georgetown.

The required improvement works for each drainage system are summarized in Table I-7-1 and I-7-2.

The proposed plan of drainage route, longitudinal profile and typical cross sections are shown in the drawing "DRAINAGE MASTER PLAN IN GEORGETOWN" compiled separately.

For drainage catchment S-10 and S-18, simulation study on the relationship between given run-off hydrograph, required pump capacity and storage capacity of retention pond were carried out for determination of optimum combination system of pump and retention pond.

Proposed sites of retention ponds and pump stations are shown in Fig.I-10.

### 5.1.4 Construction Cost of Georgetown Drainage Master Plan

The financial cost for the Georgetown Drainage Projects are summarized in Table I-11 to I-13. Total cost was estimated to be about M\$ 64.4 million.

### 5.2 Drainage Plan in the Areas Outside Georgetown

#### 5.2.1 General

### 1) Objective Areas

Drainage study in the areas outside Georgetown was carried out for those areas that are flood prone at present or in future.

In the 25 river basins outside Georgetown, the following areas are known to be commonly flooded or flood prone and lowlying. Fig.I-2 shows the location of these areas.

No. River Name

Location

13.	Sg. Gelugor	-	Brown Garden
		-	Minden Heights
14	Sg. Dua Besar		Pesta Parking Lot and Road
	-	_	Jalan Pantai Jerjak
15.	16. Sg. Nibong		Jalan Mahsuri
	Sg. Keluang		
	Sg. Relau	-	Jalan Tun Dr.Awang
	Ditch-x		Jalan Bayan Lepas
18.	Sg. Nipah		Lowlying Area
			(river Mouth)
19.	Sg. Kampung Masjid	-	Lowlying Ares
			(river mouth)
21.	Sg. Kampung Seronok		Permatang Damar Laut Area
			(Sg. Bayan Lepas)

I - 17

### 2) Causes of Flooding

All objective drains in the area outside Georgetown flow into the river or its tributary. In almost all cases drainage problems are related to the water level or flow capacity of a main stream. The major causes of the existing flood problem in the objective areas are considered as follows:

- i) Overflowing from the river due to insufficient flow capacity.
- ii) Impossibility of drainage by gravity due to higher water level of the river in comparison to the ground elevation of the objective area.
- iii) Inadequate flow capacity of drains.
- iv) Combination of the above mentioned (i~iii) causes.
- The causes of inundation and countermeasures in each objective area are summarized in Table I-9.

### 3) Drainage Plan

As the basic concept for solving the drainage problems in the objective areas, the high water level of the river should be lowered as much as possible.

For lowlying areas affected by high tide near the river mouth, the basic strategy is to fill the area to a ground level high enough to permit future development, instead of installing pumping facilities.

The features of proposed drainage facilities are shown in Table I-10.

### 5.2.2 Sg. Gelugor

### 1) Existing Conditions of Sg.Gelugor

Downstream of Sg. Gelugor has two streams. One is original river, another is Sg. Gelugor Diversion Channel. In accordance with this condition, the catchment of Sg. Gelugor is divided into Sg. Gelugor original river area (GO) and Sg. Gelugor Diversion Area (GD).

Almost all the catchment area of Sg. Gelugor were already developed for housing. Two flood prone areas, Minden Heights and Brown Garden, are identified along Sg. Gelugor as shown in Fig.I-10.

Run-off from Minden Heights and some part of U.S.M. are discharged to the original river. Run-off from the area along Sg. Gelugor main stream is directed to the diversion channel.

#### 2) Causes of Inundation

The causes of inundation of each area are as follows:

i) Brown Garden area

Overflowing of the river water due to inadequate discharge capacity at Jln. Permai (CH1200) and existence of low ground level (EL. 3.0 m) at Brown Garden.

ii) Minden Heights area

Overflowing of the drain due to inadequate flow capacity of the drain and original Sg. Gelugor.

#### 3) Drainage Plan

#### (1) Brown Garden area

Required flow capacity of the main stream is  $29 \text{ m}^3/\text{s}$  and improvement of the existing concrete channel at upstream of Jln. Gelugor will lower the Design High Water Level (D.H.W.L.) at Jln. Permai (CH1200) to 3.3 m. This would mitigate the inundation due to river overflow, considering the ground level along the stream.

However the inner drainage problem in the lowlying area (ground level +3.0 m) still remains.

Hence, reorganization of catchment area and replacement of the existing outfall will be necessary. The outfall of the drain is recommended to be shifted to the lower portion as shown in Fig.I-12. The design high water level (50 year flood) of the Sg. Gelugor at Jln. Gelugor is +2.93 m.

The proposed drain route is shown in Fig. I-12 and water level for 10 year flood is + 2.65 m at the same point. This proposed drain route might encounter land acquisition problems due to the presence of terrace houses, in which case an alternative like a pumping scheme should be investigated.

#### (2) Minden Heights area

To mitigate the inundation of this area, it is recommended that not only improvement of Sg. Gelugor Original Stretch but also improvement of drains.

### i) Improvement of Original Sg. Gelugor

The existing flow capacity of the original Sg. Gelugor, except some sections, is smaller than the design discharge of 25  $m^3/s$  calculated for 1/50 year floods. The proposed cross section and longitudinal profile are shown in Fig.I-13.

### ii) Improvement of drains

Drains which cause inundation due to inadequate flow capacity shall be improved for 10 year floods. The proposed cross section and longitudinal profile for the design discharge  $(17 \text{ m}^3/\text{s})$  are shown in Fig.I-14.

Due to the inadequate capacity of the internal drain downstream of the U.S.M. area, and also constraints in upgrading these drains, the retention pond at U.S.M. compound should be investigated at detailed design stage. The proposal for Sg. Gelugor section therefore should be reviewed due to possible attenuation effect.

This retention pond should be made by excavating the existing ground to protect the houses nearby. The downstream stretch of this pond also be improved to lowering the design bed level to obtain the effective enough depth of the pond.

### 5.2.3. Sg. Dua Besar

# 1) Existing Conditions of Sg.Dua Besar

The catchment area of the Sg. Dua Besar is  $6.72 \text{ km}^2$ , including about 50% of the upper catchment of the Sg. Dua Kecil which is diverted to the Sg. Dua Besar. (Fig. I-15)

Since the land is very flat in this area, particularly in PESTA, inundation spread widely.

### 2) Design Discharge of Sg. Dua Besar

The design discharges of Sg. Dua Besar, which was calculated for a 1/50 year floods, are 55 m3/s at the river mouth including the discharge from the Sg. Dua Kecil Diversion and around 30 m3/s at Jln. Sg. Dua.

### 3) Causes of Inundation

The causes of inundation along Sg. Dua Besar are;

- i) rising river water level and overflow due to inadequate discharge capacity along the entire stretch, and
- ii) failure of drainage from lowlying area due to rising of river water level.

### 4) Drainage Plan

After completion of widening and deepening the main stream by Urgent Project for flood mitigation, the D.H.W.L. of the main stream is expected to be reduced to 1.7 m at Jln. Sg. Nibong, 1.9 m at the diversion confluence and 3.2 m at Jln. Sg. Dua.

### (1) Downstream of Jln. Sg. Nibong

After completion of the river improvement works of the Sg. Dua Besar, the areas along the main stream will be protected from the flooding due to overflowing from the main stream.

However, the inner water problem during high tides (1.6 m) still remains in the lowlying area shown in Fig.

I-16. As a countermeasures for these areas reorganization of the catchment, realignment of existing drain and installation of the small scale pump facilities are recommended. The proposed drainage system is shown in Fig. I-16.

### (2) Area around PESTA

The existing ground level of PESTA is around 2.2 m, which is 0.3 m higher than D.H.W.L. (1.9 m). The cause of the existing inundation is considered to be mainly due to the reduced cross section at the bridge crossing Jln. Sg. Nibong. This inundation problem is expected to be solved after completion of the river improvements which will include reconstruction of the bridge.

### (3) To Jln. Sg. Dua

D.H.W.L. at the point of Jln. Sg. Dua is 3.2 m, which is about 0.5 m lower than the existing bank elevation (about 3.7 m). Most areas at the downstream of Jln. Sg. Dua, where the stream is partially embanked, are lowlying with existing ground levels between 2.5 m and 2.7 m.

Since the major land use in this lowlying area is cultivation, the inundation problem of this area will be solved by rising the ground level above the design bank level which is given in the Flood Mitigation Master Plan for the rivers.

### (4) Diversion Areas

It is presumed that existing flooding is caused by the backwater due to the bottle neck resulted by the bridge crossing Jln. Sg. Nibong and the inadequate discharge capacity of the diversion channel (5 - 14m3/s), due to the too gentle slope of the channel. (1/600 and 1/1000.)

Inundation due to river water overflow would be prevented by expanding the cross section of the diversion channel to a design discharge of 9 m3/s and removing the bottle neck by bridge reconstruction. The proposed cross section and longitudinal profile are shown in Fig. I-13.

There exists small lowlying area in the left bank near upper diversion channel. While it is difficult to fill the land because a clinic is located there, the inundation problem in this area can be solved by installing a small scale pump.

### 5.2.4. Sg. Nibong Kecil

# 1) Existing Condition of Sg. Nibong Kecil Catchment

Downstream of Sg. Nibong Kecil (from river mouth to Jln. Sungai Nibong) has already been improved by D.I.D. and construction of road side drain along Jln. Sg. Nibong was also completed. However, inundation or drainage problem is reported in the lowlying area along Jln. Relau and in the area along Jln. Mahsuri which is Sq. Relau catchment area.

Existing conditions of inundation are shown in Fig.I-18.

#### (1) Along the area of Jln. Relau

While run-off from Bukit Jambul is to flow along the Jln. Relau, the run-off presently flows into the lowlying area opposite side of Jln. Relau because the drain along the Jln. Relau is only small earth channel. The peak run-off discharge from Bukit Jambul is relatively high due to short time of concentration because of steep slope in the catchment. Accordingly the run-off exceeds the flow capacity of the existing small stream in the lowlying area and causes flooding there.

### (2) Along the area of Jln. Mahsuri

The run-off along Jln. Bukit Jambul is to flow down along the Jln. Relau, but it presently flows into the area opposite side of the road, finally reaching to the drain along the Jln. Mahsuri, since there is no trunk drain running along the Jln. Relau to Sg. Nibong Kecil outlet. The flow capacity of the drain along the Jln. Mahsuri is 8  $m^3/s$  and is not enough to cater the extra discharge from Jln. Bukit Jambul.

Since the area is flat, the inundation spreads widely through the area.

### 2) Design Discharge of the Drain along Jln. Relau

The channel along Jln. Relau is treated as a drain because; i) there is no natural river in the catchment along Jln. Relau, and ii) its catchment (55 ha) is smaller than 2 km2.

Design discharges at the target points (see Fig.I-18) for 10 year flood are;

Point A 2  $m^3/s_i$ 

Point B 4  $m^3/s$ .

#### 3) Causes of Inundation

#### (1) Along the area of Jln. Relau

The extra run-off from Bukit Jambul is considered to be the major cause of the inundation.

However, even if it is possible to cut off the runoff from Bukit Jambul by the drain along Jln. Relau, the flow capacity of the stream in the area is suspected to be not enough to cater the run-off from own catchment.

### (2) Along the area of Jln. Mahsuri

Main cause of inundation around Jln. Mahsuri is due to the run-off from Bukit Jambul area and part of Sg. Relau catchment which infact must be drained to Sg. Nibong Kecil and Sg. Relau outlets.

### 4) Drainage Plan

### (1) Along the area of Jln. Relau

To cut off the run-off from Bukit Jambul area to the opposite side area, it should be constructed the proposed road side drain along the Jln. Relau. The existing flood area is expected to be solved after completion of this drain. The proposed drain alignment is shown in Fig. I-19. The proposed cross section, longitudinal profile are shown in Fig.I-20.

However it is recommended to consider the land filling and improvement of the existing small stream when the area is developed in future.

### (2) Along the area of Jln. Mahsuri

Inundation problems of this area are expected to be solved by the construction of proposed drain along Jln. Relau, because inundation problem of this area is caused by run-off from Jln. Bukit Jambul area which is to be discharged through the proposed drain.

### (3) The catchment in the Westside of the Pesiaran Bukit Jambul Road

The run-off from the catchment in the westside of the Pesiaran Bukit Jambul road shown in Fig. I-21 is reported to flow down to the area of the Jln. Mahsuri. This catchment (A = 51 ha) initially belongs to the Sg. Relau catchment.

However, due to luck of proper drainage system to the Sg. Relau, run-off from this catchment causes flooding in the area along the Jln. Mahsuri.

The run-off discharge for 10 year flood from this catchment is  $12 \text{ m}^3/\text{s}$ .

To drain the run-off from this catchment, the construction of new drain connecting point A to the Sg. Relau as shown in Fig. I-21 is proposed.

### 5.2.5 Sg. Keluang (Sg. Relau, Sg. Ara)

### 1) Existing Condition

Sg. Keluang and downstream stretch of Sg. Ara has been improved by ongoing SDID's project.

Relau Diversion Channel (from CH.2410 of Sg. Relau to CH.2200 of Sg. Ara) is being proposed by DID and the Master Plan has incorporated this idea.

Areas along the downstream of these rivers are new industrial and housing area.

Inundation is reported for the following three areas as shown in Fig.I-22.

- (1) Sq. Ara (Jln. Tun Dr. Awang)
- (2) Sg. Relau (PDC housing area) (Jln. Tengah)
- (3) Jln. Bayan Lepas

### 2) Design Discharges of Main Stream

Design discharges of each point (see Fig.I-17) are as follows:

Point	A	(Sg.	Ara)	:	40 m <sup>3</sup> /s
Point	в	(Sg.	Relau)	:	65 m <sup>3</sup> /s
Point	с	(Sq.	Relau)	:	12 m <sup>3</sup> /s

### 3) Causes of Inundation

(1) Sg. Ara (Jln. Tun Dr. Awang)

Inundated area of Sg. Ara is limited alongside of the main stream. Causes of inundation in this area are considered to be rising of the water level due to inadequate discharge capacity of main river.

### (2) Sg. Relau (PDC housing area, Jln. Tengah)

Existing flow capacity of Sg. Relau of this area is about 10 - 30 m<sup>3</sup>/s. It is 55 - 35 m<sup>3</sup>/s less than design discharge (65 m<sup>3</sup>/s) without Relau Diversion Channel.

It can be judged that inundation is mainly caused by overflow from main stream, because drainage system of this area mostly discharges to the other river system through the road side drain of Jln. Sg. Nibong.

#### (3) Jln. Bayan Lepas

The existence of inundation was reported along the Jln. Bayan Lepas. But the actual area was not identified in the study.

### 4) Drainage Plan

Inundation or drainage problem of these areas will be solved by flood mitigation measures (river improvement, construction of diversion channel etc.) for the river.

I - 24

### (1) Sg. Ara

Improvement of Sg. Ara by deepening and widening will lower the water level and resolve the inundation problem in the areas along the river.

### (2) Sg. Relau

Design discharge of the Sg. Relau downstream stretch is 12  $m^3/s$  after completion of Relau Diversion Channel. Inundation problem will be solved by construction of Relau Diversion Channel and improvement of Sg. Relau downstream stretch.

Though some development plans are proposed in this area, it is recommended that existing river channel should be remained, because it will be necessary for the drainage in this area.

### 5.2.6 Sg. Nipah and Sg. Kampung Masjid

# 1) Existing Conditions of Sg. Nipah and Sg. Kg. Masjid

Both river basins, Sg. Nipah and Sg. Kg. Masjid, are located next to each other and areas comprise lowlying and filling up areas. Therefore the catchment can be easily changed by development works, such as housing development, road construction etc. For example several tributaries of Sg. Nipah was changed to Sg. Kg. Masjid by housing development.

There exist lowlying areas around both river mouths and the upstream. But presently, inundation was reported only upperstream area.

Upper catchments of the rivers have been rapidly developed and river channels are sometimes found to be filled without construction of any alternative drainage system. The inundation problems are observed in such ares.

Both downstream of Sg. Nipah and Sg. Kg. Masjid are affected by tide, but there is no flap gate, or any prevention structure for back flow, installed at the outlet of drains.

Existing conditions of these rivers are shown in Fig.I-23.

#### 2) Causes of Inundation

Inundation of upper catchment area is mainly considered to be caused by filling the land without any proper alternative drains or due to inadequate flow capacity of the rivers.

#### 3) Drainage Plan

The division of the catchment of Sg. Nipah and Sg. Kg. Masjid is shown in Fig. I-24.

The river improvement works for these two rivers are proposed in the Flood Mitigation Master Plan, and flooding Problems in these basins would be solved after completion of the river improvement works.

There exists the small drainage catchment (A=15 ha) in the Sg. Kg. Masjid basin.

For the drainage of this area, the road side drains along the Lebuhraya Batu Maung (B - C) and the Jln. Batu Maung (B - A) have been constructed.

In order to solve the flooding problem in the upstream basin of this catchment, the existing flow capacities of these drains were examined.

The cross section of these drains are shown in Fig. I-25

-	The flow capacity	
	Main drain type A	$2.2 \text{ m}^3/\text{s} \times 2 = 4.4 \text{ m}^3/\text{s}$
	Main drain type B	$4.2 \text{ m}^3/\text{s} \times 1 = 4.2 \text{ m}^3/\text{s}$

While, the run-off discharge of this catchment was estimated to be  $3.54 \text{ m}^3/\text{s}$  for 10 year flood.

Accordingly, This drainage system has enough capacity to cater 10 year flood, and does not need to be improved.

However, in the upper reaches of this basin, it is necessary to construct the secondary drains which shall be properly connected to the existing these main drains or rivers.

### 5.2.7 Sg. Kampong Seronok (Permatang Damar Laut)

### 1) Existing Conditions of Permatang Damar Laut Area

The Sg. Kampong Seronok flows into the tributary of Sg. Bayan Lepas passing through Permatang Damar Laut area. Under the ordinal flow condition, most of the river flow is diverted to irrigate Permatang Damar Laut paddy area and remaining water flows through small concrete channel of 200 m in length along to Jln. KEPERMATANG DAMAR LAUT and enter natural stream of secondary tributary of Sg. Bayan Lepas as shown in Fig. I-26.

In recent few years, floods occurred 3 to 5 times a year, duration of floods were 1 to 2 hours, and depth of inundation was about 1 or 2 ft.

### 2) Design Discharge of Sg. Kg. Seronok at Upstream of Permatang Damar Laut Area

Since Sg. Kg. Seronok is the one of tributaries of Sg. Bayan Lepas, this river was planned for 50-year flood.

Design discharge at target point is  $21 \text{ m}^3/\text{s}$ .

### 3) Causes of Inundation

Major causes of the inundation in Permatang Damar Laut area are due to inadequate flow capacity of the road side concrete channel (2  $m^3/s$ ) and improper operation of water gate for paddy field water intake.

### 4) Drainage Plan

The proposed countermeasures in this flooding area are river improvements for the 600 m stretches between the irrigation intake point A and confluence with tributary of the Sg. Bayan Lepas (point B) shown in Fig. 1-27.

The proposed alignment for the stretch between point A and point B was set on the east side of the road considering the existing land use condition.

The alignment of the downstream stretch from B to C basically follows the existing natural river course.

The features of the proposed river improvement works are as follows:

Concrete open channel: Rectangular width 5.0 m, depth 2.1 m, L = 200 m

Rubble pitching channel: Trapezoidal width 2.5 m, depth 2.1 m, L = 380 m

The proposed cross sections and longitudinal profile are shown in Fig. I-28.

Tables

.

# TABLE I-1-1 CHARACTERISTICS OF EXISTING OUTFALLS IN NORTH CHANNEL

	Catchmen	t Area**	Type *	Type *	Land Use of			Remarks	
Existing			of Main	or	Catchment		- (C	onditions of outf	
Outfall	(acres)	(ha)	Drain	Outfall	Area	Screen	Garbage	Siltation	Tidal Effect
N 1	50.0	20.2	CD	СВ	Park commercial	One (exit of outlet)	NONE	NONE	Some
N 2	4.9	2.0	CD	СР	Park	NONE	NONE	NONE	rarely
N 3	3.6	1.5	CD	СВ	Park	NONE	NONE	NONE	rarely
N 4	3.4	1.4	CD	СР 1	Commercial	One (exit of outlet)	NONE	NONE	Some 1
			+CD	+CD 2		Two(entranc e of outlets)			Some 2
N 5	50.6	20.5	CD	CD (heavily damaged)	Commercial	NONE	NONE	slightly	some
N 6	84.3	34.1	CD	CD	Mostly commercial	NONE	NONE	Outlet could be seen	
N7	11.8	4.8	CD	CD	Mostly residential	NONE	NONE	NONE	rarely
N 8	25.8	10.4	CD	CD	Residential	One (middle of main drain)	Some at screen	NONE	NONE
N 9	134.0	54.2	CD	CD (partly damaged)	Mostly residential	NONE	Some along main drain	slightly	heavily
N10	8.2	3.3	CD (no flow)	DC (totally silted)	Residential	NONE	Some	Totally silted up	hcavily
N11	29.7	12.0	CD	СВ	Residential	NONE	NONE	slightly	some
N12	396.0	156.2	CD	CP (one of two pipes totally silted)	Residential	NONE	Very few	Half silted up	heavily
N13	9.0	3.2	CD	СВ	Residential	NONE	NONE	Totally silted up	heavily
N14	97.7	39.5	CÐ	СВ	Residential	NONE	NONE	slightly	Some
N15	8.6	3.5	CD	CP (partly damaged)	Residential	NONE	NONE	NONE	rarely
N16	395.0	159.9	CD	СР	Residential	NONE	Very few	slightly	rarely
N17	10.0	4.0	CD	CP (partly damaged)	Residential	NONE	NONE	NONE	NONE
N18	27.3	11.0	CD	СР	Residential	NONE	Very few	NONE	rarely
N19	64.0	25.9	CD(partiy CP)	СР	Residential	NONE	Some	NONE	some
N20	241.0	97.5	CD partly	CD	Residential	One near Jin Kelawai	Some	heavily	some
N21	181.0	73,3	CD partly	Earth	Residential	NONE	Some	heavily	some

Note:

(\*)

CD = Channelized open drain

CP = Channelized pipe culvert

CB = Channelized box culvert

(\*\*) Source = Technical Report No. 14, Penang Island Structure Plan, 1985

.

mater'	Catchmer	nt Area**	· ·	Type *	Land Use of		-	Remarks	
Existing	()	<b>0</b> >	of Main	10	Catchment	<b>G</b>		Conditions of ou	•
Outfall	(acres)	(ha)	Drain	Outfall	Area	Screen	Garbage	Siltation	Tidal Effec
S 1	13.6	5.5	CD	С	Commercial	NONE	NONE	NONE	NONE
S 2	8.7	3.5	CD	С	Commercial	NONE	NONE	NONE	NONE
S 3	15	6.1	CD	CD	Commercial	NONE	Some	sightly	Some
S 4	15	6.1	CD	CD	Commercial	NONE	Some	sightly	Some
S 5	17.2	7	CD	СВ	Commercial	NONE	Some	NONE	rarely
S 6	12.6	5.1	CD	Earth	Commercial	NONE	Some	NONE	Some
S 7	18.1	7.3	CDCD	Earth	Commercial	NONE	Some	NONE	Some
S 8	11.5	4.7	CD	Earth	Commercial	NONE	Some	NONE	Some
-S 9	10	4	CD	Earth	Commercial	NONE	SomA lote	NONE	Some
\$10	279	113	CD	Earth .	Commercial	Two at pumpint station		NONE	Some
\$11	3	1.2	(almost not usable) E	(almost not usable) E	Residential	NONE	Some	sightly	Some
S12	3.9	1.6	CD, E	Е	Residential	NONE	Some	sightly	Some
S13	11.5	4.7	E	Е	Residentia]	NONE	Some	sightly	Some
S14	2.6	1.1	Е	E	Mostly residential	NONE	Some	sightly	Some
\$15	2.6	1.1	Mostly D	CD	Residential	NONE	Some	NONE	NONE
\$16	30	12.1	CD .	CD	Residential	One at the secondary drain	A lot	NONE	NONE
S17	13.1	5.3	CD	CD	Residential	NONE	Some	NONE	NONE
S18	292	118.2	CD	CD	Commercial (mostly)	NONE	Some	NONE	Some
S19	2.3	0.9	CD	CD	Residential	NONE	Some	NONE	rarely
S20	5.8	2.3	CD	CD	Residential	NONE	NONE	NONE	rarely
S21	5.9	2.4	CD	CD	Residential	NONE	NONE	Some	Some
S22	96,5	39.1	CD	Е	Residential	NONE	A lot	heavily	Some
S23	1305	528	CD	СВ	Residential	NONE	Some	NONE	NONE
S24	104.3	42.2	Mostly E	E	Residential	NONE	Some	NONE	rarely

#### TABLE I-1-2 CHARACTERISTICS OF EXISTING OUTFALLS IN SOUTH CHANNEL

Note:

(\*)

CD = Channelized open drain

CP = Channelized pipe culvert

CB = Channelized box culvert

E = Earth

(\*\*) Source = Technical Report No. 14, Penang Island Structure Plan, 1985

TABLE I-2 EXISTING DISCHARGE CAPACITY OF ML	XISTING DISCHARGE CAPACITY OF MAIN DRAIN AND OUTFALL IN NORTH AND SOUTH CHANNEL	
-	щ	

,					-																	•	L										
	Remark		-	Ţ	, c	n t	1	1 ~~	1	T	3	τ	5	-	3	.e	•	1		1 1	•	י . פי	ત્વ	63	, D	ব	ત્ય	ત	ט		લ	tr'	
pacity	(m3/s)	Outfall		4	2.7	19		4	2	20	)	17		~	2	15.4		I	0.5	_ 1		0.4	12.3	3.7	2.8	0.7	2.4	0.6	2.3		80.7	0.6	
Discharge Capacity		Main Drain	1	0.2	2.2	1.6	0.7	0.3	); ;	1.2	ļ	1.2	1	1.8		15.4			0.5		1	0.4	5.7	3.7	2.8	0.7	2.4	0.6	3.4		80.7	0.6	
No.of	Existing	Outfall	SI	S2	ß	3	S5	S6		LS		SS		6S		SIO		SII	S12	S13	S14	SIS	S16	S17	S18	S19	S20	S21	S22		EZS	\$24	
	Remark		ন্য	67	q	Ą	q	ъ	 ני	<u></u>	σ		•	q	8	q		с,	ଷ	বে	Q				·						►c>2.2>d	i Î	
Capacity	(m3/s)	Outfall	5.2	0.7	0.2	0.4	0.4	2.6	0.4	2.0	6.1	,	4	6.7	3.1	3.0	1.8	8.4	1.2	7.6	4.1									ipacity was categorized	10>b>5.5>	•	
Discharge Capacity		Main Drain		r	0.1	0.4	0.4	1.8	0.4	2.0	3.7	1	1.1	6.2	3.1	1.1	1.8	12.8	1.2	2.9	6.8									low capacity wa	period.		
No.of	Existing	Outtall	Ē	N2	R	뵷	N5	9N	Æ	N8	6N	0IN	IIN	NI2	N13	N14	NIS	N16	NI7	N18	6IN								Kemark	I he existing flow ca	by return perious at a > 10 year return	•	

1-30

### TABLE I-3 DRAIN RESERVE

Width of Drain	Drain Reserve
W < 3m	One side 1.5 m
3m < W < 7.5 m	One side 4.5 m
7.5 m < W < 15 m	One side 3 m, another side 6.0 m
15 m < W	Both sides 6 m

### TABLE I-4 RUN-OFF COEFFICIENTS FOR URBAN CENTRE

Landuse	Run-off Coefficient
Business:-	
City Areas Fully Built-up and Shophouses	0.90
Industrial:-	0.70
Fully Built-up	0.80
Residential:-	5100
4 houses/acre	0.55
4 - 8 houses/acre	0.65
8 - 12 houses/acre	0.75
12 houses/acre	0.85
Pavement	0.95
Parks (normally flat in urban areas)	0.30
Rubber	0.45
Jungle (normally steep in urban areas)	0.35
Mining Land	0.10
Bare Earth	0.75

Source:Hydrological Procedure No.16

-

PROBABLE FLOOD DISCHARGE OF DRAINAGE BASINS IN NORTH AND SOUTH CHANNEL TABLE 1-5

.

ž	NORTH CHANNEL	EL				SO	SOUTH CHANNE	Ē
	NO. of	Revised	4	Peak Discharge			NO. of	<b> </b>
	Existing	Catchment		(m3/s) .			Existing	
	Outfall	Arca					Outfail	
		(ha)	62	<u> 05</u>	010			
	īz	202	2.29	2.78	3.27		IS	
	N2	52	20	0.26	15.0		<b>S2</b>	
	EN	<u>ک</u> ا	0.19	0.2	0.27		8	
	N4	1.4	0.17	0.20	0.24		S4	
	N5	202	2.69	3.26	3.84		ß	
	9N	34.1	3.96	4.80	5.65		S6	
	Ŵ	4.8	0.69	0.84	66.0		S7	
١.	8N	10.4	1.43	1.73	2.04		Se	
	6N	542	5.66	6.88	8.09		<b>S9</b>	
	0IN	ι. Ε	0.20	0.36	0.42		<b>S10</b>	
	IIN	120	22.1	1.89	22		SII	
	N12	156.0	12.50	15.17	17.85		S12	
	N13	3.2	0.46	0.56	0.66		S13	
	N14	39.5	5.49	6.66	7.84		<b>S14</b>	
	NIS	3.5	0.52	0.63	0.74		S15	
	91N	1255	11.00	13.35	15.71		S16	
	LIN I	4.0	0.29	0.35	0.41		S17	
	N18	0.11	0.95	1.16	1.36		S18	
	61N	25.9	2.51	3.04	3.58		S19	

۰. -

۰

.

;

											_																	
				010	1.11	0.69	1.21	1.21	1.42	1.00	1.43	0.90	I.43	18.16	t	120	0.84	0.83	1.09	1.97	0.89	14.38	0.13	0.4	120	1231	•	7.32
	Peak Discharge	(m3/s)		S	0.94	650	1.03	1.03	1.21	0.85	13	0.77	13	15.44	1	23	0.71	0.71	0.93	1.67	0.76	12.65	0.11	0.34	0.31	6.15		6.22
	£.			62	0.78	0.48	0.85	0.85	66.0	0.70	1.00	0.63	1.00	1271		0.19	65.0	0.58	0.76	1.38	0.62	10.42	60.0	0.28	0.26	5.06	,	5.12
毘	Revised	Catchment	Arca	(ha)	55	35	6.1	6.1	7.0	5.1	73	4.7	7.6	120.0	1	1.6	4.7	53	6.6	120	6.8	104.0	6.0	23	24	48.8	,	42.2
DUTH CHANNEL	NO. of	Existing	Outfail		S1	<b>S2</b>	ន	S4	ß	S6	S7	88 88	65	810	SII	S12	S13	S14	<b>S15</b>	S16	S17	S18	S19	S20	\$21	223 2	£ZS	S24

•••

٠,

• .•

10 YEAR FLOOD DISCHARGE AT EXISTING OUTFALL IN THE NORTH CHANNEL TABLE I-6-1

( S/EvE)	EX OUTFAL	52	0.7	0.2	0.4	0.4		0.4	5	-	1			ŧ	3	1.8		1.2	7.6	•
( m/3/s )	EX MAIN	1		0.1	0.4	0.4	•	0.4	5			1.1		1.1	1.1	1.8		1.2	2.9	
( m^3/s)	σ	3.27	0.31	0.27	0.24	3.84	5.65	-6670	2.04	8.09	0.42	222	17.85	0.66	7.84	0.74	15.71	0.41	1.36	3.58
( mm )		121.92	121.92	127	121.92	121.92	104.14	124 46	124.46	93.98	127	124.46	71.12	127	119.38	127	88.9	127	127	127
inch )	=	4.8	4.8	5	4.8	4.8	4	4.9	4	3.7	3	4.9	2.8	5	4.7	5	3.5	S	S	5
)	0	0.667	0.546	0.778	0.792	0,772	0.786	0.876	0.873	0.773	0.540	0.758	0.759	0.876	0.817	0.885	0.812	0.672	0.747	0.830
	ర	0.72	0.66	0.65	0.65	0.72	0.73	0.68	0.65	0.74	0.67	0.70	0.76	0.67	0.73	0.67	0.62	0.43	0.47	0.47
HOUR)	Цd	0.09	0.01	0.10	0.10	0.16	0.31	0.13	0.15	0.38	0.12	0.11	0.57	0.12	0.18	0.03	0.76	0.11	0.19	0.23
RUOH) (RUOH	Тc	0.11	0.01	0.10	0.09	0.20	0.42	0.13	0.13	0.54	0.12	0.13	0.92	0.12	0.24	0.04	0.63	0.04	0.08	0.10
(mile)	L	0.1150	0.0112	0.1398	0.1305	0.2144	0.4226	0.1678	0.1958	0.5065	0.1616	0.1492	0.7707	0.1554	0.2362	0.0466)	1.0162	0.1429	0.2486	0.3108
sq. mile	A	0.078	0.010	0.006	0.005	0.079	0.132	0.019	0.040	0.209	0.013	0.046	0.602	0.012	0.153	0.014	0.485	0.015	0.042	0.100
S (%)	s	0.10	0.10	0.10	0.10	0.10	0.10	0.10	0.17	0.10	0.10	0.10	0.10	0.10	0.10	0.10	0.39	0.91	0.82	0.99
	s	0.00100	0.00100	0.00100	0.00100	0.00100	0.00100	0.00100	0.00167	0.00100	0.00100	0,00100	0.00100	0.00100	0.00100	0.00100	0.00390	0.00909	0.00820	0.00990
(E	1	185	18	225	210	345	680	270	315	815	260	240	1240	250	380	75	1635	230	400	500
(Pa)	8	20.2	2.5	1.5	1.4	20.5	34.1	4.8	10.4	54.2	3.3	12	156	3.2	39.5	3.5	125.5	4	11	25.9
	HERON	1	2	3	4	5	6	7	8	. 6	10	+- +	12	13	14	15	16	17	18	19

I-33

, <sup>i</sup>

١,

10 YEAR FLOOD DISCHARGE AT EXISTING OUTFALL IN THE SOUTH CHANNEL TABLE I-6-2

1	ain   Outfall	,	1.4	2.7	1.6	3.7	43	0.5	1.7	1.8			0.5	1	•	0.4	•	3.7	•	0.7	2.4	0.6	23	•	20
	Frunk Urain	2	0.2	2.2	1.6	0.7	0.3	1.2	1.2	1.8			0.5	•		0.4	•	3.7		0.7	2.4	0.6	3.4		
(11-3/5)	3	1.11	0.69	1.21	1.21	1.42	1.00	1.43	0.00	1.43	18.16		0.27	0.84	0.83	1.09	1.97	0.89	14.88	0.13	6.40	0.37	7.23		20 E
		121.92	121.92	119,38	119.38	121.92	119.38	116.84	116.84	114.3	83.82		119.38	121.92	106.68	111.76	104.14	121.92	86.36	121.92	121.92	121.92	101.6		0000
	-	4.8	4.8	4.7	4.7	4.8	4.7	4.6	4.6	4.5	3.3		4.7	4.8	4.2	4.4	4.1	4.8	3.4	4.8	4.8	4.8	4		4 X
0	5	0.869	0.869	0.870	0.870	0.869	0.869	0.869	0.868	0.854	0.858		0.881	0.876	0.773	0.768	0.805	0.809	0.791	0.794	0.820	0.821	0,805		100 C
	s	0.69	0.67	0.69	0,69	0.69	0.68	0.69	0.68	0.69	0.76		0.57	0.60	0.68	0.69	0.70	0.48	0.75	0.53	0.63	0.56	0.65		29 0
	D	0.09	0.04	0.12	0.11	0.10	0.21	0.24	0.24	0.27	0.44		0.19	0.16	0.37	0.30	0.35	0.06	0.43	0.01	0.10	0.12	0.49		100
	-	0.10	0.04	0.13	0.12	0.11	0.23	0.27	0.26	0:30	0.69		0.13	0.12	07.40	0.33	0.42	0.03	0.65	00.00	0.08	0.07	0.46		00.0
		0.1243	0.0472	0.1579	0.1417	0.1336	0.2878	0.3182	0.3250	0.3574	0.5966		0.2610	0.2088	0.4972	0.3990	0.4736	0.0608	0.5718	0.0093	0.1305	0.1554	0.6526		O 2850
	- ۲	0.021	0.014	0.024	0.024	0.027	0.020	0.028	0.018	0.029	0.463		0.006	0.018	0.020	0.025	0.046	0.026	0.402	0.003	0.009	0.009	0.138		59F 0
	~	0.10	0.10	0.10	0.10	0.10	0.10	0.10	0.10	0.10	0.10		0.21	0.21	0.10	0.10	0.10	0.68	0,10	0.27	0.13	0,27	0.24		176 U
	S	0.00100	0.00100	0.00100	0.00100	0.00100	0.00100	0.00100	0.00100	0.00100	0.00100		0.00207	0.00207	0.00100	0.00100	0.00100	0.00680	0.00100	0.00267	0.00133	0.00267	0.00238		0.0028
	_	200	76	254	228	215	463	512	523	575	960		420	336	800	642	762	130	920	15	210	250	1050		460
		5.5	3.5	6.1	6.1	7 7	5.1	7.3	4.7	· [ 7.6	120		1.6	4.7	5.3	6.6	12	6.8	104	0.9	2.3	2.4	48.8		10 07
Ē	<b>н</b> 000	+	2	3	4	5	6	7	s	6	10	11	12	13	14	15	16	17.	18	19	20	21	22	23	24

TABLE I-7-1	REQUIRED IMPROVEMENT	W
	NORTH CHANNEL	

#### WORKS OF DRAINS IN

No.of	Catchment		MEASUR	E OF IMPRO	OVEMENT	No. of		Q 10
Existing	Агеа	Flow			Widening/	New	Proposed	Discharge
Outfall	(ha)	Capacity	Reorganization	Realignment	Deepening	Outfall	C.A.(ha)	(m3/s)
N1	20.2	а				PN1	20.2	3.30
N2	2.5	a				PN2	2.5	0.30
N3	1.5	đ		EXT.	0	PN3	2.7	0.46
N4	1.4	а		EXT.		PN4	3.0	0.54
N5	20.5	d		EXT.	0	PN5	25.5	4.70
N6	34.1	d		EXT.	0	PN6	39.4	6.56
N7	4.8	d		EXT.	0	PN7	6.6	1.32
N8	10.4	ь	0	EXT.	0	PN8	17.3	2.33
N9 \	54.2	d	0	EXT.	0	PN9	43.7	9.04
N10	3.3	-	0	EXT.	0	-	-	
N11	12.0	-	0	EXT.	0	PN10	25.8	2.56
N12	156.0	d	0	EXT.	0	PN11	161.8	17.60
N13 <sup>]</sup>	3.2	а		o ext.			(4.9)	
N147	39.5	đ		O EXT.	0	PN12	45.6	9.40
N15 J	3.5	a		o EXT.		~	(4.8)	
· N16	125.5	đ		EXT.	· 0	PN13	126.3	16.30
N17]	4.0	а		o ext.		<u>ب</u>	(4.9)	
N18	11.0	а		o EXT.		-	(12.4)	
N19	25.9	а		O EXT.		PN14	46.0	6.39

Remark

The existing flow capacity was categorized

by return periods as follow;

a > 10 year return period, 10 > b > 5, 5 > c > 2, 2 > d

No.of	Catchment		MEASUR	E OF IMPR	OVEMENT	No. of		Q 10
Existing	Arca	Flow			Widening/	New	Proposed	Discharge
Outfall	(ha)	Capacity	Reorganization	Realignment		Outfall	C.A.(ha)	(m3/s)
S1	5.5	· · ·				PS1	5.5	1.10
S2	3.5	d			0	PS2	3.5	0.69
S3	6.1	а				PS3	6.1	1.21
S4	6.1	a				PS4	6.1	1.21
S5	7.0	d			0	PS5	7.0	1.42
S6	5.1	d		EXT.	0	PS6	9.0	1.77
S7	7.3	d		EXT.	о	PS7	12.2	2.37
S8	4.7	a		EXT.		PS8	9.2	1.77
S9	.7.6	а		EXT.		PS9	16.6	3.14
ר \$10	120.0	b		O EXT.	0	PS10	126.3	18.37
S11		-		O EXT.	· 0	-	-	
S12	1.6	а		O EXT.			(1.6)	
S13 J	4.7	-		O EXT.	0	-	(4.7)	
S14	5.3	-		EXT.	0	PS11	8.0	1.24
S15	6.6	d		O EXT.	0	.	(6.6)	
S16 J	12.0	a		O EXT.		PS12	25.3	4.05
S17	6.8	a				PS13	6.8	0.89
S18	104.0	d		EXT.	0	PS14	104.0	14.85
S19	0.9	a				PS15	0.9	0.13
S20	2.3	a				PS16	2.3	0.40
S21	2.4	a	1	1		PS17	2.4	0.37
S22	48.8	d			0	PS18	48.8	7.23
S23	528.0	а	Jelutong [	Diversion EXT	. ]	-	-	
S24	42.2	d	1	[	0	PS19	42,2	7.32

## TABLE I-7-2REQUIRED IMPROVEMENTWORKS OF DRAINS IN<br/>SOUTH CHANNEL

Remark The existing flow capacity was categorized by return periods as follow :

by return periods as follow ; a > 10 year return period, 10 > b > 5, 5 > c > 2, 2 > d FEATURES OF LOWLYING AREAS IN PENANG ISLAND TABLE I-8

Causes	of Counter Measures	Inundation	Inadequate flow Realignment of Outfall		main stream	Hightide Pumping		Lowlying hightide Filling up	Lowlying hightide Filling up	Lowlying hightide Filling up	Filling up	Filling up
	Location		Brown Garden	Minden Heights capacity of		Ch 00-800		Mid & downstream	Downstream	Downstream	Downstream	Downstream
Experienced	Flooding	Area (ha)										
Existence of	Lowlying	Areas	exist			exist	exist	exist	exist	exist	exist	exist
Lowest	Ground	Level	ε ε			1.5m		1.4 m	1.0 m	1.0 m	1.6 m	1.2 m
	NAME		Sq. Gelugor			Sg. Dua Besar	Sq. Nibong Kecil	Sg. Keluang	Sq. Nipah	Sg. Kampung Masjid	Sg. Batu	Sg. Teluk Kumbar
CATCH-	MENT	NO.	13 T			14	16	17	-1 1 1	19	22	24

Sg.Teluk Awak

2 ო

Sg. Batu Ferringghi Sg. Teluk Bahang

> 57 ŝ

Sg. Satu

Sg. Mas

6

r--

Sg. Kecil

Sg. Kelian ω

Sg. Balik Batu

Sg. Fettes

Sg. Bagan Jermal

Sg. Babi

Sg. Nibong Besar

Sg. Ikan Mati

Sg. Bayan Lepas

Sg. Mati

Sg. Gemuroh 

sg. Gertak Sanggul

no experienced flooding area in these catchments There is no lowlying areas and also there is existing ground level is higher than 2.00 m. (except for Sg. Ikan Mati 1.8 m and Sg. Bayan Lepas 1.7 m). In these river basins

 Table I- 9
 CAUSES OF INUNDATION AND COUNTERMEASURES

 IN THE AREAS OUTSIDE GEORGETOWN

2

Location	Causes of inundation	Flooding Area (ha)	Countermeasures
Sg. Gelugor - Brown Garden	Inadequate flow capacity of main stream	2	1; Improvement of Sg. Gelugor
- Minden Heights	Existence of lowlying area Inadequate flow capacity of drain.	4	<ul> <li>4. recaugiment of existing training countait</li> <li>1; Improvement of original Sg. Gelugor</li> <li>2; Improvement of drainage channel</li> <li>3; Recommendation of retention pond near USM</li> </ul>
Sg. Dua Besar - Downstream of Jin. Sg. Nibong	Existence of lowlying area Failure in drain from lowlying area along the main stream		1; Improvement of main river 2; Installation of small scale drainage pump
- Area around PESTA	Inadequate flow capacity of main stream	Total	Improvement of main river
- to Jln. Sg. Dua	Inadequate flow capacity of main stream	09	Improvement of main river and land fill
- along the Diversion	Inadequate flow capacity of the Diversion Channel Existence of lowlying area		1; Improvement of the existing diversion channel 2: Installation of small scale drainage numn
Sg. Nibong - Jln. Relau	Extra run-off from Bukit Jambul	Total	1; Construction of road side drain
- Jin. Mahsuri	Inadequate flow capacity of drain along Jin. Relau	20	2; Construction of new drain to Sg. Keiau Expected to be solved by countermeasures for the area along Jin. Relau
Sg. Keluang - Jin. Tun Dr. Awang - PDC Housing Area	Inadequate flow capacity of main stream Inadequate flow capacity of main stream	10	Improvement of Sg. Ara Expected to be solved by construction of
- Jln. Bayan Lepas	Actual area was not identified		Actal Diversion Channel
Sg. Nipah	Filling land without proper alternative drains Existence of lowlying area		1; Construction adequate alternative drain 2; Land filling of lowlying area
Sg. Kg. Masjid	Existence of lowlying area		Land filling of lowlying area
Sg. Kg. Seronok (Sg.Bayan Lepas)	Inadequate flow capacity of concrete channel stretch along the road and improper operation of intake gate for irrigation	ó	Improvement of Sg. Kg. Seronok downstream reaches

1.9 m (Bed W) x 1.7 m (Water D) Slope=1/650 | Earth Channel (1:1) Earth Channel (1:1) Concrete Channel Concrete Drain Concrete Drain Concrete Drain Concrete Drain Earth Channel Remarks 5.3 m (Bed W) x 1.7 m (Water D) Slope=1/450 3.0 m (Bed W) x 1.5 m (Water D) Slope=1/200 Upstream 1.2 m (W) x 1.0 m (D) S=1/300 Downstream 1.5 m (W) x 1.2 m (D) S=1/300 Downstream 2.5 m (W) x 1.5 m (D) S=1/110 Upstream 5.0 m (W) x 1.5 m (D) S=1/500 3.5 m (W) x 1.5 m (D) S=1/600 Size about 1,600 m about 500 m 450 m (,200 m 650 m Length 85m • Recommendation of retention pond near USM Improvement of Sg. Kg. Seronok downstream Expected to be solved by countermeasures for the area along Jln. Relau 1; Improvement of main river 2; Installation of small scale drainage pump 1; Improvement of the Diversion Channel 2; Installation of small scale drainage pump Expected to be solved by construction of Relau Diversion Channel Improvement of main river and land fill 2; Realignment of existing drainage outfall Construction of new drain to Sg. Relau 1; Construction adequate alternative drain Inprovement of original Sg. Gelugor
 Improvement of drainage channel
 Recommendation of retention pond m Countermeasures Construction of road side drain Land filling of lowlying area 2; Land filling of lwlying area 1; Improvement of main river Improvement of main river Improvement of Sg. Ara reaches - Area around PESTA along the Diversion PDC Housing Area - Jh Tun Dr. Awang - Downstream of Jln. Sg. Nibong - Minden Heights (Sg. Bayan Lepas) to Jln. Sg. Dua - Brown Garden Sg. Kg. Seronok Location - Jin Sg. Relau Sg. Kg. Masjid Sg. Dua Besar . Jin Mahsuri Sg. Gelugor Sg. Keluang Sg. Nibong Sg. Nipah

TABLE I- 10 FEATURES OF PROPOSED DRAINAGE FACILITIES IN THE AREAS OUTSIDE GEORGETOWN

	(10^3 M\$)	(10^3 M\$)	(10^3 M\$)	(10^3 M\$)	(10^3 M\$)	(10^3_M\$)
NORTH	Direct	Evacuation	Administration	Enginering	Contingency	TOTAL
NO.	costs	costs	costs	services costs		· ·
1	0	0	0	0	0	0
2	0	0	0	0	0	0
3	262	0	13	13	58	346
4	253	0	13	13	56	334
5	391	0	20	20	86	516
6	708	78	35	35	171	1,029
7	307	175	15	15	102	615
8	352	194	18	18	116	698
9	1,373	466	69	69	395	2,371
10	293	0	15	15	65	387
11	289	0	14	14	64	381
12	2,188	0	109	109	481	2,889
13	283	0	14	14	62	374
14	659	0	33	33	145	870
15	239	0	12	12	53	316
16	2,710	0	136	136	596	3,577
17	185	0	9	9	41	244
18	673	0	34	34	148	889
19	199	0	10	10	44	263
TOTAL	11,365	912,270	568	568	2,683	16,098

# TABLE I-11 FINANCIAL COST OF GEORGETOWN DRAINAGE MASTER PLAN

				· · · · ·		
	(10^3 M\$)	(10^3 M\$)	(10^3 M\$)	(10^3 M\$)	(10^3 M\$)	(10^3 M\$)
SOUTH	Direct	Evacuation	Administration	Enginering	Contingency	TOTAL
NO.	costs	costs	costs	services costs		
1	0	0	0	0	0	0
2	157	0	8	8	34	207
3	0	0	0	0	0	0
4	0	0	0	0	0	0
5	269	0	13	13	59	355
6	427	0	21	21	94	564
7	474	0	24	24	104	626
. 8	542	0	27	27	119	715
9	623	. 0	31	31	137	822
10	9,687	0	484	484	2,131	12,787
11	0	0	0	0	0	0
12	419	0	21	21	92	553
13	290	0	14	14	64	383
14	0	0	0	0	0	0
15	996	0	50	50	219	1,315
. 16	442	0	22	22	97	584
17	0	0	0	0	0	0
18	17,040	630	852	852	3,875	23,249
19	. 0	0	0	0	0	0
20	0	0	0	0	0	0
21	- 0	0	0	0	0	0
22	1,860	0	93	93	409	2,455
24	936	399	47	47	286	1,715
TOTAL	34,162	1,029	1,708	1,708	7,721	46,329

TOTAL AMOUNT (M\$)

62,427

UKAINAGE						·
	(m)	(m <sup>^</sup> 3)	(m^3)	(m^3)	(sq.m)	(nos.)
NORTH	STRETCH	EXCAVATION	CONCRETE	BACKFILL	PAVING	WOODEN PILE
1	-	-	· -	-		· · ·
2	•		-	-	• •	-
3	225	468	216	585	900	4,676
4	210	464	208	546	840	4,364
5	345	1,525	518	449	1,380	7,169
5	680	3,774	1,163	1,020	2,720	14,130
7	270	770	316	405	1,080	5,611
8	315	1,134	416	473	1,260	6,546
9	815	4,727	4,059	4,115	3,260	16,936
10	260	624	281	390	1,040	5,403
11	240	792	302	360	960	4,987
12	2,445	21,500	3,600	7,900	9,800	38,550
13	250	544	259	375	1,000	5,195
14	380	4,484	1,630	1,881	1,520	7,896
15	180	540	216	270	720	3,740
16	1,635	33,681	7,400	12,246	6,540	33,975
17	145	315	44	218	580	3,013
18	290	1,044	2,088	435	1,160	6,026
19	125	694	152	188	500	2,598
TOTAL	8,810	77,079	22,866	31,854	35,260	170,815

### TABLE I-12 BILL OF QUANTITY FOR GEORGETOWN DRAINAGE MASTER PLAN DRAINAGE


0011711	(m)	(m^3)	(m^3)	(m^3)	(sq.m)	(nos.)
SOUTH	STRETCH	EXCAVATION	CONCRETE	BACKFILL	PAVING	WOODEN PILE
1	-	-	-	-	-	-
2	76	188	83	114	304	1,579
3	-	-	-	••	-	-
4	-	-	-	<b>-</b> 1		
- 5	215	688	271	344		
6	390	1,593	579	741	1,560	
7	432	2,052	687	821	1,728	8,977
8	523	2,354	785	785	2,092	10,868
9	575	3,364	1,018	863	2,300	11,949
10	1,660	32,000	5,700	13,500	11,700	34,500
11	•	-	-	-	-	-
12	240	600	960	360	960	4,987
13	143	358	572	215		2,972
14	-					•
15	642	2,215	2,761	963	2,568	13,341
16	150	1,350	1,275	225		3,117
17	-	-	-	•	-	-
18	4,530	105,000	31,000	50,000	34,800	80,180
19	•			-	•	-
20	-	-	-		-	-
21	-	.	-	-	-	•
22	1,050	6,300	5,880	1,575	4,200	21,819
24	460	1,656	2,944	828	1,840	
TOTAL	11,086	159,717	54,514	71,332	66,084	216,419


#### TABLE I-13 BREAKDOWN OF CONSTRUCTION COST FOR GEORGETOWN DRAINAGE MASTER PLAN DRAINAGE


DRAINAGE	-						
	(10^3 M\$)	(10^3 M\$)					
NORTH	EXCAVATION		BACKFILL	PAVING	1	MISCELLANEOUS	TOTAL
1		*					
2		-	-	-			
3	4	43	, ,	90	23	100	262
4	4	42		84		100	253
5	12	104		138			. 391
6	30	233		272			708
7	6	63		108			307
. 8	9	83		126			352
9	38	812		326			1,373
10	5	56		104			293
11	6	60		96			289
12	- 172	720	24	980			2,188
13	4	52		100		100	283
14	36	326		150	39	100	659
15	4	43	1	72		100	239
16	269	1,480	37	654	170	100	2,710
17	3	9	1	58		100	185
18	8	418	1	116		100	673
19	6	30	1	50	13	100	199
TOTAL	617	4,573	96	3,526	854	1,700	11,365
	LI			0,010			11,000
	(10^3 M\$)	(10^3 M\$)					
SOUTH	EXCAVATION	CONCRETE	BACKFILL	PAVING		MISCELLANEOUS	TOTAL
1	-	-	-	-	•	- 1	-
2	2	17	0	30	8	100	157
3	-	-	-		-	-	-
4	-	-	-	-	-	.	-
5	6	54	1	86	22	100	269
6	13	116	2	156	41	100	427
7	16	137	2	173	45	100	474
8	19	157	2	209	54	100	542
-9	27	204	3	230	60	100	623
10	256	1,140	41	1,170	173	100	2,879
11	-	-	-	•	-	-	
12	5	192	1	96	25	100	419
13	3	114	1	57	15	100	290
14	-	-	-	-		-	-
15	18	552	3	257	67	100	996
16	11	255	1	60	16	100	442
17	-	-	-	-	-		-
18	840	6,200	150	3,480	401	300	11,371
19	-	-		-	-	-	-
20	-	-	-		-	-	-
21	-	-	-	-	-	-	-
22	50	1,176	5	420	109	100	1,860
24	13	589	2	184	48	100	936
TOTAL	1,278	10,903	214	6,608	1,082	1,600	21,685
					-1000	,000	6.1,000

TOTAL AMOUNT 1,136

# Figures







I-45

