

APPENDIX - E PRELIMINARY EVALUATION RESULTS AND ASSIGNMENT RESULTS OF CONCEIVABLE REHABILITATION PLAN FROM FUNCTIONAL VIEW POINT

NO.	KEY	STATE	DISTRICT	YEAR BUILT	STUDY CATEGORY	CAPACITY	TYPE OF BRIDGE	CARRIAGE WAY WIDTH	SIDE WALK WIDTH	L OR R	NO'S OF PEDESTRIAN	TRAFFIC CAPACITY	PRESENT DEMAND	TRAFFIC VIEW POINT		RIVER VIEW POINT	CONCEIVABLE REHABILITATION PLANS
														GROWTH RATE	V/C		
125	0901450	NS	K. PILAH	1950	2	SSAL	SBB	6.70	0.59	L&R		1514	250	4.6	0.17	2147	
126	0901700	NS	K. PILAH	1950	2	SSAL	SBB	6.74	0.59	L&R		1514	250	4.6	0.17	2147	
127	0901950	NS	K. PILAH	1950	2	SSAL	SBB	6.80	0.50	L&R		1514	250	4.6	0.17	2147	
128	0902270	NS	K. PILAH	1950	2	SSAL	SBB	6.74	0.50	L&R		1497	250	4.6	0.17	2147	
129	0902360	NS	K. PILAH	1950	2	SSAL	SBB	6.85	0.50	L&R		1497	250	4.6	0.17	2147	
130	0902450	NS	K. PILAH	1950	2	SSAL	SBB	6.80	0.50	L&R		1497	250	4.6	0.17	2147	
131	0902440	NS	K. PILAH	1950	2	SSAL	SBB	6.90	0.50	L&R		1497	250	4.6	0.17	2147	
132	09004300	NS	K. PILAH	1950	2	SSAL	SBB	5.90				1512	250	4.6	0.17	2147	
133	0905190	NS	JEMPUL	1950	2	SSAL	SBB	6.19				1580	541	5.1	0.35	2127	
134	0907010	NS	JELEBU	1930	2	SSAL	SBB	6.18				307	6.8	0.18	2098		
135	0906400	NS	JELEBU	1935	2	PJA	RCB	6.10				1711	307	6.8	0.18	2098	
136	0911990	PAHANG	BENTONG	1931	2	SSAL	SBB	6.10				1524	307	0.2	0.19	2107	
137	01103770	NS	JEMPUL	1970	3	SSAL	PRB	5.56	0.39	L&R		1843	499	31.6	0.29	2014	
138	01800060	PERAK	MANJUNG	1960	3	SSAL	RCS	6.50			Much	1854	2008	6.0	1.08	1930	
139	01800570	PERAK	MANJUNG	1950	3	SSAL	SBC	6.75				1730	1992	6.0	1.15	1980	ADDING & WIDENING
140	02305040	JOHOR	SEGAMAT	1950	3	SSAL	SBB	5.55				1577	259	1.6	0.16	2441	
141	02305970	JOHOR	SEGAMAT	1950	4	SSAL	RCS	6.75				1793	259	1.6	0.14	2450	RAISING GRADE
142	05001070	JOHOR	BATUPAHAT	1919	2	SSAL	SBB	6.40	4.00	L&R		2205	2097	4.0	0.94	2114	
143	05001890	JOHOR	BATUPAHAT	1950	3	SSAL	SBB	6.06	3.73	L&R		1891	1171	4.0	0.69	2147	
144	05002590	JOHOR	BATUPAHAT	1940	2	SSAL	SBB	5.90				1605	1171	6.7	0.73	2082	
145	05100840	NS	SEREMBAN	1950	3	SSAL	SBB	6.30				1531	522	-6.5	0.34	N/A	
146	05101360	NS	SEREMBAN	1940	3	SSAL	SBB	13.70	2.50	L		1762	522	-6.5	0.30	N/A	
147	05101480	NS	SEREMBAN	1950	2	SSAL	SBB	12.60	1.70	R		1762	522	-6.5	0.30	N/A	
148	05102060	NS	K. PILAH	1950	3	SSAL	SBB	7.55				1823	522	1.6	0.32	2429	
149	05102280	NS	K. PILAH	1960	3	SSAL	PRB	5.64				1531	522	1.6	0.34	2424	
150	05102380	NS	K. PILAH	1960	3	SSAL	PRB	5.70				1538	522	1.6	0.34	2424	
151	05102570	NS	K. PILAH	1960	3	SSAL	SBB	7.32				1762	522	1.6	0.30	2437	
152	05103000	NS	K. PILAH	1950	3	SSAL	SBB	6.76	0.35	L&R		1531	522	1.6	0.34	2424	
153	05103300	NS	SEREMBAN	1958	3	SSAL	SBB	6.74	0.35	L&R		1578	522	1.6	0.33	2427	
154	05200280	NS	SEREMBAN	1932	3	SSAL	SBB	6.76				2439	625	3.9	0.26	2169	
155	05202450	SELANGOR	ULANGAT	1955	3	SSAL	RCS	6.92				2087	576	4.7	0.28	2147	
156	05203970	SELANGOR	ULANGAT	1950	3	SSAL	BOX	8.40	1.12	R		2590	721	5.4	0.28	2131	
157	05204870	SELANGOR	ULANGAT	1964	3	SSAL	SBC	7.38	0.8	L&R		2590	721	5.4	0.28	2131	INADEQUATE
158	05300470	NS	PD	1950	3	SSAL	SBB	6.90				2051	653	2.2	0.32	2321	
159	05300980	NS	PD	1950	3	SSAL	SBB	6.55				1940	653	2.2	0.34	2317	
160	05301190	NS	PD	1950	3	SSAL	SBB	6.45				1940	653	2.2	0.34	2317	
161	05302050	NS	SEREMBAN	1950	3	SSAL	SBB	6.78	0.58	L&R		1940	653	2.2	0.34	2317	
162	05302160	NS	SEREMBAN	1950	3	SSAL	SBB	6.90				1994	653	2.2	0.33	2318	
163	05302340	NS	SEREMBAN	1940	3	SSAL	SBB	6.10	0.55	L&R		1994	653	2.2	0.33	2318	
164	05403460	SELANGOR	PETALING	1950	3	SSAL	RCS	9.24				1962	1000	11.3	0.51	2052	
165	05403570	SELANGOR	PETALING	1960	3	SSAL	BOX	6.90	4.00	L&R		1731	1000	11.3	0.58	2050	
166	05801510	PERAK	HLR PERAK	1950	3	SSAL	SBB	6.80				1291	417	1.0	0.32	2669	
167	05801820	PERAK	HLR PERAK	1950	2	SSAL	SBB	6.90				1291	417	1.0	0.32	2669	
168	05803340	PERAK	BTG PADANG	1950	3	SSAL	SBB	6.70				1578	941	3.5	0.25	2195	
169	05901000	PERAK	BTG PADANG	1950	3	SSAL	SBC	6.70	0.58	L&R		1749	544	19.4	0.31	2028	
170	05901070	PERAK	BTG PADANG	1950	3	SSAL	SBC	6.70	0.58	L&R		1749	544	19.4	0.31	2028	
171	05901480	PERAK	BTG PADANG	1950	3	SSAL	SBC	7.20	0.56	L&R		1749	544	19.4	0.31	2028	
172	05901580	PERAK	BTG PADANG	1950	3	SSAL	SBC	6.75	0.54	L&R		1749	544	19.4	0.31	2028	
173	05901880	PERAK	BTG PADANG	1950	3	SSAL	SBC	6.74	0.54	L&R		1749	544	19.4	0.31	2028	
174	05902060	PERAK	BTG PADANG	1950	3	SSAL	SBC	6.60	0.64	L&R		1649	544	19.4	0.33	2028	
175	05902230	PERAK	BTG PADANG	1950	3	SSAL	SBC	6.85	0.54	L&R		1649	544	19.4	0.33	2028	
176	05902860	PERAK	BTG PADANG	1950	3	SSAL	SBC	7.20	0.54	R		1749	544	19.4	0.31	2028	
177	05902920	PERAK	BTG PADANG	1950	3	SSAL	SBC	6.75	0.55	L&R		1749	544	19.4	0.31	2028	
178	05903120	PERAK	BTG PADANG	1950	3	SSAL	SBC	6.70	0.54	L&R		1749	544	19.4	0.31	2028	
179	05905070	PAHANG	LIPIS	1961	3	SSAL	PCB	6.60	0.62	L&R		1649	544	19.4	0.33	2028	
180	05805290	PAHANG	LIPIS	1930	3	SSAL	SBB	6.90				1749	544	19.4	0.31	2028	
181	05905010	PAHANG	LIPIS	1930	3	SSAL	SBB	6.85				1749	544	19.4	0.31	2028	
182	06000970	PERAK	MANJUNG	1930	3	PJA	SBE	4.60	0.40	R		1489	352	5.7	0.22	2115	
183	06001380	PERAK	MANJUNG	1960	3	SSAL	RCS	6.40				1578	352	5.7	0.22	2115	
184	06005070	PERAK	LAMSELAMA	1950	3	SSAL	SBC	6.70				1439	346	3.0	0.24	2225	
185	06005220	PERAK	LAMSELAMA	1960	3	SSAL	RCS	6.70	0.3	L&R		1439	346	3.0	0.24	2225	
186	06005740	PERAK	LAMSELAMA	1960	3	SSAL	RCS	6.90				1578	346	3.0	0.22	2116	

APPENDIX - E PRELIMINARY EVALUATION RESULTS AND ASSIGNMENT RESULTS OF CONCEIVABLE REHABILITATION PLAN FROM FUNCTIONAL VIEW POINT


NO.	KEY	STATE	DISTRICT	YEAR BUILT	STUDY CATEGORY	CAPACITY	TYPE OF BRIDGE	CARRIAGE WAY WIDTH	SIDE WALK WIDTH	L or R	NO'S OF PEDESTRIAN	TRAFFIC CAPACITY		TRAFFIC VIEW POINT		RIVER VIEW POINT BRIDGE OPENING	CONCEIVABLE REHABILITATION PLANS
												TRAFFIC CAPACITY	PEDESTRIAN	PRESENT DEMAND	GROWTH RATE		
187	06006050	PERAK	LAMBELANA	1950	3	SSAL	SBB	5.84				1405	343	5.7	0.25	2114	
188	06403300	PAHANG	JERANTUT	1930	3	SSAL	SBB	6.30				1405	169	5.4	0.12	2123	
189	06403900	PAHANG	JERANTUT	1930	3	SSAL	SBB	6.15				1405	169	5.4	0.12	2123	
190	06404270	PAHANG	JERANTUT	1930	3	SSAL	SBB	5.60				1405	169	5.4	0.12	2123	
191	06404940	PAHANG	JERANTUT	1930	3	SSAL	SBB	5.70				1405	169	5.4	0.12	2123	
192	06405660	PAHANG	JERANTUT	1930	3	P/A	SBB	6.65				1490	169	5.4	0.11	2125	
193	06405980	PAHANG	JERANTUT	1930	3	P/A	SBB	5.80				1405	169	5.4	0.12	2123	
194	06701200	KEDAH	KMUDASIK	1930	3	P/A	RCB	6.80				1822	578	4.4	0.32	2153	
195	06701230	KEDAH	KMUDASIK	1940	3	P/A	RCB	6.80		L&R		1822	578	4.4	0.32	2153	
196	06701690	KEDAH	KMUDASIK	1968	3	SSAL	PCB	7.80				1822	578	4.4	0.32	2153	
197	06702960	KEDAH	BALING	1950	3	SSAL	SBE	6.90				1822	578	4.4	0.32	2153	
198	07000290	PERAK	HLR PERAK	1950	3	SSAL	SBB	7.02				1851	417	-3.3	0.27	N/A	
199	07001780	PERAK	HLR PERAK	1970	3	SSAL	IT	7.94	1.08	L&R		1551	417	-3.3	0.27	N/A	
200	07002480	PERAK	BTG PADANG	1950	3	SSAL	SBB	5.80				1453	417	-3.3	0.29	N/A	
201	07602330	PERAK	K KANGSAR	1950	2	SSAL	SBB	5.70				1431	258	5.0	0.18	2133	
202	07602460	PERAK	K KANGSAR	1950	4	SSAL	SBB	5.80	1.06	R		1550	258	5.5	0.17	2122	
203	07604020	PERAK	HULU PERAK	1950	3	SSAL	SBB	5.60				1550	258	5.5	0.17	2122	
204	07604160	PERAK	HULU PERAK	1950	3	SSAL	SBB	5.60				1550	258	5.5	0.17	2122	
205	07604750	PERAK	HULU PERAK	1950	3	SSAL	SBB	7.00				1500	258	8.0	0.17	2081	
206	07606390	PERAK	HULU PERAK	1950	3	SSAL	SBB	5.70				1443	258	8.0	0.18	2080	
207	08601000	NS	SEREMBAN	1950	3	SSAL	SBB	6.95				1704	353	6.8	0.32	2089	
208	08601190	NS	SEREMBAN	1950	2	SSAL	SBB	5.00				1104	353	6.8	0.32	2089	
209	08601410	NS	SEREMBAN	1950	3	SSAL	SBB	5.05				1104	353	6.8	0.32	2089	
210	08601830	NS	SEREMBAN	1950	3	SSAL	SBB	6.92				1822	353	7.4	0.22	2088	
211	08602150	NS	SEREMBAN	1950	3	SSAL	SBB	6.34				1530	353	7.4	0.22	2087	
212	08602600	NS	JELERU	1950	3	SSAL	SBB	8.20	4.85	L&R		1715	277	7.4	0.15	2090	
213	08602940	NS	JELERU	1960	3	SSAL	RCB	8.29				1530	277	7.4	0.18	2088	
214	08603735	NS	JELERU	1950	3	SSAL	SBB	4.40				1530	415	8.1	0.27	2078	
215	08603960	NS	JELERU	1930	3	P/A	SBB	4.81				1530	415	8.1	0.27	2078	
216	08604640	NS	JELERU	1950	3	SSAL	SBB	6.21				1530	418	8.1	0.27	2078	

216 Bridges
<< SPECIAL Bridges >>

1	00178210	P. PINANG	SBG PRATU	1954	2	SSAL	CAR										
2	00223500	PAHANG	TERMELOH	1974	2	MTAL	SBG										
3	00371000	KELANTAN	KBHARU	Yahya Pnira			RCB										
4	00512940	JOHOR	BATU PAHAT	1965	2	SSAL	PCB										
5	01212140	PAHANG	PEKAN	1976	2	MTAL	PBX										

APPENDIX – F

**SELECTION
OF 100 BRIDGES FOR VISUAL INSPECTION**



APPENDIX-F SELECTION OF 100 BRIDGES FOR VISUAL INSPECTION

NO.	KEY	STATE	DISTRICT	YEAR BUILT	STUDY CATEGORY	CAPACITY	MAX. SPAN (M)	NO. OF SPAN	LENGTH (M)	TYPE OF BRIDGE	STRUCTURAL CONDITION			CONCEIVABLE REHABILITATION PLANS FROM STRUCTURAL VIEW POINT	CONCEIVABLE REHABILITATION PLANS FROM FUNCTIONAL VIEW POINT	FINAL SELECTION	REMARKS
											ABUT.	PIER	BEAM				
<p>YEAR BUILT < 1945</p> <p>1 00103690 JOHOR KLUANG 1937 3 MITAL 2.16 1 2.18 BOX 4 3 3 3.3 ARF</p> <p>Total no's of bridges = 1</p>																	
<p>YEAR BUILT < 1945</p> <p>1 00145600 PERAK BTG PADANG 1962 3 MITAL 2.40 1 2.40 BOX 2 2 2 2.0 NON SA</p> <p>2 00116500 JOHOR SEGAMAT 1947 3 STAL 2.44 2 4.88 BOX 3 2 2 2.3 ARF SA</p> <p>3 00355290 PERAK H. PERAK 1960 3 STAL 2.48 2 4.92 BOX 2 3 3 2.3 PRF CB</p> <p>4 00503570 SELANGOR ULANGAT 1950 3 STAL 1.80 2 3.20 BOX 3 3 3 2.3 ARF APFR SA</p> <p>5 00403570 SELANGOR PETALING 1960 3 STAL 3.05 1 3.05 BOX 3 2 2 2.5 ARF EA</p> <p>6 00102560 JOHOR J. BAHRU 1965 3 STAL 1.80 1 1.80 BOX 3 2 2 2.7 ARF SA</p> <p>7 00121280 JOHOR SEGAMAT 1955 3 STAL 2.42 1 2.42 BOX 4 2 2 3.0 ARF SA</p> <p>8 00121280 JOHOR SEGAMAT 1950 3 STAL 2.63 1 2.63 BOX 4 2 2 3.0 ARF SA</p> <p>9 00155560 PERAK KINTA 1970 3 STAL 1.81 2 3.62 BOX 2 3 4 3.0 ARF PRF SA</p> <p>10 00524990 MELAKA ALOR GAJAH 1966 3 MITAL 1.65 1 1.65 BOX 2 4 4 3.0 DCRF SA</p> <p>11 00228370 PAHANG IMPARAN 1965 3 STAL 3.03 1 3.03 BOX 4 4 3 3.5 ARF DCRF SA</p> <p>12 00539870 SELANGOR K. LANGAT 1950 4 SSAL 2.90 1 2.90 BOX 3 4 4 3.5 DCRF CA</p> <p>Total no's of bridges = 12</p>																	
<p>YEAR BUILT < 1974</p> <p>1 00146300 SELANGOR LILU S'GOR 1965 3 STAL 12.19 3 25.91 IT 1 2 1 1 3 1.3 PRF SRPF SA</p> <p>2 00149820 PERAK BTG PADANG 1969 3 STAL 12.08 3 38.24 IT 3 3 1 1 1 1.7 ARF SRPF SA</p> <p>3 00506970 JOHOR PONTIAN 1971 3 STAL 15.08 3 28.17 IT 2 2 2 2 2 1.7 PRF EURP SRPF CA</p> <p>4 00514300 JOHOR BATU PAHAT 1960 3 STAL 10.45 3 22.07 IT 2 3 1 2 3 2.0 PRF SRPF EURP CA</p> <p>5 00303390 PERAK MANJUNG 1972 3 STAL 14.07 3 41.96 IT 2 3 1 2 3 2.0 PRF SRPF EURP CA</p> <p>6 00307810 JOHOR PONTIAN 1968 3 STAL 12.06 5 47.83 IT 2 3 2 2 2 2.3 CBRF PRF EURP CA</p> <p>7 00306390 JOHOR K. TINGGI 1974 3 STAL 16.57 5 64.57 IT 3 2 2 2 2 2.5 ARF CBRF SRPF CA</p> <p>8 00308710 JOHOR K. TINGGI 1969 3 STAL 18.90 7 51.88 IT 1 3 2 4 3 2.5 EURP PRF CBSPR CA</p> <p>9 07001730 PERAK HLR PERAK 1970 3 STAL 14.60 3 44.38 IT 3 3 2 2 2 2.5 EURP SRPF CA</p> <p>Total no's of bridges = 9</p>																	
<p>YEAR BUILT < 1974</p> <p>1 00338590 TRENGGANU KEMAMAN 1965 3 STAL 28.03 16 219.13 PCB 1 3 3 1 1 1 1.5 SRPF SRF SA</p> <p>2 00507290 JOHOR PONTIAN 1966 3 STAL 11.77 3 35.21 PCB 3 3 1 1 4 2.0 APR PRF EURP BSFR CA</p> <p>3 00700660 KEDAH KOTA BETAR 1964 3 STAL 16.40 1 16.40 PCB 2 2 2 2 2 2.0 DCRF BRP ADDING SDE WALK</p> <p>4 00703390 PERLIS 1963 3 STAL 24.80 1 24.80 PCB 2 2 2 2 2 2.0 BRP ADDING SDE WALK</p> <p>5 00346740 TRENGGANU DUNJUN 1972 3 STAL 30.52 3 152.26 PCB 2 2 2 4 4 2.5 CBRF SRPF ADDING & RAISING</p> <p>6 00701810 KEDAH KG. PASU 1970 3 STAL 30.52 3 45.60 PCB 3 3 2 2 2 2.5 BRP PRF APR SRPF SA</p> <p>7 00505070 PAHANG LUPIS 1961 3 STAL 30.74 4 122.96 PCB 3 3 2 2 2 2.5 EURP BRP ADDING SDE WALK</p> <p>8 00701860 KEDAH K. MUDASIK 1968 3 STAL 30.64 3 91.52 PCB 2 3 2 3 2 2.5 DCRF PRF SRPF EURP CA</p> <p>9 00617000 PAHANG ROMPIN 1974 3 MITAL 45.78 3 387.92 PCB 2 3 4 3 4 3.0 CBRF EURP DCRF PRF CA</p> <p>10 00339210 TRENGGANU KEMAMAN 1963 3 STAL 15.22 10 152.20 PCB 4 4 4 2 2 3.5 ARF EURP SRPF CA</p> <p>11 00319110 PAHANG ROMPIN 1962 3 SSAL 30.46 7 121.06 PCB 3 4 4 4 4 3.8 CBRF EURP APR PRF CA</p> <p>Total no's of bridges = 11</p>																	
<p>YEAR BUILT < 1974</p> <p>1 00810600 PAHANG K. LUPIS 1990 3 MITAL 30.49 1 30.49 PCB 2 2 1 1 1 1 1.3 BRP SRPF SA</p> <p>2 00822340 KELANTAN GUA MUSANG 1982 3 MITAL 30.39 3 90.91 PCB 2 1 1 1 2 1.3 EURP CA</p> <p>Total no's of bridges = 2</p>																	

APPENDIX - F SELECTION OF 100 BRIDGES FOR VISUAL INSPECTION

NO.	KEY	STATE	DISTRICT	YEAR BUILT	STUDY CATEGORY	CAPACITY	MAX. SPAN (M)	NO. OF SPAN	BRIDGE LENGTH (M)	TYPE OF BRIDGE	STRUCTURAL CONDITION			CONCEIVABLE REHABILITATION PLANS FROM STRUCTURAL VIEW P.O.I.N.T.	CONCEIVABLE REHABILITATION PLANS FROM FUNCTIONAL VIEW P.O.I.N.T.	FINAL SELECTION	REMARKS
											PIER	BEAM	SCOUR				
<< TYPE OF BRIDGE PRB --- Precast R.C. beam >>																	
***** YEAR BUILT < 1945 *****																	
1	00519550	MELAKA	JASIN	1940	3	P/A	4.95	1	4.95	PRB	4	2	2	2,7 PRF	Total no's of bridges selected = 1	SELECTED	CA
***** 1946 < YEAR BUILT < 1974 *****																	
1	00200850	PAHANG	KUANTAN	1967	3	SSAL	6.40	1	6.40	PRB	4	1	1	2.0 APPR,APR,EJRP		SELECTED	CA
2	00354190	TRENGGANU	K.T.	1960	2	SSAL	5.50	2	11.18	PRB	2	3	2	2.0 PRF,SFRF		SELECTED	CB
3	00354800	TRENGGANU	K.T.	1963	3	SSAL	5.96	3	17.85	PRB	2	4	1	2.0 CBRF,SFRF,EJRP		SELECTED	CB
4	00357200	TRENGGANU	K.T.	1963	3	SSAL	5.94	3	17.82	PRB	2	3	1	2.0 CBRF,SFRF		SELECTED	CB
5	01105770	NS	JEMPUH	1970	3	SSAL	6.18	3	18.92	PRB	4	1	1	2.0 ASR,BSRF		SELECTED	CB
6	00358750	TRENGGANU	K.T.	1963	3	SSAL	5.90	3	17.70	PRB	4	2	2	2.0 ASR,EJRP		SELECTED	CB
7	00357270	TRENGGANU	K.T.	1967	3	SSAL	5.89	2	11.78	PRB	2	2	1	2.3 CBRF,CBRP	ADDING SIDE WALK	SELECTED	CA
8	00352880	PAHANG	KUANTAN	1965	3	SSAL	11.08	3	11.08	PRB	4	2	1	2.3 APPR,APR,EJRP	ADDING SIDE WALK	SELECTED	CA
9	00361490	TRENGGANU	BESUT	1960	3	SSAL	6.01	3	18.03	PRB	3	2	2	2.3 APPR,APR		SELECTED	CA
10	00520130	MELAKA	JASIN	1960	3	SSAL	5.46	1	5.46	PRB	3	2	2	2.3 APR	ADDING & WIDENING	SELECTED	CB
11	00557840	PERAK	KINTA	1965	3	SSAL	6.06	2	12.12	PRB	3	2	2	2.3 APR		SELECTED	CB
12	00319650	PAHANG	ROMPIN	1960	3	SSAL	5.67	2	11.34	PRB	2	2	2	2.5 CBRP,EJRP,BSRF		SELECTED	CB
13	00363650	TRENGGANU	BESUT	1965	3	SSAL	5.84	1	5.84	PRB	3	4	2	2.5 APR,APR		SELECTED	CB
14	00518700	MELAKA	JASIN	1961	3	SSAL	4.89	1	4.89	PRB	3	2	2	2.5 ARF		SELECTED	SA
15	00919470	PAHANG	K.LIPIS	1960	3	SSAL	11.87	1	11.87	PRB	3	2	4	2.5 APR,BSRF		SELECTED	SA
16	00326200	PAHANG	PEKAN	1965	3	SSAL	3.73	1	3.73	PRB	4	2	2	2.7 ARF,EJRP		SELECTED	CA
17	00326200	MELAKA	MELAKA TGH	1960	3	SSAL	7.71	2	14.52	PRB	2	3	3	2.8 PPR,EJRP,BSRF		SELECTED	CA
18	00314190	JOHOR	MERSING	1964	3	SSAL	5.60	2	11.00	PRB	4	2	5	3.0 APPR,APR,BSRF,EJRP		SELECTED	CA
19	00326200	PAHANG	PEKAN	1965	3	SSAL	5.86	4	28.52	PRB	4	2	2	3.0 APPR,APR,BSRF,EJRP		SELECTED	CA
20	00366860	KELANTAN	P.PUTEH	1963	3	SSAL	5.41	6	32.46	PRB	3	4	4	3.7 CBRF,APR,APR,BSRF,EJRP	ADDING & RAISING	SELECTED	CB
Total no's of bridges = 20																	
<< TYPE OF BRIDGE RCB --- R.C. beam & slab >>																	
***** YEAR BUILT < 1945 *****																	
1	00308400	NS	JELERU	1905	3	P/A	10.70	5	96.70	RCB	2	3	2	2.3 DCRF		SELECTED	SA
2	05701200	KEDAH	K.MUDASARIK	1940	3	P/A	6.05	1	6.05	RCB	2	3	3	2.3 DCRF		SELECTED	SA
3	05701290	KEDAH	K.MUDASARIK	1940	3	P/A	6.13	2	12.26	RCB	2	3	3	2.5 DCRF,CBRF		SELECTED	SA
4	00125280	NS	TAMPIN	1940	3	P/A	6.70	1	6.70	RCB	3	3	3	3.0 ARF,CBRP		SELECTED	CB
5	00545560	SELANGOR	K.SELANGOR	1939	3	P/A	6.30	1	6.30	RCB	3	4	4	3.7 CBRF,DCRF	RAISING GRADE	SELECTED	CB
Total no's of bridges = 5																	
***** 1946 < YEAR BUILT < 1974 *****																	
1	00201780	PAHANG	KUANTAN	1960	1	SSAL	7.75	1	7.75	RCB	1	1	1	1.0 NON		SELECTED	CA
2	00702850	KEDAH	KBG.PASU	1960	3	SSAL	9.54	1	9.54	RCB	2	1	1	1.3 BRF,ARF		SELECTED	CA
3	00303810	PAHANG	KUANTAN	1958	3	SSAL	12.00	3	36.00	RCB	2	3	1	1.8 BPR,APR,BSRF,BSRF	ADDING SIDE WALK	SELECTED	CA
4	00510560	JOHOR	BATU PAHAT	1960	3	SSAL	10.42	3	31.24	RCB	2	3	1	1.8 BPR,APR,BSRF,BSRF,EJRP		SELECTED	CA
5	00184400	KEDAH	KOTA SETAR	1960	3	SSAL	6.10	2	12.20	RCB	2	2	2	2.0 CAN'T INSPECT		SELECTED	CA
6	00512660	JOHOR	BATU PAHAT	1966	3	SSAL	11.30	3	33.90	RCB	4	3	1	2.3 APR,BSRF		SELECTED	CA
7	00515890	JOHOR	MUAR	1966	3	SSAL	6.03	3	17.92	RCB	2	3	2	2.3 PPR,EJRP		SELECTED	CA
8	00528560	SELANGOR	SEPANG	1960	3	SSAL	14.70	5	61.94	RCB	2	3	2	2.3 BPR,BSRF,EJRP		SELECTED	CA
9	00303220	PERAK	LAMPSELAMA	1960	3	SSAL	7.01	1	7.01	RCB	2	2	2	2.3 CBRP,BSRF		SELECTED	CA
10	00151360	PERAK	BIGPADIANG	1960	3	SSAL	9.08	7	63.96	RCB	2	2	4	2.3 DCRF		SELECTED	CA
11	00326200	NS	PD	1970	3	SSAL	11.02	5	53.24	RCB	3	2	2	2.5 APR,BSRF		SELECTED	CA
12	00394450	NS	PD	1965	3	SSAL	8.83	4	35.32	RCB	2	3	3	2.5 PPR	ADDING SIDE WALK	SELECTED	CA
13	00506740	PERAK	LAMPSELAMA	1960	3	SSAL	5.80	3	17.40	RCB	2	2	2	2.7 CBRF		SELECTED	CA
14	00514370	JOHOR	BATU PAHAT	1960	3	SSAL	6.31	1	6.31	RCB	2	4	2	2.7 CBRF		SELECTED	CA
15	00202640	NS	JELERU	1960	3	SSAL	3.08	1	3.08	RCB	2	5	1	2.8 DCRF,APR,BSRF,BSRF,CBRP	ADDING SIDE WALK	SELECTED	SA
16	00119780	JOHOR	SEGAMAT	1965	3	SSAL	8.83	3	26.49	RCB	2	3	4	2.8 CBRF,BSRF,CBRP		SELECTED	CB
17	00114920	JOHOR	SEGAMAT	1965	3	SSAL	8.46	2	12.96	RCB	2	4	3	2.8 CBRF,BSRF,CBRP		SELECTED	CB
18	00340790	SELANGOR	K.LANGAT	1960	3	SSAL	7.30	3	11.94	RCB	2	3	4	2.8 CBRF,BSRF,CBRP		SELECTED	CB
19	00536900	KELANTAN	MACHANG	1960	3	SSAL	6.01	2	12.02	RCB	2	3	3	3.0 CBRP,BSRF		SELECTED	SA
20	00108100	JOHOR	KLUANG	1964	3	SSAL	15.80	3	27.40	RCB	2	3	4	3.0 APPR,APR,BSRF,EJRP		SELECTED	CA
21	00323070	PAHANG	PEKAN	1965	3	SSAL	10.42	3	31.26	RCB	4	2	2	3.0 APPR,APR,BSRF,EJRP	ADDING SIDE WALK	SELECTED	CA
22	00441900	TRENGGANU	KEMAMAN	1965	3	SSAL	12.10	3	36.14	RCB	4	4	3	3.0 APPR,APR,BSRF,EJRP	ADDING SIDE WALK	SELECTED	CA
23	00521710	MELAKA	MELAKA TGH	1960	3	SSAL	10.72	1	10.72	RCB	4	4	3	3.0 CBRF,APR,BSRF	ADDING SIDE WALK	SELECTED	CA

APPENDIX-F SELECTION OF 100 BRIDGES FOR VISUAL INSPECTION

NO.	KEY	STATE	DISTRICT	YEAR BUILT	STUDY CATEGORY	CAPACITY	SPAN (M)	NO. OF SPAN	BRIDGE LENGTH (M)	TYPE OF BRIDGE	ABUT.	STRUCTURAL CONDITION			SCOU RING AVERAGE	CONCEIVABLE REHABILITATION PLANS FROM STRUCTURAL VIEW POINT	CONCEIVABLE REHABILITATION PLANS FROM FUNCTIONAL VIEW POINT	FINAL SELECTION	REMARKS
												PIER	DECK	BEAM					
24	00521940	MELAKA	TGH	1960	3	STAL	14.26	2	14.26	RCS	3	4	2	3.0	ARF, PFR, CBRF		SELECTED	CA, SA	
25	00501930	PERAK	MANJUNG	1960	3	STAL	5.02	3	5.02	RCS	3	4	2	3.0	CBRF, DCRP, SFRP		SELECTED	CA, SA	
26	00202450	SELANGOR	ULANGAT	1965	3	STAL	12.11	1	12.11	RCS	3	4	2	3.3	DCRPR, ARF, SFRP		SELECTED	CA, SA	
27	00514860	JOHOR	MUAR	1965	3	STAL	8.97	6	46.03	RCS	4	4	3	3.5	CBRF, ARF		SELECTED	CA, SA	
28	00524570	SELANGOR	SERANG	1960	3	STAL	6.96	9	32.54	RCS	4	4	3	3.5	DCRF, APR, PFR		SELECTED	CA, SA	
29	00521900	MELAKA	TGH	1960	3	STAL	6.00	1	6.00	RCS	3	4	4	3.7	ARF, CBRP, DCRP	ADDING SIDE WALK	SELECTED	CA, SA	
Total no's of bridges = 29																			

<< TYPE OF BRIDGE RCS --- R.C. slab >>

***** YEAR BUILT < 1945 *****																		
1	00238100	KELANTAN	MACHANG	1941	3	P/A	4.83	2	9.72	RCS	2	3	3	2.7	DCRF	WIDENING & RAISING	SELECTED	CS
2	00300800	JOHOR	K. TINGGI	1940	3	P/A	4.53	2	9.16	RCS	4	3	2	3.0	ARF	ADDING SIDE WALK	SELECTED	SA
Total no's of bridges = 2																		

***** YEAR BUILT < 1974 *****																			
1	00354950	KELANTAN	KUALA KPAI	1960	3	STAL	3.34	1	3.34	RCS	1			1.0	NON		SELECTED	CS	
2	00368850	KELANTAN	P. PUTEH	1961	3	STAL	4.79	2	9.58	RCS	2	2	2	2.0	DCRF, SFRP		SELECTED	CS	
3	00700750	KEDAH	KOTA SETAR	1970	3	STAL	15.96	1	15.96	RCS	2	1	2	2.0	BRP, ARF		SELECTED	SA	
4	00369300	KELANTAN	P. PUTEH	1965	3	STAL	4.84	2	9.68	RCS	3	3	1	2.3	ARF, PFR	RAISING GRADE	SELECTED	SA	
5	00112330	JOHOR	BATU PAHAT	1960	3	STAL	6.27	1	6.27	RCS	2	3	2	2.5	DCRF, ARF, APR, SFRP		SELECTED	SA	
6	00116400	KEDAH	KOTA SETAR	1960	3	STAL	5.20	1	5.20	RCS	3	2	2	2.3	SFRP, DCRP, APR		SELECTED	SA	
7	00194960	KEDAH	KOTA SETAR	1960	3	STAL	4.64	1	4.64	RCS	3	2	2	2.3	SFRP		SELECTED	SA	
8	00304090	JOHOR	K. TINGGI	1963	3	STAL	36.85	5	92.25	RCS	2	3	2	2.5	DCRPR, APR, SFRP, CBRP		SELECTED	SA	
9	00556900	PERAK	H. PERAK	1966	3	STAL	7.33	3	7.33	RCS	3	2	2	2.5	APR, PFR		SELECTED	SA	
10	00593300	JOHOR	PONTIAN	1968	3	STAL	11.83	4	47.52	RCS	2	4	2	3	2.7	SFRP, APR		SELECTED	SA
11	00594950	KELANTAN	KUALA KPAI	1960	3	STAL	4.63	3	13.71	RCS	2	4	4	2.7	DCRF, APR	RAISING GRADE	SELECTED	SA	
12	02305970	JOHOR	SEGAMAT	1950	4	SSAL	5.66	2	7.60	RCS	5	2	1	2.7	ARF	ADDING SIDE WALK	SELECTED	CA, SA	
13	00519360	MELAKA	JASIN	1965	3	STAL	6.22	7	42.70	RCS	3	4	2	3.0	DCRF, PFR		SELECTED	SA	
14	00601260	NS	K. PILAH	1960	3	STAL	5.74	1	5.74	RCS	2	4	4	3.0	DCRF		SELECTED	CS	
15	01800080	PERAK	MANJUNG	1960	3	STAL	3.68	1	3.68	RCS	2	4	3	3.0	DCRF	ADDING & WIDENING	SELECTED	CS	
16	00403940	SELANGOR	PETALING	1960	3	STAL	6.56	1	6.56	RCS	3	3	4	3.0	DCRF, APR, SFRP, SFRP		SELECTED	CS	
17	00316745	JOHOR	MERSING	1965	3	STAL	3.57	1	3.57	RCS	4	4	4	3.3	ARF, SFRP		SELECTED	SA	
18	00397240	PAHANG	KUANTAN	1967	3	STAL	6.53	1	6.53	RCS	5	2	2	3.5	PFR		SELECTED	SA	
19	00524420	MELAKA	MELAKA TGH	1960	3	STAL	9.60	1	9.60	RCS	4	4	3	3.5	PFR		SELECTED	CA	
20	00548980	SELANGOR	K. SELANGOR	1960	3	STAL	10.64	3	30.94	RCS	4	4	3	3.5	DCRF, APR, APR, SFRP		SELECTED	CA	
21	00313620	JOHOR	MERSING	1960	3	STAL	1.80	2	3.60	RCS	4	4	3	3.7	DCRF, APR, APR, SFRP	ADDING SIDE WALK	SELECTED	SA	
Total no's of bridges = 21																			

<< TYPE OF BRIDGE SBB --- Steel beam, buckle plate >>

***** YEAR BUILT < 1945 *****																			
1	00166220	PERAK	LRT MATANG	1945	2	SSAL	5.67	1	5.67	SBB	2	2	2	2.0	SBB	WIDENING	SELECTED	CS	
2	00501070	JOHOR	BATU PAHAT	1919	2	SSAL	4.77	1	4.77	SBB	2	2	2	2.0	DSBR		SELECTED	CS	
3	06406260	PAHANG	JERANTUT	1930	3	P/A	4.80	1	4.80	SBB	2	2	2	2.0	SBRP, SFRP, DSFR		SELECTED	CS	
4	00003660	NS	JELUBU	1930	3	P/A	9.82	1	9.82	SBB	2	2	2	2.0	SBRP, DSBR		SELECTED	CS	
5	05805290	PAHANG	LIPIS	1930	3	STAL	6.05	1	6.05	SBB	2	3	2	2.3	SBRP, DSBR, SFRP		SELECTED	CS	
6	05806010	PAHANG	LIPIS	1930	3	STAL	5.95	1	5.95	SBB	2	3	2	2.3	SBRP		SELECTED	CS	
7	06406690	PAHANG	JERANTUT	1940	3	P/A	6.81	1	6.81	SBB	2	3	2	2.3	SBRP, SFRP		SELECTED	CS	
8	00196210	KEDAH	KOTA SETAR	1940	3	SSAL	3.23	1	3.23	SBB	3	3	2	2.7	SBRP, APR		SELECTED	CS	
9	00907010	NS	JELUBU	1930	3	SSAL	6.96	1	6.96	SBB	2	3	3	2.7	SBRP, DSBR		SELECTED	CS	
10	05101360	NS	SEREMBAN	1940	3	SSAL	3.31	1	3.31	SBB	2	3	3	2.7	SBRP, DSBR		SELECTED	CS	
11	06403900	PAHANG	JERANTUT	1930	3	SSAL	12.31	1	12.31	SBB	2	3	3	2.7	SBRP, DSBR		SELECTED	CS	
12	06403900	PAHANG	JERANTUT	1930	3	SSAL	11.81	1	11.81	SBB	2	3	3	2.7	SBRP, DSBR, APR		SELECTED	CS	
13	06404940	PAHANG	JERANTUT	1930	3	SSAL	5.21	1	5.21	SBB	2	3	3	2.7	SBRP, DSBR, APR		SELECTED	CS	
14	05003590	JOHOR	BATU PAHAT	1940	2	SSAL	4.75	1	4.75	SBB	3	3	3	3.0	DSBR, SFRP		SELECTED	CS	
15	05302940	NS	SEREMBAN	1940	3	SSAL	6.70	1	6.70	SBB	2	3	3	3.0	SBRP, DSBR		SELECTED	CS	
16	06404270	PAHANG	JERANTUT	1930	3	STAL	10.91	1	10.91	SBB	2	4	3	3.0	SBRP, DSBR, SFRP, SFRP		SELECTED	CS	
17	05200280	NS	SEREMBAN	1932	3	STAL	4.86	1	4.86	SBB	3	5	2	3	3.3	CBRF, SFRP		SELECTED	CS
Total no's of bridges = 17																			

***** YEAR BUILT < 1974 *****																		
1	00228540	PAHANG	MARAN	1965	2	SSAL	6.26	1	6.26	SBB	2	2	2	2.0	SBRP, DSBR		SELECTED	CS
2	00901960	NS	K. PILAH	1960	2	SSAL	9.07	2	18.14	SBB	2	2	2	2.0	SBRP, DCRP		SELECTED	CS

APPENDIX - F SELECTION OF 100 BRIDGES FOR VISUAL INSPECTION

NO.	KEY	STATE	DISTRICT	YEAR BUILT	STUDY CATEGORY	CAPACITY	MAX SPAN (M)	NO OF SPAN	BRIDGE LENGTH (M)	TYPE OF BRIDGE	ABUT.	PIER	STRUCTURAL CONDITION			CONCEIVABLE REHABILITATION PLANS FROM STRUCTURAL VIEW POINT	CONCEIVABLE REHABILITATION PLANS FROM FUNCTIONAL VIEW POINT	FINAL SELECTION	REMARKS
													BEAM	DECK	SCOUR-RING				
3	00622650	NS	K. PILAH	1950	2	SSAL	3.11	1	3.11	SBB	2	2	2	2.0 SBPA					
4	00622630	NS	K. PILAH	1950	2	SSAL	3.10	1	3.10	SBB	2	2	2	2.0 SBPA					
5	05101450	NS	SEREMBAN	1950	2	SSAL	3.26	1	3.26	SBB	2	2	2	2.0 SBPA					
6	05122280	NS	K. PILAH	1950	2	SSAL	4.81	1	4.81	SBB	2	2	2	2.0 SBPA					
7	05103300	NS	K. PILAH	1950	2	SSAL	4.82	1	4.82	SBB	2	2	2	2.0 SBPA					
8	06601190	NS	SEREMBAN	1950	2	SSAL	4.64	2	16.08	SBB	2	2	2	2.0 SBPA					
9	06601830	NS	SEREMBAN	1950	2	SSAL	3.75	1	3.75	SBB	2	2	2	2.0 SBPA					
10	04502160	NS	SEREMBAN	1950	3	SSAL	3.70	1	3.70	SBB	2	2	2	2.0 SBPA					
11	03002270	NS	K. PILAH	1950	2	SSAL	3.11	1	3.11	SBB	2	2	2	2.3 SBPA					
12	03002440	NS	K. PILAH	1950	2	SSAL	3.10	1	3.10	SBB	2	2	2	2.3 SBPA					
13	03003300	NS	K. PILAH	1950	2	SSAL	3.77	1	3.77	SBB	2	2	2	2.3 SBPA					
14	03006190	NS	JEMPUL	1950	2	SSAL	3.94	1	3.94	SBB	2	2	2	2.3 SBPA					
15	05103030	NS	K. PILAH	1950	3	SSAL	3.79	1	3.79	SBB	2	2	2	2.3 SBPA					
16	05302050	NS	SEREMBAN	1950	3	SSAL	4.45	1	4.45	SBB	2	2	2	2.3 SBPA					
17	05601510	PERAK	HUR PERAK	1950	3	SSAL	5.00	1	5.00	SBB	2	2	2	2.3 SBPA					
18	00161140	PERAK	KINTA	1950	3	SSAL	9.77	2	19.11	SBB	2	2	2	2.5 SBPA					
19	00911990	PAHANG	BENTONG	1951	2	SSAL	10.77	4	32.96	SBB	2	2	2	2.5 SBPA					
20	07904190	PERAK	HULU PERAK	1950	3	SSAL	4.23	1	4.23	SBB	2	2	2	2.5 SBPA					
21	04503755	NS	JELERU	1950	2	SSAL	4.86	2	9.72	SBB	2	2	2	2.5 SBPA					
22	00706230	PERLIS	PERLIS	1950	2	SSAL	6.63	1	6.63	SBB	2	2	2	2.5 SBPA					
23	00901430	NS	K. PILAH	1950	2	SSAL	3.24	1	3.24	SBB	2	2	2	2.7 SBPA					
24	00901750	NS	K. PILAH	1950	2	SSAL	3.63	1	3.63	SBB	2	2	2	2.7 SBPA					
25	05001890	JOHOR	BATU PAHAT	1950	3	SSAL	5.05	1	5.05	SBB	2	2	2	2.7 SBPA					
26	05102060	NS	K. PILAH	1950	3	SSAL	4.74	1	4.74	SBB	2	2	2	2.7 SBPA					
27	05102670	NS	K. PILAH	1950	3	SSAL	3.21	1	3.21	SBB	2	2	2	2.7 SBPA					
28	05300540	NS	PD	1950	3	SSAL	9.85	1	9.85	SBB	2	2	2	2.7 SBPA					
29	05302160	NS	SEREMBAN	1950	3	SSAL	6.31	1	6.31	SBB	2	2	2	2.7 SBPA					
30	05601000	NS	SEREMBAN	1950	3	SSAL	9.82	1	9.82	SBB	2	2	2	2.7 SBPA					
31	03601410	NS	SEREMBAN	1950	3	SSAL	3.85	1	3.85	SBB	2	2	2	2.7 SBPA					
32	03602600	NS	JELERU	1950	3	SSAL	3.00	1	3.00	SBB	2	2	2	2.7 SBPA					
33	03602640	NS	JELERU	1950	3	SSAL	2.51	1	2.51	SBB	2	2	2	2.7 SBPA					
34	00161100	PERAK	KINTA	1943	3	SSAL	11.50	3	31.50	SBB	2	2	2	2.7 SBPA					
35	00161120	PERAK	KINTA	1955	3	SSAL	3.08	2	16.18	SBB	2	2	2	2.7 SBPA					
36	00505950	PERAK	KINTA	1950	2	SSAL	2.83	1	2.83	SBB	2	2	2	2.7 SBPA					
37	00528600	NS	PD	1950	3	SSAL	3.05	1	3.05	SBB	2	2	2	2.7 SBPA					
38	00504010	SELANGOR	K. LANGKAT	1950	2	SSAL	6.29	1	6.29	SBB	2	2	2	3.0 SBPA					
39	00500550	SELANGOR	BENTONG	1950	3	SSAL	3.47	1	3.47	SBB	2	2	2	3.0 SBPA					
40	00603900	PAHANG	RAUB	1952	2	SSAL	5.47	2	10.94	SBB	3	3	3	3.0 SBPA					
41	05100840	NS	SEREMBAN	1950	3	SSAL	9.41	1	9.41	SBB	2	2	2	3.0 SBPA					
42	05102930	NS	K. PILAH	1950	3	SSAL	3.21	1	3.21	SBB	2	2	2	3.0 SBPA					
43	05300960	NS	PD	1950	3	SSAL	4.27	1	4.27	SBB	2	2	2	3.0 SBPA					
44	05301190	NS	PD	1950	3	SSAL	4.84	1	4.84	SBB	2	2	2	3.0 SBPA					
45	05301620	PERAK	HUR PERAK	1950	2	SSAL	3.67	1	3.67	SBB	2	2	2	3.0 SBPA					
46	05303940	PERAK	BITUNG	1950	3	SSAL	4.97	1	4.97	SBB	2	2	2	3.0 SBPA					
47	07900230	PERAK	HUR PERAK	1950	3	SSAL	5.88	1	5.88	SBB	2	2	2	3.0 SBPA					
48	07902330	PERAK	K. KANGSAR	1950	2	SSAL	6.95	1	6.95	SBB	2	2	2	3.0 SBPA					
49	07604020	PERAK	HULU PERAK	1950	3	SSAL	6.35	1	6.35	SBB	2	2	2	3.0 SBPA					
50	07604750	PERAK	HULU PERAK	1950	3	SSAL	9.34	1	9.34	SBB	2	2	2	3.0 SBPA					
51	02603940	JOHOR	SEGAMAT	1950	3	SSAL	6.29	2	12.28	SBB	2	2	2	3.3 SBPA					
52	06000950	PERAK	KAMSELAMA	1950	3	SSAL	5.08	1	5.08	SBB	2	2	2	3.3 SBPA					
53	07002940	PERAK	BITUNG	1950	3	SSAL	3.88	1	3.88	SBB	2	2	2	3.3 SBPA					
54	07602940	PERAK	K. KANGSAR	1950	3	SSAL	5.34	1	5.34	SBB	2	2	2	3.3 SBPA					
55	07602940	PERAK	K. KANGSAR	1950	3	SSAL	3.07	1	3.07	SBB	2	2	2	3.3 SBPA					
56	00541000	SELANGOR	K. LANGKAT	1950	3	SSAL	3.24	1	3.24	SBB	2	2	2	3.5 SBPA					
57	00541210	SELANGOR	K. LANGKAT	1950	2	SSAL	4.73	1	4.73	SBB	2	2	2	3.5 SBPA					
58	00810120	PAHANG	K. LIPIS	1950	4	SSAL	6.90	1	6.90	SBB	2	2	2	3.7 SBPA					
59	00802050	PAHANG	RAUB	1950	4	SSAL	9.04	2	18.03	SBB	4	4	4	4.0 SBPA					

Total no's of bridges selected = 24

<< TYPE OF BRIDGE SBC --- Steel beam, R.C. slab >>

YEAR BUILT < 1945	REMARKS	NO.	KEY	STATE	DISTRICT	YEAR BUILT	STUDY CATEGORY	CAPACITY	MAX SPAN (M)	NO OF SPAN	BRIDGE LENGTH (M)	TYPE OF BRIDGE	ABUT.	PIER	BEAM	DECK	SCOUR-RING	CONCEIVABLE REHABILITATION PLANS FROM STRUCTURAL VIEW POINT	CONCEIVABLE REHABILITATION PLANS FROM FUNCTIONAL VIEW POINT	FINAL SELECTION	REMARKS
1900	REMBAU	2	SSAL	9.53	1	9.53	SBC	2	4	2								2.7 SBPA		SELECTED	AA
1940	K. TINGGI	3	SSAL	4.90	1	4.90	SBC	3	2	4								3.0 SBPA		SELECTED	AA
1928	K. TINGGI	3	SSAL	3.95	1	3.95	SBC	3	4	4								3.7 SBPA		SELECTED	AA

Total no's of bridges selected = 59

APPENDIX -- F SELECTION OF 100 BRIDGES FOR VISUAL INSPECTION

NO.	KEY	STATE	DISTRICT	YEAR BUILT	STUDY CATEGORY	CAPACITY	SPAN (M)	NO. OF SPAN	BRIDGE LENGTH (M)	TYPE OF BRIDGE	STRUCTURAL CONDITION			AVERAGE	CONCEIVABLE REHABILITATION PLANS FROM STRUCTURAL VIEW POINT	CONCEIVABLE REHABILITATION PLANS FROM FUNCTIONAL VIEW POINT	FINAL SELECTION	REMARKS	
											ABUT.	PIER	BEAM						DECK
Total no's of bridges = 3																			
***** YEAR BUILT < 1974 *****																			
1	05204970	SELANGOR	U LANGAT	1964	3	STAL	18.24	3	54.50	SBC	2	2	2	2	2.0	SBPR,DCRF,APRF,SFRF,EJRP	SELECTED	CA	
2	00237200	PAHANG	KUANTAN	1960	3	STAL	9.00	3	26.70	SBC	2	4	2	1	4	2.3	PRF,APR,EJRP,SBPR	SELECTED	SA
3	06005070	PERAK	L.MASELAMA	1960	3	STAL	7.20	4	27.14	SBC	2	2	3	2	2.9	DCRF,SBPR,SFRS,PRF	SELECTED	SA	
4	05001000	PERAK	BTG PADANG	1960	3	STAL	4.40	1	4.40	SBC	3	2	3	3	2.7	SBPR,DCRF,APRF,SFRS	SELECTED	SA	
5	05001580	PERAK	BTG PADANG	1960	3	STAL	7.63	1	7.63	SBC	2	3	3	3	2.7	SBPR	SELECTED	SA	
6	05002280	PERAK	BTG PADANG	1960	3	STAL	8.21	1	8.21	SBC	2	4	2	2	2.7	SBPR,DCRF	SELECTED	SA	
7	05002980	PERAK	BTG PADANG	1960	3	STAL	6.80	1	6.80	SBC	3	3	3	2	2.8	SBPR,EJRP	SELECTED	SA	
8	05001480	PERAK	BTG PADANG	1960	3	STAL	1.95	2	3.90	SBC	3	2	3	3	2.8	SBPR,DCRF,APRF,PRF	SELECTED	CA,CS	
9	01000670	PERAK	MANJUNG	1960	3	STAL	4.78	1	4.78	SBC	2	4	4	4	3.0	DCRF,SBPR,APR	SELECTED	CA,CS	
10	05001070	PERAK	BTG PADANG	1960	3	STAL	4.50	1	4.50	SBC	2	3	4	4	3.0	SBPR,DCRF	SELECTED	CA,CS	
11	05001600	PERAK	BTG PADANG	1960	3	STAL	9.00	1	9.00	SBC	2	3	4	4	3.0	SBPR,DCRF	SELECTED	CA,CS	
12	05002030	PERAK	BTG PADANG	1960	3	STAL	3.96	1	3.96	SBC	2	4	3	4	3.0	SBPR,DCRF	SELECTED	CA,CS	
13	00506500	SELANGOR	K SELANGOR	1965	3	STAL	12.61	6	63.56	SBC	3	4	3	3	3.3	SBPR,BPR,PRF,SFRF	SELECTED	CA	
14	05002920	PERAK	BTG PADANG	1960	3	STAL	6.77	1	6.77	SBC	3	4	4	3	3.3	DCRF,SBPR,EJRP	SELECTED	CA	
15	05003120	PERAK	BTG PADANG	1960	3	STAL	10.86	3	23.18	SBC	3	3	4	4	3.5	DCRF,SBPR	SELECTED	CA	
Total no's of bridges = 15																			
<<< TYPE OF BRIDGE SBE --- Ecessed Steel beam, R.C. slab >>>																			
***** YEAR BUILT < 1945 *****																			
1	00145100	SELANGOR	ULU S'GOR	1935	3	MTAL	1.85	1	1.85	SBE	3	3	3	3	3.0	DCRF	SELECTED	SA	
2	00903220	JOHOR	K TINSJI	1940	3	P/A	4.84	1	4.84	SBE	3	4	4	4	3.7	CBRF,DCRF,EJRP	SELECTED	SA	
3	00522760	MELAKA	MPM	1930	3	P/A	7.47	1	7.47	SBE	3	4	4	4	3.7	CBRF,DCRF	SELECTED	CA	
4	06000970	PERAK	MANJUNG	1930	3	P/A	3.14	1	3.14	SBE	4	3	3	3	3.7	SBPR,CBRF,DCRF,APR,SFRF	SELECTED	EA	
Total no's of bridges = 4																			
***** YEAR BUILT < 1974 *****																			
1	00231350	JOHOR	MERSING	1960	3	STAL	4.40	1	4.40	SBE	3	3	3	3	3.0	APR,EJRP,SFRF,CBPR	SELECTED	SA	
2	00520950	MELAKA	JASIN	1960	3	STAL	4.27	1	4.27	SBE	3	3	3	3	3.0	CBRF,DCRF,APR	SELECTED	SA	
3	00702080	KEDAH	BALING	1960	3	STAL	7.16	1	7.16	SBE	3	3	3	3	3.0	APR	SELECTED	SA	
4	00523300	MELAKA	MELAKA TGH	1960	3	STAL	9.35	1	9.35	SBE	3	4	3	3	3.3	DCRF,CBRF	SELECTED	CA	
Total no's of bridges = 4																			
<<< TYPE OF BRIDGE SBG --- Steel box girder >>>																			
***** YEAR BUILT < 1945 *****																			
1	00186510	PERAK	LRT MATANG	1935	3	STAL	10.72	1	10.72	SBG	3	3	2	2	2.7	SBPR,DCRF,APR	SELECTED	1	
Total no's of bridges = 1																			
Grand Total 216 Bridges																			
<<< SPECIAL Bridges >>>																			
1	00178210	P. PINANG	SBG PRAIU	1964	2	STAL	57.32	12	271.61	CAR									
2	00225600	PAHANG	TERMELOH	1974	2	MTAL	151.50	19	515.21	SBG									
3	00371000	KELANTAN	Yahya Petra	1965	2	RCB													
4	00512840	JOHOR	BATU PAHAT	1965	2	PCB	52.02	5	186.18	PCB									
5	01212140	PAHANG	PEKAN	1976	2	MTAL	58.20	7	402.30	PIX									
Total 5 Bridges selected by GOM																			

APPENDIX – G

**VISUAL INSPECTION
RESULTS FOR FIVE SPECIAL BRIDGES**




TABLE OF CONTENTS

A.	SULTAN YAHYA PETRA BRIDGE	G- 1
B.	MERDEKA BRIDGE	G- 4
C.	BATU PAHAT BRIDGE	G- 7
D.	TEMERLOH BRIDGE	G-10
E.	KUALA LEPAR BRIDGE	G-12

APPENDIX-G VISUAL INSPECTION RESULTS FOR 5 SPECIAL BRIDGES

A. SULTAN YAHYA PETRA BRIDGE

1. Bridge Data

Key	:	00371000
Name of River	:	Sg. Kelantan
State	:	Kelantan
District	:	Kota Bharu
Year Built	:	1962
No. of Span	:	29 spans
Bridge Length	:	840m
Type of Superstructure	:	RC beam and slab built monolithically to the piers
Type of Substructure	:	Pile bankseat (abutment) and rectangular RC columns (piers)

2. General

The bridge links the town of Kota Bharu and Pasir Mas. It was built by the State Government without any consultation with JKR Engineers, as a result JKR has no drawings records with regard to its construction. The bridge was designed by Raymond Wong and Associate and constructed by Kien Huat Construction Company. After construction of the bridge was completed, JKR was directed to maintain it. It has been reported that defects on the bridge starts showing up as early as 1967.

3. Observed Defects

Visual inspection was made by the Study Team in October 1990 and it was observed that all soffit of slab has been repaired by gunite, thus all defects have been covered up. However, the gunite surfaces have cracked at a few location (See Photo A-1), which indicates that repair carried out is not effective. It was reported by JKR Engineers in Kota Bharu that the soffit of deck slab was repaired in 1988 because almost all soffits of deck slab have cracked


with concrete spalling at quite an extensive area.

All RC beams have been in distress with vertical crack appearing at regular intervals. The cracks start from soffit of deck slab and propagate vertically down at side of beam to about 200mm from its soffit (See Photo A-2). Some of the RC beams have also cracked horizontally at its side which occurred at about 200mm from soffit of slab.

It has also been reported that most of the expansion joint have failed as early as 1967. The expansion joint has been reported to have cracked and the gap at the half joint has widened with its steel cover plate missing. Expansion joint was subsequently repaired in 1980. During site inspection made by the Study Team, it was observed that the expansion joint could have failed again as crack was observed on premix surfaces (See Photo A-3), especially at the abutment where excessive noise was detected whenever heavy vehicles passed through it.

4. Recommended Rehabilitation and Maintenance Work

It is recommended that further detailed investigation and analysis should be conducted for this bridge which will be carried out in Phase II(A) of the Study.



A-1

Photo A-1 :Crack at gunited surfaces of the soffit of deck slab (The crack does not show up very well in this photo)

A-2

Photo A-2 :Vertical and horizontal crack at side of all RC beams (shown here by the white marking)

A-3

Photo A-3 :Crack and wide gap formed on premix surfaces due to failure of expansion joint



B. MERDEKA BRIDGE

1. Bridge Data

Key	:	00178210
Name of River	:	Sg. Muda
State	:	Pulau Pinang
District	:	Seberang Prai
Year Built	:	1954
No. of Span	:	13
Bridge Length	:	271.61 m
Type of Superstructure	:	RC beam and concrete slab at approach spans and 3 centre spans are of RC bow string arch type of construction
Type of Substructure	:	RC wall piers and abutment at approach spans and Masonry wall pier at 3 centre spans

2. General

The bridge is located at the border between the State of Penang and Kedah. The approach span on Penang side consisted of 6 span RC beam and slab bridge while there are only 4 span on Kedah side of the approach. The main span consisted of 3 spans RC bow string arch superstructure with maximum centre span length of 57.32m. Piers and abutments at both approaches are founded on 20m long piles while piers supporting the RC arch is founded on 16m long caisson.

Very limited information is available with regards to its design or construction except for the drawing which was collected by NALS.

3. Observed Defects

All RC bow arch girder has cracked at its side along the arch line (See Photo B-1), but no rust staining free lime has been observed, thus indicating that the crack could not possibly caused by corrosive expansion of steel. In the opinion of the Study Team the cause of the problem could be


due to the fact that the concrete arch is subjected to compressive force, in which the concrete is known to be strong, but at the time the concrete in the arch is also subjected to tensile busting force acting perpendicular to the compressive forces. If inadequate stirrup is provided the concrete will not be able to hold this force especially during the early age of the concrete and thus resulting in cracking of the member.

All rectangular RC hangers has cracked due to the concrete member being subjected to tensile forces (See Photo B-2). Premix surfaces on the carriageway has cracked transversely at regular interval on mid point between the hangers (See Photo B-e). The crack on premix surfaces could have been caused by the crack which appears at the construction joint in the slab. The construction joint in the slab was constructed at midspan between the transverse girders which is supported by the hangers.

4. Recommended Rehabilitation and Maintenance Work

Transverse crack on deck slab could easily be repaired by injecting polymer modified cementitious mortar and painting of the defective members with water proof coating.

Cracks at RC arch rib and hangers are very small with no free lime and rust staining on its surfaces, thus the crack could have occurred at the early age after completion of the bridge. The immediate step is to monitor the crack width whether the crack is active or not. If the crack is inactive then repair is by painting the concrete surface to protect rusting of reinforcement bar is required. If the crack width widen at a faster rate, then repair by injection of polymer modified cementitious mortar will be required. In the opinion of the Study Team, the observed defect on the bridge is not critical, thus no further detailed study with regard to maintenance and rehabilitation work is required for this bridge.




B-1 Photo B-1 :Crack at the side of the RC bow string arch girder



B-2 Photo B-2 :Horizontal tension crack on rectangular RC hangers

B-3 Photo B-3 :Transverse crack on premix road surface at regular interval midway between RC hangers



C **BATU PAHAT BRIDGE**

1. **Bridge Data**

Key	:	00512940
Name of River	:	Sg. Batu Pahat
State	:	Johor
District	:	Batu Pahat
Year Built	:	1965
No. of Span	:	5
Bridge Length	:	196.18m
Type of Superstructure	:	Precast prestressed I-Beam
Type of Substructure	:	Steel tubular column (pile) and concrete cross head

2. **General**

The bridge is located not very far from the estuary of Batu Pahat river and thus it is within the tidal range. It replaces the ferry service which link the town of Batu Pahat and Muar. The end span consisted of 31.30m simply supported beams while the penultimate spans consisted of 31.3m simply supported beam supported on pier on one end and on half joint of a 10.3m cantilever span on the other,. The centre span is 52m long consisted of 31.4m simply supported span and 10.3m cantilever spans at each pier. Both piers at end span and abutments are founded on rectangular RC piles while pier at the centre span is supported on 1.2m diameter tubular steel piles.

3. **Observed Defects**

Expansion joint is not provided at both abutments and piers. The premix material has dropped from the road surface through the gap formed (See Photo C-1) and collected at the bearing shelf. Plant (jejawi tree) is growing at the side and soffit of deck especially at half joint.



Excessive settlement of the approach embankment has cause pothole with depth greater than 30cm to be formed (See Photo C-2). Road surface at the approach is very bumpy with excessive rutting of the pavement.

All tubular steel pile at the pier on the centre span has corroded at the splash zone (See Photo C-3). Some of the piles has laminated with rusted steel thickness varies from 5mm to 10mm.

4. Recommended Rehabilitation & Maintenance Work

Bumpy road surface together with non-existence or failure of expansion joint will lead to an excessive impact load on the bridge, thus urgent repair is required. New expansion joint should be installed, debris and plant growing at bearing shelf should be removed. Approach embankment should be repaired, settlement could be reduced by installation of embankment piles at both approaches. Rip rap protection should be provided at the front of abutment to prevent embankment material from being washed out.

Concrete jacket should be constructed to prevent tubular steel cylindrical pile from corroding further. Before concrete jacket is installed all rust should be removed and the steel pile should be blast cleaned.



C-1

Photo C-1 :Expansion joint missing at abutment

C-2

Photo C-2 :Pot hole formed at approach embankment

C-3

Photo C-3 :Corrosion of the tubular steel pile



D. TEMERLOH BRIDGE

1. Bridge Data

Key	:	00223500
Name of River	:	Sg. Pahang
State	:	Pahang
District	:	Temerloh
Year Built	:	1974
No. of Span	:	17 span
Bridge Length	:	515.21m
Type of Superstructure	:	Steel box girder on the main span and Inverted T on the approach spans.
Type of Substructure	:	RC wall abutment and V-shaped Rectangular span and RC wall pier at main span.

2. General

The bridge was built at much higher elevation than the old bridge which was severely damaged by flood. It is located on Route 2 which formed a major road link between Kuala Lumpur and Kuantan town. The Kuala Lumpur approach is made of 8 spans inverted T-beam bridge while the Kuantan approach is made up of 7 spans Inverted T-Beam bridge. The centre main span is made of 2 spans continuous steel box girder bridge. All abutments and piers are supported on pile foundation. This bridge is relatively new thus quite a number of drawings is available and collected by the NALS.

3. Observed Defects


Free lime was detected at soffit of inverted T-Beam on a few of the approach spans (See photo D-1). The defect could be caused by porosity of the bridge deck.

Expansion joint on the bridge deck directly above the pier supporting the box girder at Kuala Lumpur side has been in distress. Its epoxy nosing has failed and anchor has loosened (See photo D-2).

4. Recommended Rehabilitation Maintenance Work


Porosity of bridge deck on approach span could be repaired by providing water proof membrane on the RC deck. However, since the porosity is only at a localised areas and to minimise cost of repair, the defect should be repaired by injecting the defected areas of RC slab with polymer modified cementitious grout.

All loose anchor bolts at the defective expansion joint should be tightened and its epoxy nosing repaired by polymer modified cementitious mortar.



D-1

Photo D-1: Free lime at soffit of Inverted T-beam bridge on the approach span



D-2

Photo D-2: Damaged nosing at the expansion joint

E. KUALA LEPAR BRIDGE

1. Bridge Data

Key	:	01212140
Name of River	:	Sg. Pahang
State	:	Pahang
District	:	Pekan
Year Built	:	1976
No. of Span	:	7 spans
Bridge Length	:	402.3m
Type of Superstructure	:	Precast Prestressed segmental continuous box girder
Type of Substructure	:	RC hollow wall/box abutment and pier

2. General

The bridge is located on the road linking the town of Kuantan on the East Coast to Segamat town on the South Western side of Peninsula Malaysia and it crosses the longest river in Peninsula Malaysia. The bridge is founded on pile foundation.

3. Observed Defects

The bridge is relatively new, thus no structural defect was observed except for potholes formed on approach road surface adjacent to expansion joint at both abutments (See Photo E-1).

4. Recommended Rehabilitation and Maintenance Work

Since NALS report has highlighted this same problem (i.e. potholes) at this bridge, the Study Team concludes that the defect is caused by failure of the road pavement. Therefore, road pavement adjacent to the bridge has to be properly design and reconstructed.




E-1









Photo E-1 : Pot holes formed on approach road surface adjacent to expansion joint at the abutment

APPENDIX – H

**POSSIBLE REHABILITATION PLANS FROM
STRUCTURAL AND FUNCTIONAL VIEW POINTS**










**APPENDIX--H POSSIBLE REHABILITATION PLANS
FROM STRUCTURAL VIEW POINT**

Main Bridge Component	Conceivable Rehabilitation Plan	Input Code	Possible Rehabilitation Method	Sketch	Input Code
Steel Beam	Protection/Restoration	SBPR	- Repainting - Reshaping		SBPR
	Reinforcement	SBRF	- Welding additional steel plate		SBRF
			- Adding additional beam		
Replacement	SBRP	- Partial Replacement - Total Replacement		SBRP	
Steel Buckle Plate	Protection/Restoration	DSPR	- Repainting - Minor repair (Providing Weephole)		DSPR
	Reinforcement	DSRF	- Adding stringer		DSRF
			- Lining by concrete		
	Replacement	DSRP	- Total replacement - by R.C Slab - by I.B Slab - by Composite Slab - by Steel Deck Slab		DSRP
Concrete Beam	Protection/Restoration	CBPR	- Injection		CBPR
			- Patching		
			- Coating		










**APPENDIX-H POSSIBLE REHABILITATION PLANS
FROM STRUCTURAL VIEW POINT**

Main Bridge Component	Conceivable Rehabilitation Plan	Input Code	Possible Rehabilitation Method	Sketch	Input Code
	Protection / Restoration	CBPR	- Shooting		CBPR
	Reinforcement	CBRF	- Bonding steel plate, or FRP		CBRF
			- Lining		
			- Jacketing		
			- Prestressing		
	Replacement	CBRP	- Partial replacement - Total replacement		CBRP
Concrete Deck Slab	Protection/ Restoration	DCPR	- Injection		DCPR
			- Patching		
			- Coating		
			- Shooting		





**APPENDIX-H POSSIBLE REHABILITATION PLANS
FROM STRUCTURAL VIEW POINT**

Main Bridge Component	Conceivable Rehabilitation Plan	Input Code	Possible Rehabilitation Plan	Sketch	Input Code	
	Reinforcement	DCRF	- Bonding steel plate or FRP		DCRF	
			- Shooting w/rebar			
			- Adding stringer			
	Replacement	DCRP	- Partial replacement - Total replacement		DCRP	
	Bearing	Protection/ Restoration	BPR	- Repainting - Resetting		BPR
		Replacement	BRP	Total Replacement by Rubber bearing by Steel bearing		BRP
Concrete Abutment (body)	Protection	APR	- Injection		APR	
			- Patching			
			- Coating			

**APPENDIX-H POSSIBLE REHABILITATION PLANS
FROM STRUCTURAL VIEW POINT**








Main Bridge Component	Conceivable Rehabilitation Plan	Input Code	Possible Rehabilitation Method	Sketch	Input Code
(body)	Protection	PPR	- Injection		PPR
			- Patching		
			- Coating		
			- Shooting		
(body)	Reinforcement	PRF	- Surface Lining		PRF
			- Total Lining		
			- Prestressing		
(Foundation)	Protection	PFPR	- Scouring Protection		PFPR
			- River bed Protection		

**APPENDIX-H POSSIBLE REHABILITATION PLANS
FROM STRUCTURAL VIEW POINT**

Main Bridge Component	Conceivable Rehabilitation Plan	Input Code	Possible Rehabilitation Method	Sketch	Input Code
	Reinforcement	PFRF	- Under pinning		PFRF
Steel Pier (body)	Protection	SPPR	- Partial Lining		SPPR
	Reinforcement	SPRF	- Repainting - Surface Lining		SPRF
			- Total Lining		


APPENDIX-H

Possible Rehabilitation Plans From Functional View Point

Conceivable Rehabilitation Plan	Input Code	Possible Rehabilitation Plan	Sketch	Input Code
Widening	WIDENING	Widening of super & substructure		WIDENING
		Widening of superstructure w/cantilever support of substructure		
Adding sidewalk	ADDING	Connection of sidewalk with the existing superstructure by cantilever		ADDING
		Adding sidewalk with cantilever support attached to substructure		
		Individual structure.		
Raising of grade	RAISING	Raising superstructure		RAISING
		Extension of bridge		

APPENDIX – I

**SELECTION
OF 20 BRIDGES FOR DETAILED SURVEY**



APPENDIX-I SELECTION OF 20 BRIDGES FOR DETAILED SURVEY

NO.	KEY	STATE	DISTRICT	YEAR BUILT	STUDY CATEGORY	CAPACITY	MAX. SPAN (M)	NO. OF SPAN	BRIDGE LENGTH (M)	TYPE OF BRIDGE	RATING OF PARTS			POSSIBLE REHABILITATION PLANS FROM STRUCTURAL VIEW POINT		POSSIBLE REHABILITATION PLANS FROM FUNCTIONAL VIEW POINT		FINAL SELECTION	REMARKS	
											ABUT.	PIER	BEARING	BEAM	DECK	FROM STRUCTURAL VIEW POINT	FROM FUNCTIONAL VIEW POINT			
<< Before 1945 >>																				
--- R.C. BRIDGE ---																				
** BOX...R.C.Box Culvert																				
1	00103990	JOHOR	KLUANG	1937	3	MTAL	2.13	1	2.16	BOX	3	--	--	--	1	ARF	--	--	SA(6.28)	CA
** PRB...Precast R.C.Beam																				
2	00519550	MELAKA	JASIN	1940	3	P/A	4.95	1	4.95	PRB	4	--	--	--	1	ARF	--	--	CA	CA
** RCB...R.C.Beam																				
3	00546500	SELANGOR	K.SELANGOR	1939	3	P/A	6.30	1	6.30	RCB	1	--	--	4	3	CBRF,DCPR	RAISING GRADE	Selected	CB	CB
4	09701230	KEDAH	K.MUDA/SIK	1940	3	P/A	8.13	2	12.26	RCB	1	1	--	4	4	CBRF,DCPR	--	--	SA	SA
** RCS...R.C.Slab																				
5	00303890	JOHOR	K.TINGGI	1940	3	P/A	4.59	2	9.18	RCS	4	1	--	--	--	1	ARF	ADDING SIDE WALK	SA(6.74)	CB
6	00838100	KELANTAN	MACHANG	1941	3	P/A	4.56	2	9.12	RCS	1	3	--	--	4	DCRF,PPH	WIDENING & RAISING (REPLACEMENT)	--	CB	CB
No's of total bridges = 6																				
--- STEEL BRIDGE ---																				
** SBB...Steel Beam Buckle Plate																				
7	05001070	JOHOR	BATU PAHAT	1919	2	SSAL	4.77	1	4.77	SBB	3	--	--	4	1	SSPR,APR	--	--	Selected	Selected
8	06404940	PAHANG	JERANTUT	1930	3	STAL	6.21	1	6.21	SBB	2	--	--	3	3	SSPR,DCSPPR	--	--	--	--
9	06403900	PAHANG	JERANTUT	1930	3	SSAL	11.91	1	11.91	SBB	4	--	--	4	1	SSRF,APR	--	--	--	--
10	06404270	PAHANG	JERANTUT	1930	3	STAL	10.91	1	10.91	SBB	4	--	--	4	3	SSRF,DCSPPR,APR	--	--	--	--
11	05202630	NS	SEREMBAN	1932	3	STAL	4.65	1	4.65	SBB	1	--	--	3	1	CBPR	--	--	--	--
12	05302340	NS	SEREMBAN	1940	3	SSAL	6.70	1	6.70	SBB	3	--	--	4	1	SSPR,APR	--	--	--	--
13	00025500	JOHOR	BATU PAHAT	1940	2	SSAL	4.75	1	4.75	SBB	3	--	--	4	3	SSPR,DCSPPR,APR	--	--	--	--
14	00186210	KEDAH	KOTA SETAR	1940	3	SSAL	3.23	1	3.23	SBB	1	--	--	4	3	SSRF,DCSPPR	--	--	--	--
** SBC...Steel Beam R.C.Slab																				
15	00304390	JOHOR	K.TINGGI	1928	3	STAL	3.95	1	3.95	SBC	3	--	--	4	1	SSRF,APR,SPR	RAISING GRADE	--	--	--
** SBE...Encased Steel Beam																				
16	06002970	PERAK	MANJUNG	1930	3	P/A	3.14	1	3.14	SBE	4	--	--	4	--	CBRF,ARF	--	--	EA	EA
17	00303220	JOHOR	K.TINGGI	1940	3	P/A	4.84	1	4.84	SBE	3	--	--	4	1	CBRF,APR	--	--	SA(7.27)	SA(7.27)
** SBB...Steel Box Girder																				
18	00186510	PERAK	LRT.MATANG	1905	3	STAL	10.72	1	10.72	SBB	3	--	--	4	4	SSRF,DCRF,CBRF,APR	--	--	Selected	Selected
No's of total bridges = 12																				
<< 1946 TO 1974 >>																				
--- P.C. BRIDGE ---																				
** IT...Inverted Tee Beam																				
19	00507810	JOHOR	PONTIAN	1969	3	STAL	12.06	5	47.83	IT	1	4	--	3	--	PRF,CBPR	--	--	--	CA
20	00306710	JOHOR	K.TINGGI	1969	3	STAL	18.90	7	51.96	IT	1	1	1	3	1	CBPR	--	--	--	CA
21	00503890	PERAK	MANJUNG	1972	3	STAL	14.07	3	41.59	IT	2	4	--	1	--	PRF	--	--	Selected	CA
22	00303890	JOHOR	K.TINGGI	1974	3	STAL	16.57	5	64.57	IT	1	1	--	4	1	CBPR	--	--	--	CA
No's of total bridges = 12																				

APPENDIX-1 SELECTION OF 20 BRIDGES FOR DETAILED SURVEY

NO.	KEY	STATE	DISTRICT	YEAR BUILT	STUDY CATEGORY	CAPACITY	MAX. SPAN (M)	NO. OF SPAN	BRIDGE LENGTH (M)	TYPE OF BRIDGE	ABUT	RATING OF PARTS			DECK	POSSIBLE REHABILITATION PLANS FROM STRUCTURAL VIEW POINT	POSSIBLE REHABILITATION PLANS FROM FUNCTIONAL VIEW POINT	FINAL SELECTION	REMARKS				
												PIER	BEARING	BEAM									
** PCB...P.C. Beam																							
23	05305010	PAHANG	LIPIS	1961	3	STAL	30.74	4	122.58	PCB	1	1	3	3	1	CBPR,BPR		Selected JKR	CA,AR				
24	00319110	PAHANG	ROMPIN	1962	3	SSAL	30.46	7	121.96	PCB	4	4	4	4	1	1	APR,PPR,CBPR		Selected JKR	CA,AR			
25	00339210	TRENGGANU	KEMAMAN	1963	3	STAL	15.22	10	152.20	PCB	4	4	4	4	1	1	CBRF,APR,ARF,PRF						
26	00339300	TRENGGANU	KEMAMAN	1965	3	STAL	28.03	18	219.13	PCB	5	5	5	5	1	1	BPR,ARF,PPR			CA			
27	00507200	JOHOR	PONTIAN	1966	3	STAL	11.77	3	85.21	PCB	4	4	4	4	1	1	BPR,PRF,ARF			CA			
28	00701600	KEDAH	KULIASSIK	1966	3	STAL	30.64	3	91.36	PCB	3	4	4	4	1	1	DCRF,BSPPR			SA			
29	00701810	KEDAH	KIS. PASU	1970	3	STAL	30.52	3	48.60	PCB	3	4	4	4	1	1	BPR,ARF,PPR	PAISING		Selected JKR			
30	00546740	TRENGGANU	DUNGUN	1973	3	STAL	30.50	9	152.26	PCB	3	1	1	4	4	4	1	CBRF,ARF		Selected JKR			
31	00317000	PAHANG	ROMPIN	1974	3	MTAL	45.78	9	397.32	PCB	1	1	1	4	4	4	4	CBRF,DCRF		Selected JKR	CA		
No's of total bridges = 13																							
--- R.C. BRIDGE ---																							
** BOX...R.C.Box Culvert																							
32	00228970	PAHANG	MARAN	1965	3	STAL	3.03	1	3.03	BOX	3	3	3	3	3	3	3	DCPR,APR		SAI(6.0)			
** PRB...Precast R.C. Beam																							
33	00366900	KELANTAN	P.UTEH	1962	3	STAL	5.41	6	32.46	PRB	4	4	4	4	4	4	4	CBRF,PRF,PPR,ARF,PRF	ADDING & RAISING (REPLACEMENT)				
34	00365700	TRENGGANU	K. T.	1968	3	STAL	5.90	9	53.10	PRB	2	1	1	1	1	1	1	CBPR		Selected	CB		
35	00567840	PERAK	KUNTA	1960	3	STAL	6.06	2	12.12	PRB	3	1	1	1	1	1	1	CBPR,ARF	WIDENING		Selected		
36	00361480	TRENGGANU	BESUT	1960	3	STAL	6.01	3	18.03	PRB	1	4	4	4	4	4	4	PRF	ADDING SIDE WALK		CA		
37	00322620	MELAKA	MELAKA TGH	1960	3	STAL	7.11	2	14.22	PRB	1	4	4	4	4	4	4	CBPR,PPR			CA		
38	00314180	JOHOR	MERSING	1964	3	STAL	5.50	2	11.00	PRB	3	1	1	1	1	1	1	APRF			CA		
39	00326950	PAHANG	PEKAN	1965	3	STAL	5.83	4	23.52	PRB	4	4	4	4	4	4	4	1	CBPR,PRF,ARF		CA		
40	01105770	NS	JEMPAL	1970	3	STAL	6.18	3	18.52	PRB	4	1	1	1	1	1	1	CBPR,ARF,BSPPR			JKR		
** PCB...R.C. Beam																							
41	00321900	MELAKA	MELAKA TGH	1950	3	STAL	6.90	1	6.90	RCB	3	3	3	3	4	4	4	4	CBPR,DCRF,ARF	ADDING SIDE WALK	CA,SA		
42	00109100	JOHOR	KLUANG	1964	3	STAL	15.90	3	27.40	RCB	1	4	4	4	4	4	4	1	CBPR,PPR		SAI(7.04)		
43	00113760	JOHOR	SEGAMAT	1955	3	STAL	6.83	3	20.34	RCB	1	1	1	1	3	3	3	3	CBPR,DCPR		SAI(6.7)		
44	00114920	JOHOR	SEGAMAT	1955	3	STAL	6.43	2	12.86	RCB	1	3	3	3	3	3	3	3	PPR,CBPR		Selected JKR		
45	00341800	TRENGGANU	KEMAMAN	1955	3	STAL	12.10	3	36.14	RCB	4	4	4	4	4	4	4	1	CBRF,SPR,ARF,PRF		Selected		
46	00514800	JOHOR	MUAR	1955	3	STAL	6.97	9	46.03	RCB	1	4	4	4	4	4	4	1	CBRF,PRF		CA,SA		
47	00534570	SELANGOR	SEPANG	1960	3	STAL	6.95	6	32.54	RCB	4	4	4	4	4	4	4	1	ARF,PRF		CA		
48	00540730	SELANGOR	K. LANGAT	1960	3	STAL	7.30	3	11.94	RCB	1	1	1	1	1	1	1	1	CBPR	this bridge has been repaired	CB		
49	00151960	PERAK	BTG PADANG	1960	3	STAL	9.08	7	63.56	RCB	1	1	1	1	3	3	3	1	CBPR				
50	00519560	JOHOR	BATU PAHAT	1960	3	STAL	10.42	3	91.24	RCB	3	4	4	4	4	4	4	1	BPR,PPR,APR				
51	00521710	MELAKA	MELAKA TGH	1960	3	STAL	10.72	1	10.72	RCB	4	4	4	4	4	4	4	1	CBRF,ARF,PRF	ADDING SIDE WALK	CA		
52	00321900	MELAKA	MELAKA TGH	1960	3	STAL	7.13	2	14.26	RCB	3	4	4	4	4	4	4	1	CBRF,ARF,PRF		CA,SA		
53	00330370	PAHANG	PEKAN	1965	3	STAL	10.42	3	91.26	RCB	4	4	4	4	1	1	1	1	APR,ARF,PPR		CA		
54	00516880	JOHOR	MUAR	1966	3	STAL	8.03	3	17.82	RCB	1	4	4	4	4	4	4	1	CBPR,BPR,PPR		CA		
** RCS...R.C.Slab																							
55	00403400	SELANGOR	PETALING	1950	3	STAL	6.56	1	6.56	PCS	3	3	3	3	3	3	3	1	APR	RAISING GRADE	JKR		
56	00205970	JOHOR	SEGAMAT	1950	4	SSAL	5.68	2	7.90	PCS	4	4	4	4	4	4	4	3	ARF,DCPR		JKR		
57	00519260	MELAKA	JASIN	1955	3	STAL	6.22	7	42.70	PCS	1	4	4	4	4	4	4	2	PRF		CA,SA		
58	00337240	PAHANG	KUANTAN	1957	3	STAL	6.53	3	6.53	PCS	4	4	4	4	4	4	4	1	ARF		Selected JKR		
59	00344550	KELANTAN	KUALA KRAI	1960	3	STAL	4.60	3	13.71	PCS	1	4	4	4	4	4	4	4	DCRF,PPR		Selected JKR		
60	00313520	JOHOR	MERSING	1960	3	STAL	1.80	2	3.60	PCS	3	3	3	3	3	3	3	4	DCRF,ARF,PPR	ADDING SIDE WALK	CB		
61	01150060	PERAK	MANJUNG	1960	3	STAL	3.88	1	3.88	PCS	1	1	1	1	1	1	1	4	DCRF	ADDING & WIDENING	JKR		
62	00304080	JOHOR	K. TINGGI	1963	3	STAL	36.85	5	92.25	PCS	1	1	1	1	1	1	1	3	DCPR		Selected JKR		
63	00548990	SELANGOR	K.SELANGOR	1969	3	STAL	10.64	3	30.94	PCS	4	4	4	4	4	4	4	4	4	DCRF,ARF,ARF,PPR		Selected JKR	CA
No's of total bridges = 82																							

APPENDIX – J

BACKUP DATA OF SUBSOIL INVESTIGATION






TABLE OF CONTENTS


<u>Description</u>	<u>Page</u>
Borehole Layout Location for the 5 Bridges	J- 1
Hand Auger Location for the 10 Selected Bridges for Sulphate Survey	J- 4
Drilling Logs for the 5 Selected Bridges	J- 9
Plot of Index Properties Versus Depth at Bridge No. 00546980 (Fig. J-1 to J-3)	J-18
Plot of Index Properties Versus Depth at Bridge No. 00546980 (Fig. J-4 to J-6)	J-19
Pressuremeter Curve at 5 meters depth for Bridge No. 00546980	J-20
Pressuremeter Curve at 10 meters depth for Bridge No. 00546980	J-21
Results of Chemical Tests on Water Samples from Boreholes (Table J-1)	J-22
Results of Chemical Analysis on Soil Samples from Hand Auger Holes (Table J-2)	J-23
Results of Chemical Analysis on Soil Samples from Hand Auger Holes (Table J-3)	J-24
Recommendations for Concrete Exposed to Sulphate Attack (Table J-4)	J-25




Borehole location at Bridge No. 00161140, Perak.




Borehole location at Bridge No. 00346740, Terengganu.




Borehole location at Bridge No. 00546560, Selangor




Borehole Location at Bridge No.00546980, Selangor




Borehole location at Bridge No. 00567840, Perak




Locations of Hand Augers and collected river water samples at Bridge No. 00108100, Johor




Locations of Hand Augers and collected river water samples at Bridge No. 00114920, Johor




Locations of Hand Augers and collected river water samples at Bridge No. 00303220, Johor




Locations of Hand Augers and collected river water samples at Bridge No. 00303430, Johor




Locations of Hand Augers and collected river water samples at Bridge No. 00361490, Terengganu




Locations of Hand Augers and collected river water samples at Bridge No. 00366660, Kelantan




Locations of Hand Augers and collected river water samples at Bridge No. 00303890, Johor



Locations of Hand Augers and collected river water samples at Bridge No. 00316745, Johor



Locations of Hand Augers and collected river water samples at Bridge No. 00366890, Kelantan



Locations of Hand Augers and collected river water samples at Bridge No. 00368300, Kelantan

FIG DRILLING LOG

Project No. K03-16 Project REHABILITATION OF BRIDGE AT Type of Drilling ROTARY
 Hole Number BH-1 SC DUNGAN, TERENGGANU Elevation RL +3.60m m. Date 23rd September to 25th September 1991
 Water Table Cl-1.35 m. Bridge No. 346740 Driller Lim (Leong)

Remarks
 P : Standard Penetration Test

Scale in m	Elevation in M	Depth in m	Thickness in M	Legend	Type of Soil	Colour	Relative Density or Consistency	General Remarks	Sampling		Standard Penetration Test									
									Depth in m	Sample No.	N-Value Blows/45cm	Blows Per Each 7.6cm				N - Value				
												15 cm	15 cm	15 cm	15 cm	10	20	30	40	50
1	5.60	0.00			Clayey SILT	Whitish Grey with Reddish and Yellowish		(Fill). Traces of fine sand and gravel.												
2	4.30	1.30	1.30		SAND	Yellowish Brown	Loose to Very loose	Fine to coarse sand. Silty up to 1.8m. Fine sand predominates up to 4m. With some fine gravel below 4m.	1.65	P-1	5	1	1	1						
3									3.45	P-2	4	1	1	1						
4									4.65	P-3	3	0	0	1						
5									4.95			1	1	1						
6									6.15	P-4	3	0	1	1						
7									6.45			0	0	1						
8	-1.95	7.55	6.25		Silty CLAY	Dark grey	Soft	With organic matter and fine sand. Traces of mica fragment.	7.65	P-5	2	0	0	1						
9	-2.50	8.10	0.55						7.95			0	0	1						
10					SAND	Light brown to Light Grey to Grey	Very loose to Medium	Fine to coarse sand with fine to medium sand. Slightly clayey at bottom. With fine gravel below 10m. Max. dia. 8mm. Trace of silt below 10m. Sandy clay lense with shell fragments at bottom.	9.15	P-6	3	0	1	1						
11									9.45			3	4	3						
12									10.65	P-7	15	3	4	4						
13	-6.60	12.20	4.10						10.95			7	3							
14					SILT with rock fragments	Red to Grey Mottled Yellow and Brown		Completely weathered sedimentary rock friable to silty with hard rock fragments.	12.15	P-8	50/15	4	47							50BLOWS/15CM
15									12.30			18								
16									13.50	P-9	50/15	32								50BLOWS/15CM
17									13.65			20	15	25						
18									13.88	P-10	50/22	5	25	10						50BLOWS/22.5CM
19									16.50	P-11	50/5	50								50BLOWS/5CM
20									16.55											
21	-12.46	18.06	5.86						18.00	P-12	50/6	50								50BLOWS/6CM
22									18.06											
23																				
24																				
25																				
26																				
27																				
28																				
29																				
30																				
31																				

KISO-JIBAN CONSULTANTS (M) SDN.,BHD.

Page.....

Drilling Log - Bridge No. 00346740, Terengganu