

**Japan International Cooperation Agency**

No.
-----

**Ministry of Industry**

**The Socialist Republic of Viet Nam**

**Final Report – Case Study on  
the Master Plan Study for  
Industrial Pollution Prevention in Viet Nam  
(Wastewater)**

**September 2000**

**International Center for Environmental Technology Transfer  
Mitsubishi Chemical Engineering Corporation**

<b>M P I</b>
<b>C R(5)</b>
<b>00-162</b>

**Japan International Cooperation Agency**

**Ministry of Industry**

**The Socialist Republic of Viet Nam**

**Final Report – Case Study on  
the Master Plan Study for  
Industrial Pollution Prevention in Viet Nam  
(Wastewater)**

**September 2000**

**International Center for Environmental Technology Transfer  
Mitsubishi Chemical Engineering Corporation**

# **Contents**

Chapter 1	Textile & Garment Sub-sector
Chapter 2	Chemical Sub-sector
Chapter 3	Paper & Pulp Sub-sector
Chapter 4	Food Processing Sub-sector
Chapter 5	Metal Works Sub-sector

## **Chapter 1 Textile & Garment Sub-sector**

### **1.1 Detailed Enterprise Study**

Case Study T-01	Phong Phou Textile Company	T-1
Case Study T-02	Dong Phuong Knitting Company	T-15
Case Study T-03	Danang Textile Company	T-29
Case Study T-04	Nam Dinh Textile Company	T-43
Case Study T-05	Nam Dinh Silk Company	T-59

### **1.2 Simplified Enterprise Study**

Case Study T-06	Duc Gian Garment Export and Import Company	T-73
Case Study T-07	Vinh Phu Textile Company	T-77
Case Study T-08	Thang Long Garment Company	T-83
Case Study T-09	Dong Xuan Knitting Company	T-87
Case Study T-10	Ha Dong Woolen Enterprise	T-91
Case Study T-11	Viet Tien Garment Export and Import Company	T-95
Case Study T-12	Phuoc Long Textile Garment Company	T-97
Case Study T-13	Thanh Cong Textile Company	T-101
Case Study T-14	Dong Nam Textile Company	T-105
Case Study T-15	Binh Loi Blanket-Woolen Company	T-109
Case Study T-16	Thanhg Loi Textile Company	T-113
Case Study T-17	Hoa Tho Textile & Garment Company	T-117
Case Study T-18	29-3 Textile-Garment Company	T-123
Case Study T-19	Hue Textile Company	T-127

**Phong Phu Textile Company**

Survey Date: 1 December 1999  
24 & 25 February 2000

**1. General****1.1 Profile**

Phong Phu Textile Company is a state-owned company that was established in 1965 as a textile manufacturing company. The company profile and organization of Phong Phu Textile Company are summarized in Table 1 and Figure 1.

**Table 1 Enterprise Profile**


Name of Company:	Phong Phu Textile Company
Ownership:	State-owned
Address:	District 9 Hochiminh City
Tel:	08-8963533/34/35
Director:	
Established:	1965
Corporate Capital:	
Number of Employees:	3,500
Main Products:	Yarns, Fabrics, Towels, Garments

**1.2 Business Status****1.2.1 Production**

Table 2 shows production and sales of the Company in 1998.  
40 % of products are exported to the EU(Garment) and Japan(Towel.)

**Table 2 Production and Sales in 1998**

No.	Products	Production	Turnover
1	Fabric	9,361,000 m	227 billion VND
2	Towel	37,328,000 pcs	145.7 billion VND
3	Yarn	6,992,000 kg	84.2 billion VND
4	Garment	1,248,000 pcs	26.3 billion VND
5	Others		11.8 billion VND
	Total		495 billion VND



**Figure 1 Organization of the Phong Phu Textile Company**

### 1.2.2 Debt

Unknown

## 2. Production Technology

### 2.1 Process

Figures 2 and 3 show a simplified block flow diagram of the factory and a block flow diagram of the dyeing process, respectively.

Table 3 shows the operating condition of the dyeing process.

### 2.2 Future Plan

- (1) Installation of a wastewater treatment plant; and
- (2) Acquisition of ISO9002 certification.


## 3. Management Technology

### 3.1 Unit Consumption of Raw Material and Utilities

Table-4 shows the unit consumption of raw materials and utilities of the factory.


**Table-4 Unit Consumption**

No	Materials	Unit Consumption	Cost	Consumption/year
1	Fabric	1000 m		9,361million meter
2	Towel	1000 kg		2,400 t
3	Dye stuff			
	Fabrics (Indigo, Sulfur)	7 kg (2 %)		30 t
	Towel (Hoat Tinh)	1.5 kg (0.15 %)		3.6 t
4	Chemicals			
	a. Soda, H <sub>2</sub> O <sub>2</sub>			
	b.			120 t
5	Water			1,260,000 m <sup>3</sup>
6	F.O.		1,495 VND/kg	4,500 t
7	Electricity		775 VND/kWh	24,000,000 kWh



**Figure 2 Simplified Block Flow Diagram**





**Figure 3 Process Flow Diagram**

**Table 3 Operating Condition of the Dyeing Process**

<b>(1) White Towel (Batch Process)</b>			
M/C: Wince Type			
Fabric :270 kg			
Liquid Ratio:1:12			
Step	Chemicals	Temperature	Retention Time
De-sizing		90	45 min.
Scouring + Bleaching		100	100 min.
Hot Rinse		100	40 min.x3
Hot Rinse		80	30 min.
Cold Rinse		40	40 min.
Optical Bleaching		50	50 min.
Cold Rinse		30	20 min.
<b>(2) Color Towel (Continuous + Batch Process)</b>			
<b>(2)-1 Continuous Scouring &amp; Bleaching Process</b>			
Speed:15 m/min			
Step	Chemicals	Temperature	Retention Time
Scouring Dipping		80	
Steaming		100	45 – 60 min.
Bleaching Steaming		100	60 min.
Washing		100	
<b>(2)-2 Batch Dyeing Process</b>			
M/C: Overflow Type			
Fabric:270 kg			
Liquid Ratio:1:12			
Step	Chemicals	Temperature	Retention Time
Hot Rinse		50	40 min.
Cold Rinse		30	20 min.
Dye		60	180 min.
Cold Rinse		30	30 min.
Washing		40	35 min.
Hot Rinse		60	70 min.
Cold Rinse		30	30 min.
<b>(3) Cotton Fabric (after Sigeing)</b>			
M/C: Jigger			
Fabric:250kg			
Liquid Ratio:1/3			
Step	Chemicals	Temperature	Retention Time
Scaming		98	200 min.
Hot Rinsing		50	60 min.
Cold Rinsing		30	20 min.
Mercerizing		30	140 min.
Hot Rinsing		30	60 min.
Cold Rinsing		30	20 min.
Bleaching		98	180 min.
Hot Rinsing		98	80 min.
Cold Rinsing		30	20 min.
Dyeing		60	230 min.
Cold Rinsing		30	30 min.
Fixing		40	30 min.
Cold Rinsing		30	15 min.
Washing		60	30 min.

## **4. Industrial Wastewater Treatment and Discharge**

### **(1) Outline**

1. The plant discharges a lot of wastewater at a volume of 3,600m<sup>3</sup>/day, and its contamination is striking. PH, BOD and COD are in excess of the environmental standards of Vietnam.
2. Wastewater treatment is only done by sedimentation of SS in the sedimentation tank.
3. However, this treatment has no effect on the wastewater because the tank volume is too small to discharge volume.

### **(2) Sampling Points of the Field Study on December 1999**

Wastewater samples were taken at the following spots for analysis in this study.

Date: 1 December 1999

- S1 : At Scouring m/c( wash water of the #1tank)
- S2 : At Scouring m/c( wash water of the #4 tank )
- S3 : At Bleaching m/c(wash water after bleaching)
- S4 : At Wince dyeing m/c ( wash water after dyeing)
- S5 : At Jet dyeing m/c ( wash water after dyeing)
- S6 : Wastewater from the dyeing factory
- S7 : Discharged wastewater from whole factory (to city sewage)

### **(3) Results of Wastewater Analysis in December 1999**

Wastewater qualities analyzed by Hanoi University Civil Engineering Center of Environment Engineering of Towns and Industrial Areas (CEETIA) are shown in Table 5.

### **(4) Sampling Points in February 2000**

Wastewater samples were taken at the following spots for analysis during this study.

Date: 28 February 2000

S1 : Composite sampling at the outlet of the dyeing factory (21samples mixing)

Sampling time: Taken every 15 minutes from 9:00 to 15:00

S2 : At Wince dyeing m/c(after 1<sup>st</sup> cold rinse ) Sampling time:9:45

S3 : At Wince dyeing m/c(after dyeing1<sup>st</sup> cold rinse ) Sampling time:11:48

S4 : At Wince dyeing m/c(after 2<sup>nd</sup> cold rinse ) Sampling time:11:55

S5 : At Wince dyeing m/c(after 3<sup>rd</sup> cold rinse ) Sampling time:12:20

S6: At Wince dyeing m/c(after washing ) Sampling time:12:30

S7: At Wince dyeing m/c(after fixing) Sampling time:13:15

S8: At Wince dyeing m/c(after 4<sup>th</sup> cold rinse ) Sampling time:13:45

S9: At Wince dyeing m/c(after 5<sup>th</sup> cold rinse ) Sampling time:13:50

**Table 5 Wastewater Quality in December 1999**

	Unit	S1	S2	S3	S4	S5	S6	S7
Temperature			61.5		31.9	33	47	44.4
pH		12.98	9.5	8.16	6.6	11.48	11.46	11.4
Elec. Conductivity	μ S/cm	9900	120	80	10	1190	350	11420
Turbidity	NTU	398	98	111	265		338	220
Oil Content	mg/l	191	12	42	Not det	7	24	33
BOD	mg/l	44	13	38	1	8	90	91
COD	mg/l	6568	198	321	10	75	487	608
DO	mg/l	5.5	1.7	1.5	10.5	13.8	11.6	
SS	mg/l	360	32	14	0	7	20	30
Total Nitrogen	mg/l	31.4	2.1	3.1	0.3	1.5	9.2	9.3
Residual Chlorine	mg/l	Not det	Not det	Not det	Not det	Not det	Not det	Not det
SO <sub>4</sub>	mg/l	60	6	7	7	11200	132	97
Cyanogen	mg/l							0.05

**(5) Results of Wastewater Analysis in February 2000**

Wastewater qualities analyzed by Hanoi University Civil Engineering Center of Environment Engineering of Towns and Industrial Areas (CEETIA) are shown in Table 6.

**Table 6 Wastewater Quality in February 2000**

	Unit	S1	S2	S3	S4	S5	S6	S7	S8	S9
Temperature		32.8	29.3	75.2	42.5	32.9	30.2	29.1	28.9	29.5
pH		11.36	9.3	10.1	10.46	9.26		6.34	5.5	6.21
Elec. Conductivity	μ s/cm	5360	220	1000	8420	3060	660	300	160	230
Turbidity	NTU	116	2	15	9	6	3	5	0	1
Oil Content	mg/l	10.66	7.8	6.4	7.93	5.33	0.8	3.57	0.92	1.55
BOD	mg/l	384	22	24	14	7	3	7	0	3
COD	mg/l	844	38	152	38	10	9	32	2	8
DO	mg/l	7.7	7.7	7.6	7.7	7.5	7.6	7.6	7.6	7.6
SS	mg/l	60	1	13	9	5	1	3	1	2
All Nitrogen	mg/l	22.5	0.8	3.3	1.2	0.3	0.8	9.1	0	0
Residual Chlorine	mg/l	Not det	Not det	Not det	Not det	Not det	Not det	Not det	Not det	Not det
SO4	mg/l	295	5	349	328	409	170	16	6	13
Cyanogen	mg/l									

## 5. Countermeasures for Improvement

### 5.1 Countermeasures for Production Technology Improvement

#### (1) Current Problems

- a. Czech-made rotor type spinning machines have problems with quality.
- b. Steam and water leakage from the pipe line is conspicuous.
- c. Some dyeing machines(Wince type) are superannuated and corroded.
- d. No countermeasures for energy saving have been adopted, except for recovery of steam condensation.
- e. The liquid ratio of liquid flow type machines is high at 1:10 ~ 1:12.

#### (2) Countermeasures

- a. Czech-made spinning machines should be improved.
- b. Steam and water pipe lines should be repaired.
- c. Some superannuated dyeing machines (Wince Type) should be renewed and converted into the low liquid ratio type machines.
- d. Countermeasures for energy saving such as recovery of cooling water and heat recovery from the wastewater should be adopted.

## **5.2 Countermeasures for Management Technology Improvement**

### **(1) Current Problems**

- a. The inside and outside of the dyeing plant are in disorder.
- b. Standardization of operations and operation manual construction and utilization are inefficient.
- c. Cost management measures, such as calculating unit consumption of the raw materials and energy, are hardly carried out.
- d. The maintenance of facilities is inefficient.

### **(2) Countermeasures**

- a. The “5S Movement” should be executed.
- b. Standardization of operation is very important. Operation manuals should be prepared and placed in a position where operators can see them easily.
- c. ISO9000 series should be introduced.
- d. Unit consumption analysis and promotion of cost reduction program should be executed.
- e. As a first step, the total consumption of water and steam should be grasped.
- f. The maintenance function should be reinforced.

## **5.3 Countermeasures for Wastewater Treatment**


They should install the following wastewater treatment system to improve the quality of the wastewater of the factory to within Vietnam standards.

### **(1) Outline of the Wastewater Treatment System**

- a ) Volume of wastewater: 3,600m<sup>3</sup>/day;
- b ) Production capacity: 100,000m/day (Dyeing fabric);
- c ) Treatment Methods: Activated sludge process & Coagulating Sedimentation;
- d ) Investment Cost: 8,170,000,000 VND

### **(2) Flow Diagram of the Wastewater Treatment System**

Figure 4 shows the flow diagram of the wastewater treatment system.



**Figure 4 Flow diagram of wastewater treatment system**

### (3) Investment Cost

Table 7 shows the investment cost.

**Table 7 Required Investment Cost of the Wastewater Treatment System**

Items	Unit	Quantity	Unit price VND	Expenses VND
Equalization tank	m <sup>3</sup>	1,800	700,000	1,260,000,000
pH neutralization tank	m <sup>3</sup>	300	700,000	210,000,000
Aeration tank	m <sup>3</sup>	3,600	700,000	2,520,000,000
Sedimentation tank	m <sup>3</sup>	1,200	850,000	840,000,000
Coagulation tank	m <sup>3</sup>	900	850,000	765,000,000
Final tank	m <sup>3</sup>	50	700,000	35,000,000
Sludge tank	m <sup>3</sup>	50	700,000	35,000,000
Sewerage: 500 x 600	m <sup>3</sup>	150	300,000	45,000,000

<b>Sub Total 1(Construction)</b>				<b>5,710,000,000</b>
Wastewater Pump	piece	4	10,000,000	40,000,000
Aerator; capacity 150 m <sup>3</sup> /h	piece	5	30,000,000	150,000,000
pH meter and metering pump	set	1	40,000,000	40,000,000
Agitator; capacity: 2 HP	piece	4	7,500,000	30,000,000
Acid mixture apparatus	set	1	200,000,000	200,000,000
Coagulant mixture apparatus	set	2	200,000,000	400,000,000
Sludge dehydrating machine	set	1	800,000,000	800,000,000
Electricity	set	1	200,000,000	200,000,000
Pipeline and accessories	set	1	300,000,000	300,000,000
Other equipment				300,000,000
<b>Sub Total 2(Equipment)</b>				<b>2,460,000,000</b>
<b>Grand Total</b>				<b>8,170,000,000</b>



## 6. Recommended Countermeasure for Improvement

### 6.1 Short Term Countermeasures


No	Countermeasure	Expected Results
1	Repair of the steam & water pipes	Energy savings and, improvement of the working environment
2	Installation of flow meters for water and steam	Grasp of unit consumption (Cost reduction)
3	Installation of a cooling water recovery system	Energy savings
4	Installation of a heat recovery system from the waste water	Energy savings
5	Standardization of operations	Improvement of product quality and cost reduction
6	Reinforcement of the maintenance function	Increase in equipment capacity, productivity and product quality
7	Execution of the “5S Movement”	Elimination of waste-fullness, increased worker morale, improvement in product quality and a gain in customer's trust.

### 6.2 Mid and Long Term Countermeasures

No	Countermeasure	Expected Results
1	Installation of a wastewater treatment system	Improvement of wastewater quality
2	Modernization of the Color Kitchen	Improvement of the accuracy of scaling, prevention of contamination and improvement of the working environment
3	Replacement of old wince type dyeing machines with liquid flow type ones that have a low liquid ratio	Reduction in the wastewater volume, reduction of chemical consumption, improvement of productivity and increased possibility of producing high value-added products
4	Acquisition of ISO9000 series certification	Improvement of product quality and cost reduction
5	Introduction of cost reduction programs	Cost reduction
6	Introduction of new dyeing technologies such as the Rapid Dyeing Method	Energy savings, reduction of chemical consumption and improvement of wastewater quality

## 7. Proposed Implementation Schedule

The proposed implementation schedule is shown in Figure 5.



**Figure 5 Proposed Implementation Schedule for Pollution Prevention Countermeasure**

**Dong Phuong Knitting Company**

Survey Date: 8 December 1999

28 &amp; 29 February 2000

**1. General****1.1 Profile**

Dong Phuong Knitting Company is a state-owned company that was established in 1972 as a textile manufacturing company. The company profile and organization of Dong Phuong Knitting Company are summarized in Table 1 and Figure 1.

**Table 1 Enterprise Profile**

Name of Company:	Dong Phuong Knitting Company
Ownership:	State-owned
Address:	10 AU CO ST., Ward 17, Tan Binh District, Hochiminh City
Tel:	08-8101802
Director:	
Established:	1972
Corporate Capital:	
Number of Employees:	480
Main Products:	Knitting Fabrics & Knitting Garments


**1.2 Business Status****1.2.1 Production**

Table 2 shows production and sales of the Company in 1998.

50 ~ 60% of their products are exported to Germany, Czech, France, Portugal, Korea, USA and Japan.

**Table 2 Production and Sales in 1998**

No.	Products	Production	Turnover
1	Warp Knitting Fabric (for Internal Production)	1,573,000 m <sup>2</sup>	7,512 million VND
	(for Customer Supply)	578,000 m <sup>2</sup>	
2	Circular Knitting Fabric (for Internal Production)	281,000 m <sup>2</sup>	13,337 million VND
	(for Customer Supply)	117,000 m <sup>2</sup>	
3	Garments	726,000 pcs	17,951 million VND
4	Others		131 million VND
	Total		38,931 million VND



**Figure 1 Organization of Dong Phuong Knitting Company**

### 1.2.2 Debt

(1) Vay TTCN GDI; 7,937 million VND

(2) Vay 1,700 million VND

## 2. Production Technology


### 2.1 Process

Figures-2 and 3 show a simplified block flow diagram of the factory and a block flow diagram of the dyeing process.


Table 3 shows the operating condition of the dyeing process.

**Table 3 Operating Condition of the Dyeing Process**

(1) Polyester/Cotton			
M/C:Jet Type			
Fabric:270 kg			
Liquid Ratio:1/10			
Step	Chemicals	Temperature	Retention Time
Scouring		98	60 min.
Rinsing			30 min.
Bleaching(H <sub>2</sub> O <sub>2</sub> )		98	60 min.
Rinsing			30 min.
Dyeing of PES		130	30-60 min.
Rinsing			30 min.
Reduction		80	20 min.
Rinsing			30 min.
Dyeing of Cotton		60-80	60 min.
Rinsing			30 min.
(2) Cotton			
M/C: Over Flow Type			
Fabric:270 kg			
Liquid Ratio:1/10			
Step	Chemicals	Temperature	Retention Time
Scouring		98	60 min.
Rinsing		80	20 min.
Bleaching		98	60 min.
Rinsing		80	20 min.
Neutralizing		80	20 min.
Rinsing		98	30 min.
Dyeing		60-80	30-60 min.
Rinsing/Soaping		60	10 min.
Neutralizing		60	20 min.
Washing		98	30 min.
Fixing		50	30 min.



**Figure 2 Simplified Block Flow Diagram**



**Figure 3 Process Flow Diagram**

## 2.2 Future Plans

- (1) Installation of a wastewater treatment system;
- (2) Acquisition of ISO9002 certification;

### **3. Industrial Wastewater Treatment and Discharge**

#### **(1) Outline**

1. No wastewater treatment system has been installed. Wastewater from the factory is discharged to the sewage directly.
2. PH, BOD, COD and SS are in excess of the environmental standards of Vietnam, and the introduction of a treatment system is indispensable to improving the wastewater water quality of the factory.
3. Wastewater volume is 500m<sup>3</sup>/day.

#### **(2) Sampling Points in December 1999:**

Wastewater samples were taken at the following spots for analysis in this study.

Date: 8 December 1999

- S1: At Jet dyeing m/c ( wash water after dyeing)
- S2: Discharged wastewater from the whole factory (to city sewage)
- S3: Supply water from the well ( under ground )
- S4: Dyeing factory supply water after treatment
- S5: At Wince dyeing m/c (wash water after bleaching)

#### **(3) Results of Wastewater Analysis in December 1999**

Wastewater qualities analyzed by Hanoi University Civil Engineering Center of Environment Engineering of Towns and Industrial Areas (CEETIA) are shown in Table 4.

#### **(4) Sampling Points in March 2000**

Wastewater samples were taken at the following spots for analysis in this study.

Date: 1 March 2000

- |   |                     |
|---|---------------------|
| S1: At Overflow dyeing m/c #3(after scouring )                  | Sampling time:13:33 |
| S2: At Overflow dyeing m/c#3(after 1 <sup>st</sup> cold rinse ) | Sampling time:13:45 |
| S3: At Overflow dyeing m/c#3(after bleaching)                   | Sampling time:15:07 |
| S4: At Overflow dyeing m/c#3(after 2 <sup>nd</sup> cold rinse ) | Sampling time:10:15 |
| S5: At Overflow dyeing m/c#2(after dyeing )                     | Sampling time:11:36 |
| S6: At Overflow dyeing m/c#1(after neutralizing)                | Sampling time:10:20 |
| S7: At Overflow dyeing m/c#1(after washing)                     | Sampling time:11:26 |
| S8: At Overflow dyeing m/c#1(after fixing)                      | Sampling time:12:50 |
| S9: At Overflow dyeing m/c#4(after 2 <sup>nd</sup> bleaching)   | Sampling time:11:15 |



**Table 4 Wastewater Quality in December 1999**

	Unit	S 1	S 2	S 3	S 4	S 5
Temperature		60	34.4	29.2	28.9	94
pH		8.52	6.23	4.53	4.73	10.8
Electric Conductivity	μ S/cm	800	514	460	410	230
Turbidity	NTU	9	1	3	0	106
Oil content	mg/l	Not det	4.7	Not det	Not det	16
BOD	mg/l	29	4	1	0	105
COD	mg/l	153	16	4	3	600
DO	mg/l	0.87	3.43	5.71	6.88	0.56
SS	mg/l	12	5	0	0	125
Total Nitrogen	mg/l	12	2.08	2.18	1.18	19.8
Residual Chlorine	mg/l	Not det	2.73	Not det	Not det	12.6
SO <sub>4</sub>	mg/l	22	48	12	10	46
Cyanogen	mg/l					

**(5) Results of Wastewater Analysis in March 2000**

Wastewater qualities analyzed by Hanoi University Civil Engineering Center of Environment Engineering of Towns and Industrial Areas (CEETIA) are shown in Table 5.

**Table 5 Wastewater Quality in March 2000**

	Unit	S1	S2	S3	S4	S5	S6	S7	S8	S9
Temperature		60	36.6	60	31.4	53.3	30.2	66	41	41
PH		10.15	10.74	10.36	3.78	10.3	3.76	8.16	5.53	6.64
Elec. Conductivity	μ S/cm	18300	1700	3800	510	22460	450	750	900	510
Turbidity	NTU									
Oil content	mg/l	62.2	26.6	37.8	0.9	4.6	0.6	15	2.2	1.6
BOD	mg/l	3525	438	600	8	300	4	290	20	23
COD	mg/l	6411	553	1206	23	1131	15	754	60	45
DO	mg/l	1.16	5.09			5.27	4.99	1.53		4.72
SS	mg/l	142	23	100	1	9	3	21	1	4
Total Nitrogen	mg/l	0.8	12	25	1.8	6.7	2.2	27.8	13.9	1.3
Residual Chlorine	mg/l	Ndtcd	Ndtcd		Ndtcd	Ndtcd	Ndtcd	Ndtcd	Ndtcd	Ndtcd
SO <sub>4</sub>	mg/l	40	9	28	5	11730	17	10	48	7
Cyanogen	mg/l									

## (6) Wastewater Treatment Facility Study

The results examined by Dong Phuong Knitting Co. in 1998 are as follows.

### 1) Design condition

Production	Mosquito net :	6,560,000 m/year
	Knitting fabric	300 t/year
	T shirts	300,000 pcs/year
	Polo shirts	100,000 pcs/year
Wastewater Volume		1,000 m <sup>3</sup> /day
Wastewater quality		
Temperature	45	
PH	5.2 ~ 5.6	
BOD	289 mg/l	
COD	515 mg/l	
SS	45 mg/l	
Color	160	
Setting Area	638 m <sup>2</sup> ( 23.3 m × 25 m )	

### 2) Investment cost ( Currency Unit: French Franc )

Table 6 shows the investment cost of a wastewater treatment facility.

**Table 6 Investment Cost of a Wastewater Treatment Facility**

Item	Cost (FF)	%
Equipment	2,060,800	67%
Construction	676,800	22%
Transfer Technology	185,600	6%
Assembling & Operation	137,600	4.5%
Others	16,000	0.5%
<b>Total</b>	<b>3,076,800</b>	<b>100%</b>

## 4. Countermeasures for Improvement

### 4.1 Countermeasures for Production Technology Improvement

#### (1) Current Problems

- a. Warp knitting machines are old and the tension adjustment does not work well. Accordingly, there is unevenness.

- b. Liquid ratio is high, at 1:10 ~ 1:12, for the liquid flow type machines.
- c. Facilities of the laboratory and the system of the color kitchen are not properly prepared.
- d. No countermeasures for energy saving have been adopted including recovery of steam condensate.
- e. The quality of supply water is at very low level.

**(2) Countermeasures**

- a. Low liquid ratio dyeing machines (as 1:6) should be introduced if there is a chance to increase or renew machines.
- b. Countermeasures for energy saving, such as recovery of steam condensate, recovery of cooling water and heat recovery from the wastewater should be adopted.
- c. A supply water treatment system should be installed.
- d. More proper facilities in the laboratory should be prepared.
- e. The color kitchen system should be modernized.

**4.2 Countermeasures for Management Technology Improvement**

**(1) Current Problems**

- a. The color kitchen and outside of the dyeing plant are in disorder.
- b. Standardization of operations and operation manual construction and utilization are inefficient.
- c. Cost management, such as calculating unit consumption of the raw materials and energy, is hardly carried out.
- d. The maintenance of facilities is inefficient.

**(2) Countermeasures**

- a. The “5S Movement” should be executed.
- b. Analysis of unit consumption and promotion of cost reduction program should be executed.
- c. As a first step, the company should grasp the amount of water and steam consumed.
- d. ISO9000 series should be introduced.
- e. Maintenance function should be reinforced.

### 4.3 Countermeasures for Wastewater Treatment


They should install the following wastewater treatment system in order to improve the quality of the wastewater of the factory to satisfy the Vietnamese standards.

#### (1) Outline of the Wastewater Treatment System

- a ) Volume of wastewater. : 1,000 m<sup>3</sup>/day
- b ) Production capacity : 30,000 m/day (Dyeing fabric)
- c ) Treatment Methods : Activated sludge process & Coagulating Sedimentation
- d ) Investment Cost : 3,344,000,000 VND

#### (2) Flow Diagram of the Wastewater Treatment System

Figure 4 shows the flow diagram of the wastewater treatment system.



**Figure 4 Flow Diagram of the Wastewater Treatment System**

### (3) Required Investment Cost

Table 7 shows the required investment cost.

**Table 7 Required Investment Cost for a Wastewater Treatment System**

Items	Unit	Quantity	Unit price VND	Expenses VND
Equalization tank	m <sup>3</sup>	500	700,000	350,000,000
PH neutralization tank	m <sup>3</sup>	80	700,000	56,000,000
Aeration tank	m <sup>3</sup>	1,000	700,000	700,000,000
Sedimentation tank	m <sup>3</sup>	400	850,000	340,000,000
Coagulation tank	m <sup>3</sup>	300	850,000	255,000,000
Final tank	m <sup>3</sup>	20	700,000	14,000,000
Sludge tank	m <sup>3</sup>	20	700,000	14,000,000
Sewerage: 500 x 600	m <sup>3</sup>	150	300,000	45,000,000
<b>Sub Total 1(Construction)</b>				<b>1,774,000,000</b>
Wastewater Pump	piece	4	10,000,000	40,000,000
Aerator; capacity 150 m <sup>3</sup> /h	piece	2	30,000,000	60,000,000
pH meter and metering pump	set	1	40,000,000	40,000,000
Agitator; capacity: 2 HP	piece	4	7,500,000	30,000,000
Acid mixture apparatus	set	1	100,000,000	100,000,000
Coagulant mixture apparatus	set	2	100,000,000	200,000,000
Sludge dehydrating machine	set	1	500,000,000	500,000,000
Electricity	set	1	200,000,000	200,000,000
Pipeline and accessories	set	1	200,000,000	200,000,000
Other equipment				200,000,000
<b>Sub Total 2(Equipment)</b>				<b>1,570,000,000</b>
<b>Grand Total</b>				<b>3,344,000,000</b>

## 5. Recommended Countermeasure for Improvement

### 5.1 Short Term Countermeasures


No	Countermeasure	Expected Results
1	Installation of flow meters for water and steam	Grasp of unit consumption (Cost reduction)
2	Installation of a steam condensate recovery system	Energy savings
3	Installation of a cooling water recovery system	Energy savings
4	Installation of heat recovery system from the waste water	Energy savings
5	Standardization of operations	Improvement of product quality and cost reduction
6	Execution of the "5S Movement"	Elimination of waste-fullness, increase in worker's morale, improvement of product quality, and a gain in customer's trust

### 5.2 Mid and Long Term Countermeasures

No	Countermeasure	Expected Results
1	Installation of a wastewater treatment system	Improvement of wastewater quality
2	Modernization of the Color Kitchen	Improvement of the accuracy of scaling, prevention of contamination, improvement of the working environment
3	Acquisition of ISO9000 series certification	Improvement of product quality and cost reduction
4	Introduction of a cost reduction program	Cost reduction
5	Introduction of low liquid ratio type dyeing machines	Energy saving, reduction of chemical consumption and improvement of wastewater quality
6	Introduction of new dyeing technology such as the Rapid Dyeing Method	Energy saving, reduction of chemical consumption and improvement of wastewater quality

## 6. Proposed Implementation Schedule

A proposed implementation schedule is shown in Figure 5.



**Figure 5 Proposed Implementation Schedule for Pollution Prevention Countermeasure**





**Danang Textile Company**

Survey date: 15 December 1999

6 &amp; 7 March 2000

**1. General****1.1 Profile**

Danang Textile Company is a local state-owned company that was established in 1976 as a textile manufacturing company. It started out as a joint company invested partly by private capital and partly by state capital and became a local state-owned factory in 1982. In 1994 it rose to become a local state-owned company in 1994. The company profile and organization of Danang Textile Company is summarized in Table 1 and Figure 1.

**Table 1 Enterprise Profile**

Name of Company:	Danang Textile Company
Ownership:	Local state-owned
Address:	Hoa Khanh, Lien Chieu Danang City
Tel:	84 511 842127
Director:	Mr. HOANG SY PHONG
Established:	1976
Corporate Capital:	
Number of Employees:	400
Main Products:	Fabrics & Towels


**1.2 Business Status****1.2.1 Production**

Table 2 shows production and sales of the Company in 1998.

The main market of this company is domestic.

**Table 2 Production and Sales in 1998**

<b>Product</b>	<b>Production</b>	<b>Turnover</b>
Woven fabrics	2,307,760 m <sup>2</sup> /year	20,204,217,000 VND



**Figure 1 Organization of Danang textile Company**

### 1.2.2 Debt

- a. Short-term debt: 5,756.7 million VND.
- b. ICO long-term debt: 38,396.42 US\$.
- c. Long-term debt: 5,915,000,000 VND.
- d. Long-term investment fund: 506,533,000 VND.

## 2. Production technology

### 2.1 Process

Figures-2 and 3 show a simplified block flow diagram of the factory and a block flow diagram of the dyeing process, respectively.


Table 3 shows the operating condition of the dyeing process.

**Table 3 Operating Condition for Cotton Towels**


(1) Scouring & Bleaching			
M/C:Jigger			
Fabric:100 kg			
Liquid Ratio:1/5			
Step	Chemicals	Temperature	Retention Time
Scouring & Bleaching		60	60 min
Washing		60	30 minx3
(2) Dyeing			
M/C: Jet Type			
Fabric: 200 kg			
Liquid Ratio: 1/10			
Step	Chemicals	Temperature	Retention Tome
Dyeing		60	60 min
Washing		60	40 min
Neutralization		60	20 min
Washing		60	30 min

### 2.2 Future Plan

- (1) Installation of a wastewater treatment system



**Figure 2 Simplified Block Flow Diagram**



**Figure 3 Process Flow Diagram**

### 3. Management Technology

Table 4 shows the unit consumption of raw materials and utilities.

**Table 4 Unit Consumption of Raw Materials and Utilities**

No.	Items	Quantity/year	Cost (VND)
1	Yarns	330 tons	30,000,000/ton
2	Dyes	6 tons	180,000,000/ton
3	Organic auxiliaries	24 tons	2,700,000/ton
4	Detergents	0.3 tons	30,000,000 VND/ton
5	Water	30,000 m <sup>3</sup>	1,000 VND/m <sup>3</sup>
6	FO	350 tons	1,800,000 VND/ton
7	Electricity	1,085,545 kWh	770 VND/kWh

### 4. Industrial Wastewater Treatment and Discharge

#### (1) Outline

1. Wastewater is discharged outside without any treatment.
2. The company has a plan to install a wastewater treatment system which is estimated to cost 230 million VND. However the local government will not permit this project because of unprofitable investment.
3. Wastewater volume is 40 m<sup>3</sup>/day.

#### (2) Sampling Points in December 1999

Wastewater samples were taken at the following spots for analysis in this study.

Date: 15 December 1999

S1 : At Jigger dyeing m/c ( washing water after bleaching)

S2 : Wastewater discharged from dyeing factory (to city sewage)

#### (3) Result of Wastewater Analysis of Samples Taken in December 1999

Wastewater qualities analyzed by Hanoi University Civil Engineering Center of Environment (CEETIA) are shown in Table 5.

**Table 5 Wastewater Quality in December 1999**

	Unit	S1	S2
Temperature		70	48.2
PH		12.2	11.4
Electric Conductivity	μ S/cm	50900	4400
Turbidity	NTU	102	212
Oil content	mg/l	Trace	Trace
BOD	mg/l	208	236
COD	mg/l	8430	8610
DO	mg/l	2.08	8.4
SS	mg/l	117	253
Total Nitrogen	mg/l	36.1	17.2
Residual Chlorine	mg/l	Trace	Trace
SO <sub>4</sub>	mg/l	2842	644
Cyanogen	mg/l		

**(4) Sampling Points of the Field Study in March 2000**

Wastewater samples were taken at the following spots for analysis in this study.

Date: 4 March 2000

S1 : At the outlet of the dyeing factory : Composite Sampling

Sampling time:    10:45        11:00        11:15        11:30        11:45  
                           13:57        14:20        14:40        15:00

**(5) Wastewater Analysis in March 2000**

Wastewater qualities analyzed by Hanoi University Civil Engineering Center of Environment (CEETIA) are shown in Table 6.

**Table 6 Wastewater Qualities in March 2000**

	Unit	S1
Temperature		35.6
PH		10.12
Electric Conductivity	μ S/cm	1330
Turbidity	NTU	51.8
Oil content	mg/l	0.92
BOD	mg/l	222
COD	mg/l	325
DO	mg/l	5.3
SS	mg/l	62
Total Nitrogen	mg/l	0.7
Residual Chlorine	mg/l	Trace
SO <sub>4</sub>	mg/l	214.6
Cyanogen	mg/l	

## **(6) Study on Wastewater Treatment Facility**

The results of the examination by Danang Textile Co. in 1999 are as follows.

### **1) Design condition**

Production :	Dyeing fabric	23,000,000 m <sup>2</sup> /year
Wastewater Volume :		25 m <sup>3</sup> /day
Wastewater Quality :	PH	9.3 ~ 10.0
	BOD	140 ~ 200mg/l
	COD	180 ~ 320mg/l
	SS	150 ~ 160 mg/l

Treatment methods : Coagulating sedimentation, Biological treatment

### **2) Investment Cost**

Table 7 shows the investment cost of the wastewater treatment facility.

## **5. Countermeasures for Improvement**

### **5.1 Countermeasures for Production Technology Improvement**

#### **(1) Current Problems**

- a. Shuttle type weaving machines are very old and not very efficient.
- b. The exchange of shuttles is done manually, so that the machines must be stopped when shuttles are exchanged. This cause the quality of the fabric to be bad as an unevenness of tension occurs.
- c. The maintenance of the soft cheese winders is very poor and the winders are operating without some parts.
- d. There is a lot of steam leakage from the pipe lines.
- e. No countermeasure for energy saving have been adopted, including the recovery of steam condensate.
- f. The liquid ratio is high at 1:10 ~ 1:12 for the liquid flow type machines.

#### **(2) Countermeasures**

- a. Automatic shuttle change type weaving machines should be introduced as early as possible.
- b. Sufficient maintenance of the weaving machines must be performed.
- c. The steam leakage problem at the dyeing plant should be solved immediately.
- d. Countermeasures for energy saving such as recovery of cooling water and heat recovery from the wastewater should be adopted.



- e. Low liquid ratio dyeing machines should be introduced when the number of machines are increased or renewed.

**Table 7 Investment Cost of a Wastewater Treatment Facility**

Items	Unit	Quantity	Unit price VND	Expenses VND
<b>a. Expenses for construction and equipment installation</b>				
Wastewater collection:				
- Sewerage: 300 x 400 BT	Mts	108	125,000	13,500,000
- Collection pits with screen	piece	6	1,250,000	7,500,000
Regulation tank: 3.5 3.5 x 1.8	m <sup>3</sup>	22	650,000	14,300,000
Coagulation tank: 1.55 x 1.5 x 1.8	m <sup>3</sup>	7	750,000	5,250,000
Sedimentation tank1: 2.7 x 3.3 x 3.0	m <sup>3</sup>	27	750,000	20,250,000
pH neutralization tank: 1.55 x 1.5 x 3.0	m <sup>3</sup>	7	750,000	5,250,000
Aeration + sedimentation 2: 3.3 x 4.8 x 3.0	m <sup>3</sup>	47.5	650,000	30,888,000
Sludge tank: 2.0 x 2.0 x 2.0	m <sup>3</sup>	8	650,000	5,200,000
Pump P1 and P2 (Italian-made)	piece	2	5,100,000	10,200,000
Pump after neutralization	piece	1	4,500,000	4,500,000
Platform	mts	12	450,000	5,400,000
Agitator; capacity: 2 HP	piece	2	7,500,000	15,000,000
Aerator; capacity 150 m <sup>3</sup> /h	piece	1	23,800,000	23,800,000
pH meter and metering pump	set	1	33,000,000	33,000,000
Pipeline and auxiliaries	-			15,000,000
Coagulant and neutralization agent tank	piece	3	150,000	450,000
<b>Sub Total (A)</b>				<b>209,488,000</b>
<b>b. Other expenses</b>				
Expenses for project management (including construction, examination and approval):		5 % x 209,488,000 = 10,500,000 VND.		
Expenses for designing and technology transfer:		3.5% x 209,488,000 = 7,330,000 VND		
Expenses for examination of design and budget estimation:		1.5% x 209,488,000 = 3,142,000 VND.		
<b>Sub Total (B)</b>				<b>20,972,000 VND</b>
<b>Grand total: (A)+ (B)</b>				<b>230,460,000 VND</b>

## **5.2 Countermeasures for Management Technology Improvement**

### **(1) Current Problems**

- a. The inside and outside of the dyeing plant are in disorder.
- b. Operation standardization and creation of operation manuals are not sufficient.
- c. Cost management, such as calculating unit consumption of raw materials and energy, is hardly being executed.

### **(2) Countermeasure**

- a. The “5S Movement” should be executed.
- b. Operation standardization is very important. Operation manuals should be prepared and placed in a position where operators can see them.
- c. Introduction of ISO9000 series should be promoted.
- d. Analysis of unit consumption and promotion of cost reduction program should be executed.
- e. As a first step, water and steam consumption levels need to be grasped.
- f. Maintenance function need to be reinforced.

## **5.3 Countermeasures for Wastewater Treatment**

They should install the following wastewater treatment system to improve the quality of the factory wastewater to within Vietnam standard values.

### **(1) Outline of the Wastewater Treatment System**


- a ) Volume of wastewater. : 400m<sup>3</sup>/day
- b ) Production capacity : 14,000 m/day (Dyeing fabric)
- c ) Treatment Methods : Activated sludge process & Coagulating Sedimentation
- d ) Investment Cost : 1,485,000,000VND

### **(2) Flow Diagram of Wastewater Treatment System**

Figure 4 shows the flow diagram of the wastewater treatment system.

### **(3) Investment Cost**

Table 8 shows the investment cost of the wastewater treatment system.



**Figure 4 Flow Diagram of Wastewater Treatment System**

**Table 8 Investment Cost of a Wastewater Treatment System**

<b>Items</b>	<b>Unit</b>	<b>Quantity</b>	<b>Unit Price VND</b>	<b>Expenses VND</b>
Equalization tank	m <sup>3</sup>	200	700,000	140,000,000
pH neutralization tank	m <sup>3</sup>	40	700,000	28,000,000
Aeration tank	m <sup>3</sup>	400	700,000	280,000,000
Sedimentation tank	m <sup>3</sup>	140	850,000	119,000,000
Coagulation tank	m <sup>3</sup>	100	850,000	85,000,000
Final tank	m <sup>3</sup>	20	700,000	14,000,000
Sludge tank	m <sup>3</sup>	20	700,000	14,000,000
Sewerage: 500 x 600	m <sup>3</sup>	50	300,000	15,000,000
<b>Sub Total 1(Construction)</b>				<b>695,000,000</b>
Wastewater Pump	piece	4	10,000,000	40,000,000
Aerator: capacity 150 m <sup>3</sup> /h	piece	1	30,000,000	30,000,000
pH meter and metering pump	set	1	40,000,000	40,000,000
Agitator: capacity: 2 HP	piece	4	7,500,000	30,000,000
Acid mixture apparatus	set	1	50,000,000	50,000,000
Coagulant mixture apparatus	set	2	50,000,000	100,000,000
Sludge dehydrating machine	set	1	200,000,000	200,000,000
Electricity	set	1	100,000,000	100,000,000
Pipeline and accessories	set	1	100,000,000	100,000,000
Other equipment				100,000,000
<b>Sub Total 2(Equipment)</b>				<b>790,000,000</b>
<b>Grand Total</b>				<b>1,485,000,000</b>

## 6. Recommended Countermeasure for Improvement

### 6.1 Short Term Countermeasures


No	Countermeasure	Expected Results
1	Installation of flow meters for water and steam	Grasp of unit consumption (Cost reduction)
2	Installation of a steam condensate recovery system	Energy savings
3	Installation of a cooling water recovery system	Energy savings
4	Installation of heat recovery system from the waste water	Energy savings
5	Operation standardization	Improvement of product quality and cost reduction
6	Reinforcement of the maintenance function	Increase in equipment capacity, productivity and products quality
7	Execution of the "5S Movement"	Elimination of waste-fullness, increase in worker's morale, improvement of product quality and a gaining in customer's trust

### 6.2 Mid and Long Term Countermeasures

No	Countermeasure	Expected Results
1	Installation of a wastewater treatment system	Improvement of wastewater quality
2	Modernization of the Color Kitchen	Improvement of the accuracy of scaling, prevention of contamination and improvement of the working environment
3	Acquisition of ISO9000 series certification	Improvement of product quality and cost reduction
4	Introduction of a cost reduction program	Cost reduction
5	Introduction of new dyeing technology such as the Rapid Dyeing Method	Energy saving, reduction of chemical consumption and improvement of wastewater quality

## 7. Proposed Implementation Schedule

The proposed implementation schedule is shown in Figure 5.



**Figure 5 Proposed Implementation Schedule for Pollution Prevention Countermeasure**

**Nam Dinh Textile Company**

Survey Date: 25 November 1999

9 &amp; 15 March 2000

**1. General****1.1 Profile**

Nam Dinh Textile Company is a state-owned company that was established in 1889 as a textile manufacturing company. The company profile and organization of Nam Dinh Textile Company is summarized in Table 1 and Figure 1.

**Table 1 Enterprise Profile**

Name of Company:	Nam Dinh Textile Company
Ownership:	State-owned
Address:	43 To Hieu Nam Dinh
Tel:	0350-849422-849749
Director:	NGO HUAN
Established:	1889
Corporate Capital:	
Number of Employees:	7,500
Main Products:	Yarns, Fabrics, Garments, Towels

**1.2 Business Status****1.2.1 Production**

Table 2 shows production and sales of the Company in 1999. 40% of products are exported to Japan, Sweden, Hong Kong, Norway, Korea, Germany, Netherlands, Russia and Poland.

**1.2.2 Debt**

Debts up to 31 December 1998:

- |                     |                            |
|---------------------|----------------------------|
| 1. Short-term debt: | 203.38 billions VND;       |
| 2. Long-term debt:  | 196.21 billions VND;       |
| 3. Interest:        | 3,409.00 billions VND; and |
| 4. Other debt:      | 46.54 billions VND         |
| Total:              | 480.22 billions VND        |

**Table 2 Production and Sales in 1999**

No.	Items	Unit	1999	
			Plan	Implementation (V.A.T Included)
I	Industrial production value	1,000VND	392,500	400,000
II	Turnover	1,000 VND	378,000	410,680
III	Export turnover	1,000 US\$	8,120	8,160
IV	Main product			
	- Various yarns	t	9,430	9,998
	- Sold yarns	t	4,069	6,323
	- Finished fabrics	1,000 m	15,619	14,626
	- Various kitchen towels	1,000 pcs	80,187	52,029
	- Garments	1,000 pcs	825	716
	(including subcontracted ones)		601	518
	( Company contracted garments)			
V	Payment to Government budget	Million VND	4,900	3,500
VI	Total employees	person	7,560	7,745
VII	Average income	VND/month	457,000	432,000
VIII	Profit (+), Loss (-)	Billion VND		

## 2. Production Technology

### 2.1. Process

Figures-2 and 3 show a simplified block flow diagram of the factory and a block flow diagram of the dyeing process, respectively.

Table 3 shows the operating condition of the dyeing process.

### 2.2 Future Plan

- (1) Installation of a Wastewater Treatment system

## 3. Management Technology


Table 4 shows Unit Consumption of Raw Materials and Utilities.




**Table 3 Operating Condition of Dyeing Process**

(1) Continuous Process			
Step	Chemicals	Temperature	Retention Time
Singeing	2-4 burners, by Petro	95-100	
Washing			
De-sizing	By Enzyme	70-80	6-7 hours
Washing			
Scouring	NaOH, Na <sub>2</sub> CO <sub>3</sub> and Others	100	90 min
Washing			
Bleaching	H <sub>2</sub> O <sub>2</sub> , Na <sub>2</sub> SiO <sub>3</sub> and Others	100	60 min
Washing			
Mercerizing	NaOH and Others		
Washing	H <sub>2</sub> SO <sub>4</sub> ,		
Pdding(Cotton)	Reactive Dye, Urea, Na <sub>2</sub> CO <sub>3</sub> ,		
(Cotton/Polyester)	Ractive/Disaperse Dye, Urea, Acetic Acid, Na <sub>2</sub> CO <sub>3</sub> ,Others		
Infra-red Drying			
Hot Flue		170	50-60 min
Washing			
Drying			
(2) Jigger			
Step	Chemicals	Temperature	Retention Time
Scouring (M=1/5)	NaOH, Na <sub>2</sub> CO <sub>3</sub> , Others	100	
Washing (M=1/5)			
Bleaching (M=1/5)	NaClO, H <sub>2</sub> O <sub>2</sub> , NaOH, Na <sub>2</sub> SiO <sub>3</sub> ,	95	
Washing (M=1/5)			
Dyeing (M=1/3) Vat Reactive Sulfur Directive	NaOH, Na <sub>2</sub> CO <sub>3</sub> , Na <sub>2</sub> S <sub>2</sub> O <sub>4</sub> , H <sub>2</sub> SO <sub>4</sub> , Others		
Washing (M=1/5)			


(Remark) M:Liquid Ratio



**Figure 1 Organization system**



**Figure 2 Simplified Block Flow Diagram**



**Figure 3 Process Flow Diagram**

**Table 4 Unit Consumption of Raw Materials and Utilities**

<b>No.</b>	<b>Materials</b>	<b>Production/year</b>	<b>Expenses</b>
<b>1</b>	<b>Yarn</b>		
1-1	Cotton fibers	6,268 tons	131,284 millions VND
1-2	Manmade fibers	3,163 tons	33,717 millions VND
1-3	Water	434,632 m <sup>3</sup>	131 millions VND
1-4	NH3	960 kg	9 millions VND
1-5	Electricity	35,025,776 kWh	25,503 millions VND
1-6	Grease and oil		458 millions VND
<b>2</b>	<b>Fabrics and towel</b>		
2-1	Yarns	3,954 tons	
2-2	Sizing agents	46 tons	
2-3	Electricity	5,576,088 kWh	4,059 millions VND
2-4	Water	310,000 m <sup>3</sup>	93.6 millions VND
<b>3</b>	<b>Dyeing</b>		
3-1	Grey fabrics	9,600,000 meters	
3-2	Grey towels	62,300,000 pieces	
3-3	Dyes	36 tons	
3-4	Detergents	508 tons	
3-5	Auxiliaries	870 tons	
3-6	Water	1,600,000 m <sup>3</sup>	483.2 millions VND
3-7	Electricity	2,688,912 kWh	1,957 millions VND
3-8	FO	378,000 litters	
<b>4</b>	<b>Steaming</b>		
4-1	Coals	17,157 tons	
4-2	FO	427,000 litters	
4-3	Water	333,600 m <sup>3</sup>	102.6 millions VND

#### **4. Industrial Wastewater Treatment and Discharge**

##### **(1) Outline**

1. The volume of wastewater is very high at 7,000 m<sup>3</sup>/day. Furthermore, pollutant materials, such as PH, SS, BOD, and COD, exceed the environmental standards in Vietnam.
2. There is no wastewater treatment facility, and the company needs to improve the present condition because pollution problems are already occurring.
3. For their future plans, the company is complementary, having a wastewater treatment facility. However, they do not know when will be realize this plan due to a lack of financing.

## (2) Sampling Points in November 1999

Wastewater samples were taken at following spots for analysis in this study.

Date: 25 November 1999

S1 : At Scouring m/c( washing water of the 3 rd tank )

S2 : At Scouring m/c( washing water after scouring )

S3 : At Bleaching m/c(washing water after bleaching)

S4 : At Scouring m/c( washing water of the 1st tank)

## (3) Results of Wastewater Analysis in November 1999

Wastewater qualities analyzed by Hanoi University Civil Engineering Center of Environment (CEETIA) are shown in Table 5.

**Table 5 Wastewater Quality in November 1999**

	Unit	S1	S2	S3	S4
Temperature		65.8	49.9	56	63.5
PH		10.6	10.66	8.64	10.6
Electric Conductivity	μ S/cm	4650	4970	530	9970
Turbidity	NTU	123	302	39	376
Oil content	mg/l	0.05	0.04	0.07	0.09
BOD	mg/l	797.3	1050	559.7	910.8
COD	mg/l	1555	3240	589	3325
DO	mg/l	5.4	2.52	4.1	4.7
SS	mg/l	138	320	46	384
Total Nitrogen	mg/l	8.12	9.6	10.8	5.5
Residual Chlorine	mg/l	Trace	Trace	Trace	Trace
SO <sub>4</sub>	mg/l	806.7	932.4	193.8	1232.2
Cyanogen	mg/l	0	0	Trace	Trace

## (4) Sampling Points of in March 2000

Wastewater samples were taken at the following spots for analysis in this study.

Date: 15 March 2000

S1 : At the outlet of continuous dyeing m/c : Composite Sampling

Sampling time: 11:10, 14:00, 14:30, 15:00

S2 : Supply water for dyeing process : Sampling time: 15:40

## (5) Results of Wastewater Analysis in March 1999

Wastewater qualities analyzed by Hanoi University Civil Engineering Center of Environment (CEETIA) are shown in Table 6.

**Table 6 Wastewater Quality in March 1999**

	Unit	S1	S2
Temperature		31.6	22.8
PH		9.51	7.85
Elec. Conductivity	μ S/cm	501	189
Turbidity	NTU	4	0
Oil content	mg/l	Trace	0
BOD	mg/l	97	9.64
COD	mg/l	154	14
DO	mg/l	4.04	6.28
SS	mg/l	7	1
Total Nitrogen	mg/l	0.5	1.2
Residual Chlorine	mg/l	Trace	Trace
SO <sub>4</sub>	mg/l	18	21
Ca	mg/l		33.2
Fe	mg/l		0.2
Mg	mg/l		6.7
CaCO <sub>3</sub>	mg/l		83

**(6) Study on Wastewater Treatment Facility**

The results of the examination by NamDinh Textile Co. in 1998 is as follows:

**1) Design condition**

Production :    Yarns:            10,000 tons/year  
                      Fabrics:        40,000,000 m/year  
                      Garments:    1,500,000 items/year

Wastewater Volume :            9,600 m<sup>3</sup>/day

Wastewater Quality :

PH                    4 ~ 9  
BOD                 120 ~ 440 mg/l  
COD                 110 ~ 360 mg/l  
SS                    100 mg/l

Treatment Methods :    Filtration, Biochemical Treatment, Disaffection

**2) Investment Cost**

Table 7 shows the investment cost of the wastewater treatment system.

**Table 7 Investment Cost of Wastewater Treatment Facility**

<b>Items</b>	<b>Cost US\$</b>
To purchase a wastewater treatment plant made overseas	2,500,000
Transportation and Insurance cost to Hai phong Port	52,000
Cost for manufacturer experts to install equipment	54,000
Other expenditures for project management, designing, construction materials and construction, transportation from Hai phong port, workers' training	1,400,000
<b>Total</b>	<b>4,060,000</b>

## **5. Countermeasures for Improvement**

### **5.1 Countermeasures for Production Technology Improvement**

#### **(1) Current Problems**

- a. There is a lot of steam leakage from the pipe line.
- b. No countermeasures for energy saving have been adopted, but steam condensate is being recovered.
- c. Laboratory facilities and the color kitchen system are not properly prepared.
- d. The data on the quality of supply water is too at low a level. If this data is actual, it is a very important problem for the dyeing process.

#### **(2) Countermeasures**

- a. The steam piping should be repaired.
- b. Countermeasure for energy saving, such as recovery of cooling water and heat recovery from the wastewater, should be adopted.
- c. More suitable laboratory facilities should be prepared. (Now in planning)
- d. The color kitchen system should be modernized.
- e. The data on the quality of supply water should be checked. If the data is correct, the water treatment system should be completed.

### **5.2 Countermeasures for Management Technology Improvement**

#### **(1) Current Problems**

- a. The company started its operation a long time ago and it is now quite a large-scale plant. Accordingly, the facilities have a mixture of old and new machines, and these are divided into good and bad ones in terms of productivity and quality.
- b. Regarding the spinning and weaving facilities, the management of old machines



is not good.

- c. New continuous dyeing facilities, which were installed about 4 years ago, are in operation, and they are producing good results in their own way. However, their process control is at a very low level and it seems that these good facilities have not produced good efficient results in terms of quality.
- d. Operation standardization of and preparation of operation manuals are inefficient.
- e. Cost management, such as calculating unit consumption of the raw materials and energy, is hardly carried out.
- f. Maintenance is inefficient, not only for old dyeing facilities, but also for new ones.
- g. Most of the old dyeing facilities have suspended operations and their surroundings are dirty.
- h. The color kitchen is very dirty and in disorder.

## **(2) Countermeasures**

- a. The ISO9000 certification program, which has just started for the dyeing process, should be strongly promoted. The experience gained from this program should be made the most of, and transfer to other processes.
- b. Unnecessary facilities should be removed and the inside of the factory should be kept clean and in good order.
- c. The maintenance function for facilities should be reinforced.
- d. Operation standardization is very important. Operation manuals should be prepared and place in a position where operators can see them.
- e. An analysis of unit consumption and promotion of a cost reduction program should be executed.
- f. As a first step, water and steam consumption need to be grasped.
- g. The “5S Movement” should be executed.

## **5.3 Countermeasures for Wastewater Treatment**

The company should install the following wastewater treatment system in order to improve the quality of the factory wastewater to within Vietnam standard value.

### **(1) Outline of the Wastewater Treatment System**

- a ) Volume of wastewater. : 4,800 m<sup>3</sup>/day
- b ) Production capacity : 140,000 m/day (Dyeing fabric)


- c) Treatment Methods : Activated sludge process & Coagulating Sedimentation
- d) Investment Cost : 10,668,000,000 VND

**(2) Flow Diagram of the Wastewater Treatment System**

Figure 4 shows the flow diagram of the wastewater treatment system.

**(3) Investment Cost**

Table 8 shows the investment cost of the wastewater treatment system.



**Figure 4 Flow Diagram of Wastewater Treatment System**

**Table 8 Investment Cost of Wastewater Treatment System**

<b>Items</b>	<b>Unit</b>	<b>Quantity</b>	<b>Unit price VND</b>	<b>Expenses VND</b>
Equalization tank	m <sup>3</sup>	2,400	700,000	1,680,000,000
pH neutralization tank	m <sup>3</sup>	400	700,000	280,000,000
Aeration tank	m <sup>3</sup>	4,800	700,000	3,360,000,000
Sedimentation tank	m <sup>3</sup>	1,600	850,000	1,360,000,000
Coagulation tank	m <sup>3</sup>	1,200	850,000	1,020,000,000
Final tank	m <sup>3</sup>	70	700,000	49,000,000
Sludge tank	m <sup>3</sup>	70	700,000	49,000,000
Sewerage: 500 x 600	m <sup>3</sup>	300	300,000	90,000,000
<b>Sub Total 1(Costruction)</b>				<b>7,888,000,000</b>
Wastewater Pump	piece	4	10,000,000	40,000,000
Aerator; capacity 150 m <sup>3</sup> /h	piece	7	30,000,000	210,000,000
pH meter and metering pump	set	1	40,000,000	40,000,000
Agitator; capacity: 2 HP	piece	4	7,500,000	30,000,000
Acid mixture apparatus	set	1	200,000,000	200,000,000
Coagulant mixture apparatus	set	2	200,000,000	400,000,000
Sludge dehydrating machine	set	1	900,000,000	900,000,000
Electricity	set	1	260,000,000	260,000,000
Pipeline and accessories	set	1	400,000,000	400,000,000
Other equipment				300,000,000
<b>Sub Total 2(Equipment)</b>				<b>2,780,000,000</b>
<b>Grand Total</b>				<b>10,668,000,000</b>

## 6. Recommended Countermeasure for Improvement

### 6.1 Short Term Countermeasures


No	Countermeasure	Expected Results
1	Installation of flow meters for water and steam	Grasp of unit consumption (Cost reduction)
2	Installation of a cooling water recovery system	Energy savings
3	Installation of heat recovery system from the waste water	Energy savings
4	Increased substantiality of the laboratory (in planning)	Improvement of product quality and cost reduction
5	Acquisition of ISO9000 series certification	Improvement of product quality and cost reduction
6	Reinforcement of the maintenance function	Increase of equipment capacity, productivity and product quality
7	Execution of the "5S Movement"	Elimination of waste-fullness, increase in of worker's morale, improvement of product quality and a gain of customer's trust

### 6.2 Mid and Long Term Countermeasures

No	Countermeasure	Expected Results
1	Installation of a wastewater treatment system	Improvement of wastewater quality
2	Modernization of the Color Kitchen	Improvement of the accuracy of scaling, prevention of contamination and improvement of the working environment
3	Introduction of a cost reduction program	Cost reduction

## 7. Proposed Implementation Schedule

The proposed implementation schedule is shown in Figure 5.



**Figure 5 Proposed Implementation Schedule for Pollution Prevention Countermeasure**



## CASE STUDY T-05

### Nam Dinh Silk Company

Survey Date: 26 November 1999

13 & 14 March 2000

#### 1. General

##### 1.1 Profile

Nam Dinh Silk Company is a state-owned company that was established in 1959 as a textile manufacturing company. The company profile and organization of Nam Dinh Silk Company is summarized in Table 1 and Figure 1.

**Table 1 Enterprise Profile**

Name of Company:	Nam Dinh Silk Company
Ownership:	State-owned
Address:	N 4 Ha Huy Tap Nam Dinh City
Tel:	0350-849622-849497
Director:	
Established:	1959
Corporate Capital:	
Number of Employees:	1,700
Main Products:	Yarns, Fabrics

##### 1.2 Business Status


###### 1.2.1 Production

Table 2 shows production and sales of the Company in 1998.

Some products are exported to France, Italy, Japan, Germany, etc.

**Table 2 Production and Sales in 1998**

No.	Products	Production	Turnover
1	Fabric	3,367,000 m	104,465 million VND
2	Yarn	441,000 kg	8,759 million VND
	Total		113,204 million VND



**Figure-1 Organization of NAM DINH SILK Company**



### 1.2.2 Debt

Total debt with Banks: 40,037,373,729 VND

Short-term debt (including VND and US\$): 14,277,640,039 VND

Long-term debt: (including VND and US\$): 17,820,112,967 VND

Long-term (including VND and US\$): 6,435,223,640 VND

Short term debt: (US\$) 1,504,397,033 VND

### 2. Production Technology


Figure 2 and 3 show the simplified block flow diagram of the factory and the block flow diagram of the dyeing process, respectively.

### 3. Management Technology


Table 3 shows unit consumption of the raw materials and utilities.

**Table 3 Unit Consumption of Raw Materials and Utilities**

No.	Materials	Production	Expenses (VND)
1	Fabrics	5,585,000 m <sup>2</sup>	
2	Yarns	500 t	
3	Disperse dyes	25,000 kg	
4	Vat dyes	9,750 kg	
5	NaOH	27,500 kg	
6	H <sub>2</sub> O <sub>2</sub>	40,000 kg	
7	Salt	3,800 kg	
8	Water	600,000 m <sup>3</sup>	1,170,000,000 VND
9	FO	83,685 kg	1,631,837,500 VND
10	Coal	4,083 tons	1,224,900,000 VND
11	Electricity	5,358,500 kWh	4,340,385,000 VND



**Figure 2 Simplified Block Flow Diagram**



**Figure 3 Process Flow Diagram**

#### 4. Industrial Wastewater Treatment and Discharge

##### (1) Outline

1. The volume of wastewater is large at 1,600 m<sup>3</sup>/day, and BOD, COD and SS levels are high;
2. No wastewater treatment system has been installed;
3. Wastewater is discharged to the city sewage directly.

##### (2) Sampling Points in November 1999

Wastewater samples were taken at the following spots for analysis.

Date: 26 November 1999

- S1 : At Bobbin dyeing m/c ( wash water after dyeing)
- S2 : At Bobbin dyeing m/c ( wash water after scouring)
- S3 : At Jet dyeing m/c ( wash water after scouring)
- S4 : Waste water from the dying factory (to city sewage)

##### (3) Results of Wastewater Analysis in November 1999

Wastewater qualities analyzed by Hanoi University Civil Engineering Center of Environment (CEETIA) are shown in Table 4.

**Table 4 Wastewater Quality in November 1999**

	Unit	S1	S2	S3	S4
Temperature		47	70.3	63	35.3
PH		8.14	3.7	4.25	8.93
Electric Conductivity	μ S/cm	230	270	1190	370
Turbidity	NTU	1.8	8.2	757	13.5
Oil content	mg/l	0.01	0.01	0.02	0.02
BOD	mg/l	60.2	132	644.2	522.7
COD	mg/l	83.8	880	2550	665
DO	mg/l	3.9	3.5	3.1	4.2
SS	mg/l	2.8	9.5	780	17.3
Total Nitrogen	mg/l	4.2	4.9	5.9	9.2
Residual Chlorine	mg/l	0.35	Trace	Trace	Trace
SO <sub>4</sub>	mg/l	62.4	28.2	100.4	91.2
Cyanogen	mg/l	0.01	Trace	Trace	Trace

#### (4) Sampling Points in March 2000

Wastewater samples were taken at following spots for analysis in this study.

Date: 13 & 14 March 2000

S1 : At the outlet of the dyeing factory : Composite Sampling 13 Mar.

Sampling time: 13:50, 14:05, 14:20, 14:35, 14:50, 15:05, 15:20, 15:35

S2 : Supply water after Ion treatment for calendar m/c : Sampling 14 Mar .

Sampling time: 13:38

S3 : Supply water for the dyeing process : Sampling time: 13:50

S4: Supply water after sand filtration for bobbin dyeing : Sampling time: 13:56

S5: At the outlet of the dyeing factory : Composite Sampling 14 Mar.

Sampling time: 10:00 10:15 10:30 10:45 11:00 11:15 11:30 14:00  
14:15 14:30 14:45 15:00

#### (5) Results of Wastewater Analysis in March 2000

Wastewater qualities analyzed by Hanoi University Civil Engineering Center of Environment (CEETIA) are shown in Table 5.

**Table 5 Wastewater Quality in March 2000**

	Unit	S1	S2	S3	S4	S5
Temperature		25.3	28.8	23.5	21.1	24.9
pH		6.67	8.28	8.3	8.09	9.53
Elec. Conductivity	μ S/cm	510	960	890	181	313
Turbidity	NTU	48	2	2	1	10
Oil content	mg/l	Trace	0	0	0	Trace
BOD	mg/l	49.2				135
COD	mg/l	74				360
DO	mg/l	10.7	3.56	6.85		4.28
SS	mg/l	62	6	4	3	19
All Nitrogen	mg/l	2.82	0.15	0.12	0.09	3.4
Residual Chlorine	mg/l	0.29	Trace	Trace	Trace	0.31
SO <sub>4</sub>	mg/l	38	1.88	1.32	0.59	46
Ca <sup>2+</sup>	mg/l		4.4	30.8	40.8	26.4
Fe <sup>2+</sup>	mg/l		0.77	0.13	0.21	0.41

#### (6) Study on Wastewater Treatment Facility

The results of examination by Namdinh Silk Co. in 1998 are as follows:

##### 1) Design conditions

Production: Yarns: 500 tons/year {average count (Ne):, 45/1}

Woven fabrics: 6,000,000 m<sup>2</sup>/year {average fabric weight: 260 g/m<sup>2</sup> }  
Dyeing fabrics 8,000,000 m<sup>2</sup>/year  
Garments: 120,000 shirts/year  
Wastewater Volume : 1,500 m<sup>3</sup>/day  
Treatment Methods : Coagulating Sedimentation  
Setting Area : 4,500 m<sup>3</sup>

## **2) Investment cost**

The investment cost of the wastewater treatment system is estimated as follows;

- 1- Collecting tank of 100 m<sup>3</sup>
- 2 - Sedimentation tank of 300 m<sup>3</sup>
- 3- Reaction tank of 200 m<sup>3</sup>
- 4- Overflow tank of 300 m<sup>3</sup> with filter
- 5- Separation tank of 300 m<sup>3</sup>

**Total : 100,000,000 VND**

## **5. Countermeasures for Improvement**

### **5.1 Countermeasures for Production Technology Improvement**

#### **(1) Current Problems**

- a. The roller part of the spinning machines is an outdated type that does not adopt use of a large packaging system that causes the evenness of yarns to be bad.
- b. A hand-binding type RT Winder is used for yarn winding, because it does not have a splicer system, and it does not satisfy export standards.
- c. The maintenance of machines is poor. Especially, card wire damage is conspicuous at the spinning plant.
- d. There is a lot of steam leakage in pipe lines.
- e. No countermeasures for energy saving have been adopted, but of steam condensate is recovered.
- f. The liquid ratio for jet type dyeing machines is high at 1:10 ~ 1:12.
- g. The laboratory facilities and the color kitchen system are not properly prepared.

#### **(2) Countermeasures**

- a. The roller parts of the spinning machines should be changed to a new type.
- b. The splicing system should be equipped with hand-binding type winders.
- c. It is necessary to change card wires deliberately otherwise it influences the quality of products greatly.

- d. The steam leakage problem should be solved.
- e. Countermeasure for energy saving, such as recovery of cooling water and heat recovery from the wastewater, should be adopted.
- f. Low liquid ratio dyeing machines (as 1:6) should be introduced when there is a chance to increase or renew machines.
- g. More suitable laboratory facilities should be prepared.
- h. The color kitchen system should be modernized.

## **5.2 Countermeasures for Management Technology Improvement**

### **(1) Current Problems**

- a. Product diversification is the major problem for management, but it is needed to determine production items which can utilize existing facilities efficiently.
- b. Generally, the cleaning, arrangement and tidying of the facilities are insufficient and the maintenance of production facilities is poor.
- c. In the dyeing process, the reproduction ratio is very high at 20 %. This means that quality control is inefficient.
- d. In the dyeing process, water consumption is too high.
- e. The color kitchen is very dirty and in disorder.
- f. Operation standardization of and make-up of operation manuals are inefficient.
- g. Cost management, such as calculating unit consumption of the raw materials and energy, is hardly carried out.
- h. The maintenance of facilities is inefficient.

### **(2) Countermeasures**

- a. Production technology which meets the markets needs should be introduced.
- b. Analysis of unit consumption and promotion of a cost reduction program should be executed.
- c. As a first step, water and steam consumption level should be grasped.
- d. Operation manuals should be prepared and place in a position where operators can see them.
- e. The "5S Movement" should be executed.
- f. ISO9000 series should be introduced.
- g. The maintenance function should be reinforced.

### 5.3 Countermeasures for Wastewater Treatment

The company should install the following wastewater treatment system in order to improve the quality of the factory wastewater to within Vietnam standard value.

#### (1) Outline of the Wastewater Treatment System

- a ) Volume of wastewater. : 1,500 m<sup>3</sup>/day
- b ) Production capacity : 40,000 m/day (Dyeing fabric)
- c ) Treatment Methods : Activated sludge process & Coagulating Sedimentation
- d ) Investment Cost : 4,111,000,000 VND

#### (2) Flow Diagram of the Wastewater Treatment System

Figure-4 shows the flow diagram of the wastewater treatment system.




Figure 4 Flow Diagram of Wastewater Treatment System



### (3) Investment Cost

Table 6 shows the investment cost of the wastewater treatment system.

**Table 6 Investment Cost of wastewater treatment system**

Items	Unit	Quantity	Unit price VND	Expenses VND
Equalization tank	m <sup>3</sup>	750	700,000	525,000,000
pH neutralization tank	m <sup>3</sup>	120	700,000	84,000,000
Aeration tank	m <sup>3</sup>	1,500	700,000	1,050,000,000
Sedimentation tank	m <sup>3</sup>	500	850,000	425,000,000
Coagulation tank	m <sup>3</sup>	400	850,000	340,000,000
Final tank	m <sup>3</sup>	30	700,000	21,000,000
Sludge tank	m <sup>3</sup>	30	700,000	21,000,000
Sewerage: 500 x 600	m <sup>3</sup>	150	300,000	45,000,000
<b>Sub Total 1 (Costruction)</b>				<b>2,511,000,000</b>
Wastewater Pump	piece	4	10,000,000	40,000,000
Aerator; capacity 150 m <sup>3</sup> /h	piece	3	30,000,000	90,000,000
pH meter and metering pump	set	1	40,000,000	40,000,000
Agitator; capacity: 2 HP	piece	4	7,500,000	30,000,000
Acid mixture apparatus	set	1	100,000,000	100,000,000
Coagulant mixture apparatus	set	2	100,000,000	200,000,000
Sludge dehydrating machine	set	1	500,000,000	500,000,000
Electricity	set	1	200,000,000	200,000,000
Pipeline and accessories	set	1	200,000,000	200,000,000
Other equipment				200,000,000
<b>Sub Total 2(Equipment)</b>				<b>1,600,000,000</b>
<b>Grand Total</b>				<b>4,111,000,000</b>

## 6. Recommended Countermeasure for Improvement

### 6.1 Short Term Countermeasures


No	Countermeasure	Expected Results
1	Installation of flow meters for water and steam	Grasp of unit consumption (Cost reduction)
2	Installation of a cooling water recovery system	Save energy
3	Installation of heat recovery system from the waste water	Save energy
4	Operation standardization	Improvement of products quality, Cost reduction
5	Reinforcement of maintenance function	Upkeep of equipment capacity, productivity and products quality
6	Execution of the "5S Movement"	Elimination of waste-fullness, Lift up of worker's morale, Improvement of products quality, Gaining of customer's trust

### 6.2 Mid and Long Term Countermeasures

No	Countermeasure	Expected Results
1	Installation of a wastewater treatment system	Improvement of wastewater quality
3	Modernization of the Color Kitchen	Improvement of the accuracy of scaling, Prevention of contamination, Improvement of the working environment
4	Acquisition of ISO9000 series certification	Improvement of product quality, Cost reduction
5	Introduction of a cost reduction program	Cost reduction
6	Introduction of low liquid ratio type dyeing machines	Reduction of wastewater volume, Reduction of chemicals consumption, Improvement of productivity, Possibility to produce high value-added products
7	Introduction of new dyeing technology, such as the Rapid Dyeing Method	Save energy, Reduction of chemicals consumption, Improvement of wastewater quality

## 7. Proposed Implementation Schedule

The proposed implementation schedule is shown in Figure 5.



**Figure 5 Proposed Implementation Schedule for Pollution Prevention Countermeasure**



**Duc Giang Garment Export and Import Company**

Survey Date: 19 November 1999

**1. General****1.1 Profile**

Duc Giang Garment Export and Import Company is a state-owned company that was established in 1989 as a garment manufacturing company. The company profile of Duc Giang Garment Export and Import Company is summarized in Table 1.

**Table 1 Enterprise Profile**

Name of Company:	Duc Giang Garment Export and Import Company
Ownership:	State-owned
Address:	Thi Tran Duc Giang, Hanoi
Tel:	04-8271621
Director:	
Established:	1989
Corporate Capital:	
Number of Employees:	2,800
Main Products:	Jackets, Shirts

**1.2 Business Status****1.2.1 Production**

Table 2 shows production and sales of the company in 1998.

More than 95% of products are exported to the EU, Poland, Czech, Hong-Kong, Japan, etc.

**Table 2 Production and Sales in 1998**

No.	Items	Production	Turnover (1000VND)
1	Jackets	10,536	797,785
2	Shirts	71,812	1,618,565
3	Other items	20,124	457,136
	<b>Total</b>	<b>102,472</b>	<b>2,863,506</b>


### 1.2.2 Debt

Unknown

## 2. Production Technology

### 2.1 Process

The process flow of the factory is shown in Figure 1.



**Figure 1 Process Flow of the Factory**

### 2.2 Unit Consumption

The unit consumption of raw materials and utilities is shown in Table 3.

**Table 3 Unit Consumption of Raw Materials and Utilities**

No.	Materials	Production (tons)	Expenses
<b>1</b>	<b>Jackets</b>		
1-1	Fabrics	55.844	
1-2	Nonwoven interlining	23.933	
1-3	Auxiliaries	15.955	
<b>2</b>	<b>. Shirts</b>		
2-1	Fabrics	32.171	
2-2	Auxiliaries	16.500	
2-3	Softener	0.236	
<b>3</b>	<b>Water and Power</b>		
3-1	Water	97,200 m <sup>3</sup> /year	
3-2	FO	21 tons/year	
3-3	Electricity	2,500,000 kWh/year	

### 2.3 Future Plans

Unknown

### **3. Management Technology**

- (1) The factory is very clean and in good order.
- (2) The washing plant is especially well organized, neat, tidy, and clean and there is no problem with 5S.
- (3) The facilities are well maintained.
- (4) The operation is very simple, so there is no problem with operation management.

### **4. Industrial Wastewater Treatment and Discharge**

- (1) Flow Rate: 70 m<sup>3</sup>/day
- (2) Quantity: SS is the main pollutant, besides softener and enzymes.
- (3) Treatment Facility: Only two sedimentation tanks are installed.
- (4) Sampling:

Wastewater samples were taken at following spots for analysis in this study.

Date: 19 November 1999

S1 : Supply water to the washing factory

S2 : Wastewater from the washing factory ( to the sedimentation tank)

S3 : At the sedimentation tank

S4 : Discharged wastewater from the sedimentation tank (to city sewage)

- (5) Wastewater Quality

Wastewater qualities analyzed by Hanoi University Civil Engineering Center of Environment Engineering of Towns and Industrial Areas (CEETIA) are shown in Table 4.

### **5. Recommended Countermeasure for Improvement**

- (1) It will be beneficial for the company to maintain its facility arrangement and tidiness from now on.
- (2) The company needs to prepare operation manuals.
- (3) In case that the quality of wastewater gets worse due to increased softener use or something similar, it will more efficient if bad quality wastewater is separated and small treatment facility is set up.

**Table 4 Wastewater Quality in November 1999**

	Unit	S1	S2	S3	S4
Temperature		28.1	30.3	30.2	36.4
pH		7.1	7.45	7.28	7.8
Electric Conductivity	μ S/cm	310	390	270	400
Turbidity	NTU	4.2	10.8	7.6	8.2
Oil content	mg/l	0	0.02	0.01	0.03
BOD	mg/l	5.7	40.7	38.2	33.4
COD	mg/l	15	55	47	52
DO	mg/l	5.7	1.7	1.6	9.8
SS	mg/l	4.9	12.1	10.2	11
Total Nitrogen	mg/l	4.9	7.9	8.1	8.5
Residual Chlorine	mg/l	20.6	13.4	22.0	4.96
SO <sub>4</sub>	mg/l	18.4	63.4	39.6	4.8
Cyanogen	mg/l	Trace	0.02	0.02	0.03



**Vinh Phu Textile Company**

Survey Date: 22 November 1999

**1. General****1.1 Profile**

Vinh Phu Textile Company is a state-owned company that was established in 1972 as a textile manufacturing company. The company profile of Vinh Phu Textile Company is summarized in Table 1.

**Table 1 Enterprise Profile**

Name of Company:	Vinh Phu Textile Co
Ownership:	State-owned
Address:	108 Hung Vuong Str. Viet Tri City Phu Tho Pro.
Tel:	021-845886
Director:	
Established:	1972
Corporate Capital:	
Number of Employees:	2,000
Main Products:	Yarns, Fabrics and Garments of Polyester and cotton

**1.2 Business Status****1.2.1 Production**

Table 2 shows production and sales of the Company in 1998.

90% of products are made for the domestic market because the quality of their products is not so high.

**Table 2 Production and Sales in 1998**

No.	Items	Production	Turnover (VND)
1	Yarns	657 tons	19.118 billions
2	Fabrics	5,665,000 meters	49.547 billions
3	Garments	202,000 pieces	4.816 billions
4	Others		2.714 billions
	<b>Total</b>		<b>76.195 billions</b>


**1.2.2 Debt**

Debts to Commerce bank:	40,694,278,894 VND
Debt to Government credit:	<u>50,702,134,668 VND</u>
Total	91,396,413,562 VND

## 2. Production Technology

### 2.1 Process

The Process flow of the factory is shown in Figure 1.



**Figure 1 Process Flow of the Factory**

### 2.2 Unit Consumption

The unit consumption of raw materials and utilities is shown in Table -3.

### 2.3 Future Plans

Unknown

## 3. Management Technology

- (1) The roller part of China-made machines, which account for 70% of spinning machines, is outdated. The introduction of a large packaging system has been delayed, so the evenness of yarns is not good.
- (2) The width of the fabric made by 500 China-made weaving machines is narrow and its production rate is low because its applications are limited.
- (3) The China-made facilities can process only narrow-width fabric and the printing facilities have the same specifications. This is the most important problem in this factory.
- (4) The inside of the plant is not well organized, is untidy, and is not cleaned well. The maintenance of the production lines is very poor.
- (5) The spinning process especially, lacks process management and there are many problems with operation control.
- (6) There are no improvement activities, such as a 5S campaign or QC activities, at the plant.
- (7) As the production rate of old machines and new machines is not balanced, there

are many suspended machines, and the new ones have not been given full scope to their ability yet.

- (8) Plant management and administration staff lack experience and knowledge for improving productivity and quality. It is inevitable to educate or train leaders and technicians, and also to have technical instruction from outside the company.

#### **4. Industrial Wastewater Treatment and Discharge**

- (1) A biological water treatment system has been installed.
- (2) The pH of wastewater is not controlled, so the efficiency of treatment is very low.
- (3) Sampling:

Wastewater samples were taken at the following spots for analysis in this study on 22 November 1999.

S1 : Wastewater from the spinning & weaving factory(to)

S2 : At the wastewater treatment system ( before biological treatment)

S3 : Discharged wastewater (to city sewage after biological treatment)

- (4) Wastewater Quality

Wastewater qualities analyzed by Hanoi University Civil Engineering Center of Environment Engineering of Towns and Industrial Areas (CEETIA) are shown in Table 4.

#### **5. Recommended Countermeasures for Improvement**

- (1) The highest priorities should be introduce a splicing method, which is the global standard in the spinning yarn business, to expand sales routes and raise the operation rate.
- (2) Full-automatic German winding machines are too expensive to invest in, so it is better to introduce cheaper Italian manual splicing machines.
- (3) pH of wastewater from the plant is high and it is not efficient for a biological system. Neutralization with acids at the mixing tank should be carried out.

**Table 3 Unit Consumption of Raw Materials and Utilities**

<b>No.</b>	<b>Material</b>	<b>Production</b>	<b>Expenses (VND)</b>
<b>1</b>	<b>Yarn production</b>		
1-1	Main materials (fibbers)	674.044 t	13,324,635,669
1-2	Auxiliaries		311,346,587
1-3	Water	11,247 m <sup>3</sup>	20,201,577
1-4	Electricity	2,091,082 kWh	1,512,458,879
1-5	Depreciation		664,732,836
1-6	Other expenses		1,437,460,735
1-7	Salary and Social insurance		1,221,732,213
<b>2</b>	<b>Fabric production</b>		
2-1	Main material (yarns)	1,124.568 t	32,571,383,738
2-2	Auxiliaries	66.778 t	591,443,692
2-3	Water	7,895 m <sup>3</sup>	14,500,324
2-4	Electricity	1,555,123 kWh	1,121,231,764
2-5	Depreciation		1,830,549,532
2-6	Other expenses		3,382,508,937
2-7	Salary and Social insurance		2,147,291,677
<b>3</b>	<b>Dyeing and printing production</b>		
3-1	Main materials(gray and dyed fabrics)	5,964,099 m	43,071,258,745
3-2	Dyes, chemicals, package materials	182.197 t	1,488,600,545
3-3	Water	212,160 m <sup>3</sup>	394,885,331
3-4	Electricity	362,445 kWh	261,758,140
3-5	Depreciation		439,845,033
3-6	Other expenses		2,472,792,137
3-7	Salary and Social insurance		402,635,551
<b>4</b>	<b>Steam production:</b>	<b>12,878 t</b>	
4-1	Main material(coal dust)	3,603.806 t	1,256,358,848
4-2	2. Water	245,179 m <sup>3</sup>	456,341,708
4-3	3. Coal	52.356 t	29,891,272
4-4	4. Electricity	365,964.7 kWh	264,299,771

**Table 4 Wastewater Quality in November 1999**

	Unit	S1	S2	S3
Temperature		24.7	24.7	23.6
pH		7.3	10.7	10.47
Electric Conductivity	μ S/cm	290	1880	1180
Turbidity	NTU	2.8	47.2	66.5
Oil content	mg/l	0.04	0.03	0.01
BOD	mg/l	16.5	116.4	132
COD	mg/l	21.5	151	158
DO	mg/l	2.4	3.8	2.75
SS	mg/l	5.8	51.7	73.5
Total Nitrogen	mg/l	19.1	18.5	18.7
Residual Chlorine	mg/l	Trace	Trace	Trace
SO <sub>4</sub>	mg/l	97.6	192	259.2
Cyanogen	mg/l	0.02	0.03	0.02



**Thang Long Garment Company**

Survey Date: 23 November 1999

**1. General****1.1 Profile**

Thang Long Garment Company is a state-owned company that was established in 1958 as a garment manufacturing company. The company profile of Thang Long Garment Company is summarized in Table 1.

**Table 1 Enterprise Profile**

Name of Company:	Thang Long Garment Company
Ownership:	State-owned
Address:	250 Minh Khai Str. Hanoi
Tel:	04-8623372
Director:	
Established:	1958
Corporate Capital:	
Number of Employees:	200
Main Products:	Jackets, Shirts, Trousers Jeans

**1.2 Business Status****1.2.1 Production**

Table 2 shows production and sales of the Company in 1998.

80% of products are exported to Taiwan, Hong Kong, Korea, etc.

**Table 2 Production and Sales in 1998**

No.	Products	Production	Turnover
1	Jackets	743,000 pcs	50,140 million VND
2	Shirts	141,000 pcs	2,866 million VND
3	Trousers	86,000 pcs	2,356 million VND
4	Jeans	216,000 pcs	10,522 million VND
5	Jeans Shirts	102,000 pcs	7,566 million VND
6	Others	254,000 pcs	5,476 million VND
	Total		78,881 million VND

**1.2.2 Debt**


20 billion VND with a foreign trading bank (Running Capital)

10 billion VND with an investment & development bank (Investment Capital)

## 2. Production Technology

### 2.1 Process

The Process flow of the factory is shown in Figure 1.



**Figure 1 Process Flow of the Factory**

### 2.2 Unit Consumption

The unit consumption of the raw materials and utilities is shown in Table 3.

### 2.3 Future Plans

Unknown

## 3. Management Technology

- (1) Due to the old age of the facilities, the thermometer doesn't function so workers control the temperature according to their senses. Other than that, water volume and chemical volume control are done irresponsibly and are wasted. Accordingly, such things influence the quality of products.
- (2) The company doesn't recover steam condensate from dryers, but discharges it as wastewater.
- (3) The inside of the plant is in confusion and untidy.
- (4) There are many empty beverage packs discharged in a sedimentation tank.
- (5) As gauges are not maintained well all operations are controlled by the sense of workers.



**Table 3 Unit Consumption of Raw Materials and Utilities**

<b>No.</b>	<b>Materials</b>	<b>Unit consumption</b>	<b>Expenses (VND/pieces)</b>
<b>1</b>	<b>Jackets:</b>		
1-1	Fabric	3 meters	60,000
1-2	Water	0.07 m <sup>3</sup>	105
1-3	Detergent	0.026 kg	187
1-4	Electricity	0.8 kWh	640
1-5	FO	0.8 kg	1,440
<b>2</b>	<b>Shirts:</b>		
2-1	Fabric	2 meters	32,000
2-2	Detergent	0.015 kg	108
2-3	Softener	0.01 kg	440
2-4	Whitening agent	0.001 kg	80
2-5	Acetic acid	0.001 kg	13
2-6	Electricity	0.5 kWh	400
2-7	FO	0.3 kg	540
2-8	Water	0.05 m <sup>3</sup>	75
<b>3</b>	<b>Jeans:</b>		
3-1	Fabric	2 meters	48,000
3-2	NaClO	1 litter	900
3-3	Oxalic acid	0.04 kg	308
3-4	H <sub>2</sub> O <sub>2</sub>	0.01 kg	165
3-5	Acetic acid	0.001 kg	13
3-6	Whitening agent	0.002 kg	160
3-7	Softener	0.02 kg	880
3-8	Stone	0.3 kg	1,000
3-9	Enzyme	0.01 kg	1,000
3-10	Water	0.08 m <sup>3</sup>	120
3-11	Electricity	0.7 kWh	560
3-12	FO	0.8 kg	1,440

**4. Industrial Wastewater Treatment and Discharge**

(1) Wastewater is discharged to a river after going through only two stage sedimentation pits.

(2) Sampling

Wastewater samples were taken at following spots for analysis in this study.

Date: 23 November, 1999

- S1 : At washing m/c ( Enzyme washing Stage-1)
- S2 : At washing m/c ( Enzyme washing Stage-2)
- S3 : At washing m/c ( Enzyme washing Stage-3)
- S4 : At washing m/c ( Enzyme washing Stage-4)
- S5 : Discharged waste water from the factory(to city sewage)
- S6 : At washing m/c ( Stone washing Stage-1)
- S7 : At washing m/c ( Stone washing Stage-2)
- S8 : At washing m/c ( Stone washing Stage-3)
- S9 : At washing m/c ( Stone washing Stage-4)

### (3)Wastewater Quality

Wastewater qualities analyzed by Hanoi University Civil Engineering Center of Environment Engineering of Towns and Industrial Areas (CEETIA) are shown in Table 4.

**Table 4 Wastewater Quality in November 1999**

	Unit	S1	S2	S3	S4	S5
Temperature		45.5	45.4	30.8	39	30.3
PH		7.4	7.94	7.28	4.32	6.09
Elec. Conductivity	μ S/cm	320	440	270	500	300
Turbidity	NTU	76.2	66.7	38.5	181	31.5
Oil content	mg/l	0.01	0.01	Trace	Trace	Trace
BOD	mg/l	31.6	61.8	51.8	51.8	79
COD	mg/l	62.8	71.2	52.8	56.3	88
DO	mg/l	7.33	6.73	7.6	6.55	6.9
SS	mg/l	89	78	41	196	40
Total Nitrogen	mg/l	9.11	9.42	8.2	10.1	8.96
Residual Chlorine	mg/l	22.7	9.93	Trace	9.22	7.09
SO <sub>4</sub>	mg/l	89.2	153.6	98.4	192.8	100.8
Cyanogen	mg/l	0.04	0.03	0/05	0.04	0.08

	Unit	S6	S7	S8	S9
Temperature		48.2	30.3	46.9	37.2
PH		10.1	2.29	6.5	7.18
Elec. Conductivity	μ S/cm	5900	2730	640	240
Turbidity	NTU	270	321	315	247
Oil content	mg/l	Trace	Trace	0.01	Trace
BOD	mg/l	57.3	42.1	42.6	41.4
COD	mg/l	72.6	54.2	55.8	60.6
DO	mg/l	6.3	7.67	9.15	8.7
SS	mg/l	288	330	327	261
Total Nitrogen	mg/l	181.1	8.12	35.1	25.7
Residual Chlorine	mg/l	56.0	Trace	Trace	Trace
SO <sub>4</sub>	mg/l	297.6	212.8	133.6	48.0
Cyanogen	mg/l	0.11	0.09	0.06	0.03

### 5. Recommended Countermeasures for Improvement

- (1) The company should keep gauges in good repair and reduce the volume of water and amount of steam and chemicals used, as well as control the quality.
- (2) The company should recover steam condensate from a dryer for saving energy.
- (3) It is necessary for the company to reinforce the administration system such as arranging things and keeping the work place tidy, and to improve the morals of workers.

**Dong Xuan Knitting Company**

Survey Date: 24 November 1999

**1. General****1.1 Profile**

Dong Xuan Knitting Company is a state-owned company that was established in 1959 as a knitting fabric manufacturing company. The company profile of Dong Xuan Knitting Company is summarized in Table1.

**Table 1 Enterprise Profile**

Name of Company:	Dong Xuan Knitting Company
Ownership:	State-owned
Address:	67 Ngo Thi Nham Str. Hanoi
Tel:	04-9716565
Director:	
Established:	1959
Corporate Capital:	
Number of Employees:	1,200
Main Products:	Knitwear

**1.2 Business Status****1.2.1 Production**

Table2 shows production and sales of the Company in 1998.

A major part of their products are exported to the EU and Asia and 60% of products are exported to Japan.

**Table 2 Production and Sales in 1998**

No.	Product items	Production (pieces)	Turnover (1998 figures)
1	Knitwear	6,036,000	75,722 billion VND
	<b>Total</b>	<b>6,036,000</b>	<b>75,722 billion VND</b>

**1.2.2 Debt**

75,000,000,000 VND (1998)


STATE BANK 15,000,000,000VND(Long Term Loan)

COMMERCIAL BANK 15,000,000,000VND (Interest Ratio 9.6%/year)

## 2. Production Technology

### 2.1 Process

The Process flow of the factory is shown in Figure 1.



**Figure 1 Process Flow of the Factory**

### 2.2 Unit Consumption

The unit consumption of raw materials and utilities is shown in Table3.

**Table 3 Unit Consumption of Raw Materials and Utilities**

No.	Materials	Amount	Unit price	Expense
1	Yarn 40s/1	507,340 kg	45,980 VND/kg	23,328 millions VND
2	Yarn 30s/1	40,000 kg	44,390 VND/kg	1,756 millions VND
3	H <sub>2</sub> O <sub>2</sub>	134.50 kg	3,994 VND/kg	536.555 millions VND
4	CH <sub>3</sub> COOH	5,913 kg	9,610 VND/kg	56.820 millions VND
5	Dyes			
6	Water	220,000 m <sup>3</sup>	1,000 VND/m <sup>3</sup>	220 millions VND
7	FO	416,000kg	1,800 VND/kg	748.8 millions VND
8	Coal	2,158,000 kg	340 VND	733.7 millions VND
9	Electricity	1,867,510 kWh	800 VND/kWh	1,493.3 millions VND

### 2.3 Future Plans

The company has future plans to remove the dyeing factory, which discharges pollutants to the surrounding suburbs, because this factory is located in a thickly populated residential area and there is no space to install a wastewater treatment system.

The planned re-location area is in the southern part of Hanoi city where two textile factories are in operation and one food factory is scheduled to move out. A plan for constructing a water treatment center is being investigated in this area.

The company estimates the factory moving cost at US\$ 4,000,000, but

investment funding is a problem.

### **3. Management Technology**

- (1) Many of the facilities are old, but they are used efficiently in their own way. The quality is not so bad.
- (2) The management lacks the ability to cope with market diversification. The company manufactures mainly underwear and the like that is low in added value. Also, products, which are not technically difficult to produce are mostly manufactured.
- (3) The company needs to improve production facilities and technology to meet the demand of customers in the future.
- (4) Generally the plant is organized, neat, tidy and cleaned well and the working environment is good.
- (5) A director has introduced a 5S campaign from Japan and the company is now implementing it.  
This activity has had good results in its own way, including increase in productivity improvement.
- (6) The company started working to obtain ISO9002 in August 1999, and is making effort to be certified by October 2000.
- (7) The reprocessing rate is low as 3 %. The company has a system for increasing or decreasing the salary of workers according to the degree in which its targets accomplished. This system works well.
- (8) The company has a good grasp of unit consumption of energy, raw material and chemicals.

### **4. Industrial Wastewater Treatment and Discharge**

- (1) Only SS is removed from wastewater at the sedimentation tank.
- (2) Sampling

Wastewater samples were taken at following spots for analysis in this study.

Date: 24 November 1999

S1 : Discharged wastewater from the whole factory(to city sewage)

- (3) Wastewater Quality

Wastewater qualities analyzed by Hanoi University Civil Engineering Center of Environment Engineering of Towns and Industrial Areas (CEETIA) are shown in Table4.

**Table 4 Wastewater Quality in November 1999**

	Unit	S1
Temperature		47.6
pH		7.94
Elec. Conductivity	$\mu$ S/cm	540
Turbidity	NTU	11
Oil content	mg/l	0.09
BOD	mg/l	39.5
COD	mg/l	41.5
DO	mg/l	6.2
SS	mg/l	15.3
Total Nitrogen	mg/l	5.8
Residual Chlorine	mg/l	4.8
SO <sub>4</sub>	mg/l	184
Cyanogen	mg/l	Trace

**5. Recommended Countermeasures for Improvement**

- (1) The company should recover steam condensate from the processes to a boiler as a measure to reduce steam consumption at the dyeing plant.
- (2) The company should conduct a study on recovering and recycling discharged hot water from heat exchangers of dyeing machines.
- (3) The company should drive forward the establishment of a joint wastewater treatment facility in the industrial zone where it is going to move in.

## CASE STUDY T-10

### **Ha Dong Woolen Enterprise**

Survey Date: 29 November 1999

#### **1. General**

##### **1.1 Profile**

Ha Dong Woolen Enterprise is a state-owned company that was established in 1989 as a textile manufacturing company. The company profile of Ha Dong Woolen Enterprise is summarized in Table 1.

**Table 1 Enterprise Profile**

Name of Company:	Ha Dong Woolen Enterprise
Ownership:	State-owned
Address:	Durong 70 Thi Xa Ha Dong Ha Tay
Tel:	04-8542745
Director:	
Established:	1959
Corporate Capital:	
Number of Employees:	595
Main Products:	Yarns for Carpet and Blanket, Fabrics dyed and printed

##### **1.2 Business Status**

###### **1.2.1 Production**

Table 2 shows production and sales of the Company in 1998.

The major parts of products are for the domestic market. A pretty large amount of products had been exported to Russia until last year, but the number of products exported in 1999 was zero.

**Table 2 Production and Sales in 1998**

	<b>Items</b>	<b>Production</b>	<b>Turnover</b>
1	Carpet Yarn	121 t	7,441 million VND
2	Acrylic Yarn (for Blanket)	161 t	4,839 million VND
3	Knitting Fabric	40 t	1,600 million VND
4	Dyed Fabric	202,000 m	495 million VND
5	Printed Fabric	98,500 m	179 million VND
	Total		14,555 million VND


###### **1.2.2 Debt**

860 million VND with a commercial bank

## 2. Production Technology

### 2.1 Process

The Process flow of the factory is shown in Figure1.



**Figure 1 Process Flow of the Factory**

### 2.2 Unit Consumption

The unit consumption of raw materials and utilities is shown in Table 3.

### 2.3 Future Plans

Unknown

## 3. Management Technology

- (1) The facility was not in operation during our visit therefore, the study team did not have much of an opportunity to check it.
- (2) The facilities are old, and both productivity and quality are not good.
- (3) The spinning facilities are old and they are in poor repair as well.
- (4) We were unable to make any judgments on the dyeing facilities as they were not in operation. However, it seems that the facilities are very old and maintenance on them is poor. Accordingly, it is impossible to expect profitable operations.
- (5) We could not evaluate the administrative aspects of the dyeing facilities because they were not in operation. However, it seems that quality control is



not well performed from the appearance of the facilities.

(6) Generally, cleaning, arrangement and tidying of facilities are insufficient.

**Table 3 Unit Consumption of Raw Materials and Utilities**

No.	Material	Consumption	Remark	Expense (1000VND)
<b>1</b>	<b>Carpet Yarn</b>			
1-1	Yarns	138.5 ton	30,760 VND/kg	4,260,260.00
1-2	Acid Dye Stuff	1.338	80,000	107,040.00
1-3	CH <sub>3</sub> COOH	2.077	9,500	19,731.50
1-4	Na <sub>2</sub> SO <sub>4</sub>	11.080	1,800	19,944.00
1-5	Others	1.662	25,000	41,550.00
<b>2</b>	<b>Acrylic Yarn(Blanket)</b>			
2-1	Yarns	170 ton	12,200 d/kg	2,074,000.00
2-2	Cationic Dye Stuff	2.890	135,000	390,150.00
2-3	CH <sub>3</sub> COOH	2.550	9,500	24,225.00
2-4	Na <sub>2</sub> SO <sub>4</sub>	6.800	1,800	12,240.00
<b>3</b>	<b>Acrylic Knit</b>			
3-1	Tow	42.6 ton	20,800 VND/kg	886,080.00
3-2	Cationic Dye Stuff	0.724	135,000	97,740.00
3-3	CH <sub>3</sub> COOH	0.852	9,500	8,094.00
3-4	Na <sub>2</sub> SO <sub>4</sub>	3.408	1,800	6,134.40
3-5	Others	1.704	30,000	51,120.00
<b>4</b>	<b>Dyed Fabric</b>			
4-1	Gray Fabric	201,400 m	6,000 VND/m	1,208,400.00
4-2	Directive Dye Stuff	1.407 ton	95,000 VND/kg	133,665.00
4-3	Chemicals	1.407	4,000	5,628.00
4-4	Wetting Agent	2.613	15,000	391,950.00
4-5	H <sub>2</sub> O <sub>2</sub>	0.201	7,000	1,407.00
4-6	Others	0.100	15,000	1,500.00
<b>5</b>	<b>Utility</b>			
5-1	Electricity	1,216,200 kWh	840 VND/kWh	1,021,608.00
5-2		741 ton	450 VND/kg	333,450.00
	<b>Total</b>			<b>10,725,161</b>

#### 4. Industrial Wastewater Treatment and Discharge

(1) The company's wastewater treatment facility, which has quite a big sedimentation tank, is located outside of the plant. However, they receive complaints from residents because they are discharging wastewater without any treatment.

## (2) Sampling

Wastewater samples were taken at following spots for analysis in this study.

Date: 29 November 1999

S1 : Discharged wastewater from the whole factory (to city sewage)

## (3) Wastewater Quality

Wastewater qualities analyzed by Hanoi University Civil Engineering Center of Environment Engineering of Towns and Industrial Areas (CEETIA) are shown in Table 4.

**Table 4 Wastewater Quality in November 1999**

	Unit	S1
Temperature		20.2
PH		7.5
Elec. Conductivity	$\mu$ S/cm	380
Turbidity	NTU	11
Oil content	mg/l	Trace
BOD	mg/l	63.9
COD	mg/l	85.6
DO	mg/l	1.6
SS	mg/l	15.5
Total Nitrogen	mg/l	6.05
Residual Chlorine	mg/l	Trace
SO <sub>4</sub>	mg/l	105.6
Cyanogen	mg/l	0

## 5. Recommended Countermeasures for Improvement

- (1) The inside of the plant is dirty and in confusion. Workers should try to clean, tidy up and put things in order. In addition, the company should work to increase the spirits and morale of workers.
- (2) The maintenance of facilities is poor. For this reason, it is hard to produce high-quality products and productivity declines. This is the main point for the company to focus on.

## CASE STUDY T-11

### Viet Tien Garment Export and Import Company

Survey Date: 2 December 1999

#### 1. General

##### 1.1 Profile

Viet Tien Garment Export and Import Company is a state-owned company that was established in 1976 as a garment manufacturing company. The company profile of Viet Tien Garment Export and Import Company is summarized in Table 1.

**Table 1 Enterprise Profile**

Name of Company:	Viet Tien Garment Export and Import Company
Ownership:	State-owned
Address:	7 Le Minh Xuaqn Str. Tan Binh District Hochiminh City
Tel:	08-8640800-8645082
Director:	
Established:	1976
Corporate Capital:	
Number of Employees:	5,000
Main Products:	Shirts, Jackets, Trousers, Sports suites

##### 1.2 Business Status

###### 1.2.1 Production

The major parts of products are exported to Japan(32-33%), the EU(35%), Taiwan(29%) and East Europe and Canada. Only 3-5% of products are for domestic market.


###### 1.2.2 Debt

13,839,134,820 VND

#### 2. Production Technology

##### 2.1 Process

The Process flow of the factory is shown in Figure 1.



**Figure 1 Process Flow of the Factory**

## **2.2 Unit Consumption**

**Omission**

## **2.3 Future Plan**

**Unknown**

## **3. Management Technology**

- (1) The company has a sewing plant only. The study team cannot comment on this plant because it does not discharge wastewater.
- (2) Regarding the plant administration, the company has introduced TQM, KAIZEN and 5S and it also has obtained ISO9002 certification.

## **4. Industrial Wastewater Treatment and Discharge**

Not Applicable

## **5. Recommended Countermeasure for Improvement**

- (1) The company should try and work hard to maintain its current level. However, administrators should always check the operation, conditions and it is desirable for them to make efforts to improve further.

## CASE STUDY T-12

### **Phuoc Long Textile Garment Company**

Survey Date: 3 December 1999

#### **1. General**

##### **1.1 Profile**

Phuoc Long Textile Garment Company is a state-owned company that was established in 1975 as a textile manufacturing company by combining two companies which are established in 1959. The company profile of Phuoc Long Textile Garment Company is summarized in Table 1.

**Table 1 Enterprise Profile**

Name of Company:	Phuoc Long Textile Garment Company
Ownership:	State-owned
Address:	Phuoc Long B Ward District 9 Hochiminh City
Tel:	08-8961100
Director:	Mr. LE VANG PHUC
Established:	1975
Corporate Capital:	
Number of Employees:	1,500
Main Products:	Fabrics

##### **1.2 Business Status**

###### **1.2.1 Production**

Table 2 shows production and sales of the Company in 1998.

15% of products were exported to Japan and Europe in 1998 and 20% of products are expected to be exported in 1999.

**Table 2 Production and Sales in 1998**

<b>Product</b>	<b>Production</b>	<b>Turnover</b>
Fabric	13,395,000 m <sup>2</sup>	99,500 million VND


###### **1.2.2 Debt**

Unknown

#### **2. Production Technology**

##### **2.1 Process**

The Process flow of the factory is shown in Figure 1.



**Figure 1 Process Flow of the Factory**

## 2.2 Consumption of Raw Materials & Utility

The unit consumption of raw materials and utilities is shown in Table 3.

**Table 3 Unit Consumption of Raw Materials and Utilities**

No.	Material	Consumption	Remark
1	Gray Fabric	15 million m <sup>2</sup> /year	
2	Dye Stuff	680 kg/month	
3	Softener	450 kg/month	
4	Auxiliary Chemicals	29,705 kg/month	
5	Sizing agent	1,470 kg/month	
6	Water	1,500 m <sup>3</sup> /day	
7	Fuel	12,000 l/day	
8	Electricity	800,000 kWh/month	

## 2.3 Future Plans

Unknown

## 3. Management Technology

- (1) The quality of wastewater is very bad and there are no treatment facilities.
- (2) The plant discharges a lot of wastewater without any treatment,
- (3) During the time we investigated the dyeing plant, no tidying up was done, nor were things put in order, or cleaned. Furthermore, there appears to be problems with production management.
- (4) UNIDO performed a program for cleaner production from January 1998 to June 1999, but the study team was unable to get concrete information on the project from the person in charge.

#### **4. Industrial Wastewater Treatment and Discharge**

- (1) No wastewater treatment system has been installed.
- (2) This company is investigating the possibility of introducing the wastewater treatment system.  
(Coagulation + Biological System). They requested EPC, which belongs to army, to design the system.
- (3) The volume of wastewater is 1500 m<sup>3</sup>/day.
- (4) Sampling

Wastewater samples were taken at following spots for analysis in this study.

Date: 3 December 1999

- S1 : Discharged wastewater from the whole factory A (to city sewage)
- S2 : At Jet dying m/c ( washing water after dying)
- S3 : Discharged wastewater from the whole factory B (to city sewage)
- S4 : At Jet dying m/c ( washing water after bleaching)
- S5 : At sizing m/c of the weaving factory (waste sizing stuff)
- S6 : At sizing m/c (cooling water of the sizing tank)

#### **(5) Wastewater Quality**

Wastewater qualities analyzed by Hanoi University Civil Engineering Center of Environment Engineering of Towns and Industrial Areas (CEETIA) are shown in Table4.

#### **5. Recommended Countermeasure for Improvement**

- (1) Product quality must be improved and production costs must be reduced.
- (2) The inside and outside of the plant is not tidy and this influences quality and moral. The company needs to keep the site clean.
- (3) To solve the problems mentioned above, the company should undertake a 5S campaign and TQC activities.

**Table 4 Wastewater Quality in December 1999**

	Unit	S1	S2	S3	S4	S5	S6
Temperature		43	58.6	58	60	32.2	33.8
pH		11.3	5.14	3.8	10.24	7.15	4.43
Elec. Conductivity	μ S/cm	490	380	782	3140	1020	580
Turbidity	NTU	1	545	25	114	999	14
Oil content	mg/l	4.5	0.9	0.8	5.2	113	2.4
BOD	mg/l	784	16	5	40	9450	44
COD	mg/l	957	25	14	172	23998	172
DO	mg/l	4.2	2.33	4.3	2.5	0.39	5.33
SS	mg/l	19	10	30	12	8800	100
Total Nitrogen	mg/l	1.4	0.9	4.42	1.3	350	29.7
Residual Chlorine	mg/l	1.8	18.2	3.6	Trace	7.2	6.4
SO <sub>4</sub>	mg/l	40	83	21	880	1200	31
Cyanogen	mg/l	0.05	0.01	0.02	0.37	Not det	Trace



**Thanh Cong Textile Company**

Survey Date: 6 December 1999

**1. General****1.1 Profile**

Thanh Cong Textile Company is a state-owned company that was converted in 1976 from a private company that has been established originally in 1972 as a textile manufacturing company. The company profile of Thanh Cong Textile Company is summarized in Table 1.

**Table 1 Enterprise Profile**

Name of Company:	Thanh Cong Textile Company
Ownership:	State-owned
Address:	N0.8 Qoac Lo 1, Tan Binh District, Hochiminh City
Tel:	08-8495968
Director:	
Established:	1976
Corporate Capital:	
Number of Employees:	3,700
Main Products:	Yarns, Fabrics, Garments

**1.2 Business Status****1.2.1 Production**

Table 2 shows production and sales of the Company in 1998.

More than 50% of their products (90% of garments ) are exported to Japan, USA, Korea, Taiwan etc.

**Table 2 Production and Sales in 1998**

No.	Products	Production	Turnover
1	Yarn	3,753 t	
2	Fabrics	13,680,487 m	
3	Garments	5,484,709 pcs	
	Total		440,000 million VND


**1.2.2 Debt**

Unknown

## 2. Production Technology

### 2.1 Process

The Process flow of the factory is shown in Figure 1.



**Figure 1 Process Flow of the Factory**

### 2.2 Unit Consumption

The unit consumption of raw materials and utilities is shown in Table 3.

**Table 3 Unit Consumption of Raw Materials and Utilities**

No.	Items	Source/ Type	Utilization	Consumption (ton/year)	Notes
1	Fibres	Imported from various source	producing yarns	3,020	
2	Chemicals and auxiliaries	Imported	Sizing and dyeing yarn	4,827.3	
3	Dyes	Disperse, Direct, Active, Cationic dyes	Dyeing	85.5	

### 2.3 Future Plans

The company is planning to install new WJ type weaving machines to replace old shuttle type looms.

## 3. Management Technology

- (1) A Japanese technician, who was dispatched by JODC, is instructing the plant so the management level of the plant is high.
- (2) A TQM program is now in progress. There are many notices that help raise the morale of employees.
- (3) There are no quality control activities, but there are graphs describing the production situation at many places throughout the factory.
- (4) A 5S campaign has been performed thoroughly.

(5) A program to obtain ISO 9002 is now in progress.

#### 4. Industrial Wastewater Treatment and Discharge

- (1) No water treatment system has been installed.
- (2) Wastewater from the factory is discharged to sewage through the wastewater tank.
- (3) The wastewater volume is very large of 4800 m<sup>3</sup>/day.
- (4) Sampling

Wastewater samples were taken at following spots for analysis in this study.

Date: 6 December 1999

S1 : At Jet dying m/c ( washing water after reproducing)

S2 : Discharged wastewater from the whole factory (to city sewage)

S3 : At Jet dying m/c ( washing water after dying)

#### (5) Waste water Quality

Wastewater qualities analyzed by Hanoi University Civil Engineering Center of Environment Engineering of Towns and Industrial Areas (CEETIA) are shown in Table 4.

**Table 4 Wastewater Quality in December 1999**

	Unit	S1	S2	S3
Temperature		60	33.1	60
pH		6.75	10.0	10.24
Elec. Conductivity	μ S/cm	14600	2480	3900
Turbidity	NTU	4	42	31
Oil content	mg/l	11.8	31.9	5
BOD	mg/l	4	77	13
COD	mg/l	21	269	115
DO	mg/l	0.15	7.64	0.46
SS	mg/l	3	45	14
Total Nitrogen	mg/l	3.0	4.62	13.16
Residual Chlorine	mg/l	Not det	0.2	2.6
SO <sub>4</sub>	mg/l	5025	240	126
Cyanogen	mg/l	0.43	0.07	0.08

#### 5. Recommended Countermeasures for Improvement

- (1) The company should set up wastewater treatment facilities.
- (2) Plant management at the company is progressing well. It is hoped that this situation will be maintained after the Japanese technician leaves the plant.



**Dong Nam Textile Company**  
**(DOMATEX J.VCO., LTD)**

Survey Date: 7 December 1999

**1. General****1.1 Profile**

DOMATEX J.VCO. LTD is a joint venture company between Dong Nam Textile Company, a state-owned company and Taiwan Capital and was established in 1992 as a dyeing sub-contracting. The company profile of DOMATEX J.VCO., LTD is summarized in Table 1.

**Table 1 Enterprise Profile**

Name of Company:	DOMATEX J.VCO., LTD
Ownership:	Joint Venture between Dong Nam Textile Company and Taiwan
Address:	18/3 Au Co. St. W. 17. TB. District Hochiminh City
Tel:	08-8425519
Director:	
Established:	1992
Corporate Capital:	
Number of Employees:	70
Main Products:	Dyed knit fabrics

**1.2 Business Status****1.2.1 Production**

Table 2 shows production and sales of the company in 1998.

**Table 2 Production and Sales in 1998**

No.	Item	Production	Turnover
1	Dyed fabrics	882,793 kg	11,416,118,000 VND
2	Bleached fabrics	558,528 kg	7,610,746,000 VND
	Total	1,471,321 kg	19,026,864,000 VND


**1.2.2 Debt**

Debt with commercial banks: 1,100,000,000 VND

## 2. Production Technology

### 2.1 Process

The Process flow of the factory is shown in Figure 1.



**Figure 1 Process Flow of the Factory**

### 2.2 Unit Consumption

The unit consumption of raw materials and utilities is shown in Table 3.

**Table 3 Unit Consumption of Raw Materials and Utilities**

No.	Materials	Production (tons)	Remarks
1	Gray Fabric	1,559,600 kg	
2	Dye Stuff	12,000 kg	4,661,802,000 VND
3	Water		
4	F.O.	1,548,000 lit	2,435,140,000 VND
5	Electricity	1,329,600 kWh	996,852,000 VND
6	Chemicals		
6-1	NAOH	1,500 kg/	
6-2	Soda	6,300 kg/	
6-3	NA <sub>2</sub> SO <sub>4</sub>	18,000 kg/	
6-4	H <sub>2</sub> O <sub>2</sub>	3,500 kg/	
6-5		130 kg/	

### 2.3 Future Plans

Unknown

## 3. Management Technology

- (1) The surroundings of machines in the dyeing plant are kept tidy, but the chemical kitchen is not in good order.
- (2) No improvement activities, such as a 5S campaign or TQC activities, are been undertaken.
- (3) Operation manuals and information on production conditions are not provided

at the plant site. Therefore, a visual system for operation control has not been adopted.

#### 4. Industrial Wastewater Treatment and Discharge

- (1) Regarding wastewater treatment, the company applies both a chemical treatment by using coagulating agents and a physical treatment with filtration equipment.
- (2) However, as the wastewater treatment performance is insufficient, the discharged wastewater doesn't clear standards in Vietnam.
- (3) Wastewater volume is 300 m<sup>3</sup>/day.
- (4) Sampling:

Wastewater samples were taken at following spots for analysis in this study.

Date: 7 December, 1999

S1 : Waste water from the dyeing factory

S2 : Discharged wastewater from the whole factory (to city sewage)

S3 : At Jet dyeing m/c ( washing water after scouring)

S4 : At Jet dyeing m/c ( washing water after dyeing)

#### (5) Wastewater Quality

Wastewater qualities analyzed by Hanoi University Civil Engineering Center of Environment Engineering of Towns and Industrial Areas (CEETIA) are shown in Table 4.

**Table 4 Wastewater Quality in December 1999**

	Unit	S1	S2	S3	S4
Temperature		39	35	60	60
pH		10.8	10	10.64	4.2
Elec. Conductivity	μS/cm	3040	1730	834	759
Turbidity	NTU		10	28	73
Oil content	mg/l	7.1	0.57	7.5	11.5
BOD	mg/l	17	308	12	263
COD	mg/l	126	2353	66	1820
DO	mg/l	0.8	0.47	0.55	0.66
SS	mg/l	4.8	40	88	97
Total Nitrogen	mg/l	2.4	3.1	37.7	10.6
Residual Chlorine	mg/l	1.24	1.87	0.75	0.12
SO <sub>4</sub>	mg/l	352.2	37.4	518	60
Cyanogen	mg/l	0.1	0.05	0.19	0.34

## **5. Recommended Countermeasures for Improvement**

- (1) Improve product quality and reduce production cost at the dyeing plant:
  - A) The color matching laboratory and chemical kitchen are untidy. As this influences product quality and productivity, it is necessary to clean them up regularly.
  - B) The company should positively conduct a study to save water and recover heat both are effective method for cutting manufacturing cost and environmental loads.
- (2) It is recommendable that the company build a joint wastewater treatment facility with the knit dyeing plant next door.



**Binh Loi Blanket-Wool Company**

Survey Date: 9 December 1999

**1. General****1.1 Profile**

Binh Loi Blanket-Wool Company is a state-owned company that was established in 1963 as a textile manufacturing company. This company was joined with the Vietnam Blanket-Wool Company group. The company profile of Binh Loi Blanket-Wool Company is summarized in Table 1.

**Table 1 Enterprise Profile**

Name of Company:	Binh Loi Blanket-Wool Company
Ownership:	State-owned
Address:	438 No Tranglong St., Binh Thanh District Hochiminh City
Tel:	08-8432359
Director:	
Established:	1963
Corporate Capital:	
Number of Employees:	850
Main Products:	Blanket, Moa Fabric, Acrylic Yarn, Acrylic Top

**1.2 Business Status****1.2.1 Production**

Table 2 shows production and sales of the company in 1998.

Main market of this company is domestic and only 10 ~ 15% of products are exported.

**Table 2 Production and Sales in 1998**

No.	Products	Production	Turnover
1	Blankets	1,074,760 m <sup>2</sup>	43,697 million VND
2	Acrylic Yarn	399,995 kg	23,297 million VND
3	Boa Fabric	87,439 m	3,652 million VND
4	Acrylic Top	444,695 kg	4,332 million VND
	Total		75,246 million VND


**1.2.2 Debt**

Unknown

## 2. Production Technology

### 2.1 Process

The process flow of the factory is shown in Figure 1.



**Figure 1 Process Flow of the Factory**

### 2.2 Unit Consumption

The unit consumption of the raw materials and utilities is shown in Table 3.

**Table 3 Unit Consumption of Raw Materials and Utilities**

No.	Material	Consumption	Remarks
1	Acrylic Fiber	896,858 kg	
2	Polyester Fiber	182,532 kg	
3	Wool Fiber	55,080 kg	
4	Warp Yarn(PET/PECO=30)	11,453 kg	
5	Acrylic Tow	676,612 kg	
6	Dye Stuff	164,207 kg	
7	Organic Auxiliary	6,701 kg	
8	Water	68,084 m <sup>3</sup>	
9	Fuel Oil	433,514 lit	
10	Electricity	156,054 kWh	

### 2.3 Future Plans

The company has the following plans;

- (1) To install new tow dyeing machines that are fitted for tow dyeing
- (2) To improve the printing machine to be capable of printing 8 colors (the present machine can print only 6 colors.) and can connect to a continues heat setter

## 3. Management Technology

- (1) It is obvious that machines have become too old for use, and there are quality

problems. The maintenance of the tow converters is especially not good and they do not seem to be operating normally.

- (2) The handling of fiber and tow at the dyeing process is in disorder.  
Needless to say, but there are stains and mixtures of foreign materials and this causes damage to the form of the tow.
- (3) Generally, the inside and outside of the plant is untidy, not in order, and not clean, and production facilities are not maintained well. It is hard to say that they have a normal level of factory management.
- (4) There are no improvement activities such as a 5S campaign or QC activities.

#### **4. Industrial Wastewater Treatment and Discharge**

- (1) A biological wastewater treatment system has been installed.
- (2) However, the wastewater treatment system does not function fully.
- (3) Wastewater volume is 200 m<sup>3</sup>/day.
- (4) Sampling

Wastewater samples were taken at following spots for analysis in this study.

Date: 9 December 1999

- S1 : At a tow dying m/c ( washing water after dying)
- S2 : At a Acrylic fiber dying m/c (washing water after dying)
- S3 : Wastewater from the dying factory
- S4 : At the biological treatment Tank ( wastewater treatment system)
- S5 : At the sedimentation tank (after biological treatment)
- S6 : Discharged wastewater from the whole factory (to city sewage)
- S7 : At tow dying m/c (washing water after bleaching)

- (5) Wastewater Quality

Wastewater qualities analyzed by Hanoi University Civil Engineering Center of Environment Engineering of Towns and Industrial Areas (CEETIA) are shown in Table 4.

#### **5. Recommended Countermeasures for Improvement**

- (1) To improve product quality and reduce product cost:
  - A) It is necessary to tidy up and clean inside and outside of the plant thoroughly.  
A 5S campaign is an effective way to solve such kinds of problems.
  - B) The handling of products is too rough. Acrylic fibers are very delicate and required to be handled with care.

- C) The company should reinforce the maintenance of machines, especially tow converters at the spinning plant.
- D) Managers and plant leaders should not attribute the reason that their products don't meet the standards of the export market, only to their old production facilities. Instead they should be aware of the lack of their own plant management technology and try to devote themselves to their responsibilities.

**Table 4 Wastewater Quality in December 1999**

	Unit	S1	S2	S3	S4	S5
Temperature		37.5	34.9	35.7	31.1	30.8
PH		4.77	4.97	4.75	7.3	7.35
Elec. Conductivity	μ S/cm	1220	1050	300	1510	1540
Turbidity	NTU	3	7			24
Oil content	mg/l	22	18.4	45	23	12.8
BOD	mg/l	42	51	186	90	15
COD	mg/l	229	188	445	449	113
DO	mg/l	8.34	8.9	2.12	7.05	3.88
SS	mg/l	31	20	30	358	85
Total Nitrogen	mg/l	9.96	4.25	16.2	43.4	26.5
Residual Chlorine	mg/l	Not det	Not det	Not det	0.12	0.15
SO <sub>4</sub>	mg/l	785	45	134	148	154
Cyanogen	mg/l	0.22	0.25	0.13	0.07	0.03

	Unit	S6	S7
Temperature		29.6	33.5
pH		3.19	3.8
Elec. Conductivity	μ S/cm	3160	240
Turbidity	NTU		9
Oil content	mg/l	7.6	9.3
BOD	mg/l	2	107
COD	mg/l	52	240
DO	mg/l	3.07	7.05
SS	mg/l	6	2
Total Nitrogen	mg/l	6.83	10.9
Residual Chlorine	mg/l	0.7	Not det
SO <sub>4</sub>	mg/l	160	17
Cyanogen	mg/l	0.03	0.11

**Thang Loi Textile Company**

Survey Date: 10 December 1999

**1. General****1.1 Profile**

Thang Loi Textile Company is a state-owned company that was established in 1959 as a textile manufacturing company. This company was unified from Vinatexco and Vinatenifico. The company profile of Thang Loi Textile Company is summarized in Table 1.

**Table 1 Enterprise Profile**

Name of Company:	ThangLoi Textile Company
Ownership:	State-owned
Address:	No.2 Highway No.1, 15 <sup>th</sup> ward-Tanbinh Dist. Hochiminh City
Tel:	08-8495977
Director:	
Established:	1959
Corporate Capital:	
Number of Employees:	3000
Main Products:	Yarns, Finishing fabrics, Apparel products

**1.2 Business Status****1.2.1 Production**

Table 2 shows production and sales of the Company in 1998.

The main market of this company is the domestic market and only 10 ~ 15% of products are exported.

**Table 2 Production and Sales in 1998**

No.	Items	Design	1998	1999 plan
1	Yarns	8, 000 t/year	5,725	5,400
2	Finished fabrics	15,000,000 m./year	12,834,000	11,200,000
3	Apparel products	1,500,000 converted items /year	1,041,000	1,200,000


**1.2.2 Debt**

Unknown

## 2. Production Technology

### 2.1 Process

The Process flow of the factory is shown in Figure 1.



**Figure 1 Process Flow of the Factory**

### 2.2 Unit Consumption

The unit consumption of raw materials and utilities is shown in Table 3.

**Table 3 Unit Consumption of Raw Materials and Utilities**

No.	Items	Utilization in	Quantity (ton/year)	Note
1	Cotton fiber	Spinning	4,000	
2	Manmade fibers	Spinning	2,500	
3	F.O	Boilers, oil-circulation heater	3,200.000	
4	D.O	Generators and cars	288,000 litters/year	
5	Electricity	Production and illumination	32,000,000 kWh	

### 2.3 Future Plans

Unknown

## 3. Management Technology

- (1) The machines in the new spinning factory are in pretty operating good condition. However, the study team was not able to see the old spinning factory and the weaving factory.
- (2) The condition of the dyeing factory is a little better than the average condition in other factories, which was observed in this study. However, the condition and operating levels of the machines are insufficient.
- (3) There are a lot of steam leakage from machines and steam pipings.

- (4) The reprocessing ratio is very high, between 10 ~ 15%. This means that the quality control system is not effective.
- (5) A program to obtain the certification of ISO 9002 certification was under progress.
- (6) The technical manager of the company has been to Japan to receive training on factory management systems such as TQM and Kaizen.

#### **4. Industrial Wastewater Treatment and Discharge**

- (1) No water treatment system has been installed.
- (2) Wastewater from the factory is discharged to the sewage directly.
- (3) Wastewater volume is 4800 m<sup>3</sup>/day.
- (4) Sampling :

Wastewater samples were taken at following spots for analysis in this study.

Date: 10 December 1999

S1 : At Jet dyeing m/c ( washing water after dyeing)

S2 : At Wince dyeing m/c (washing water after bleaching)

S3 : At Rotary printing m/c( washing water of the rotary screen)

S4 : Discharged wastewater from the whole factory (to city sewage)

- (5) Wastewater Quality

Wastewater qualities analyzed by Hanoi University Civil Engineering Center of Environment Engineering of Towns and Industrial Areas (CEETIA) are shown in Table 4.

#### **5. Recommended Countermeasures for Improvement**

- (1) The rate of reprocessing is too high (10 to 15%). There are quality control problem and the company should introduce TQM and 5S.
- (2) There is a lot of steam leakage and this causes an energy loss. The company should try save energy as much as possible.
- (3) The company's plan for wastewater treatment facilities is flawed, because it will only be able to treat wastewater from the dyeing process organically and will treat wastewater from the scouring process chemically. The company needs to review this problem.

**Table 4 Wastewater Quality in December 1999**

	Unit	S1	S2	S3	S4
Temperature		36	60	27.8	31.2
PH		10.0	11.2	5.96	10.5
Elec. Conductivity	μ S/cm	9900	12300	40	460
Turbidity	NTU		53	445	
Oil content	mg/l	156	22	123	1
BOD	mg/l	294	162	228	14
COD	mg/l	5125	2753	1372	341
DO	mg/l	0.4	0.98	0.4	1.2
SS	mg/l	450	86	260	12
Total Nitrogen	mg/l	51.3	25.9	27.8	10.5
Residual Chlorine	mg/l	3.1	14.2	0.22	0.45
SO <sub>4</sub>	mg/l	1523	2210	11.2	164
Cyanogen	mg/l				



**Hoa Tho Textile & Garment Company**

Survey date: 14 December 1999

**1. General****1.1 Profile**

Hoa Tho Textile Company is a state-owned company that was established in 1961 as a textile manufacturing company. The company profile of Hoa Tho Textile Company is summarized in Table 1.

**Table 1 Enterprise Profile**

Name of Company:	Hoa Tho Textile Company
Ownership:	State-owned
Address:	Hoa Tho Vang, Danang City
Tel:	84511846217
Director:	Mr. TRAN VAN PHO
Established:	1961
Corporate Capital:	
Number of Employees:	1300
Main Products:	Yarns, Fabric, Towels and Subcontracted of Sewing Products

**1.2 Business Status****1.2.1 Production**

Table 2 shows production and sales of the company in 1998.

The main markets of this company are Taiwan, Japan & the EU for garment and towels and the domestic market for fabrics.

**Table 2 Production and Sales in 1998**

No.	Products	Output	Revenue
1	Type of Fiber:(kg)	1,430,415	33,809,913,068 VND
1-1	-PE Fiber	317,947	
1-2	-Cotton	42,790	
1-3	-PECO	1,069,678	
2	Type of Fabrics(m)	20288,254	9,656,762,388 VND
2-1	-Towel	1,410,957	
2-2	-Calico	877,297	

### 1.2.2 Debt

Liabilities at the end of 1998: VND 2,810,500,000


USD 3,372,000

Of which:	payable to employees	151,500,000 VND
	payable to financial company	2,659,000,000 VND
	bank borrowing	3,372,000 VND

## 2. Production technology

### 2.1 Process

The Process flow of the factory is shown in Figure 1.



**Figure 1 Process Flow of the Factory**

### 2.2 Unit Consumption

The unit consumption of raw materials and utilities is shown in Table 3.

### 2.3 Future Plans

Unknown

## 3. Management Technology

- (1) New spinning machines are maintained at a standard level, but it is obvious that old machines have become too old for use. There are also many problems with product quality.
- (2) A splicing system is not installed at the winding process.
- (3) A ring-type machine is used at the yarn twisting process, but double twisters have not been introduced yet. There are problems with splicing control.
- (4) Although new and powerful comer machines have been introduced, all of them are currently suspended, and only card yarns which are low in added value are

manufactured.

- (5) Sizing machines at the weaving preparation process are made in the U.S. and they are in good operating condition.
- (6) All weaving machines are shuttle type and their weaving width is narrow.  
It is necessary to renovate these machines.
- (7) Towel weaving machines are getting too old for use and can manufacture only low value added products, such as towels for advertising.
- (8) Tidiness and arrangement of the spinning plant are comparatively good, but the maintenance of the old type machines is poor.
- (9) Management of bobbins at the robbing, spinning and yarn winding processes is not good.
- (10) The weaving plant is generally untidy and in disorder. Weaving machines are too old for use and also in poor maintenance because the company cannot get spare parts sufficiently.
- (11) There are no improvement activities such as a 5S campaign and QC activities at the plant.

**Table 3 Unit Consumption of Raw Materials and Utilities**

No.	Material	Quantity	Expenses (VND)
1	Fiber products		
1-1	Main material:(kg)	1,596,679	18,236,621,423
(1)	-PE	1,295,435	
(2)	-Original cotton	190,080	
(3)	-Tan dung cotton	111,164	
1-2	Auxiliary material		360,507,889
1-3	Electricity (kWh)	6,871,087	5,906,399,229
2	Fabrics products		
2-1	Fiber material:(kg)	270,578	7,231,789,083
(1)	-Cotton	127,838	
(2)	-PECO	142,740	
2-2	Auxiliary material		191,915,188
2-3	FO(kg)	122,000	103,965,375
2-4	Electricity (kWh)	539,415	450,143,939
3	Garment products		
3-1	Fabric material		
3-2	Auxiliary material		95,910,723
3-3	Electricity (kWh)	119,794	101,687,968
4	Regional water	19,530	39,060,000
4-1	-Air conditioning	8,694	
4-2	-Industrial hygiene	9,545	
4-3	-Boiler	220	
4-4	-Water put on fire tree	1,070	

#### 4. Industrial Wastewater Treatment and Discharge

- (1) Industrial wastewater is discharged only from the sizing system of the weaving process in small quantities.
- (2) The wastewater from the sizing system is treated by a small biological system.
- (3) Sampling

Wastewater samples were taken at following spots for analysis in this study.

Date : 14 December 1999

S1 : At Sizing m/c of the weaving factory ( discharged sizing stuff)

S2 : Wastewater from the weaving factory(after biological treatment tank)

- (4) Wastewater Quality

Wastewater qualities analyzed by Hanoi University Civil Engineering Center of Environment Engineering of Towns and Industrial Areas (CEETIA) are shown in Table 4.

**Table 4 Wastewater Quality in December 1999**

	Unit	S1	S2
Temperature		58.4	34.1
pH		6.69	4.39
Elec. Conductivity	$\mu$ S/cm	540	27200
Turbidity	NTU	1295	261
Oil content	mg/l	0	Trace
BOD	mg/l	18450	1768
COD	mg/l	77800	17220
DO	mg/l	1.8	2.3
SS	mg/l	19600	362
Total Nitrogen	mg/l	235	28.7
Residual Chlorine	mg/l	0.71	Trace
SO <sub>4</sub>	mg/l	184	536
Cyanogen	mg/l		

#### 5. Recommendation

- (1) Sizing agents from the weaving plant are treated, but the company should reduce the discharge volume by the reuse method.
- (2) As for plant management, in order to improve the quality of products and manufacturing costs:
  - A) It is necessary for the company to tidy up inside and outside of the plant and to clean the plant thoroughly. A 5S campaign is an effective way to solve such kind of problems.
  - B) Some of the old machines are operating without some parts. This is a

problem for product quality and they need to reinforce the maintenance of the machines.

- C) The company must to pay attention to mistakes in variety mixture (bobbin color control and so on) which is the basic of process management.
- D) It is desirable that managers and plant leaders take leadership for solving the above-mentioned problems and make efforts to improve results.



**29-3 Textile-Garment Company**

Survey date: 16 December 1999

**1. General****1.1 Profile**

29-3 Textile-garment Company is a local state-owned company that was established in 1976 as a textile manufacturing company. The company profile of 29-3 Textile-Garment Company is summarized in Table 1.

**Table 1 Enterprise Profile**

Name of Company:	29-3 Textile-Garment Company
Ownership:	Local state-owned
Address:	Dien Bien Phu St. Danang City
Tel:	84 511 821275
Director:	Mr. HUYNH VAN CHINH
Established:	1976
Corporate Capital:	
Number of Employees:	1,700
Main Products:	Towels, Cotton Garment, Polyester and Rayon

**1.2 Business Status****1.2.1 Production**

Table 2 shows production and sales of the Company in 1998.

Most of their products are exported to Japan.

**Table 2 Production and Sales in 1998**

No.	Items	Design	1998	1999
1	Towels	500 tons	253 tons	400 tons
2	Garment	2,500,000 pieces	2,026,079 pieces	2,100,000 pieces
3	Stone-washing	1,000,000 pieces		100,000 pieces


**1.2.2 Debt**

Unknown

## 2 Production technology

### 2.1 Process

The Process flow of the factory is shown in Figure 1.



**Figure 1 Process Flow of Factory**

### 2.2 Unit Consumption

The unit consumption of raw materials and utilities is shown in Table 3.

**Table 3 Unit Consumption of Raw Materials and Utilities**

No.	Items	Quantity	Cost	Total
1	Towels	400 tons		
	Bleached towels	200 tons		
	Dyed towels	200 tons		
2	Dyes	0.5 ton		
3	Organic solvents	25 tons		
4	H <sub>2</sub> O <sub>2</sub> 50%	45 tons		
5	Water	250 m <sup>3</sup> /day	2,000 VND/m <sup>3</sup>	100,000 m <sup>3</sup> /year
6	FO	400 tons		
7	Electricity	200 kWh	800 VND/kWh	16 hours/day

### 2.3 Future Plans

Uncertain



### **3 Management Technology**

- (1) The weaving machines in use are very old. They are working well, but are terribly inefficient.
- (2) The garment washing plant is new and has not been established very long, so it is very clean, tidy and things are in order. 60% of products are exported to Japan and the plant is requested to be kept tidy by Japanese buyer.
- (3) The situation at the inspection process is the same as at the garment washing plant.
- (4) The dyeing plant is not as good as the other 2 plants. Hank dyeing is done by traditional hand-dyeing.
- (5) The printing process is also done manually.

### **4 Industrial Wastewater Treatment and Discharge**

- (1) Chemical treatment (Coagulation and sedimentation) facilities have been completed and will serve as the companies wastewater treatment facilities. These facilities will be in operation shortly. However, there are some problems with the design conditions.
- (2) The wastewater treatment system has just been completed and will begin operation by the end of 1999.
- (3) This system consists of coagulation and sedimentation.
- (4) In the future, a biological system will be added.
- (5) Wastewater quantity is 250 m<sup>3</sup>/day.
- (6) Sampling

Wastewater samples were taken at the following spots for analysis in this study.

Date: 16 December 1999

S1 : At Wince dying m/c ( washing water after bleaching)

S2 : Wastewater discharged from the dying factory

S3 : Discharged wastewater from the whole factory (to city sewage)

S4 : At Wince dying m/c ( washing water after dying)

- (7) Wastewater Quality

Wastewater qualities analyzed by Hanoi University Civil Engineering Center of Environment Engineering of Towns and Industrial Areas (CEETIA) are shown in Table 4.

**Table 4 Wastewater Quality in December 1999**

	Unit	S1	S2	S3	S4
Temperature		95	22.2	31.8	96
PH		10.4	7.4	9.9	10.8
Elec. Conductivity	μ S/cm	960	1440	271	27520
Turbidity	NTU	1136	123	19	23
Oil content	mg/l	0	Trace	Trace	0
BOD	mg/l	2504	1674	84.7	104
COD	mg/l	19640	4870	433	467
DO	mg/l	4.35	1.31	6.64	1.85
SS	mg/l	1200	141	25	30
Total Nitrogen	mg/l	115	18.5	4.1	4.25
Residual Chlorine	mg/l	Trace	Trace	Trace	1.06
SO <sub>4</sub>	mg/l	292	384	82.4	60.4
Cyanogen	mg/l				

### 5. Recommendations

- (1) Some of the weaving machines are being renovated. It is expected to be managed in the same way at its washing plant not to be dragged into old machines.
- (2) Sufficient maintenance of old machines should be carried out.
- (3) A 5S should be introduced at the dyeing plant.
- (4) Printing facilities should be improved (renewed) and converted to a mechanical system.
- (5) It is recommended that not only should ISO9000 certification be obtained, but also that quality control methods, such as TQM, should be introduced.
- (6) It may be difficult to clear regulation standards at the wastewater treatment plant which is using only chemical treatment. It is necessary to conduct a study on the possibility of introducing a biological treatment system as soon as possible.

**Hue Textile company**

Survey Date: 3 &amp; 4 March 2000

**1. General****1.1 Profile**

Hue Textile Company is a state-owned company that was established in 1988 as a textile company. The company profile of Hue Textile Company is summarized in Table 1.

**Table 1 Enterprise Profile**

Name of Company:	Hue Textile Company
Ownership:	State-owned
Address:	Xa Thuy duong, Huong Thuy, unH Thua thien Hue
Tel:	054 822011, 054 822012
Director:	HUYNH VAN THAO
Established:	1988
Corporate Capital:	
Number of Employees:	1800
Main Products:	Yarns, Towel, Garment

**1.2 Business Status****1.2.1 Production**

Table 2 shows production and sales of the Company in 1998.

More than 90% of towels and knitting garment products are exported to Japan, Taiwan, Germany, Poland, etc.

**Table 2 Production and Sales in 1998**

Products	Capacity	Turnover
Yarns	4,200 ton	
Towel	200 ton	
Knitting Products	400 ton	
Total	4,800 ton	160 billion VND


**1.2.2 Debt**

Unknown

## 2. Production Technology

### 2.1 Process

The Process flow of the factory is shown in Figure 1.



**Figure 1 Process Flow of the Factory**

### 2.2 Unit Consumption

The unit consumption of the raw materials and utilities is shown in Table 3.

**Table 3 Unit Consumption of Raw Materials and Utilities**

Material	Quantity	Expenses(VND)
1. Spinning	4,200 ton	
(1) Cotton	2,500 ton	
(2) PE Fiber	2,000 ton	
(3) Water	240,000 m <sup>3</sup>	
(4) Electricity	22,500,000 kWh	
. Knitting Process	400 ton	
(1) Water	88,000 m <sup>3</sup>	
(2) FO.	600 ton	
(3) Electricity	1,500,000 kWh	
(4) Dyestuff	7,014.2 kg	
(5) Caustic Soda	5,400 kg	
(6) Bleaching Chemicals	18,000 kg	
. Towel	260 ton	
(1) Yarns	230 ton	
(2) Water	50,000 m <sup>3</sup>	
(3) Electricity	700,000 kWh	
(4) Dyestuff	3,600 kg	
(5) Caustic Soda	9,000 kg	

### **2.3 Future Plans**

- (1) To invest in a combed spinning line of 8,000 spindles.
- (2) To upgrade to a total of 50,000 spindles in the existing spinning mill.
- (3) To increase the capacity of the knitting mill up to 1,500 ton/year.
- (4) To invest in a weaving and dyeing, finishing mill with capacity of 10,000,000 m<sup>2</sup> /year


### **3. Management Technology**

- (1) The spinning plant is in good order and tidy. Operation management is good too.
- (2) The weaving and knitting machines which are at another site are very old and the maintenance on them is inefficient. They have many problems with quality.
- (3) The dyeing plant of the main factory is kept in good order, is tidy and is clean. They do not have so many problems with operation management.
- (4) A water treatment system has been installed in the dyeing plant, but it is in disorder, untidy and dirty. The operation management is at a very low level. For example, coal in the filter tank has not been changed for 3 years since the plant was start up.
- (5) The flow rate of the wastewater from the factory is 300 m<sup>3</sup>/day. The quality of the wastewater is out of the standards in Vietnam.

### **4. The Treatment and Discharge of Industrial Wastewater**

- (1) Volume of the wastewater: 300 m<sup>3</sup>/day
- (2) Method of wastewater treatment:
  - a. Neutralization
  - b. Trickling Filter
  - c. Filtration

(3) The wastewater treatment system:



**Figure-2 Wastewater Treatment System**

(4) Sampling:

Wastewater samples were taken at following spots for analysis in this study.

Date: 4 March 2000

S1 : At the outlet of the dyeing factory : Sampling time:10:17

S2 : At the Regulation Tank : Sampling time:11:00

S3 : At the outlet of the dyeing factory : Sampling time:12:00

S4: At the Regulation Tank : Sampling time:11:45

S5: At the outlet of the Carbon Filtration Tank : Sampling time:11:50

(5) The quality of the wastewater

Wastewater qualities analyzed by Hanoi University Civil Engineering Center of Environment Engineering of Towns and Industrial Areas (CEETIA) are shown in Table 4.

**Table 4 Wastewater Quality in March 2000**

	Unit	S1	S2	S3	S4	S5
Temperature		33.7		31.5	32.4	27.5
pH		10.67		10.3	10.7	9.76
Elec. Conductivity	μ S/cm			6,060	10,800	1,400
Turbidity	NTU	83	21	32.6	16.2	16.8
Oil content	mg/l	Trace	1	Trace	Trace	2
BOD	mg/l	231	186	194	114	273
COD	mg/l	720	1020	520	1120	920
DO	mg/l	2.59		4.49	4.54	8.06
SS	mg/l	91	74	35	28	18
Total Nitrogen	mg/l	24.5	31.5	17.5	21	28.2
Residual Chlorine	mg/l	0	53.2	0	92.4	0
SO <sub>4</sub>	mg/l	893	908	791	881	326
Cyanogen	mg/l					

**5. Recommended Countermeasures for Improvement**

- (1) Management of the wastewater treatment system should be thoroughly improved.
  - a. Operating conditions should be cleared.
  - b. Operators should be trained.
  - c. The equipment should be maintained.
  - d. The system, including its surroundings should be kept in good order and clean.
- (2) The quality of the treated water is not clearing Vietnam standards because the design of the existent treatment system is not adequate for this factory. When planning for the next treatment system is carried out, a careful survey is necessary for introducing a suitable system.
- (3) It is desired that the company will makes efforts to realize their very aggressive future plans.
- (4) They are investigating the possibility ISO9002 acquisition. Furthermore, the company should introduce activities such as TQC, 5S,etc. in succession.

