

## **6-4. Soundness of the Bridges**

## **1. Bridge Soundness Sheet**

**Table-A Bridge Soundness Sheet (Sheet No. ) Bridge No.7**

NAME OF BRIDGE : Prek Chik		CLASS OF ROAD		CROSSING: NAME OF RIVER OR ROAD		DATE OF INSPECTION : Jan. 31.2000		INSPECTION BY Y. Takai	
Design Information		Yes		No		Date of Construction : 1962-68		Maintenance by MPWT	
Type of Bridge		Superstructure		Simple RC-T Girder		Design Loading			
STA. 11+380		Substructure		Abutment		Design Standard		BS AASHTO	
				Pier		Skew of Bridge		Skew CURVE (deg.R= )	
Length of Bridge		12 m		Span		1*12.0 m		Road	
Width of Bridge		11.02 m		Carriage		9.1 m		Ped. 2*0.65 m	
Affixed Articles		Overall		Kind		Condition of Crossing		(River)	
Traffic Volume		(year)		Ratio of Heavy Vehicle (year)		Others			
Final Record of Repair		Pavement		Deck Slab		Main Beam		Painting	
				Expansion Joint					
Others : The revetments have already been repaired by the steel sheet piles.									
Component		Conditions Of Damage				Component		Conditions of Damage	
Pavement		(Good) Wave , Rut , Crack , Pothole , Others : Crack in the approach road				Abutment (PP side)		(Good) Crack , Spall , Deformation , Rebar-exposed , Broken , Settlement , Scouring , Others : The pile diameter is 41.7 cm. The lower parts of piles are corroded.	
(Type : AS )						(Type : Steel Pile )			
Curb		(Good) Scale , Crack , Spall , Rebar-exposed , Others				Abutment (KC side)		(Good) Crack , Spall , Deformation , Rebar-exposed , Broken , Settlement , Scouring , Others : The pile diameter is 41.7 cm. The lower parts of piles are corroded.	
(Type : RC )						(Type : Steel Pile )			
Railing		(Good) Scale , Crack , Spall , Rebar-exposed , Others				Pier		(Good) Crack , Spall , Deformation , Rebar-exposed , Broken , Settlement , Scouring , Others	
(Type : RC )						(Type : Steel Pile )			
Deck slab		(Good) Honeycombs , Crack , Deformation , Rebar-exposed , Other				Pier		(Good) Crack , Spall , Deformation , Rebar-exposed , Broken , Settlement , Scouring , Others	
(Type : RC )						(Type : Steel Pile )			
Main Beam		(Good) Honeycombs , Crack , Deformation , Rebar-exposed , Other				Pier		(Good) Crack , Spall , Deformation , Rebar-exposed , Broken , Settlement , Scouring , Others	
(Type : RC )						(Type : Steel Pile )			
Cross Beam		(Good) Crack , Deformation , Rebar-exposed , Others				Others : The lower parts of steel sheet pile revetments are pushed out. It occurred many cracks to the transverse direction in the pavement on the top of backfill.			
(Type : RC )						Comment			
Painting		Condition				Rating		Rating	
						1		1	
Exp.Joint		(Good) Abnormal Sound , Deformation , Gap , Broken , Others				Rating		Rating	
(Type : AS )						2		1	
Shoe		(Good) Abnormal Sound , Deformation , Gap , Broken , Others				Rating		Rating	
(Type : Steel )						1		3	
Drainage		(Good) Clogged Leakage , Broken , Others				Rating		Rating	
(Type : Steel )						1		3	
<Plan / Profiles>									
<p>1) The superstructure is sound although the concrete is a few deteriorated.</p> <p>2) The type pf abutment is steel pipe pile bent and the corrosion is in progress on the lower part of steel pipe piles.</p> <p>3) The abutment beams and revetment steel sheet piles are jointed. It will damage the abutment in case the steel sheet piles move due to embankment sliding.</p> <p>4) The embankment sliding can be seen to the longitudinal direction. It caused many cracks on the pavement.</p> <p>5) The steel sheet piles are temporary structure, and the investigation shall be conducted on them in detail.</p>									
<Remarks>									
<p>PP : Phnom Penh , KC : Kampong Cham</p> <p>○ : corresponding item</p> <p>AS : Asphalt</p> <p>RC : Reinforced Concrete</p>									

**Table-A Bridge Soundness Sheet (Sheet No. ) Bridge No.10**

NAME OF BRIDGE : Prek Ta Som		CLASS OF ROAD		CROSSING: NAME OF RIVER OR ROAD		DATE OF INSPECTION : Jan. 31, 2000		INSPECTION BY Y. Takai	
Design Information		Yes		No		Date of Construction :		Maintenance by MPWT	
Type of Bridge		Superstructure		Simple RC-T Girder		Design Loading		Yes	
STA. 15+460		Substructure		Abutment		Design Standard		BS (AASHTO) RUSSIA OTHERS( )	
		Pier				Skew of Bridge		(Square) Skew Curve (deg.R= )	
Length of Bridge		12 m		Span		1*12.0 m		Road	
Width of Bridge		11.00 m		Carriage		9.1 m		Pede. 2*0.65 m	
Affixed Articles		Kind		Number				Design Quantity	
Traffic Volume		(year)		Ratio of Heavy Vehicle (year)		Others		10.8 m 4.0 m 0.6 m m3/sec	
Final Record of Repair		Pavement		Deck Slab		Main Beam		Painting	
		Expansion Joint						Bearing	
		Others : The cracks on the revetments due to settlement have already been repaired by mortar.						Drainage	
								Curb	
								Affixed Articles	

Component	Conditions Of Damage	Rating	Component	Conditions of Damage	Rating
Pavement	(Good) Wave , Rut , Crack , Pothole , Others :	1	Abutment (PP side)	(Good) Crack , Spall , Deformation , Rebar-exposed , Broken , Settlement , Scouring , Others :	1
Curb	(Good) Scale , Crack , Spall , Rebar-exposed , Others	1	Abutment (KC side)	(Good) Crack , Spall , Deformation , Rebar-exposed , Broken , Settlement , Scouring , Others :	1
Railing	(Good) Scale , Crack , Spall , Rebar-exposed , Others	1	Pier	(Good) Crack , Spall , Deformation , Rebar-exposed , Broken , Settlement , Scouring , Others	
Deck slab	(Good) Honeycombs , Crack , Deformation , Rebar-exposed , Other	1	Pier	(Good) Crack , Spall , Deformation , Rebar-exposed , Broken , Settlement , Scouring , Others	
Main Beam	(Good) Honeycombs , Crack , Deformation , Rebar-exposed , Other	1	Others : The revetments are settled on both side, and it causes some crack on the revetments.		
Cross Beam	(Good) Crack , Deformation , Rebar-exposed , Others	1	Comment		
Painting	Condition		OVERALL EVALUATION RATING		
Exp.Joint	(Good) Abnormal Sound , Deformation , Gap , Broken , Others	2	1) No damage detected on the basis of the inspection results.		
Shoe	(Good) Abnormal Sound , Deformation , Gap , Broken , Other (None)		2) Damage has been detected and a follow-up survey is required.		
Drainage	(Good) Clogged Leakage, Broken , Others	1	3) There is significant damage and a detailed survey needs to be carried out to establish whether repair work is to be carried out or not.		
			4) There is significant damage and urgent repair is required or the bridge has to be closed to traffic or restriction on vehicle weight to be imposed.		
			(or to be re-constructed new bridge)		
Final rating			Super Structure		
			Sub Structure		

<Plan / Profile>		<Remarks>	
1) The superstructure and substructures are sound although the concrete is a few deteriorated.		PP : Phnom Penh , KC : Kampong Cham	
2) The revetments around the abutments are settled. It causes some cracks on it. The regular inspection is required.		○ : corresponding item	
		AS : Asphalt	
		RC : Reinforced Concrete	

**Table-A Bridge Soundness Sheet (Sheet No. ) Bridge No.11**

NAME OF BRIDGE : Prek Ta Pich		CLASS OF ROAD		CROSSING: NAME OF RIVER OR ROAD		DATE OF INSPECTION : Jan. 31, 2000		INSPECTION BY : Y. Takai	
Design Information		Yes		No		Construction By : USA		Maintenance by : MPWT	
Type of Bridge		Superstructure		Simple RC-T Girder		Design Loading		Yes	
STA. 16+520		Substructure		Abutment		Design Standard		BS	
		Pier		Steel Pipe Pile Bent Type		Skew of Bridge		RUSSIA OTHERS( )	
Length of Bridge		12 m		Span		Condition of Crossing		Curve (deg.R= )	
Width of Bridge		11.00 m		Carriage 9.0 m		Pede. 2*0.70 m		Free Board	
Affixed Articles		Kind		Number		11.0 m		4.7 m	
Traffic Volume		(year)		Ratio of Heavy Vehicle (year)		Others		Design Quantity	
Final Record of Repair		Pavement		Deck Slab		Main Beam		Painting	
		Railing		Expansion Joint		Bearing		Curb	
		Others : The cracks on the revetments due to settlement have already been repaired by mortar.						Affixed Articles	

Component	Conditions Of Damage	Rating	Component	Conditions of Damage	Rating
Pavement (Type : AS )	Good, Wave , Rut , Crack , Pothole , Others :	1	Abutment (PP side) (Type : Steel Pile )	Good, Crack , Spall , Deformation , Rebar-exposed , Broken , Settlement , Scouring , Others :	1
Curb (Type : RC )	Good, Scale , Crack , Spall , Rebar-exposed , Others	1	Abutment (KC side) (Type : Steel Pile )	Good, Crack , Spall , Deformation , Rebar-exposed , Broken , Settlement , Scouring , Others :	1
Railing (Type : RC )	Good, Scale , Crack , Spall , Rebar-exposed , Others	1	Pier (Type : )	Good, Crack , Spall , Deformation , Rebar-exposed , Broken , Settlement , Scouring , Others	
Deck slab (Type : RC )	Good, Honeycombs , Crack , Deformation , Rebar-exposed , Other	1	Pier (Type : )	Good, Crack , Spall , Deformation , Rebar-exposed , Broken , Settlement , Scouring , Others	
Main Beam (Type : RC )	Good, Honeycombs , Crack , Deformation , Rebar-exposed , Other	1	Others : The revetments are settled on PP side. It caused some cracks on the revetments (They have already been repaired.)		2
Cross Beam (Type : RC )	Good, Crack , Deformation , Rebar-exposed , Others	1	Comment		
Painting	Condition		OVERALL EVALUATION RATING		
Exp.Joint (Type : AS )	Good, Abnormal Sound , Deformation , Gap , Broken , Others	1	1. No damage detected on the basis of the inspection results. 2. Damage has been detected and a follow-up survey is required. 3. There is significant damage and a detailed survey needs to be carried out to establish whether repair work is to be carried out or not. 4. There is significant damage and urgent repair is required or the bridge has to be closed to traffic or restriction on vehicle weight to be imposed. (or to be re-constructed new bridge)		
Shoe (Type : )	Good, Abnormal Sound , Deformation , Gap , Broken , Other		Final rating		
Drainage (Type : Steel )	Good, Clogged Leakage, Broken , Others	1	Super Structure		
			Sub Structure		
<Plan / Profile>		<Remarks>			
1) The superstructure and substructures is sound although the concrete is a few deteriorated. 2) The revetments around the abutments are settled. The cracks caused by the settlement have already repaired. The regular inspection is required.		PP : Phnom Penh , KC : Kampong Cham ○ : corresponding item AS : Asphalt RC : Reinforced Concrete			

**Table-A Bridge Soundness Sheet (Sheet No. ) Bridge No.12**

NAME OF BRIDGE : Prek Tabenn		CLASS OF ROAD		CROSSING: NAME OF RIVER OR ROAD		DATE OF INSPECTION : Jan. 29, 2000		INSPECTION BY Y. Takai	
Design Information		Yes		No		Date of Construction : 1962-68		Maintenance by MPWT	
Type of Bridge		Superstructure		Simple RC-T Girder		Design Loading			
STA. 17+470		Substructure		Abutment		Design Standard		BS AASHTO RUSSIA OTHERS( )	
		Pier		Steel Pipe Pile Bent Type		Skew of Bridge		Curve (deg, R= )	
Length of Bridge		24 m		Span		2*12.0 m			
Width of Bridge		11.04 m		Carriage		9.1 m		Free Board	
Affixed Articles		Kind		Number		2*0.67 m		Design Quantity	
Traffic Volume		(year)		Ratio of Heavy Vehicle (year)		Others		m3/sec	
Final Record of Repair		Pavement		Deck Slab		Main Beam		Painting	
		Others :		Expansion Joint		Bearing		Drainage	
								Curb	
								Affixed Articles	

Component	Conditions Of Damage	Rating	Component	Conditions of Damage	Rating
Pavement (Type : AS )	Good, Wave, Rut, Crack, Pothole, Others : Crack in the approach road	1	Abutment (PP side) (Type : Steel Pile )	Good, Crack, Spall, Deformation, Rebar-exposed, Broken, Settlement, Scouring, Others :	1
Curb (Type : RC )	Good, Scale, Crack, Spall, Rebar-exposed, Others	1	Abutment (KC side) (Type : Steel Pile )	Good, Crack, Spall, Deformation, Rebar-exposed, Broken, Settlement, Scouring, Others :	1
Railing (Type : RC )	Good, Scale, Crack, Spall, Rebar-exposed, Others	1	Pier (Type : Steel Pile )	Good, Crack, Spall, Deformation, Rebar-exposed, Broken, Settlement, Scouring, Others : The pile diameter is 40.7 cm. The corrosion is in progress.	2
Deck slab (Type : RC )	Good, Honeycombs, Crack, Deformation, Rebar-exposed, Other	3	Pier (Type : )	Good, Crack, Spall, Deformation, Rebar-exposed, Broken, Settlement, Scouring, Others	
Main Beam (Type : RC )	Good, Honeycombs, Crack, Deformation, Rebar-exposed, Other	2	Others :		1
Cross Beam (Type : RC )	Good, Crack, Deformation, Rebar-exposed, Others	1	Comment		
Painting	Condition		OVERALL EVALUATION RATING		
Exp Joint (Type : AS )	Good, Abnormal Sound, Deformation, Gap, Broken, Others	3	1. No damage detected on the basis of the inspection results.		
Shoe (Type : )	Good, Abnormal Sound, Deformation, Gap, Broken, Other Nong		2. Damage has been detected and a follow-up survey is required.		
Drainage (Type : Steel )	Good, Clogged Leakage, Broken, Others	1	3. There is significant damage and a detailed survey needs to be carried out to establish whether repair work is to be carried out or not.		
			4. There is significant damage and urgent repair is required or the bridge has to be closed to traffic or restriction on vehicle weight to be imposed.		
			(or to be re-constructed new bridge)		

<p>&lt;Plan / Profile&gt;</p> <p>1) The expansion joints should be repaired.</p> <p>2) There are some cracks on the deck slab and girder ends.</p> <p>3) The tracking observation and repair investigation are required.</p>	<p>&lt;Remarks&gt;</p> <p>PP : Phnom Penh, KC : Kampong Cham</p> <p>○ : corresponding item</p> <p>AS : Asphalt</p> <p>RC : Reinforced Concrete</p>
--	--

Table-A Bridge Soundness Sheet (Sheet No. )

Bridge No.13

NAME OF BRIDGE : Prek Thei		CLASS OF ROAD : CROSSING : NAME OF RIVER OR ROAD		DATE OF INSPECTION : Jan. 29, 2000		INSPECTION BY : Y. Takai	
Design Information		Yes (No)		Construction By : USA		Maintenance by : MPWT	
Type of Bridge		Superstructure : Simple RC-T Girder		Design Loading		Load limitation : (No) Yes	
STA. 18+560		Substructure : Abutment		Design Standard		BS : AASHTO RUSSIA OTHERS( )	
		Pier		Skew of Bridge		Curve (deg, R= )	
Length of Bridge		24 m Span		2*12.0 m			
Width of Bridge		11.00 m		Carriage 9.1 m		Pede. 2*0.65 m	
Affixed Articles		Kind		Number		Design Quantity	
Traffic Volume		(year)		Ratio of Heavy Vehicle (year)		22.5 m 6.0 m 1.2 m	
Final Record of Repair		Pavement		Deck Slab		Bearing	
		Others : The revetments have already been repaired.		Expansion Joint		Curb	
Component		Conditions Of Damage		Rating		Conditions of Damage	
Pavement		Good, Wave, Rut, Crack, Pothole, Others : Crack in the approach road		1		Good, Crack, Spall, Deformation, Rebar-exposed, Broken, Settlement, Scouring, Others :	
Curb		Good, Scale, Crack, Spall, Rebar-exposed, Others		1		Good, Crack, Spall, Deformation, Rebar-exposed, Broken, Settlement, Scouring, Others :	
Railing		Good, Scale, Crack, Spall, Rebar-exposed, Others		1		Good, Crack, Spall, Deformation, Rebar-exposed, Broken, Settlement, Scouring, Others :	
Deck slab		Good, Honeycombs, Crack, Deformation, Rebar-exposed, Other		2		Good, Crack, Spall, Deformation, Rebar-exposed, Broken, Settlement, Scouring, Others : The pile diameter is 41.4 cm. The corrosion is in progress.	
Main Beam		Good, Honeycombs, Crack, Deformation, Rebar-exposed, Other		2		Good, Crack, Spall, Deformation, Rebar-exposed, Broken, Settlement, Scouring, Others :	
Cross Beam		Good, Crack, Deformation, Rebar-exposed, Others		1		Others : The revetments are settled on KC side. It caused some cracks on the revetments	
Painting		Condition				Comment	
Exp-Joint		Good, Abnormal Sound, Deformation, Gap, Broken, Others		1		OVERALL EVALUATION RATING	
Shoe		Good, Abnormal Sound, Deformation, Gap, Broken, Other (No)				1. No damage detected on the basis of the inspection results.	
Drainage		Good, Clogged Leakage, Broken, Others		1		2. Damage has been detected and a follow-up survey is required.	
						3. There is significant damage and a detailed survey needs to be carried out to establish whether repair work is to be carried out or not.	
						4. There is significant damage and urgent repair is required or the bridge has to be closed to traffic or restriction on vehicle weight to be imposed.	
						(or to be re-constructed new bridge)	
<Plan / Profile>						<Remarks>	
						PP : Phnom Penh, KC : Kampong Cham	
						AS : Asphalt	
						RC : Reinforced Concrete	

**Table-A Bridge Soundness Sheet (Sheet No. ) Bridge No.17**

NAME OF BRIDGE : Prek Hok Leng		CLASS OF ROAD		CROSSING: NAME OF RIVER OR ROAD		CONSTRUCTION BY		DATE OF INSPECTION : Jan. 29, 2000		INSPECTION BY	
Yes		No		USA		USA		Y. Takai		Maintenance by	
Superstructure		Simple RC-T Girder		Steel Pipe Pile Bent Type		Design Loading		Date of Construction : 1962-68		MPWT	
Substructure		Abutment		Steel Pipe Pile Bent Type		Design Standard		Load limitation		Yes	
STA. 31+790		Pier		Steel Pipe Pile Bent Type		BS AASHTO		RUSSIA		OTHERS( )	
Length of Bridge		36.0 m		Span		3*12.0 m		Skew		Curve (deg.R= )	
Width of Bridge		11.05 m		Carriage		9.07 m		Pede.		2*0.69 m	
Affixed Articles		Kind		Number		Ratio of Heavy Vehicle (year)		Width of River		Free Board	
Traffic Volume		(year)		Main Beam		Painting		Depth		Design Quantity	
Final Record of Repair		Revetment		Deck Slab		Expansion Joint		Drainage		Railing	
Others :		Others :		Others :		Others :		Curb		Affixed Articles	

Component	Conditions Of Damage	Rating	Component	Conditions of Damage	Rating
Pavement (Type : AS )	Good Wave , Rut , Crack , Pothole , Others : Crack in the approach road	2	Abutment (PP side) (Type : Steel Pile )	Good Crack , Spall , Deformation , Rebar-exposed , Broken , Settlement , Scouring , Others :	1
Curb (Type : RC )	Good Scale , Crack , Spall , Rebar-exposed , Others	1	Abutment (KC side) (Type : Steel Pile )	Good , Crack , Spall , Deformation , Rebar-exposed , Broken , Settlement , Scouring , Others :	2
Railing (Type : RC )	Good Scale , Crack , Spall , Rebar-exposed , Others	1	Pier (Type : Steel Pile )	Good , Crack , Spall , Deformation , Rebar-exposed , Broken , Settlement , Scouring , Others : The lower parts of steel piles are widely corroded.	2
Deck slab (Type : RC )	Good Honeycombs , Crack , Deformation , Rebar-exposed , Other	1	Pier (Type : )	Good , Crack , Spall , Deformation , Rebar-exposed , Broken , Settlement , Scouring , Others	
Main Beam (Type : RC )	Good Honeycombs , Crack , Deformation , Rebar-exposed , Other	1	Others : The revetments are settled on KC side, and it caused many cracks.		
Cross Beam (Type : RC )	Good Crack , Deformation , Rebar-exposed , Others	1	Some cracks on the revetments on KC side can be seen.		
Painting	Condition		Comment		
OVERALL EVALUATION RATING					
Exp-Joint (Type : AS )	Good , Abnormal Sound , Deformation , Gap , Broken , Others	3	1. No damage detected on the basis of the inspection results.		
Shoe (Type : )	Good , Abnormal Sound , Deformation , Gap , Broken , Other Non		2. Damage has been detected and a follow-up survey is required.		
Drainage (Type : Steel )	Good , Chugged Leakage , Broken , Others	1	3. There is significant damage and a detailed survey needs to be carried out to establish whether repair work is to be carried out or not.		
			4. There is significant damage and urgent repair is required or the bridge has to be closed to traffic or restriction on vehicle weight to be imposed.		
			(or to be re-constructed new bridge)		
<Plan / Profiles>		<Remarks>			
1) The superstructure is a few deteriorated.		PP : Phnom Penh , KC : Kampong Cham			
2) The abutments themselves are sound. The revetments are settled due to scouring and many cracks can be seen on it. The early repairment is required.		○ : corresponding item			
3) The lower parts of steel pipe piles on the piers are corroded.		AS : Asphalt			
		RC : Reinforced Concrete			



**Table-A Bridge Soundness Sheet (Sheet No. ) Bridge No.18**

NAME OF BRIDGE : Prek Ta Oun		CLASS OF ROAD		CROSSING: NAME OF RIVER OR ROAD		DATE OF INSPECTION : Jan. 29/2000		INSPECTION BY Y. Takai	
Design Information		Yes		No		Construction By USA		Date of Construction : 1962-68	
Type of Bridge		Superstructure		Simple RC-T Girder		Design Loading		Maintenance by MPWT	
STA. 31+940		Substructure		Abutment		Steel Pipe Pile Bent Type		Load limitation (N)	
		Pier		Span		Steel Pipe Pile Bent Type		BS AASHTO RUSSIA OTHERS( )	
Length of Bridge		36.0 m		Span		3*12.0 m		Skew Curve (deg.R= )	
Width of Bridge		11.00 m		Carriage		9.10 m		Road	
Affixed Articles		Kind		Number		2*0.65 m		River	
Traffic Volume		(year)		Ratio of Heavy Vehicle (year)		Others		Width of River	
Final Record of Repair		Pavement		Deck Slab		Main Beam		Painting	
		Others : The cracks on the revetments have already been repaired by mortar.		Expansion Joint		Bearing		Drainage	
								Curb	
								Affixed Articles	

Component	Conditions Of Damage	Rating	Component	Conditions of Damage	Rating
Pavement (Type : AS )	Good Wave , Rut , Crack , Pothole , Others : Crack in the approach road	1	Abutment (PP side) (Type : Steel Pile )	Good Crack , Spall , Deformation , Rebar-exposed , Broken , Settlement , Scouring , Others :	1
Curb (Type : RC )	Good Scale , Crack , Spall , Rebar-exposed , Others	1	Abutment (KC side) (Type : Steel Pile )	Good Crack , Spall , Deformation , Rebar-exposed , Broken , Settlement , Scouring , Others :	1
Railing (Type : RC )	Good Scale , Crack , Spall , Rebar-exposed , Others	1	Pier (Type : Steel Pile )	Good Crack , Spall , Deformation , Rebar-exposed , Broken , Settlement , Scouring , Others :	2
Deck slab (Type : RC )	Good Honeycombs , Crack , Deformation , Rebar-exposed , Other	1	Pier (Type : )	Good Crack , Spall , Deformation , Rebar-exposed , Broken , Settlement , Scouring , Others :	
Main Beam (Type : RC )	Good Honeycombs , Crack , Deformation , Rebar-exposed , Other	1	Others :		
Cross Beam (Type : RC )	Good Crack , Deformation , Rebar-exposed , Others	1	Comment		
Painting	Condition		OVERALL EVALUATION RATING		
Exp-Joint (Type : AS )	Good , Abnormal Sound , Deformation , Gap (Broken) , Others	2	1. No damage detected on the basis of the inspection results.		
Shoe (Type : )	Good , Abnormal Sound , Deformation , Gap , Broken , Other (Non)		2. Damage has been detected and a follow-up survey is required.		
Drainage (Type : Steel )	Good , Clogged Leakage , Broken , Others	1	3. There is significant damage and a detailed survey needs to be carried out to establish whether repair work is to be carried out or not.		1
			4. There is significant damage and urgent repair is required or the bridge has to be closed to traffic or restriction on vehicle weight to be imposed. (or to be re-constructed new bridge)		1

<Plan / Profiles>	<Remarks> PP : Phnom Penh , KC : Kampong Cham AS : Asphalt RC : Reinforced Concrete
-------------------	--

**Table-A Bridge Soundness Sheet (Sheet No. ) Bridge No.22**

NAME OF BRIDGE : Prek Kra Poes		CLASS OF ROAD		CROSSING: NAME OF RIVER OR ROAD		DATE OF INSPECTION : Jan. 28. 2000		INSPECTION BY Y. Takai	
Design Information		Yes		Construction By USA		Date of Construction : 1962-68		Maintenance by MPWT	
Type of Bridge		Superstructure		Simple RC-T Girder		Design Loading		Yes	
STA. 36+880		Substructure		Abutment		Design Standard			
		Pier		Steel Pipe Pile Bent Type		Skew of Bridge		BS AASHTO RUSSIA OTHERS( )	
Length of Bridge				Span		Condition of Crossing		Curve (deg.R= )	
				120.0 m		10*12.0 m			
Width of Bridge				Carriage		Pavement		Free Board	
				11.00 m		9.10 m		120.0 m	
Affixed Articles		Kind		Number		Design Quantity		0.3 m	
								m3/sec	
Traffic Volume		(year)		Ratio of Heavy Vehicle (year)		Others			
Final Record of Repair		Pavement		Deck Slab		Painting		Curb	
								Affixed Articles	
Others : Three (3) span superstructures have been replaced. The 7th Pier from PP (P7) has been replaced.									

Component	Conditions Of Damage	Rating	Component	Conditions of Damage	Rating
Pavement (Type : AS )	Good, Wave, Rut, Crack, Pothole, Others : Crack in the approach road	1	Abutment (PP side) (Type : Steel Pile )	Good, Crack, Spall, Deformation, Rebar-exposed, Broken, Settlement, Scouring, Others :	1
Curb (Type : RC )	Good, Scale, Crack, Spall, Rebar-exposed, Others	1	Abutment (RC side) (Type : Steel Pile )	Good, Crack, Spall, Deformation, Rebar-exposed, Broken, Settlement, Scouring, Others :	1
Railing (Type : RC )	Good, Scale, Crack, Spall, Rebar-exposed, Others	1	Pier (Type : Steel Pile )	Good, Crack, Spall, Deformation, Rebar-exposed, Broken, Settlement, Scouring, Others : The steel piles are widely corroded.	3
Deck slab (Type : RC )	Good, Honeycombs, Crack, Deformation, Rebar-exposed, Other	1	Pier (Type : Steel Pile )	Good, Crack, Spall, Deformation, Rebar-exposed, Broken, Settlement, Scouring, Others	4
Main Beam (Type : RC )	Good, Honeycombs, Crack, Deformation, Rebar-exposed, Other	1	Others : The revetments on both sides are settled. It causes vertical cracks on them. The cracks have been repaired by mortar.		
Cross Beam (Type : RC )	Good, Crack, Deformation, Rebar-exposed, Others	1	Comment		
Painting	Condition		OVERALL EVALUATION RATING		
Exp-Joint (Type : AS )	Good, Abnormal Sound, Deformation, Gap (Broken), Others	2	1. No damage detected on the basis of the inspection results.		
Shoe (Type : )	Good, Abnormal Sound, Deformation, Gap, Broken, Other (None)		2. Damage has been detected and a follow-up survey is required.		
Drainage (Type : Steel )	Good, Clogged Leakage, Broken, Others	1	3. There is significant damage and a detailed survey needs to be carried out to establish whether repair work is to be carried out or not.		
<Plan / Profile>			4. There is significant damage and urgent repair is required or the bridge has to be closed to traffic or restriction on vehicle weight to be imposed. (or to be re-constructed new bridge)		

1) The superstructures are sound. 2) The steel pipe piles are heavily corroded. 3) The revetments are settled, and it causes some big cracks on them due to pile bent style abutment in high embankment. 4) The investigation of repair is required.		<Remarks> PP : Phnom Penh, KC : Kampong Cham AS : Asphalt RC : Reinforced Concrete
---	--	---

**Table-A Bridge Soundness Sheet (Sheet No. ) Bridge No.23**

NAME OF BRIDGE : Prek Ampong Prasat		CLASS OF ROAD		CROSSING: NAME OF RIVER OR ROAD		DATE OF INSPECTION : Jan. 28, 2000		INSPECTION BY : Y. Takai	
Design Information		Yes		No		Date of Construction : 1962-68		Maintenance by : MPWT	
Type of Bridge		Superstructure		Simple RC-T Girder		Design Loading		Yes	
STA. 37+600		Substructure		Abutment : Reversed T Type (steel pipe pile)		Design Standard			
				Pier : Wall Type (steel pipe pile)		Skew of Bridge		BS (AASHTO) RUSSIA OTHERS( )	
Length of Bridge		60.0 m		Span		3*20.0 m		Curve (deg, R= )	
Width of Bridge		11.45 m		Carriage		9.05 m		Free Board	
Affixed Articles		Overall		Number		2*0.90 m		Design Quantity	
Traffic Volume		(year)		Ratio of Heavy Vehicle		(year)		m <sup>3</sup> /sec	
Final Record of Repair		Pavement		Deck Slab		Main Beam		Painting	
		Others : The revetments on both sides have been repaired.		Expansion Joint		Bearing		Drainage	
								Curb	
								Affixed Articles	

Component	Conditions Of Damage	Rating	Component	Conditions of Damage	Rating
Pavement (Type : AS )	Good, Wave , Rut , Crack , Pothole , Others : Crack in the approach road	1	Abutment (PP side) (Type : Reversed T )	Good, Crack , Spall , Deformation , Rebar-exposed , Broken , Settlement , Scouring , Others :	1
Curb (Type : RC )	Good, Scale , Crack , Spall , Rebar-exposed , Others	1	Abutment (KC side) (Type : Reversed T )	Good, Crack , Spall , Deformation , Rebar-exposed , Broken , Settlement , Scouring , Others :	1
Railing (Type : RC )	Good, Scale , Crack , Spall , Rebar-exposed , Others	1	Pier (Type : Wall Type )	Good, Crack , Spall , Deformation , Rebar-exposed , Broken , Settlement , Scouring , Others : The steel piles are widely corroded.	3
Deck slab (Type : RC )	Good, Honeycombs , Crack , Deformation , Rebar-exposed , Other	1	Pier (Type : )	Good, Crack , Spall , Deformation , Rebar-exposed , Broken , Settlement , Scouring , Others	
Main Beam (Type : RC )	Good, Honeycombs , Crack , Deformation , Rebar-exposed , Other	1	Others : The revetments on both sides are settled. It causes vertical cracks on them. The cracks have been repaired by mortar.		1
Cross Beam (Type : RC )	Good, Crack , Deformation , Rebar-exposed , Others	1	Comment		
Painting	Condition		OVERALL EVALUATION RATING		
Exp. Joint (Type : AS )	Good , Abnormal Sound , Deformation , Gap (Broken , Others	1	1. No damage detected on the basis of the inspection results.		
Shoe (Type : )	Good , Abnormal Sound , Deformation , Gap , Broken , Other (None		2. Damage has been detected and a follow-up survey is required.		1
Drainage (Type : Steel )	Good, Clogged Leakage, Broken , Others	1	3. There is significant damage and a detailed survey needs to be carried out to establish whether repair work is to be carried out or not.		
<Plan / Profiles>			4. There is significant damage and urgent repair is required or the bridge has to be closed to traffic or restriction on vehicle weight to be imposed. (or to be re-constructed new bridge)		1

1) The superstructure and substructures are sound. 2) The revetments have been repaired and reinforced.		<Remarks> PP : Phnom Penh , KC : Kampong Cham ○ : corresponding item AS : Asphalt RC : Reinforced Concrete	
--	--	--	--

**Table-A Bridge Soundness Sheet (Sheet No. ) Bridge No.24**

NAME OF BRIDGE : Prek Ampong Prab 1		CLASS OF ROAD		CROSSING : NAME OF RIVER OR ROAD		DATE OF INSPECTION : Jan. 27,2000		INSPECTION BY : Y. Takai	
Design Information		Yes		Construction By : USA		Date of Construction : 1962-68		Maintenance by : MPWT	
Type of Bridge		Superstructure		Simple RC-T Girder		Design Loading		Load limitation : (No) Yes	
STA. 39+890		Substructure		Abutment		Design Standard		BS (AASHTO) RUSSIA OTHERS( )	
Length of Bridge		Pier		Steel Pipe Pile Bent Type		Skew of Bridge		Skew Curve (deg.R= )	
Width of Bridge		Span		84.0 m		Condition of Crossing		Road	
Affixed Articles		Overall		11.00 m		Carriage		9.00 m	
Traffic Volume		Kind		Number		Ratio of Heavy Vehicle (year)		Others	
Final Record of Repair		Pavement		Deck Slab		Main Beam		Painting	
		Expansion Joint		Bearing		Drainage		Railing	
		Curb		Curb		Affixed Articles			
Others : The first span girder, abutments and revetments on KC side have been replaced.									

Component	Conditions Of Damage	Rating	Component	Conditions of Damage	Rating
Pavement (Type : AS )	Good Wave , Rut , Crack , Pothole , Others : Crack in the approach road	1	Abutment (PP side) (Type : Steel Pile )	Good Crack , Spall , Deformation , Rebar-exposed , Broken , Settlement , Scouring , Others :	1
Curb (Type : RC )	Good Scale , Crack , Spall , Rebar-exposed , Others	1	Abutment (KC side) (Type : Steel Pile )	Good Crack , Spall , Deformation , Rebar-exposed , Broken , Settlement , Scouring , Others :	1
Railing (Type : RC )	Good Scale , Crack , Spall , Rebar-exposed , Others	1	Pier (Type : Beam )	Good Crack Spall , Deformation , Rebar-exposed , Broken , Settlement , Scouring , Others :	3
Deck slab (Type : RC )	Good Honeycombs , Crack , Deformation , Rebar-exposed , Other	1	Pier (Type : Steel Pile )	Good Crack , Spall , Deformation , Rebar-exposed , Broken , Settlement , Scouring , Others : The lower parts of steel pipe piles are heavily corroded. $\phi = 33.7$ cm.	4
Main Beam (Type : RC )	Good Honeycombs , Crack , Deformation , Rebar-exposed , Other	1	Others : The revetment on PP side is settled. It causes horizontal cracks on it.		3
Cross Beam (Type : RC )	Good Crack , Deformation , Rebar-exposed , Others	1	The revetment on KC side is settled and the gap has been repaired.		
Painting	Condition		Comment		
Exp-Joint (Type : AS )	Good , Abnormal Sound , Deformation , Gap (Broken) , Others	2	OVERALL EVALUATION RATING		
Shoe (Type )	Good , Abnormal Sound , Deformation , Gap , Broken , Other (None)		1. No damage detected on the basis of the inspection results.		
Drainage (Type : Steel )	Good , Clogged Leakage , Broken , Others	1	2. Damage has been detected and a follow-up survey is required.		
<Plan / Profile>			3. There is significant damage and a detailed survey needs to be carried out to establish whether repair work is to be carried out or not.		
			4. There is significant damage and urgent repair is required or the bridge has to be closed to traffic or restriction on vehicle weight to be imposed. (or to be re-constructed new bridge)		
			Final rating		
			Super Structure		
			Sub Structure		
			Rating		

<Remarks>	
1) The superstructures are sound. 2) The lower parts of steel pipe piles are heavily corroded (1 to 3mm). Some piles have been damaged by woods or stones. 3) Some intermediate beams of piles are deteriorated and are going to fall down. Others are damaged and run offed, and it causes buckling and structural instability on the steel pipe piles. Some piles are not set in the center of piers. 4) The pipe bent type abutment in high embankment causes settlement and land sliding to the longitudinal direction. (The pavement has been repaired) 5) Overall substructures and foundations are damaged and deteriorated. This bridge is unstable, and should be reinforced or replaced soon.	PP : Phnom Penh , KC : Kampong Cham : corresponding item AS : Asphalt RC : Reinforced Concrete

Table-A Bridge Soundness Sheet (Sheet No. )

Bridge No.25

NAME OF BRIDGE : Prek Ampong Prah 2		CLASS OF ROAD		CROSSING: NAME OF RIVER OR ROAD		DATE OF INSPECTION : Jan. 26, 2000		INSPECTION BY : Y. Takai	
Design Information		Yes		Construction By : USA		Date of Construction : 1962-68		Maintenance by : MPWT	
Type of Bridge		Superstructure		Simple RC-T Girder		Design Loading		Yes	
STA. 40+520		Substructure		Steel Pipe Pile Bent Type		Design Standard		Load limitation ( )	
Length of Bridge		Abutment		12.0 m		Skew of Bridge		BS (AASHTO) RUSSIA OTHERS( )	
Width of Bridge		Pier		Span		Condition of Crossing		Curve (deg, R= )	
Overall		Carriage		9.00 m		Road		Width m Clearance m Skew deg.	
Affixed Articles		Kind		Number		River		Width of River Depth Free Board	
Traffic Volume		(year)		Ratio of Heavy Vehicle (year)		Others		10.5 m 5.3 m 0.0 m	
Final Record of Repair		Pavement		Deck Slab		Expansion Joint		Bearing	
Others : The embankment and pavement on the approach road have been repaired. The gabions have been placed in the area of 30m from the bridge to the upstream on the riverbed.		Main Beam		Painting		Drainage		Curb	
Component		Conditions Of Damage		Rating		Component		Conditions of Damage	
Pavement (Type : AS )		Good (Wave, Rut, Crack, Pothole, Others : Crack in the approach road)		2		Abutment (PP side) (Type : Steel Pile )		Good (Crack, Spall, Deformation, Rebar-exposed, Broken, Settlement, Scouring, Others : )	
Curb (Type : RC )		Good (Scale, Crack, Spall, Rebar-exposed, Others)		1		Abutment (KC side) (Type : Steel Pile )		Good (Crack, Spall, Deformation, Rebar-exposed, Broken, Settlement, Scouring, Others : )	
Railing (Type : RC )		Good (Scale, Crack, Spall, Rebar-exposed, Others)		1		Pier (Type : )		Good (Crack, Spall, Deformation, Rebar-exposed, Broken, Settlement, Scouring, Others : )	
Deck slab (Type : RC )		Good (Honeycombs, Crack, Deformation, Rebar-exposed, Other : The 4.0 m <sup>2</sup> in the center of span has been repaired.)		2		Pier (Type : )		Good (Crack, Spall, Deformation, Rebar-exposed, Broken, Settlement, Scouring, Others : )	
Main Beam (Type : RC )		Good (Honeycombs, Crack, Deformation, Rebar-exposed, Other)		1		Others : The revetments around the abutments are settled, it causes some cracks on them. These cracks have been repaired by mortar.		3	
Cross Beam (Type : RC )		Good (Crack, Deformation, Rebar-exposed, Others)		1		Comment			
Painting		Condition				OVERALL EVALUATION RATING		Final rating	
Exp-Joint (Type : AS )		Good (Abnormal Sound, Deformation, Gap, Broken, Others)		3		1. No damage detected on the basis of the inspection results. 2. Damage has been detected and a follow-up survey is required. 3. There is significant damage and a detailed survey needs to be carried out to establish whether repair work is to be carried out or not. 4. There is significant damage and urgent repair is required or the bridge has to be closed to traffic or restriction on vehicle weight to be imposed. (or to be re-constructed new bridge)		Super Structure	
Shoe (Type : )		Good (Abnormal Sound, Deformation, Gap, Broken, Other, None)						Sub Structure	
Drainage (Type : Steel )		Good (Clogged Leakage, Broken, Others)		1				2	
<Plan / Profile>		1) The superstructure and substructures are sound although they are a few deteriorated. 2) The expansion joints are damaged, and it caused abnormal sound by the vehicles. 3) The revetments around the abutments are scoured and settled. It causes some cracks but they have been repaired by mortar. 4) The gabions are placed on the riverbed.				<Remarks> PP : Phnom Penh, KC : Kampong Cham AS : Asphalt RC : Reinforced Concrete			


**Table-A Bridge Soundness Sheet (Sheet No. ) Bridge No.26**

NAME OF BRIDGE : Prek Ampong Prah 3		CLASS OF ROAD		CROSSING: NAME OF RIVER OR ROAD		DATE OF INSPECTION : Jan. 26.2000		INSPECTION BY Y. Takai	
Design Information		Yes	No	Construction By USA		Date of Construction : 1962-68		Maintenance by MPWT	
Type of Bridge		Superstructure		Simple RC-T Girder		Design Loading			
STA. 41+210		Substructure		Abutment		Design Standard			
		Pier		Steel Pipe Pile Bent Type		Skew of Bridge		BS AASHTO RUSSIA OTHERS( )	
Length of Bridge				36.0 m		Span		3*12.0 m	
Width of Bridge		Overall		11.00 m		Carriage		9.00 m	
Affixed Articles		Kind		Number		Pavement		2*0.65 m	
Traffic Volume		(year)		Ratio of Heavy Vehicle (year)		Others			
Final Record of Repair		Pavement		Deck Slab		Main Beam		Painting	
Others : The revetments around the abutments have been reinforced by the steel sheet piles in 1994. The superstructures and substructures were damaged and runoffed in 1996.									
Component		Conditions Of Damage		Rating		Component		Conditions of Damage	
Pavement (Type )		Good , Wave , Rut , Crack , Pothole , Others : Crack in the approach road				Abutment (PP side) (Type : )		Good , Crack , Spall , Deformation , Rebar-exposed , Broken , Settlement , Scouring , Others :	
Curb (Type )		Good , Scale , Crack , Spall , Rebar-exposed , Others				Abutment (KC side) (Type : )		Good , Crack , Spall , Deformation , Rebar-exposed , Broken , Settlement , Scouring , Others :	
Railing (Type )		Good , Scale , Crack , Spall , Rebar-exposed , Others				Pier (Type : )		Good , Crack , Spall , Deformation , Rebar-exposed , Broken , Settlement , Scouring , Others :	
Deck slab (Type )		Good , Honeycombs , Crack , Deformation , Rebar-exposed , Other : The 4.0 m <sup>2</sup> in the center of span has been repaired.				Pier (Type : )		Good , Crack , Spall , Deformation , Rebar-exposed , Broken , Settlement , Scouring , Others :	
Main Beam (Type )		Good , Honeycombs , Crack , Deformation , Rebar-exposed , Other				Pier (Type : )		Good , Crack , Spall , Deformation , Rebar-exposed , Broken , Settlement , Scouring , Others :	
Cross Beam (Type )		Good , Crack , Deformation , Rebar-exposed , Others				Others :			
Painting		Condition				Comment			
Exp-Joint (Type )		Good , Abnormal Sound , Deformation , Gap , Broken , Others				OVERALL EVALUATION RATING		Final rating	
Shoe (Type )		Good , Abnormal Sound , Deformation , Gap , Broken , Others None				1. No damage detected on the basis of the inspection results.			
Drainage (Type )		Good , Clogged Leakage , Broken , Others				2. Damage has been detected and a follow-up survey is required.		Super Structure	
						3. There is significant damage and a detailed survey needs to be carried out to establish whether repair work is to be carried out or not.		Sub Structure	
						4. There is significant damage and urgent repair is required or the bridge has to be closed to traffic or restriction on vehicle weight to be imposed. (or to be re-constructed new bridge)			
<Plan / Profiles>		1) The riverbed was scoured and the embankments on the backside of abutments were runoffed due to the flood damage in 1991. 2) The revetments were reinforced by the steel sheet piles as emergency repair in 1994. 3) The riverbed was heavily scoured and the embankments on the backside of abutments were runoffed again due to the big flood in 1996. 4) The piers are settled down 30cm together with the superstructure. It causes impossibility of vehicle pass. The superstructures have been removed and some structures remain in the site.				<Remarks> PP : Phnom Penh , KC : Kampong Cham AS : Asphalt RC : Reinforced Concrete			

## **2. Ration of Overall Evaluation for each Bridge**

**Table-A' Rating Method of Overall Evaluation for the Bridge (Sheet No. )**


Evaluation Item		Rating Point (E.P.)	Bridge Weight Factor(W/F)	Point (E.P.)*(W/F)
Durability	Degree of superstructure damage and defect	good to bad 1 2 3 4	0.4	
	Degree of substructure damage and defect	good to bad 1 2 3 4	0.6	
Load Capacity	Low traffic volume ( heavy vehicle with axle load less than 8 ton )	1	0.2	
	High traffic volume ( heavy vehicle with axle load greater than 8 ton )	3	0.2	
Function	Constructed after 1980 (use less than 20 years )	1	0.1	
	Constructed before 1980 (use more than 20 years )	3	0.1	
	Sufficient width for traffic capacity and flood flow	1	0.2	
Overall evaluation for bridge (Range of point)	Insufficient width for traffic capacity and flood flow	3	0.2	
	D: Sound	1.5-2.5	Min. 1.5	D
	C: Fairly sound	2.5-3.5		C
	B: Unsound / Lack of safety	3.5-4.25		B
	A: Danger	4.25-5.5	Max. 5.5	A



**Figure Weight Factors (W/F) for Evaluation Items**

**Table 2.3.37 Rating Method of Bridge Conditions**

Bridge Conditions	Rating	Evaluation
Survey results showed no damages and defects. And, bridge has functional stability.	1	D
Damage has been detected and a follow-up survey is required. And, bridge has functional stability at present.	2	C
There are significant damages / defects. Therefore, a detailed survey is needed and the necessity of repair work including function of bridge should be considered.	3	B
There are significant damages / defects, and no function. Therefore, urgent repair is required. The bridge has to be closed for traffic or restriction on vehicle weight to be imposed. (or re-construction of bridge)	4	A



**Fig. Overall Evaluation Graph of Soundness for Requested Bridges**

**Table. Overall Evaluation Point of Bridge Soundness Survey**

Eva. Item	Bridge No.																			
	7	10	11	12	13	17	18	22	23	24	25	26								
Durability																				
Super Str. Damage	0.4	0.4	0.4	0.8	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.8								
Sub Str. Damage	1.8	0.6	0.6	1.2	0.6	1.2	0.6	1.8	0.6	2.4	1.2									
Loading	0.6	0.6	0.6	0.6	0.6	0.6	0.6	0.6	0.6	0.6	0.6									
Function	0.3	0.3	0.3	0.3	0.3	0.3	0.3	0.3	0.3	0.3	0.3									
Constructed Year	0.3	0.3	0.3	0.3	0.3	0.3	0.3	0.3	0.3	0.3	0.3									
Width, Flood	0.6	0.6	0.6	0.6	0.6	0.6	0.6	0.6	0.6	0.6	0.6									
D: 1.5-2.5		2.5	2.5		2.5		2.5													
C: 2.5-3.5				3.5		3.1			2.5											
B: 3.5-4.25	3.7							3.7			3.5									
A: 4.25-5.5																				
Overall Evaluation	B	D	D	C	D	C	D	B	D	A	B	A								



Table-A Rating of Overall Evaluation for the Bridge (Bridge No. 7)

	Evaluation Item	Rating Point (E.P.)	Bridge (E.P.)	Weight Factor(W/F)	Point (E.P.)*(W/F)
Durability	Degree of superstructure damage and defect	good to bad 1 2 3 4	1	0.4	0.4
	Degree of substructure damage and defect	good to bad 1 2 3 4	3	0.6	1.8
Load Capacity	Low traffic volume ( heavy vehicle with axle load less than 7 ton )	1		0.2	
	High traffic volume ( heavy vehicle with axle load greater than 7 ton )	3	3	0.2	0.6
Function	Constructed record	1		0.1	
	Constructed after 1980 (use less than 20 years )	3	3	0.1	0.3
	Constructed before 1980 (use more than 20 years )	1		0.2	
	Effective width of bridge	3	3	0.2	0.6
Overall evaluation for bridge (Range of point)	Insufficient width for traffic capacity	3			
	D: Sound	1.5-2.5		Min. 1.5	D
	C: Fairly sound	2.5-3.5			C
	B: Unsound / Lack of safety	3.5-4.25	B	Max. 5.5	A
	A: Danger	4.25-5.5			

Table-A Rating of Overall Evaluation for the Bridge (Bridge No. 11)

	Evaluation Item	Rating Point (E.P.)	Bridge (E.P.)	Weight Factor(W/F)	Point (E.P.)*(W/F)
Durability	Degree of superstructure damage and defect	good to bad 1 2 3 4	1	0.4	0.4
	Degree of substructure damage and defect	good to bad 1 2 3 4	1	0.6	0.6
Load Capacity	Low traffic volume ( heavy vehicle with axle load less than 7 ton )	1		0.2	
	High traffic volume ( heavy vehicle with axle load greater than 7 ton )	3	3	0.2	0.6
Function	Constructed record	1		0.1	
	Constructed after 1980 (use less than 20 years )	3	3	0.1	0.3
	Constructed before 1980 (use more than 20 years )	1		0.2	
	Effective width of bridge	3	3	0.2	0.6
Overall evaluation for bridge (Range of point)	Insufficient width for traffic capacity	3			
	D: Sound	1.5-2.5	D	Min. 1.5	D : 2.5
	C: Fairly sound	2.5-3.5			C
	B: Unsound / Lack of safety	3.5-4.25			B
	A: Danger	4.25-5.5		Max. 5.5	A

Table-A Rating of Overall Evaluation for the Bridge (Bridge No. 10)

	Evaluation Item	Rating Point (E.P.)	Bridge (E.P.)	Weight Factor(W/F)	Point (E.P.)*(W/F)
Durability	Degree of superstructure damage and defect	good to bad 1 2 3 4	1	0.4	0.4
	Degree of substructure damage and defect	good to bad 1 2 3 4	1	0.6	0.6
Load Capacity	Low traffic volume ( heavy vehicle with axle load less than 7 ton )	1		0.2	
	High traffic volume ( heavy vehicle with axle load greater than 7 ton )	3	3	0.2	0.6
Function	Constructed record	1		0.1	
	Constructed after 1980 (use less than 20 years )	3	3	0.1	0.3
	Constructed before 1980 (use more than 20 years )	1		0.2	
	Effective width of bridge	3	3	0.2	0.6
Overall evaluation for bridge (Range of point)	Insufficient width for traffic capacity	3			
	D: Sound	1.5-2.5	D	Min. 1.5	D : 2.5
	C: Fairly sound	2.5-3.5			C
	B: Unsound / Lack of safety	3.5-4.25			B
	A: Danger	4.25-5.5		Max. 5.5	A

Table-A Rating of Overall Evaluation for the Bridge (Bridge No. 12)

	Evaluation Item	Rating Point (E.P.)	Bridge (E.P.)	Weight Factor(W/F)	Point (E.P.)*(W/F)
Durability	Degree of superstructure damage and defect	good to bad 1 2 3 4	2	0.4	0.8
	Degree of substructure damage and defect	good to bad 1 2 3 4	2	0.6	1.2
Load Capacity	Low traffic volume ( heavy vehicle with axle load less than 7 ton )	1		0.2	
	High traffic volume ( heavy vehicle with axle load greater than 7 ton )	3	3	0.2	0.6
Function	Constructed record	1		0.1	
	Constructed after 1980 (use less than 20 years )	3	3	0.1	0.3
	Constructed before 1980 (use more than 20 years )	1		0.2	
	Effective width of bridge	3	3	0.2	0.6
Overall evaluation for bridge (Range of point)	Insufficient width for traffic capacity	3			
	D: Sound	1.5-2.5		Min. 1.5	D
	C: Fairly sound	2.5-3.5	C		C : 3.5
	B: Unsound / Lack of safety	3.5-4.25			B
	A: Danger	4.25-5.5		Max. 5.5	A

**Table-A Rating of Overall Evaluation for the Bridge ( Bridge No. 13 )**

	Evaluation Item	Rating Point (E.P.)	Bridge (E.P.)	Weight Factor(W/F)	Point (E.P.)*(W/F)
Durability	Degree of superstructure damage and defect	good to bad 1 2 3 4	1	0.4	0.4
	Degree of substructure damage and defect	good to bad 1 2 3 4	1	0.6	0.6
Load Capacity	Low traffic volume ( heavy vehicle with axle load less than 7 ton )	1		0.2	
	High traffic volume ( heavy vehicle with axle load greater than 7 ton )	3	3	0.2	0.6
Function	Constructed record	1		0.1	
	Constructed before 1980 (use less than 20 years )	3	3	0.1	0.3
	Sufficient width for traffic capacity	1		0.2	
	Insufficient width for traffic capacity	3	3	0.2	0.6
Overall evaluation for bridge (Range of point)	D: Sound	1.5-2.5	D	Min. 1.5	D:2.5
	C: Fairly sound	2.5-3.5			C
	B: Unsound / Lack of safety	3.5-4.25			B
	A: Danger	4.25-5.5		Max. 5.5	A

**Table-A Rating of Overall Evaluation for the Bridge (Bridge No. 18 )**

	Evaluation Item	Rating Point (E.P.)	Bridge (E.P.)	Weight Factor(W/F)	Point (E.P.)*(W/F)
Durability	Degree of superstructure damage and defect	good to bad 1 2 3 4	1	0.4	0.4
	Degree of substructure damage and defect	good to bad 1 2 3 4	1	0.6	0.6
Load Capacity	Low traffic volume ( heavy vehicle with axle load less than 7 ton )	1		0.2	
	High traffic volume ( heavy vehicle with axle load greater than 7 ton )	3	3	0.2	0.6
Function	Constructed record	1		0.1	
	Constructed before 1980 (use less than 20 years )	3	3	0.1	0.3
	Sufficient width for traffic capacity	1		0.2	
	Insufficient width for traffic capacity	3	3	0.2	0.6
Overall evaluation for bridge (Range of point)	D: Sound	1.5-2.5	D	Min. 1.5	D:2.5
	C: Fairly sound	2.5-3.5			C
	B: Unsound / Lack of safety	3.5-4.25			B
	A: Danger	4.25-5.5		Max. 5.5	A

**Table-A Rating of Overall Evaluation for the Bridge ( Bridge No. 17 )**

	Evaluation Item	Rating Point (E.P.)	Bridge (E.P.)	Weight Factor(W/F)	Point (E.P.)*(W/F)
Durability	Degree of superstructure damage and defect	good to bad 1 2 3 4	1	0.4	0.4
	Degree of substructure damage and defect	good to bad 1 2 3 4	2	0.6	1.2
Load Capacity	Low traffic volume ( heavy vehicle with axle load less than 7 ton )	1		0.2	
	High traffic volume ( heavy vehicle with axle load greater than 7 ton )	3	3	0.2	0.6
Function	Constructed record	1		0.1	
	Constructed before 1980 (use less than 20 years )	3	3	0.1	0.3
	Sufficient width for traffic capacity	1		0.2	
	Insufficient width for traffic capacity	3	3	0.2	0.6
Overall evaluation for bridge (Range of point)	D: Sound	1.5-2.5		Min. 1.5	D
	C: Fairly sound	2.5-3.5	C		C:3.1
	B: Unsound / Lack of safety	3.5-4.25			B
	A: Danger	4.25-5.5		Max. 5.5	A

**Table-A Rating of Overall Evaluation for the Bridge ( Bridge No. 22 )**

	Evaluation Item	Rating Point (E.P.)	Bridge (E.P.)	Weight Factor(W/F)	Point (E.P.)*(W/F)
Durability	Degree of superstructure damage and defect	good to bad 1 2 3 4	1	0.4	0.4
	Degree of substructure damage and defect	good to bad 1 2 3 4	3	0.6	1.8
Load Capacity	Low traffic volume ( heavy vehicle with axle load less than 7 ton )	1		0.2	
	High traffic volume ( heavy vehicle with axle load greater than 7 ton )	3	3	0.2	0.6
Function	Constructed record	1		0.1	
	Constructed before 1980 (use less than 20 years )	3	3	0.1	0.3
	Sufficient width for traffic capacity	1		0.2	
	Insufficient width for traffic capacity	3	3	0.2	0.6
Overall evaluation for bridge (Range of point)	D: Sound	1.5-2.5		Min. 1.5	D
	C: Fairly sound	2.5-3.5			C
	B: Unsound / Lack of safety	3.5-4.25	B		B:3.7
	A: Danger	4.25-5.5		Max. 5.5	A

**Table-A Rating of Overall Evaluation for the Bridge (Bridge No. 23)**

	Evaluation Item	Rating Point (E.P.)	Bridge (E.P.)	Weight Factor(W/F)	Point (E.P.)*(W/F)
Durability	Degree of superstructure damage and defect	good to bad 1 2 3 4	1	0.4	0.4
	Degree of substructure damage and defect	good to bad 1 2 3 4	1	0.6	0.6
Load Capacity	Low traffic volume ( heavy vehicle with axle load less than 7 ton )	1		0.2	
Function	High traffic volume ( heavy vehicle with axle load greater than 7 ton )	3	3	0.2	0.6
	Constructed after 1980 (use less than 20 years )	1		0.1	
	Constructed before 1980 (use more than 20 years )	3	3	0.1	0.3
	Sufficient width for traffic capacity	1		0.2	
Overall evaluation for bridge (Range of point)	Insufficient width for traffic capacity	3	3	0.2	0.6
	D: Sound	1.5-2.5	D	Min. 1.5	D:2.5
	C: Fairly sound	2.5-3.5			C
	B: Unsound / Lack of safety	3.5-4.25			B
	A: Danger	4.25-5.5		Max. 5.5	A

**Table-A Rating of Overall Evaluation for the Bridge (Bridge No. 25)**

	Evaluation Item	Rating Point (E.P.)	Bridge (E.P.)	Weight Factor(W/F)	Point (E.P.)*(W/F)
Durability	Degree of superstructure damage and defect	good to bad 1 2 3 4	2	0.4	0.8
	Degree of substructure damage and defect	good to bad 1 2 3 4	2	0.6	1.2
Load Capacity	Low traffic volume ( heavy vehicle with axle load less than 7 ton )	1		0.2	
Function	High traffic volume ( heavy vehicle with axle load greater than 7 ton )	3	3	0.2	0.6
	Constructed after 1980 (use less than 20 years )	1		0.1	
	Constructed before 1980 (use more than 20 years )	3	3	0.1	0.3
	Sufficient width for traffic capacity	1		0.2	
Overall evaluation for bridge (Range of point)	Insufficient width for traffic capacity	3	3	0.2	0.6
	D: Sound	1.5-2.5		Min. 1.5	D
	C: Fairly sound	2.5-3.5			C
	B: Unsound / Lack of safety	3.5-4.25	B		B:3.5
	A: Danger	4.25-5.5		Max. 5.5	A

**Table-A Rating of Overall Evaluation for the Bridge (Bridge No. 24)**



	Evaluation Item	Rating Point (E.P.)	Bridge (E.P.)	Weight Factor(W/F)	Point (E.P.)*(W/F)
Durability	Degree of superstructure damage and defect	good to bad 1 2 3 4	1	0.4	0.4
	Degree of substructure damage and defect	good to bad 1 2 3 4	4	0.6	2.4
Load Capacity	Low traffic volume ( heavy vehicle with axle load less than 7 ton )	1		0.2	
Function	High traffic volume ( heavy vehicle with axle load greater than 7 ton )	3	3	0.2	0.6
	Constructed after 1980 (use less than 20 years )	1		0.1	
	Constructed before 1980 (use more than 20 years )	3	3	0.1	0.3
	Sufficient width for traffic capacity	1		0.2	
Overall evaluation for bridge (Range of point)	Insufficient width for traffic capacity	3	3	0.2	0.6
	D: Sound	1.5-2.5		Min. 1.5	D
	C: Fairly sound	2.5-3.5			C
	B: Unsound / Lack of safety	3.5-4.25	B		B
	A: Danger	4.25-5.5	A	Max. 5.5	A: 4.3

**Table-A Rating of Overall Evaluation for the Bridge ( Bridge No. 26 )**


	Evaluation Item	Rating Point (E.P.)	Bridge (E.P.)	Weight Factor(W/F)	Point (E.P.)*(W/F)
Durability	Degree of superstructure damage and defect	good to bad 1 2 3 4		0.4	
	Degree of substructure damage and defect	good to bad 1 2 3 4		0.6	
Load Capacity	Low traffic volume ( heavy vehicle with axle load less than 7 ton )	1		0.2	
Function	High traffic volume ( heavy vehicle with axle load greater than 7 ton )	3		0.2	
	Constructed after 1980 (use less than 20 years )	1		0.1	
	Constructed before 1980 (use more than 20 years )	3		0.1	
	Sufficient width for traffic capacity	1		0.2	
Overall evaluation for bridge (Range of point)	Insufficient width for traffic capacity	3		0.2	
	D: Sound	1.5-2.5		Min. 1.5	D
	C: Fairly sound	2.5-3.5			C
	B: Unsound / Lack of safety	3.5-4.25	B		B
	A: Danger	4.25-5.5	A	Max. 5.5	A : 5.5

## **6-5. Drawings of Basic Design**






MINISTRY OF PUBLIC WORKS AND TRANSPORT		THE KINGDOM OF CAMBODIA	
PROJECT	Improvement of Bridges on National Highway Route 6A		
CONSULTANT	PACIFIC CONSULTANTS INTERNATIONAL		
DRAWING TITLE	General View of Project Road (2)		
SCALE	A1=1:1000	A3=1:2000	DRAWING 2/20




PLAN  
SCALE 1:1000




PROFILE  
SCALE 1:1000





MINISTRY OF PUBLIC WORKS AND TRANSPORT		THE KINGDOM OF CAMBODIA	
PROJECT	Improvement of Bridges on National Highway Route 6A		
CONSULTANT	PACIFIC CONSULTANTS INTERNATIONAL		
DRAWING TITLE	General View of Project Road (3)		
SCALE	1 : 1000	DRAWING	3/20








SUPER ELEVATION	-2.00% L. & R. EDGE									
	@ PROFILE									
GRADIENT	VCL = 80.00									
	±0.00%									
DESIGNED FINISH LEVEL	14.200	14.284	14.350	14.392	14.399	14.400	14.400	14.400	14.400	14.400
EXISTING LEVEL	9.150	7.400	8.800	7.400	8.800	7.367	4.100	2.143	1.974	1.950
STATION	39+812.000	39+825.000	39+837.950	39+844.950	39+850.000	39+854.950	39+864.950	39+874.950	39+884.950	39+893.025
	39+825.000	39+837.950	39+844.950	39+850.000	39+854.950	39+864.950	39+874.950	39+884.950	39+893.025	39+900.000
STATION	39+904.950	39+914.95	39+918.025	39+924.950	39+934.950	39+943.025	39+944.950	39+950.000	39+954.950	39+964.950
	39+966.025	39+974.950	39+984.950	39+994.950	40+000.000	40+001.950	40+018.050	40+027.950	40+041.950	40+050.000
STATION	40+061.950	40+081.950	40+091.950	40+101.950	40+111.950	40+121.950	40+131.950	40+141.950	40+151.950	40+161.950
	40+171.950	40+181.950	40+191.950	40+201.950	40+211.950	40+221.950	40+231.950	40+241.950	40+251.950	40+261.950



DESIGN CRITERIA	
GENERAL CONDITION	
Design Speed	V=60 km/h
Bridge length (Span Length)	150.05 m. (6 @25 m.)
Total Width	11.00 m.
Longitudinal Gradient	Level
Cross-fall of Carriage way	2%
Superstructure Type	PC-I Shape Girder
Substructure Type	Abutment RC. Reversed T-Shape
Foundation Type	Pier RC. Wall (Cantilever-beam)
MATERIAL STRENGTH	
Supper structure Type	Girder 6 ck=350 kgf/cm2
	Cross Beam 6 ck=240 kgf/cm2
	PC panel 6 ck=500 kgf/cm2
	Slab 6 ck=240 kgf/cm2
Surface	Asphalt Pavement Thickness=50 mm.
	Curb, Hand wall 6 ck=210 kgf/cm2
Substructure	6 ck=210 kgf/cm2
RC. Pile (Cast-in-place)	6 ck=300 kgf/cm2
Prestressing Steel	Main Beam T-12.7 mm. (6 py-180 kgf/mm2)
	Cross Beam T-19.3 mm. (6 py-160 kgf/mm2)
Reinforcing Steel	SD295.SD345 (py-30 kgf/mm2)


MINISTRY OF PUBLIC WORKS AND TRANSPORT		THE KINGDOM OF CAMBODIA	
PROJECT	Improvement of Bridges on National Highway Route 6A		
CONSULTANT	PACIFIC CONSULTANTS INTERNATIONAL		
DRAWING TITLE	GENERAL VIEW OF BRIDGE No. 24		
SCALE	AS SHOWN	DRAWING NO.	5/20




LONGITUDINAL SECTION  
SCALE 1:600

SUPER ELEVATION	
GRADIENT	±0.00% VCL= 50.00
DESIGNED FINISH LEVEL	14.400
EXISTING LEVEL	12.308 12.308 12.313 12.298 12.305 12.324 14.400 14.400
STATION	40+450.000 40+454.090 40+464.090 40+474.090 40+475.000 40+485.090 40+495.090 40+498.000(A1) 40+500.000 40+504.090 40+516.090 40+525.000 40+526.090 40+536.090 40+548.050 40+550.000 40+556.090 40+558.000 40+566.090 40+575.000 40+576.090 40+583.000 PVI 40+596.090 40+600.000


PROFILE  
SCALE 1:600




BRIDGE PLAN WITH CONTOUR LINE  
SCALE 1:600




CROSS SECTION OF PC-I GIRDER  
SCALE 1:100




FRONT VIEW ABUTMENT A1 & A2  
SCALE 1:200




SADE VIEW  
SCALE 1:200



FRONT VIEW  
SCALE 1:200



PIER  
SCALE 1:200



LONGITUDINAL SECTION  
SCALE 1:1000

DESIGN CRITERIA	
GENERAL CONDITION	
Design Speed	V=60 km/h
Bridge length (Span Length)	150.05 m. (6 @ 25 m.)
Total Width	11.00 m.
Longitudinal Gradient	Level
Cross-fall of Carriage way	2%
Superstructure Type	PC-I Shape Girder
Substructure Type	Abutment RC. Reversed T-Shape
	Pier RC. Wall (Cantilever-beam)
Foundation Type	
MATERIAL STRENGTH	
Supper structure Type	Girder 6 ck=350 kgf/cm2
	Cross Beam 6 ck=240 kgf/cm2
	PC panel 6 ck=500 kgf/cm2
	Slab 6 ck=240 kgf/cm2
Surface	Asphalt Pavement Thickness=50 mm.
	Curb, Hand wall 6 ck=210 kgf/cm2
Substructure	6 ck=210 kgf/cm2
RC. Pile (Cast-in-place)	6 ck=300 kgf/cm2
Prestressing Steel	Main Beam T-12.7 mm. (6 py-160 kgf/mm2)
	Cross Beam T-19.3 mm. (6 py-160 kgf/mm2)
Reinforcing Steel	SD295.SD345 (py-30 kgf/mm2)


MINISTRY OF PUBLIC WORKS AND TRANSPORT		THE KINGDOM OF CAMBODIA	
PROJECT	Improvement of Bridges on National Highway Route 6A		
CONSULTANT	PACIFIC CONSULTANTS INTERNATIONAL		
DRAWING TITLE	GENERAL VIEW OF BRIDGE No. 25		
SCALE	AS SHOWN	DRAWING NO.	6/20



SCALE 1:1000




MINISTRY OF PUBLIC WORKS AND TRANSPORT		THE KINGDOM OF CAMBODIA	
PROJECT	Improvement of Bridges on National Highway Route 6A		
CONSULTANT	PACIFIC CONSULTANTS INTERNATIONAL		
DRAWING TITLE	GENERAL VIEW OF BRIDGE No. 26		
SCALE	AS SHOWN	DRAWING NO.	7/20




LONGITUDINAL SECTION WITH GABION

SCALE 1:800




STONE WALL DETAIL

SCALE 1:20



PLAN OF GABION AND STONE WALL



SCALE 1:800



CUTTING EDGE DETAIL


SCALE 1:20

MINISTRY OF PUBLIC WORKS AND TRANSPORT		THE KINGDOM OF CAMBODIA	
PROJECT	Improvement of Bridges on National Highway Route 6A		
CONSULTANT	PACIFIC CONSULTANTS INTERNATIONAL		
DRAWING TITLE	General View of Protection (Wet Masonry and Gabion) of Bridge No.24		
SCALE	1 : 800	DRAWING NO.	8/20




MINISTRY OF PUBLIC WORKS AND TRANSPORT		THE KINGDOM OF CAMBODIA	
PROJECT	Improvement of Bridges on National Highway Route 6A		
CONSULTANT	PACIFIC CONSULTANTS INTERNATIONAL		
DRAWING TITLE	General View of Protection (Wet Masonry and Gabion) of Bridge No.25		
SCALE	1 : 400	DRAWING NO.	9/20







LONGITUDINAL SECTION  
SCALE 1:800



CUTTING EDGE DETAIL  
SCALE 1:20




STONE WALL DETAIL  
SCALE 1:20




PLAN OF GABION AND STONE WALL  
SCALE 1:800


MINISTRY OF PUBLIC WORKS AND TRANSPORT		THE KINGDOM OF CAMBODIA	
PROJECT	Improvement of Bridges on National Highway Route 6A		
CONSULTANT	PACIFIC CONSULTANTS INTERNATIONAL		
DRAWING TITLE	General View of Protection (Wet Masonry and Gabion) of Bridge No.26		
SCALE	1 : 800	DRAWING NO.	10/20




BRIDGE PLAN  
SCALE 1:250




I- GIRDER PLAN  
SCALE 1:75




I- GIRDER SIDE VIEW  
SCALE 1:75




SECTION  
SCALE 1:100



A - A  
SCALE 1:50




B - B  
SCALE 1:50



C - C  
SCALE 1:50  
END DIAPHRAGME BEAM




D - D  
SCALE 1:50  
CROSS BEAM




DETAIL "A"  
SCALE 1:50


MINISTRY OF PUBLIC WORKS AND TRANSPORT		THE KINGDOM OF CAMBODIA	
PROJECT	Improvement of Bridges on National Highway Route 6A		
CONSULTANT	PACIFIC CONSULTANTS INTERNATIONAL		
DRAWING TITLE	General View of PC-I Girder for Bridge No.24		
SCALE	A1=1:250	A3=1:500	DRAWING NO. 11/20




BRIDGE PLAN  
SCALE 1:150




SECTION  
SCALE 1:50




I- GIRDER PLAN  
SCALE 1:75




I-GIRDER SIDE VIEW  
SCALE 1:75




A - A  
SCALE 1:20



B - B  
SCALE 1:20




C - C  
SCALE 1:20



D - D  
SCALE 1:20

END DIAPHRAGM BEAM CROSS BEAM




DETAIL " A "  
SCALE 1:20

MINISTRY OF PUBLIC WORKS AND TRANSPORT		THE KINGDOM OF CAMBODIA	
PROJECT	Improvement of Bridges on National Highway Route 6A		
CONSULTANT	PACIFIC CONSULTANTS INTERNATIONAL		
DRAWING TITLE	General View of PC-I Girder for Bridge No.25		
SCALE	A1=1:150	A3=1:300	DRAWING NO. 12/20









FRONT VIEW  
SCALE 1:100

ABUTMENT A1 & A2




SIDE VIEW  
SCALE 1:100




BORING PILE PLAN  
SCALE 1:100

MINISTRY OF PUBLIC WORKS AND TRANSPORT		THE KINGDOM OF CAMBODIA	
PROJECT	Improvement of Bridges on National Highway Route 6A		
CONSULTANT	PACIFIC CONSULTANTS INTERNATIONAL		
DRAWING TITLE	General View of Abutment for Bridge No.24		
SCALE	1 : 100	DRAWING NO.	14/20




FRONT VIEW  
SCALE 1:100

PIER




SIDE VIEW  
SCALE 1:100




BORING PILE PLAN  
SCALE 1:100

MINISTRY OF PUBLIC WORKS AND TRANSPORT		THE KINGDOM OF CAMBODIA	
PROJECT	Improvement of Bridges on National Highway Route 6A		
CONSULTANT	PACIFIC CONSULTANTS INTERNATIONAL		
DRAWING TITLE	General View of Pier for Bridge No.24		
SCALE	1 : 100	DRAWING NO.	15/20




FRONT VIEW  
SCALE 1:400

ABUTMENT A1 & A2




SIDE VIEW  
SCALE 1:400




BORING PILE PLAN  
SCALE 1:400

MINISTRY OF PUBLIC WORKS AND TRANSPORT		THE KINGDOM OF CAMBODIA	
PROJECT	Improvement of Bridges on National Highway Route 6A		
CONSULTANT	PACIFIC CONSULTANTS INTERNATIONAL		
DRAWING TITLE	General View of Abutment for Bridge No.25		
SCALE	1 : 400	DRAWING NO.	16/20



FRONT VIEW


SCALE 1:400



SIDE VIEW

SCALE 1:400

PIER




BORING PILE PLAN

SCALE 1:400


MINISTRY OF PUBLIC WORKS AND TRANSPORT		THE KINGDOM OF CAMBODIA	
PROJECT	Improvement of Bridges on National Highway Route 6A		
CONSULTANT	PACIFIC CONSULTANTS INTERNATIONAL		
DRAWING TITLE	General View of Pier for Bridge No.25		
SCALE	1 : 400	DRAWING NO.	17/20

RC. CAST-IN PLACE #1000  
L = 11.00 m. N=8.00




FRONT VIEW  
SCALE 1:100

ABUTMENT A1 & A2




SIDE VIEW  
SCALE 1:100




BORING PILE PLAN  
SCALE 1:100

MINISTRY OF PUBLIC WORKS AND TRANSPORT		THE KINGDOM OF CAMBODIA	
PROJECT	Improvement of Bridges on National Highway Route 6A ,		
CONSULTANT	PACIFIC CONSULTANTS INTERNATIONAL		
DRAWING TITLE	General View of Abutment for Bridge No.26		
SCALE	1 : 100	DRAWING NO.	18/20




FRONT VIEW  
SCALE 1:100

PIER



SIDE VIEW  
SCALE 1:100



BORING PILE PLAN  
SCALE 1:100

MINISTRY OF PUBLIC WORKS AND TRANSPORT		THE KINGDOM OF CAMBODIA	
PROJECT	Improvement of Bridges on National Highway Route 6A		
CONSULTANT	PACIFIC CONSULTANTS INTERNATIONAL		
DRAWING TITLE	General View of Pier for Bridge No.26		
SCALE	1 : 100	DRAWING NO.	19/20

CURVE DATA	
PI-1	STA. 0+015.000
$\Delta$	= 50°-40'-51.21" (RT)
T	= 15.000 M
R	= 31.674M
E	= 3.372M
LC	= 28.018M
PC	= STA. 0+000.000
PT	= STA. 0+028.018

CURVE DATA	
PI-4	STA. 0+213.224
$\Delta$	= 47°-07'-15.95" (RT)
T	= 16.000 M
R	= 36.691M
E	= 3.537M
LC	= 30.176M
PC	= STA. 0+197.224
PT	= STA. 0+227.400

CURVE DATA	
PI-2	STA. 0+067.307
$\Delta$	= 50°-40'-51.21" (LT)
T	= 13.000 M
R	= 27.452 M
E	= 2.923M
LC	= 24.282M
PC	= STA. 0+054.307
PT	= STA. 0+078.309

CURVE DATA	
PI-3	STA. 0+158.189
$\Delta$	= 47°-07'-15.95" (LT)
T	= 20.000 M
R	= 45.864M
E	= 4.171M
LC	= 37.720M
PC	= STA. 0+138.189
PT	= STA. 0+178.909

CONTROL POINTS		
POINT	COORDINATES	
No.	N	E
MDR-1	500.000	500.000
MDR-2	478.548	523.758
MDR-3	500.010	528.455
MDR-4	515.967	515.463
MDR-5	481.507	487.088

SOIL BORING TEST		
POINT No.	LOCATION OF BORE HOLE	EXISTING GROUND LEVEL
1	STA. 0+140.000 25.10m. NORTH SIDE OF E. ROAD	+8.155
2	STA. 0+230.000 27.10m. NORTH SIDE OF E. ROAD	+7.837

LEGEND:	
	MD
	SURVEY POINT
	CONTOUR LINE OF GROUND LEVEL
	CATCH
	HOUSE
	BORE HOLE POINT

MINISTRY OF PUBLIC WORKS AND TRANSPORT		THE KINGDOM OF CAMBODIA	
PROJECT	Improvement of Bridges on National Highway Route 6A		
CONSULTANT	PACIFIC CONSULTANTS INTERNATIONAL		
DRAWING TITLE	Detour Road and Temporary Bridge for Bridge No.25		
SCALE	A1=1:400	A3=1:800	DRAWING NO. 20/20



## **6-6. Data Collection**

## List of Data Collection

Area	South-east Asia	Name of the Project	Basic Design Study on the Project for Improvement of Bridges on National Road 6A	Basic Design Study		Collected By	
				Period of the Survey	Published By	Chief Consultant	
Country	The Kingdom of Cambodia				2000/01/16 - 2000/02/24 2000/05/14 - 2000/05/24	Mr. Yoshiaki Kaneko	

No.	Document Name	Size	Pages	Original / Copy	Nos.	Published By			
1	Road Net Work Scale=1/1,000,000 & 1/2,000,000	A1 A3	1 1	Original	3 3	Ministry of Public Works and Transport (MPWT)			
2	Boundary Map Scale=1/100,000	A1	4	Original	3	MPWT			
3	Road Design Standard Part-1,2,3	A4	227	Copy	1	JICA Expert			
4	Bridge Design Standard	A4	25	Copy	1	JICA Expert			
5	As-built Drawing for Route 6A	A1	86 69	Copy	2	MPWT			
6	Preliminary Study & Evaluation/Photo	A4	One set	Original	1	JICA Tokyo			
7	Development Objectives strategies & Programs	A4	21	Original	1	JICA Tokyo			
8	Bridge Data Information, National Road 1, 2, 3, 4, 5, 6, 7, 11	A4	One set	Original	1	JICA Tokyo			
9	Public Investment Programme, 1998-2000	A4	One set	Original	1	JICA Tokyo			

No.	Document Name	Size	Pages	Original / Copy	Nos.	Published By					
10	Cambodia Road Net Work Phnom Penh Oct.1998	A4	37	Original	1	JICA Tokyo					
11	Basic Design Report for Route No.6 & 7	A4	One set	Copy	1	MPWT					
12	Detailed Design Drawings for Route No.6 & 7	A3	One set	Copy	1	MPWT					
13	Detailed Design Report for Mekong Bridge on Route No.7 (Design Condition)	A4	One set	Copy	1	MPWT					
14	Priority of National Road Restoration (Road Map of Grant Aid)	A3	1	Original	3	MPWT					
15	Basic Design Study for Route 6A Draft Final Report	A4	One set	Copy	1	MPWT					
16	Proposal for Mekong River	A4	One set	Copy	1	MPWT					
17	Construction Method for Route 6 and 7	A4	Two set	Copy	2	MPWT					
18	Monthly Bulletin of Statistics	A4	One set	Copy	1	MPWT					
19	The present and Future Sihanoukville Port Authority	A4	One set	Copy	1	JICA Expert					
20	Price List from 01-01-1998 Building and Public Works Laboratory	A4	One set	Copy	1	MPWT					
21	Bridge No.26 of National Road Route 6A	A4	One set	Original	1	JICA Tokyo					

No.	Document Name	Size	Pages	Original / Copy	Nos.	Published By						
22	Costoms Tariff 2000	A4	One set	Original	1	Ministry of Economy and Finance						
23	Labor Code 1999	A4	One set	Original	1	National Assembly						
24	Aerial Photo 1992	A4	19	Original	1	MPWT						
25	Topographic Map 1965, 1/50,000	A1	1	Original	1	MPWT						
26	Geology Map Phnom penh 1/500,000	A1	1	Original	1	MPWT						
27	Cambodia Reconnaissance survey Digital Data	A4	One set	Copy	1	MPWT						
28	Law on Environmental Protection and Natural Resource Management	A4	One Set	Copy	1	Ministry of Environment						
29	Sub-Degree on Environmental Impact Assessment Progress	A4	One Set	Copy	1	Ministry of Environment						
30	First Socioeconomic Development Plan 1996-2000	A4	One Set	Copy	1	Ministry of Planning						
31	Initial Environmental Examination and Social Impact Report	A4	One Set	Copy	1	SMEC, ADB						
32	Economic Evaluation and Review of TRS	A4	One Set	Copy	1	SMEC, ADB						

No.	Document Name	Size	Pages	Original / Copy	Nos.	Published By				
33	National Programme to Rehabilitate and Develop Feb.1994	A4	One Set	Copy	1	The Royal Government of Cambodia				
34	Topo map s = 1:100,000		6	Original	1	Ministry of Public Works and Transport, Public Works Research Center				
35	Daily and Monthly water level at Chruoy Changva, Kampong Cham, Prek Kdam, Bassac	A4	One Set	Copy	1	Ministry of Water Resources and Meteorology				
36	Monthly discharge at Chruoy Changva, Kampong Cham, Prek Kdam	A4	One Set	Copy	1	Ministry of Water Resources and Meteorology				
37	Daily water level at Chruoy Changva, Kampong Cham, Prek Kdam, Bassac	A4	One Set	Copy	1	Ministry of Water Resources and Meteorology				
38	Daily discharge at Chruoy Changva, Kampong Cham, Prek Kdam	A4	One Set	Copy	1	Ministry of Water Resources and Meteorology				
39	Basic River at Phnom Penh (Station Description)	A4	One Set	Copy	1	Ministry of Water Resources and Meteorology				
40	Water Level and H-Q curve at Speam Tras Year 1999 National Road No.6, 6A & No.24Br.	A4	5	Copy	1	Ministry of Water Resources and Meteorology				
41	Hydraulic Atlas Mekong River in Cambodia Volume 1, Mekong River from Cambodia / Viet Nam Border to Phnom Penh	A2 Long	One Set	Copy	1	Ministry of Public Works and Transport, Department of Waterways				
42	Hydraulic Atlas Mekong River in Cambodia Volume 2, Mekong River from Phnom Penh to Cambodia / Laos Border	A3 Long	One Set	Original	1	Ministry of Public Works and Transport, Department of Waterways				
43	Hydraulic Atlas Mekong River in Cambodia Volume 3, Tonle Sap River from Phnom Penh to Tonle Sap Lake	A4 Long	One Set	Original	1	Ministry of Public Works and Transport, Department of Waterways				
44	Meteorological Data of Temperature, Relative Humidity, Wind Direction & Velocity, Rainfall at Phnom Penh, Kampong Cham, Pusat	A4	One Set	Copy	1	Ministry of Water Resources and Meteorology				