

Valenzuela


Individual Information Sheets for the Traffic Bottleneck Points

- VL-01 Karuhatan / A Pablo / MacArthur Hwy
- VL-02 MacArthur Hwy / A Fernando St
- VL-03 MacArthur Hwy / P Valenzuela St
- VL-04 MacArthur Hwy / Tamaraw Hills
- VL-05 Fatima Ave / Serrano St
- VL-06 MacArthur Hwy / Poblacion Road




Name	Kai	ruhatan / A. Pablo / MacArthur Hwy	Code	VL-01					
Sheet	Summary of Observations LGU Valenzuela								
ons	1)	Heavy pedestrian movements due to the market and the transfer to t Karuhatan.	he public	: transport plying					
	2)	2) Passengers of jeepneys and buses board and alight at locations clearly marked as forbidden.							
S	3)	3) No clear marking of pedestrian lanes.							
Traffic Conditions	4)	4) Pedestrians along the Karuhatan approach are sometimes forced to use the road because of the narrowness of the sidewalks.							
F	5)	5) Total traffic on MacArthur is 9 times the traffic volume on Karuhatan.							
	1)	A four-leg but skewed intersection located at Valenzuela.							
<u>s</u>	2)	The main road, MacArthur Highway has four undivided lanes and paved with concrete.							
tion	3)	3) Pablo St. measures only 4.00 meters while Karuhatan Road is 5.25 meters wide.							
ndi	4)	4) All street corners have substandard radii.							
္မ	5)	5) No clear marking of pedestrian lanes.							
Physical Conditions	6)	6) Unpaved shoulder located at the corner of A1 and A2 along MacArthur highway. Also, shir high "walls" observed at this corner.							
۵	7)	Narrow sidewalks along Karuhatan.							
	8)	Construction work on Karuhatan for drainage improvement and floor	d mitigat	ion					

Signalization	Manual	Pavement Markings		With markings		Peak	8:00-9:00
A I-		Peak Hour Traffic Volume			PCUs)	% Public	Pedestrian
Approach	Dimensions	Left	Through	Right	Right Total		t Volume
A1: McArthur Hwy (N)	15.0m	65	1460	19	1545	45.15%	9
A2: Karuhatan (E)	6.0m	159	22	180	361	17.15%	0
A3: McArthur Hwy (S)	15.0m	4	1134	97	1235	49.79%	6
A4: A Pablo (W)	5.0m	38	23	5	66	25.71%	o l
	Total	266	2,639	301	3,207		
Pass	enger Flows						



Name	Karuhatan / A. Pablo / MacArthur Hwy	Code	VL-01
Sheet	Analysis	LGU	Valenzuela

- 1) Pedestrians along the Karuhatan approach are sometimes forced to use the road because of the narrowness of the sidewalks.
- 2) Current construction activity for the improvement of drainage is constricting the entry to Karuhatan. Flooding has been a problem during heavy rains due to poor drainage.
- 3) Unpaved shoulder does not allow jeepneys to leave the travel-way or at least allow following vehicles to easily overtake.
- 4) Some shin-high walls slightly restrict the easy movement of pedestrians from the market who are crossing MacArthur Highway.
- 5) Cycle times being used exceed 3 minutes (based on observations) and would need to be shortened.
- 6) Cycle allocations should be based on traffic volumes. Between 50% and 60% of all green times should be given to the north-south and south-north traffic flow on MacArthur Highway.



Sheet	Karuhatan / A. Pablo / MacArthur Hwy	Code	VL-01
Silver	Proposed Improvements	LGU	Valenzuela
Engineering	 Provide lane markings as well as zebra crossings. Modify signal phasing into 4, as shown below, with one cycle lind install traffic signal controller. Modify turning radii. Place turning movement guide markings, such as left-turn arrown Designate loading / unloading or boarding / alighting areas. Pedestrian barriers and sidewalk improvements already done on Barangay government. Additional barrier or bollard along MacA 	ws. A. Pablo by V	/alenzuela /
Enforcement	1) Enforce anti-jaywalking strictly. 2) Apprehend public transport stopping (allowing boarding and a areas. Pedestrians who get on or off at areas other than designa jaywalking.	lighting) at no ited can be ch	on-designated larged with
	Geometric improvement Removal/push back fence & provide sidewalk Pavement improvement Geometric improvement Removal/push back fence & provide sidewalk Pavement improvement Geometric improvement Removal/push back fence & provide sidewalk Pavement improvement According to the provide sidewalk improvement automatic signal	of with	lacement of avement markings Provisions of loading/unloading area & passenger waiting she


SSTRIMM

LOCATION: VL-01: Karuhatan / A. Pabio / MacArthur Hwy (VALENZUELA) (cost summary based on actual implementation)

. Pavement Markings	<u>Unit</u>	Quantity	<u>Unit Cost</u>	Total Cost
Longitudinal Lines				
1. Center Lines				
a.) Broken Lines, 100 or 150 mm width, 3m length				
4.50 m gaps	l.m.	547.00	90.00	49,230.00
b.) Solid White Lines, 150mm width	l.m.	-	-	
2. Lane Lines (100 or 150mm width)				
a.) Solid Lines, w = 150mm	l.m.	16.80	60.00	1,008.00
b.) Broken Lines, w = 150mms, 200mm width	l.m.	-	•	-
3. Barrier Lines				
a.) Unbroken Double Yellow Lines (100 or 150mm width)	l.m.	430.00		10 800 00
b.) Single Yellow Line with broken White Lines (100-150mm)	l.m.	120.00	90.00	10,800.00
Edge Lines a.) Pavement Edge (Shoulders)	l.m.			
b.) Median Edge	l.m.	-	_	_
5. Continuity Lines	l.m.		_	_
6. Transition Line	l.m.	_	_	_
o. Hammon cine	1.411.			
Transverse Lines				
1. Stop Lines (Solid Lines) white, width = 450mm	l.m.	30.00	270.00	8,100.00
2. Give Way (Yield Lines)	l.m.	-		-
3. Pedestrian Crossing Markings				
a.) Zebra Crossing (Non-Signalized), width = 300mm	i.m.	-	-	-
b.) Cross Walks (Signalized), width = 300mm	l.m.	245.00	180.00	44,100.0
Other Lines				
1. Turn Lines (Broken Lines)	l.m.	-	-	-
2. Parking Bay Lines	1			
a.) Parallel Bays, width = 100mm	l.m. l.m.	-	-	-
b.) Angle Bays 3. Painted Median Islands	l.m.	-	-	-
4. Bus and PUJ Lane Markings	l.m.	-	_	
5. Channelized Junction Pavement Marking	1.m.	-	_	_
6. Yellow Box Line, w = 200mm	l.m.	-	-	-
Other Markings				
Approach Markings to Island and Obstructions	l.m.	-	-	-
2. Chevron Markings	l.m.	•	- 1	-
3. Curb Markings to Parking Restrictions	l.m.	•	-	-
4. Approach to Railroad Crossings	l.m.	-	-	-
5. Loading/Unloading Zone Lines , (w=200mm)	1.m.	•	-	•
Messages and Symbols				
1. Messages	pcs.	-	_	-
2. Symbols	p-co.			
a.) Give Way Symbol	pcs.		_	
b.) Pavement Arrows	•			
1.) Through Arrow = 1.21 sq.m. / each	pcs.	-	4	-
2.) Combined Arrow = 2.44 sq.m. / each	pcs.	4.00	1,575.00	6,300.0
3.) Turn Arrow = 1.46 sq.m. / each	pcs,	-	-	
c.) Numerals	•			
P. Charles				
B. Signs				
1. PUJ Loading/Unloading Sign	pcs.	-	3.040.00	7 830 4
2. No Loading/Unloading Sign	pcs.	2.00	3,910.00	7,820.0
3. Tricycle Loading/Unloading Sign	pcs.	•	-	•
4. No Double Parking Area	pcs.	-	-	-
C. Other Works				
1. Installation of Signal Controller	l.s.	1.00	75,000.00	75,000.0
Provide Pedestrian Railing (Steel Railing) 6m/pc	1.s. f.m.	1.00	73,000.00	, 3,000,0
2. Tronde redestrion having (steel having) onlype	1.111.	•	-	
TOTAL				202.358.0
TOTAL				202,358.0


Name	MacArthur Hwy /A Fernando St	Code	VL-02				
Sheet	Summary of Observations	LGU	Valenzuela				
Traffic Conditions	 Unsignalized T-intersection. Major traffic is on MacArthur Highway. Tricycles waiting along A. Fernando on the exit lane near the intersection are fairly well-ordered/well-parked. Light pedestrian traffic. A few vehicles are parked on road. 						
Physical Conditions	 A few vehicles are parked on road. Concrete pavement on both roads. A. Fernando is a relatively narrow two-lane road, further narrowed by the tricycles. No pavement markings along A. Fernando nor MacArthur. Sidewalk on the side of A. Fernando exit lane. Unpaved, not raised, sidewalk on side of A. Fernando approach lane, with an intermitten open canal near the intersection approach. Deep hole on the right turning side of intersection approach lane on A. Fernando. Unpaved shoulder to the right of the entry lane on A. Fernando. Damaged pavement with puddling found about 50 meters from the intersection. Waiting shed immediately fronting A. Fernando on the other side of McArthur (southbou lane). Existing safety devices: Dual traffic mirror on the side of the waiting shed. 						

Signalization	None	Pavemen	t Markings	ys None		Peak 0	9:00-10:00
Annanah			Hour Traffic	Volumes (PCUs)		% Public	Pedestrian
Approach	Dimensions	Left	Through	Right	Total	Transport	Volume
A1: McArthur Hwy (N)	14.5m	11	1,922	NA	1,933	32.86%	Light
A2: Fernando	5.0m	156	NA	11	167	22.75%	Light
A3: McArthur Hwy (S)	16.2m	NA	1,408	119	1,526	45.29%	Light
A4: None	None	None	None	None	None	None	None
	Total	167	3,329	130	3,626		
Pass	enger Flows		·		T		



Name	MacArthur Hwy /A Fernando St	Code	VL-02
Sheet	Analysis	LGU	Valenzuela

- 1) The open canal forces pedestrians on to the road and constricts vehicular movement on A. Fernando. Although pedestrian traffic is light, this situation is unsafe.
- 2) Damaged pavement (due to narrow excavation across A. Fernando) causes unnecessary slowing of vehicles, and risk to vehicles.
- 3) Present location and orientation of tricycles exposes passengers to the traffic, their loading and unloading into and from the sidecar being immediately facing the carriageway. This is unsafe for the passengers and presents an opportunity for numerous instances of tricycle passengers obstructing traffic on the carriageway.
- 4) Tricycles reduce the capacity of A. Fernando, but there are presently no viable alternative locations to take them off the road.
- 5) Tricycles, being located at the intersection inadvertently cause exiting traffic to take all or part of the opposing lane on Tamaraw Hills road. This would further limit the capacity of the entering lane and cause tie-ups in traffic.




	MacArthur Hwy /A Fernando St	Code	VL-02
Sheet	Proposed Improvements	LGU	Valenzuela
Engineering	 Current unpaved shoulder should be paved and the open canal corporate the loading and unloading areas of the tricycles; prefer intersection. Install traffic control signages as follows: "STOP" or yield sign for traffic coming from A. Fernando Sign indicating appropriate loading and unloading area for traffic. 	ably farther	
Enforcement	 Tricycles should be oriented such that passengers will load from the carriageway. For example, if a sidewalk on the side of the open carriageway. For example, if a sidewalk on the side of the open carriageway. For example, if a sidewalk on the side of the open carriageway. For example, if a sidewalk on the side where traffic is entering the intersection. Tricycles should be set back at least 10 meters away from the intervehicles turning into and from MacArthur highway. Strict enforce unloading should be at designated areas only. San Miguel Brewery may have to be required to provide a flagman vehicles; when frequency is high or during peak hours. 	inal become ht side of the rsection to p ment that lo	s viable, tricycles e road, that is, the provide space for ading and

LOCATION: VL02, A. Fernando Street / MacArthur Highway (VALENZUELA) (cost summary)

(cost summar)	y)			
A. Pavement Markings	<u>Unit</u>	Quantity	Unit Cost	Total Cost
Longitudinal Lines:				
1. Center Lines				
a) Broken Line, 100 or 150mm width, 3m length, w = 150mm	ł.m	140.00	45.00	6,300.00
b) Solid White Lines, 200mm width	· l.m	60.00	150.00	9,000.00
Lane Lines (100mm or 150mm width) a) Solid Lines, w = 150 mm	l.m	30.00	112.50	3,375.00
b) Broken Lines w= 150 mm	Lm	470.00	45,00	21,150.00
3. Sarrier Lines	1.114	470.00	43,00	21,150.00
a) Unbroken Double Yellow Lines (100 or 150mm width)	i.m		_	_
b) Single Yellow Line with broken White Lines (100-150mm)	l,m	-	-	
4. Edge Lines		•	•	
a) Pavement Edge (Shoulders)	l.m	-	-	•
b) Median £dge	1.m	-	-	-
5. Continuity Line	l.m	-	-	•
6. Transition Line	l.m	•	-	-
Turania 18				
Transverse Lines:	1.m	19.00	337,50	6,412.50
1. Stop Lines (Solid Lines) white, width = 450 mm 2. Give Way (Yield Lines)	i.m	19.00	337.30	0,412.30
3. Pedestrian Crossing Markings	. 5119	· -		•
a) Zebra Crossing (Non-Signalized), width = 300mm	l.m	240.00	225.00	54,000.00
b) Cross Walks (Signalized), width = 300mm	i,m			,500.00
.,				
Other Lines:				
1. Turn Lines (broken Lines)	l.m	. •	•	-
2. Parking Bay Lines				
a) Parallel Bays, width = 100mm	l.m	-	· -	•
b) Angle Bays	l.m	•		-
3. Painted Median Islands	l.m	-	•	-
4. BUS and PUJ Lane Markings	i.m	•	•	-
5, Channelized Junction Pavement Marking 6, Yellow Box Line, w= 150mm	l.m l.m	•	-	· · · · · ·
o. Tenow Box Line, w= 150)[[iii	I,III	-	-	•
Other Markings:				
1. Approach Markings to Islands and Obstructions	1.m	•	• •	
2. Chevron Markings	l.m	•	-	•
3. Curb Markings for Parking Restrictions	1.m	-	-	-
4. Approach to Railroad Crossings	l.m	•	•	-
5. Diagonal Markings on Sealed Shoulders		•		
a) Outline, 150mm width	l.m	•	-	-
b) Diagonal Bars, 300mm width	l,m	-	-	-
Messages and Symbols:				
1) Messages	pcs			_
2) Symbols	F			
a) Give Way symbol	pcs	_	•	-
b) Pavement Arrows				
1) Through Arrow = 1.21 sq.m / each	pcs -	•	•	-
2) Combined Arrow = 2.44 sq.m / each	pcs	-	-	•
3) Turn Arrow = 1.46 sq. m / each	DC2	•	-	-
c) Numerals	pcs	-	•	•
B, Signs				
1. No Parking Sign	Units	1.90	2,716,00	2,716.00
2. Pedestrian Crossing Sign	Units	3.00	3,850.00	11,550.00
3. Stop Sign	Units	1.00	2,718.00	2,718.00
4. Directional Sign	Units		-	-
S. Bus / PUJ Stop Sign	Units	-	-	•
C. Other Works				
Reprogramming of Traffic Signal Reduction Stort Bailing	l.s.		-	•
Pedestrian Steel Railing Sidewalk Improvement along A. Fernando St.	l.m.	•	•	-
a) Excavation & Subgrade Preparation	l.m	100.00	49.50	4,950.00
b) 4* Concrete Sidewalk	l.m	100.00	395.00	39,500.00
4. Rapair Damaged Pavement along A. Fernando St.		.30,00		,
a) Excavation & Subgrade Preparation	sq.m	40.00	65.25	2,610.00
b) 8" Concrete Pavement	sq.m	40.00	790.00	31,600.00
	•			
TOTAL				195,881.50
Contingencies, 5%				9,794.08
CMS, 10%				19,588.15
Miscellaneous (fees, permits, etc), 5%				9,794.08
Govt. Supervision, 2%				3,917.63
TOTAL COST				238,975.43
IVINCTON				20,313.43


Name	MacArthur Hwy /P Valenzuela St	Code	VL-03
Sheet	Summary of Observations	LGU	Valenzuela
Traffic Conditions	 Unsignalized T-intersection. The tricycle terminal has been established inside a minor road (app Valenzuela Street. Some vendors on sidewalk obstruct pedestrian flow. Several vehicles park on road. Some pedestrians use the road. 	arently De	Guia) off Pio
Physical Conditions	 There are no lane markings on either of the intersecting roads. Pavement in good condition on both roads. Relatively high sidewalk (approx. 20 cm) on Pio Valenzuela. Convenience store at the Southeast corner, and a gasoline station 	at the Nort	theast corner.

Signalization	None	Pavement Markings		None		Peak	07:00-08:00
		Peak Hour Traffic Volumes (PCUs)			% Public	Pedestrian	
Approach	Dimensions	Left	Through	Right	Total	Transport	Volume
A1: MacArthur Hwy(N)	14.7m	157	1,770	NA	1,927	60.1	l Light
A2: Valenzuela	7.1m	. 35	NA	282	317	32.28	Moderate
A3: MacArthur Hwy (S)	14.6m	NA	1,073	87	1,160	54.46	Light
A4: None	None	None	None	None	None	None	None
	Total	439	2,843	122	3,404		
Pass	enger Flows					[



Name	MacArthur Hwy /P Valenzuela St	Code	VL-03
Sheet	Analysis	LGU	Valenzuela

- 1) Existing practice of keeping tricycles off Pio Valenzuela should be maintained.
- 2) Vendors on sidewalks obstruct pedestrian flows, causing pedestrians to use the carriageway.
- 3) Main traffic is along MacArthur Highway, accounting for 90% of 2-way volumes. Problem arises when "green" for Pio Valenzuela traffic gets more than proportionate allocation, or when cycle time become too long (more than 2 minutes).




Name	MacArthur Hwy /P Valenzuela St	Code	VL-03
Sheet	Proposed Improvements	LGU	Valenzuela
Engineering	Vehicle volume on Pio Valenzuela does not warrant ma than the installation of pavement markings (lanes, dire-	jor re-engineering of th ctional arrows, stop line	e junction, other , zebra).
Enforcement	Continue policy of disallowing tricycles from picking u Remove vendors from sidewalks, while their numbers		Valenzuela,
	Provide line markings up to 100 mtrs. away from intersection	Disallow vendors from obstruction dicate pedestrian crossings ith zebra markings	cting sidewalk

LOCATION: VL03, MacArthur Highway / P. Valenzuela Street (VALENZUELA) (cost summary)

(cost sailing	***			
A. Pavement Markings:	<u>Unit</u>	Quantity	Unit Cost	Total Cost
Longitudinal Lines:				
1, Center Unes			** **	
a) Broken Line, 100 or 150mm width, 3m length, w = 200mm	i,m i,m	140.00 60.00	60.00 150.00	8,400.00 9,000.00
b) Solid White Lines, 200mm width 2. Lane Lines (100mm or 150mm width)	6-[]1	• • • • • • • • • • • • • • • • • • • •	150.00	3,000.00
a) Solid Lines, w = 150 mm	l.m	30.00	112.50	3,375.00
b) Broken Lines w= 150mm	l.m	470.00	45.00	21,150.00
3. Barrier Lines				
a) Unbroken Double Yellow Lines (100 or 150mm width)	l.m	-	٠	-
b) Single Yellow Line with broken White Lines (100-150mm)	l.m	-	•	•
4. Edge Lines a) Pavement Edge (Shoulders)	l.m			_
b) Median Edge	l.m	•	-	
5. Continuity Line	l.m	•	-	-
6. Transition Line	l.m	•	•	-
Transverse Lines:				
1. Stop Lines (Solid Lines) white, width = 450 mm	1.m	20.00	337.50	6,750.00
2. Give Way (Yield Lines)	i.m	•	-	
3. Pedestrian Crossing Markings				
a) Zebra Crossing (Non-Signalized), width = 300mm	l.m	240.00	225.00	54,000.00
b) Cross Walks (Signalized), width = 300mm	l.m	-	-	•
Other Lines:				
1. Turn Lines (broken Lines)	l.m	-		-
2. Parking Bay Lines				
a) Parallel Bays, width = 100mm	l.m	-	-	-
b) Angle Bays	l.m	•	•	
3. Painted Median Islands 4. 8US and PUJ Lane Markings	l.m l.m	-	•	į
S. Channelized Junction Pavement Marking	1.m		-	
6. Yellow Box Line, w= 150mm	1.m	-	•	
Other Markings;				
Approach Markings to Islands and Obstructions Chevron Markings	l.m l.m	•	•	-
3. Curb Markings for Parking Restrictions	l.m	-	-	•
4. Approach to Railroad Crossings	l.m			
5. Diagonal Markings on Sealed Shoulders				
a) Outline, 150mm width	l.m	~	_	-
b) Diagonal Bars, 300mm width	l.m	-	-	-
Messages and Symbols:				
1. Messages	· pcs			-
2. Symbols				
a) Give Way symbol	pcs	-	-	-
b) Pavement Arrows				
1) Through Arrow = 1.21 sq.m / each 2) Combined Arrow = 2.44 sq.m / each	pcs	2.00 3.00	907.50 1.830.00	1,815.00 5,490.00
2) Combined Arrow = 2.44 sq.m / each 3) Turn Arrow = 1.46 sq. m / each	bcz bcz	3.00	1,030.00	3,490.00
c) Numerals	bcz	•	-	-
·	,			
B. Signs				
1. No Parking Sign	Units	1.00	2,716.00	2,716.00
2. Pedestrian Crossing Sign	Units Units	3,00 1,00	3,850.00	11,550.00
3. Stop Sign 4. Directional Sign	Units	1.00	2,718.00	2,718.00
5. 8us / PUJ Stop Sign	Units	-	-	
C. Other Works				
1. Reprogramming of Traffic Signal	1.5.	•	•	-
2. Pedestrian Steel Railing	l.m.	•	•	-
Sidewalk Improvement a) Excavation & Subgrade Preparation	J.m			_
b) 4" Concrete Sidewalk	1.m	•	-	
4. Repair Damaged Pavement				
a) Excavation & Subgrade Preparation	sq.m	•	-	•
b) 8" Concrete Pavement	इ प्.ता	•	•	•
70741				435565
TOTAL Contingencies, 5%				126,964.0 6,348.2
CMS, 10%				12,696.4
Miscellaneous (fees, permits, etc), 5%				6,348.2
Govt. Supervision, 2%				2,539.2
				***====
TOTAL COST				154,896.08


Name	Ma	cArthur Hwy / Tamaraw Hills	Code	VL-04			
Sheet	Sui	nmary of Observations	LGU	Valenzuela			
Traffic Conditions	1) 2) 3)	Unsignalized T-intersection Tricycles waiting along Tamaraw Hills road on the exit lane near timmediately at the intersection, though fairly well-ordered/well-pknown to occupy both sides of the road during peak hours Few pedestrians on road					
itions	1)	No lane markings on either of the intersecting roads. Pavement damage on exit and entry lanes of Tamaraw Hills cause	sed apparent	ly by some kind of			
Physical Conditions	3)	excavation that was not properly refilled. 3) Convenience store at the north corner of Tamaraw Hills Rd, where the narrow sidewalk begins.					
hysica	5)	4) Petron gas station at the south corner of Tamaraw Hills Rd. 5) Sign on Tamaraw Hills Rd approach lane, "Tricycle Pedicab, BAWAL PUMASOK".					
	6)	Waiting shed on the northbound side of MacArthur just north of	f the Tamara	w Hills entry lane.			

Signalization	None	ne Pavement Markings None		None Pavement N		ne	Peak	15:00-16:00
	_, ,	Peak Hour Traffic Volumes (PCUs)				% Public	Pedestrian	
Approach	Dimensions	Left	Through	Right	Total	Transpor	t Volume	
A1: MacArthur Hwy(N)	14.6m	22	992	NA	1,014	41.5	8 Light	
A2: Tamaraw Hills	3.4m	85	NA	25	109	35.2	5 Moderate	
A3: MacArthur Hwy (S)	14.6m	NA	1,310	152	1,462	42.5	2 Light	
A4: None	None	None	None	None	None	Non	e None	
	Total	106	2,302	176	2,584			
Pass	enger Flows							



Name	MacArthur Hwy / Tamaraw Hills	Code	VL-04
Sheet	Analysis	LGU	Valenzuela

- 1) Volume on Tamaraw Hills constitute less than 5% of junction traffic, but eats up more than proportionate time. Partly caused by pavement damage.
- 2) Present location and orientation of tricycles exposes passengers to the traffic, their loading and unloading into and from the sidecar being immediately facing the carriageway. This is unsafe for the passengers and presents an opportunity for numerous instances of tricycle passengers obstructing traffic on the carriageway.
- 3) Tricycles reduce the capacity of Tamaraw Hills Rd but there are presently no viable alternative locations to take them off the road. Tricycles, being located at the intersection inadvertently cause exiting traffic to take all or part of the opposing lane on Tamaraw Hills Rd.




Vame	MacArthur Hwy / Tamaraw Hills	Code	VL-04
Sheet	Proposed Improvements	LGU	Valenzuela
Engineering	 Repair pavement damaged by waterworks excavations, as well as a turning right to Tamaraw Hills from MacArthur (from the South). Install pavement markings (lanes, zebra, double-yellow) as indicated. Designate the loading and unloading areas of tricycles, 50 meters at Appropriate traffic control signage should be placed. These are espated. Sign indicating "STOP" for traffic coming from A. Fernando b. Sign indicating appropriate loading and unloading area for tricy. 	d. away from pecially:	
Enforcement	 Tricycles should be set back at least 10 meters away from the inter vehicles turning into and coming from MacArthur highway. Loadin designated areas only. Presence of Traffic Enforcers, especially during peak hour, to clear Give priority to traffic at MacArthur (15% of time), without too lor 	ig / unloadi entry / exit	ng be at of Tamaraw Hills
	Application of turn arrows Provide lane markings up to 100 meters away from the intersection Repair pavement damage Indicate pedestrian crossings with zebra markings		

LOCATION: VL04, MacArthur Highway / Tamaraw Hills (VALENZUELA) (cost summary)

(cost summary)	•			
A. Pavement Markings	<u>Voi</u> t	Quantity	Unit Cost	Total Cost
Longitudinal Lines:				
1. Center Lines		242.00	50.00	12,600.00
a) Broken Line, 100 or 150mm width, 3m length, w = 200mm	l.m	210.00 90.00	60.00 150.00	13,500.00
b) Solid White Lines, 200mm width 2, Lane Lines (100mm or 150mm width)	l.m	90.00	130,00	,5,504.55
a) Solid Lines, w = 150 mm	· l.m		-	-
b) Broken Lines w= 150mm	l.m	400.00	45.00	18,000,00
3. Barrier Lines				•
a) Unbroken Double Yellow Lines (100 or 150mm width)	l.m	•	-	•
b) Single Yellow Line with broken White Lines (100-150mm)	i.m	•	•	-
4. Edge Lines a) Pavement Edge (Shoulders)	1.m			<u>-</u>
b) Median Edge	l.m	-	•	•
5. Continuity Line	l.m	-	-	•
6. Transition Line	l.m	•	-	•
Transverse Lines:	٠.			
1, Stop Lines (Solid Lines) white, width = 450 mm	l.m t.m	20,00	337.50	6,750.00
Give Way (Yield Lines) Pedestrian Crossing Markings	i.m	•	•	
a) Zebra Crossing (Non-Signalized), width = 300mm	l.m	110.00	225.00	24,750.00
b) Cross Walks (Signalized), width = 300mm	l.m	• .	. •	•
Other Lines:				
1. Turn Lines (broken Lines)	l.m	-	· -	-
2. Parking Bay Lines				
a) Parallel Bays, width = 100mm	l.m	•	. •	•
b) Angle Bays	J.m	-	•	•
3. Painted Median Islands	J.m	•	-	-
4. 8US and PUJ Lane Markings	l.m l.m	•	-	
5. Channelized Junction Pavement Marking 6. Yellow Box Line, w= 150mm	l.m	-	•	
7. Tricycle Stand Markings, width = 100mm	l.m	52.00	75.00	3,900.00
Orbon Markings.			٠.	
Other Markings: 1. Approach Markings to Islands and Obstructions	l.m		_	
2. Chevron Markings	l.m	-	-	
3. Curb Markings for Parking Restrictions	l.m	-	•	-
4, Approach to Railroad Crossings	l.m	-	-	•
5. Diagonal Markings on Sealed Shoulders			+	
a) Outline, 150mm width	l.m	-	-	•
b) Diagonal Bars, 300mm width	i.m	•	-	•
Messages and Symbols:				
1. Messages	pcs	• .	-	-
2. Symbols				
a) Give Way symbol	pcs	•	-	•
b) Pavement Arrows 1) Through Arrow	pcs		•	
2) Combined Arrow = 2.44 sq.m/each	pcs	•	-	
3) Turn Arrow = 1.46 sq. m / each	pcs		•	-
c) Numerals	pcs	-	-	-
n class				
8. Signs 1. No Parking Sign	Units			
2. Pedestrian Crossing Sign	Units	3.00	3,850.00	11,550.00
3, Stop Sign	Units	1.00	2,718.00	2,718.00
4. Directional Sign	Units		-	-
5. Bus / PUJ Stop Sign	Units	-	-	-
C. Other Works				
1. Reprogramming of Traffic Signal	l.s.	-	•	-
2. Pedestrian Steel Railing],m.	-	•	•
3. Sidewalk Improvement				
a) Excavation & Subgrade Preparation	l.m	•	•	
b) 4* Concrete Sidewalk 4. Repair Damaged Pavement	l.m	-	•	•
4, Repair Damaged Pravement a) Excavation & Subgrade Preparation	sq.m	48,00	65.25	3,132.00
b) 8* Concrete Pavement	sq.m		790.00	37,920.00
ŢŎŢĀ;				134,820.00
TOTAL Contingencies, 5%				6,741.00
CMS, 10%				13,482.00
Miscellaneous (fees, permits, etc), 5%				6,741.00
Govt. Supervision, 2%				2,696.40
·				*** *** *** *** *** ***
TOTAL COST				164,480.40


Name	rme Fatima Ave / Serrano St Code VL-0								
Sheet	Sui	mmary of	Observation	S		LGU	Vale	nzuela	
Traffic Conditions	1) 2) 3) 4)	Tricycles s Our Lady	tand along Fat	ion being fed by a Y-inte tima Avenue before the s ch is a major traffic gene served	outh corner of M. Serr		eet.		
Physical Conditions	1)	40 meters	s away from to the highway.		junction. This may po	ose a p	roblen	n if vehicle	
Physical	3)	 Sidewalk on Fatima Ave has many obstructions, especially area closer to the intersection. Fatima Avenue and T. Serrano St both meet at MacArthur Highway, but a median with plants divides the two streets before reaching MacArthur Highway. 							

Signalization	None	ne Pavement Markings None		Pavement Markings		None		09:00-10:00
A	Di-	Peak	Hour Traffic	% Public	Pedestrian			
Approach	Dimensions	Left	Through	Right	Total	Transport	Volume	
A1: MacArthur Hwy(N)	14.4m	69	1,464	NA	1,532	42.45%	Light	
A2: Fatima Ave (NE)	10.2m	44	NA	13	57	34.02%	Light	
A3: Serrano (SE)	7.2m	17	. NA	25	41	46.22%	Light	
A4: MacArthur Hwy (S)	14.4m	NA	1,268	134	1,401	21.00%	Light	
	Total	129	2,731	170	3,030	-		
Pass	enger Flows		.					



Name	Fatima Ave / Serrano St	Code	VL-05
Sheet	Analysis	LGU	Valenzuela

- 1) The crossing of vehicles from Serrano St to Fatima Ave, before reaching MacArthur Highway, creates conflict with vehicles coming from MacArthur. Length of Fatima (from MacArthur Higway/to Serrano St) is too short and capacity reduced by tricycles and roadside friction.
- 2) Present location and orientation of tricycles exposes passengers to the traffic, their loading and unloading into and from the sidecar being immediately facing the carriageway. This is unsafe for the passengers and presents an opportunity for numerous instances of tricycle passengers obstructing traffic on the carriageway.




	Fatima Ave / Serrano S	it		Code	VL-05
Sheet	Proposed Improvemen	nts		LGU	Valenzuela
Engineering	 2) Installation of signs we markings such as arrown Fatima Avenue before 3) Relocate tricycle stance 4) Indicate pedestrian cr 	median which obstruct view which indicate directionality lows and lane markings. Inst e Serano. It to Northern side of Fatima cossings with zebra marking lane markings up to 100 me	of the approaches, all "Right lane mus a. s (on MacArthur an	t turn Righ d Fatima).	nt" sign along
Enforcement	Serrano). According intersection to provide	ng on both sides of Fatima ly, tricycles should be set ba de space for vehicles turning vement, from Fatima Ave to	ick at least 10 mete g into and from Ma	rs away fro cArthur H	om the
	l				
	up t	vide lane markings to 100 meters away possible) from resection		Fallen Aug.	Nace 'Merging Traffic Sign'

LOCATION: VLOS, Fatima Avenue / Serrano St. (VALENZUELA) (cost summary)

(cost summar	y)			
A. Pavement Markings	<u>Unit</u>	Quantity	Unit Cost	Total Cost
Longitudinal Lines:				
1. Center Lines 2. Broken Line 100 or 150mm width 2m leanth w = 200mm	l.m	340.00	60.00	20,400.00
a) Broken Line, 100 or 150mm width, 3m length, w = 200mm b) Solid White Lines, 200mm width	l.m	60.00	150,00	9,000.00
2. Lane Lines (100mm or 150mm width)				••••
a) Solid Lines, w = 150 mm	i.m	. •	•	•
b) Broken Lines w= 150mm	l.m	400.00	45,00	18,000.00
3, Barrier Lines				
a) Unbroken Double Yellow Lines (100 or 150mm width)	1.m	-	-	•
b) Single Yellow Line with broken White Lines (100-150mm)	l.m	-	-	•
4. Edge Lines a) Pavement Edge (Shoulders)	l.m			
b) Median Edge	. lan			_
5. Continuity Line	l.m	-	•	•
6. Yransition Line	l.m	-	-	•
Transverse Lines:				
1. Stop Lines (Solid Lines) white, width = 450 mm	1.m	16.00	337.50	5,400.00
2. Give Way (Yield Lines)	l.m	-	•	-
3. Pedestrian Crossing Markings			425.44	C 4 000 00
a) Zebra Crossing (Non-Signalized), width = 300mm	i.m I.m	288.00	225.00	64,800.00
b) Cross Walks (Signalized), width = 300mm	LH	•		
Other Lines:				•
1. Turn Lines (broken Lines)	l,en	-		-
2. Parking Bay Lines				
a) Parallel Bays, width = 100mm	l.m	-	-	•
b) Angle Bays	l.m I.m	•	•	•
3. Painted Median Islands 4. 8US and PUJ Lane Markings	Lm	•		-
5. Channelized Junction Pavement Marking	Lm		-	-
6. Yellow Box Line, w= 150mm	1.m	•	* * * · · <u>-</u>	•
7. Tricycle Stand Markings, width = 100mm	l.m	40.00	75.00	3,000.00
Other Markings:				
1. Approach Markings to Islands and Obstructions	l.m	-	•	•
2. Chevron Markings	l.m	•		•
3. Curb Markings for Parking Restrictions	l.m	-	-	•
4. Approach to Railroad Crossings	l.m	-	-	•
 Diagonal Markings on Sealed Shoulders Outline, 150mm width 	1.m		_	
b) Diagonal Bars, 300mm width	l.m	•	-	•
Messages and Symbols:			_	_
1. Messages 2. Symbols	pcs	•	-	
a) Give Way symbol	pcs		_	
b) Pavement Arrows	•			
1) Through Arrow = 1.21 sq.m / each	pcs	6.00	907.50	5,445.00
2) Combined Arrow = 2.44 sq.m / each	pcs	2,00	1,830.00	3,660.00
3) Turn Arrow = 1.46 sq. m / each	pcs	•	-	-
c) Numerals	pcs	•	•	•
B. Signs				
1. No Parking Sign	Units	·	- '	•
2, Pedestrian Crossing Sign	Units		3,850.00	11,550.00
3. Stop Sign	Units		2,718.00	2,718.00
4. Directional Sign, "Keep Right"	Unit		2,716.00	2,716.00
5, Bus / PUJ Stop Sign 6. Merging Traffic Sign	Unit: Unit:		3,850.00	3,850.00
C. Other Signs 1. Reprogramming of Traffic Signal	l.s.		_	
1. Reprogramming of Traffic Signal 2. Pedestrian Steel Railing	i.s. i.m.	:		-
3. Removal of Plants on Median	l.s.		-	3,000.00
3. Sidewalk Improvement			•	
a) Excavation & Subgrade Preparation	l.m	-	•	•
b) 4" Concrete Sidewalk	1.m	•	•	-
4. Repair Damaged Favement				
a) Excavation & Subgrade Preparation b) 8° Concrete Pavement	n.pa n.pa			
·	M'u		-	
TOTAL				153,539.00
Contingencies, 5%				7,676.95
CMS, 10%				15,353.90
Miscellaneous (fees, permits, etc), 5% Govt. Supervision, 2%		•		7,676.95 3,070.78
GOTE Supervision, 276				3,0,0,0
TOTAL COST				187,317.58


Name	MacArthur Hwy / Poblacion Road	Code	VL-06					
Sheet	Summary of Observations	LGU	Valenzuela					
Traffic Conditions	 Signalized T-intersection under manual control. Heavy pedestrian volume. Pedestrians cross Poblacion II at any location. Major traffic is on MacArthur Highway. 							
Physical Conditions	 Pedestrian barriers installed at both corners of Poblacion Road, t crossing. Debris on sidewalks. Narrow sidewalk from South Supermarket towards Poblacion Road. Lane markings non-existent or ill-defined. 	o contro	ol the location o					

Signalization	Manual	Pavemen	Pavement Markings Very li		Very limited		6:00-1700
		Peak Hour Traffic Volumes (PC			PCUs)	% Public	Pedestrian
Approach	Dimensions	Left	Through	Right	Total	Transport	Volume
A1: Poblacion Rd	10.1m	133	NA	76	209	29.61%	Moderate
A2: MacArthur Hwy(N)	14.2m	NA	1,199	160	1,359	53.29%	Heavy
A3: None	None	None	None	None	None	None	None
A4: MacArthur Hwy (S)	14.2m	30	964	NA	994	54.26	Moderate
	Total	163	2,163	236	2,561		
Pass	enger Flows					1	



Name	McArthur Highway / Poblacion Road	Code	VL-06
Sheet	Analysis	LGU	Valenzuela

- 1) Poblacion II is an important access to the Valenzuela City Hall. Uncontrolled crossing of pedestrians. Hamper smooth entry / exit from MacArthur. Turning radii at corners also not convenient.
- 2) Traffic on MacArthur comprised about 92% of vehicles passing through the junction, but maybe getting less than proportionate green time from the enforcers controlling the signal.



Name	McArthur Highway / Poblacion Road	Code	VL-06
Sheet	Proposed Improvements	LGU	Valenzuela
Engineering	 Install pavement markings designation, (lane, zebra, double-yello MacArthur Highway and Poblacion Rd. Yellow box for indicating "Keep Intersection Clear" should be pai Widen/improve sidewalks, along side of A4 and A2. Smoothen sharp corners, north and south, to facilitate turning management 	nted at the ir	itersection.
Enforcement	 Discipline pedestrians to cross only at designated areas, and only is "Red". (Green on MacArthur Highway). Signal phasing should give priority to MacArthur Highway and li 		
	S	w Box markings top Line	Otherway

LOCATION: VL06, MacArthur Highway / Poblacion Road (VALENZUELA) (cost summary)

(cost summary)				
Pavement Markings:	<u>Unit</u>	Quantity	Unit Cost	Total Cost
Longitudinal Lines:				
1. Center Lines		450.00	60.00	9,600.00
a) Broken Line, 100 or 150mm width, 3m length, w = 200mm	i.m	160.00 90.00	150.00	13,500.00
b) Solid White Lines, 200mm width	l.m	90.00	(50.00	13,300,00
2. Lane Lines (100mm or 150mm width)	1.m	60.00	-	_
a) Solid Lines, w = 150 mm	l.m	140.00	45.00	6,300.00
b) Broken Lines w≈ 150mm 3. Barrier Lines	7.111	140.00		
a) Unbroken Double Yellow Lines (100 or 150mm width)	l.m	•		
b) Single Yellow Line with broken White Lines (100-150mm)	l.m	-		
4. Edge Lines				
a) Pavement Edge (Shoulders)	l.m	-		-
b) Median Edge	J.m	-	-	
5. Continuity Line	l.m	-	-	
6. Transition Line	l.m	•	•	-
Transverse Unes:				
1. Stop Lines (Solid Lines) white, width = 450 mm	l.m	22.00	337.50	7,425.00
2. Give Way (Yield Lines)	l.m		-	•
3. Pedestrian Crossing Markings				
a) Zebra Crossing (Non-Signalized), width = 300mm	ŧ.m	•	-	-
b) Cross Walks (Signalized), width = 300mm	l.m	84.00	225.00	18,900.00
Other Lines:				
1. Turn Lines (broken Lines)	l.m	-	-	-
2. Parking Bay Lines				
a) Parallel Bays, width = 100mm	l.m	-	•	-
b) Angle Bays	l.m	• .	•	•
3. Painted Median Islands	1.m	•	•	•
4. BUS and PUJ Lane Markings	l.m	-	-	-
5. Channelized Junction Pavement Marking	l.m	99.00	75.00	7,425.00
6. Yellow Box Line, w= 150mm	l.m	99.00	/5,00	7,425.00
7. Tricycle Stand Markings, width = 100mm	Lm	•	-	•
Other Markings:				
1. Approach Markings to Islands and Obstructions	l.m	•	•	-
2. Chevron Markings	l.m	-	•	•
3. Curb Markings for Parking Restrictions	l.m	-	-	-
4. Approach to Railroad Crossings	l.m	•	•	-
5. Diagonal Markings on Sealed Shoulders				
a) Outline, 150mm width b) Diagonal Bars, 300mm width	l.m l.m	:		
by blagottal bals, scotting ender				
Messages and Symbols:				-
1. Messages	pcs	-	•	
2. Symbols	200		_	_
a) Give Way symbol	pcs		-	
b) Pavement Arrows	200	4.00	907.50	3,630,0
1) Through Arrow = 1.21 sq.m / each 2) Combined Arrow = 2.44 sq.m / each	bcz bcz	4.00	1.830.00	7,320.0
2) Combined Arrow = 2.44 sq.m / each 3) Turn Arrow = 1.46 sq. m / each	pcs		1,050.00	.,524.0
c) Numerals	pcs			
cy reality and	F			
, Signs				
1. No Parking Sign	Units	3.00	3,850.00	11,550.0
2. Pedestrian Crossing Sign	Units			2,718.0
3. Stop Sign	Units Units	1,00	2,718.00	2,710.0
4. Directional Sign, "Keep Right" 5. Bus / PUJ Stop Sign	Units			
3. 543 / 1 44 4 44 5 1311				
. Other Works	1.6			
1. Reprogramming of Traffic Signal	l.s.	-	. •	•.
2. Pedestrian Steel Railing	i,m.	-	-	17,000.0
	l.m.	•	•	.,,000,0
3. Improve/Smoothen Sharp Curve				6,187.5
Improve/Smoothen Sharp Curve Sidewalk Improvement (Widening) Sides A4 & A2	1 m	125.00	49.50	
Improve/Smoothen Sharp Curve Sidewalk Improvement (Widening) Sides A4 & A2 Excavation & Subgrade Preparation	i.m	125.00 125.00	49.50 395.00	49,375.0
3. Improve/Smoothen Sharp Curve 4. Sidewalk Improvement (Widening) Sides A4 & A2 a) Excavation & Subgrade Preparation b) 4" Concrete Sidewalk	i.m i.m	125.00 125.00	49.50 395.00	49,375.0
3. Improve/Smoothen Sharp Curve 4. Sidewalk Improvement (Widening) Sides A4 & A2 a) Excavation & Subgrade Preparation b) 4' Concrete Sidewalk 5. Repair Damaged Pavement).m			49,375.0
3. Improve/Smoothen Sharp Curve 4. Sidewalk Improvement (Widening) Sides A4 & A2 a) Excavation & Subgrade Preparation b) 4" Concrete Sidewalk				49,375.0
3. Improve/Smoothen Sharp Curve 4. Sidewalk Improvement (Widening) Sides A4 & A2 a) Excavation & Subgrade Preparation b) 4" Concrete Sidewalk 5. Repair Damaged Pavement a) Excavation & Subgrade Preparation	l.m sq.m			
3. Improve/Smoothen Sharp Curve 4. Skidewalk Improvement (Widening) Sides A4 & A2 a) Excavation & Subgrade Preparation b) 4' Concrete Sidewalk 5. Repair Damaged Pavement a) Excavation & Subgrade Preparation b) 8' Concrete Pavement TOTAL	l.m sq.m			160,930.9
3. ImproverSmoothen Sharp Curve 4. Skiewalk Improvement (Widening) Sides A4 & A2 a) Excavation & Subgrade Preparation b) 4" Concrete Sidewalk 5. Repair Damaged Pavement a) Excavation & Subgrade Preparation b) 8" Concrete Pavement TOTAL Contingencies, 5%	l.m sq.m			160,930.9 8,046.9
3. Improve/Smoothen Sharp Curve 4. Sidewalk Improvement (Widening) Sides A4 & A2 a) Excavation & Subgrade Preparation b) 4' Concrete Sidewalk 5. Repair Damaged Pavement a) Excavation & Subgrade Preparation b) 8' Concrete Pavement TOTAL Contingencies, 5% CMS, 10%	l.m sq.m			160,930.5 8,046.5 16,093.1
3. Improve/Smoothen Sharp Curve 4. Sidewalk Improvement (Widening) Sides A4 & A2 a) Excavation & Subgrade Preparation b) 4" Concrete Sidewalk 5. Repair Damaged Pavement a) Excavation & Subgrade Preparation b) 8" Concrete Pavement TOTAL Contingencies, 5% CMS, 10% Miscellaneous (fees, permits, etc), 5%	l.m sq.m			160,930.5 8,046.5 16,093.6 8,046.5
3. Improve/Smoothen Sharp Curve 4. Sidewalk Improvement (Widening) Sides A4 & A2 a) Excavation & Subgrade Preparation b) 4" Concrete Sidewalk 5. Repair Damaged Pavement a) Excavation & Subgrade Preparation b) 8" Concrete Pavement TOTAL Contingencies, 5% CMS, 10%	l.m sq.m			160,930.5 8,046.5 16,093.0 8,046.5 3,218.6



