Case No.	1st category			
MW-33 Production management				
2nd category				
	5S			

Division ,	/ Process
Stainless exhaust p	pipe manufacturing
Industry	Sector / Product
Automotive parts mfg. (after-market)	Exhaust pipe manufacturing

Subject

Reduction of time to search jigs and tools by providing a storage space (improvement of workability through 5S activities)

Di				

Many welding jigs are hooked on hangers without assortment or marking and it takes time to find a right one. Tools are kept disorderly in tool boxes and it is hard to tell which is in use or available.

■ Guidance:

- 1) To assign a serial number to each jig, mark the name and the number on the jig, and hook it on a designated position of the hanger; and
- 2) To indicate tool shapes in each box.

Response of the enterprise (as confirmed during the follow-up activity):

The recommendations have not been implemented as the company plans to relocate the factory and is busy with new jobs.

Other relevant points (issues to be solved and problems remained):

Although the management understands what they should do, but they do not seem to feel the need for improvement strongly because they do not have management staff and are busy with daily operation. It is important to visit them frequently and provide information and guidance repeatedly.

Description of Problems

- 1) Many kinds of jig for tail pipe assembling work are hung on the store stand. It is difficult to find the necessary jig due to them being not labeled properly.
- 2) The work place has reduced in the pipe cutting shop because there are too many obsolete products.
- 3) Many hand tools are hung on the hanger in a toolbox, which is situated on the wall of the welding shop. It is however difficult to know what tools are in use due to inadequate labeling.

Diagnosis and Recommendation

- 1) Jigs should be clearly labeled, showing their name and control number. Their storing address and control number should also be shown on the storing stand. It makes the accessibility of jigs easy and increases productivity (See Photograph 1).
- 2) Products should be arranged and obsolete products disposed off.
- 3) The shape of each tool should be drawn on the hanging board, which would indicate which tools are in use as well as the proper position of the tools (See Photograph 2).

Photograph 1 The assembling jigs for tail pipe and the store stand

The Present state






Recommendation

Jigs should be clearly labeled, showing their name and control number. Their storing address and control number should also be shown on the storing stand.

It makes the accessibility of jigs easy and increases productivity.

Photograph 2 The hand toolbox in the welding shop

The Present state





Recommendation

The shape of each tool should be drawn on the hanging board, which would indicate which tools are in use as well as the proper position of the tools.

1	Case No.	1st category	
	MW-34	Production management	
		2nd category	
1		Process control	Aui

Dívision /	Process
Stainless exhaust p	lpe manufacturing
Industry	Sector / Product
Automotive parts mfg. (after-market)	Exhaust pipe manufacturing

_	
	•
	_

	 - 4	3 - 11	production	4-4-	1	
 	 Ψ.		production	~~~	ų,	PICCOS

	nos	

No daily production data are collected for each process and absence of such data prohibits identification of problems in a particular process.

Guidance:

To collect daily production data in each process and analyze them to see if any problem occurs.

Response of the enterprise (as confirmed during the follow-up activity):

The recommendations have not been implemented as the company plans to relocate the factory and is busy with new jobs.

Other relevant points (issues to be solved and problems remained):

Although the management understands what they should do, but they do not seem to feel the need for improvement strongly because they do not have management staff and are busy with daily operation. It is important to visit them frequently and provide information and guidance repeatedly.

Description of Problems

The daily production quantities of components are not known at every workshop process.

Diagnosis and Recommendation

The data of actual production quantities should be collected and analyzed to know the conditions of production. The problems of the workshop will be clear by analyzing of production data, and countermeasures to the problems will be taken easier.

Case No.	1st category	
MW-35	Production management	
	2nd category	
	55	

····	Divisio	n / Process
		The second control of the entire entre second control of the entire entre entr
	Automotive steeri	ng knuckle processing
	Industry	Sector / Product
	Metalworking	Machining

Subject

5S activities in the materials and products storage yards

■ Diagnosis:

Storage yards for materials and finished products, a final inspection station, and other facilities are provided within the warehouse. Jig and old tools and apparatuses are also stacked. Due to the limited space, pallets storing materials are stacked in five stages, which can collapse to cause an accident.

Guidance:

Rearrangement of the warehouse floor is recommended as follows:

- 1) To separate the materials and products storage yards clearly from the work space including the inspection station;
- 2) To assort and dispose old tools and equipment, and relocate jigs to the machine shop; and
- 3) To restrict the stacking of pallets up to four stages,

Response of the enterprise (as confirmed during the follow-up activity):

The materials and products storage yards have been relocated to another building and the entire floor is used as workspace. Old equipment and tools have been disposed.

Other relevant points (issues to be solved and problems remained):

The company makes rearrangement of the entire factory and plans to expand it by acquiring an adjacent land. Upon completion of the rearrangement project, areas of improvement achieved through 5S activities and remaining problems should be checked.

Description of Problems

The reasons for the stock floor being crowded resulting in inefficiency are that receiving materials for work, shipping of products, painting and final inspection and storing of Machining jigs, old equipment and materials are carried out in this area. The baskets with the castings are stacked 5 high this is not only dangerous but also makes it difficult to lift the baskets up and down.

Diagnosis and Recommendation

(See Sketch & Photographs)

The set up of the stock floor needs to be rearranged in order to get the most efficient usage by placing all needed articles into the right position.

- 1) The stock place for materials and products has to be separated from the painting space and the final inspection place.
- 2) All existing articles have to be sorted and only the articles needed on the stock floor should be kept and placed into the right position. See positioning below.

Castings and materials: Stock floor

• Completed products: Stock floor

• Old equipment and unused material: Dispose

• Machine Jigs: Machine shop

3) The baskets should be stacked 4 high in order to be safe.

Sketch: The Present Layout of Stock Floor

Machine Shop	Painting Final Inspection Machining Jig	Temp. Storage FC Stock	Office
		AL Stock	

Photographs: The View of Stock Store Inside





Case No.	1st category	Division / Process				
MW-36	Production management	Automotive steering knuckle processing				
2nd category		Industry	Sector / Product			
Transportation management		Metalworking	Machining			

2nd category Transportation management	Industry	Sector / Product
Hurisportation management	Metalworking	Machining
	Subject	
Improvement of workflow between proce	esses	
Diagnosis:		
Four machines are arranged without of	consideration of process flo	w, resulting in disorderly workflow
■ Guidance:		
To rearrange the machines in order o	f processes and create a lin	ear and efficient layout.
Response of the enterprise (as confir	rmed during the follow-up	activity):
The company carried out a rearrangel according to the order of processes.	ment project that would inc	lude the change in machine layou
Other relevant points (issues to be s	olved and problems remain	ned):
After completion of the layout change activities.		


Description of Problems

Observing the work flow of the steering knuckle the following was noted. Four machines located in distant areas on the factory floor are used to produce this main product.

Diagnosis and Recommendation


The layout for this procedure needs to become a straight line workflow in order to lessen transport distance of the work between processes (See Sketch).

Sketch: The Present Flow of Steering Knuckle in the Machine Shop



Recommendation

The layout for this procedure needs to become a straight line workflow in order to lessen transport distance of the work between processes.



Case No.	1st category							
MW-37 Production managemen								
	2nd category							
Transp	ortation management							

Division	n / Process
Automotive steering	ng knuckle processing
Industry	Sector / Product
Metalworking	Machining

Subject

Improvement of transportation of in-process work pieces between processes

■ Diagnosis:

Work pieces, upon completion of each process, are placed on a large pallet, from which they are transferred manually to another vacant pallet (on a cart) for the subsequent process. It takes long time and is inefficient.

■ Guidance:

The following improvement was proposed:

- 1) To keep a small basket placed on a carriage near the machine, put completed work pieces in the basket, and move the carriage to the subsequent process as soon as the basket becomes full; or
- 2) To use a small basket with wheels for the same purpose.

Response of the enterprise (as confirmed during the follow-up activity):

The above recommendation was not implemented because the company intended to change machine layout and consider pallet modification after the layout change has been completed.

Other relevant points (issues to be solved and problems remained):

It is possible to eliminate the pallet if work arrangement is modified with the planned layout change, such as use of a slider. Periodical visit and guidance are required to encourage the recommended improvement.

Description of Problems

Steel baskets are used for storage and transportation of the products in the machine shop, it is impossible for a worker to lift the filled basket by hand because it is too large and too heavy (Size: 1,500 mm L x 900 mm W x 600 mm H).

The worker is currently moving the product from a filled basket to an empty basket on a cart and transporting or carrying 2 items at a time to the next process. Both methods are time consuming and unproductive.

Diagnosis and Recommendation

1) For Immediate Action


Smaller baskets and trolleys are needed to carry the products to the next process. Although this will increase the frequency of carriage it will improve the inefficiency of current methods used (See Sketch 1).

2) For Future Consideration

A steel basket of approximate size: 750 mm L x 450 mm W x 500 mm H, with 4 wheels needs to be built (See Sketch 2).

Sketch 1 The Improvement of Carrying Method of Works


The Present Carrying Method



In the case of carrying the works quickly out, a worker has 2 pieces of works in his both hands and carry them to the next process because it takes long times to fill the works in the basker



The Recommendation




It is necessary to make small baskets and trolleys to carry the works to the next process.

When the recommended basket is used, Useless works such as the shifting work and the carrying work by hand become unnecessary because transportation become easy and the number of times of carriage also increases.


Sketch 2 The Improvement of Steel Basket

The Existing Steel Basket









Case No.	1st category		-
MW-38	Production management]	
	2nd category		
	5S		

Division	/ Process									
Automotive steering knuckle processing										
Industry	Sector / Product									
Metalworking	Machining									

_			٠
~ 11	1		2
- 4 - 1		~~	4

5S	activities	on	the	shop	floor

Diagnosis:

The shop floor is littered with cuttings and oil, and a paint indicating a service path is partly lost. Poor housekeeping suggests the lack of systematic 5S activities.

Guidance:

It was advised to implement 5S activities as explained in the seminar and to resurface the floor (uneven and damaged due to wear and tear) with paint.

Response of the enterprise (as confirmed during the follow-up activity):

The above recommendation was not implemented because the company intended to change machine layout and resurface and paint the floor as part of the project, followed by promotion of 5S activities around the machine.

Other relevant points (issues to be solved and problems remained):

It was revealed that the management was willing to promote 5S activities as taught in the seminar and explained during the follow-up survey, but they did not understand the concept of 5S practice completely. Periodical visit and guidance are required to encourage full deployment of 5S activities.

Description of Problems


5S principals are not applied. Shop floor is partial demarcated and too many articles are placed in different areas.


Diagnosis and Recommendation

5S activity needs to be implemented as introduced at the seminar. The shop floor needs to be repaired and cleaned (See Photographs).

Photographs The state of 5S

The Present state of 5S







Recommendation

5S activity needs to be implemented. This can be done by referring to the document of 5S activity introduced at the seminar.

Case No.	1st category	Division / Process								
MW-39	Production management	Production management								
	2nd category	Industry	Sector / Product							
	Process control	Metalworking	Machining, Press, Welding							

2nd category	Industry	Sector / F	roduct
Process control	Metalworking	Machining, Pre	ss, Welding
	Subject		
Production planning and scheduling			
■ Diagnosis:			
As a result, information is not share manager is consulted when product production data for systematic production of production targets. A	tion volume and schedule is no duction management because	otified, he is not able no production plan i	e to use daily s available in
■ Guidance:			
Field guidance was made to teach preparation, which are suitable for	· · · · · · · · · · · · · · · · · · ·	vell as the method fo	or

Response of the enterprise (as confirmed during the follow-up activity):

Other relevant points (issues to be solved and problems remained):

The corporate manager is virtually responsible for production management and has no time to introduce planning practice, although he is willing to do so. Clearly, he requires management staff to assist him, which takes long time. In the meantime, he should use a consultant who provide guidance on a continuous basis by proposing specific actions and providing follow-up advice. Then, in the long run, it is imperative to establish a mechanism to train and promote employees to management staff in a systematic manner.

Description of Problems

There are neither production plans nor schedules put in writing.

Diagnosis and Recommendation

Weekly and daily production planning and scheduling should be made,

- 1) Steps for production planning and scheduling
 - Start the weekly and daily production scheduling from your important products (3 – 5 items). You can modify the schedule forms, and expand the scheduling into other products.
 - Compare the schedule plans with actual production results and analyze reasons for differences. This will improve the management of the production progress.
- 2) Example of Anti-loose Fastener (Refer Attachment A).


How to make the Production Schedule?

(Example: in the case of Anti-loose Fastener)

Break down the product of received order to component parts.
 Example: Anti-loose Fastener



2. Design the manufacturing processes on the basis of the component parts.




3. Make a rough production schedule on a time chart with the consideration of each manufacturing process and capacity.

The start time of manufacturing should be calculated back from the requested Delivery time (shipping date).

Example: Anti-loose Fastener

Production Time Chart of Anti-loose Fastener



- 4. Make a weekly production schedule on the basis of the production time chart. The manufacturing days of each parts should be shown with a bar in the weekly production schedule sheet. [Bar chart] (See Attachment A-1)
- 5. Make a daily production schedule on the basis of the weekly production schedule. The working schedule should be shown in the column of Planned with bar. [Bar chart] (See Attachment A-2)
- 6. Fill in the existent operation cards on the basis of daily production schedule.

- 7. Hand over the operation cards to operators through the foreman.
- 8. Gather the operation cards with the recorded actual production results from the foreman.
- 9. Check whether the jobs were done as scheduled, compare the results with the plans. If any differences arise, the reason of failure should be inquired by the foreman and the operator.
- 10. Add the left jobs in the first place of following day.

Remarks;

- 1. The control system in this recommendation should be applied on the main products (3 5 Items) at the beginning, and then transferred to other products.
- 2. Bottleneck process (weak process), bottleneck machine and important machines should be concentrically controlled.

Weekly Production Schedule (Example)

Scheduled by:								Schedu	led on:	0.	9.Nov.20	01	Week-e	nding:			
						Mo	nday	Tues	days	Wedr	nesday	Thu	rsday	Fr	day	Sati	irday
Order Number	Customer	Product	Parts	Qty	Process	(12.N	ov. (01)	(13.N	ov.'01)	(14.N	ov.'01)	(15,N	ov. '01)	(16.N	ov.'01)	(17.N	ov.'01)
		<u> </u>			· · · · · · · · · · · · · · · · · · ·	AM	PM	АМ	РМ	AM	PM	AM	PM	AM	PM	AM	PM
101	Α	Anti-loose Fastener			Machining		_				ļ		ļ	<u></u>	•		
			Pin	10,000	Machining						ļ						
			Toggle	10,000	Press						1						
				10,000	Assembly	<u> </u>		<u> </u>									
				10,000	Plating (Out)				_								
						<u> </u>											
102	В	Plate Back Hook	Pin	5,000	Press	<u> </u>	·	<u> </u>							İ.,.		<u> </u>
	<u> </u>	<u></u>		"	Machining						,						
			Plate	5,000	Press											_	
				1	Machining						1				-1		
					Plating												
					Assembly						<u> </u>				-		
						 									1		
	<u> </u>					l —								-			
		 											<u> </u>				
							1										-
				 		<u> </u>	<u> </u>										
	 	 -	1	<u> </u>		 							 				
			<u> </u>	 		<u> </u>										·	
									-				-				
		+		<u> </u>													
			 			<u> </u>			· ·	<u> </u>							
·- <u></u>		<u> </u>				 	ļ	 					-		ļ		
<u></u>																	
			[_			

Manufacuturing Process:

Daily Production Schedule

Vorking Date			Scheduled by				Sched	uled on:					Week-e	nding:				
a , ,, ,		_ , .		Used			Working Time											
Order Number	Customer	Preduct	Parts	Machine		Oty	7	8	9	10	11	12	13	14	15	16	17	18
101	٨	Anti-loose	Body		Planned	5,0	000											
101	А	Fastner	Pody	Lathe	Actual													
					Planned	5,	000 -		_				- -					
				Milling	Actual		1											
			Pin		Planned	10,	000							 				
			FILL	Lathe	Actual	1								•				
					Planned													
					Actual													
*00	В	Plate	Plate		Planned													
102	В	Back Hook	riate	Milling	Actual	3,4	100											
				Ĭ	Planned													
					Actual													
				Planned							<u> </u>							
					Actual			_										
					Planned	 	_			1		1		1	1			1
					Actual			_			1		 					
	·····		<u> </u>		Planned		<u>-</u>				T		<u> </u>					T
					Act⊔al	1						· · · · · · · · · · · · · · · · · · ·						_
		-	 		Planned	1					† · · · · · · ·	1						\vdash
-				i	Actual				<u> </u>		 	† · · ·	-	 				-
		····			Actual Planned					-	-		 	 			 	+-
]					Actual	1												
					Planned													1
					Actual													
					Planned							1						_
					Actual	· · · · · · · · · · · · · · · · · · ·					1							$\overline{}$
			+		Planned								 	<u> </u>				1
Í					Actual									1			<u> </u>	+-
 					Planned	1			 				 					<u> </u>
			•		Actual	1		-	· · · · · · · · · · · · · · · · · · ·					†			 -	
					Planned			 	 	·			 	-				
1				!	Actual									 				╁
			 		Planned			-	 					 			-	
			•		Actual	· · · · · · · · · · · · · · · · · · ·			+					 	-			├
			 		Planned		+	- 										-
					Actual	+	+		 				 	 	-			
					Actual Planned	+	+	+-	1				 -	-				-
					Actual				1									<u> </u>
			+		Planned	1		 				· · · · · · · · · · · · · · · · · · ·						—
					Actual	 						-		 				-
		 	- 		Planned	 	-	+										†
		1			Actual	-								 				

Case No.	1st category	Divisio	n / Process
MW-40	Production management	Production	n management
2nd category		Industry	Sector / Product
	Quality control	Metalworking	Machining, Press, Welding

MW-40 Production management	Producti	on management	
2nd category	Industry	Sector / Produc	t
Quality control	Metalworking	Machining, Press, W	elding
	Subject		
	Subject		
velopment of the quality managemen	t system		
	c oystem		
Diagnosis:			
Throughout the production process,	work pieces are sampled for	dimensional check. Also	. proc
dimensions are measured upon the d			
data are not used for quality manage			
			•
Guidance:			
Response of the enterprise (as conf	irmed during the follow-up	activity):	
Response of the enterprise (as conf	irmed during the follow-up	activity):	
Response of the enterprise (as conf	îrmed during the follow-up	activity):	
Response of the enterprise (as conf	irmed during the follow-up	activity):	
Response of the enterprise (as conf	îrmed during the follow-up	activity):	
Response of the enterprise (as conf			

guidance on a continuous basis by proposing specific actions and providing follow-up advice. Then, in the long run, it is imperative to establish a mechanism to train and promote employees to management staff in a systematic manner.

Description of Problems

The quality control system is not established.

Diagnosis and Recommendation

- The operation cards should be modified to count defect numbers.
- QC tools should be used to monitor and control quality (Refer Attachment A).

Recommendations for the future

- To improve quality and productivity, the defect rate chart is a useful tool. Start using it from important processes (3-5 items), and then expand the usage to other processes.
- To keep the critical processes in a stable condition, the control chart is a useful tool.
 Use x mean R range chart to keep the critical dimension in control.
- The quality charts and daily schedule should be put on a board in the shop. To
 visualize the production activities to everybody is very important not only for the
 management of the shop floor but also to have the transparency among employees.

QC Tools for Quality Control and Quality Management System

1. Control Chart --- Dimensional control by inspection data

To utilize the inspection data for the production management, make the control charts on the critical dimensions, and watch the tendency. If the value goes out of the control limit, you must take some action. The chart is made for each production process, and it is located besides the machine of the process. I recommend you to use "X bar-R Chart" for control of machined dimensions. (Refer Attachment A-1)

2. Defect Rate Chart --- Follow-up of the in-house quality defects

To improve the quality continuously, follow up the in-house defect rate, and take action to improve it when the defect rate is more than the target rate value. You can see the result of the work by using the defect rate chart. The chart is made for each machine, and it is located besides the machine. Defect rate is calculated by defect number/ production quantity. Defect number is summation of scraps, reworks, and additional works. Additional works mean off-standard works like bur cutting. (Refer Attachment A-2)

Customer Rejection and Action Report --- Follow-up of the customer rejections

To improve the customer satisfaction, quick response to the customer rejections is important. Make the reports of the customer complain and follow up your actions. Your actions and results are recorded. So you can use this record to prevent the recurrence of customer complains. (Refer Attachment A-3)


4. Quality Control Flow Chart --- Adoption of quality into production process

When you are planning new machine process of a new component, use the QC flow chart to make up the quality into the production process.

Control Chart

Component:	Customer:	Machine:	
(Average of mean)=10	UCL=10.06	LOL=9.94	
(Average of range)=0.10	UCL=0.21		

Date	Lot No.	1	2	3	4	5 Mean	Range
	1					10.05	
	2					9.98	0.09
	3					10	0.15
	4					9.96	0.13
	5					10.04	0.1
	6					9.93	0.08
	7					10.03	0.09
	8					10	0.1



CL=Average value of mean of each lot UCL & LCL of mean=Calculated from a formula CLR=Average value of range of each lot UCL of range=Caluculated from a formula

Daily In-house Defect Rate Report

Machine:	Month:	Year;	Reported by
			1111

Customer	Component	Order No.	Operation No.	Date	Quantity (A)	Defect Number (B)	Defect Rate (B/A)	Coment
				1			1.20	. <u> </u>
				2			0.55	
				3			1.55	
				4			0.80	
-				5			2.10	
	·			6			1.00	
				7			0.60	
				8				
				9				
	I	I		4				
	2.50							
	0.50 Defect Rate %			-∧	UCL			
	1.50		٨	/ \	\			
	00.1 <u>ق</u>	•	/ \ <u>/</u>	/	1			
	ص _{0.50}	\vee	•		``•			
	0.00			1	.			
		1 2	3 4	5	6 7			
			DAY					
				19				
				20				
				21	,			
				22				
				23				
				24				
				25				
				26				
				27				
				28				
				29				
				30				
		<u> </u>		31				

Daily defect number of in-house production is summation of scraps, reworks, and additional works. Additional works are works which are requierd off-standard works like burr cuttings.

Customer Rejection and Action Report

Component:	Quantity:	Date:
Customer:	Operation No.:	Made by:
Details of Non-conformance		
What was wrong:	*	
By whom and how was it find:		
Request from Customer:		
·		•
Cause Analisys		
Could you recover Rejected Parts:		
Results of Inspection:		
	•	
Estimated Cause:		
<u> </u>		<u> </u>
Actions taken and Results		
Actions		Results
·		•
	·	
	i	

Case No.	1st category	Division / Process				
MW-41 ′	Production management	Stainless exhaust pipe manufacturing				
	2nd category	Industry	Sector / Product			
	Productivity	Automotive parts mfg. (after-market)	Exhaust pipe manufacturing			

-	337	
	0 2 [3	

mprovem	ent of	work	rabilitv	in tl	ne nine	cutting	process
.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		*****	· · · · · · · · · · · · · · · · · · ·	111 51	IC DIDC	CULLITY	20,00030

_	— ·			
-	Diac	. ~ -		• :
	1 21 711	JI 16	100	٠.

Pipes are measured by a scale attached to a guide before being clamped. As every pipe must be measured, it takes considerable time when a large number of pipes are cut.

■ Guidance:

It was advised to install a pipe stopper that serves a guide for cutting.

Response of the enterprise (as confirmed during the follow-up activity):

The recommendation has not been implemented as the company plans to relocate the factory and is busy with new jobs.

■ Other relevant points (issues to be solved and problems remained):

Although the management understands what they should do, but they do not seem to feel the need for safety improvement strongly because they do not have management staff and are busy with daily operation. It is important to visit them frequently and provide information and guidance repeatedly.

Description of Problems


Pipes are cut to length using a cutting grinder with an adjustable scale installed on a guide. This process is not only unproductive but also liable to inaccuracy.

Diagnosis and Recommendation

A sliding stopper should be installed on the guide. Using the stopper also stabilizes the pipe when cutting (See Photograph)

Photograph: The cutting work of pipes

The present state



- 1. Although a scale is installed on the guide, operator is required to adjust the length of pipe each time because there is no stopper for length adjustment.
- 2. The cutting grinder is dangerous due to the safety cover being too small.



Recommendation

- 1. A sliding stopper should be installed on the guide.
- 2. The safety cover should be expanded.