


- Legend:**
- Overburden and Completely Weathered Bedrock/alluvium
 - Highly to Moderately Weathered Bedrock
 - Slightly Weathered to Sound Bedrock
 - Limit of Weathering
 - Refractor Surface
 - Trace of Bedding
 - Fault
- Geologic Log**
- Fine Clastics: Siltstone, Mudstone, Shale
 - Coarse Clastics: Sandstone Greywacke, Fine Breccia and Conglomerate
 - Granule Conglomerate (as Marker Horizon)
 - F** Fracturation Spacing (in Centimeters)
 - RQD** Rock Quality Designation (in %)
 - LU** Permeability (in Lugeon Units)

NOTE : For Location of Section, See DWG, No. 1765-23-1-03-003 in MWSP 1984 Report



By Electrowatt et.al (1984)

Figure 3.9
Profile of Laiban Dam Axis






Figure 3.10
 Profile Sketch of Kaliwa Low Dam No.2 Site



Profile along Dam Axis



By Nippon-Koei (1981)

Figure 3.11
Profile of Agos Dam Axis





Figure 3.13
Profile of Kanana No.2 Dam Axis






Figure 3.14
 Geological Profile of Kaliwa-Abuyod Transfer Tunnel
 (Upstream Part of Kaliwa-Angono Waterway)





Figure 3.15
 Geological Profile of Laiban-Tanay Transfer Tunnel
 (Upstream Part of Laiban-Angono Waterway)



Scale 0 2.5km

Note This figure shows 1/50,000 scaled topographic map of NAMRIA (1952), on which coastline and river channel (blue-color lines explained in the "Legend" below) of photogrammetric map produced from aerial photos taken in 1995 are illustrated to assess these changes in Infanta Peninsula that took place between 1952 and 1995.

Legend
 — Coastline and river channel drawn based on a photogrammetric map produced from aerial photos taken in 1995

Figure 3.16
 Comparison of Coastlines and River Channels of Infanta Peninsula
 in 1952 and 1995




Existing Retaining Wall



Bank Erosion



Bank Erosion in General Nakar Municipality



The bridge in Barangay Pinaglapatan, Infanta, Quezon Province

Figure 3.17 River Conditions of the Lower Agos