

Inspection Memo 3 Inspection of Hopin Small Hydropower Station in Hopin, Kachin

26.11.2002

3.1 Township Information

- Hopin, Kachin State

3.2 General Information of Hopin Power Station

- Access



River crossing toward Hopin Station



11 kV Distribution Line crossing the river



- General layout



- Intake



Looking intake weir from downstream



Water flowing into headtank

- Headrace



Steps on Siphon Pipes



Siphone



Outlet of Siphon



Side-overflow of headrace channel



Headrace channel



Trace of small slide upside the channel



Downside slope much eroded by water

- Headtank with regulating pond and desander



Excess water spillway



Inlet gate



A distant view of approach road and river

- Penstock



Hopin Power Station & penstock



A distant view of penstock

- Powerhouse



- Generating equipment



- Tailrace



- Distribution lines



3.3 Particular Information of Hopin Power Station

- Unit 1 in automatic operation at guidevane opening of 63%
- Unit 2 in manual operation
- 55 Hz, 0.125 MW

Salient Features:

Name	: Hopin Ga Lang Chaung Hydropower Station
Location	: 8 miles northeast of Hopin Township, Kachin State
River Name	: Ga Lang Chaung
Catchment area	: 9.0 sq.mile (23.3 km ²)
Head	: Net head of 625 ft (190.5 m)
Discharge	: 15 cusec x 2 units = 30 cusec (0.425 x 2 = 0.85 m ³ /s)
Output	: 630 kW x 2 units = 1,260 kW
Weir	: 30 ft (L) x H 7 ft (9.1 m L x 2.1 m H)
Siphon	: 550 ft (L) x ϕ 2 ft (167.6 m L x ϕ 0.61 m)
Power Canal	: 2,300 ft (L) x 3 ft (B) x 2.5 ft (D) (701 m L x 0.91 m B x 0.76 m D)
Head Tank	: 2,425 ft (L) x 50 ft (B) x 6.5 ft (D) (739 m L x 15.24 m B x 1.98 m D)

	108,000 cu ft (3,058 m ³)
Penstock	: 1,900 ft (L) x ϕ 2 ft (579 m L x ϕ 0.61 m)
Turbine	: Pelton with 1 nozzle, made in Kunmin China
Annual Energy	: 2.3 GWh
Distribution line	: 11kV line, 14km between Station and Hopin + 32km in Hopin, Nammar, and Moe Nyin = 46km in total
Construction	: Feb 1990 – Sep 1991
Commissioning	: 07-Sep-1991
Project cost	: Public contribution 20.4 x 10 ⁶ Kyat MEPE LC 6.8 x 10 ⁶ Kyat FC 0.19 x 10 ⁶ US\$ (1.2 x 10 ⁶ Kyat) 28.4 x 10 ⁶ Kyat in total
Supply Area	: Hopin, Monyin, and Namma
Peak Load	: 1,300 kW. Load shedding is made at the peak time from 6 p.m. to 10 p.m.
Consumer	: 3,147 in total (1,246 in Hopin, 1,223 in Monyin, and 678 in Namma)
Operation	: 300 kW (1 unit) from March to May : 1,100 kW (2 units) from Jun to Jan : 900 kW (2 units) in Feb

3.4 Issues

(1) Civil Structures

- It appears that the head tank has not been utilized for peak power generation. A water level gauge in the head tank needs to be installed for peak operation.
- 168 m long siphon consists of the waterway to cross the deep waterfall of Ga Lang Chaung. However, it appears that the debris and/or driftwoods have not been so significant to fill the inside of siphon or attack during floods, seeing from the sedimentation around the weir site.
- 100% of the river flow was taken at the Intake Weir, and led to the Head Tank on 26-Nov-2002. Some of the flow spilled out from the spillway of the Head Tank. The power output was 300 kW (unit-1) and 100 kW (unit-2) at that time.
Turbine discharge $400 / 1,260 \times 0.85 \text{ m}^3/\text{s} = 0.27 \text{ m}^3/\text{s}$ approx.
River discharge might be $0.4 \sim 0.5 \text{ m}^3/\text{s}$
- The state of flow from the siphon to the canal is of super-critical flow, and changes to sub-critical state.

Assuming slope=1/500, n=0.014 and b=0.90 m, uniform flow depths are as follows:

For $Q = 0.50 \text{ m}^3/\text{s}$ $h = 0.49 \text{ m}$

For $Q = 0.85 \text{ m}^3/\text{s}$ (max. design discharge) $h = 0.74 \text{ m}$ (canal height 0.76 m)

- It was observed at the open canal that slope sliding above the waterway entered the canal once and dammed off the flow, of which overflow induced the slope failure below the canal.
- It appears that the Head Tank was designed to supply the maximum design discharge for just 1.0 hour only ($0.85 \text{ m}^3/\text{s} \times 3,600 = 3,060 \text{ m}^3$)
- The water leakage was observed at 2 locations of expansion joints of Penstock.

3.5 Plates of Equipment

Automatic Speed Governor

Type : XT-300 Standard No. GB 9652
 No. 91-01 Governor Capacity : 3,000 J
 Rated Oil Pressure : 2.5 Mpa
 Date : 1991
 Kunming Electrical Machinery Works Co., Ltd

Oil Pressure Unit

Type : Hyz-01 Standard No. : GB9652
 No.91-02
 Rated Oil Pressure : 2.5 Mpa
 P. Tank Volume : 0.1 m^3

Electromagnetic Generator

Type : TFY05-10 No.512-018
 Output : 0.5 kW

	Main	Sub
Voltage :	380, 220, 110V	190, 110 V
Current :	0.608, 1.09, 2.1 A	0.304, 0.525 A
Connection :	, , 2	,
Rotation :	600/1200 rpm	Frequency : 50 Hz
Raway Speed :	1050 rpm	
Conn : Y	cos : 0.3	Phase : 3

Kunming Electrical Machinery Works

Transformer to I.E.C 76

Type : SFW630-11/1180 No.691-06
 Capacity: 750 kVA Rated Frequency : 50 Hz
 Type of Cooling : Onan
 Rated Volt (No Load) : HV 11,000, LV 400 V
 Rated Current Load : HV 39.36, LV, 1982 A
 Insulation Level : HV 75 kV_p LV 25 kV
 Insulation liquid rise : 50
 Winding Resistance Rise : 60
 Year of Manufacture : 1981
 Connection Symbol : Dynll
 Untaking mass : 1190 kg, Total mass : 2,484 kg
 Transportation mass : 2136 kg
 Mass of oil : 520 kg Oil : 609 L
 Maker's serial No. : 65299/10
 Hawker Siddeley Brush Transformer Ltd., England

Turbine

Type : J22-W-92/1x11
Head : 190 m Flow : 0.424 m³/s
Output : 663 kW Speed : 600 rpm
Weight : 6500 kg No. S91-007
Kunming Electrical Machinery Works Co., Ltd

Special Valve Cabinet

Oper V : 110V Cont P : 2.5 MPa
No. 91-01 Date: 1991
Kunming Electrical Machinery Works Co., Ltd

Generator

Type : SFW630-11/1180 No.691-06
Output : 630 kW
Sta Volt : 400 V Sta Curr 1137 A
Rotation : 1500/1800 rpm Frequency : 50 Hz
Raway Speed : 1050 rpm
Conn : Y cos : 0.3 Phase : 3
Stator 6, Rotor F
Rotation: Nil
Date : 1991 03
Kunming Electrical Machinery Works Co., Ltd

Inspection Memo 4 Inspection of Zi Chaung Power Station during De-Watering

23 to 29 May 2003

4.1 Topographic Mapping of Intake Area



4.2 Lecture on Topographic Survey



Lecture on leveling to MEPE staff



Mapping by Total Station



4.3 Discharge Measurement Along Headrace Channel



4.4 Inspection of Headrace Channel

On 26 May 2003, the power station was shut down for inspection of turbine runner etc. On this occasion, the headrace channel was also dewatered and inspected from the intake down to the regulating pond.

The principal findings are:

- Sediment deposits had significant depth and volume on the channel floor with maximum thickness of about 35 cm.
- Most of the sediments entered the channel through the intake while the trashracks were left washed out while minor volume were from side slopes beside the channel.
- Sediment deposits are significant immediate downstream of the side spillway where water flow is violent and does not allow sediments to settle.
- Further downstream, much sediments are observed on the straight sections while less or almost nil on the curved sections.
- Joints between the floor slab and side walls received significant erosion probably by flowing sands and gravels.



Intake weir site being surveyed



Gravel deposits upstream of the intake



Gravel deposits in front of intake



Piers in front of intake trashracks



Intake trashrack and wreck of deck for operator to remove leaves etc.



Intake gates looked from upstream



Sand flushing gate



Sand flushing gate fully opened



Side overflow spillway section, bow being Blocked with concrete to avoid leakage



Intake gates fully closed for inspection
Water leakage is marginal.



Side spillway section after intake gates fully closed.



Sediments deposits in the same section.



Water remains undrained in the spillway section (left) due to the thick sediments in the downstream section (right) from where water has been mostly drained.



Sediments and test pit on the channel floor

Hole depth so far dug is 32 cm.



Side wall height at 1.70 m.

Water pond seen in the curved section is created by dam up effect of the sediments downstream, looking downstream



Water depth at this curved section was at 35 cm. Sediments observed mostly in straight sections



Sediments are limited in curved section (left) or nil in some section (right)



Erosion of channel floor



Erosion of side wall foot



Channel floor in the leakage section right



Outside foundation of leakage section (it seemed the foundation has been eroded by leakage water.)



Channel bridge over a tributary



Rock from side slopes



Rock fallen in the channel.



Debris once entered into and removed outside beside the channel. These channel sections should be placed with concrete cover.



Debris on the channel cover, proving effectiveness of the cover.



Channel floor at one of the leakage points



Joint between floor slab and side wall



De-sanding basin



Eel found from the waterway for



A hole is made on side wall to divert water flushing works in the Regulating Pond



Sediments in the upper part of Regulating Pond, mainly consisting of silt



Sloped pond floor towards penstock inlet looking upstream



Looking penstock inlet. Sediments were flushed in mid-May 2003



Sediment top covered with algae



Sediment surface in the Regulating Pond



4.5 Sand Flushing Tests

4.5.1 Testing of Flute Type Flushing Head (stationary, to be fixed to floor)



Flute made for testing purpose



Flute buried in the pond with sand



Water filled to the Pond



Flute under the water after sand flushing, part of horizontal pipe seen in the bottom of depression that was created by flushing sands around



PVC pipe connected to gain a higher head



Flushing by siphon action at a head of 0.8 m



Flushing at a head of 4 m



ditto



Flushing at a head of 5.5 m



Witnesses



Visitors from villages nearby

4.5.2 Testing of Saxophone Type Flushing Head (movable, to be operated from on raft)



Three suction head made for testing



Saxophone Type 1 (with smaller slits)



Saxophone Type 2 (with larger slits)



Saxophone Type 3 (with horizontal slits)

Saxophone Type 3 (with horizontal slits)



Test operation of Saxophone Type 3
(with horizontal slits)



Flushing at a head of 4 m



Flushing at a head of 4 m
Saxophone Type 1 (with smaller slits)



Test operation of Saxophone Type 1 (with smaller slits) from on a raft



Pipe connection to Flushing head and removing air from pipe



under flushing operation with Flushing head being moved



White color of the pipe shows less sacking of sand (left) while black full sacking (right)



Flushing at a head of 4 m



Flushing at a head of 1.8 m



Flushing at a head of 0.8 m