

13.3 BRIDGE CONDITION SURVEY AND IDENTIFICATION OF DAMAGES

13.3.1 Measurement of Shapes and Dimensions

(1) Objective

The purpose of this survey is to provide information on the overall dimensions of the bridge and section properties of members or elements consisting of the structures.

While a few available as-built drawings and repair or rehabilitation drawings were taken as reference for this activity, other important dimensions were measured in addition to the shapes and dimensions of elements or members. The data were collected, processed, and summarized, for the use in other activities, including modeling of structure and Load Rating.

(2) Inspection Teams

Several teams of inspectors were deployed on site to cover the whole Ayala Bridge structure within an eleven-day survey, to conduct hands-on verification of representative shapes and dimensions of elements or members of the Ayala Bridge. Two inspectors formed one team, which covered a specific area of the Ayala Bridge on a given schedule. Engineers coordinated the activities of all the inspection teams.

The inspectors were tasked to simultaneously perform another activity, Close-Up Visual Inspection of Damage.

(3) Coverage Areas

The bridge was divided into four general inspection areas: (a) Road/Deck level (RD), (b) Above Deck level (AD), (c) Below Deck level (BD), and (d) Substructure including Bearings (SB).

Items for verification on the road/deck level included deck road dimensions near midspan of both the South and North Spans, and approach road dimensions, taken approximately 1.0m from the face of the abutments. (See **Photo 13.3.1-1**)

Items for verification on the above deck level included shapes and dimensions of main truss members (excluding the bottom chord), sway brace members, and gusset plates. Spacing of main truss panels were also measured. (See **Photo 13.3.1-2**)




Photo 13.3.1-1 Road Deck Level - South Approach Road (Looking North East)



Photo 13.3.1-2 Above Deck Level - Main/Truss Members, Gusset Plates, and Sway Braces

Access to the connection of cross beams to bottom chords was very limited and no hands-on verifications could be made (See **Photo 13.3.1-3**). Items for verification on Substructures including Bearings included shapes and dimensions of bearings, including bearing shoe, at the substructures. The presence of the Pier concrete structure below water was verified with limited subsurface measurements around the Pier. Distances between bearings were also measured. (See **Photo 13.3.1-4**)



Photo 13.3.1-3 Below Deck Level - Bottom Chords, Cross Beams, Stringers, Deck Bracing and Gusset Plates. North Span shown (Looking South)



Photo 13.3.1-4 Substructures and Bearings - Pier Shown (Looking East)

(4) Reference Information

The Study Team was furnished with copies of a few as-built drawings, and repair and rehabilitation drawings of Ayala Bridge, and used them as references in planning this activity, and in designing the preliminary verification forms.

(5) Equipment and Procedure

Each team was equipped with safety gear (including hard hats, safety belts, safety goggles, safety shoes, and rain coat), measurement tools (8.0m tape measure, caliper) for verification, hammer for damage inspection, and digital video or still cameras, and verification forms and pencils for documentation.

Inspection on the road/deck level measured bridge section dimensions perpendicular to the bridge centerline. The dimension of approach road was measured at approximately 1 meter from the abutment.

Inspectors on the above deck level climbed up mobile scaffolds installed sidewalks to access the East and West Trusses, and mobile scaffolds installed on the median to access the Middle Trusses (See **Photo 13.3.1-5**). With the mobile scaffolds, verification of top chord members, gusset plates at the top chord, and sway braces were carried-out, (See **Photo 13.3.1-6**). Other members and gusset plates were accessed from the road/deck level, or were climbed up (see **Photo 13.3.1-7**). Verification on the below deck level was made possible by the use of a tugboat, with scaffolds installed on top, mainly at the South Span (see **Photo 13.3.1-8**), and by the use of a pontoon, mainly at the North Span (see **Photo 13.3.1-9**).



Photo 13.3.1-5 Use of Scaffolding at Main Truss



Photo 13.3.1-6 Measurement of Top Chord Member



Photo 13.3.1-7 Measurement of Mid Height Gusset Plates and Truss Members

Inspectors on the substructure including bearings climbed up telescoping ladders to perform verification on the bearings. The pier was accessed also via the use of the tugboat.

Verification on the below deck level was made possible by the use of a tugboat, with scaffolds installed on top, mainly at the South Span (See **Photo 13.3.1-8**), and by the use of a pontoon, mainly at the North Span. (See **Photo 13.3.1-9**).



Photo 13.3.1-8 Measurement of Below Deck Level Using Tugboat



Photo 13.3.1-9 Measurement of Below Deck Level Using Pontoon



Photo 13.3.1-10 Miscellaneous structures (Pipes)

Verification forms were based on reference documents. The inspector took note of the shapes of elements or members, and used a caliper to measure thickness, and a tape measure for other dimensions. Dimensions were measured at least two locations on the members, and averaged. The inspectors then filled up the inspection forms with this average value.

(6) Results

Table 13.3.1-1 lists drawings made based on the data presented in the inspection forms. Where dimensions that may be necessary for structure modeling and analysis could not be measured, information from the reference documents were reflected and marked with an asterisk (*) in drawings of Appendices shown in Table 13.3.1-1.

Table 13.3.1-1 List of Drawings

| No. | Sheet No. | Title | Appendix |
|-----|-----------|--|-----------|
| 1 | 1 | General Elevation, Plan Reflected Plan and Section | 13.3.1-1 |
| 2 | 2 | South Span Truss | 13.3.1-2 |
| 3 | 3 | North Span Truss | 13.3.1-3 |
| 4 | 1 | Cross Beam, Stringer, and Deck Bracing | 13.3.1-4 |
| 5 | 2 | Sway Brace | 13.3.1-5 |
| 6 | 1 | South Span Truss Gusset Plates at Top Chord | 13.3.1-6 |
| 7 | 2 | South Span Truss Gusset Plates at Mid-Height | 13.3.1-7 |
| 8 | 3 | South Span Truss Gusset Plates at Bottom Chord | 13.3.1-8 |
| 9 | 4 | North Span Truss Gusset Plates at Top Chord | 13.3.1-9 |
| 10 | 5 | North Span Truss Gusset Plates at Mid-Height | 13.3.1-10 |
| 11 | 6 | North Span Truss Gusset Plates and Splice Plate at Bottom Chord | 13.3.1-11 |
| 12 | 7 | Connection of Cross Beam to Bottom Chord | 13.3.1-12 |
| 13 | 8 | Deck Bracing Gusset Plates, and Connection of Stringer to Cross Beam | 13.3.1-13 |
| 14 | 1 | Pier | 13.3.1-14 |
| 15 | 2 | South Abutment | 13.3.1-15 |
| 16 | 3 | North Abutment | 13.3.1-16 |

(7) Miscellaneous Structures

Miscellaneous structures, including non-structural elements, were noted, and those photographs were taken. These include pipes, lighting, and other architectural accessories. Photo 13.3.1-10 shows an example of these miscellaneous structures.

13.3.2 Close-up Visual Inspection

(1) Objective

The purposes of this inspection are:

- (a) To check the element/member condition and find the following structural damages and defects,
 - Structural damages and defects such as deformation, missing members, deflection, etc.
 - Material deficiencies and damages such as corrosion of steel members, loss or reduction of sections, cracks (width, length, depth), etc.
- (b) To make judgment of damage degrees with damage rating, and
- (c) To make detailed documentation including digital photos and videos.

The X-Y-Z method as described in the Manual, was used for the damage ratings. The data were collected, processed, and summarized, for the use of other activities, including: Non-Destructive Test of Material; Static Load Test and Microtremor Measurement Survey of Superstructure; Impact Vibration Test of Substructure; and Modelling of Structure and Load Rating.

(2) Inspection Teams

Several teams of inspectors were deployed on site to cover the whole Ayala Bridge structure within an eleven-day period to conduct close-up visual inspection of damages on the Ayala Bridge. Two inspectors formed one team, which covered a specific area of the Ayala Bridge on a given schedule. Engineers coordinated the activities of all the inspection teams.

The inspectors were tasked to simultaneously perform another activity, Verification of Shape and Dimension

(3) Coverage Areas

For inspection purposes, the bridge was divided into four general inspection areas or levels:

- (a) Road/Deck Level (RD) / (b) Above Deck Level (AD) / (c) Below Deck Level (BD) / (d) Substructure including Bearings (SB).

(4) Reference Information

The Study Team was furnished with copies of a few as-built drawings, and repair and rehabilitation drawings of Ayala Bridge, and used them as references in planning this activity, and in designing the preliminary inspection forms.

(5) Equipment and Procedure

Equipment and access methods to the target areas were described in **Section 13.3.1** because the same team as the team for the shape and dimension survey conducted the close-up inspection.

The inspectors noted the damages found at each specific location, and the filenames of photographs or videos taken at that location. A damaged sheet containing one or two photographs, and type of damages inspected, assessed X, Y, Z levels, and damage rating, was prepared for each location where damage was found. Damage sheets were grouped according to inspection levels. A total of 9, 16, 160, and 16 damage sheets were each prepared for road/deck elements, above deck truss elements, below deck truss elements, and substructures and bearings, respectively.

The inspectors performed hammer test at each inspected member, to detect delamination of concrete or steel members, if any. A hammer was tapped along an area approximately 1.0 m².

(6) Criteria for Damage Rating

The X-Y-Z method for damage rating was used. In rating the damage for a specific member (steel, concrete, or miscellaneous structure), the type of damage was determined first. However, some members had two or more types of damages.

X was evaluated depending on the location or pattern of the damage; Y was evaluated depending on the depth or severity of the damage; and Z was evaluated depending on the scale or expanse of the damage. It was also determined if the member was a secondary or a main member.

(7) Results

Table 13.3.2-1 presents the results of the damage rating obtained from the Close-Up Visual Inspection; **Photo 13.3.2-1** shows typical damages by the structural component.

The inspection results are summarized as follows.

- Abnormal deflection is observed during vehicles passing at the north span was observed.
- A sway bracing at the south span and a stringer at the north span are missing.
- Stringers of the east side of north span are completely broken near the abutment. These stringers are presently supported by a temporary support structure.
- Serious section loss of a bottom chord is found at the joint.
- Cross beams are heavily corroded.
- Most of joint areas are heavily corroded.
- Steel bearings are not functioning properly because of cracks and heavy corrosion.
- Substructures are mostly sound, while having small cracks.
- The upper chords are mostly sound, while corrosion at joints are found.

From the serious damage conditions of members below the floor deck, a quantitative evaluation of the carrying capacity of superstructure is required since local failures are primary concerns.

Table 13.3.2-1 Damage Rating of Main Members by Close-Up Visual Inspection

| Component | Item | Member/Location | Damage Rating | Description |
|----------------|-------------------|--------------------------------------|---------------|-------------------------------|
| Superstructure | Shape / Dimension | Bot. Chord/South Span, East | III | Deformed |
| | | Stringer/ North Span | I | Missing |
| | | Deck Slab/North Span | I | Abnormal Deflection |
| | | Sway Bracing / South Span | I | Missing |
| | Material Damage | Deck Slab / North Span | III | Crack |
| | | Bot. Chord / South Span, East Truss | I | Heavily Corroded |
| | | Gusset Plate / North Span, Mid Truss | I | Heavily Corroded |
| | | Stringer / North Span | I | Crack / Broken |
| | | Stringer / South Span | I | Reduced Section |
| | | Bearing/All Location | I | Heavily Corroded/ Malfunction |
| Substructure | Material Damage | South Abutment / Main wall | III | Crack |
| | | Bearings | I | Crack / Heavily Corroded |
| | | North Abutment / Main wall | III | Crack |

13.3.3 Non-Destructive Test of Material

(1) Objective

The purposes of this activity are to provide information on material properties and any damage that may not be visually observed based on the following tests conducted on steel and concrete members.



(a) Fractured Stringer and Heavily Corroded Cross Beams



(b) Reduced cross section of Bottom Chord due to corrosion



(c) Fractured Stringer at North East Portion



(d) Heavily Corroded Stringer at South East



(e) Damaged at Substructures and Bearings, Corrosion and (Abnormal) movement of Bearing at North Abutment. Roller most likely stuck-up



(f) Cracks and Concrete Spalling at Abutment (View South)

Photo 13.3.2-1 Typical Damages

(a) Steel Members

- Ultrasonic Thickness Gauging / Brinell Hardness Test / Ultrasonic Flaw Detection / Dye Penetrant Test

(b) Concrete Members

- Schmidt Rebound Hammer / Coring / Compression Test / Crack Width Comparator / Ultrasonic Pulse Velocity Test / Phenolphthalein Test / Chloride Test / Petrographic Analysis

To conduct this activity, the results of close-up visual inspection and the importance of the member/joint were considered to decide the locations of the non-destructive tests.

(2) Results

Table 13.3.3-1 shows the test results.

Table 13.3.3-1 Results of Non-Destructive Test

| Test | Description and Results | Reference Appendices |
|--|---|---------------------------|
| Ultrasonic Thickness Gauging (UTG) (To measure the present thickness of the steel sections) | For the outer trusses, the measured side plate thickness ranged from 7 mm to 10 mm, and from 13 mm to 17 mm. For the middle trusses, the measured side plate thickness ranged from 8 mm to 9 mm, 15 mm to 18 mm, and 20 mm to 25 mm. Measured bottom plate thickness ranged from 7 mm to 10 mm. | Appendix 13.3.3-1 |
| Brinell Hardness Test (To measure the hardness of the steel members) | Brinell Hardness Numbers ranged from 96 to 158, corresponding to equivalent tensile strengths of 328 MPa and 540 MPa respectively. In comparison, the standard tensile strength of A36 steel is in the range of 400 MPa to 550 MPa. | Appendix 13.3.3-2(1), (2) |
| Ultrasonic Flaw Detection Test (UFD) (To determine the presence of any internal defects or discontinuities in the steel sections) | The results showed no relevant indication of defects in any of the locations tested. | Appendix 13.3.3-3 |
| Dye Penetrant Test (UFD) (To detect any surface - breaking defects) | Portions tested for DPT were as follows: 1) gusset plate; and 2) bottom flange of cross beam. The results of the DPT showed no relevant indication of defects in any of the locations tested. | Appendix 13.3.3-4(1), (2) |
| Schmidt Rebound Hammer Test (To determine the in-situ uniformity, surface hardness, and approximate compressive strength of concrete) | Measured rebound numbers ranged from 44 to 49 corresponding to calibrated compressive strengths ranging from 41 Mpa to 49 Mpa. | Appendix 13.3.3-5 |
| Compression Test (To obtain the compressive strength of concrete) | Results of the two compression tests are 19MPa and 25MPa. | Appendix 13.3.3-5 |
| Width Comparator (To eliminate surface crack widths) | Measured surface crack widths ranged from 0.8 mm to more than 1.5 mm. | Appendix 13.3.3-5 |
| Ultrasonic Pulse Velocity (UPV) (To measure surface crack depths) | Estimated surface crack depth were: 107 mm (corresponding to crack width of > 1.5 mm); 126 mm (corresponding to crack width of > 1.5 mm); and 139 mm (corresponding to crack width of 0.8 mm). | Appendix 13.3.3-5 |
| Phenolphthalein Test (To determine the depth of carbonation) | Measured depth of carbonation ranged from nil (0 mm) to 45 mm. | Appendix 13.3.3-5 |
| Chloride Test (To assess the distribution of chlorides) | Results of the chloride test revealed low chloride levels ranging from 0.02% to 0.09%. | Appendix 13.3.3-5 |
| Petrographic Analysis (To test for alkali-silica reaction) | Findings of the petrographic analysis showed no evidence of alkali-silica reaction. | Appendix 13.3.3-5 |

13.3.4 Static Load Test of Superstructure**(1) Objective**

This activity aims to obtain the data for use in modeling of structures and Load Rating. During the static truck loading of the south span, the following in-situ measurements were taken: a) vertical deflections of selected points on the bridge deck; and b) corresponding

strains in selected steel truss members. The static truck loading was conducted on the downstream side of the south span.

(2) Location of Deflection Survey Points and Strain Gauges

Figure 13.3.4-1 shows the locations of the deflection survey points and strain gauges. A total of nine (9) points were surveyed for deflections, while a total of twelve (12) truss members were measured for strains. Deflection survey points were distributed along the bridge deck, including three (3) near the west truss and three (3) near the middle truss. Strain gauges were attached on members located near the midspan.




Figure 13.3.4-1 Location of Deflection Survey Points and Strain Gauges

(3) Step Load Pattern of Trucks

Photo 13.3.4-1 and Figure 13.3.4-2 show the step load pattern of the trucks. Traffic was closed from midnight to 4:00AM on the day of testing. The structure was control-loaded using three (3) dump trucks. Truck Nos. 1 and 2 weighted 12.5 tons. Step Load No. 1 had Truck No. 1, Step Load No.2 had Truck Nos.1 and 2, and Step Load No.3 had Truck Nos. 1 to 3. The maximum truck load was 40.7 tons. After each step load, deflection and strain measurements were taken. The trends in measured deflection or strain were observed and instructions were then obtained from the Study Team whether to proceed to the next load case.




Figure 13.3.4-2 Step Load Pattern of Trucks




Photo 13.3.4-1 Step Load Pattern of Trucks

(4) Deflection Survey

Deflections were measured using Precise Level Wild NK – 2 complete with leveling rods and leveling bubbles, accuracy of the instrument was ± 1 mm. Each deflection measurement was made thrice or twice and the average was recorded.

Measured deflections generally tended to increase with the addition of each truck load. Maximum deflection at the west truss) during step load 3, while maximum deflection was 7mm at deflection survey points D1 and D2 (near the middle of the roadway) also during step load 3.

Figure 13.3.4-3 summarizes the results of the deflection survey.




Figure 13.3.4-3 Results of Deflection Survey

(5) Strain Measurement

Strain were measured using TML FLA-30-11 strain gauges. Strain data were collection thru a data acquisition system connected to a computer.

Figure 13.3.4-4 summarizes the results of the strain measurement. Measured strains were extremely small and ranged from 0.6 $\mu\epsilon$ to 6.2 $\mu\epsilon$.

13.3.5 Microtremor Measurement Survey

(1) Objective

This activity has two (2) specific objectives as follows:

- (a) To identify and confirm the modes relevant to the deformations due to the dead load and governing live load cases (MS 18 lane loadings) considered in Modeling of Structure.




Figure 13.3.4-4 Results of Strain Measurement

(b) To confirm that the Impact Vibration Test of Substructure are associated with the vertical modes of the superstructure, not with the natural frequency of the bridge pier.

The microtremor measurements were conducted on both the South Span and the North Span with closing to traffic during the survey.

(2) Acceleration Sensors

Figure 13.3.5-1 shows the locations of the sensors on both spans during the survey.

Five (5) force balance accelerometers (Kinometrics ES-U) were used in the survey in each measurement event: four (4) were set to measure vertical accelerations and one (1) was set to measure horizontal acceleration. All the accelerometers were set to a full-scale range $\pm 0.25g$.

The sensors were mounted on designated locations using beeswax, and were connected to a data acquisition system with 16-bit analog-to-digital converter using control cables.

For each span, twelve (12) measurement events were recorded. At each measurement event, accelerations were measured simultaneously at 1000 samples per second. Each event lasted around 8 minutes.

(3) Most Probable Natural Frequencies

The most probable natural frequencies are shown in Table 13.3.5-1.

- For the South Span, the most probable natural frequency of the 1st vertical mode is 3.2Hz, and that of the 1st torsional mode is 3.9Hz.
- For the North Span, the most probable natural frequency of the 1st vertical mode is 2.7Hz, and that of the 1st torsional mode is 3.4Hz




Figure 13.3.5-1 Location of Acceleration Sensors

Table 13.3.5-1 Most Probable Natural Frequencies

| Span | 1 st Vertical Mode | 1 st Torsional Mode |
|------------|-------------------------------|--------------------------------|
| South Span | 3.2 Hz (3.3) | 3.9 Hz (4.0) |
| North Span | 2.7 Hz (2.8) | 3.4 Hz (3.4) |

() : Frequencies obtained from structural analysis model

The 1st vertical and 1st torsional modes of the south were shown usually for reference in **Figure 13.3.5-2**.




Figure 13.3.5-2 First Vertical and Torsional Modes

The results of the survey also confirm that the peaks around 2Hz and 5Hz in the spectra obtained for pier vibration¹ are associated to vertical modes of the superstructure, as would be evident in the succeeding discussion.

The above natural frequencies of the South Span and North Span have been identified as follows:

- Using the FFT algorithm, the amplitude spectra of the acceleration records of all the measurement events are plotted. The amplitude spectra of these records are shown in **Figures 13.3.5-3 and 13.3.5-4**.
- From the spectra of each measurement event, the resonant peaks are identified and their locations are noted. Where such peaks occurred clearly in two or more channels, a natural frequency is deemed indicated. Following this procedure, it can be inferred from **Figure 13.3.5-3** that the South Span has probable vertical vibration modes around 3.2 Hz, 3.8Hz, and 5.1 Hz. The North Span, on the other hand, has probable vertical vibration modes around 2.7Hz, 3.4Hz, and 4.7Hz, as can be observed from **Figures 13.3.5-4**.
- The amplitudes among the peaks shown in the spectra are compared to associate these peaks with the shapes of the vibration modes of interest.

- From **Figure 13.3.5-3** it can be observed that the spectral peaks around 3.2Hz have almost the same amplitudes that can be associated to the 1st vertical mode of the South Span (See **Figure 13.3.5-3**). The peaks at around 3.9Hz, on the other hand, can be associated the 1st torsional mode (see **Figure 13.3.5-3**), taking into account that the amplitudes of vibrations are maximum and almost the same at the mid-span of the East and West Trusses while the amplitude at the mid-span of the Middle Truss is considerably less. The spectral peak around 3.9Hz in **Figure 13.3.5-3** at sensor location 'S', confirms that the mode associated with the 3.9Hz peak is torsional. The spectral peaks around 5.1Hz could be associated to a higher mode of vertical vibration.
- Similarly from **Figure 13.3.5-4**, it can be observed that the spectral peaks around 2.7Hz and 5.1Hz and those of the North Span around 2.7Hz and 4.7Hz are associated to the observed peaks around 3Hz and 5Hz of the amplitude spectrum of the data gathered in the impact vibration test of the bridge pier (see **Figure 13.3.6-2** of **Section 13.3.6**).
- The results from the spectral analysis of all the records taken from other sensor locations are used to confirm the natural frequencies and the associated mode shapes that are identified in (2) and (3).
- The natural frequencies from the microtremor survey are closely correlated with the corresponding natural frequencies of the base models of both spans, as can be observed from **Tables 13.3.5-1**. The close correlation between survey and analysis results confirms that the engineering assumptions made in **Section 13.3.6** to take into account uncertain or missing data are valid.




Figure 13.3.5-3 South Span Sample Amplitude Spectra: Vertical Direction




Figure 13.3.5.4 North Span Sample Amplitude Spectra: Vertical Direction

13.3.6 Impact Vibration Test of Substructure

(1) Objective

This Test was employed to evaluate the substructure soundness by focusing on the natural frequency of the pier.

(2) Procedure

Figure 13.3.6-1 shows the evaluation procedure for the soundness of the pier with the Impact Vibration Test. The feature of this test is as follows:

- The natural frequency can be obtained through several measurements of response waves with allowing normal vehicles passing on the bridge.

(3) Impact Pendulum

An impact pendulum was specially fabricated for this activity. The pendulum was positioned to impact the centerline of the Middle Pier of the bridge. (See **Photo 13.3.6-1**). The impacting head used had a mass of about 100 kg. (See **Photo 13.3.6-2**). The tip of the head was covered with rubber.




Photo 13.3-6-1 North Face of the Ayala Bridge Pier. Impact Pendulum highlighted (Looking South)



Photo 13.3.6-2 Impacting head of yellow-painted Pendulum, viewed from top of Pier (Looking West)

(4) Sensor and Locations

Five (5) force balance accelerometers (Kinematics ES-U) were calibrated to capture accelerations in the horizontal direction, and were positioned at Locations A, B, C, D and E on top of the Pier, beside the concrete bearing pads as shown in **Figure 13.3.6-2**

(5) Data Processing

Vibration measurement data were processed using developed routines and algorithms in the MATLAB environment. For this processing, ten (10) individual measurement events that captured the impact of the pendulum on the Pier were superimposed; i.e., the location of the peak value in the time history of each event was determined, and each event was cropped as specific seconds before the peak and after the peak. The ten (10) events were then algebraically added, to form a superimposed measurement event. The total length of the superimposed event was about six (6) seconds.

Basically, processing consisted of plotting the recorded vibration acceleration against time (or time history), computing the root-mean-square (RSM) and peak values of the time-history as indicator of the level of vibration, and plotting the amplitude spectrum (acceleration vs. frequency), which was obtained using the Fast Fourier Transform algorithm. (See **Figure 13.3.6-2**).




Figure 13.3.6-1 Evaluation Procedure for Soundness of Pier




Figure 13.3.6-2 Sensor Location, Analysis and Response Acceleration at E
Result of Fast Fourier

(6) Test Results

The peak and RMS acceleration at Location A and C, which are on the same side (north) or the Pier as Location E, but located beside the bearings of the outer truss are calculated. The computed peak and RMS acceleration at Location C was more than 4 times those at Location B and D, which are behind Locations A and C, respectively, on the outer south bearings on the Pier. (See Table 13.3.6-1 for computed peak and RMS values acceleration. Refer to Figure 13.3.6-2 for the relative locations of the sensors.

Table 13.3.6-1 Summary of Vibration Data

| Sensor Location | Acceleration (gal) | | Remarks |
|-----------------|--------------------|-----|--|
| | Peak | RMS | |
| A | 31.2 | 1.5 | This data is result of the Super-Position of the ten (10) Events described below |
| C | 35.6 | 1.6 | |
| B | 25.7 | 1.3 | |
| D | 25.5 | 1.3 | |
| E | 126.4 | 5.8 | Peak and RMS Values of Acceleration Shown only for Location E |
| E | 8.2 | 0.7 | |
| E | 19.2 | 1.1 | |
| E | 7.7 | 0.6 | |
| E | 18.0 | 1.0 | |
| E | 14.4 | 0.8 | |
| E | 8.8 | 0.6 | |
| E | 23.0 | 1.1 | |
| E | 24.4 | 1.1 | |
| E | 25.1 | 1.2 | |
| E | 38.8 | 1.8 | |

The natural frequency of the Pier was expected to be above 10 Hz. From the amplitude spectra generated from the superimposed measurement event, a peak occurring at around 17 Hz was taken to be the fundamental natural frequency of the Pier in the longitudinal direction of the bridge. Peaks in the spectra around 3 Hz and around 5 Hz were presumed to be associated with predominantly vertical modes of vibration of the superstructure.

(7) Eigenvalue Analysis

The eigenvalue analysis of the pier was carried out for the following cases with consideration of the present bearing conditions.




Figure 13.3.6-3 Cases for Eigenvalue Analysis

The results obtained from Eigenvalue Analysis are given in **Table 13.3.6-2**

Table 13.3.6-2 Results of Eigenvalue Analysis

| CASE | Frequency of the First Mode |
|----------|-----------------------------|
| Case - 1 | 15.2 Hz |
| Case - 2 | 17.0 Hz |
| Case - 3 | 20.5 Hz |

(8) Comparison on Natural Frequency

According to the criteria given in **Table 13.3.6-3**, it was demonstrated that the pier was sound because of the following reasons:

- In original design both the spans were fixed at the pier and movable at the abutment. This means that case-1 is fit for the evaluation model in the ideal condition.

- According to the Microtremor Measurement Survey, motion associated with superstructures was observed. This means that bearing conditions are still effective under the small displacement or deflection, and case-3 is not adequate for the evaluation model.
- Movable conditions at both the abutment are not ideal states because of friction between the superstructure and substructure through bearings. The friction works even in conditions intended in the design under the quite small displacement or deflection.
- In case that interaction springs between foundation and surrounding ground are installed in the model, the calculated natural frequency will be smaller. This means that the natural frequencies indicated in **Table 13.3.6-2** become smaller in when taking into consideration the soil-structure interaction.
- From the above, the natural frequency obtained from the eigenvalue analysis is to be between case-1 and case-2. This natural frequency is smaller than that measured from the Impact Vibration Test.

In light of the definition of the soundness of the pier shown in **Figure 13.3.6-4** the pier is evaluated to be sound.

Table 13.3.6-3 Criteria for Substructure Soundness

| $\text{Rating Index (k)} = \frac{\text{(Natural Frequency of Test)}}{\text{(Natural Frequency of Analysis)}}$ | | | |
|---|--------|------|---|
| Rating Index | Rating | | Action |
| 0.7 or less | A | (A1) | In dangerous condition to abnormal external forces. Improvement work is required. |
| 0.85 or less | | (A2) | To conduct follow-up test to check the progress of deterioration. |
| 0.86 or more | B | | No problem at present |

Table 13.3.6-4 Rating Index of Test Result

| Case | Natural Frequency | | Rating Index | Action* |
|--------|-------------------|-------|--------------|---------|
| | Analysis | Test | | |
| Case-1 | 15.2 Hz | 17 Hz | 1.12 | B |
| Case-2 | 17.0 Hz | | 1.00 | B |
| Case-3 | 20.5 Hz | | 0.83 | (A2) |

* : Refer to Table 13.3.6-2

13.3.7 Assessment of Critical Damages

Damages of bridge members inspected under the close-up visual inspection and non-destructive test of material were identified and evaluated in compliance with the procedure shown in **Figure 13.3.7-1**.

(1) Damage Rating with X, Y, Z Method

The kinds of damages are divided into thirty two (32) types by the material composition of the structure. Regarding damage type and evaluation method, the detailed and concrete explanations were described to inspectors in order to identify damages readily.




Figure 13.3.7-1 Procedure of Diagnosis for the Soundness of Bridge

Figure 13.3.7-2

shows an example of the damage rating recorded in the study it has two (2) damages types with damage rating given in Figure 13.3.7-3.




Figure 13.3.7-2 Damage Rating Example Adopting the X, Y, Z Method

For members given a damage rating of II by the inspectors, the responsible engineer identified whether the members would be given of rating I or II through consultation with the DPWH.

(2) Categorization of Damage Rating

The damage ratings were categorized as discussed in Chapter 6.

(3) Evaluation of Damages

The results of damage evaluation for main members are summarized in Table 13.3.7-1. In the table heavily damaged main members are shown. Members given in the table can be identified by referring to the joint numbers shown in Figure 13.3.7-4.

Damage Type | (1) CORROSION

Corrosion is the representative damage of steel caused by oxidation of the member by the environment. Because of being progressive in nature but easy to be found, this is one of the important damages whose progress shall be protected by maintenance activities.

| | | Influence of Damage on Load-Carrying Capacity and Durability | |
|-------------------------|--------------------|---|---|
| | | High | Low |
| Location or Pattern (X) | Severeness | - | - |
| | Sample Description | - | - |
| Depth (Y) | Severeness | Section Loss | Surface Rust |
| | Sample Description | Swollenness of steel surface or reduction of cross section area due to missing of corrosion parts | Dotted surface rust areas |
| Expanse (Z) | Severeness | Entire | Local |
| | Sample Description | Entire expanse of corrosion or rust to members | Local expanse such as leakage area of corrosion or rust |

| Rating | | | |
|--------|------|-------------------|--------------|
| Y | Z | Secondary Members | Main Members |
| High | High | II | II |
| | Low | III | II |
| Low | High | III | II |
| | Low | IV | III |

Damage Type | (2) Crack



Almost all cracks generate at or near the welded connection area. Since cracks are hard to find, it is necessary to inspect carefully referring to figures or pictures of similar damages. When cracks are found, in-depth survey shall be conducted by qualified engineers.

| | | Influence of Damage on Load-Carrying Capacity and Durability | |
|-------------------------|--------------------|--|-----|
| | | High | Low |
| Location or Pattern (X) | Severeness | - | - |
| | Sample Description | - | - |
| Depth (Y) | Severeness | Cracks | - |
| | Sample Description | - | - |
| Scale (Z) | Severeness | - | - |
| | Sample Description | - | - |

| Rating | | |
|-----------------|---|-------------|
| Y | Z | All Members |
| High (presence) | | II |

Damage Type | (10) Honeycomb



Honeycomb is mainly caused by insufficient compaction of concrete under construction. The extent of damage is determined by the presence of exposed reinforcing bars.

| | | Influence of Damage on Load-Carrying Capacity and Durability | |
|-------------------------|--------------------|---|---|
| | | High | Low |
| Location or Pattern (X) | Severeness | - | - |
| | Sample Description | - | - |
| Depth (Y) | Severeness | Exposed Reinforcing Bar | No Exposed Reinforcing Bar |
| | Sample Description |  |  |
| Expanse (Z) | Severeness | Large area generated | Small area generated |
| | Sample Description | Superstructure: 0.1 m2 or more Substructure : 1.0 m2 or more | Superstructure: below 0.1 m2 Substructure : below 1.0 m2 |

| Rate | | | |
|------|------|-------------------|--------------|
| Y | Z | Secondary Members | Main Members |
| High | High | II | II |
| | Low | IV | II |
| Low | High | IV | III |
| | Low | IV | IV |

Damage Type | (11) Wear / Abrasion / Erosion

In this damage, the surface of concrete substructures is worn-out, abraded or eroded by water. The extent of the influence of the damage is determined from whether the damage has reached the reinforcing bar.

| | | Influence of Damage on Load-Carrying Capacity and Durability | |
|-------------------------|--------------------|---|---|
| | | High | Low |
| Location or Pattern (X) | Severeness | - | - |
| | Sample Description | - | - |
| Depth (Y) | Severeness | Exposed Reinforcing Bar | No Exposed Reinforcing Bar |
| | Sample Description |  |  |
| Expanse (Z) | Severeness | Large Area Generated | Small Area Generated |
| | Sample Description | Substructure : 1.0 m2 or more | Substructure : below 1.0 m2 |

| Rate | | |
|------|------|-------------|
| Y | Z | All Members |
| High | High | II |
| | Low | III |
| Low | High | III |
| | Low | IV |

Figure 13.3.7-3 Examples for Damage Rating Reference Used in the Field Inspection

Table 13.3.7-1 Evaluation of Damages for Main Members of Superstructure

| SOUTH SPAN | | | | | | NORTH SPAN | | | | | |
|--------------------------|-----------------------|-------------|----------------------------------|---------------------|-------------------|--------------------------|-----------------------|-------------|----------------------------------|---------------------|-------------------|
| Location | Members Reference No. | Damage Type | Evaluation Based on Field Survey | | Estimated Section | Location | Members Reference No. | Damage Type | Evaluation Based on Field Survey | | Estimated Section |
| | | | Damage Rating | Diagnostic Category | | | | | Damage Rating | Diagnostic Category | |
| South Span, West Truss | | | | | | North Span, West Truss | | | | | |
| Bottom | M109-112 | CO | I | A | 30% | Bottom | M139-142 | CO | I | A | 30% |
| Chord | M112-115 | CO | I | A | 30% | Chord | M142-145 | CO | I | A | 30% |
| | M115-121 | CO | I | A | 30% | | M154-157 | CO | I | A | 40% |
| | M124-127 | CO | I | A | 30% | North Span, Middle Truss | | | | | |
| South Span, Middle Truss | | | | | | Bottom | | | | | |
| Bottom | M206-209 | CO | I | A | 30% | Bottom | M234-238 | CO | I | A | 50% |
| Chord | M209-212 | CO | I | A | 30% | Chord | M238-239 | CO | I | A | 30% |
| | M212-215 | CO | I | A | 30% | | M239-242 | CO | I | A | 30% |
| | M215-218 | CO | I | A | 40% | M242-245 | CO | I | A | 30% | |
| | M218-221 | CO | I | A | 40% | M245-248 | CO | I | A | 30% | |
| | M221-224 | CO | I | A | 30% | M248-251 | CO | I | A | 30% | |
| South Span, East Truss | | | | | | M251-254 | CO | I | A | 40% | |
| Bottom | M309-312 | CO | I | A | 30% | M254-257 | CO | I | A | 40% | |
| Chord | M312-315 | CR | I | A | 30% | M257-260 | CO | I | A | 30% | |
| | M315-318 | CO | I | A | 40% | M260-263 | CO | I | A | 30% | |
| | M318-321 | CR | I | A | 40% | M263-266 | CO | I | A | 30% | |
| | M321-324 | CO | I | A | 30% | M266-269 | CO | I | A | 10% | |
| | M324-327 | DE | I | A | 30% | M271-272 | CO | I | A | 50% | |
| | | | | | | North Span, East Truss | | | | | |
| | | | | | | Bottom | M342-345 | CO | II | B | 10% |
| | | | | | | Chord | M351-354 | CO | III | B | 15% |
| | | | | | | | M357-360 | CO | I | A | 30% |
| | | | | | | M360-363 | CO | II | B | 10% | |




Figure 13.3.7-4 Node Numbers for Reference

Moreover, the damage evaluation of substructure is shown in **Table 13.5.1-1** of **Section 13.5.1**.

The detailed section and material properties are discussed in **Section 13.4**.

13.4 PRESUMPTION OF ORIGINAL DESIGN AND LOAD RATING

13.4.1 Objective

The purpose of the presumption of original design is to prepare the structural shapes, dimensions and material properties for the analysis model of the Load Rating as discussed in the **Section 13.4.3**. The following policy are used in the presumption of the original design:

- Inspection results are to be used for the determination of shapes and dimensions of visible portions such as superstructure, exposed parts of substructures.
- Material properties of members are to be basically determined from the non-destructive test. For the members for which the non-destructive test was not carried out, the material properties are to be estimated based on the relevant reference materials and as-built drawings, if indicated.
- The foundation type and its embedded depth are to be determined from as-built drawings, geotechnical survey results and relevant reference materials.
- The number of piles are to be fixed from the calculation based on the original design code.

13.4.2 Structural Shapes and Dimensions

(1) Superstructure

Most structural data of the superstructure does not need to be assumed because almost all the dimensions and details were measured. The shape and dimension measurement was used for structural analysis while the drawings are included in **Appendix 13.3.1**.

The material properties of each member use in the analysis are given in **Appendix 13.4.2-2**.

(2) Substructure

The dimension of exposed portion of the substructure were all measured. It is necessary to calculate the dead load and live load for the estimation of the scale of foundation.

The type of foundation were found from the as-built drawing. The availability of materials and construction is known, thus the pile capacity of each pile could be estimated. **Appendix 13.4.2-3** shows the assumed shapes, dimensions and details of substructures.

Table 13.4.2-1 shows reactions estimated at the bearings.

Table 13.4.2-1 Reactions Estimated at Supporting Points

| | | South Span | | North Span | |
|-------------------|--------------|------------|------|------------|----------|
| | | Abutment | Pier | Pier | Abutment |
| Dead Load | West Trust | 201 | 200 | 238 | 235 |
| | Middle Trust | 348 | 352 | 413 | 422 |
| | East Trust | 215 | 213 | 262 | 257 |
| | Sub-Total | 765 | 765 | 914 | 914 |
| Live Load | West Trust | 68 | 68 | 78 | 78 |
| | Middle Trust | 102 | 102 | 117 | 117 |
| | East Trust | 68 | 68 | 78 | 78 |
| | Sub-Total | 238 | 238 | 274 | 274 |
| Total Reaction | | 1003 | 1003 | 1187 | 1187 |
| Total Dead Weight | | 1530 | | 1828 | |

Unit: tons

13.4.3 Load Rating

(1) Objective

The purpose of this analysis is to evaluate quantitatively the load carrying capacity of prime members of superstructure. With the bridge condition survey results and the “Presumption of Original Design”, the structural data were evaluated and integrated in order to build a complete and realistic structural frame model of the superstructure.

As far as the substructures are concerned, its capacity-demand ratio was discussed in “Vulnerability to Disaster” of **Section 13.6** because the safety of substructures are usually determined from seismic forces in this country.

(2) Procedure

The allowable stress method expressed by the following formula was used to evaluate the capacity of the members:

$$RF = \frac{\text{Capacity for Live Load Effect}}{\text{Vehicle Load Capacity}} = \frac{R - D}{L(1 + i)}$$

Where,

| | | |
|----------|---|------------------------------------|
| RF | = | Rating Factor (RF) |
| R | = | Allowable stress of member |
| | | • Inventory Level = 125 MPa |
| | | • Operating Level = 170 MPa |
| | | • Yield Stress = 228 MPa |
| D | = | Stress due to dead loads |
| L(1 + i) | = | Stress due to live loads |
| i | = | Impact factor for live load effect |

Structural member damages, corruptions and missing members were evaluated and taken into account in the model to truly reflect them on the actual status of the bridge. The resulting bridge structural model were then checked and verified if the calculated deflection is comparatively equal with the conducted Static Load Test of the bridge and the analysis model was verified with the Microtremor Test whether or not its model represented the actual motion.

The bridge superstructure was modeled using the Strand7 Finite Elements Analysis System. An analysis of Load Effects was performed. A fully rigid joint as well as a pin joint assumption were both analyzed and investigated. MS 18 Load was used in the Live Load Analysis.

The Rating Factor (RF) can be used to determine the Load Rating (LR) of the superstructure members as follows:

$$LR = RF \cdot W$$

Where,

W = Weight of the Rating Vehicle in metric tons

(3) Analysis Results

Figure 13.4.3-1 and 13.4.3-2 show the members with RF less than 1.0., which are highlighted, for the Inventory Level and the Operating Level, respectively.

The calculated numeric data of RF for each main member is given in Appendix 13.4.3-1 (1/6) ~ (6/6)

The results of minimum RF per location are shown in Table 13.4.3-1

Table 13.4.3-1 Minimum RF per Location

| | | South Span | | North Span | |
|--------------|-------------------------------|-----------------|-----------------|-----------------|-----------------|
| | | Inventory Level | Operating Level | Inventory Level | Operating Level |
| West Truss | Bottom Chord | 0.3 (10) | 1.6 (51) | 0.1 (3) | 0.5 (15) |
| | Top Chord | 2.4 (77) | 4.4 (141) | 1.2 (38) | 2.7 (85) |
| | Main Vertical | 2.1 (67) | 3.3 (106) | 4.2 (70) | 3.4 (109) |
| | Main Diagonal | 2.1 (109) | 5.7 (182) | 2.7 (86) | 4.7 (150) |
| Middle Truss | Bottom Chord | - 0.2 (0) | 0.9 (29) | - 0.6 (0) | 0.1 (3) |
| | Top Chord | 2.3 (74) | 4.3 (138) | 1.2 (38) | 3.0 (95) |
| | Main Vertical | 1.2 (38) | 2.1 (67) | 0.6 (19) | 2.0 (64) |
| | Main Diagonal | 1.6 (51) | 3.3 (106) | 1.8 (58) | 3.7 (118) |
| East Truss | Bottom Chord | 0.0 (0) | 1.2 (38) | 0.1 (3) | 1.1 (35) |
| | Top Chord | 1.9 (61) | 4.2 (134) | 0.5 (16) | 1.9 (61) |
| | Main Vertical | 1.4 (45) | 2.3 (74) | 0.5 (16) | 1.9 (61) |
| | Main Diagonal | 1.6 (51) | 3.3 (106) | 1.4 (45) | 3.1 (99) |
| Remarks | () : Equivalent Truck (tons) | | | | |




Figure 13.4.3-1 Member Below 1.0 of Rating Factor at Inventory Level




Figure 13.4.3-2 Member Below 1.0 Rating Factor at Operating Level

The analysis results suggest that the following counter measures shall be undertaken.

- Strict implementation of the regulation on the present vehicle load limit from 5 to 3 tons should be done, if improvement works are not carried out. However, the drastic improvement works of main members shall be required because RF_i of the inventory level is still insufficient for any vehicle.

- The drastic improvement works of the bridge should be conducted as soon as possible in order to secure safety of the facility and to prevent the potential partial or total collapse of the bridge.
- The planning of the improvement works shall be implemented so as to meet the latest design code requirements with consideration of the present traffic conditions.

The minimum Rating Factors were generated at the bottom chord of middle truss of the north span. This situation of the member can be understood by the following calculation (refer to **Figure 13.4.3-3** below).




Figure 13.4.3-3 Effective Stress for Members with Section Loss

13.5 TRAFFIC CONDITION

13.5.1 Traffic Condition on the Ayala Bridge

Figure 13.5.1-1 shows the hourly traffic volume variation of weekday on the Ayala Bridge by direction. Traffic volume bound for the south (Direction 2) changes considerably depending on the time zone: the most congested time is from 8:00am to 2:00pm. This suggests that the Ayala Bridge is mainly used for business activities.




Figure 13.5.1-1 Hourly Traffic Volume Variation

The Level of Service (LOS) on the Ayala Bridge in 2002 was estimated to be D level (v/c ratio = 0.74) from the traffic count survey results conducted in the Study as discussed in Section 5.4.2. At this level, the drivers have little freedom to maneuver since traffic condition is approaching unstable flow.

The counted traffic volume on the Ayala Bridge in December of 2002 was 40,390 PCU as AADT, with the vehicle type composition of: passenger car accounting for 92%, jeepney at 3%, large bus at 2% and trucks at 3%.

According to the Geometric Design of Highways and Streets (AASHTO 2001), the appropriate level of service for urban arterial area is required to be C level, that is, stable flow is required. In line with the policy on the geometric design requirements, the extent of traffic congestion is judged to be inappropriate.

13.5.2 Traffic Condition on Adjacent Intersections

Table 13.5.2-1 indicates the level of service of each approach road and intersection.

Table 13.5.2-1 LOS of Approach Roads and Intersections

| | South Intersection | | | North Intersection | |
|--------------|--------------------|-----|--------------|--------------------|-----|
| | Delay Time (sec.) | LOS | | Delay Time (sec.) | LOS |
| Approach Ⓐ | 97.8 | F | Approach Ⓓ | 59.2 | E |
| Approach Ⓑ | 16.5 | B | Approach Ⓔ | 29.2 | C |
| Approach Ⓒ | 23.2 | C | Approach Ⓕ | 81.1 | F |
| - | - | - | Approach Ⓖ | 24.5 | C |
| Intersection | 48.1 (average) | D | Intersection | 39.1 (average) | D |

Reference Figure

For the above table, the following features of the intersections are seen:

- The levels of service of both intersections are D, and the delay time is within 60 seconds,
- Approach Ⓐ, Ⓓ and Ⓕ are estimated to be heavily crowded,
- One reason for the traffic congestion of approach road Ⓐ is due to the high composition rate of heavy vehicles: accounting for 14%, and
- There are large variations in the level of service among approaches, which suggests that traffic congestion at the intersections may be improved by leveling the traffic congestion of approach roads with control of traffic signal.

13.6 VULNERABILITY TO DISASTER

Ayala Bridge is located within the area prone to disasters including earthquakes, typhoons, wind and flood. An average of more than 20 typhoons is expected to pass over the Philippine area of responsibility annually. The Philippines is also within the region of high seismic activities.

13.6.1 Earthquake

The earthquake vulnerability of a bridge can be assessed by considering the following factors discussed in details in **Chapter 10**.

(1) Bridge Site

Ayala Bridge is located 13km from the Marikina Valley Fault System (MVFS). As a rule, bridge structures less than 5km distance are considered highly vulnerable. The 13km distance of Ayala Bridge makes it moderately vulnerable to earthquake.

(2) Date of Construction

Ayala Bridge was originally constructed on 1935 and reconstructed on 1950. Before and during those times, AASHTO has no recommendations with regards to seismic design. Therefore Ayala Bridge could be prone to seismic forces.

(3) Capacity – Demand Ratio under Earthquakes

The safety of the bridge under earthquakes is determined from the capacity and stability of substructures. Vulnerability of the bridge to earthquakes shall be represented by the ratio of capacity-demand under earthquakes.

The existing dimensions and structural data of substructures for the analysis were determined from the field survey results, as-built plans and “Presumption of Original Design” using the old code.

According to the Impact Vibration Test results, the pier may be sound. Calculation results using the old code is given in **Table 13.6.1-1**, which shows that the existing bridge may meet requirements specified in the old code. However, when considering the requirements specified in the latest code, the bridge has high vulnerability to earthquakes as shown in **Table 13.6.1-2**. This means the substructures of Ayala Bridge may not meet the latest seismic code requirements.

Table 13.6.1-1 Capacity / Demand Ratio of the Substructure Using the Old Code

| (Using the Old Code) | | | | | |
|----------------------|-----------------|--------------|--------------|--------------|--------------|
| Substructure | Pile Foundation | Footing | Main Wall | Column | Wingwall |
| Abutment-A (South) | 1.0 Safe | 1.00 Safe | 1.00 Safe | --- | 1.00 Safe |
| Abutment-B (North) | 1.00 Safe | 1.00 Safe | 1.00 Safe | --- | 1.00 Safe |
| Pier | 1.13 Safe | --- | --- | 1.27 Safe | --- |

Table 13.6.1-2 Capacity/Demand Ratio of the Substructure Using the Latest Code

| (Using the New Code) | | | | | |
|----------------------|-----------------|--------------|--------------|--------------|--------------|
| Substructure | Pile Foundation | Footing | Main Wall | Column | Wingwall |
| Abutment-A (South) | 0.69 Fail | 0.61 Fail | 0.60 Fail | --- | 1.00 Safe |
| Abutment-B (North) | 0.57 Fail | 0.61 Fail | 0.60 Fail | --- | 0.98 Fail |
| Pier | 0.41 Fail | --- | --- | 0.32 Fail | --- |

Appendix 13.6.1-1 shows the capacity/demand ratio for each structural component of substructures in detail.

13.6.2 Wind

The National Structural Code of the Philippines (NSCP 2001) recommends a design basic wind speed of 200 kph. While AASHTO recommends only 160 kph. The maximum cyclone center wind velocity of 225 kph passing Metro Manila where Ayala Bridge is located was recorded in 1995 with a gust velocity reaching to 255 kph. This indicates that Ayala Bridge has been exposed to more than 200 kph basic design wind speed specified in the Philippine Code. Therefore Ayala Bridge is not vulnerable to wind forces.

13.6.3 Flood

The pier is located very close to the island being at down stream side. According to the scour survey carried out in the Study, there is no evidence of scouring observed. The pressure from flood water flow is usually quite small comparing to the lateral design force adopted under the earthquake in the Philippines. This means that the earthquake forces dictate the scale and the safety of the substructures.

However, considering the present condition and configuration of the Ayala Bridge, especially the pier, the bridge is judged to be not vulnerable to flood action.

13.7 SPECIAL ISSUES

13.7.1 Vessel Collision

(1) Vessel Collision with Girders

The vertical clearance of Ayala Bridge is 3.50m less than a regulatory clearance of 3.75 m.

(2) Vessel Collision with Piers

The navigational space between pier and abutment of Ayala Bridge is 60.2 meters more than the preferable space of 43 meters.

13.7.2 Utilities

The existing utility lines of Ayala Bridge were as follows:

- 1) Two (2) Ø 400mm Water Pipes
- 2) Sixteen (16) Electricity Lines
- 3) Eight (8) Telecommunication Lines

13.7.3 Informal Settlers

There is one informal settler along Ayala Bridge according to the Social Condition Survey and the Environmental Impact Assessment.

Therefore, there will be few problems during the implementation of the project.

13.8 OVERALL ASSESSMENT OF EXISTING CONDITION

The present state of Ayala Bridge condition was summarized as shown in **Table 13.8-1**, and assessed as follows:

(1) Superstructure

- As shown in **Figures 13.4.3-1** and **13.4.3-2**, most of the lower chords show the rating factor, either inventory or operating level, less than 1.0, which means the structural capacity of bridge is less than 32.7 tons (design load).
- Floor system including cross beams and stringers are heavily corroded or fractured, while requires very urgent replacement.
- The corrosion of members are observed to be heavy due to water leak from the deck slab further and aggravated by a bigger number of vehicles and present load of heavy vehicle than expected.

(2) Substructure

- As shown in **Table 13.5.1-1** the existing pier is sound to carry original design load, with minor damages.
- However, the stability and capacity of the pier and abutment are not sufficient to carry the load of the present design code with 0.4 ~ 0.7 capacity/demand ratios (C/D ratio).
- The insufficient stability of the substructure is due to the change of design code and requirements.
- The foundation is taken to consist of timber piles, which may not meet the latest seismic design code requirements.

(3) Traffic Function and Social Environment

- Large deflection of deck slab occurs during passage of vehicles.
- Traffic load limit is recommended to be set to 3.0 tons.
- As mentioned in **Section 13.1.3**, the National Historical Institute declared that the Ayala Bridge is one of the historical bridge, and strongly endorse the policy that the configuration of historical structures should be preserve.
- The present vertical clearance of 3.50m shall be improved at least up to the regulatory vertical clearance of 3.75m in order to prevent vessel collision with girders.
- No serious dislocation of people affected by the improvement works were observed.

Table 13.8-1 Overall Assessment of Existing Condition of Ayala Bridge

| Item | | Member/ Location | Rating | Remark | Main Survey Method | |
|------------------------------------|-----------------------------------|--|--|------------------|------------------------|--|
| Structural Soundness | Superstructure | Shape/Dimension | Bot.Chord/South Span-East Truss | II | Deformed | Shapes/Dimension Survey |
| | | | Stringer/ North Span | I | Missing | |
| | | | Stringer/South Span | I | Loss End Section | |
| | | | Deck Bracing/South Span-East Truss | I | Missing | |
| | | | Stringer/South Span-East | I | Reduced Section | |
| | Material/Damage | Superstructure | Deck Slab/North Span | II | Crack | Damage Survey |
| | | | Bottom Chord | I | Heavily Corroded | Material Survey |
| | | | Gusset Plate/North Span-Mid Truss | I | Heavily Corroded | |
| | | | Cross Beam/North Span-East Truss | I | Heavily Corroded | |
| | | | Stringer/North Span | I | Crack (broken) | |
| | | | Bearing /All Locations | I | Heavily Corroded | |
| | | | 130 test locations for UTG | o.k. | 7mm to25mm | NDT |
| | | | 40 test locations for Brinell Hardness | o.k. | 328MPa-540MPa | |
| | | | 37 test locations for UFD | o.k. | No Defects | |
| | | | Load-Carrying Capacity | Superstructure | West Truss South Span | o.k. |
| | West Truss South Span | o.k. | | | Strain (0.6-6.2 me) | |
| | Operating Level | Superstructure | North Span=3 tons | not o.k. | Equiv. Truck=32.7 tons | Structural Calculations |
| | | | South Span = 29 tons | not o.k. | Equiv. Truck=32.7 tons | |
| | Assessment of Superstructure | Superstructure | Not O.K. for 32 ton truck & heavy corrosions @ bottom chords & floor system | | | |
| | Structural Soundness | Substructure | Shape/Dimension | North Abutment | o.k. | - |
| Pier | | | | o.k. | - | |
| South Abutment | | | | o.k. | - | |
| Material/Damage | | Substructure | North Abutment/Mainwall | III | Crack | Damage Survey |
| | | | Bearing Pedestal/Pier | I | Crack | Material Survey |
| | | | South Abutment/Mainwall | III | Crack | |
| | | | 3 test locations for Schmidt Hammer | o.k. | 41MPa to 49MPa | NDT |
| Stability | | Substructure | 6 test locations for Coring & Comp. | o.k. | 19MPa to 25MPa | |
| | | | North Abutment | - | - | Impact Vibration Test |
| | | | Pier | o.k. | 17 Hz (Rigid) | |
| | | | South Abutment | - | - | |
| | | | North Abutment/Mainwall,Wingwall | not o.k. | Bending Moment | Structural Calculations using latest code |
| Pier Column | | not o.k. | Spiral Requirement | | | |
| Assessment of Substructure | | Substructure | Minor damage on existing substructure but design can not comply with the latest code | | | |
| Foundation | | Structure/Shape | North Abutment/Ø300 -Timber Piles | not o.k. | 665 Pcs.L=15m | Shape/Dimension |
| | Pier/Ø300 -Timber Piles | | not o.k. | 523 Pcs.L=15m | | |
| | South Abutment/Ø300 -Timber Piles | | not o.k. | 576 Pcs.L=15m | | |
| | Scouring | Foundation | No exposed foundation | o.k. | - | Echo Sound Survey |
| | Bearing Capacity/Stability | Foundation | Pier | - | - | Impact Vibration Test |
| | | | North Abutment/compression piles | not o.k. | C/D ratio = 0.72 | Structural Calculations using new code |
| | | | Pier/compression piles | not o.k. | C/D ratio = 0.65 | |
| South Abutment/compression piles | | | not o.k. | C/D ratio = 0.67 | | |
| Assessment of Foundation | Foundation | Existing Pile Foundation can not comply with the latest AASHTO codes | | | | |
| Assessment of Structural Soundness | | Existing Bridge structure needs strengthening to meet the present required strength for a bridge. | | | | |
| Traffic Function | Vehicle Weight Limitation Use | | 5 tons limitation during rehabilitation | | | |
| | LOS | | D (V/C=0.70, V=42,000, C=59,000 PCU) | | | |
| | Geometrical Features | | Fair (including access road to Hospicio de San Jose) | | | |
| | Safety of Vessel Transport | | An existing vertical clearance of 3.50 m is insufficient for a regulatory clearance of 3.75 m. | | | |
| | Assessment of Traffic Function | | Insufficient | | | |
| Social Environment | Utilities Hanged at the Bridge | | 2 water pipes (d=400mm), 16 electricity lines and 8 telecommunication lines. | | | |
| | Squatters | | Four families live around the south abutment. | | | |
| | Historical Aspects | | National Historical Institute lists Ayala Bridge as a historical structure. | | | |
| | Assessment of Social Aspects | | Historical situation shall be considered. | | | |
| Overall Assessment | | Superstructure is necessary for the improvement work. Substructure shall be strengthened. Vertical clearance shall be improved at least up to regulatory vertical clearance of 3.75 m. | | | | |