


Main Equipment List

ANNEX 7-10


	Equipment	Field of Activity	Usage
1-1	Strong Motion Accelerograph	Strong Motion Observation	Evaluation of Input Earthquake
1-2	Bore-hole Sensor	Strong Motion Observation	Evaluation of Input Earthquake
1-3	Bore-hole Transmitter	Strong Motion Observation	Evaluation of Input Earthquake
1-4	External Sensor	Strong Motion Observation	Evaluation of Input Earthquake
2-1	Boring Machine	Soil Testing, Ground Investigation	Ground Investigation
2-2	Boring Pump	Soil Testing, Ground Investigation	Ground Investigation
2-3	Boring Tool	Soil Testing, Ground Investigation	Ground Investigation
2-4	Standard Penetration Testing Machine	Soil Testing, Ground Investigation	Ground Investigation
2-5	Data Collection System	Soil Testing, Ground Investigation	Testing of Ground Condition
2-6	Down-hole Sensor	Soil Testing, Ground Investigation	Testing of Ground Condition
2-7	Ground Surface Sensor	Soil Testing, Ground Investigation	Testing of Ground Condition
2-8	Micro-tremor Data Collection System	Soil Testing, Ground Investigation	Testing of Ground Condition
2-9	Micro-tremor Sensor	Soil Testing, Ground Investigation	Testing of Ground Condition
2-10	Data Analysis Software	Soil Testing, Ground Investigation	Testing of Ground Condition
2-11	Tri-Axial Testing Machine	Soil Testing, Ground Investigation	Testing of Ground Condition
2-12	Bender-Element Testing Machine	Soil Testing, Ground Investigation	Indoor Soil Testing
2-13	Physical Characteristics Testing System	Soil Testing, Ground Investigation	Indoor Soil Testing
2-14	Data Collection/Analysis System	Soil Testing, Ground Investigation	Indoor Soil Testing
2-15	Carrying Vehicle	Soil Testing, Ground Investigation	Testing Vehicle
3-1	Reaction Frame	Structural Testing	Loading Facility
3-2	Hydraulic Jack	Structural Testing	Loading Facility
3-3	Power Pump Unit	Structural Testing	Loading Facility
3-4	Hydraulic Pump / Controller	Structural Testing	Loading Control
3-5	Control Computer / Software	Structural Testing	Measurement System
3-6	Data Logger	Structural Testing	Measurement System
3-7	Switch Box	Structural Testing	Measurement System
3-8	Load Cell	Structural Testing	Measurement System
3-9	Displacement Scale	Structural Testing	Measurement System
3-10	Computer / Software for Measurement	Structural Testing	Measurement System
3-11	Dynamic Strain Scale	Structural Testing	Measurement System
3-12	Measurement Frame	Structural Testing	Measurement System

Annex 7-11-1

Earthquake Epicenters in and around Romania :984-1988:



## Organization Chart of Disaster Prevention Countermeasures



Buildings with more than 5 stories built before 1940 in Bucharest and identified as having highest risk of collapse in case of strong (comparable to 1977) earthquake\* (Buildings numbered 1 through 10 are accepted retrofitting works by their residents.)

No	Address	Year of building construction	Commercial occupancy of ground floor	Storeys	No. of Apt.	Total area sqm.	Damages after the 1977 earthquake in structural elements	Repairing work after the 1977 earthquake and labour	SD*	Designer	P100- earthquake capacity ratio - Trans. Long.
1	Balcescu 24 (Pherkide)	1928	Yes	13	61	12,197	Columns : Extreme Beams : Extreme	Jacketing of columns and beams	100	IPCT	0,024
2	Demaniei 5	1934	Yes	11,5	25	2750	Columns : Light Beams : Light	Masonry Repairs	100	IPCT	0,023
3	Balistei 5	1938	Yes	11	21	3680	Columns : Light Beams : Light	Jacketing of columns and beams	2,5	-	0,10
4	Calea Victoriei 101 A-R	1937	Yes	11	61	6111	Columns : Extreme Beams : Extreme	Masonry Repairs	2,5	-	0,10
5	Beldiman 1	1940	Yes	10	80	8700	Columns : Medium Beams : Medium	Epoxy resin injections	86	IPU	0,15
6	Magheru 20	1935	Yes	10	52	5484	Columns : Extreme Beams : Light	Masonry Repairs	57	ICMPC	0,09
7	Ilfovianu 44	1940	-	10	28	2607	Columns : Light Beams : Light	Epoxy resin injections	11	-	0,16
8	Bucium 3A	1936	-	9,5	30	4997	Columns : Light Beams : Light	Masonry Repairs	25	IPROMET	0,27
9	Biserica 8	1940	Yes	9,5	58	4106	Columns : Light Beams : Light	Masonry Repairs	11	-	0,16
10	Maria Rosetti 55	1934	-	9,5	20	52059	Columns : Extreme Beams : Medium	Jacketing of one column	70,5	-	0,14
11	Magheru 27	1935	Yes	9,5	36	6005	Columns : Light Beams : Light	Masonry Repairs	36	-	0,11
12	Calea Victoriei 2-4	1928	Yes	9	76	12994	Columns : Light Beams : Light	Masonry Repairs	29	-	0,102
13	Ion Ghica 3	1938	Yes	9	53	5835	Columns : Light Beams : Light	Masonry :	25	-	0,11

\* D<sub>r</sub>, damage score for fragile buildings is based on the damage methodology proposed by Gulkani, 1994

No	Address	Year of building construction	Commercial occupancy of ground floor	Stores	No. of Apt.	Total area sqm.	Damages after the 1977 earthquake in structural elements	Repairing work after the 1977 earthquake	SD'	Designer	P100-earthquake capacity ratio Long. Trans.
14 Republicii 47		1934	-	9	23	2784	Columns : Light Masonry : Medium Beams : Light	-	29	-	0.178 0.36
15 Tiner Arghizi 26		1939	Yes	9	26	7627	Columns : Light Masonry : Medium Beams : Light Epoxy resins injections	-	29	-	0.1
16 Calea Victoriei 128A		1935	Yes	9	22	6675	Columns : Extreme Masonry : Medium Beams : Extreme Masonry Repairs	-	100	IPCT	0.15 0.12
17 Republicii 86		1939	-	9	18	3230	Columns : Extreme Masonry : Medium Beams : Extreme Masonry Repairs	-	4	-	0.17 0.18
18 Al Xemxpol 3		1940	-	9	19	4451	Columns : Extreme Masonry : Light Beams : Extreme Masonry Repairs	-	86	ICPMC	0.15 0.15
19 Rezzanana 6		1936	Yes	9	31	1686	Columns : Extreme Masonry : Medium Beams : Extreme Epoxy resins injections	-	-	-	0.11
20 Calea Victoriei 112		1939	Yes	9	27	5210	Columns : Extreme Masonry : Extreme Beams : Medium Light	-	56.5	-	0.11
21 Iuliu Barash 12		1936	-	7.5	16	1640	Columns : Extreme Masonry : Medium Beams : Light Epoxy resins injections	-	100	ICPIL	0.08 0.07
22 Ion Campineanu 22		1938	Yes	9	59	3929	Columns : Extreme Masonry : Light Beams : Extreme Epoxy resins injections	-	25	-	0.14 0.14
23 Speranței 24		1940	-	9	11	1600	Columns : Extreme Masonry : Medium Beams : Light	-	-	-	-
24 Stăniței Voilei 17		1936	Yes	9	58	6140	Columns : Extreme Masonry : Medium Beams : Light Epoxy resins injections	-	7	-	0.185 0.152
25 Dr. Mărcuței 9		1934	-	9	41	8783	Columns : Extreme Masonry : Medium Beams : Light Masonry Repairs	-	43	-	0.197 0.196
26 Griviței 13		1930	Yes	8.5	24	3683	Columns : Extreme Masonry : Medium Beams : Light Epoxy resins injections	-	11	-	0.155 0.155
27 Calea Victoriei 203		1940	Yes	8.5	44	5200	Columns : Extreme Masonry : Medium Beams : Light Epoxy resins injections	-	86	-	0.194 0.159
28 I. Michellet 1		1937	Yes	8.5	17	2165	Columns : Extreme Masonry : Medium Beams : Light Epoxy resins injections	-	86	IPCT	0.10 0.15
29 Kogălniceanu 97		1943	-	8	43	6120	Columns : Extreme Masonry : Medium Beams : Light Epoxy resins injections	-	77	-	0.20 0.05

No	Address	Year of building construction	Commercial occupancy of groundfloor	Stores No. of Apts.	Total area sum.	Damages after the 1977 earthquake in structural elements	Repairing work after the 1977 earthquake	SIJ'	Designer	P100- earthquake capacity ratio
30	Calea Victoriei 139	1934	Yes	8	30	1290 Columns : Light Beams : Light	Masonry Repairs	29	-	Long. Trusses, 0.135
31	J. I. Calderon 59	1935	-	9	19	3680 Columns : Medium Masonry : Medium	Light Masonry Repairs	-	-	0.15
32	Mihai Viteazu 42	1932	-	8	30	4232 Columns : Extreme Masonry : Extreme	Jacketing of columns Light Masonry Repairs	36	IPIU	0.07 0.14
33	Stimule 6	1935	Yes	8	32	5700 Columns : Extreme Masonry : Extreme	Jacketing of columns Light Masonry Repairs	85.5	-	0.15
34	Spiralul Familiei 5	1938	-	8	30	3160 Columns : Light Masonry : Light	Jacketing of columns Partially collapsed in 1977	105	-	0.17
35	Dionisie Lupu 53	1937	-	8	13	2461 Columns : Light Beams : Light	Jacketing of columns and beams Epoxy resin injections	21	-	0.16
36	Hristo Botev 3	1923	Yes	8	14	4625 Columns : Light Beams : Light	Masonry Repairs Epoxy resin injections	17.5	IPIB	0.2 0.2
37	Poenari Borda 12-14	1937	-	8	24	2831 Columns : Light Beams : Light	Jacketing of walls Light Masonry Repairs	25	-	0.114
38	Smechedin 18	1940	Yes	8	31	7273 Columns : Light Beams : Light	Masonry Repairs Finishes	25	-	0.105
39	Sirbet Voda 16	1934	Yes	8	23	4414 Columns : Light Beams : Light	Masonry Repairs Jacketing of columns	56.5	-	0.111
40	Iliescu 31B	1935	-	8	26	5596 Columns : Light Beams : Light	Jacketing of 6 columns Medium Masonry Repairs	28.5	-	0.108
41	Pecatu Barden 16	1936	-	8	30	3160 Columns : Extreme Masonry : Extreme	Jacketing of columns Light Masonry Repairs	64	-	0.22
42	Pracin 9	1938	-	8	17	1435 Columns : Light Masonry : Medium	* Partially consolidated in 1979	20	Tinsul Carpali	0.248
43	Lahovari 5A	1935	Yes	8	18	2955 Columns : Extreme Masonry : Extreme	Jacketing of columns Epoxy resin injections Mortar injections	100	IPIB	0.18

No	Address	Year of building construction	Commercial occupancy of ground floor	Storeys	No. of Apts.	Total area sqm.	Damages after the 1977 earthquake	Repairing work after the 1977 earthquake	SID*	Designer	"1000-earthquake capacity ratio - Long. Trans."
44 Ion Campineanu 9	1915	Yes	7.5	25	3141	3140	Columns : Masonry : Beams : Extreme	Masonry Repairs : Finishes	77	-	0.04
45 Nicolae Iorga 22	1939	-	7.5	31	3140	3140	Columns : Masonry : Beams : Extreme	Jacketing of columns and beams Masonry Repairs	79	IPCT	0.10
46 Elena Narcisoiu 5	1929	-	7.5	22	2914	2914	Columns : Masonry : Beams : Light Extreme	Jacketing of columns Masonry Repairs	21	ISLGC	0.154
47 J. Michelie 2-6	1940	Yes	7.5	12	1905	1905	Columns : Masonry : Beams : Light Extreme	Masonry Repairs : Finishes	43	-	0.159
48 Piata Mior 27	1936	-	7.5	26	2722	2722	Columns : Masonry : Beams : Medium	Epoxy resins injections Masonry Repairs	71	-	0.11
49 Piata Mior 29	1936	-	7.5	59	4639	4639	Columns : Masonry : Beams : Extreme	Jacketing of columns and beams	86	-	0.15
50 Aurel Vlaicu 39	1940	-	7	36	5041	5041	Columns : Masonry : Beams : Extreme	Jacketing of columns and beams	100	IPB, UTC B	0.11
51 Vasile Lascăr 18	1937	-	7	35	5041	5041	Columns : Masonry : Beams : Light Extreme	Jacketing of 2 columns Epoxy resins injections	21	IPB	0.1
52 Vasile Lascăr 26-28	1937	Yes	7	28	3080	3080	Columns : Masonry : Beams : Extreme	Masonry Repairs	86	ICRAI	0.095
53 Iuliu Maniu 9	1910	Yes	7	45	5116	5116	Columns : Masonry : Beams : Light	Masonry Repairs	77	IPCT	0.125
54 Sfatului I	1935	-	7	17	1870	1870	Columns : Masonry : Beams : Extreme	Jacketing of columns	14	-	0.23
55 Realiștul 5	1916	-	7	44	5259	5259	Columns : Masonry : Beams : Light	Masonry Repairs : Finishes	14	-	0.15
56 Mihai Eminescu 28	1938	Yes	7	10	1671	1671	Columns : Masonry : Beams : Light	Jacketing of columns	25	-	0.15
57 Stelca Spitalul 17	1937	-	7	53	4125	4125	Columns : Masonry : Beams : Extreme	Masonry Repairs	14	-	0.2
58 Tudor Arghezi 54	1924	Yes	7	19	2756	2756	Columns : Masonry : Beams : Medium	Jacketing of 4 columns and one beam	93	-	0.15
59 Mihai Voda 15	1914	Yes	7	15	1878	1878	Columns : Masonry : Beams : Extreme	*Partial consolidation in 1978	19	-	0.13
60 Filitti 6	1930	-	6.5	12	1690	1690	Columns : Masonry : Beams : Light	Finishes	28.5	-	0.2
											0.25

No	Address	Year of building construction	Commercial occupancy of ground floor	Storeys	No. of Apl. stories	Total area sqm.	Damages after the 1977 earthquake in structural elements	Repairing work after the 1977 earthquake	SD*	Designer	100-earthquake capacity ratio
61	Balecesu 25 (Wilson)	1928	Yes	12	93	12287	Columns : Extreme Beams : Extreme Masonry : Extreme Epoxy resin injections	Jacketing of columns and beams Masonry Repairs Epoxy resin injections, Mortar injections	105	IPB	0.16
62	Mesnilor 131	1934	Yes	6,5	29	1868	Columns : - Beams : - Masonry : Light	-	19	-	0.224
63	Republiechi 63	1937	Yes	6,5	16	1764	Columns : - Beams : - Masonry : Medium	Masonry Repairs	38	-	0.147
64	Ursulestului 5	1930	-	6,5	12	1615	Columns : - Beams : - Masonry : Medium	Masonry Repairs	76	-	0.09
65	Calea Victoriei 124	1930	Yes	6,5	28	3045	Columns : - Beams : - Masonry : Medium/Extreme	Masonry Repairs	37	-	0.10
66	Ostaszewski 4	1927	-	6	18	2832	Columns : - Beams : - Masonry : Medium	Masonry Repairs	38	-	0.15
67	Iuliu Maniu 52	1934	Yes	6,5	25	6070	Columns : Light Beams : Light	Masonry Repairs	2,5	-	0.043
68	Dionisie Lepu 55	1936	-	6,5	13	1410	Columns : - Beams : - Masonry : Medium	Masonry Repairs	38	-	0.10
69	A.I. Sahia 2	1910	Yes	6	22	3745	Columns : Light Beams : Light	Masonry Repairs	19	-	0.20
70	Histerica Vac 14	1936	Yes	6	29	2775	Columns : - Beams : - Masonry : Extreme	Jacketing Masonry Repairs Epoxy resin injections	100	ISPIE-M AIA	0.15
71	Blănarii 14	1935	Yes	6	40	2655	Columns : - Beams : - Masonry : Medium	-	38	-	0.25
72	Obor 2	1930	Yes	6	12	1320	Columns : - Beams : - Masonry : Medium	-	50	-	0.43
73	J.J. Calderon 61	1930	-	6	13	2404	Columns : - Beams : - Masonry : Medium	Epoxy resin injections	42	-	0.09
74	Iepureni 94	1930	Yes	6	16	2107	Columns : - Beams : - Masonry : Medium	Jacketing of columns and beams	50	-	-
75	Paleologu 3	1936	-	6	20	3414	Columns : - Beams : - Masonry : Medium	Masonry Repairs	100	-	0.132
76	Sălămașilor 12	1936	-	6,5	18	2396	Columns : - Beams : - Masonry : -	Masonry Repairs	0	-	0.16

78

No	Address	Year of building construction	Commercial occupancy of ground floor	Stories	No. of Apts.	Total area sqm.	Damages after the 1977 earthquake in structural elements	Repairing work after the 1977 earthquake	SD'	Designer	P100-earthquake capacity ratio Long. Trans.
77	Vulturilor 25	1935	-	6	20	2061	Columns : Medium Beams : Medium	Masonry Repairs : Medium Finishes : Medium	21	-	0.05
78	Bucsa 3	1932	-	6	25	2875	Columns : Medium Beams : -	-	38	-	0.1
79	Irenium 38	1934	-	6	7	1600	Columns : Light Beams : -	Masonry Repairs : Medium Finishes : -	18	-	0.1
80	Sapientei 1	1930	Yes	6	22	2189	Columns : Light Beams : Light	Masonry Repairs : Medium Epoxy resins injections : -	21	-	0.107
81	Vasatori 1	1938	-	6	8	918	Columns : Light Beams : Light	Masonry Repairs : Medium Epoxy resins injections : -	25	-	0.110
82	Grivitei 107-109	1934	Yes	6	44	5200	Columns : Light Beams : -	-	0	IPB	0.185 (A) 0.3 (B)
83	Nicolae Iorga 31	1936	-	6	19	1720	Columns : Light/ Medium Masonry Repairs : Medium Beams : Light/ Medium Epoxy resins injections : -	Jacketing of 2 columns and one beam	29	IPSCAIA	0.10
84	(Ch. Manolescu 3	1940	-	7	20	1750	Columns : Extreme Beams : Extreme	Jacketing of walls/ Masonry Repairs : Medium	100	-	0.11
85	Mesilor 42	1930	Yes	5.5	4	442	Columns : Medium Beams : Medium	Masonry Repairs : Light	19	-	0.465
86	C.A. Rosetti 25	1933	Yes	9	36	7000	Columns : Medium Beams : Medium	Masonry Repairs : Medium	43	-	0.05
87	Luchian 12	1933	Yes	5.5	8	1409	Columns : Medium Beams : Medium	Masonry Repairs : Light	19	-	0.12
88	SV Vinici 5	1933	-	5.5	17	1299	Columns : Medium Beams : Medium	Epoxy resins injections : -	7	-	0.1
89	Hellerie 11	1936	-	5.5	10	1295	Columns : Medium Beams : Medium	Epoxy resins injections : -	25	-	0.1
90	Riserien Anzel 8	1935	-	5.5	20	2081	Columns : Light Beams : Light	Epoxy resins injections : -	25	-	0.26
91	Calea Victoriei 25	1936	Yes	13	49	6078	Columns : Extreme Beams : Extreme	Jacketing of 6 columns Epoxy resins injections : -	100	TCI	0.36
92	Calea Victoriei 95	1938	Yes	10.5	51	4010	Columns : Extreme Beams : Extreme	Jacketing of columns and beams Epoxy resins injections : -	100	IPCT	0.14

No	Address	Year of building construction	Commercial occupancy of ground floor	Storeys	No. of API.	Total area sqm.	Damages after the 1977 earthquake in structure elements	Repairing work after the 1977 earthquake	SD'	Designer	P100-earthquake capacity ratio
93	Galeșeu Nicolae 5	1938	Yes	10	21	1766	Columns : Medium Beams : Light/ Medium	-	42,5	IPB	Long. Trans. 0,142 0,232
94	Bucium 32-34	1935	Yes	10	41	6996	Columns : Light/ Medium Masonry : -	Masonry Repairs	-	-	0,17 0,202
95	Bălcescu 30	1936	Yes	9,5	25	2156	Columns : Extreme Beams : Medium	Masonry Repairs	42,5	-	-
96	Mihai Eminescu 17	1937	Yes	8,5	40	6063	Columns : Medium Beams : Light/ Medium	Epoxy resins injections	64	-	0,16 0,13
97	Kogălniceanu 43	1937	-	8	16	1740	Columns : Light/ Medium Beams : Light	Masonry Repairs	25	IPROMI T	0,2 0,2
98	Kogălniceanu 49	1938	-	8	83	13670	Columns : Light/ Medium Beams : Light	Jacketing of columns Epoxy resins injections	-	-	-
99	Irălanu 5	1936	Yes	7,5	24	2050	Columns : Light/ Medium Beams : Light	Jacketing of columns and beams	36	-	0,29 0,49
100	Nicolae Bălcescu 7	1933	Yes	7	15	2730	Columns : Light/ Medium Beams : Light	Jacketing of columns and beams	25	-	0,31 0,48
101	Mosilei 96	1900	Yes	6,5	11	2114	Columns : Light/ Medium Beams : Light/ Medium	Epoxy resins injections	50	-	0,08 0,09
102	Iachim 3	1936	-	6,5	9	2067	Columns : Medium/ Extreme Beams : Light	Masonry Repairs	36	IPB-1978	0,196 0,111
103	George Enescu 21	1932	-	6,5	12	1331	Columns : Medium/ Extreme Beams : Light	Masonry Repairs	28,5	-	0,13 0,13
104	Calea Victoriei 33-35	1930	Yes	6,5	39	4800	Columns : Medium/ Medium Beams : Medium	Jacketing of columns Masonry Repairs	70,5	-	0,08 0,08
105	Chimie 18	1936	-	6	13	2073	Columns : Light/ Medium Beams : Light	Masonry Repairs	21	-	0,117 0,105
106	Lascăr Catargiu 15A	1934	-	6	17	2351	Columns : Medium/ Medium Beams : Medium	Jacketing of columns Masonry : Extreme	50	-	0,24 0,24
107	Mendelsohn 17	1935	Yes	7	47	7022	Columns : Light/ Medium Beams : Light	Masonry : -	21	ICRAL Internau	0,08-0,19 0,08-0,19

No	Address	Year of building construction	Commercial occupancy of groundfloor	Storeys	No. of Apt.	Total area sqm.	Damages after the 1977 earthquake in structural elements	Repairing work after the 1977 earthquake	SD*	Designer	P100-earthquake capacity ratio I-long.
108	Semilucei 8	1935	-	6	6	1300	Columns : Medium Beams : Light	Jacketing of columns	42.5	-	0.14
109	Armenescu 28	1935	-	6	6	1280	Masonry : - Columns : Medium Beams : Light	Jacketing of columns	36	-	0.14
110	Armenescu 28 A	1935	-	6	8	1971	Columns : Medium Beams : Light	Jacketing of columns	36	-	0.17
111	Arcuhi 4 *	1932	-	6	8	1971	Columns : Extreme Beams : - Masonry : -	Jacketing of columns	57	-	0.13
112	Iuliu Maniu 22 *	1875	-	8	26	-	-	-	-	-	0.21
113	Loudia 16-20 *	1924	-	4,5	3	-	-	-	-	-	-
114	Magheru 12-14 *	1929	Yes	5,5	104	-	-	-	-	-	-
115	Carol 151 *	1929	-	9	30	-	-	-	-	-	-


\* Information to be added

A damage score for the fragile building structures from the list of 115 buildings in Bucharest was computed with a simplified version of the damage methodology proposed by Gulkan (1994). Middle East Technical University, Ankara, Turkey.


SD varies from 0 to 100. The damage vulnerability classes can be selected based on SD score.

**Project implementing organization structure**

Annex 7-11-4



.Chart of organizational structure for Project management



Annex 7-11-6

INCERC's facilities concerning the Project and their current conditions

**FACILITIES WHICH ARE IN OPERATION(SEISMIC TESTING HALL)**

No	Name of equipment	Amount (number of pieces)	Specification (technical characteristics )	Condition -working -maintenance	Remarks
1.	The large capacity reaction wall	1	testing area: 24x24 meters height of the wall: 12 meters max. horizontal loads: 40-50 mN max. overturning moment: 200-250 mNm	needs: -a great variety of servo-actuators -equipment for the pumping station -load cells -strain gauges	Wall is in operation. Equipment to be upgraded.
2.	Loading devices, hydraulic jacks, pumping unit, mechanical devices data acquisition facilities				Devices and facilities to be upgraded.

**FACILITIES IN STRUCTURAL TESTING LABORATORY OF INCERC BUCHAREST**

**FACILITIES WHICH ARE NOT IN OPERATION(SEISMIC TESTING HALL)**

No.	Name of equipment	Amount (number of pieces)	Specification (technical characteristics in the project of facilities)	Condition -working -maintenance	Remarks
3.	The small shaking table	1	plan dimensions: 3x3 meters shaking table mass: 12 tones max. model mass: 5 tones horizontal displacement: ± 150 mm vertical displacement: ± 50 mm horizontal velocity: 1,2 m/sec vertical velocity: 0,6 m/sec horizontal acceleration: 38 m/sec <sup>2</sup> bandwidth: 0.2- 40 hz	Needs: -8 horizontal and 4 vertical actuators -equipment for the pumping station and adequate oil lines for the hydraulic network -safe systems -automated control systems	It is not in operation.
4.	The large shaking table	1	plan dimensions: 6x6 meters shaking table mass: 55 tones max. model mass: 60 tones horizontal displacement: ± 150 mm vertical displacement: ± 50 mm horizontal velocity: 1,2 m/sec vertical velocity: 0,6 m/sec horizontal acceleration: 24 m/sec <sup>2</sup> bandwidth: 0.5- 35 hz	Needs: -8 horizontal and 4 vertical actuators -equipment for the pumping station and adequate oil lines for the hydraulic network -safe systems -automated control systems	It is not in operation. It was never finished.

Annex 7-11-7

List of Participants of the PCM Workshop (discussed by two groups)

Group A

Prof. D. Lungu (General Director, INCERC)  
Mr. C. Stamatiade (Vice Director, Tech. Direction for Construction, MLPTL)  
Mr. T. Cornea (IPCT S.A.)  
Mr. C. Arion (UTCB)  
Dr. D. Capatana (General Director, IPCT S.A.)  
Mr. D. Badea (Technical Director, PROJECT Bucharest)  
Mr. C. Balan (IPCT S.A.)

Group B

Mr. I. Stanescu (General Director, MLPTL)  
Dr. D. Georgescu (Scientific Director, INCERC)  
Dr. S. Demetriu (UTCB)  
Dr. R. Vacareanu (UTCB)  
Mr. A. Aldea (UTCB)  
Mr. C. Balan (IPCT)  
Prof. Radu Petrovici (Univ. of Architecture, Bucharest)  
Mr. M. Mironescu (Miro Group)  
Dr. E.S. Georgescu (Head of Seismic Risk Assessment and Disaster Precaution Laboratory, INCERC)

Notice: INCERC: National Institute for Building Research, MLPTL: Ministry of Public Works, Transports and Housing, IPCT S.A.: (Private Design Company). UTCB: Technical University of Civil Engineering, Bucharest, PROJECT Bucharest (Private Design Company)

**Tentative Staff List Categorized by Output and Activity of PDM**

**Output 1 (Leader: Vacareanu, R. Assoc. prof. dr.) (UTCB, D1, PT)**

1.1	Prof. Dr. Lungu (INCERC, PM, FT) Postelnicu, T., Prof. dr. (UTCB, D1, PT) Călinițiu (D1, PT)	Cornea, T. (UTCB, D1, FT) Badea, D. (Proiect București, D1, PT)	Găbă, M., Prof. dr. (UTCB, D1, PT) Stănescu, I., (MLPTL, D1, PT)	Pavel, C., prof. dr. (UTCB, D1, PT) Mironescu, M. (D1, PT)
1.2	Prof. Dr. Lungu (INCERC, IJM, FT) Postelnicu, T., Prof. dr. (UTCB, D1, PT) Tomoiță, Gh., (MLPTL, D4, PT)	Cornea, T. (UTCB, D1, PT) Badea, D. (Proiect București, D1, PT) Mironescu, M. (D1, PT)	Găbă, M., Prof. dr. (UTCB, D1, PT) Stănescu, C., (MLPTL, D4, PT)	Pavel, C., prof. dr. (UTCB, D1, PT) Stanescu, T., (MLPTL, D1, PT)
1.3	Arioiu, C. (UTCB, D2, FT) Iancovici, M., Asis. prof. (UTCB, D3, PT) Vacareanu, R. Assoc. prof. dr. (UTCB, D1, PT)	Cornea, T. (UTCB, D1, PT) Pavel, C., prof. dr. (UTCB, D1, PT)	Cristea, Gh., Prof. dr. (UTCB, D4, PT) Popa, V., asist. prof. (UTCB, D3, PT)	Găbă, M., Prof. dr. (UTCB, D1, PT) Postelnicu, T., Prof. dr. (UTCB, D1, PT)
1.4	Cornel, T. (UTCB, D1, FT) Vacareanu, R. Assoc. prof. dr. (UTCB, D1, PT) Stănescu, I., (MLPTL, D1, PT)	Chiriac, C. (INCERC, D1, FT) Mironescu, M. (D1, PT)	Felix, O. (INCERC, D2, FT) Căpățina (D1, PT)	Georgescu, D., Dr. (INCERC, D3, PT)
1.5	Găbă, M., Prof. dr. (UTCB, D1, PT) Stănescu, I., (MLPTL, D1, PT)	Găbă, M., Prof. dr. (UTCB, D1, PT) Georgescu, D., Dr. (INCERC, D3, PT)	Pavel, C., prof. dr. (UTCB, D1, PT) Bădeu, D. (Proiect București, D1, PT)	Postelnicu, T., Prof. dr. (UTCB, D1, PT)
		Mironescu, M. (D1, PT)	Căpățina (D1, PT)	Stanescu, C., (MLPTL, D4, PT)
		Iancovici, M., Asis. prof. (UTCB, D3, PT)	Pavel, C., prof. dr. (UTCB, D1, PT) Georgescu, E.S., Dr. (INCERC, D4, PT)	Postelnicu, T., Prof. dr. (UTCB, D1, PT)
		Tomașă, Gh., (MLPTL, D4, PT)		

\* Number 1.1-1.5 indicates Activity number of PDM.

**Output 2 (Leader: Pavel, C. prof. dr.) (UTCB, D1, PT)**

2.1	Prof. Dr. Lungu (INCERC, PM, FT) Pavel, C., prof. dr. (UTCB, D1, PT) 1 electronic engineer (FT)	Călinițiu, D., Asist. prof. (UTCB, D3, PT) Popa, V., asist. prof. (UTCB, D3, PT)	Găbă, M., Prof. dr. (UTCB, D1, PT) Vacareanu, R. Asist. prof. (UTCB, D1, PT)	Iancovici, M., Asis. prof. (UTCB, D3, PT) 2 technicians (FT)
2.2	Călinițiu, D., Asist. prof. (UTCB, D3, PT) Popa, V., asist. prof. (UTCB, D3, PT)	Găbă, M., Prof. dr. (UTCB, D1, PT)	Iancovici, M., Asis. prof. (UTCB, D1, PT)	Pavel, C., prof. dr. (UTCB, D1, PT)
2.3	Alecu, A., Lecturer (UTCB, D3, PT) Iancovici, M., Asis. prof. (UTCB, D3, PT)	Vacareanu, R. Asist. prof. dr. (UTCB, D1, PT) Chiriac, C. (INCERC, D1, FT)	Călinițiu, D., Asist. prof. (UTCB, D1, PT)	I electronic engineer (FT)

D1,PT)	Crainic, L., prof.dr.(UTCIB, D1,PT)	Chesaru, E., prof.dr.(UTCIB, D1,PT)	Borcia, C., (INCERC, D2,PT)	Sandu, C., (INCERC, D2,PT)
2.4	Arian, C., (UTCIB, D2,PT) 1 or 2 geophysicists (FT)	2 technicians (FT)	Arian, C., (UTCIB, D2,FT) (INCERC,D3,PT)	1 electronic engineer (FT)
2.5	Aldea, A., Lecturer(UTCIB, D3,PT)		Arian, C., (UTCIB, D2,FT) (INCERC,D3,PT)	Demetru, S., Assoc.prof. (UTCIB,D2,PT)
2.6	Borcia, C., (INCERC,D2,PT) Arian, C., (UTCIB, D2,FT) 1 electronic engineer(FT)	Bucatariu, R., (INCERC,D3,PT)	Sandu, C., (INCERC, D2,PT)	1 or 2 geophysicists (FT)
2.7	Aldea, A., Lecturer(UTCIB, D3,PT)	Arian, C., (UTCIB, D2,FT)	Bucatariu, R., (INCERC,D3,PT)	1 or 2 geophysicists (FT)
2.8	Aldea, A., Lecturer(UTCIB, D3,PT)	Arian, C., (UTCIB, D2,FT) Sandu, C., (INCERC, D2,PT)	Bucatariu, R., (INCERC,D3,PT)	1 or 2 geophysicists (FT)
2.9	Aldea, A., Lecturer(UTCIB, D3,PT)	Arian, C., (UTCIB, D2,FT)	Demetru, S., Assoc.prof. (UTCIB,D2,PT)	Demetru, S., Assoc.prof. (UTCIB,D2,PT)
2.10	Sandu, C., (INCERC, D2,PT) Prof. D. Lungu(INCERC, PIM, FT)	Aldea, A., Lecturer(UTCIB, D3,PT) (INCERC,D2,PT)	Arian, C., (UTCIB, D2,FT)	Borcia, C., (INCERC, D2,PT)
2.11	Vacareanu,R.,Assoc.prof.dr.(UTCIB, D1,PT)	Berica, C., (INCERC,D2,PT)	Berica, C., (UTCIB, D2,FT)	Cornea, T., (UTCIB, D1,PT)
2.12	Prof. D. Lungu(INCERC, PIM, FT)	Arian, A., Lecturer(UTCIB, D3,PT) (INCERC,D2,PT)	Pavel,C.,prof.dr.(UTCIB,D1,PT)	Pavel,C.,prof.dr.(UTCIB,D1,PT)
	Vacareanu,R.,Assoc.prof.dr.(UTCIB, D1,PT)	Boreia, C., (INCERC,D2,PT)	Stanescu, I., (MLPTL,D1,PT)	Postelnicu, T., Prof. dr. (UTCIB, D1,PT)
	Cristea, Gh., Prof. dr. (UTCIB, D4,PT)			Stamatiade, C. (MLPTL,D4,PT)
	Prof. D. Lungu(INCERC, PIM, FT)	Aldea, A., Lecturer(UTCIB, D3,PT)		
	Demetru, S.,Assoc.prof. (UTCIB,D2,PT)			
	Vacareanu,R.,Assoc.prof.dr.(UTCIB, D1,PT)	Gabor, M., Prof. dr. (UTCIB, D1,PT) Georgescu,D.,Dr. (INCERC, D3,PT)	Pavel,C.,prof.dr.(UTCIB,D1,PT)	Postelnicu, T., Prof. dr. (UTCIB, D1,PT)
	Stanescu, I., (MLPTL,D1,PT)	Georgescu,E.S.,Dr. (INCERC,D4,PT)	Georgescu,E.S.,Dr. (INCERC,D4,PT)	Radea,D.(ProjectBucuresti,D1,PT)

\*Number 2.1-2.12 indicates Activity number of PDM.

Output 3(Leader: Georgescu, D., Dr. (INCERC, D3,PT))

3.1	Cristea, Gh., Prof. dr.(UTCIB,D1,PT) Georgescu,D.,Dr. (INCERC, D3,PT)	Postelnicu,T.,Prof. dr. (UTCIB, D1,PT)	Chiriaci, C. (INCERC, D1,PT)	Felix, O. (INCERC, D2,PT)
	Georgescu,E.S.,Dr (INCERC,D4,PT)		Radea,D.(ProjectBucuresti,D1,PT)	

3.2	Crisan, Ch., Prof. dr. (UTCBr, D4,PT)	Gaher, M., Prof. dr. (UTCBr, D1,PT)	Pavel, C., prof.dr.(UTCBr,D1,PT)	Poitecneiu, T., Prof. dr. (UTCBr, D1,PT)
	Chiriaci, C. (INCERC, D1,FT) Baciu, D.,ProjectBucharest, D1,PT)	Felix,O (INCERC, D2,FT)	Georgescu,D.,Dr. (INCERC, D3,PT)	Georgescu, E.S., Dr. (INCERC,D4,PT)
3.3	Prof. D. Lungu@INCERC, P/M, FT) Pascu,Nicu,T.,Prof.dr.,(UTCBr, D1,PT)	Crisan, Gh., Prof. dr. (UTCBr, D4,PT) Georgescu, D., Dr. (INCERC, D3,PT)	Gaher, M., Prof. dr. (UTCBr, D1,PT)	Iancovici, M., Asis. prof. (UTCBr, D3,PT)

\* Number 3.1-3.3 indicates Activity number of PDM.

#### Output 4(I.leader: Georgescu, E.S., Dr.)(INCERC, D4,PT)

4.1	Popa, V., assit.prof. (UTCBr, D3,PT) Stamatiade, C. (MLPTL,D4,PT)	Felix, O (INCERC, D2,FT)	Georgescu,E.,S.,Dr. (INCERC,D4,PT)
4.2	Prof. D. Lungu@INCERC, P/M, FT) Stamatiade, C., (MLPTL,D4,PT)	Popa, V., assit.prof. (UTCBr, D3,PT) Tomodaia, Gh., (MLPTL,D4,PT)	Georgescu, E.S., Dr. (INCERC,D4,PT)
4.3	Prof. D. Lungu@INCERC, P/M, FT) Stamatiade, C. (MLPTL,D4,PT)	Popa, V., assit.prof. (UTCBr,D3,PT)	Georgescu, E.S., Dr. (INCERC,D4,PT)

\* Number 4.1-4.3 indicates Activity number of PDM.

\*\*FT: Full time PT: Part time, D1-4: Division1-4, P/M: Project Manager