

**THE FOLLOW-UP STUDY  
ON  
THE REHABILITATION OF  
HYDROPOWER STATIONS IN THE  
KELANI RIVER BASIN  
FOR  
HYDROPOWER OPTIMIZATION  
IN  
SRI LANKA**

**FINAL REPORT  
Vol. II  
APPENDIX**

**JULY 2005**

**JAPAN INTERNATIONAL COOPERATION AGENCY  
ECONOMIC DEVELOPMENT DEPARTMENT**

**ED**

**JR**

**05 - 055**

# **Appendix**

## **Contents**

- A MAINTENANCE AND INSPECTION MANUAL FOR CIVIL STRUCTURE**
  - A-1 GEOLOGICAL INVESTIGATIONS
  - A-2 INSPECTION REPORT ON HEADRACE TUNNEL OF WIMALASURENDRA HYDROPOWER PLANT
  - A-3 INSPECTION MANUAL FOR HYDROPOWER PLANT CIVIL VERSION
  
- B MAINTENANCE AND INSPECTION MANUAL FOR HYDROMECHANICAL EQUIPMENT**
  - B-1 MAINTENANCE OF HYDROMECHANICAL WORKS
  - B-2 INSPECTION MANUAL FOR HYDROMECHANICAL WORKS
  - B-3 DETERIORATION MONITORING MANUAL FOR HYDROMECHANICAL WORKS
  - B-4 REPAINTING MANUAL FOR HYDROMECHANICAL WORKS
  
- C MAINTENANCE AND INSPECTION MANUAL ELECTRO-MACHINE EQUIPMENT**
  - C-1 SIMPLIFIED EFFICIENCY TEST USING A PORTABLE ULTRASONIC FLOW METER
  - C-2 STUDIES ON THE UNIT SPECIFICATIONS AND EFFICIENCY IMPROVEMENTS
  - C-3 CONTROL / PROTECTION EQUIPMENT LIST OF CONTROL ROOM LAYOUT (with Picture )
  - C-4 CEB's CHECK LIST FOR CANYON HYDROPOWER STATION
  - C-5 INSPECTION ITEMS AND EXAMPLE OF MAINTENANCE MANUAL FOR ELECTRO-MECHANICAL EQUIPMENT

*APPENDIX A*  
*MAINTENANCE AND INSPECTION MANUAL*  
*FOR CIVIL STRUCTURE*

***APPENDIX A-1***  
***GEOLOGICAL INVESTIGATIONS***

# 1. ASSUMED GEOLOGICAL PROBLEMS AND ADDITIONAL INVESTIGATIONS

The problems to be studied in terms of geology are as follows.

- Assumed collapse of tunnel walls at Wimalasurendra Power Station
- Water leakage and slope instability around the surge tank of New Laxapana Power Station
- Slope instability around Polpitiya Power Station
- Instability of the slope behind Polpitiya Power Station

To study the above assumed problems, the additional investigations shown in Table 1.1 was carried out from October, 2004 to March, 2005.

**Table 1.1 Additional Investigations**

Name of Power Station	Structure	Inferred geological problem	Inspection of tunnel inside	Topographic survey	Geological mapping	Water quality test	Mesurement of discharge volume
Wimalasurendra	Headrace Tunnel	collapse	yes			1set	
New Lavapana	Surge Tank and surroundings	leakage and slope stability		20ha	20ha	1set	1set
Polpitiya	Intake and surroundings	slope stability		6ha	6ha		
	Slope behind Power Station	slope stability		10ha	10ha		

## 2. THE HEADRACE TUNNEL OF WIMALASURENDRA POWER STATION

Some problems such as collapsing walls had been a concern in the headrace tunnel of Wimalasurendra because mad water was observed at the outlet of the power station. Accordingly, the Study Team conducted the investigation with CEB, when the headrace tunnel was dewatered at the end of February 2005.

Consequently, only several small wall collapses were detected. However, there are no serious damages caused by geologically weak zones.

The small collapses have been repaired by CEB during the dewatering period.

## 3. AROUND THE SURGE TANK OF NEW LAXAPANA POWER STATION

### 3.1 General

There are many water springs on the slopes around the surge tank of New Laxapana Power Station. The history of these springs is as follows.

- There were small springs on the slope above the tarred road away from the valve house.
- It is reported that with the excavation of the tunnel, the springs on the valve house slope had dried up.

- They reappeared only a few years after filling the tunnel. Since then, there has been an increase in the number of springs.
- After slow dewatering of the Head race tunnel in Feb-March 1998, the springs on the slope area around the valve house dried up, and reappeared a few hours after the start of tunnel filling.
- At present, seepage water from a cluster of springs by the roadside is routed through pipes for domestic use by the villagers living on the lower slopes.

The above information clearly indicates that the water of the springs around the surge tank are from the waterway of the New Laxapana Power Station.

To study the effect of the springs on slope stability, a topographical survey, geological mapping, water quality test and measurement of discharge of small streams were carried out.

### **3.2 Topography and Geology**


The slopes around the surge tank incline west at an average of 30 degrees. Limited outcrops are observed along the cliffs extending in the NE-SW direction. The surge tank is upslope of the cliffs and the penstocks lie on the gentle slope of less than 15 degrees below them. A paved road traverses at the elevation around 860 m, just below the valve house of the penstock, where completely weathered or moderately weathered rock could be seen on the road cut.

Geological mapping around the surge tank was carried out in January and February, 2005, and provided the geological map of Figure 3.1.

Bedrock is composed of charnockitic gneiss, charnockite and quartzite. The dip angle of foliation of bed rock varies from 30 – 50 degrees which is about the same or steeper than the slopes. The dip direction of foliation falls in a narrow band from 220 – 250 degrees which are somewhat oblique to the downslope direction.

Overburden material was divided into ten categories as shown in Table 3.1, based on the type of material and nature of surface conditions.

Within the mapped area some manmade fill also can be seen. This fill is made of the rock material that came from the excavation of tunnel and adits of the New Laxapana hydropower project. Estimated age of occurrence of slips forming debris material is tabulated in that table.




**LEGEND**

- BEDROCK**
- Gn GNESIC ROCK. (UNDIFFERENTIATED, MAINLY CHARNOKITE GNSS.)
  - Qz QUARTZITE.
- OVERBURDEN**
- RS RESIDUAL SOIL  
REDDISH BROWN CLAYEY SANDS & SANDY CLAYS WITH GRAVEL THICKNESS 0.5-2m.  
WHERE SOIL LAYER IS THINER THAN UNDER LYING BEDROCK OUTCROPS  
AT PLACES LARGE ANGULAR BLOCKS OF (UP TO 7m)  
SLIGHTLY RECOMPOSED GNESIC BEDROCK APPEAR ON SURFACE.
  - RS1 AREA COVERED WITH OLD LAND SLIDE DEBRIS.  
MATERIAL CONSISTS OF YELLOWISH TO REDDISH BROWN CLAYEY SAND WITH GRAVEL.  
1-2cm ANGULAR TO SUB-ANGLED BOULDERS ARE EMBEDDED IN SOIL MATRIX.  
AMOUNT OF BOULDERS VARIES.
  - RS3 AREA COVERED WITH SECONDARY LANDSLIDE DEBRIS.  
MATERIAL IS MADE OF YELLOWISH TO REDDISH BROWN CLAYEY SAND AND  
SANDY CLAYS MIXED WITH BOULDERS PRELIMINARILY OF SIZES LESS THAN 1m.
  - RS4 VARY LARGE ROCK SLIP DEBRIS.  
MATERIAL PRELIMINARILY IS MADE UP OF EXTRA LARGE ANGULAR BOULDERS OF FRESH GNESIC ROCK.  
(SOME BLOCKS EXCEED 20m).
  - BL BOULDERS LYING ON THE STREAM BED.  
MATERIAL CONSISTS OF SUB-ANGULAR TO SUB-ROUNDED BOULDERS OF GNESIC ROCKS.  
THEIR RANGE FROM 0.5-4m.
  - BL2 YELLOWISH TO REDDISH BROWN SANDY CLAY WITH EMBEDDED BOULDERS. (1-2m.)
  - TL TALUS  
ROCK MATERIAL DERIVED FROM ROCKY CLIFF FACE.  
MATERIAL IS MADE UP OF BOULDERS OF SIZE OF 0.5-1.5m.  
SOIL FRACTION MADE UP MAINLY OF CLAYEY GRAVEL MATERIAL ABOUT 20/-30/.

- Ma MARSY AREA COVERED WITH THIN CLAY LAYER.  
BROWN SILTY PLASTIC CLAY CONTAINS SOME GRAVEL THICKNESS 0.2-0.3m. (UNDERLAIN BY EARTH SLIP DEBRIS.)
- Db SMALL ACTIVE SECONDARY SLIDES IN DEBRIS MATERIAL.
- Mu MAIN MADE UP OF ROCK  
MATERIAL EXCAVATED FROM TUNNEL & PENSTOCK ADIT.  
SIZE OF ROCK FRAGMENTS 0.1-0.5m, MAINLY GNESIC ROCK AND SOME CRYSTALLINE LIMESTONE.
- Boundary between rock types or categories of overburden.
- C TOP OF SCARP FACE FORMED BY EXPOSED BEDROCK.
- C LANDSLIDE SCAR.
- TENSION CRACK ON SOIL.
- o SPRING.
- o DIRECTION OF FOLIATION
- o SCARP OF FOLIATION
- o FOLIATION OF BEDROCK.
- X FOLIATION JOINT.
- X JOINT.

Figure 3.1 Geo Map (New Laxapana - 1)

JICA STUDY TEAM (ELECTRIC POWER DEVELOPMENT CO., LTD.) INVESTIGATION WORKS FOR THE FOLLOW-UP STUDY ON HYDROPOWER STATIONS IN THE KELANI RIVER BASIN FOR HYDROPOWER OPTIMIZATION - IN SRI LANKA GEOLOGICAL MAP NEW LAXAPANA SURGE SHAFT AND SURROUNDING AREA (SHEET 01 OF 02)			
DESIGNER: .....	DRAWN: .....	RECOMMENDED: .....	APPROVED: TOH (MS)
GENERAL ENGINEERING CONSULTANCY BUREAU, 415, BANGALORE AVENUE, COLOMBO 7 - SRI LANKA.		SCALE: 1:500	DATE: FEBRUARY 2005
		DRG. No. 647/IN/03/01	REV.



**LEGEND**

**BEDROCK**

- Gn** GNEISSIC ROCK. (UNDIFFERENTIATED, MAINLY CHARNOKITIC GNEISS.)
  - Qz** QUARTZITE.
- OVERBURDEN**
- RS** RESIDUAL SOIL. REDDISH BROWN CLAYEY SANDS & SANDY CLAYS WITH GRAVEL. THICKNESS 0.5-2m. WHERE SOIL LAYER IS THIN UNDER LYING BEDROCK DAYLIGHTS. AT PLACES LARGE AND BLOCKS OF UP TO 7m. SLIGHTLY DECOMPOSED GNEISSIC BEDROCK APPEAR ON SURFACE.
  - RS'** AREA COVERED WITH OLD LAND SLIDE DEBRIS. MATERIAL CONSISTS OF YELLOWISH TO REDDISH BROWN CLAYEY SAND WITH GRAVEL. 1-2m. ANGULAR TO SUB-ROUNDED BOULDERS ARE EMBEDDED IN SOIL MATRIX. AMOUNT OF BOULDERS VARY.
  - RS3** AREA COVERED WITH SECONDARY LANDSLIDE DEBRIS. MATERIAL IS MADE OF YELLOWISH TO REDDISH BROWN CLAYEY SAND AND SANDY SILTS MIXED WITH BOULDERS PREDOMINANTLY OF SIZES LESS THAN 1m.
  - RS4** VARY LARGE ROCK SLIP DEBRIS. MATERIAL PREDOMINANTLY MADE UP OF EXTRA LARGE ANGULAR BOULDERS OF FRESH GNEISSIC ROCK. (SOME BLOCKS EXCEED 20m).
  - BL** BOULDERS LYING ON THE STREAM BEDS. MATERIAL IS MADE UP OF BOULDERS OF SIZE OF 0.5-1.5m. THEIR RANGE FROM 0.5-4m.
  - BL2** YELLOWISH TO REDDISH BROWN SANDY CLAY WITH EMBEDDED BOULDERS. (1-2m).
  - TL** TALUS. ROCK MATERIAL DERIVED FROM ROCKY CLIFF FACE. MATERIAL IS MADE UP OF BOULDERS OF SIZE OF 0.5-1.5m. SOIL FRACTION MADE UP MAINLY OF CLAYEY GRAVEL MATERIAL ABOUT 20-30%.

- M** MAREY AREA COVERED WITH THIN CLAY LAYER. BROWN SILTY PLASTIC CLAY CONTAINS SOME GRAVEL. THICKNESS 0.2-0.3m. (UNDERLAIN BY EARTH SLIP DEBRIS.)
- Db** SMALL ACTIVE SECONDARY SLIDES IN DEBRIS MATERIAL.
- Mu** MUD - MADE FILL. MADE UP OF THE ROCK MATERIAL EXCAVATED FROM TUNNEL & DEVSTOCK ADIT. SIZE OF ROCK FRAGMENTS 0.1-0.2m. MAINLY GNEISSIC ROCK AND SOME CRYSTALLINE LIMESTONE.
- BOUNDARY BETWEEN ROCK TYPES OR CATEGORIES OF OVERBURDEN.
- TOP OF SCARP FACE FORMED BY EXPOSED BEDROCK.
- LANDSLIDE SCARP.
- TENSION CRACK ON SOIL.
- SPRING.
- DIRECTION OF FOLIATION.
- FOLIATION OF BEDROCK.
- FOLIATION JOINT.
- JOINT.

Figure 3.2 Geo Map (New Laxapana - 2)

JCA STUDY TEAM J. S. Perera (ELECTRIC POWER DEVELOPMENT CO., LTD) INVESTIGATION WORKS FOR THE FOLLOW-UP STUDY ON HYDROPOWER STATIONS IN THE KELANI RIVER BASIN FOR HYDROPOWER OPTIMIZATION IN SRI LANKA GEOLOGICAL MAP NEW LAXAPANA SURGE SHAFT AND SURROUNDING AREA (SHEET 02 OF 02)			
DATE: .....	DWG: .....	RECOMMENDED	APPROVED DGM (M)
BY: .....	SUB: .....	DATE: FEBRUARY 2005	AO
CENTRAL ENGINEERING CONSULTANCY BUREAU		SCALE: 1:500	DRG. No. 647/IN/03/02
115, BACHCHALOMA, MABANTALA, COLOMBO 7 - SRI LANKA.			REV.



**Table 3.1 Details of Formations of Overburden**

Type of Formation	Average Thickness (m)	Interpreted Age of Last Event (yrs.)	Ground Stability
RS	1-20	In situ material	Stable
RS'	5-10	More than 75	Stable
RS4	10-15	More than 75	Stable
BL2	1-5	More than 50	Unstable
TL	2-6	After RS2	Unstable
RS3	5-7	1944	Unstable
MU	2-5	About 35	Stable
MS	<1	5-8	Unstable
Db	2-5	1-5	Unstable
BL	1-3	1-5	Unstable

### 3.3 Springs

Eleven springs were found on the slopes around the surge tank. They are shown in Table 3.2. Many of them are springing through joints of the bed rock. Their total discharge is 730 L/min, and the largest is 150 L/min. The discharge of the stream that gathers spring waters, measured by V notches, was about 240 L/sec (14400 L/min). The poor discharge of other streams indicate that most of the stream water is leaked from the waterway. The amount of leakage from the waterway is much larger than that measured at the springs.

**Table 3.2 Location and Nature of Springs**

Location of Spring	Outflow L/min	Formation /Nature of Spring	Behavior with time (Monitoring Period 2 months: August –Sep 2005)
A	50	Clear water, through open joint in Gneissic rock	Continuous: No significant change in flow
B	150	Clear water, through open joint in Gneissic rock	* Flow changes with the operation of valve house
C	150	Clear water, a hole about 4-cm in diameter appearing under a tree root. Area filled with tunnel muck	Continuous: No significant change in flow
D	5	Clear water, through hole in soil	Continuous: No significant change in flow
E	25	Clear water, through open joint in Gneissic rock	* Flow changes with the operation of valve house
F	40	Clear water, through hole in debris material of earth slip	Continuous: No significant change in flow
G	100	Clear water, through hole in debris material of earth slip	Continuous: No significant change in flow
H	20	Clear water, through open joint in Gneissic rock	Continuous: No significant change in flow
I	40	Clear water, through open joint in Gneissic rock	Continuous: No significant change in flow
J	80	Clear water, through hole in debris material of earth slip	Continuous: No significant change in flow
K	70	Clear water, through hole in debris material of earth slip	Continuous: No significant change in flow

Water quality was investigated to confirm the origin of the spring and stream water.

Water samples of the waterway were collected from the intake, surge tank, and outlet of the New Laxapana plant. Samples of springs and streams were also collected around the surge tank. The following physical and chemical qualities were measured and analyzed.

- Electrical conductivity
- Suspended solids
- pH
- Temperature
- Dominant ions (Na<sup>+</sup>, K<sup>+</sup>, Ca<sup>2+</sup>, Mg<sup>2+</sup>, Fe<sup>2+</sup>, Mn<sup>2+</sup>, Cl<sup>-</sup>, SO<sub>4</sub><sup>2-</sup>, Total alkalinity)

The results of the water quality investigation are shown in Table 3.3.

Electrical conductivity of water of the waterway is 20 $\mu$ S (NWL – 1, NWL – 2). That of springs and streams around or downslope of the surge tank is 10 to 20 $\mu$ S. Streams distant from the waterway are less than 10 $\mu$ S (Figure 3.3 and Figure 3.4). Electrical conductivity indicates that the water of springs and streams around or downslope of the surge tank resemble to or contain much water of the waterway.

Chemical quality is shown in pattern diagram in Figure 3.5. This diagram is shown in milligram equivalent per liter, which is obtained by dividing concentration of ion by the equivalent weight of that ion. Judging from patterns in this diagram and location of water samples, waters collected at this time are divided in 4 chemical quality groups. Their distribution is shown in Figure 3.6 and Figure 3.7.

- Group A ( shown in red in Figures): Rich in Ca<sup>2+</sup>
- Group B ( shown in yellow in Figures): Rich in Ca<sup>2+</sup> and rich in Cl<sup>-</sup>
- Group C ( shown in yellow in Figures): Poor in Ca<sup>2+</sup> and rich in Cl<sup>-</sup>
- Group D ( shown in yellow in Figures): Poor in Ca<sup>2+</sup> and poor in Cl<sup>-</sup>

Group A is the same or almost the same as the water of the waterway. Group C is quite different from Group A and likely to be water traveling underground for a long time. Group B seems to be a mixture of Group A and Group C. Group D resembles rain water. (NLW – 20 is rain water. But its ion concentration is higher than usual rainwater. This sample may contain contaminated materials.)

Water leaked from the tunnel belongs to Group A. NLW - 10, NLW – 12 and NLW – 14 are spring water and belong to Group A. Stream waters near the road such as NLW – 6 and NLW – 7 are mostly composed of leaked water. Downstream, stream waters belong to Group B except NLW – 8, which belongs to Group A indicating the presence of a large amount of leaked water in the stream.

The volume of the leakage water around the surge tank of New Laxapana is roughly estimated as below. NLW-2, NLW-18 and NLW-8 is used as water in the tunnel, surface water and stream water respectively.

- A: Ion concentration in tunnel water
- B: Ion concentration in surface water
- C: Ion concentration in stream water
- Qa: Volume of leakage from tunnel
- Qb: Volume of surface water
- Qc: Volume of stream water

For Ion amount  $A \times Qa + B \times Qb = C \times Qc$

For volume  $Qa + Qb = Qc$

$$Qa = Qc \times (B - C) / (B - A)$$

$(B - C) / (B - A)$  indicates the rate of leakage.

$(B - C) / (B - A)$  of each ion is shown below.

Ca <sup>2+</sup>	1
Na <sup>+</sup>	2/3
K <sup>+</sup>	4/5
Cl <sup>-</sup>	0
SO <sub>4</sub> <sup>2-</sup>	1

The rates of leakage water shown by the above ions are more than 2/3 except Cl<sup>-</sup>. Because the observed discharges of the other streams are very small, the rate of leakage water is estimated almost 100% or more than 80%.


Table 3.3 Water Quality Test Results

Area A

Sample No.		NLW-1	NLW-2	NLW-3	NLW-4	NLW-5*	NLW-6	NLW-7	NLW-8	NLW-9	NLW-10	NLW-11	NLW-12	NLW-13	NLW-14	NLW-15	NLW-16	NLW-17	NLW-18	NLW-19	NLW-20	NLW-21**
Locality		Reservoir near intake of New Laxapana Power Plant	Surge shaft of Laxapana Power Plant	Masukeltha river just upstream of Laxapana Power Plant	Outlet of Laxapana Power Plant	Stream at V1 notch	Stream at V2 notch	Stream at V3 notch	Stream at V4 notch	Stream at V5 notch	Spring just below the cliff	Guided water at the roadside	Guided water at the roadside	Spring from the wall to the NE of valve house	Spring from the outlet of penstock tunnel	Spring below the cliff to the SW of valve house	Large spring downstream of V2	Just downstream of the waterfall of Seegra Ela	Stream of Seegra Ela beside the road	Stream beside the road	Rain water near Laxapana Power Plant	
pH		6.33	6.19	6.84	6.35		7.11	7.00	7.08	7.13	6.29	7.24	6.72	6.86	6.34	7.17	6.48	6.90	7.00	6.63	6.39	6.15
EC	µs/cm	20	20	20	19		18	20	18	18	19	17	26	15	20	17	20	8	8	9	19	19
Na <sup>+</sup>	ppm	4.0	4.5	5.2	3.8		3.5	4.0	4.0	3.5	4.0	3.5	3.5	3.5	3.5	4.0	4.0	3.0	3.0	3.0	3.9	3.5
(1e=23g)	me/l	0.2	0.2	0.2	0.2		0.2	0.2	0.2	0.2	0.2	0.2	0.2	0.2	0.2	0.2	0.2	0.1	0.1	0.1	0.2	0.2
K <sup>+</sup>	ppm	1.7	1.5	1.5	1.2		1.1	1.3	1.3	1.2	1.2	1.1	1.3	0.9	1.2	1.2	1.2	0.6	0.5	0.4	1.3	1.2
(1e=39g)	me/l	0.0	0.0	0.0	0.0		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
Na <sup>+</sup> + K <sup>+</sup>	me/l	0.2	0.2	0.3	0.2		0.2	0.2	0.2	0.2	0.2	0.2	0.2	0.2	0.2	0.2	0.2	0.1	0.1	0.1	0.2	0.2
Ca <sup>2+</sup>	ppm	8	6	8	10		8	8	6	8	8	4	12	4	8	8	8	4	2	4	18	8
(1e=20g)	me/l	0.4	0.3	0.4	0.5		0.4	0.4	0.3	0.4	0.4	0.2	0.6	0.2	0.4	0.4	0.4	0.2	0.1	0.2	0.9	0.4
Mg <sup>2+</sup>	ppm	2	4	4	2		4	2	2	2	2	2	2	2	2	2	2	2	2	4	4	2
(1e=12 g)	me/l	0.2	0.3	0.3	0.2		0.3	0.2	0.2	0.2	0.2	0.2	0.2	0.2	0.2	0.2	0.2	0.2	0.2	0.3	0.3	0.2
Fe <sup>2+</sup>	ppm	<0.1	<0.1	<0.1	<0.1		<0.1	0.1	0.1	0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	0.1	<0.1
(1e=28g)	me/l							0.00	0.00	0.00											0.00	
Mn <sup>2+</sup>	ppm	<0.05	<0.05	<0.05	<0.05		<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
(1e=27.5g)	me/l																					
Cation		0.78	0.87	1.00	0.86		0.91	0.78	0.68	0.75	0.77	0.55	0.95	0.54	0.75	0.77	0.77	0.51	0.41	0.67	1.44	0.75
Cl <sup>-</sup>	ppm	5.7	5.7	7.1	8.5		5.7	5.7	2.8	8.5	6.0	8.5	5.7	8.5	5.7	8.5	7.1	11.0	2.8	2.8	4.3	5.7
(1e=17.5g)	me/l	0.3	0.3	0.4	0.5		0.3	0.3	0.2	0.5	0.3	0.5	0.3	0.5	0.3	0.5	0.4	0.6	0.2	0.2	0.2	0.3
SO <sub>4</sub> <sup>2-</sup>	ppm	1.4	0.6	1.0	0.4		0.3	0.5	0.6	1.2	0.6	1.0	1.2	1.1	0.2	0.5	0.7	1.1	1.1	0.6	0.3	0.6
(1e=48g)	me/l	0.0	0.0	0.0	0.0		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
HCO <sub>3</sub> <sup>-</sup>																						
	me/l	0.4	0.5	0.6	0.4		0.6	0.4	0.5	0.2	0.4	0.0	0.6	0.0	0.4	0.3	0.4	(0.1)	0.2	0.5	1.2	0.4
Total Alkalinity	ppm	6	10	10	8		12	10	6	8	8	6	14	10	8	6	8	6	4	6	18	8
SS	ppm	9.2	13.2	10.0	7.6		21.6	2.0	1.6	2.4	7.6	5.6	2.4	8.0	2.0	5.2	8.0	9.6	19.2	1.6	30.0	17.6


\* Water is not available at the location

\*\* Water sampled from a new location (spring) just downstream of the corporative shop between NLW-16 and NLW-18



- |   |        |       |   |
|---|--------|-------|---|
| ⊙ | Stream | NLW-1 | Name of location                        |
| ○ | Spring | ●     | Electrical conductivity $> 20 \mu S$    |
| ⊙ | Shaft  | ●     | Electrical conductivity $10 - 20 \mu S$ |
|   |        | ●     | Electrical conductivity $< 10 \mu S$    |

**Figure 3.3 Electrical conductivity**



**Figure 3.4 Electrical Conductivity**





Figure 3.5 Water Quality by Hexadiagram




Area of Figure 5.18

- ☉ Stream
- Spring
- ◎ Shaft
- Ca<sup>+</sup> rich
- ◐ Ca<sup>+</sup> rich and Cl<sup>-</sup> rich
- ◑ Ca<sup>+</sup> poor and Cl<sup>-</sup> rich
- ◒ Ca<sup>+</sup> poor and Cl<sup>-</sup> poor

NLW-1 Name of location

**Figure 3.6 Water Quality**





- |               |                  |                         |   |
|---------------|------------------|-------------------------|---|
| ○ (with dots) | Stream           | ● (black)               | Ca <sup>+</sup> rich                          |
| ○ (white)     | Spring           | ○ (light gray)          | Ca <sup>+</sup> rich and Cl <sup>-</sup> rich |
| NLW-1         | Name of location | ● (dark gray)           | Ca <sup>+</sup> poor and Cl <sup>-</sup> rich |
|               |                  | ○ (light gray with dot) | Ca <sup>+</sup> poor and Cl <sup>-</sup> poor |

**Figure 3.7 Water Quality**