

APPENDIX 6

OTHER REFERENCE MATERIALS/INFORMATION

- 6-1 Technical Memorandum (at Field survey stage)
- 6-2 Results of the Natural Conditions Survey (Soil)
- 6-3 Results of Site Investigation (Traffic Count)
- 6-4 Exiting Assin Praso Bridge Inspection Sheets
- 6-5 Basic Design Drawings

6-1 Technical Memorandum (at Field survey stage)



CONSTRUCTION PROJECT CONSULTANTS, INC.

YSK Bldg., 3-23-1 Takadanobaba, Shinjuku-ku,

Tokyo 169-0075, JAPAN

Phone:+81-3-5337-4062

Facsimile:+81-3-5337-4092

28 April, 2008

The Chief Executive
Ghana Highway Authority (GHA)
The Republic of Ghana

Subject: Submission of Technical Note for The Basic Design Study on the Project for the Rehabilitation of National Truck Road N8 of the Japanese Grant Aid Project

Dear Sir,

We are pleased to submit the Technical Note which indicates the key design value to be used for the Basic Design Study for the captioned project by the Japan International Cooperation Agency (JICA) as Japanese Grant Aid Project.

The values on the Technical Note are following the result of discussion by the Study Team and GHA technical representative which was carried out at the conference room of GHA head quarter on 28th April, 2008.

Please confirm the attached Technical Note and we are looking forward to receive your reply for us to start our designing work.

Very truly yours,

A handwritten signature in black ink, appearing to read 'Hideaki Morita', is written over a horizontal line.

Hideaki Morita

Chief Consultant

The Basic Design Study on the Project for the Rehabilitation of National Truck Road N8
Construction Project Consultants, Inc. Japan (CPC)

Memorandum

28-April, 2008


Subject: Technical note of Design Value to be used for the Basic Design Study on the Project for the Rehabilitation of National Truck Road N8

The Japan International Cooperation Agency (JICA) Basic Design Study Team will propose the following principal standard for the design of .captioned project.

Description		Units	Value
Road			
Design Speed		Km/hr	80
No. of Lanes		No.	2
Right of Way Width		m	60 (30m each from existing road center)
Carriageway Width		m	7.3
Climbing Lane Width		m	3.5
Shoulder width		m	2.0
Cross Fall on Carriageway		%	2.5
Cross Fall on Shoulder		%	3.0
Minimum Radius of Horizontal Curve		m	233
Maximum Gradient		%	4 (Max = 8)
Maximum Superelevation		%	6
Fill Slope	Granular soil	Angle	1:1.5~2.0 (depend on soil type)
Cut Slope	Hard Rock	Angle	1:0.5
	Decomposed Rock	Angle	1:0.75
	Other than Rock	Angle	1:1.0~1.5 (depend on soil type)
Pavement Design Life		-	15 years (GHA standard)
Pavement Type (Carriageway)		-	AC
Pavement Type (Shoulder)		-	AC
Bridge			
Location		-	30m downstream side from existing Assin Praso Bridge
Standard		-	Specification for Highway Bridges of Japan Road Association
Seismic coefficient		-	0.1
Carriageway Width		m	8.3
Footway Width		m	1.5 x 2

Elevation of bottom of girder	-	1m higher than the elevation of surface of slab of existing Assin Praso Bridge, tentatively
Type	-	3 span bridge
others	-	Existing Assin Praso Bridge will be remained as Pedestrian Bridge

Note: Proposed horizontal road alignment will be traced on the existing road alignment except Assin Praso Bridge section, AC = Asphaltic Concrete.



E. ODURO-KONADU
CHIEF EXECUTIVE
GHANA HIGHWAY AUTHORITY



H. MORITA
 Chief Consultant of JICA Study Team
 The Basic Design Study on the Project for the
 Rehabilitation of National Truck Road N8

MATERIALS REPORT

ASSIN PRASO - ANWIANKWANTA

ROAD REHABILITATION PROJECT



(1) EXECUTIVE SUMMARY

As part of the studies for the Assin Praso – Awiankwanta Road Rehabilitation Project, a material survey has been carried out.

The survey has entailed the identification of possible sources of road building materials. The survey has identified possible sources of aggregates for asphalt concrete, surface dressing and Portland cement concrete.

Also identified were two possible sources of sand as fine aggregate for use in asphalt concrete and Portland cement concrete.

Seven possible sources of natural gravel sub-base, selected fill and ordinary fill were also identified.

Materials were taken from the identified sources and subjected to appropriate laboratory tests to enable the suitability or otherwise of the sources be determined.

The assessment of the materials from the identified sources have been made based on the Ghana Ministry of Transportation's "STANDARD SPECIFICATION FOR ROAD AND BRIDGE WORKS" published in February 2007.

The investigations indicate that while the identified source of coarse aggregates meets the requirement for Portland cement concrete it is regarded as marginal with respect to the requirement for its use in asphalt concrete and surface dressing.

Of the two sources of natural sand, material from one source was found to be unacceptable for use as fine aggregate either in asphalt concrete or in Portland cement concrete. The other source could be sieved and blended with other sources of fine aggregate and in Portland concrete cement or asphalt concrete.

Material from none of the seven identified natural gravel sources met the specifications for natural gravel sub-base.

Although materials from four of the sources could be regarded as marginal in meeting the required specifications, they could be used as selected fill in areas with good drainage.

Material from all seven borrow pits met the specifications for common fill.

Some of the materials could be stabilized with cement or other cementitious material for use as sub-base.

It is recommended that further investigations be carried out within the road corridor for other possible sources which may have materials meeting all the requirements of the specifications.

ASSIN PRASO – ANWIANKWANTA ROAD REHABILITATION PROJECT

SUMMARY OF TEST RESULTS ON SOIL (1 of 2)

(2) RABORATORY TEST RESULTS

SAMPLE IDENTIFICATION	PARTICLE SIZE DISTRIBUTION													ATTERBERG LIMITS		
	PERCENTAGE BY WEIGHT PASSING B.S. SIEVE													LL	PL	PI
	75	53.0	37.5	26.5	19.0	10.0	4.75	2.00	1.00	425	300	150	75			
LABELLED	mm	mm	mm	mm	mm	mm	mm	mm	mm	µm	µm	µm	µm	%	%	%
BH 1,2+800 _m DEPTH 0.80 _m	100	100	100	100	100	99	90	82	78	74	71	58	47	59	27	32
BH 2,7+800 _m DEPTH 0.70 _m	100	100	100	98	97	89	56	40	37	36	35	30	25	45	23	22
BH 3,25+000 _m DEPTH 0.50 _m	100	100	100	99	98	97	95	91	89	77	72	62	52	53	29	24
BH 4,30+000 _m STOCK PILE	100	100	100	100	100	97	73	54	50	48	46	40	33	42	21	21
B P S	100	96	95	93	55	49	32	22	20	18	17	14	11	43	22	21
BH 6,42+570 _m DEPTH 0.40 _m	100	100	100	97	96	93	75	59	57	55	53	44	38	57	31	26
BH 7,65+000 _m TRAIL PIT	100	97	91	87	80	60	43	31	29	25	24	22	20	53	30	23

ASSIN PRASO – ANWIANKWANTA ROAD REHABILITATION PROJECT

SUMMARY OF TEST RESULTS ON SOIL (2 of 2)

SAMPLE IDENTIFICATION	COMPACTION TEST			CBR TEST			
	MDD	OMC	NMC	96HRS SOAKED			
	kg/m ³	%	%	100%	98%	95%	93%
LABELLED							
BH 1,2+800m DEPTH 0.80m	1780	17.3	-	21	15	6	3
BH 2,7+800m DEPTH 0.70m	2142	10.4	-	50	44	36	31
BH 3,25+000m DEPTH 0.50m	1840	14.5	-	17	15	12	10
BH 4,30+000m STOCK PILE	2160	10.4	-	22	20	18	17
B P S	2300	8.9	-	47	36	24	19
BH 6,42+570m DEPTH 0.40m	2020	13.9	-	21	18	12	9
BH 7,65+000m TRAIL PIT	2015	7.0	-	16	15	13	12

ASSIN PRASO – ANWIANKWANTA ROAD REHABILITATION PROJECT

SUMMARY OF TEST RESULTS ON SAND (1 of 1)

DATE: 23 - 05 - 2008

SAMPLE IDENTIFICATION	PARTICLE SIZE DISTRIBUTION														ATTERBERG LIMITS		
	PERCENTAGE BY WEIGHT PASSING B.S. SIEVE														LL	PL	PI
	75	53.0	37.5	26.5	19.0	10.0	4.75	2.00	1.00	600.00	425	300	150	75			
SAMPLE LABELLED	mm	mm	mm	mm	mm	mm	mm	mm	mm	µm	µm	µm	µm	µm	%	%	%
AHINSAN 0.70M SAND PIT 2	100	100	100	100	100	100	99	97	60	36	32	30	26	23	36	17	19
OLD EDUBIASE	100	100	100	100	100	100	100	97	76	53	43	35	22	16	NON PLASTIC		

ASSIN PRASO – ANWIANKWANTA ROAD REHABILITATION PROJECT

SUMMARY OF TEST RESULTS ON ROCK (1 of 3)

DATE: 23 - 05 - 2008

SAMPLE IDENTIFICATION	AGGREGATE IMPACT VALUE (%)	LOS ANGELES ABRASION VALUE (%)	S. G. APPARENT kg/m³	ABSORPTION (%)	SODIUM SULPHATE SOUNDNESS (%)
APONSIE ROCK SAMPLE	25	32	2644	0.58	0.39

SUMMARY OF TEST RESULTS ON ROCK (3 OF 3)

GHANA HIGHWAY AUTHORITY
CENTRAL MATERIALS LABORATORY
STRIPPING TEST SUMMARY SHEET

CUSTOMER: TWUM BOAFO AND PARTNERS

DATE: 4TH JULY 2008

PROJECT: APONSIE QUARRY

SAMPLE IDENTIFICATION	LESS THAN 5% STRIPPED	GREATER THAN 5% STRIPPED
ROCK	YES	

NOTE: THIS RESULTS DO NOT CONSTITUTE APPROVAL BY GHA

X-RAY FLOURESCENCE RESULTS FOR APONSIE ROCK

DATE: 27-06-2008

Major Elemenets


Element	Dimension	APONISIE
Na ₂ O	%	4.01
MgO	%	1.47
Al ₂ O ₃	%	13.92
SiO ₂	%	72.41
P ₂ O ₅	%	0.12
SO ₃	%	0.15
Cl	%	< 0.00060
K ₂ O	%	3.60
CaO	%	1.57
TiO ₂	%	0.17
MnO	%	0.02
Fe ₂ O ₃	%	1.15
L.O.I	%	1.50
Total	%	100.09

Minor Elements

V	ppm	22
Cr	ppm	35
Co	ppm	< 15
Ni	ppm	15.7
Cu	ppm	15.8
Zn	ppm	35.8
Ga	ppm	21.8
Br	ppm	< 0.6
Rb	ppm	159.4
Sr	ppm	335
Y	ppm	< 1.1
Zr	ppm	232.9
Nb	ppm	17.3
Mo	ppm	3.7
Cs	ppm	< 8.2
Ba	ppm	1201
La	ppm	38.6
Ce	ppm	60
Hf	ppm	28
Ta	ppm	8.9
Pb	ppm	27.8
Bi	ppm	6.9
Th	ppm	9.8
U	ppm	26.9

ATTN: TWUM BOAFO & PARTNERS

NB: SAMPLE TYPE ROCK QUARRY


 MR. EMMANUEL EFFUM
 (SENIOR TECHNICAL OFFICER)
 GEOLOGICAL SURVEY DEPARTMENT
 P. O. BOX M. 88
 ACCRA

X-RAY FLOURESCENCE RESULTS FOR AHESAN AND OLD EDUBIASE SAND DEPOSITS

DATE: 27-06-2008

Major Elements


Element	Dimension	AHESAN	OLD EDUBIASE
Na ₂ O	%	3.46	3.86
MgO	%	2.17	2.38
Al ₂ O ₃	%	14.62	14.69
SiO ₂	%	69.51	66.43
P ₂ O ₅	%	0.02	0.05
SO ₃	%	0.17	0.16
Cl	%	< 0.0030	< 0.0030
K ₂ O	%	0.23	0.40
CaO	%	0.05	0.06
TiO ₂	%	1.29	1.03
MnO	%	0.02	0.01
Fe ₂ O ₃	%	2.73	1.38
L.O.I	%	5.50	9.50
Total	%	99.76	99.94

Minor Elements

V	ppm	84	47
Cr	ppm	715	587
Co	ppm	< 22	< 16
Ni	ppm	22	17.1
Cu	ppm	4.2	4.1
Zn	ppm	69.1	69.1
Ga	ppm	17.5	11.5
Br	ppm	3.2	0.5
Rb	ppm	17.6	14.8
Sr	ppm	17.1	17.6
Y	ppm	16.6	12.7
Zr	ppm	732	802
Nb	ppm	28.6	20
Mo	ppm	7.2	< 4.8
Cs	ppm	10.7	< 6.8
Ba	ppm	76.7	160.6
La	ppm	29.2	30.8
Ce	ppm	44	53.7
Hf	ppm	38.1	33.2
Ta	ppm	12.4	7.3
Pb	ppm	22	13.7
Bi	ppm	12.3	4.7
Th	ppm	10.3	3.4
U	ppm	21.3	14.7

ATTN: TWUM BOAFO & PARTNERS

NB: SAMPLE TYPE SOIL



MR. EMMANUEL EFFUM
(SENIOR TECHNICAL OFFICER)
 GEOLOGICAL SURVEY DEPARTMENT
 P. O. BOX M. 80
 ACCRA

TRAFFIC REPORT

ASSIN PRASO - ANWIANKWANTA
ROAD REHABILITATION PROJECT



(1) INTRODUCTION

The traffic surveys, which involved manual classified link counts, pedestrian volume counts and origin and destination surveys, commenced on the 25th of April 2008 and were carried out at three established census stations on the Yamoransa – Bekwai road for three (3) days. Apart from these surveys, turning movement counts were also conducted at the Praso-Obuasi-Bekwai intersection to determine vehicle manoeuvre as well as their composition.

Vehicles were classified in the following categories:-

- Motorcycle;
- Taxi, Jeep and Pick-up;
- Minibus and Wagon;
- Medium Bus and Large Bus;
- 2-axle Truck;
- 3-axle Truck;
- 4-axle Truck;
- 5-axle Truck;
- 6-axle Truck;
- 8-axle Truck; and
- Others.

The counts were carried out for 24 hours at the various census stations.

(2) TRAFFIC SURVEY RESULT

Question 1.1 Sex of Drivers

Sex	Sex of Respondents	
	Frequency	Percentage
Male	112	100.0
Female	0	0.0
Total	112	100

Question 1.2 Vehicle Classification

Vehicle Type	Classification of Vehicle	
	Frequency	Percentage
2 axles truck	25	22.3
3 axles truck	11	9.8
4 axles truck	16	14.3
5 axles truck	36	32.1
6 axles truck	23	20.5
7 axles truck	0	0.0
8 axles truck	1	0.9
Total	112	100.0

Question 1.3 Age of Drivers

Age	Age of Respondents	
	Frequency	Percentage
20-29	11	9.8
30-39	49	43.8
40-49	32	28.6
50-59	17	15.2
>60	3	2.7
Total	112	100.0

Question 1.4 Trip Purpose

Purpose	Trip Purpose	
	Frequency	Percentage
Business	111	99.1
Personal	1	0.9
Total	112	100

Question 1.4b Classification of Cargo

Cargo	Type of Cargo	
	Frequency	Percentage
Cocoa	14	12.5
Lime	1	0.9
Cement	21	18.8
Flour powder	1	0.9
Beer/ Soft drink	6	5.4
Construction Material	5	4.5
Chemical	5	4.5
Wood/ Log	15	13.4
Bauxite	4	3.6
Gold	0	0.0
General goods	22	19.6
Cotton	0	0.0
Food Stuff	15	13.4
Fuel	2	1.8
Others	1	0.9
Total	112	100.0

Question 2.1a Origin and Destination of Trip

Town	Origin	
	Frequency	Percentage
Fr. Kumasi	26	23.2
Fr. Obuasi	4	3.6
Fr. Burkina Faso	0	0.0
Fr. Techiman	3	2.7
Fr. New Edubiase	2	1.8
Fr. Dunkwa Offin	2	1.8
Fr. Dompooase	1	0.9
Fr. Wa	2	1.8
Fr. Brong Ahafo	1	0.9
Fr. Wurayie	1	0.9
Fr. North	1	0.9
Fr. Tema	1	0.9
Fr. Ejisu	1	0.9
Fr. Niger	1	0.9
Fr. Swedru	1	0.9
Fr. Awaso	1	0.9
Fr. Takoradi	45	40.2
Fr. Capecoast	8	7.1
Fr. Accra	2	1.8
Fr. Assin Praso	2	1.8
Fr. Assin Fosu	5	4.5

Fr. Mankessim	1	0.9
Fr. Oda	1	0.9
Total	112	100.0

Question 2.1b Origin and Destination of Trip

Town	Destination	
	Frequency	Percentage
To. Takoradi	24	21.4
To. Capecoast	3	2.7
To. Accra	3	2.7
To. Assin Praso	4	3.6
To. Assin Fosu	4	3.6
To. Tema	3	2.7
To. Elmina	2	1.8
To. Oda	1	0.9
To. Twifo Praso	1	0.9
To. Mankessim	1	0.9
To. Ivory Coast	1	0.9
To. Sefwi	1	0.9
To. Kumasi	39	34.8
To. Obuasi	3	2.7
To. Burkina Faso	0	0.0
To. Atobiase	2	1.8
To. Techiman	5	4.5
To. Wa	2	1.8
To. New Edubiase	2	1.8
To. Kenyasi	2	1.8
To. Niger	2	1.8
To. Sunyani	2	1.8
To. Awaso	3	2.7
To. Bibiani	1	0.9
To. Tamale	1	0.9
Total	112	100.0

Question 2.1c Origin and Destination of Trip through where?

Town	Through where?	
	Frequency	Percentage
Obuasi	64	57.1
Fomena	48	42.9
Total	112	100.0

Question 2.2 Frequency of use of the road

	Frequency use of road	
	Frequency	Percentage
Everyday	24	21.4
Once a week	61	54.5
More than once a week	14	12.5
Once or twice in a month	13	11.6
Less than once a month	0	0.0
No reply	0	0.0
Total	112	100.0

Question 2.3 If frequency is everyday, how many time in a day.

	No. of times in a day	
	Frequency	Percentage
Less one way in a day	0	0.0
One way in a day	0	0.0
One round-trip in a day	20	17.9
Two round-trips in a day	3	2.7
More two round-trips in a day	0	0.0
No daily trip	89	79.5
Total	112	100.0

Question 2.4 Travel Hours spent on road.

Time (Hours)	Hours Spent on Road	
	Frequency	Percentage
1-5	26	23.2
6-10	58	51.8
11-15	13	11.6
16-20	4	3.6
21-25	6	5.4

26-30	1	0.9
Over >30	4	3.6
Total	112	100.0

Question 3.0 Problems faced the on Road.

Category of Problems	Problems on Road	
	Frequency	Percentage
Pot hole(P)	40	27.2
Narrow width (W)	1	0.7
No sufficient sight-distance(S)	0	0.0
Steep in Mountain terrain(M)	12	8.2
Darkness (D)	0	0.0
Many Curves (C)	0	0.0
Insufficient Road Signs (RS)	1	0.7
Road Depression (DR)	64	43.5
Many Balancing(B)	16	10.9
Others (O)	0	0.0
No Problem (N)	13	8.8
Total	147	100.0

Question 3.0 Problems faced the on Bridge.

Category of Problems	Problems on Bridge	
	Frequency	Percentage
Narrow width (W)	91	81.3
None(N)	21	18.8
Total	112	100.0

6-4 Exiting Assin Praso Bridge Inspection Sheets


Inspection Form (No.1) Bridge Elements & Comprehensive Observations														
Bridge Name	Assin Praso Bridge			Road Name	National Highway No.8				Governing Agency	Ghana Highway Authority (GHA)			Bridge Code	
Location	From	Assin Praso		Station No.	From				Governing Agency	Date Inspected	Oct. 16, 2008			
	To				To									
Opening Date		Bridge Length	82m	Live Load & Grade					Standard	BS			Traffic Condition	
Superstructure	Truss	Width	Wide Width	Verge	Foot Path	Traffic Lane/Lane	Traffic Lane/Lane	Foot Path	Verge	Middle Traffic Lane	Central Reservation	Year Inspected	2003	
			Carriageway	0.15m	0m	5.5m	1						Traffic Volume	2600/day
Substructure	Ellipse Wall Type	Memo										Heavy Vehicle Index	40%	
Foundation	Unknown											Allowable Load	Truck 12ton	
Comprehensive Observations														
<ol style="list-style-type: none"> The bridge was constructed 72 years ago. Limit loads indicated are truck=12t, trailer=18t and crowd load=100lb/sq.ft. Current traffic per day is 800-2200 including traffic of heavy trailers and heavy trucks whose live loads extremely exceed the limit loads. Substructure: Due to inadequate treatment of horizontal construction joint at upper part under bearing concrete of right side pier, seepage was observed. There seems no problem in strength of concrete. Superstructure: Lateral member of vertical element was removed and reinforcing angles were mounted on the truss crowns in lieu. Deformed guardrail pipes, as well as a deformed vertical element, signify frequent bumps by vehicles. The original structure seems jointed with rivets, and most of them were replaced with high tension bolts. All drainage structures were closed with asphalt when the bridge surface was rehabilitated. As for kerbs, cracks were observed at every transverse beam positions. From these cracks, rainwater has been seeped onto the transverse beams under the floor slab and aggravate the corrosion of transverse beams. In the middle of the bridge, considerable oscillation was observed during the transit of heavy trailers. GHA (Ghana Highway Authority) concluded the soundness survey on October 15, 2003 and resulted that no problem had been found with the bridge. However, considering comprehensively the current conditions of the bridge observed and surveyed through this study as stated 1, 5 and 7 above, it is highly recommendable that the bridge shall be reconstructed as urgently as possible. GHA is desirous to use the existing bridge as a pedestrian bridge after completion of the new bridge. <ul style="list-style-type: none"> Provide drainage structures to the existing bridge; Repair crack of kerb concrete; and Implement countermeasure works which prevent corrosion of cross beam and stringer under the floor slab. 														

Inspection Form (No.2) General View for Each Span										Span No.	1,2,3	
Bridge Name	Assin Praso Bridge			Road Name	National Highway No.8				Governing Agency	Ghana Highway Authority (GHA)		
Location	From			Station No.	From				Governing Agency	Date Inspected	Oct. 16, 2008	
	To				To							
General View 1												
Span 1,2,3												
General View 2												
Span 2												

Inspection Form (No.2) General View for Each Span						Span No.	1,2,3
Bridge Name	Assin Praso Bridge	Road Name	National Highway No.8	Governing Agency	Ghana Highway Authority (GHA)	Bridge Code	
Location	From	Station No.	From			Date Inspected	Oct. 16, 2008
	To		To				


General View 1

Span 1,2,3



General View 2


Span 2



Inspection Form (No.2) General View for Each Span						Span No.	1,2,3
Bridge Name	Assin Praso Bridge	Road Name	National Highway No.8	Governing Agency	Ghana Highway Authority (GHA)	Bridge Code	
Location	From	Station No.	From			Date Inspected	Oct. 16, 2008
	To		To				


General View 1





Span 1,2,3








General View 2

Span 3



Inspection Form (No.3) Photo/Current Condition							Span No.	1,2,3			
Bridge Name	Assin Praso Bridge		Road Name	National Highway No.8		Governing Agency	Ghana Highway Authority (GHA)	Bridge Code			
Location	From		Station No.	From			Date Inspected	Oct. 16, 2008			
	To			To							
Photo/Current Condition											
Photo No.	1		Date	2008.04.11		Photo No.	2		Date	2008.04.14	
Span No.	1,2,3.		Memo			Span No.	1,2,3.		Memo		
Comment	Front View		From Kumasi side			Comment	Side View		From upper right bank		
											
Photo No.	3		Date	2008.04.14		Photo No.	4		Date	2008.04.14	
Span No.	1,2,3.		Memo			Span No.	1,2,3.		Memo		
Comment	Bridge surface		From Yamoransa			Comment	Floor system		L Span 2 Floor slab under side F Span 1 Floor slab under side		
											

Inspection Form (No.3) Photo/Current Condition							Span No.	1,2,3			
Bridge Name	Assin Praso Bridge		Road Name	National Highway No.8		Governing Agency	Ghana Highway Authority (GHA)	Bridge Code			
Location	From		Station No.	From			Date Inspected	Oct. 16, 2008			
	To			To							
Photo/Current Condition											
Photo No.	5		Date	2008.04.14		Photo No.	6		Date	2008.04.14	
Span No.	2		Memo			Span No.	2		Memo		
Comment	Superstructure		Portal bracing had been removed			Comment	Clearance		Where the standard clearance is designated as 5.2m, the clearance of the bridge is 4.6m.		
											
Photo No.	7		Date	2008.04.14		Photo No.	8		Date	2008.04.14	
Span No.	1,2,3.		Memo			Span No.	2		Memo		
Comment	Loads limit		Truck : 12 ton Trailer : 18 ton Crowd load : 100 lb/ft ²			Comment	Revetment work		Collapse of Concrete block of the revetment work.		
											


Inspection Form (No.3) Photo/Current Condition										Span No.		1,2,3			
Bridge Name		Assin Praso Bridge		Road Name		National Highway No.8		Governing Agency		Ghana Highway Authority (GHA)		Bridge Code			
Location		From		Station No.		From				Date Inspected		Oct. 16, 2008			
		To				To									
Photo/Current Condition															
Photo No.		9		Date		2008.04.21		Photo No.				Date			
Span No.		1,2,3		Memo				Span No.				Memo			
Comment		Drainage				Drainage lost its function after the asphalt pavement work had been implemented on the bridge surface regardless of the drainage.		Comment							
Photo No.				Date				Photo No.				Date			
Span No.				Memo				Span No.				Memo			
Comment								Comment							

Inspection Form (No.4) Numbers of Parts and Elements										Span No.		1		
Bridge Name		Assin Praso Bridge		Road Name		National Highway No.8		Governing Agency		Ghana Highway Authority (GHA)		Bridge Code		
Location		From		Station No.		From				Date Inspected		Oct. 16, 2008		
		To				To								
Numbers of Parts and Elements														
Cross Beam (Cr)							Stringer (St)							
0101	0102	0103	0104	0105	0106	0107	0101	0102	0103	0104	0105	0106	0107	0108
0201	0202	0203	0204	0205	0206	0207	0201	0202	0203	0204	0205	0206	0207	0208
0301	0302	0303	0304	0305	0306	0307	0301	0302	0303	0304	0305	0306	0307	0308
0401	0402	0403	0404	0405	0406	0407	0401	0402	0403	0404	0405	0406	0407	0408
0501	0502	0503	0504	0505	0506	0507	0501	0502	0503	0504	0505	0506	0507	0508
0601	0602	0603	0604	0605	0606	0607								
A1							P1							

Inspection Form (No.4) Numbers of Parts and Elements							Span No.	1
Bridge Name	Assin Praso Bridge		Road Name	National Highway No.8		Governing Agency	Ghana Highway Authority (GHA)	Bridge Code
Location	From		Station No.	From			Date Inspected	Oct. 16, 2008
	To			To				

Numbers of Parts and Elements


Diagonal Bracing/Vertical Member Downstream (Dtd)



A1

P1

Diagonal Bracing/Vertical Member Upstream (Dtu)




A1

P1

Inspection Form (No.4) Numbers of Parts and Elements							Span No.	1
Bridge Name	Assin Praso Bridge		Road Name	National Highway No.8		Governing Agency	Ghana Highway Authority (GHA)	Bridge Code
Location	From		Station No.	From			Date Inspected	Oct. 16, 2008
	To			To				

Numbers of Parts and Elements


Upper/Bottom Chord Downstream (Btd)



A1

P1

Upper/Bottom Chord Upstream (Btu)



A1

P1


Inspection Form (No.4) Numbers of Parts and Elements							Span No.	2	
BridgeName	Assin Praso Bridge		RoadName	National Highway No.8		Governing Agency	Ghana Highway Authority (GHA)	BridgeCode	
Location	From		StationNo.	From			Date Inspected	Oct. 16, 2008	
	To			To					

Numbers of Parts and Elements										
Cross Beam (Cr)										
	0101	0102	0103	0104	0105	0106	0107	0108	0109	
	0201	0202	0203	0204	0205	0206	0207	0208	0209	
	0301	0302	0303	0304	0305	0306	0307	0308	0309	
	0401	0402	0403	0404	0405	0406	0407	0408	0409	
	0501	0502	0503	0504	0505	0506	0507	0508	0509	
	0601	0602	0603	0604	0605	0606	0607	0608	0609	
P1										P2
Stringer (St)										
	0101	0102	0103	0104	0105	0106	0107	0108	0109	0110
	0201	0202	0203	0204	0205	0206	0207	0208	0209	0210
	0301	0302	0303	0304	0305	0306	0307	0308	0309	0310
	0401	0402	0403	0404	0405	0406	0407	0408	0409	0410
	0501	0502	0503	0504	0505	0506	0507	0508	0509	0510
P1										P2


Inspection Form (No.4) Numbers of Parts and Elements							Span No.	2	
BridgeName	Assin Praso Bridge		RoadName	National Highway No.8		Governing Agency	Ghana Highway Authority (GHA)	BridgeCode	
Location	From		StationNo.	From			Date Inspected	Oct. 16, 2008	
	To			To					

Numbers of Parts and Elements												
Diagonal Bracing/Vertical Member Downstream (Dtd)												
	0101	0102	0103	0104	0105	0106	0107	0108	0109	0110	0111	0112
		0201	0202	0203	0204	0205	0206	0207	0208	0209		
P1											P2	
Diagonal Bracing/Vertical Member Upstream (Dtu)												
	0101	0102	0103	0104	0105	0106	0107	0108	0109	0110	0111	0112
		0201	0202	0203	0204	0205	0206	0207	0208	0209		
P1											P2	


Inspection Form (No.4) Numbers of Parts and Elements							Span No.	2	
Bridge Name	Assin Praso Bridge		Road Name	National Highway No.8		Governing Agency	Ghana Highway Authority (GHA)	Bridge Code	
Location	From		Station No.	From			Date Inspected	Oct. 16, 2008	
	To			To					




Inspection Form (No.4) Numbers of Parts and Elements							Span No.	3	
Bridge Name	Assin Praso Bridge		Road Name	National Highway No.8		Governing Agency	Ghana Highway Authority (GHA)	Bridge Code	
Location	From		Station No.	From			Date Inspected	Oct. 16, 2008	
	To			To					



Inspection Form (No.4) Numbers of Parts and Elements							Span No.	3	
Bridge Name	Assin Praso Bridge		Road Name	National Highway No.8		Governing Agency	Ghana Highway Authority (GHA)	Bridge Code	
Location	From		Station No.	From			Date Inspected	Oct. 16, 2008	
	To			To					



Inspection Form (No.4) Numbers of Parts and Elements							Span No.	3	
Bridge Name	Assin Praso Bridge		Road Name	National Highway No.8		Governing Agency	Ghana Highway Authority (GHA)	Bridge Code	
Location	From		Station No.	From			Date Inspected	Oct. 16, 2008	
	To			To					



Inspection Form (No.5) Defects						Span No.	1
Bridge Name	Assin Praso Bridge	Road Name	National Highway No.8	Governing Agency	Ghana Highway Authority (GHA)	Bridge Code	
Location	From	Station No.	From			Date Inspected	Oct. 16, 2008
	To		To				

Defects

**Upper/Bottom Chord Downstream (Btd)
Diagonal Bracing/Vertical Member Downstream (Dtd)**

- Weed at Bearing due to accumulated soil
- Bearing buried in seat
- Flaking of paint
- Corrosion of bolts joining cross beam and bottom chord
- Water seepage and weed due to crack in kerb concrete.

Cross Beam (Gr)

A1 P1
Corrosion entirely spread over cross beam

**Upper/Bottom Chord Upstream (Btu)
Diagonal Bracing/Vertical Member Upstream (Dtu)**

- Weed at Bearing due to accumulated soil
- Bearing buried in seat
- Corrosion of bolts joining cross beam and bottom chord
- Water seepage and weed due to crack in kerb concrete.

Stringer (St)

A1 P1
Rust stain on surface of concrete due to corrosion of cross beam

Corrosion entirely spread over stringer

Inspection Form (No.5) Defects						Span No.	2
Bridge Name	Assin Praso Bridge	Road Name	National Highway No.8	Governing Agency	Ghana Highway Authority (GHA)	Bridge Code	
Location	From	Station No.	From			Date Inspected	Oct. 16, 2008
	To		To				

Defects

**Upper/Bottom Chord Downstream (Btd)
Diagonal bracing/Vertical Member Downstream (Dtd)**

- Partially distorted/buckled vertical member
- Weed at Bearing due to accumulated soil

Cross Beam (Gr)

P1 P2
Rust on stringer flange entirely

**Upper/Bottom Chord Upstream (Btu)
Diagonal bracing/Vertical Member Upstream (Dtu)**





- Distorted/buckled vertical member due to bump of car
- Flaking of paint



Stringer (St)




P1 P2
Stain on surface of pier concrete due to rust of stringer





Inspection Form (No.5) Defects							Span No.	3
BridgeName	Assin Praso Bridge	RoadName	National Highway No.8	Governing Agency	Ghana Highway Authority (GHA)	BridgeCode		
Location	From	StationNo.	From			Date Inspected	Oct. 16, 2008	
	To		To					
Defects								
<p>Upper/Bottom Chord Downstream (Btd) Diagonal bracing/Vertical Member Downstream (Dtd)</p> <p>P2 - Weed at Bearing due to accumulated soil - Bearing buried in seat</p>				<p>Cross Beam (Cr)</p> <p>Corrosion entirely spread over stringer</p>				
<p>Upper/Bottom Chord Upstream (Btu) Diagonal bracing/Vertical Member Upstream (Dtu)</p> <p>P2 - Weed at Bearing due to accumulated soil - Bearing buried in seat</p>				<p>Stringer (St)</p> <p>P2 Stain on surface of pier concrete due to rust of stringer</p>				

Inspection Form (No.6) Photo/Defects							Span No.	1
BridgeName	Assin Praso Bridge	RoadName	National Highway No.8	Governing Agency	Ghana Highway Authority (GHA)	BridgeCode		
Location	From	StationNo.	From			Date Inspected	Oct. 16, 2008	
	To		To					
Defects								
ProbNo	1	SpanNo	1	Date	2008.4.15	ProbNo	2	
Parts&Elements	Bottom Chord	ElementNo.	Btd/Btu 0101-0108	Memo		Parts&Elements	Bottom Chord	
Defects	Corrosion	Grade	d	Flaking of paint of bottom chord.		Defects	Corrosion	
ProbNo	3	SpanNo	1	Date	2008.4.15	ProbNo	4	
Parts&Elements	Pavement	ElementNo.		Memo		Parts&Elements	Expansion Joint	
Defects	Pothole	Grade	e	Flaking of pavement of bridge surface.		Defects	Accumulated Soil	





Inspection Form (No.6) Photo/Defects										Span No.		1											
Bridge Name		Assin Praso Bridge		Road Name		National Highway No.8		Governing Agency		Ghana Highway Authority (GHA)		Bridge Code											
Location		From		Station No.		From		To		Date Inspected		Oct. 16, 2008											
		To				To																	
Defects																							
Photo No.		5		Span No.		1		Date		2008.4.13		Photo No.		6		Span No.		1		Date		2008.4.13	
Parts & Elements		Cross Beam / Stringer		Element No.		Cr 0101-0607 St 0101-0508		Memo				Parts & Elements		Stringer		Element No.		0108		Memo			
Defects		Corrosion		Grade		e		Corrosion spread over cross beam entirely.				Defects		Corrosion		Grade		e		Rust stain on surface of pier concrete due to corrosion of stringer.			
																							
Photo No.		7		Span No.		1		Date		2008.4.13		Photo No.		8		Span No.		1		Date		2008.4.15	
Parts & Elements		Stringer		Element No.		0101		Memo				Parts & Elements		Cross Beam / Stringer		Element No.		Cr 0101-0607 St 0101-0508		Memo			
Defects		Accumulated Soil		Grade		e		Bearing buried in accumulate soil.				Defects		Corrosion		Grade		e		Corrosion spread over cross beam and stringer entirely.			
																							




Inspection Form (No.6) Photo/Defects										Span No.		1											
Bridge Name		Assin Praso Bridge		Road Name		National Highway No.8		Governing Agency		Ghana Highway Authority (GHA)		Bridge Code											
Location		From		Station No.		From		To		Date Inspected		Oct. 16, 2008											
		To				To																	
Defects																							
Photo No.		9		Span No.		1		Date		2008.4.15		Photo No.		10		Span No.		1		Date		2008.4.15	
Parts & Elements		Bearing		Element No.		Bearing (entire)		Memo				Parts & Elements		Bearing		Element No.		Seat Concrete		Memo			
Defects		Accumulate Soil		Grade		e		Weed at Bearing due to accumulated soil.				Defects		Reduced section		Grade		e		Bearing of cross beam buried in seat.			
																							
Photo No.				Span No.				Date				Photo No.				Span No.				Date			
Parts & Elements				Element No.				Memo				Parts & Elements				Element No.				Memo			
Defects				Grade								Defects				Grade							



Inspection Form (No.6) Photo/Defects							Span No.	1			
Bridge Name	Assin Praso Bridge		Road Name	National Highway No.8		Governing Agency	Ghana Highway Authority (GHA)	Bridge Code			
Location	From		Station No.	From			Date Inspected	Oct. 16, 2008			
	To			To							
Defects											
Phot No.	11	Span No.	1	Date	2008.4.15	Phot No.		Span No.		Date	
Parts & Elements	Kerb	Bement No.	-	Memo			Parts & Elements		Bement No.		Memo
Defects	Crack	Grade	e	Weed at joint of cross beam and bottom chord due to crack of kerb.			Defects		Grade		
											
Phot No.	12	Span No.	1	Date	2008.4.15	Phot No.	13	Span No.	1	Date	2008.4.15
Parts & Elements	Bearing	Bement No.	Bearing (entire)	Memo			Parts & Elements	Bearing	Bement No.	Bearing (entire)	Memo
Defects	Accumulated Soil	Grade	e	Weed at Bearing due to accumulated soil.			Defects	Accumulated Soil	Grade	e	Same as left.
											
											


Inspection Form (No.6) Photo/Defects							Span No.	2			
Bridge Name	Assin Praso Bridge		Road Name	National Highway No.8		Governing Agency	Ghana Highway Authority (GHA)	Bridge Code			
Location	From		Station No.	From			Date Inspected	Oct. 16, 2008			
	To			To							
Defects											
Phot No.	1	Span No.	2	Date	2008.4.13	Phot No.	2	Span No.	2	Date	2008.4.15
Parts & Elements	Stringer	Bement No.	0101, 0201, 0101, 0401, 0501	Memo			Parts & Elements	Cross Beam	Bement No.	0101-0609	Memo
Defects	Corrosion	Grade	e	Rust stain on surface of pier concrete due to corrosion of stringer.			Defects	Corrosion	Grade	e	Entire corrosion of cross beam down side flange.
											
											
Phot No.	3	Span No.	2	Date	2008.4.15	Phot No.	4	Span No.	2	Date	2008.4.14
Parts & Elements	Cross Beam / Stringer	Bement No.	Cr 0101-0609 St 0101-0510	Memo			Parts & Elements	Cross Beam / Stringer	Bement No.	Cr 0101-0609 St 0101-0510	Memo
Defects	Corrosion	Grade	e	Rust stain on stringer. Corrosion of cross beam down side flange.			Defects	Corrosion	Grade	e	Same as left.
											
											

Inspection Form (No.6) Photo/Defects										Span No.	2
Bridge Name	Assin Praso Bridge		Road Name	National Highway No.8		Governing Agency	Ghana Highway Authority (GHA)		Bridge Code		
Location	From		Station No.	From			Date Inspected	Oct. 16, 2008			
	To			To							
Defects											
Photo No.	5	Span No.	2	Date	2008.4.15	Photo No.	6	Span No.	2	Date	2008.4.15
Parts & Elements		Bement No.	Bearing (entire)	Memo		Parts & Elements	Bearing	Bement No.	Bearing (entire)	Memo	
Defects	Accumulated Soil	Grade	e	Weed at Bearing due to accumulated soil.		Defects	Accumulated Soil	Grade	e	Same as left	
											
Photo No.	7	Span No.	2	Date	2008.4.15	Photo No.	8	Span No.	2	Date	2008.4.15
Parts & Elements	Bearing	Bement No.	Bearing (entire)	Memo		Parts & Elements	Bearing	Bement No.	Bearing (entire)	Memo	
Defects	Accumulated Soil	Grade		Same as above		Defects	Accumulated Soil	Grade	e	Same as above	
											

Inspection Form (No.6) Photo/Defects										Span No.	2
Bridge Name	Assin Praso Bridge		Road Name	National Highway No.8		Governing Agency	Ghana Highway Authority (GHA)		Bridge Code		
Location	From		Station No.	From			Date Inspected	Oct. 16, 2008			
	To			To							
Defects											
Photo No.	9	Span No.	2	Date	2008.4.15	Photo No.	10	Span No.	2	Date	2008.4.15
Parts & Elements	Handrail	Bement No.	-	Memo		Parts & Elements	Vertical Member	Bement No.	Dtu0204	Memo	
Defects	Distortion-Buckling	Grade	c	Distortion-Buckling of handrail pipe due to bump of car.		Defects	Distortion-Buckling	Grade	C	Distortion-Buckling of vertical member due to bump of car. Large vibration by traffic of heavy vehicles.	
											
Photo No.	11	Span No.	2	Date	2008.4.15	Photo No.	12	Span No.	2	Date	2008.4.15
Parts & Elements	Vertical Member	Bement No.	Dtu0205	Memo		Parts & Elements	Bearing	Bement No.	Bearing (entire)	Memo	
Defects	Corrosion	Grade	c	Flaking of paint of some vertical members.		Defects	Accumulated Soil	Grade	e	Weed at Bearing due to accumulated soil.	
											

Inspection Form (No.6) Photo/Defects										Span No.	
Bridge Name		Assin Praso Bridge		Road Name		National Highway No.8		Governing Agency		Ghana Highway Authority (GHA)	
Location		From		Station No.	From		To			Bridge Code	
Defects											
Photo No.	13	Span No.		Date		Photo No.	14	Span No.		Date	2008.4.15
Parts & Elements		Element No.		Memo			Parts & Elements		Element No.		Memo
Defects		Grade		Distortion-Buckling of some handrails due to bump of cars.			Defects		Grade		Flaking of pavement of bottom chord.
											
Photo No.	15	Span No.		Date		Photo No.	16	Span No.		Date	
Parts & Elements		Element No.		Memo			Parts & Elements		Element No.		Memo
Defects		Grade		Distortion-Buckling of some vertical members.			Defects		Grade		
											

Inspection Form (No.6) Photo/Defects										Span No.	
Bridge Name		Assin Praso Bridge		Road Name		National Highway No.8		Governing Agency		Ghana Highway Authority (GHA)	
Location		From		Station No.	From		To			Bridge Code	
Defects											
Photo No.		Span No.		Date	2008.4.15	Photo No.		Span No.		Date	2008.4.15
Parts & Elements		Element No.		Memo			Parts & Elements		Element No.		Memo
Defects		Grade		Water seepage at construction joints of pier concrete.			Defects		Grade		Corrosion of cross beam.
											
Photo No.		Span No.		Date		Photo No.		Span No.		Date	
Parts & Elements		Element No.		Memo			Parts & Elements		Element No.		Memo
Defects		Grade					Defects		Grade		

Inspection Form (No.6) Photo/Defects										Span No.	3				
Bridge Name		Assin Praso Bridge		Road Name		National Highway No.8		Governing Agency		Ghana Highway Authority (GHA)					
Location		From		Station No.	From					Bridge Code		Date Inspected	Oct. 16, 2008		
	To			To											
Defects															
Photo No.		Span No.		Date		2008.4.15		Photo No.		Span No.		Date		2008.4.15	
Parts & Elements		Element No.		Memo				Parts & Elements		Element No.		Memo			
Defects		Grade		Weed at Bearing due to accumulated soil.				Defects		Grade		Same as left.			
															
Photo No.		Span No.		Date				Photo No.		Span No.		Date			
Parts & Elements		Element No.		Memo				Parts & Elements		Element No.		Memo			
Defects		Grade						Defects		Grade					