


# Inspection sheet of visual survey


Bridge No. 16


Photo No. ( ~ )

Bridge name		RAMA III Bridge		Route name		-		Authority		DRR		Code of authority		-			
Place		from Khet Thon Buri to Khet Bang Kho Leam		Distance		from km+ 0 to km+ 0						No.		-			
												Survey date		2009/10/23			
Bridge properties	Bridge type(1)	main road · side road · ramp															
	Bridge type(2)	bridge · viaduct · plank pass															
	Bridge type(3)	3-span continuous PC box girder															
	Total length	476.00 (m)															
	Span	125 + 226 + 125 (m)															
	Nos. of span	3 span															
	Width	23.00 (m) / (m)															
	Completion	2000															
Road information	Horizontal	Straight · incli ( $\theta =$ ° ) · Curve ( R m )															
	Gradient	One way ( ↗ · ↘ ) parabo ( $\frac{1}{4}$ · $\frac{3}{4}$ )															
	Nearby tunnel	yes · no ( m )															
	Nearby crossing	yes · no ( m )															
	Traffic	Much · Medium · Little															
	Commercial traffic	Much · Medium · Little															
Environ	1. Urban				2. Suburbs				3. Mountain				4. Seaside				
	5. Industrial				6. Harbor				7. Residential				8. Business				
	9. Salty				10. Cold and snow				11. Heavy snow				12. Others				
Under brid	1. Shinkanser				2. Railway				3. Highway				4. Road				
	5. River				6. Lake				7. Ravine				8. Valley				
	9. Waterway				10. Parking				11. Bike parkin				12. Park				
	13. Vacant				14. Harbor				Name ( Chao Phraya )								
Access method	Superstructure		1. Inspection car 2. Falsework 3. On ground 4. Ladder 5. Lift car 6. On boat 7. Special camera 8. Others ( )														
	Substructure		1. Inspection car 2. Falsework 3. On ground 4. Ladder 5. Lift car 6. On boat 7. Special camera 8. Others ( )														
	Reason		· All bridge section is on the water · If inspection car is not available, false work will be required														
Survey result	Camber deform		yes · no														
	Difference in glade		yes · no														
	Continuous of barrier		yes · no														
	Continuous of curve		yes · no														
	Noise		yes · no														
	Joint	Space change		yes · no													
		difference grade		yes · no													
		draining damage		yes · no													
		Blocked drainage		yes · no													
	Out line of damage	Crack of pavement		yes · no													
Damage of lighting		yes · no															
Damage of sign		-															
Damage of handrail		yes · no															
Possibility of scour		yes · no															
Walkway yes · no																	
Inspection way	Vehicle yes · no																
Impressions	Height of girder		about 34m														
	Deterioration of bridge		deficient · fair · good														
	Noticeable point		Survey from boat														
	History of repair		Repaint ; - yy - mm														
	Surveyor ;		Mr. Chujo, Mr. Kudo														

Present state ( 1 / 2 )					
Authority	DRR	Address	Bangkok	Data	31-Oct-09
Bridge	Rama 3				



	Picture No.	1
	Span	1
	Member	Side view

	Picture No.	2
	Span	1
	Member	View under girder

	Picture No.	3
	Span	1
	Member	View of pier

Present state ( 2 / 2 )					
Authority	DRR	Address	Bangkok	Data	31-Oct-09
Bridge	Rama 3				

	Picture No.	4
	Span	1
	Member	Pier
	Unfilled hole	
	Picture No.	5
	Span	1
	Member	Girder
	Unfilled hole	
	Picture No.	6
	Span	1
	Member	




# Inspection sheet of visual survey

Bridge No. 17

Photo No. ( ~ )

Bridge name		Krung Thep Bridge		Route name		-		Authority		DRR		Code of authority		-			
Place		from Khet Thon Buri to Khet Bang Kho Leam		Distance		from km+ 0 to km+ 0						No.		-			
												Survey date		2009/10/23			
Bridge properties	Bridge type(1)	main road · side road · ramp															
	Bridge type(2)	bridge · viaduct · plank pass															
	Bridge type(3)	5-span steel truss															
	Total length	316.00 (m)															
	Span	64 + 64 + 60 + 64 + 64 (m)															
	Nos. of span	5 span															
	Width	12.00 (m) / (m)															
	Completion	1959															
Road information	Horizontal	Straight · incli (θ = 1.7 %) (R m)															
	Gradient	One way ( ↗ · ↘ ) parabo ( ▽ · ▽ ) 3.45%															
	Nearby tunnel	yes · no ( m)															
	Nearby crossing	yes · no ( m)															
	Traffic	Much · Medium · Little															
	Commercial traffic	Much · Medium · Little															
Environ	1. Urban				2. Suburbs				3. Mountain				4. Seaside				
	5. Industrial				6. Harbor				7. Residential				8. Business				
	9. Salty				10. Cold and snow				11. Heavy snow				12. Others				
Under brid	1. Shinkanser				2. Railway				3. Highway				4. Road				
	5. River				6. Lake				7. Ravine				8. Valley				
	9. Waterway				10. Parking				11. Bike parkin				12. Park				
	13. Vacant				14. Harbor				Name ( Chao Phraya )								
Access method	Superstructure		1. Inspection car 2. Falsework 3. On ground 4. Ladder 5. Lift car 6. On boat 7. Special camera 8. Others ( )														
	Substructure		1. Inspection car 2. Falsework 3. On ground 4. Ladder 5. Lift car 6. On boat 7. Special camera 8. Others ( )														
	Reason		· All bridge section is on the water · If inspection car is not available, false work will be required														
Survey result	Camber deform		yes · no														
	Difference in glade		yes · no														
	Continuous of barrier		yes · no														
	Continuous of curve		yes · no														
	Noise		yes · no														
	Joint	Space change		yes · no													
		difference grade		yes · no													
		draining damage		yes · no													
Blocked drainage		yes · no															
Out line of damage	Crack of pavement		yes · no														
	Damage of lighting		yes · no														
	Damage of sign		-														
	Damage of handrail		yes · no														
	Possibility of scour		yes · no														
	Walkway yes · no																
	Vehicle yes · no																
Inspection way																	
Impressions			· Painting is renewd. But Reduction of steel thickness was seen at connection part bet and concrete slab.														
			· Rust was seen over paint, it might insufficinet of scraping before paint.														
			· Crack(0.8mm on top) and flacture of concrete was seen on slab of walkway														
Diagnosis	Height of girde		about 7.5m														
	◆ Deterioration of bridge ◆		deficient · fair · good														
	◆ Noticeable point ◆		· Corrosion of vertical membe · Breaking of slab														
History of repair			· Countermeasure was planed by ODA at 1982														
	Surveyor ;		Mr. Chujo, Mr. Kudo														

Present state （ 1 / 16 ）					
Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Krung Thep Bridge				

	Picture No.	1
	Span	1
	Member	Side view
	Picture No.	2
	Span	3
	Member	View on road
	Picture No.	3
	Span	1
	Member	View under girder



## Present state ( 2 / 16 )

Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Krung Thep Bridge				



Picture No.	4
Span	1
Member	Side view of side span



Picture No.	5
Span	1
Member	Side view of center sp



Picture No.	6
Span	1
Member	View of walkway

Present state ( 3 / 16 )

Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Krung Thep Bridge				



Picture No.	7
Span	1
Member	Approach bridge
Limit vehicle height 2.3m	



Picture No.	8
Span	1
Member	Expansion joint



Picture No.	9
Span	1
Member	Expansion joint
Deterioration of drainage function	



# Present state ( 4 / 16 )

Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Krung Thep Bridge				



Picture No.	10
Span	1
Member	Expansion joint
Height adjustment around joint	



Picture No.	11
Span	1
Member	Bearing
Locker bearing, Approach bridge	



Picture No.	12
Span	1
Member	Expansion joint
Fracture of concrete edge of locker bearing	
Falling of water proofing material	



## Present state ( 5 / 16 )

Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Krung Thep Bridge				

[illegible][illegible]


Picture No.	15
Span	1
Member	Center span
Hinge part	
Continuous vibration	
It is important to check fatigue crack around rotation center.	

# Present state ( 6 / 16 )

Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Krung Thep Bridge				



Picture No.	16
Span	1
Member	Stay cable
Hinge of drawbridge	
Mechanical parts is replaced every 2 years.	



Picture No.	17
Span	1
Member	Vertical member
Mount up around vertical member to prevent remaining water.	



Picture No.	18
Span	1
Member	Vertical member
Deterioration of calking in gap	

Present state ( 7 / 16 )					
Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Krung Thep Bridge				



Picture No.	19
Span	1
Member	Vertical member
Deterioration of calking.	



Picture No.	20
Span	1
Member	Chord member
Mark of repaired (bottom of picture repair by bolt.	



Picture No.	21
Span	1
Member	slab
Fracture of mortar for height adjustment	



Present state ( 8 / 16 )					
Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Krung Thep Bridge				



Picture No.	22
Span	1
Member	Center span
Fracture of mortar for height adjustment	



Picture No.	23
Span	1
Member	Center span
Manufactured by plasticity deformation	



Picture No.	24
Span	1
Member	Center span
Continuous vibration	
Painting is not	
塗装が完全ではない	




# Present state ( 9 / 16 )

Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Krung Thep Bridge				



Picture No.	25
Span	1
Member	Center span
Over coating is not painted lower side of flange.	



Picture No.	26
Span	1
Member	Center span
Middle splice plate is divided in 2 plate.	



Picture No.	27
Span	1
Member	Center span
Reduction of plate thickness of steel plate.	

# Present state (10/16)

Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Krung Thep Bridge				



Picture No.	28
Span	1
Member	Center span
Reduction of plate thickness of steel plate.	
There is no remaining water	



Picture No.	29
Span	1
Member	Center span
Dirt line is seen at bottom of we	
Possibility of remaining water and soil	



Picture No.	30
Span	1
Member	Center span
Difference at center joint	

# Present state (11/16)

Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Krung Thep Bridge				



Picture No.	31
Span	1
Member	Center span
Manhole	
Lost of bolt	
No key	



Picture No.	32
Span	1
Member	Center span
Door to access to center joint	



Picture No.	33
Span	1
Member	Center span
Rust from painting part	
Possibility of insuficient of scraping before painting	



# Present state (12/16)

Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Krung Thep Bridge				



Picture No.	34
Span	1
Member	Center span
Around center joint	
Change from revet to bolt	
Mark of remarkable corrosion	
Rust from painting part	
Possibility of insuficient of scraping before painting	



Picture No.	35
Span	1
Member	Center span
Deflection between vertical member?	



Picture No.	36
Span	1
Member	Center span
Inclination of locker bearing Bangkok side	



# Present state (13/16)

Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Krung Thep Bridge				



Picture No.	37
Span	1
Member	Vertical member
Reinforcement by additional plate	




Picture No.	38
Span	1
Member	Approach bridge
Exfoliation	



Picture No.	39
Span	1
Member	Approach bridge
Remaining water at shoe	

## Present state (14 / 16)

Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Krung Thep Bridge				

[illegible][illegible]

Picture No.	42
Span	1
Member	
Crack above bracket	
<i>*Survey on board, 31-oct</i>	



## Present state (15 / 16)

Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Krung Thep Bridge				



Picture No.	43
Span	1
Member	Slab
Fracture of slab on bracket	
<i>*Survey on board, 31-oct</i>	



Picture No.	44
Span	4
Member	Slab
Crack	
Free lime	
*Survey on board, 31-oct	



Picture No.	45
Span	3
Member	Slab
Center span	
<i>*Survey on board, 31-oct</i>	

## Present state (16 / 16)

Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Krung Thep Bridge				



Picture No.	46
Span	1
Member	Bearing

Deterioration of corrosion proofi

\*Survey on board, 31-oct

Picture No.	47
Span	1
Member	

Picture No.	48
Span	1
Member	



# Inspection sheet of visual survey

Bridge No. 18

Photo No. ( ~ )


Bridge name		RAMA IX Bridge		Route name		-		Authority		EXAT		Code of authority		-					
Place		from Khet Rat Burana to Khet Yan Nawa		Distance		from km+ 0 to km+ 0		Mr. Pittaya, Mr. Yadpong		Survey date		26-Oct-2009							
Bridge properties	Bridge type(1)		main road		side road		ramp		Camber deform		yes		no						
	Bridge type(2)		bridge		viaduct		plank pass		Difference in grade		yes		no						
	Bridge type(3)		7-span steel box girder cable stayed bridge										Continuous of barrier		yes		no		
	Total length		781.20 (m)										Continuous of curve		yes		no		
	Span		8 + 57.6 + 61.2 + 450 + 61.2 + 57.6 + 46.8 (m)										Noise		yes		no		
	Nos. of span		7 span										Space change		yes		no		
	Width		33.00 (m) / (m)										difference grade		yes		no		
	Completion		1987										draining damage		yes		no		
Road information	Horizontal		Straight		incli (θ = 2.5 %)		Curve (R m)		Blocked drainage		yes		no						
	Gradient		One way ( ↗ )		parabo ( ▭ )		( ▭ )		Crack of pavement		yes		no						
	Nearby tunnel		yes		no		( m )		Damage of lighting		yes		no						
	Nearby crossing		yes		no		( )		Damage of sign		-								
	Traffic		Much		Medium		Little		Damage of handrail		yes		no						
	Commercial traffic		Much		Medium		Little		Possibility of scour		yes		no						
													Walkway		yes		no		
													Vehicle		yes		no		
Environ	1. Urban		2. Suburbs		3. Mountain		4. Seaside		Inspection way										
	5. Industria		6. Harbor		7. Residential		8. Bussiness												
Under brid	1. Shinkanser		2. Railway		3. Highway		4. Road												
	5. River		6. Lake		7. Ravine		8. Valley												
Access metho	Superstructure		1. Inspection car 2. Falsework 3. On ground 4. Ladder 5. Lift car 6. On boat 7. Special camera 8. Others ( Inspection vehicle )										Height of girde		about 45m				
	Substructure		1. Inspection car 2. Falsework 3. On ground 4. Ladder 5. Lift car 6. On boat 7. Special camera 8. Others ( Inspection vehicle )										Deterioration of bridge		deficient		fair		
	Reason		False work might be prepared for pylon Inspection vehicle is set on center and side spar										Noticeable point						
													Under repairing work		from 2005				
												History of repair				Repaint ;		- yy - mm	
												Surveyor ;		Mr. Chujo, Mr. Kudo					

添付-207

添付資料

## Present state ( 1 / 9 )

Authority	EXAT	Address	Bangkok	Data	26-Oct-09
Bridge	RAMA IX Bridge				

[illegible][illegible]

Picture No.	3
Span	1
Member	View of connection girder
<i>*Survey on board, 31-oct</i>	

## Present state ( 2 / 9 )

Authority	EXAT	Address	Bangkok	Data	26-Oct-09
Bridge	RAMA IX Bridge				



Picture No.	4
Span	1
Member	View under bridge
Under repainting using inspection vehicle	
<i>*Survey on board, 31-oct</i>	

[illegible][illegible]




# Present state ( 3 / 9 )

Authority	EXAT	Address	Bangkok	Data	26-Oct-09
Bridge	RAMA IX Bridge				



Picture No.	7
Span	1
Member	Inspection vehicle


Preparing work for painting?



Picture No.	8
Span	1
Member	Pylon

Bottom flange is repainted.

Shrinkage crack is seen in pier.



Picture No.	9
Span	1
Member	Bottom flange

Deterioration of corrosion proofing



Present state ( 4 / 9 )					
Authority	EXAT	Address	Bangkok	Data	26-Oct-09
Bridge	RAMA IX Bridge				



Picture No.	10
Span	1
Member	Expansion joint
Replaced on Oct-2009	
Only surface plate was replaced	




Picture No.	11
Span	1
Member	Cable
Rocked coil cable.	
Outside was repainted.	




Picture No.	12
Span	1
Member	Cable damper


Present state ( 5 / 9 )					
Authority	EXAT	Address	Bangkok	Data	26-Oct-09
Bridge	RAMA IX Bridge				



Picture No.	7
Span	1
Member	Drainage
Guide of rain water	




Picture No.	8
Span	1
Member	Manhole




Picture No.	9
Span	1
Member	Walkway in girder




Present state ( 6 / 9 )					
Authority	EXAT	Address	Bangkok	Data	26-Oct-09
Bridge	RAMA IX Bridge				



Picture No.	10
Span	1
Member	Diaphragm
Mark of MT inspedction	





Picture No.	11
Span	1
Member	Bottom flange
Reinforcement by CFRT	



Picture No.	12
Span	1
Member	slab
Mark of deformation of member	
Axial stress is small at span cer	
Normaly, far from yield stress.	
It's not clear the deformation	
and reinforcement at this survev.	



Present state ( 7 / 9 )					
Authority	EXAT	Address	Bangkok	Data	26-Oct-09
Bridge	RAMA IX Bridge				
				Picture No.	13
				Span	1
				Member	Sensor
				Temperature sensor	
				Picture No.	14
				Span	1
				Member	Sensor
				Strain gauge	
				Picture No.	15
				Span	1
				Member	Sensor
				Accelerometer	

Present state ( 8 / 9 )					
Authority	EXAT	Address	Bangkok	Data	26-Oct-09
Bridge	RAMA IX Bridge				
				Picture No.	16
				Span	1
				Member	Girder damper
				4-damper in girder	
				Picture No.	17
				Span	1
				Member	Pavement
				All layer of pavement was replaced at 2005	
				Picture No.	18
				Span	1
				Member	slab

Present state ( 9 / 9 )

Authority	EXAT	Address	Bangkok	Data	26-Oct-09
Bridge	RAMA IX Bridge				



Picture No.	13
Span	1
Member	Meeting

Picture No.	14
Span	1
Member	

Picture No.	15
Span	1
Member	



# Inspection sheet of visual survey

Bridge No. 19


Photo No. ( ~ )


Bridge name		Industrial Ring Road North Bridge		Route name		-		Authority		DRR		Code of authority		-						
Place		from Ket Yan Nawa to Amphoe Phra Pradaeng		Distance		from km+ 0 to km+ 0						No.		-						
												Survey date		22-Oct-2009						
Bridge properties	Bridge type(1)	main road · side road · ramp																		
	Bridge type(2)	bridge · viaduct · plank pass																		
	Bridge type(3)	5-span composite I girder cable stayed bridge																		
	Total length	578.30 (m)																		
	Span	50.6 + 74.5 + 326 + 74.5 + 50.6 (m)																		
	Nos. of span	5 span																		
	Width	35.9 - 55.2 (m) / (m)																		
	Completion	2006																		
Road information	Horizontal	Straight · incli (θ = 2.5 %) · Curve (R m)																		
	Gradient	One way ( ↗ · ↘ ) parabo ( ▽ · ▹ )																		
	Nearby tunnel	yes · no ( m)																		
	Nearby crossing	yes · no ( ramp way )																		
	Traffic	Much · Medium · Little																		
	Commercial traffic	Much · Medium · Little																		
Environ	1. Urban	2. Suburbs			3. Mountain			4. Seaside												
	5. Industria	6. Harbor			7. Residential			8. Bussiness												
	9. Salty	10. Cold and snow			11. Heavy snow			12. Others												
	1. Shinkanser	2. Railway			3. Highway			4. Road												
	5. River	6. Lake			7. Ravine			8. Valley												
	9. Waterway	10. Parking			11. Bike parkin			12. Park												
	13. Vacant	14. Harbor			Name ( Chao Phraya )															
Access method	Superstructure	1. Inspection car 2. Falsework 3. On ground 4. Ladder 5. Lift car 6. On boat 7. Special camera 8. Others ( Inspection vehicle )																		
	Substructure	1. Inspection car 2. Falsework 3. On ground 4. Ladder 5. Lift car 6. On boat 7. Special camera 8. Others ( Inspection vehicle )																		
	Reason	· False work should be prepared for side span and p																		
Survey result	Camber deform	yes · no																		
	Difference in glade	yes · no																		
	Continuous of barrier	yes · no																		
	Continuous of curve	yes · no																		
	Noise	yes · no																		
	Space change	yes · no																		
	difference grade	yes · no																		
	draining damage	yes · no																		
Joint	Blocked drainage	yes · no																		
	Crack of pavement	yes · no																		
	Damage of lighting	yes · no																		
	Damage of sign	-																		
	Damage of handrail	yes · no																		
	Possibility of scour	yes · no																		
	Walkway	yes · no																		
	Vehicle	yes · no																		
Inspection way																				
Out line of damage	Item	Type		State																
	Main girder	Composite I girder		-																
	Cross beam	I section steel		-																
	Stringer	-		-																
	Cross frame	-		-																
	Lateral brace	-		-																
	Slab			Crack around fixing structure, free lime																
	Abutment	-		-																
Impressions	Pier	Rectangular		Crack around cross beam																
	Bearing	Fix at pylon		-																
	Barrier	Trapezoidal, steel		Generally healthy																
	Railing	Stainless		Generally healthy																
	Curb	-		-																
	Pavement	asphalt · concrete		-																
	Joint	drained · undrained		Occurrence of sound of impact																
	Drainage	yes · no																		
History of repair	· Occurrence of sound of impact and jumping by heavy vehicle at at expansion joint · Crack is seen in pylon around cross beam end. It is required detailed investigation. especially in the case of increasing the defect after completion. · Improvement around fixing structure is recommended.																			
Surveyor ;	Mr. Chujo, Mr. Kudo										Repaint ;					- yy - mm				


添付-217

添付資料


Present state ( 1 / 14 )					
Authority	DRR	Address	Bangkok	Data	22-Oct-09
Bridge	Industrial Ring Road Bridge (North)				

	Picture No.	1
	Span	1
	Member	Side view
<i>*Survey on board, 31-oct</i>		


	Picture No.	2
	Span	2
	Member	View on road

	Picture No.	3
	Span	1
	Member	View of connection gir
	<i>*Survey on board, 31-oct</i>	


Present state ( 2 / 14 )					
Authority	DRR	Address	Bangkok	Data	22-Oct-09
Bridge	Industrial Ring Road Bridge (North)				



Picture No.	4
Span	1
Member	View under bridge
<i>*Survey on board, 31-oct</i>	






Picture No.	5
Span	1
Member	Pylon




Picture No.	6
Span	1
Member	Inspection way




Present state （ 3 / 14 ）					
Authority	DRR	Address	Bangkok	Data	22-Oct-09
Bridge	Industrial Ring Road Bridge (North)				

	Picture No.	7
	Span	1
	Member	Cable fixing part
	Picture No.	8
	Span	1
	Member	Vertical alignment
	Saged vertical alignment	
	Picture No.	9
	Span	1
	Member	Vertical alignment
	Saged vertical alignment	


Present state ( 4 / 14 )					
Authority	DRR	Address	Bangkok	Data	22-Oct-09
Bridge	Industrial Ring Road Bridge (North)				



Picture No.	10
Span	1
Member	Expansion joint
South side. Adjustment of difference of grade	



Picture No.	11
Span	1
Member	Expansion joint
North side.	
Occurrence of sound of impact	
Jumping by heavy vehicle	



Picture No.	12
Span	1
Member	Expansion joint
Looseness of bolt	

Present state ( 5 / 14 )

Authority	DRR	Address	Bangkok	Data	22-Oct-09
Bridge	Industrial Ring Road Bridge (North)				

	Picture No.	7
	Span	1
	Member	Expansion joint
	Connection between main bridge and ramp. No spacing	
	Picture No.	8
	Span	1
	Member	Stay cable
	Picture No.	9
	Span	1
	Member	Stay cable
	Peeling of projection material for cable vibration control	



Present state ( 6 / 14 )					
Authority	DRR	Address	Bangkok	Data	22-Oct-09
Bridge	Industrial Ring Road Bridge (North)				



Picture No.	10
Span	1
Member	Stay cable
ooze out of grease	



Picture No.	11
Span	1
Member	Inspection vehicle






Picture No.	12
Span	1
Member	slab
Crack from cable fixing structure	
It is striking cables near pylon	

Present state ( 7 / 14 )					
Authority	DRR	Address	Bangkok	Data	22-Oct-09
Bridge	Industrial Ring Road Bridge (North)				

	Picture No.	13
	Span	1
	Member	slab
	Crack from cable fixing structure	
	0.1mm~0.2mm	


	Picture No.	14
	Span	1
	Member	slab
	Crack from cable fixing structure	


	Picture No.	15
	Span	1
	Member	slab
	Remaining water	


Present state （ 8 / 14 ）					
Authority	DRR	Address	Bangkok	Data	22-Oct-09
Bridge	Industrial Ring Road Bridge (North)				
			Picture No.	16	
			Span	1	
			Member	slab	
			Accumulaton soil at fixing struct		
			Picture No.	17	
			Span	1	
			Member	slab	
			Accumulaton soil at fixing struct		
			Picture No.	18	
			Span	1	
			Member	slab	
			Remaining water and deterioration of corrosion proofi		



Present state ( 9 / 14 )					
Authority	DRR	Address	Bangkok	Data	22-Oct-09
Bridge	Industrial Ring Road Bridge (North)				

	Picture No.	13
	Span	1
	Member	slab
	Crack from cable fixing structure	
	PC girder part	

	Picture No.	14
	Span	1
	Member	slab
	Crack from cable fixing structure	
	0.1mm~0.15mm	
	PC girder part	

	Picture No.	15
	Span	1
	Member	slab
	crack	
	PC girder part	

# Present state (10/14)

Authority	DRR	Address	Bangkok	Data	22-Oct-09
Bridge	Industrial Ring Road Bridge (North)				



Picture No.	16
Span	1
Member	slab
Peeling of concrete	



Picture No.	17
Span	1
Member	slab
Fixing structure	
Mold?	




Picture No.	18
Span	1
Member	slab
Remaining water	

Present state (11 / 14)					
Authority	DRR	Address	Bangkok	Data	22-Oct-09
Bridge	Industrial Ring Road Bridge (North)				
			Picture No.	19	
			Span	1	
			Member	Pylon	
			crack around cross beam end		
			Picture No.	20	
			Span	1	
			Member	Pylon	
			crack around cross beam end		
			Picture No.	21	
			Span	1	
			Member	Lighting	
			Continuous vibration of pole		
			Possibility of fatigue crack		




Present state (12/14)					
Authority	DRR	Address	Bangkok	Data	22-Oct-09
Bridge	Industrial Ring Road Bridge (North)				



Picture No.	22
Span	1
Member	Electric wire




Picture No.	23
Span	1
Member	Lighting pole
Gap between base plate and foundation	




Picture No.	24
Span	1
Member	Lighting pole
Gap between base plate and foundation	


Present state (13/14)					
Authority	DRR	Address	Bangkok	Data	22-Oct-09
Bridge	Industrial Ring Road Bridge (North)				

	Picture No.	25
	Span	1
	Member	Newel


	Picture No.	26
	Span	1
	Member	Electric wire
	Lost of cover and looseness of bc	

	Picture No.	27
	Span	1
	Member	Drainage


Present state (14/14)					
Authority	DRR	Address	Bangkok	Data	22-Oct-09
Bridge	Industrial Ring Road Bridge (North)				



Picture No.	28
Span	1
Member	
North bridge- South pylon - cente	
crack	
*Survey on board, 31-oct	



Picture No.	29
Span	1
Member	
North bridge - North pylon - cent	
crack	
*Survey on board, 31-oct	



Picture No.	30
Span	1
Member	
North bridge - North pylon - cent	
crack	
*Survey on board, 31-oct	




# Inspection sheet of visual survey


Bridge No. 20


Photo No. ( ~ )

Bridge name		Industrial Ring Road South Bridge		Route name		-		Authority		DRR		Code of authority		-		
Place		from Bangkok		Distance		from km+ 0						No.		-		
		to				to km+ 0						Survey date		22-Oct-2009		
Bridge properties	Bridge type(1)		main road · side road · ramp													
	Bridge type(2)		bridge · viaduct · plank pass													
	Bridge type(3)		5-span composite I girder cable stayed bridge													
	Total length		702.30 (m)													
	Span		68.6 + 83.5 + 398 + 83.5 + 68.6 (m)													
	Nos. of span		5 span													
	Width		35.9 - 55.2 (m) / (m)													
	Completion		2006													
Road information	Horizontal		Straight · incli ( $\theta = 2.5$ % ) · Curve ( R m )													
	Gradient		One way ( ↗ · ↘ ) parabo ( ▴ · ▽ )													
	Nearby tunnel		yes · no ( m )													
	Nearby crossing		yes · no ( ramp way )													
	Traffic		Much · Medium · Little													
	Commercial traffic		Much · Medium · Little													
Environ	1. Urban		2. Suburbs		3. Mountain		4. Seaside									
	5. Industria		6. Harbor		7. Residential		8. Bussiness									
	9. Salty		10. Cold and snow		11. Heavy snow		12. Others									
Under brid	1. Shinkanser		2. Railway		3. Highway		4. Road									
	5. River		6. Lake		7. Ravine		8. Valley									
	9. Waterway		10. Parking		11. Bike parkin		12. Park									
	13. Vacant		14. Harbor		Name ( Chao Phraya )											
Access method	Superstructure		1. Inspection car 2. Falsework 3. On ground 4. Ladder 5. Lift car 6. On boat 7. Special camera 8. Others ( Inspection vehicle )													
	Substructure		1. Inspection car 2. Falsework 3. On ground 4. Ladder 5. Lift car 6. On boat 7. Special camera 8. Others ( Inspection vehicle )													
	Reason		· False work should be prepared for side span and p													
Survey result	Camber deform		yes · no													
	Difference in glade		yes · no													
	Continuous of barrier		yes · no													
	Continuous of curve		yes · no													
Joint	Noise		yes · no													
	Space change		yes · no													
	difference grade		yes · no													
	draining damage		yes · no													
Blocked drainage	Blocked drainage		yes · no													
	Crack of pavement		yes · no													
	Damage of lighting		yes · no													
	Damage of sign		-													
Damage of handrail	Damage of handrail		yes · no													
	Possibility of scour		yes · no													
	Walkway		yes · no													
	Vehicle		yes · no													
Inspection way	Height of girde		about 55m													
Out line of damage	Item		Type		State											
	Main girder		Composite I girder		-											
	Cross beam		I section steel		-											
	Stringer		-		-											
Cross frame	Cross frame		-		-											
	Lateral brace		-		-											
	Slab				Crack around fixing structure, free lime											
	Abutment		-		-											
Pier	Pier		Rectangular		Crack around cross beam											
	Bearing		Fix at pylon		-											
	Barrier		Trapezoidal, steel		Generally healthy											
	Railing		Stainless		Generally healthy											
Curb	Curb		-		-											
	Pavement		asphalt · concrete		-											
	Joint		drained · undrained		-											
	Drainage		yes · no		-											
Impressions																
History of repair												Repaint ;		- yy - mm		
Surveyor ;		Mr. Chujo, Mr. Kudo														

Present state ( 1 / 5 )					
Authority	DRR	Address	Bangkok	Data	22-Oct-09
Bridge	Industrial Ring Road Bridge (South)				

	Picture No.	1
	Span	1
	Member	Side view
	<i>*Survey on board, 31-oct</i>	

	Picture No.	2
	Span	1
	Member	View on road

	Picture No.	3
	Span	1
	Member	View under girder

Present state ( 2 / 5 )					
Authority	DRR	Address	Bangkok	Data	22-Oct-09
Bridge	Industrial Ring Road Bridge (South)				


	Picture No.	4
	Span	1
	Member	Inspection way

	Picture No.	5
	Span	1
	Member	Inspection vehicle


	Picture No.	6
	Span	1
	Member	Inspection vehicle




Present state ( 3 / 5 )					
Authority	DRR	Address	Bangkok	Data	22-Oct-09
Bridge	Industrial Ring Road Bridge (South)				



Picture No.	7
Span	1
Member	slab bottom surface
Free lime from filled hole	




Picture No.	8
Span	1
Member	slab
Crack from cable fixing structure	



Picture No.	9
Span	1
Member	bottom slab
Crack from cable fixing structure	
0.15mm - 0.3mm	

# Present state ( 4 / 5 )


Authority	DRR	Address	Bangkok	Data	22-Oct-09
Bridge	Industrial Ring Road Bridge (South)				



Picture No.	10
Span	1
Member	bottom slab
Back surface of crack around fixed	
Crack cannot find from inspection vehicle (about 2m from eye height)	



Picture No.	11
Span	1
Member	Connection girder
Inside of connection girder	
Harm of bird	



Picture No.	12
Span	1
Member	Pylon
Vertical crack at cross beam end	
Inclined crack of pylon shaft	
Opening construction joint	

**Present state ( 5 / 5 )**

Authority	DRR	Address	Bangkok	Data	22-Oct-09
Bridge	Industrial Ring Road Bridge (South)				



Picture No.	7
Span	1
Member	Pylon

Vertical crack of pylon shaft

Possibility of shirincage crack during construction is high.
--



Picture No.	8
Span	1
Member	Pylon

Crack
-------

\*Survey on board, 31-oct



Picture No.	9
Span	1
Member	PC girder

\*Survey on board, 31-oct