

Inspection sheet of visual survey

 Bridge No. 10

Photo No. (~)

Bridge name		Krung Thon Bridge		Route name	-		Authority	Code of authority	-		
Place		from Khat Bang Phlat to Khet Dusit		Distance	from	km+	0	No.	-		
					to	km+	0	Survey date	2009/10/24		
Bridge properties	Bridge type(1)	<input checked="" type="checkbox"/> main road · <input type="checkbox"/> side road · <input type="checkbox"/> ramp		Camber deform	yes · <input checked="" type="checkbox"/> no		Outline of damage	Item	Type	State	
	Bridge type(2)	<input checked="" type="checkbox"/> bridge · <input type="checkbox"/> viaduct · <input type="checkbox"/> plank pass		Difference in grade	yes · <input checked="" type="checkbox"/> no			Main girder	Truss	Corrosion, Deterioration of proofing, deformation by collision	
	Bridge type(3)	6-span steel truss		Continuous of barrier	<input checked="" type="checkbox"/> yes · <input type="checkbox"/> no			Cross beam	I section steel	-	
	Total length	360.00 (m)		Continuous of curve	<input checked="" type="checkbox"/> yes · <input type="checkbox"/> no			Stringer	I section steel	Deterioration of proofing	
	Span	58 + 58 + 64 + 64 + 58 + 58 (m)		Noise	yes · <input checked="" type="checkbox"/> no			Cross frame	T section steel	Expansion by corrosion	
	Nos. of span	6 span		Space change	yes · <input checked="" type="checkbox"/> no			Lateral brace	-	-	
	Width	12.00 (m) / (m)		difference grade	yes · <input checked="" type="checkbox"/> no			Slab	-	Crack, free lime, Exfoliation	
	Completion	1958		draining damage	<input checked="" type="checkbox"/> yes · <input type="checkbox"/> no			Abutment	-	-	
Road information	Horizontal	<input checked="" type="checkbox"/> Straight · <input type="checkbox"/> incli(= 1.7 %) · Curve (R m)		Blocked drainage	<input checked="" type="checkbox"/> yes · <input type="checkbox"/> no			Pier	Rectangular	-	
	Gradient	One way () · <input type="checkbox"/> parabo (<input type="checkbox"/> · <input type="checkbox"/>)		Crack of pavement	<input checked="" type="checkbox"/> yes · <input type="checkbox"/> no			Bearing	Pin bearing	Corrosion, accumulation of soil, flucture of locker bearing	
	Nearby tunnel	yes · <input checked="" type="checkbox"/> no (m)		Damage of lighting	yes · <input checked="" type="checkbox"/> no		Barrier	Trapezoidal	Flucture of edge		
	Nearby crossing	yes · <input checked="" type="checkbox"/> no (m)		Damage of sign	-		Railing	Steel	Generally healthy		
	Traffic	Much · <input checked="" type="checkbox"/> Medium · <input type="checkbox"/> Little		Damage of handrail	yes · <input checked="" type="checkbox"/> no		Curb	-	-		
	Commercial traffic	Much · <input type="checkbox"/> Medium · <input checked="" type="checkbox"/> Little		Possibility of scour	<input checked="" type="checkbox"/> yes · <input type="checkbox"/> no		Pavement	<input checked="" type="checkbox"/> asphalt · <input type="checkbox"/> concrete	Generally healthy		
Environment	1.Urban		2.Suburbs		3.Mountain		4.Seaside		Impressions		
	5.Industrial		6.Harbor		7.Residential		8.Bussiness				
	9.Salty		10.Cold and snow		11.Heavy snow		12.Others				
Under bridge	1.Shinkansen		2.Railway		3.Highway		4.Road				
	<input checked="" type="checkbox"/> 5.River		6.Lake		7.Ravine		8.Valley				
	9.Waterway		10.Parking		11.Bike parkin		12.Park				
	13.Vacant		14.Harbor		Name (Chao Phraya)						
Access method	Superstructure	1.Inspection car 2.Falsework 3.On ground 4.Ladder 5.Lift car 6.On boat 7.Special camera 8.Others()		Walkway	yes · <input checked="" type="checkbox"/> no		Diagnosis	· scour (information from DRR)			
	Substructure	1.Inspection car 2.Falsework 3.On ground 4.Ladder 5.Lift car 6.On boat 7.Special camera 8.Others()		Vehicle	yes · <input checked="" type="checkbox"/> no			· Remarkable crack and exfoliation is found at bottom surface of walkway			
	Reason	· All bridge section is on the water · If inspection car is not available, false work will be required		Height of girde	about 8.5m			· Some drainage pipe was drop off			
						· Condision of painting is not bad, but some plate thickness was reduced by corrosion Especially flange of bracket should be take care a strength.					
						· Deformation by ship collision was found at 1 center span.					
						History of repair ; · Detail survey was finished on Sep.2009					
						Surveyor ; Mr.Chujo, Mr.Kudo					
						Repaint ; - yy - mm					

Ap-145

Appendices

Present state (7 / 19)					
Authority	DRR	Address	Bangkok	Data	24-Oct-09
Bridge	Krung Thon Bridge				



Picture No.	19
Span	1
Member	Bearing
Deterioration of corrosion proof i	
Fracture of edge	
Approach bridge	



Picture No.	20
Span	1
Member	Bearing
Bearing on cross beam between main girder	
Approach bridge	



Picture No.	21
Span	1
Member	Bearing
Deterioration of corrosion proof i	

Present state (9 / 19)					
Authority	DRR	Address	Bangkok	Data	24-Oct-09
Bridge	Krung Thon Bridge				



Picture No.	25
Span	1
Member	Bearing
Rivet at bottom side is replaced by bolt	
It might be corroded before	



Picture No.	26
Span	1
Member	Cross frame
Peeling of paint	
Expansion of steel by corrosion	



Picture No.	27
Span	1
Member	Bearing
Accumulation of soil	

Present state (13 / 19)

Authority	DRR	Address	Bangkok	Data	24-Oct-09
Bridge	Krung Thon Bridge				



Picture No.	37
Span	1
Member	Upper chord
Deterioration of corrosion proof	



Picture No.	38
Span	1
Member	Vertical member
Reinforcement by additional plate	
4-vertical member was reinforced	



Picture No.	39
Span	1
Member	Cross frame
Deformation at the end of cross frame	
Adjustment of height?	

Present state (15 / 19)

Authority	DRR	Address	Bangkok	Data	24-Oct-09
Bridge	Krung Thon Bridge				



Picture No.	43
Span	1
Member	Slab
Slab under walkway	
Crack and free lime	




Picture No.	44
Span	1
Member	Slab
Exposure of rebar	
Crack above bracket	



Picture No.	45
Span	1
Member	slab
Exposure of rebar	

Present state (17 / 19)

Authority	DRR	Address	Bangkok	Data	24-Oct-09
Bridge	Krung Thon Bridge				



Picture No.	49
Span	1
Member	Under bridge
Residence under bridge	
Bangkok side	



Picture No.	50
Span	1
Member	Slab
Signboard of inspection and repairing work	
150days from 2009.Feb	
Consultant is Norconsultant	



Picture No.	51
Span	1
Member	Substructure
*Survey on board, 31-oct	

Present state (18 / 19)

Authority	DRR	Address	Bangkok	Data	24-Oct-09
Bridge	Krung Thon Bridge				



Picture No.	52
Span	1
Member	Slab
Falling of drainage pipe	
*Survey on board, 31-oct	



Picture No.	53
Span	1
Member	slab
Crack and free lime under walkway	
*Survey on board, 31-oct	



Picture No.	54
Span	1
Member	Slab
Crack and free lime under walkway	
*Survey on board, 31-oct	

Present state (19 / 19)

Authority	DRR	Address	Bangkok	Data	24-Oct-09
Bridge	Krung Thon Bridge				



Picture No.	55
Span	1
Member	Slab
Deformation by ship collision	
*Survey on board, 31-oct	



Picture No.	56
Span	1
Member	Water supply
Deterioration of corrosion proofing	
*Survey on board, 31-oct	



Picture No.	57
Span	1
Member	

Inspection sheet of visual survey

 Bridge No. 11

Photo No. (~)

Bridge name		RAMA VIII Bridge		Route name	-		Authority		BMA		Code of authority	-		
Place	from	Khat Bang Phlat		Distance	from	km+	0		Survey date	23-Oct-2009				
	to	Khet Phra Nakhon			to	km+	0							
Bridge properties	Bridge type(1)	<input type="checkbox"/> main road · <input type="checkbox"/> side road · <input type="checkbox"/> ramp		Survey result	Camber deform	yes	<input type="checkbox"/> no		Outline of damage	Item	Type	State		
	Bridge type(2)	<input type="checkbox"/> bridge · <input type="checkbox"/> viaduct · <input type="checkbox"/> plank pass			Difference in grade	yes	<input type="checkbox"/> no			Main girder	Composite I girder	-		
	Bridge type(3)	4-span composite 2 I girder cable stayed bridge			Continuous of barrier	yes	<input type="checkbox"/> no			Cross beam	I section steel	-		
	Total length	475.00 (m)			Continuous of curve	yes	<input type="checkbox"/> no			Stringer	-	-		
	Span	75 + 50 + 50 + 300 (m)			Noise	yes	<input type="checkbox"/> no			Cross frame	-	-		
	Nos. of span	4 span			Space change	yes	<input type="checkbox"/> no			Lateral brace	-	-		
	Width	29.20 (m) / (m)			difference grade	yes	<input type="checkbox"/> no			Slab	-	(cannot see from outside due to decorative plate)		
	Completion	2002			draining damage	yes	<input type="checkbox"/> no			Abutment	-	-		
Road information	Horizontal	<input type="checkbox"/> Straight · <input type="checkbox"/> incli(= 2 %) · Curve (R m)		Blocked drainage	yes	<input type="checkbox"/> no		Pier		Rectangular	Free lime at cross beam			
	Gradient	One way (·) <input type="checkbox"/> parabo (<input type="checkbox"/> · <input type="checkbox"/>)		Crack of pavement	yes	<input type="checkbox"/> no		Bearing		Slide bearing	-			
	Nearby tunnel	yes · <input type="checkbox"/> no (m)		Damage of lighting	yes	<input type="checkbox"/> no		Barrier		Steel	Generally healthy			
	Nearby crossing	yes · no (ramp way)		Damage of sign	-		Railing	Steel		Generally healthy				
	Traffic	Much · <input type="checkbox"/> Medium · Little		Damage of handrail	yes	<input type="checkbox"/> no		Curb		-	-			
	Commercial traffic	Much · Medium · <input type="checkbox"/> Little		Possibility of scour	yes	<input type="checkbox"/> no		Pavement		<input type="checkbox"/> asphalt · <input type="checkbox"/> concrete	Pot hole			
Environment	1.Urban		2.Suburbs		3.Mountain		4.Seaside		Impressions					
	5.Industrial		6.Harbor		7.Residential		8.Business							
9.Salty		10.Cold and snow		11.Heavy snow		12.Others								
Under bridge	1.Shinkansen		2.Railway		3.Highway		4.Road							
	5.River		6.Lake		7.Ravine		8.Valley							
	9.Waterway		10.Parking		11.Bike parkin		12.Park							
	13.Vacant		14.Harbor		Name (Chao Phraya)									
Access method	Superstructure	1.Inspection car		2.Falsework		3.On ground		4.Ladder		5.Lift car				
	Substructure	1.Inspection car		2.Falsework		3.On ground		4.Ladder		5.Lift car				
	Reason	· Center span section is on the water · If inspection car is not available, false work will be required												
Diagnosis	Height of girder		about 10m		Deterioration of bridge		deficient · fair · <input type="checkbox"/> good			History of repair		Repaint ; - yy - mm		
	Noticeable point		· Leakage form cable		Surveyor ;		Mr,Chujo, Mr.Kudo							

Ap-165

Appendices

Present state (4 / 8)

Authority	BMA	Address	Bangkok	Data	23-Oct-09
Bridge	RAMA VIII				



Picture No.	10
Span	1
Member	Cable fixing structure
Gap and calking between cable and slab. And mounted up around cable to prevent remaining water.	



Picture No.	11
Span	1
Member	Cable fixing structure
slab. And mounted up around cable to prevent remaining water.	



Picture No.	12
Span	1
Member	Cable fixing structure
Calking and name plate of cable	
well maintained but aging	

Inspection sheet of visual survey

 Bridge No. 12

Photo No. (~)

Bridge name		Pinklao Bridge		Route name	-		Authority	DRR	Code of authority	-		
Place	from	Khat Bangkok Noi		Distance	from	km+	0	Survey date	2009/10/23			
	to	Khet Phra Nakhon			to	km+	0					
Bridge properties	Bridge type(1)	<input type="checkbox"/> main road · <input type="checkbox"/> side road · <input type="checkbox"/> ramp		Survey result	Camber deform	<input type="checkbox"/> yes · <input type="checkbox"/> no		Outline of damage	Item	Type	State	
	Bridge type(2)	<input type="checkbox"/> bridge · <input type="checkbox"/> viaduct · <input type="checkbox"/> plank pass			Difference in grade	<input type="checkbox"/> yes · <input type="checkbox"/> no			Main girder	PC-Box	Leakage from box girder	
	Bridge type(3)	3-span continuous PC box girder			Continuous of barrier	<input checked="" type="checkbox"/> yes · <input type="checkbox"/> no			Cross beam	-	-	
	Total length	276.00 (m)			Continuous of curve	<input checked="" type="checkbox"/> yes · <input type="checkbox"/> no			Stringer	-	-	
	Span	83 + 110 + 83 (m)			Noise	<input type="checkbox"/> yes · <input type="checkbox"/> no			Cross frame	-	-	
	Nos. of span	4 span			Space change	<input type="checkbox"/> yes · <input type="checkbox"/> no			Lateral brace	-	-	
	Width	32.21 (m) / (m)			difference grade	<input type="checkbox"/> yes · <input type="checkbox"/> no			Slab	free lime		
	Completion	1973			draining damage	<input checked="" type="checkbox"/> yes · <input type="checkbox"/> no			Abutment	-	-	
Road information	Horizontal	<input type="checkbox"/> Straight · <input type="checkbox"/> incli(= °) · Curve (R m)		Joint	Blocked drainage	<input checked="" type="checkbox"/> yes · <input type="checkbox"/> no			Pier	Rectangular	-	
	Gradient	One way () · <input type="checkbox"/> parabo (<input type="checkbox"/> · <input type="checkbox"/>)			Crack of pavement	<input type="checkbox"/> yes · <input type="checkbox"/> no			Bearing	Slide bearing	-	
	Nearby tunnel	<input type="checkbox"/> yes · <input checked="" type="checkbox"/> no (m)			Damage of lighting	<input checked="" type="checkbox"/> yes · <input type="checkbox"/> no			Barrier	Steel	Generally healthy	
	Nearby crossing	<input type="checkbox"/> yes · <input checked="" type="checkbox"/> no (m)			Damage of sign	-			Railing	Steel	Generally healthy	
	Traffic	Much · <input checked="" type="checkbox"/> Medium · Little			Damage of handrail	<input type="checkbox"/> yes · <input type="checkbox"/> no			Curb	-	-	
	Commercial traffic	Much · <input checked="" type="checkbox"/> Medium · Little			Possibility of scour	<input checked="" type="checkbox"/> yes · <input type="checkbox"/> no			Pavement	<input checked="" type="checkbox"/> asphalt · concrete	Generally healthy	
Environment	1.Urban		2.Suburbs		3.Mountain		4.Seaside		Impressions			
	5.Industrial		6.Harbor		7.Residential		8.Bussiness					
	9.Salty		10.Cold and snow		11.Heavy snow		12.Others					
	1.Shinkansen		2.Railway		3.Highway		4.Road					
Under bridge	5.River		6.Lake		7.Ravine		8.Valley					
	9.Waterway		10.Parking		11.Bike parkin		12.Park					
	13.Vacant		14.Harbor		Name (Chao Phraya)							
Access method	Superstructure	1.Inspection car 2.Falsework 3.On ground 4.Ladder 5.Lift car 6.On boat 7.Special camera 8.Others()		Inspection way	Walkway	<input type="checkbox"/> yes · <input type="checkbox"/> no		History of repair		· Sever leakage from expansion joint		
	Substructure	1.Inspection car 2.Falsework 3.On ground 4.Ladder 5.Lift car 6.On boat 7.Special camera 8.Others()			Vehicle	<input type="checkbox"/> yes · <input type="checkbox"/> no				· Water flow in box girder may cause defect in box.		
	Reason	· All bridge section is on the water · If inspection car is not available, false work will be required			Diagnosis	Height of girde	about 11.5m			· Crack of pier of approach bridge		
			Deterioration of bridge	deficient · <input checked="" type="checkbox"/> fair · good								
			Noticeable point	· Crack of pier of approach · Leackage from manhole								
										Repaint ; - yy - mm		
						Surveyor ;			Mr.Chujo, Mr.Kudo			

Ap-174

Appendices

Present state (4 / 7)

Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Phra Pin Klao Bridge				



Picture No.	10
Span	1
Member	Approach bridge
Crack	




Picture No.	11
Span	1
Member	Man hole
Leakage from manhole	
Leakage from water supply?	



Picture No.	12
Span	1
Member	Pylon
Mark of leakage from joint of barrier	

Present state (6 / 7)


Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Phra Pin Klao Bridge				



Picture No.	16
Span	1
Member	Slab
Free lime from construction joint	
*Survey on board, 31-oct	



Picture No.	17
Span	1
Member	Hinge
Leakage	
*Survey on board, 31-oct	



Picture No.	18
Span	1
Member	Slab
Nest harm	
*Survey on board, 31-oct	

Inspection sheet of visual survey

 Bridge No. 13

Photo No. (~)

Bridge name		Memorial Bridge		Route name		-		Authority		DRR Code of authority - No. - Survey date 2009/10/23	
Place	from	Khat Thon Buri		Distance	from	km+	0				
	to	Khet Phra Nakhon			to	km+	0				
Bridge properties	Bridge type(1)	<input checked="" type="checkbox"/> main road <input type="checkbox"/> side road <input type="checkbox"/> ramp		Survey result	Camber deform		<input checked="" type="checkbox"/> yes <input type="checkbox"/> no	Outline of damage	Item	Type	State
	Bridge type(2)	<input checked="" type="checkbox"/> bridge <input type="checkbox"/> viaduct <input type="checkbox"/> plank pass			Difference in grade		<input checked="" type="checkbox"/> yes <input type="checkbox"/> no		Main girder	Truss	Corrosion, Deterioration of proofing, deformation by collision
	Bridge type(3)	3-span steel truss			Continuous of barrier		<input checked="" type="checkbox"/> yes <input type="checkbox"/> no		Cross beam	I section steel	-
	Total length	234.00 (m)			Continuous of curve		<input checked="" type="checkbox"/> yes <input type="checkbox"/> no		Stringer	I section steel	-
	Span	78 + 78 + 78 (m)			Noise		<input checked="" type="checkbox"/> yes <input type="checkbox"/> no		Cross frame	T section steel	Deformation by collision
	Nos. of span	3 span			Space change		<input checked="" type="checkbox"/> yes <input type="checkbox"/> no		Lateral brace	-	-
	Width	10.00 (m) / (m)			Joint difference grade		<input checked="" type="checkbox"/> yes <input type="checkbox"/> no		Slab	-	Crack (under and top of road, under walkway), free lime,
	Completion	1932			draining damage		<input checked="" type="checkbox"/> yes <input type="checkbox"/> no		Abutment	-	-
Road information	Horizontal	<input checked="" type="checkbox"/> Straight <input type="checkbox"/> incli (= °) <input type="checkbox"/> Curve (R m)		Blocked drainage		<input checked="" type="checkbox"/> yes <input type="checkbox"/> no	Pier	Octagon	-		
	Gradient	One way () <input type="checkbox"/> parabo (<input type="checkbox"/> · <input type="checkbox"/>)		Crack of pavement		<input checked="" type="checkbox"/> yes <input type="checkbox"/> no	Bearing	Pin bearing	Deterioration of proofing of anchor bolt		
	Nearby tunnel	<input checked="" type="checkbox"/> yes <input type="checkbox"/> no (m)		Damage of lighting		<input checked="" type="checkbox"/> yes <input type="checkbox"/> no	Barrier	-	-		
	Nearby crossing	<input checked="" type="checkbox"/> yes <input type="checkbox"/> no (m)		Damage of sign		-	Railing	Steel	Generally healthy		
	Traffic	Much · <input checked="" type="checkbox"/> Medium · <input type="checkbox"/> Little		Damage of handrail		<input checked="" type="checkbox"/> yes <input type="checkbox"/> no	Curb	-	-		
	Commercial traffic	Much · Medium · <input checked="" type="checkbox"/> Little		Possibility of scour		<input checked="" type="checkbox"/> yes <input type="checkbox"/> no	Pavement	<input checked="" type="checkbox"/> asphalt · <input type="checkbox"/> concrete	Generally healthy		
Environment	1.Urban 2.Suburbs 3.Mountain 4.Seaside		Walkway		<input checked="" type="checkbox"/> yes <input type="checkbox"/> no	Joint	<input checked="" type="checkbox"/> drained · <input type="checkbox"/> indrained	Partly leakage			
	5.Industrial 6.Harbor 7.Residential 8.Bussiness		Vehicle		<input checked="" type="checkbox"/> yes <input type="checkbox"/> no (center span)	Drainage	<input checked="" type="checkbox"/> yes · <input type="checkbox"/> no	Blocked			
	9.Salty 10.Cold and snow 11.Heavy snow 12.Others		Inspection way								
Under bridge	1.Shinkansen 2.Railway 3.Highway 4.Road		Deterioration of bridge		deficient · <input checked="" type="checkbox"/> fair · good		Impressions				
	5.River 6.Lake 7.Ravine 8.Valley		Noticeable point		· Deformation by collision						
	9.Waterway 10.Parking 11.Bike parkin 12.Park		· Corrosion of some member		· Crack under walkway						
Access method	Superstructure		1.Inspection car 2.Falsework 3.On ground 4.Ladder 5.Lift car		Height of girde		about 7.3m				
	Substructure		1.Inspection car 2.Falsework 3.On ground 4.Ladder 5.Lift car								
	Reason		· All bridge section is on the water · If inspection car is not available, false work will be required for center span								
						History of repair		· Maintenance and repairing work was done by ODA at 1984 Repaint ; - yy - mm			
						Surveyor ;		Mr.Chujo, Mr.Kudo			

Ap-182


Appendices

Present state (3 / 18)

Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Memorial Bridge				



Picture No.	7
Span	1
Member	material
The material made in England	
It's seems that same fabricator provide material for repairing wo	




Picture No.	8
Span	1
Member	Material
A325 (ASTM), NKYM	
High tension bolt produced MISUBOSHI	



Picture No.	9
Span	1
Member	Inspection vehicle
Han powered inspection vehicle.	

Present state (4 / 18)

Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Memorial Bridge				



Picture No.	10
Span	1
Member	Expansion joint
Bangkok side	



Picture No.	11
Span	1
Member	Expansion joint
Bangkok side	
Deterioration of corrosion proofing	



Picture No.	12
Span	1
Member	Expansion joint
between side span and center span	
Peeling of surface layer	

Present state (5 / 18)

Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Memorial Bridge				



Picture No.	7
Span	1
Member	Bearing
Deterioration of corrosion protection	



Picture No.	8
Span	1
Member	Bearing
Remaining water	



Picture No.	9
Span	1
Member	Bearing
Mark of remarkable corrosion	
There is no remaining water at survey. Improved?	

Present state (6 / 18)


Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Memorial Bridge				



Picture No.	10
Span	1
Member	Stay cable
Connection between steel and slab	
It looks make gap around steel member from bottom side.	



Picture No.	11
Span	1
Member	Inspection vehicle
Mounted up around steel member to prevent remaining water.	
It looks no gap around steel member from top side.	



Picture No.	12
Span	1
Member	slab
It looks no gap around steel member from top side.	

Present state (7 / 18)

Authority	DRR	n	Bangkok	Data	23-Oct-09
Bridge	Memorial Bridge				



Picture No.	13
Span	1
Member	slab
Reinforcement by additional plate	
Original structure is connected by rivet	
Reinforcement structure is connected by high tension bolt.	



Picture No.	14
Span	1
Member	slab
Reinforcement plate top and bottom of member	



Picture No.	15
Span	1
Member	slab
Remaining water is seen inside of chord member	

Present state (8 / 18)

Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Memorial Bridge				



Picture No.	16
Span	1
Member	slab
Remaining water It will make corrosion	



Picture No.	17
Span	1
Member	slab
Remarkable reduced section	



Picture No.	18
Span	1
Member	slab
Rivet is not changed to bolt.	
Reinforcement plate was connected only center by bolt.	

Present state (9 / 18)

Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Memorial Bridge				



Picture No.	13
Span	1
Member	slab
Deterioration of corrosion proof	




Picture No.	14
Span	1
Member	slab
Corrosion of diaphragm	
Accumulation of soil	



Picture No.	15
Span	1
Member	Lighting pole
Corrosion of diaphragm	

Present state (11 / 18)

Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Memorial Bridge				



Picture No.	19
Span	1
Member	Bolt
Falling of rivet	



Picture No.	20
Span	1
Member	Upper chord
Deformation	



Picture No.	21
Span	1
Member	Lighting pole
Corrosion	

Present state (12 / 18)


Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Memorial Bridge				



Picture No.	22
Span	1
Member	Stringer
Stringer is connected by high tension bolt.	
All stringer might be replaced at repairing work	



Picture No.	23
Span	1
Member	Bottom chord
Deformation by vehicle collision	
Limit of vehicle height is 3.5m	
No warning frame is set before bridge at Thon Buri side	



Picture No.	24
Span	1
Member	Bottom chord
Deformation by vehicle collision	
Thon Buri side	


Present state (13 / 18)					
Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Memorial Bridge				



Picture No.	25
Span	1
Member	Cross frame
Thon Buri side	
Buckling by vehicle collision	



Picture No.	26
Span	1
Member	End cross beam
Deformation	



Picture No.	27
Span	1
Member	Bottom chord
Rupture of rivet by vehicle collision	

Present state (15 / 18)					
Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Memorial Bridge				



Picture No.	31
Span	1
Member	slab
Replaced slab	
Free lime is seen on slab of center span and walkway	



Picture No.	32
Span	1
Member	slab
Crack and free lime	



Picture No.	33
Span	1
Member	Drainage
Blocked	

Present state (16 / 18)

Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Memorial Bridge				



Picture No.	34
Span	1
Member	Slab
Longitudinal crack between road and walkway	
Insufficiency of rigidity of bracket member of walkway?	
*Survey on board, 31-oct	



Picture No.	35
Span	1
Member	Slab
Longitudinal crack between road and walkway	
*Survey on board, 31-oct	




Picture No.	36
Span	1
Member	Slab
Longitudinal crack between road and walkway	
Fracture of surface	
*Survey on board, 31-oct	

Present state (17 / 18)

Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Memorial Bridge				



Picture No.	37
Span	1
Member	slab
Crack and free lime on bottom surface of slab	
Deformation of cross frame by ship collision	
*Survey on board, 31-oct	



Picture No.	38
Span	1
Member	Inspection car rail
Lack of bolt	
*Survey on board, 31-oct	



Picture No.	39
Span	1
Member	Cross frame
Drop off 1 member by ship collision	
*Survey on board, 31-oct	

Present state (18 / 18)					
Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Memorial Bridge				

	Picture No.	40
	Span	1
	Member	Gusset plate
	Damage by ship collision	
	*Survey on board, 31-oct	

	Picture No.	41
	Span	1
	Member	

	Picture No.	42
	Span	1
	Member	

Inspection sheet of visual survey

 Bridge No. 14

Photo No. (~)

Bridge name		Phra Pokklao Bridge				Route name	-		Authority	DRR	Code of authority	-	
Place	from	Khat Bangkok Noi				Distance	from	km+		0	No.	-	
	to	Khet Phra Nakhon					to	km+	0	Survey date	2009/10/23		
Bridge properties	Bridge type(1)	<input type="checkbox"/> main road · <input type="checkbox"/> side road · <input type="checkbox"/> ramp				Survey result	Camber deform	yes	<input type="checkbox"/> no	Outline of damage	Item	Type	State
	Bridge type(2)	<input type="checkbox"/> bridge · <input type="checkbox"/> viaduct · <input type="checkbox"/> plank pass					Difference in grade	yes	<input type="checkbox"/> no		Main girder	PC-Box	free lime
	Bridge type(3)	3-span continuous PC box girder					Continuous of barrier	yes	<input type="checkbox"/> no		Cross beam	-	-
	Total length	212.00 (m)					Continuous of curve	yes	<input type="checkbox"/> no		Stringer	-	-
	Span	56 + 100 + 56 (m)					Noise	yes	<input type="checkbox"/> no		Cross frame	-	-
	Nos. of span	3 span					Space change	yes	<input type="checkbox"/> no		Lateral brace	-	-
	Width	13.2 X 2 (m) / (m)					difference grade	yes	<input type="checkbox"/> no		Slab	-	free lime
	Completion	1984					draining damage	yes	<input type="checkbox"/> no		Abutment	-	-
Road information	Horizontal	<input type="checkbox"/> Straight · <input type="checkbox"/> incli(= °) · Curve (R m)				Joint	Blocked drainage	yes	<input type="checkbox"/> no		Pier	Rectangular	-
	Gradient	One way (·) <input type="checkbox"/> parabo (<input type="checkbox"/> · <input type="checkbox"/>)					Crack of pavement	yes	<input type="checkbox"/> no		Bearing	Slide bearing	-
	Nearby tunnel	yes · <input type="checkbox"/> no (m)					Damage of lighting	yes	<input type="checkbox"/> no		Barrier	Trapezoidal	Exfoliation
	Nearby crossing	yes · <input type="checkbox"/> no (m)					Damage of sign	-	-		Railing	Steel	Generally healthy
	Traffic	Much · <input type="checkbox"/> Medium · Little					Damage of handrail	yes	<input type="checkbox"/> no		Curb	-	-
	Commercial traffic	Much · <input type="checkbox"/> Medium · Little					Possibility of scour	yes	<input type="checkbox"/> no		Pavement	<input type="checkbox"/> asphalt · <input type="checkbox"/> concrete	Generally healthy
Environment	1.Urban 2.Suburbs 3.Mountain 4.Seaside 5.Industrial 6.Harbor 7.Residential 8.Bussiness 9.Salty 10.Cold and snow 11.Heavy snow 12.Others				Inspection way	Walkway	yes	<input type="checkbox"/> no	Impressions	Joint	<input type="checkbox"/> drained · <input type="checkbox"/> indrained	leakage at end	
	1.Shinkansen 2.Railway 3.Highway 4.Road 5.River 6.Lake 7.Ravine 8.Valley 9.Waterway 10.Parking 11.Bike parkin 12.Park 13.Vacant 14.Harbor Name (Chao Phraya)					Vehicle	yes	<input type="checkbox"/> no		Drainage	<input type="checkbox"/> yes · <input type="checkbox"/> no	Generally healthy	
	Superstructure 1.Inspection car 2.Falsework 3.On ground 4.Ladder 5.Lift car 6.On boat 7.Special camera 8.Others()					Height of girde	about 8.9m						
	Substructure 1.Inspection car 2.Falsework 3.On ground 4.Ladder 5.Lift car 6.On boat 7.Special camera 8.Others()					Diagnosis	Deterioration of bridge						
Reason				Noticeable point									
· All bridge section is on the water · If inspection car is not available, false work will be required						History of repair							
						Surveyor ;		Mr,Chujo, Mr.Kudo					
						Repaint ;							

Ap-201

Appendices

Present state (4 / 4)					
Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Phra Pokklao Bridge				

	Picture No.	10
	Span	1
	Member	Drainage
	Scratch by ship collision	

	Picture No.	11
	Span	1
	Member	Substructure

	Picture No.	12
	Span	1
	Member	Pylon

Inspection sheet of visual survey

 Bridge No. 15

Photo No. (~)


Bridge name		Taksin Bridge				Route name		-		Authority		Code of authority		-		
Place		from Khet Khlong San to Khet Sathoo				Distance		from km+ 0 to km+ 0		Survey date		2009/10/27				
Bridge properties	Bridge type(1)	main road · side road · ramp														
	Bridge type(2)	bridge · viaduct · plank pass														
	Bridge type(3)	3-span continuous PC box girder														
	Total length	224.00 (m)														
	Span	66 + 92 + 66 (m)														
	Nos. of span	3 span														
	Width	12.85 x 2 (m) / (m)														
	Completion	1982														
Road information	Horizontal	Straight · incli(= °) · Curve (R m)														
	Gradient	One way (·) parabo (▽ · ▽)														
	Nearby tunnel	yes · no (m)														
	Nearby crossing	yes · no (m)														
	Traffic	Much · Medium · Little														
	Commercial traffic	Much · Medium · Little														
	Environment		1.Urban 2.Suburbs 3.Mountain 4.Seaside 5.Industrial 6.Harbor 7.Residential 8.Bussiness 9.Salty 10.Cold and snow 11.Heavy snow 12.Others													
	Under bridge		1.Shinkansen 2.Railway 3.Highway 4.Road 5.River 6.Lake 7.Ravine 8.Valley 9.Waterway 10.Parking 11.Bike parkin 12.Park 13.Vacant 14.Harbor Name (Chao Phraya)													
Access method	Superstructure	1.Inspection car 2.Falsework 3.On ground 4.Ladder 5.Lift car 6.On boat 7.Special camera 8.Others()														
	Substructure	1.Inspection car 2.Falsework 3.On ground 4.Ladder 5.Lift car 6.On boat 7.Special camera 8.Others()														
	Reason	· All bridge section is on the water · If inspection car is not available, false work will be required														
Survey result	Camber deform		yes · no													
	Difference in glade		yes · no													
	Continuous of barrier		yes · no													
	Continuous of curve		yes · no													
	Noise		yes · no													
	Joint	Space change		yes · no												
		difference grade		yes · no												
		draining damage		yes · no												
Blocked drainage		yes · no														
Outline of damage	Crack of pavement		yes · no													
	Damage of lighting		yes · no													
	Damage of sign		-													
	Damage of handrail		yes · no													
	Possibility of scou		yes · no													
	Walkway		yes · no													
	Vehicle		yes · no													
	Inspection way		Height of girde about 12m													
Diagnosis	Deterioration of bridge deficient · fair · good															
	Noticeable point															
	· Crack or cold joint on web															
	· Longitudinal move of girder															
	History of repair		Repaint ; - yy - mm													
	Surveyor ;		Mr.Chujo, Mr.Kudo													
	Impressions		· Suspicious of shear crack is found in Thonburi side span. It is recommended watching continuously · Movement to center span was seen at Bangkok side bearing. It is recommended watching continuously. · Cover of barrier and railing was disappear on expansion joint.													
	Item		Type		State											
Main girder		PC-Box		free lime, Suspicious of crack												
Cross beam		-		-												
Stringer		-		-												
Cross frame		-		-												
Lateral brace		-		-												
Slab		-		free lime, leakage												
Abutment		-		-												
Pier		V shape		-												
Bearing		Slide bearing		Deterioration of proofing												
Barrier		Trapezoidal		Lack of cover at expansion joint, Exfoliation												
Railing		Steel		Generally healthy												
Curb		-		-												
Pavement		asphalt · concrete		Unevenness												
Joint		drained · indrained		leakage at end												
Drainage		yes · no		Blocked												

Ap-206

Appendices

Present state (3 / 8)

Authority	DRR	Address	Bangkok	Data	27-Oct-09
Bridge	Taksin bridge				



Picture No.	7
Span	1
Member	Water supply
modular type is applied for the bridge of upstream	
Lack of cover of barrier	



Picture No.	8
Span	1
Member	Bearing
Movement of bearing.	
Bangkok side	
Already reach to end of sliding plate	




Picture No.	9
Span	1
Member	Bearing
Movement of Thon Buri side is sma	

Present state (4 / 8)

Authority	DRR	Address	Bangkok	Data	27-Oct-09
Bridge	Taksin bridge				



Picture No.	10
Span	1
Member	Expansion joint
Deterioration of drain function	
Mark of leakage	



Picture No.	11
Span	1
Member	Vertical alignment
Bent angle between main bridge and approach bridge	



Picture No.	12
Span	1
Member	Slab
Free lime	

Present state (5 / 8)


Authority	DRR	Address	Bangkok	Data	27-Oct-09
Bridge	Taksin bridge				



Picture No.	7
Span	1
Member	Box girder
Shear crack or severe cold joint Detailed study is recommended	
Free lime from filled hole Without waterproofing?	



Picture No.	8
Span	1
Member	Catch basin
Free lime from filled hole Without waterproofing?	



Picture No.	9
Span	1
Member	Barrier
Exposure of rebar	

Present state (6 / 8)

Authority	DRR	Address	Bangkok	Data	27-Oct-09
Bridge	Taksin bridge				



Picture No.	10
Span	1
Member	Slab
Mark of repair	



Picture No.	11
Span	1
Member	Bearing
Leakage from joint	
Upstream, Thon Buri side	



Picture No.	12
Span	1
Member	Lighting pole
Free lime (lower)	
Crack (upper)	
Upstream, Bangkok side	

Present state (8 / 8)					
Authority	DRR	Address	Bangkok	Data	27-Oct-09
Bridge	Taksin bridge				

	Picture No.	10
	Span	1
	Member	Girder
	Free lime from construction joint	

	Picture No.	11
	Span	1
	Member	Girder
	Acumuration of soil	

	Picture No.	12
	Span	1
	Member	Pier
	Test of carbonation is recommended	

Inspection sheet of visual survey

 Bridge No. 16

Photo No. (~)

Bridge name		RAMA III Bridge		Route name	-		Authority	Code of authority	-			
Place		from	Khet Thon Buri		from	km+		0	No.	-		
		to	Khet Bang Kho Leam		to	km+	0	Survey date	2009/10/23			
Bridge properties	Bridge type(1)	<input type="checkbox"/> main road · <input type="checkbox"/> side road · <input type="checkbox"/> ramp		Survey result	Camber deform	<input type="checkbox"/> yes · <input type="checkbox"/> no		Outline of damage	Item	Type	State	
	Bridge type(2)	<input type="checkbox"/> bridge · <input type="checkbox"/> viaduct · <input type="checkbox"/> plank pass			Difference in grade	<input type="checkbox"/> yes · <input type="checkbox"/> no			Main girder	PC-Box	Generally healthy	
	Bridge type(3)	3-span continuous PC box girder			Continuous of barrier	<input checked="" type="checkbox"/> yes · <input type="checkbox"/> no			Cross beam	-	-	
	Total length	476.00 (m)			Continuous of curve	<input checked="" type="checkbox"/> yes · <input type="checkbox"/> no			Stringer	-	-	
	Span	125 + 226 + 125 (m)			Noise	<input type="checkbox"/> yes · <input type="checkbox"/> no			Cross frame	-	-	
	Nos. of span	3 span			Space change	<input type="checkbox"/> yes · <input type="checkbox"/> no			Lateral brace	-	-	
	Width	23.00 (m) / (m)			difference grade	<input type="checkbox"/> yes · <input type="checkbox"/> no			Slab	-	-	
	Completion	2000			draining damage	<input type="checkbox"/> yes · <input type="checkbox"/> no			Abutment	-	-	
Road information	Horizontal	<input type="checkbox"/> Straight · <input type="checkbox"/> incli(= °) · Curve (R m)		Joint	Blocked drainage	<input checked="" type="checkbox"/> yes · <input type="checkbox"/> no		Impressions	Pier	Rectangular	-	
	Gradient	One way (·) <input type="checkbox"/> parabo (<input type="checkbox"/> · <input type="checkbox"/>)			Crack of pavement	<input type="checkbox"/> yes · <input type="checkbox"/> no			Bearing	-	-	
	Nearby tunnel	<input type="checkbox"/> yes · <input checked="" type="checkbox"/> no (m)			Damage of lighting	<input type="checkbox"/> yes · <input type="checkbox"/> no			Barrier	-	-	
	Nearby crossing	<input type="checkbox"/> yes · <input checked="" type="checkbox"/> no (m)			Damage of sign	-			Railing	-	-	
	Traffic	Much · <input checked="" type="checkbox"/> Medium · Little			Damage of handrail	<input type="checkbox"/> yes · <input type="checkbox"/> no			Curb	-	-	
	Commercial traffic	Much · <input checked="" type="checkbox"/> Medium · Little			Possibility of scour	<input checked="" type="checkbox"/> yes · <input type="checkbox"/> no			Pavement	<input checked="" type="checkbox"/> asphalt · <input type="checkbox"/> concrete	Generally healthy	
Environment	1.Urban 2.Suburbs 3.Mountain 4.Seaside		Inspection way	Walkway	<input type="checkbox"/> yes · <input type="checkbox"/> no		History of repair	· Hole for fixing of formwork of pier was not filled by mortar				
	5.Industrial 6.Harbor 7.Residential 8.Bussiness			Vehicle	<input type="checkbox"/> yes · <input type="checkbox"/> no			· New bridge				
Under bridge	1.Shinkansen 2.Railway 3.Highway 4.Road		Diagnosis	Height of girde		about 34m						
	5.River 6.Lake 7.Ravine 8.Valley			Deterioration of bridge		deficient · fair · <input checked="" type="checkbox"/> good						
Access method	Superstructure		1.Inspection car 2.Falsework 3.On ground 4.Ladder 5.Lift car									
	Substructure		6.On boat 7.Special camera 8.Others()									
Reason		· All bridge section is on the water										
		· If inspection car is not available, false work will be required										
						Surveyor ; Mr.Chujo, Mr.Kudo						
						Repaint ; - yy - mm						

Ap-215

Appendices

Inspection sheet of visual survey

 Bridge No. 17

Photo No. (~)

Bridge name		Krung Thep Bridge				Route name		-		Authority		Code of authority		-			
Place		from Khet Thon Buri to Khet Bang Kho Leam				Distance		from km+ 0 to km+ 0		Survey date		2009/10/23					
Bridge properties	Bridge type(1)	main road · side road · ramp															
	Bridge type(2)	bridge · viaduct · plank pass															
	Bridge type(3)	5-span steel truss															
	Total length	316.00 (m)															
	Span	64 + 64 + 60 + 64 + 64 (m)															
	Nos. of span	5 span															
	Width	12.00 (m) / (m)															
	Completion	1959															
Road information	Horizontal	Straight · incli(= 1.7 %) (R m)															
	Gradient	One way (·) parabo (▽ · 3.45%)															
	Nearby tunnel	yes · no (m)															
	Nearby crossing	yes · no (m)															
	Traffic	Much · Medium · Little															
	Commercial traffic	Much · Medium · Little															
	Environment		1.Urban 2.Suburbs 3.Mountain 4.Seaside 5.Industrial 6.Harbor 7.Residential 8.Bussiness 9.Salty 10.Cold and snow 11.Heavy snow 12.Others														
	Under bridge		1.Shinkansen 2.Railway 3.Highway 4.Road 5.River 6.Lake 7.Ravine 8.Valley 9.Waterway 10.Parking 11.Bike parkin 12.Park 13.Vacant 14.Harbor Name (Chao Phraya)														
Access method	Superstructure	1.Inspection car 2.Falsework 3.On ground 4.Ladder 5.Lift car 6.On boat 7.Special camera 8.Others()															
	Substructure	1.Inspection car 2.Falsework 3.On ground 4.Ladder 5.Lift car 6.On boat 7.Special camera 8.Others()															
	Reason	· All bridge section is on the water · If inspection car is not available, false work will be required															
Survey result		Camber deform		yes · no													
		Difference in glade		yes · no													
		Continuous of barrier		yes · no													
		Continuous of curve		yes · no													
		Noise		yes · no													
		Space change		yes · no													
		difference grade		yes · no													
		draining damage		yes · no													
Outline of damage		Blocked drainage		yes · no													
		Crack of pavement		yes · no													
		Damage of lighting		yes · no													
		Damage of sign		-													
		Damage of handrail		yes · no													
		Possibility of scour		yes · no													
		Walkway		yes · no													
		Vehicle		yes · no													
Inspection way		Height of girde		about 7.5m													
		Deterioration of bridge		deficient · fair · good													
		Noticeable point		· Corrosion of vertical membe · Breaking of slab													
		History of repair		· Countermeasure was planed by ODA at 1982 Repaint ; - yy - mm													
		Surveyor ;		Mr.Chujo, Mr.Kudo													
		Impressions		· Painting is renewd. But Reduction of steel thickness was seen at connection part bet and concrete slab. · Rust was seen over paint. it might insufficinet of scraping before paint. · Crack(0.8mm on top) and flacture of concrete was seen on slab of walkway													
		Diagnosis		Deterioration of bridge deficient · fair · good Noticeable point · Corrosion of vertical membe · Breaking of slab													

Ap-218


Appendices

Present state (6 / 16)

Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Krung Thep Bridge				



Picture No.	16
Span	1
Member	Stay cable
Hinge of drawbridge	
Mechanical parts is replaced every 2 years.	



Picture No.	17
Span	1
Member	Vertical member
Mount up around vertical member to prevent remaining water.	



Picture No.	18
Span	1
Member	Vertical member
Deterioration of caulking in gap	

Present state (8 / 16)

Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Krung Thep Bridge				



Picture No.	22
Span	1
Member	Center span
Fracture of mortar for height adjustment	



Picture No.	23
Span	1
Member	Center span
Manufactured by plasticity deformation	



Picture No.	24
Span	1
Member	Center span
Continuous vibration	
Painting is not	
塗装が完全ではない	

Present state (9 / 16)					
Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Krung Thep Bridge				

	Picture No.	25
	Span	1
	Member	Center span
	Over coating is not painted lower side of flange.	

	Picture No.	26
	Span	1
	Member	Center span
	Middle splice plate is divided in 2 plate.	

	Picture No.	27
	Span	1
	Member	Center span
	Reduction of plate thickness of steel plate.	

Present state (10 / 16)					
Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Krung Thep Bridge				

	Picture No.	28
	Span	1
	Member	Center span
	Reduction of plate thickness of steel plate.	
	There is no remaining water	

	Picture No.	29
	Span	1
	Member	Center span
	Dirt line is seen at bottom of web	
	Possibility of remaining water and soil	


	Picture No.	30
	Span	1
	Member	Center span
	Difference at center joint	

Present state (11 / 16)

Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Krung Thep Bridge				



Picture No.	31
Span	1
Member	Center span
Manhole	
Lost of bolt	
No key	



Picture No.	32
Span	1
Member	Center span
Door to access to center joint	



Picture No.	33
Span	1
Member	Center span
Rust from painting part	
Possibility of insufficient of scraping before painting	

Present state (12 / 16)					
Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Krung Thep Bridge				



Picture No.	34
Span	1
Member	Center span
Around center joint	
Change from rivet to bolt	
Mark of remarkable corrosion	
Rust from painting part	
Possibility of insufficient of scraping before painting	



Picture No.	35
Span	1
Member	Center span
Deflection between vertical member?	



Picture No.	36
Span	1
Member	Center span
Inclination of locker bearing Bangkok side	

Present state (13 / 16)					
Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Krung Thep Bridge				

	Picture No.	37
	Span	1
	Member	Vertical member
	Reinforcement by additional plate	

	Picture No.	38
	Span	1
	Member	Approach bridge
	Exfoliation	

	Picture No.	39
	Span	1
	Member	Approach bridge
	Remaining water at shoe	

Present state (15 / 16)

Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Krung Thep Bridge				



Picture No.	43
Span	1
Member	Slab
Fracture of slab on bracket	
*Survey on board, 31-oct	



Picture No.	44
Span	4
Member	Slab
Crack	
Free lime	
*Survey on board, 31-oct	



Picture No.	45
Span	3
Member	Slab
Center span	
*Survey on board, 31-oct	

Present state (16 / 16)					
Authority	DRR	Address	Bangkok	Data	23-Oct-09
Bridge	Krung Thep Bridge				

	Picture No.	46
	Span	1
	Member	Bearing
	Deterioration of corrosion proof i	
	<i>*Survey on board, 31-oct</i>	

	Picture No.	47
	Span	1
	Member	

	Picture No.	48
	Span	1
	Member	

Inspection sheet of visual survey

 Bridge No. 18

Photo No. (~)

Bridge name		RAMA IX Bridge		Route name	-		Authority	EXAT		Code of authority	-	
Place	from	Khet Rat Burana		Distance	from	km+	0		Mr.Pittaya, Mr.Yadpong	No.	-	
	to	Khet Yan Nawa			to	km+	0			Survey date	26-Oct-2009	

Bridge properties	Bridge type(1)	<input type="checkbox"/> main road · <input type="checkbox"/> side road · <input type="checkbox"/> ramp		Survey result	Camber deform	yes · <input type="checkbox"/> no	Outline of damage	Item	Type	State	
	Bridge type(2)	<input type="checkbox"/> bridge · <input type="checkbox"/> viaduct · <input type="checkbox"/> plank pass			Difference in glade	yes · <input type="checkbox"/> no		Main girder	Steel box girderr	Under reinforcement of U-rib	
	Bridge type(3)	7-span steel box girder cable stayed bridge			Continuous of barrier	<input checked="" type="checkbox"/> yes · <input type="checkbox"/> no		Cross beam	truss	Mark of MT	
	Total length	781.20 (m)			Continuous of curve	<input checked="" type="checkbox"/> yes · <input type="checkbox"/> no		Stringer	-	-	
	Span	8 + 57.6 + 61.2 + 450 + 61.2 + 57.6 + 46.8 (m)			Noise	yes · <input type="checkbox"/> no		Cross frame	-	-	
	Nos. of span	7 span			Space change	yes · <input type="checkbox"/> no		Lateral brace	-	-	
	Width	33.00 (m) / (m)			difference grade	yes · <input type="checkbox"/> no		Slab	-	-	
	Completion	1987			draining damage	yes · <input type="checkbox"/> no		Abutment	-	-	
Road information	Horizontal	<input checked="" type="checkbox"/> Straight · <input type="checkbox"/> incli(= 2.5 %) · Curve (R m)		Inspection way	Blocked drainage	yes · <input type="checkbox"/> no	Impressions	Pier	Rectangular	Generally healthy	
	Gradient	One way (·) <input type="checkbox"/> parabo (<input type="checkbox"/> · <input type="checkbox"/>)			Crack of pavement	yes · <input type="checkbox"/> no		Bearing	Link bearing	-	
	Nearby tunnel	yes · <input type="checkbox"/> no (m)			Damage of lighting	yes · <input type="checkbox"/> no		Barrier	Steel	Generally healthy	
	Nearby crossing	yes · <input type="checkbox"/> no ()			Damage of sign	-		Railing	Steel	Generally healthy	
	Traffic	Much · <input checked="" type="checkbox"/> Medium · Little			Damage of handrail	yes · <input type="checkbox"/> no		Curb	-	-	
	Commercial traffic	Much · <input checked="" type="checkbox"/> Medium · Little			Possibility of scour	yes · <input type="checkbox"/> no		Pavement	<input checked="" type="checkbox"/> asphalt · <input type="checkbox"/> concrete	-	
Environment	1.Urban 2.Suburbs 3.Mountain 4.Seaside		Diagnosis	Walkway	<input checked="" type="checkbox"/> yes · no	History of repair	· 10year inspection was completed on 2003				
	5.Industrial 6.Harbor 7.Residential 8.Bussiness			Vehicle	<input checked="" type="checkbox"/> yes · no		· Evaluation program by Chulalongkorn Univ. Jan2005 to Mar.2009.				
Under bridge	1.Shinkansen 2.Railway 3.Highway 4.Road		Access method	Height of girde	about 45m	Surveyor ;	· Cable and pylon was repainted and girder is repainting using inspection vehicle				
	5.River 6.Lake 7.Ravine 8.Valley			Deterioration of bridge			· Reinforcement of U-rib by CFRT				
9.Waterway 10.Parking 11.Bike parkin 12.Park		6.On boat 7.Special camera 8.Others(Inspection vehicle)		deficient · fair · <input checked="" type="checkbox"/> good		· Replace of expansion joint					
13.Vacant 14.Harbor Name (Chao Phraya)		· False work might be prepared for pylon		Noticeable point		· Pavement was replaced to 'jonmix' tested by institute of DOH at 2005					
Reason		· Inspection vehicle is set on center and side spar		· Under repairing work		· Repaint ; - yy - mm					
				from 2005							

Ap-235


Appendices

Present state (2 / 9)

Authority	EXAT	Address	Bangkok	Data	26-Oct-09
Bridge	RAMA IX Bridge				



Picture No.	4
Span	1
Member	View under bridge
Under repainting using inspection vehicle	
*Survey on board, 31-oct	




Picture No.	5
Span	1
Member	Inspection way



Picture No.	6
Span	1
Member	View of pier
1 inspection vehicle apply for all side span.	
Numbers of vehicles are 3.	

Present state (3 / 9)


Authority	EXAT	Address	Bangkok	Data	26-Oct-09
Bridge	RAMA IX Bridge				



Picture No.	7
Span	1
Member	Inspection vehicle
Preparing work for painting?	




Picture No.	8
Span	1
Member	Pylon
Bottom flange is repainted.	
Shrinkage crack is seen in pier.	



Picture No.	9
Span	1
Member	Bottom flange
Deterioration of corrosion proofi	

Present state (9 / 9)					
Authority	EXAT	Address	Bangkok	Data	26-Oct-09
Bridge	RAMA IX Bridge				

	Picture No.	13
	Span	1
	Member	Meeting

	Picture No.	14
	Span	1
	Member	

	Picture No.	15
	Span	1
	Member	

Inspection sheet of visual survey

 Bridge No. 19

Photo No. (~)

Bridge name		Industrial Ring Road North Bridge		Route name		-		Authority		Code of authority		-				
Place		from Ket Yan Nawa		Distance		from km+ 0		No.		-		Survey date		22-Oct-2009		
		to Amphoe Phra Pradaeng				to km+ 0										
Bridge properties	Bridge type(1)	<input checked="" type="checkbox"/> main road · <input type="checkbox"/> side road · <input type="checkbox"/> ramp		Camber deform		yes · <input checked="" type="checkbox"/> no		Item		Type		State				
	Bridge type(2)	<input checked="" type="checkbox"/> bridge · <input type="checkbox"/> viaduct · <input type="checkbox"/> plank pass		Difference in grade		yes · <input checked="" type="checkbox"/> no		Main girder		Composite I girder		-				
	Bridge type(3)	5-span composite I girder cable stayed bridge		Continuous of barrier		<input checked="" type="checkbox"/> yes · <input type="checkbox"/> no		Cross beam		I section steel		-				
	Total length	578.30 (m)		Continuous of curve		<input checked="" type="checkbox"/> yes · <input type="checkbox"/> no		Stringer		-		-				
	Span	50.6 + 74.5 + 326 + 74.5 + 50.6 (m)		Noise		yes · <input checked="" type="checkbox"/> no		Cross frame		-		-				
	Nos. of span	5 span		Space change		yes · <input checked="" type="checkbox"/> no		Lateral brace		-		-				
	Width	35.9 - 55.2 (m) / (m)		Joint difference grade		yes · <input checked="" type="checkbox"/> no		Slab		-		Crack around fixing structure, free lime				
	Completion	2006		draining damage		yes · <input checked="" type="checkbox"/> no		Abutment		-		-				
Road information	Horizontal	<input checked="" type="checkbox"/> Straight · <input type="checkbox"/> incli(= 2.5 %) · Curve (R m)		Blocked drainage		yes · <input checked="" type="checkbox"/> no		Pier		Rectangular		Crack around cross beam				
	Gradient	One way (·) <input type="checkbox"/> parabo (<input type="checkbox"/> · <input type="checkbox"/>)		Crack of pavement		yes · <input checked="" type="checkbox"/> no		Bearing		Fix at pylon		-				
	Nearby tunnel	yes · <input checked="" type="checkbox"/> no (m)		Damage of lighting		<input checked="" type="checkbox"/> yes · <input type="checkbox"/> no		Barrier		Trapezoidal, steel		Generally healthy				
	Nearby crossing	<input checked="" type="checkbox"/> yes · <input type="checkbox"/> no (ramp way)		Damage of sign		-		Railing		Stainless		Generally healthy				
	Traffic	Much · <input checked="" type="checkbox"/> Medium · Little		Damage of handrail		yes · <input checked="" type="checkbox"/> no		Curb		-		-				
	Commercial traffic	<input checked="" type="checkbox"/> Much · Medium · Little		Possibility of scour		yes · <input checked="" type="checkbox"/> no		Pavement		<input checked="" type="checkbox"/> asphalt · <input type="checkbox"/> concrete		-				
Environment	1.Urban		2.Suburbs		3.Mountain		4.Seaside		Joint		<input checked="" type="checkbox"/> drained · <input type="checkbox"/> indrained		Occurrence of sound of impact			
	<input checked="" type="checkbox"/> 5.Industrial		6.Harbor		7.Residential		8.Business		Drainage		<input checked="" type="checkbox"/> yes · <input type="checkbox"/> no					
	9.Salty		10.Cold and snow		11.Heavy snow		12.Others									
Under bridge	1.Shinkansen		2.Railway		3.Highway		4.Road		Impressions		· Occurrence of sound of impact and jumping by heavy vehicle at at expansion joint		· Crack is seen in pylon around cross beam end. It is required detailed investigation especially in the case of increasing the defect after completion.		· Improvement around fixing structure is recommended.	
	<input checked="" type="checkbox"/> 5.River		6.Lake		7.Ravine		8.Valley									
		9.Waterway		10.Parking		11.Bike parkin		12.Park								
		13.Vacant		14.Harbor		Name (Chao Phraya)										
Access method	Superstructure		1.Inspection car		2.Falsework		3.On ground		4.Ladder		5.Lift car		History of repair		Repaint ; - yy - mm	
	Substructure		6.On boat		7.Special camera		8.Others(Inspection vehicle)		Height of girde		about 55m		Surveyor ;		Mr,Chujo, Mr.Kudo	
	Reason		· False work should be prepared for side span and p		Diagnosis		Deterioration of bridge deficient · <input checked="" type="checkbox"/> fair · good		Noticeable point		· Crack around pylon		· Crack around fixing structure			

Ap-245


Appendices

Present state (4 / 14)

Authority	DRR	Address	Bangkok	Data	22-Oct-09
Bridge	Industrial Ring Road Bridge (North)				



Picture No.	10
Span	1
Member	Expansion joint
South side. Adjustment of difference of grade	



Picture No.	11
Span	1
Member	Expansion joint
North side. Occurrence of sound of impact	
Jumping by heavy vehicle	



Picture No.	12
Span	1
Member	Expansion joint
Looseness of bolt	

Present state (9 / 14)

Authority	DRR	Address	Bangkok	Data	22-Oct-09
Bridge	Industrial Ring Road Bridge (North)				



Picture No.	13
Span	1
Member	slab
Crack from cable fixing structure	
PC girder part	



Picture No.	14
Span	1
Member	slab
Crack from cable fixing structure	
0.1mm ~ 0.15mm	
PC girder part	



Picture No.	15
Span	1
Member	slab
crack	
PC girder part	


Present state (10 / 14)					
Authority	DRR	Address	Bangkok	Data	22-Oct-09
Bridge	Industrial Ring Road Bridge (North)				



Picture No.	16
Span	1
Member	slab
Peeling of concrete	



Picture No.	17
Span	1
Member	slab
Fixing structure	
Mold?	




Picture No.	18
Span	1
Member	slab
Remaining water	

Present state (11 / 14)					
Authority	DRR	Address	Bangkok	Data	22-Oct-09
Bridge	Industrial Ring Road Bridge (North)				

	Picture No.	19
	Span	1
	Member	Pylon
	crack around cross beam end	

	Picture No.	20
	Span	1
	Member	Pylon
	crack around cross beam end	

	Picture No.	21
	Span	1
	Member	Lighting
	Continuous vibration of pole	
	Possibility of fatigue crack	

Present state (14 / 14)


Authority	DRR	Address	Bangkok	Data	22-Oct-09
Bridge	Industrial Ring Road Bridge (North)				



Picture No.	28
Span	1
Member	
North bridge- South pylon - center	
crack	
*Survey on board, 31-oct	



Picture No.	29
Span	1
Member	
North bridge - North pylon - center	
crack	
*Survey on board, 31-oct	



Picture No.	30
Span	1
Member	
North bridge - North pylon - center	
crack	
*Survey on board, 31-oct	

Inspection sheet of visual survey

 Bridge No. 20

Photo No. (~)

Bridge name		Industrial Ring Road South Bridge				Route name		-		Authority		Code of authority		-							
Place		from Bangkok				Distance		from km+ 0		Survey date		22-Oct-2009									
		to						to km+ 0													
Bridge properties	Bridge type(1)	<input type="checkbox"/> main road · <input type="checkbox"/> side road · <input type="checkbox"/> ramp				Camber deform		<input type="checkbox"/> yes · <input type="checkbox"/> no		Outline of damage	Item	Type	State								
	Bridge type(2)	<input type="checkbox"/> bridge · <input type="checkbox"/> viaduct · <input type="checkbox"/> plank pass				Difference in grade		<input type="checkbox"/> yes · <input type="checkbox"/> no			Main girder	Composite I girder	-								
	Bridge type(3)	5-span composite I girder cable stayed bridge				Continuous of barrier		<input checked="" type="checkbox"/> yes · <input type="checkbox"/> no			Cross beam	I section steel	-								
	Total length	702.30 (m)				Continuous of curve		<input checked="" type="checkbox"/> yes · <input type="checkbox"/> no			Stringer	-	-								
	Span	68.6 + 83.5 + 398 + 83.5 + 68.6 (m)				Noise		<input type="checkbox"/> yes · <input type="checkbox"/> no			Cross frame	-	-								
	Nos. of span	5 span				Space change		<input type="checkbox"/> yes · <input type="checkbox"/> no			Lateral brace	-	-								
	Width	35.9 - 55.2 (m) / (m)				Joint difference grade		<input type="checkbox"/> yes · <input type="checkbox"/> no			Slab		Crack around fixing structure, free lime								
	Completion	2006				Joint draining damage		<input type="checkbox"/> yes · <input type="checkbox"/> no			Abutment	-	-								
Road information	Horizontal	<input checked="" type="checkbox"/> Straight · <input type="checkbox"/> incli(= 2.5 %) · Curve (R m)				Blocked drainage		<input type="checkbox"/> yes · <input type="checkbox"/> no			Pier	Rectangular	Crack around cross beam								
	Gradient	One way () · <input type="checkbox"/> parabo (<input type="checkbox"/> · <input type="checkbox"/>)				Crack of pavement		<input type="checkbox"/> yes · <input type="checkbox"/> no			Bearing	Fix at pylon	-								
	Nearby tunnel	<input type="checkbox"/> yes · <input checked="" type="checkbox"/> no (m)				Damage of lighting		<input type="checkbox"/> yes · <input type="checkbox"/> no			Barrier	Trapezoidal, steel	Generally healthy								
	Nearby crossing	<input checked="" type="checkbox"/> yes · <input type="checkbox"/> no (ramp way)				Damage of sign		-			Railing	Stainless	Generally healthy								
	Traffic	Much · <input checked="" type="checkbox"/> Medium · Little				Damage of handrail		<input type="checkbox"/> yes · <input type="checkbox"/> no			Curb	-	-								
	Commercial traffic	<input checked="" type="checkbox"/> Much · Medium · Little				Possibility of scour		<input type="checkbox"/> yes · <input type="checkbox"/> no			Pavement	<input checked="" type="checkbox"/> asphalt · <input type="checkbox"/> concrete	-								
Environment	1.Urban 2.Suburbs 3.Mountain 4.Seaside				Walkway		<input checked="" type="checkbox"/> yes · <input type="checkbox"/> no		Impressions	· Crack is seen in pylon around cross beam end. It is required detailed investigation. · Improvement around fixing structure is recommended. especially in the case of increasing the defect after completion.											
	5.Industrial 6.Harbor 7.Residential 8.Business				Vehicle		<input checked="" type="checkbox"/> yes · <input type="checkbox"/> no														
	9.Salty 10.Cold and snow 11.Heavy snow 12.Others				Inspection way																
Under bridge	1.Shinkansen 2.Railway 3.Highway 4.Road				Height of girder		about 55m														
	5.River 6.Lake 7.Ravine 8.Valley				Diagnosis		Deterioration of bridge														
	9.Waterway 10.Parking 11.Bike parkin 12.Park						deficient · <input checked="" type="checkbox"/> fair · good														
Access method	13.Vacant 14.Harbor Name (Chao Phraya)				Reason		· False work should be prepared for side span and p									History of repair		Repaint ; - yy - mm			
	1.Inspection car 2.Falsework 3.On ground 4.Ladder 5.Lift car															Surveyor ;		Mr.Chujo, Mr.Kudo			
	6.On boat 7.Special camera 8.Others(Inspection vehicle)																				

Ap-260

Appendices

Present state (4 / 5)


Authority	DRR	Address	Bangkok	Data	22-Oct-09
Bridge	Industrial Ring Road Bridge (South)				



Picture No.	10
Span	1
Member	bottom slab
Back surface of crack around fixed	
Crack cannot find from inspection vehicle (about 2m from eye height)	



Picture No.	11
Span	1
Member	Connection girder
Inside of connection girder	
Harm of bird	



Picture No.	12
Span	1
Member	Pylon
Vertical crack at cross beam end	
Inclined crack of pylon shaft	
Opening construction joint	

Present state (5 / 5)

Authority	DRR	Address	Bangkok	Data	22-Oct-09
Bridge	Industrial Ring Road Bridge (South)				



Picture No.	7
Span	1
Member	Pylon
Vertical crack of pylon shaft	
Possibility of shirincage crack during construction is high.	



Picture No.	8
Span	1
Member	Pylon
Crack	
<i>*Survey on board, 31-oct</i>	



Picture No.	9
Span	1
Member	PC girder
<i>*Survey on board, 31-oct</i>	