独立行政法人 国際協力機構 インド国電力省 インド火力発電公社

インド国 火力発電所運用改善計画調査

ファイナルレポート Volume II

平成 22 年 11 月 (2010 年)

電源開発株式会社 九州電力株式会社 中国電力株式会社

> 産業 CR10

10 - 128

TABLE OF CONTENTS

CONCI	LUSIO	N AND RECOMMENDATION	
Con	clusion	1	
Reco	ommeno	dation5	
СНАРТ	ER 1	INTRODUCTION	
1.1	Backg	round of the Study1-1	
1.2	Purpos	se of the Study1-1	
1.3	Schedu	ule of the Study1-1	
1.4	Scope	of the Study1-2	
1.5	Outline	e of the Study1-3	
1.6	Basic l	Policy of the Study1-3	
1.7	Counte	erpart Agencies1-6	
1.8	Study '	Team Member1-8	
СНАРТ	TER 2	POWER SECTOR IN INDIA	
2.1	Govern	nment Policy2-1	
	2.1.1	Law/Regulation	
	2.1.2	Power Sector Structure2-1	
	2.1.3	Power Demand and Supply2-7	
	2.1.4	Policy and Development Plan and MEGA Project2-12	2
	2.1.5	Tariff2-15	5
	2.1.6	Assistance Policy and Present Situation of Project Formation Proposed by	
	(Other Donors	9
СНАРТ	ER 3	PERFORMANCE IMPROVEMENT IN NTPC POWER PLANTS	
3.1	NTPC	Limited Power Plant	
3.2	Statues	s of Operation	
3.3	Forme	r Performance Improvement in NTPC	
СНАРТ	ER 4	WORK IN INDIA	
4.1	#1 Kic	k off Meeting4-1	
4.2	#2 Kic	ek off Meeting4-1	
4.3	#1 Fiel	ld Work4-3	
4.4	#2 Fiel	ld Work4-9	
4.5	#3 Fiel	ld Work4-9	
4.6	#4 Fiel	ld Work4-9	
4.7	#5 Fiel	ld Work4-9	J

Vol. I

4.8	#6 Fie	ld Work	4-9
СНАРТ	TER 5	SELECTION OF CANDIDATE UNITS OF NTPC AND STUDY	
		SCOPE SCOPE	
5.1	Select	ed Units and Study Scope	5-1
5.2	Preser	t Operation Condition of the Selected Units	5-9
СНАРТ	ΓER 6	STUDY RESULT AND RECOMMENDATION	
6.1		osis of Boiler Problem	6-1
6.2	•	ustion Simulation	
		Introduction	
	6.2.2	Outline of the Combustion Simulation and the Subject in this Project	6-11
	6.2.3	The Mesh Pattern and the Simulation Cases	6-12
	6.2.4	Results	6-13
	6.2.5	Additional Case study for the Effect of the Air and Fuel Bias	6-16
6.3	Boiler	Remaining Life Assessment	6-21
	6.3.1	Overview	6-21
	6.3.2	Procedure	6-23
	6.3.3	Report	6-23
6.4	Air He	eater (AH) Performance Improvement	6-26
	6.4.1	Korba #6	6-26
	6.4.2	Singrauli Unit 4	6-29
	6.4.3	Efficiency Improvement Proposals	6-33
6.5	Turbir	e RLA	6-42
6.6	Conde	nser Leak Buster	6-51
6.7	Pump	Assessment	6-52
6.8	Seal F	in Replacement	6-55
6.9	Contro	ol System Assessment	6-59
	6.9.1	Overview	6-59
	6.9.2	Details	6-59
	6.9.3	Evaluation	6-59
	6.9.4	Improvement Proposals and Effects	6-60
6.10) BFP T	urbine Parameter Assessment	6-60
6.11	Gener	ator Assessment	6-62
	6.11.1	Target Generator for Assessment and the Procedure	6-62
	6.11.2	Korba#6 Generator Assessment	6-63
	6.11.3	Rihand#2 Generator Assessment	6-64
	6 11 1	Singraulitta Canarator Assassment	6 65

Vol. I

2 Generator Transformer Assessment	6-66
6.12.1 Target Transformers for Assessment and the Procedure	6-66
6.12.2 Korba #6 GT Assessment	6-68
6.12.3Rihand#2 GT Assessment	6-69
6.12.4Singrauli#6 (R-Phase) GT Assessment	6-71
6.12.5 Korba #6 GT Assessment (3 rd year: 2010)	6-72
Analysis of Current Performance and Performance Degradation	6-73
6.13.1 General	6-73
6.13.2Boiler Performance Test	6-77
6.13.3 Turbine Performance Test	6-90
4 Review and Improvement of Past and Present O&M Procedure	6-99
6.14.1 Current Conditions of Thermal Power Station Operations	6-99
6.14.2 Current Conditions of Operation	6-99
6.14.3 Outline of a Power Station Management System	6-100
6.14.4 Power Generation Equipment Operating States in Each Power Station	6-114
6.14.5 Issues and Countermeasures about Operation of Power Generation	
Equipment	6-115
6.14.6Provided Reports and Instructions	6-122
5 Economic and Financial Analysis	6-124
6.15.1 Concept	6-124
6.15.2 Scope	6-124
6.15.3Method	6-125
6.15.4Economic and Financial Analysis - Case Study	6-135
6.15.5 Environmental Value Added Analysis	6-181
5 Application of CDM	6-198
6.16.1 Outline of CDM	6-198
6.16.2 Implementation of preparation of PDD Draft	6-202
6.16.3 Summary of PDD Draft	6-203
6.16.4 Planning of schedule of preparatory works for CDM procedure for	
submission and approval	6-220
7 Recommendation	6-224
ΓER 7 TRAINING PROGRAM	
	6.12.1 Target Transformers for Assessment and the Procedure 6.12.2 Korba #6 GT Assessment 6.12.3 Rihand#2 GT Assessment 6.12.4 Singrauli#6 (R-Phase) GT Assessment 6.12.5 Korba #6 GT Assessment (3 rd year: 2010) 8 Analysis of Current Performance and Performance Degradation 6.13.1 General 6.13.2 Boiler Performance Test 6.13.3 Turbine Performance Test 8 Review and Improvement of Past and Present O&M Procedure 6.14.1 Current Conditions of Thermal Power Station Operations 6.14.2 Current Conditions of Operation 6.14.3 Outline of a Power Station Management System 6.14.4 Power Generation Equipment Operating States in Each Power Station 6.14.5 Issues and Countermeasures about Operation of Power Generation Equipment 6.14.6 Provided Reports and Instructions 6 Economic and Financial Analysis 6.15.1 Concept 6.15.2 Scope 6.15.3 Method 6.15.4 Economic and Financial Analysis - Case Study 6.15.5 Environmental Value Added Analysis 6 Application of CDM 6.16.1 Outline of CDM 6.16.2 Implementation of preparation of PDD Draft 6.16.3 Summary of PDD Draft 6.16.4 Planning of schedule of preparatory works for CDM procedure for submission and approval

Vol. I

8.4.11 Turbine RLA

7.2	2 Boiler Residual Life Assessment Technique Training			
	7.2.1 Boiler Residual Life Assessment Technique Training Course	7-7		
7.3	Boiler Combustion Simulation Training	7-8		
	7.3.1 Boiler Combustion Simulation Training Course	7-9		
7.4	Evaluation of the Trainings	7-10		
	7.4.1 Evaluation of Training Programs	7-10		
	7.4.2 Evaluation of Training Program and Implementation	7-10		
СНАР	FER 8 ATTACHMENT		Vol. I	
8.1	Minutes of Meeting (MOM)			
	8.1.1 MoM of First Steering Committee			
	8.1.2 MoM of Second Steering Committee			
	8.1.3 MoM of Third Steering Committee			
	8.1.4 MoM of Fourth Steering Committee			
8.2	Presentation Slides			
	8.2.1 #1 Work Shop			
	8.2.2 Other work shop and seminar			
8.3	Survey Sheets for the Selection of the Candidate Units	<u> </u>	J	
8.4	Assessment / Test procedure and report	_	Vol. II	
	8.4.1 Boiler RLA	=	J	
	8.4.2 Condenser Leak Buster			
	8.4.3 Pump Test			
	8.4.4 Control System Assessment		X7 1 TTT	
	8.4.5 Generator Assessment		Vol. III	
	8.4.6 Generator Transformer Assessment			
	8.4.7 Performance Test			
	8.4.8 Combustion Simulation	_	J	
	8.4.9 BFPT Parameter Assessment		Vol. IV	
	8.4.10Preparation of PDD Draft		Vol. IV	
	8.4.11 Turbine RI A	_	J 101. 1	

8.4.1 Boiler RLA

Scope of work and diagnosis procedure for Boiler RLA

< Objectives of power plants >

- (1) Singrauli Unit 6
- (2) Unchahar Unit 2
- (3) Rihand Unit 2

< Objectives of boiler components>

- (1) Water wall (2) Super heater
- (3) Reheater
- (4) Super heater header
- (5) De super heater pipe
- (6) Reheater header
- (7) Main steam pipe

< Procedure>


Boiler remaining life assessment will carried out based on the following procedure.

NO.	Parts	INSPECTION	Singrauli 6	Rihand 2	Unchahar 2	Reference
1	WATER WALL	VT	Mainly at burner level Erosion part		*	
2		THICKNESS	•20 points(5points each from	m 4corners)	*	8-4-1-1
3	SUPER HEATER	VT	·Mainly Platen super heater	,	*	
4		THICKNESS MEASUREMENT	•50 points around soot blow	ver	*	8 -4 - 1 - 2
5		SAMPLE TUBE INSPECTION	1 tube with 1m length for joint portion		*	8 -4 - 1 - 3
6		CREEP RUPTURE TEST (inspected in Japan)	-3 specimens from base me joint from the tube identical		*	8 -4 - 1 - 4
7		SUS SCALE DEPOSITION INSPECTION	•50 points of bottom bend p tubes	portion of austenitic steel	*	8 -4 - 1 - 5
8		VT	· Mainly around soot blower		*	
9		THICKNESS MEASUREMENT	_	_	*	
10	REHEATER	SAMPLE TUBE INSPECTION (inspected in Japan).	•2 tubes with 1m length for furnace inside and penthous portion		*	8 -4 - 1 - 3
11		CREEP RUPTURE TEST (inspected in Japan) for 1 tube with 1m length.	•3 specimens from base me weld joint from the tube idea above sample tubes		*	8 -4 - 1 - 4
12		SUS SCALE DEPOSITION INSPECTION	•50 points of bottom bend p tubes	portion of austenitic steel	*	8 -4 - 1 - 5
13		VΤ	 Visual inspection in pentho If the fiber scope is shippe inspection is carried out for 	d in time, fiber scope	*	
14		PT(DPT)	•4 portions at stub weld of	Inlet header	*	8 -4 - 1 - 6
15	SUPER HEATER HEADER	UT	• 1ring of circumferential we and TOFD identical to the r		*	8 -4 - 1 - 7
16		REPLICA INSPECTION	circumferential weld of left	·2 point on 1ring of circumferential weld of outlet header	*	8 -4 - 1 - 8 8 -4 - 1 - 9 8 -4 - 1 - 10
	DE SUPER HEATER PIPE	REPLICA INSPECTION	-2 points (one each from 2 weld)	rings of circumferential	*	8 -4 - 1 - 8 8 -4 - 1 - 9 8 -4 - 1 - 10
18	REHEATER HEADER	VT	•Visual inspection in pentho		*	
19		REPLICA INSPECTION	•2 points (one each from circumferential weld of left and right of out let header		*	8 -4 - 1 - 8 8 -4 - 1 - 9 8 -4 - 1 - 10
	MAIN STEAM PIPE (near the stop valve weld joint)	REPLICA INSPECTION	circumferential weld of left main steam pipe	2 points (one each from left and right side)	*	8 -4 - 1 - 8 8 -4 - 1 - 9 8 -4- 1 - 10

*:Decided after site meeting, basically followed by items of the other two units.

^{*}BUILDING OF SCAFFOLDS, REMOVAL OF THERMAL INSULATION, AND REMOVAL OF DUST IN BOILER FURNACE SHALL BE COMPLETED IN ADVANCE.

Thickness Measurement (Water wall tube)



Bird's eye view of boiler



Example of measurement points


Selection criteria

•The most severe heat load potion like the upper part of the burner level . (Available metal temperature data would help the selection)

Measurement points and quantity

• 5 points of each corner.


Thickness Measurement (Super heater tube)



Bird's eye view of boiler

•Total 50 points of the straight portion of outer tube (1-3rd) around soot blower

Sample Tube Inspection (Super heater tube, Reheater tube)



Bird's eye view of boiler



Example of sampling point for SH

Examination item

- 1.Appearance inspection
- 2. Inner and outer suface inspection
- 3. Inner scale examination (adhesion thickness, composition(water wall tube))
- 4.Hardness test
- 5. Tube dimensions measurement
- 6. Microstructure examination

Selection criteria

[Super heater tube]


•The highest temperature portion of super heater tubes (or reheater tubes) .

Measurement points and quantity

[Super heater tube] [Reheater tube]


1 tube with 1m length including weld joint portion. 2 tubes with 1m length for Final RH (one each from furnace inside and penthouse) including weld joint portion.

Creep Rupture Test (Super heater tube, Reheater tube)




Bird's eye view of boiler

SUS Scale Deposition Inspection (Super heater tube, Reheater tube) Front side



Bird's eye view of boiler



Example of inspection points

Selection criteria


- •Portion of super heater tubes and reheater tubes where austenitic stainless steel is used.
- ·Bottom bend portion where exfoliated steam oxidation scale from inner surface of tube by thermal expansion and contraction during start-stop is expected to fall and pile up.

Measurement points and quantity

Inspection portion

- •50 points of bend portion of austenitic stainless steel for selected final superheater panel.
- •50 points of bend portion of austenitic stainless steel for selected rerheater panel.

Penetrant Testing(Stub portion of final super heater header)



Bird's eye view of boiler



Example of inspection points


Selection criteria

- •The highest temperature stub, if metal temperature data is available.
- •The high stressed stub by structural constraint, if metal temperature data is not available.

Measurement points and quantity

- •4 points with high temperature portion among axial direction, if metal temperature data is available.
- •4points of stubs with high stressed portion by structural constraint, if metal temperature data is not available.


UT Inspection, TOFD Inspection (Final super heater header circumferential weld portion)



Bird's eye view of boiler

 All around one circumferential weld (1Ring), except interference portion with stubs.

Replica Inspection (Final super heater header, Desuper header, Reheater header and Main steam pipe)



Bird's eye view of boiler

Examination Technique of Remaining Life Assessment for Boiler High Temperature part

Japanese RLA guidline

- (1) Degradation factor to be evaluated
- Creep rupture remaining life
 (Designed temperature beyond 450°C)
- (2) Components to be evaluated and the method to assess the remaining life

[Components]

- ·Furnace evaporation header
- ·Super heater header or Main steam pipe
- Reheater header or High temperature reheat pipe Representative points among high heat loaded and high stressed portion in these components

[Method to assess the remaining life]

More than one method shown in table

- (3) Effective (countable) remaining life
- •1/2 of remaining life evaluated by above methodes

	Guideline		This study	
Method	Base	Weld (HAZ)	Base metal	Weld (HAZ)
Hardness measuring	_	0		
Electrical resisitance	—	0		
Chemical composition of carbide	0	0		
Creep cavity evaluation	— ·	0		
Microstructural comparison	0	0	0	0
Urtra sonic scattering noise		0		
Interparticle spacing	0	_		
Crystal grain deformation	0	_		
Destructive test	0	0		
Analytical method	0	0		

O:applicable, -: not applicable

(Microstructural comparison method outline)


Remaining life synthetically evaluated by three types of damage as shown below.

[Base metal]


- · Evaluation of average diameter
- •Comparison with the reference picture of microstructure related to creep the damage ratio
- *Comparison with the reference picture of carbide precipitationrelated to the creep damage ratio


[Weld metal] •Comparison with the reference picture of creep void and


- micro crack related to creep the damage ratio
- Comparison with the reference picture of microstructure related to creep the damage ratio
- Comparison with the reference picture of carbide precipitationrelated to the creep damage ratio





Microstructural Comparison Method (Weld portion)















Schedule of work for Boiler RLA



Boiler RLA demo in Singrauli #6unit & Unchahar #2

JICA Study Team for Enhancing Efficiency of Operating Thermal Power Plant in NTPC-India


Boiler RLA &

Kyudensangyo Co.,Inc

27.October 2009 -11.November 2009

Schedule for Boiler RLA demo

Schedule for Boiler RLA



Scope of work (1)


NO.	Parts	INSPECTION	Singrauli #6	Unchahar #2
1	WATER WALL	VT	Mainly at burner level Errosion part	
2		THICKNESS MEASUREMENT	•20 points(5points each from 4corners)	
3	SUPER HEATER	VT	• Mainly Platen super heater	
4		THICKNESS MEASUREMENT	- 50 points around soot blower	
5		SAMPLE TUBE INSPECTION *	1 tube with 1m length for Platen SH including weld joint portion	2 tubes with 1m length from Final SH, 1 tubes with 1m length from Platen SH including weld joint portion that is selected by steam oxide scale measurement result.
6		CREEP RUPTURE TEST*	•3 specimens from base metal, 3 specimens from weld joint from the tube identical to above.	• 3 specimens from base metal, 3 specimens from weld joint from the tube identical to above.
7		SUS SCALE DEPOSITION INSPECTION	• 50 points of bottom bend portion of austenitic steel tubes	•29 ×3 points of bottom bend portion of austenitic steel tubes
8		VT	• Mainly around soot blower.	
9		SAMPLE TUBE INSPECTION *	2 tubes with 1m length for Final RH (one each from furnace inside and penthouse) including weld joint portion.	
10	REHEATER	CREEP RUPTURE TEST*	• 3 specimens from base metal, 3 specimens from weld joint from the tube identical to the one of the above sample tubes.	
11		SUS SCALE DEPOSITION INSPECTION	• 50 points of bottom bend portion of austenitic steel tubes	

^{*:} Examined in Japan


Scope of work (2)

NO.	Parts	INSPECTION	Singrauli #6	Unchahar #2
12		VT	· Visual inspection in penthouse	
13	SUPER HEATER HEADER	PT(DPT)	•4 portions at stub weld of Inlet header.	• 4 portions at stub weld of Platten inlet header right side.
14		UT		• 1ring of circumferential weld of Final outlet header right side with UT and TOFD identical to the replica portion
15		REPLICA INSPECTION	 1 point on 1ring of circumferential weld of left outlet header. 1 point on base metal of left outlet header. 	• 1 point of circumferential weld potion of right side of Final outlet header.
16	DE SUPER HEATER PIPE	REPLICA INSPECTION	• 2 points (one each from 1 ring of circumferential	weld right and left).
17		VT	• Visual inspection in penthouse	
18	REHEATER	UT	• 1ring of circumferential weld of outlet header with UT and TOFD identical to the replica portion	
19	HEADER	REPLICA INSPECTION	•2 points (one each from circumferential weld of left and right of out let header.	• 3 points of circumferential weld potion of right and left side outlet header.
20	MAIN STEAM PIPE (near the stop valve weld joint)	REPLICA INSPECTION	•2 points on a circumferential weld of left main steam pipe	• 2 points on two circumferential welds of right main steam pipe
21	HOT RHEAT PIPE	REPLICA INSPECTION		• 1 point on a circumferential weld of right High temperature reheat pipe.

Inspection points



Inspection points (Unchahar #2)



Findings (1) (Singrauli #6)

Components	Inspection method	Findings
Water wall tube	Visual check	 Erosion of a number of tubes around short soot blower were found. No erosion at any other portions. No erosion and decease in thickness around burners.
		Thickness was measured at erosion regions around soot blowerrs near each 4 corner. Min. thickness was 3.7mm(2nd blower in forntwal first from right. f 51* 5.6mm, SA210 Gr.C
	Visual check	 Attrition of binding tube #4 and #5 was found. (Min.2.8mm) Attrition of cooling spacer tubevwith front tube of #14 panel (Min.5.0mm) Disorder of arrangement at lower part of panel with distortion to adjacent panel. A number of disjointed slide spac
Platten SH	Thickness measurement of tubes	•1:Outer tube of rear side portion at sootblower level [24points] ⇒ Min.6.3mm φ 63.5* 6.3mm SA213 TP347H •2:Outer bottom tube [24points] ⇒ Min.9.8mm φ 54.0* 9.5mm SA213 TP347H •3:Attrition of coolin
Timon 511	SUS scale deposition inspection	Nos. exceeding 10% fullness: 7 /50 (magnetized effect of material)
	Tube sampling for sample tube inspection (inspected in Japan).	#3-1(from leftside in penthouse)
	Creep rupture test (inspected in Japan)	

Findings (2) (Singrauli #6)

Components Inspection method		Findings
	Visual check	•Disorder of arrangement at lower part of panel with distortion to adjacent panel.
	SUS scale deposition inspection	No exceeding 10% fullness
	Tube sampling for sample	#3-1(from leftside in penthouse) 1m including weld
Reheater	tube inspection	f 54*5.6, SA213 T22
	(inspected in Japan).	#14-5(from rear side in furnace) (SA213T22 f 54*4.5-SA213T11 f 54*4.0)
	Creep rupture test	
	(inspected in Japan) for 1	
	tube with 1m length.	
	Visual check	No appearance abnormarity in stubs and other weld portion.
		#2(1,4,7,12) Indication was found in #2-12 stub at tube side. Indication disaappeared after grinding off the
Super heater header		tube in 1mm depth.
	Replica inspection	No crack in Base metal, HAZ(Heat Affected Zone) and weldmetal.
	Replica hispection	• More detail microstructural observation is required in labo.
De superheater pipe	Replica inspection	•No crack in Base metal, HAZ(Heat Affected Zone) and weldmetal.
De supernealer pipe	Replica inspection	More detail microstructural observation is required in labo.
	Visual check	No appearance abnormarity in stubs and other weld portion.
	Replica inspection	·No crack in Base metal, HAZ(Heat Affected Zone) and weldmetal.
	Replica hispection	More detail microstructural observation is required in labo.
Reheater header	UT	No detection of flaw beyond H-detection line.
		• 4 detected flaw under H-detection line.
	TOFD	• A number of flaw considered as satle blow holes and slag inclusions were detected.
	TOTE	No considerable crack detected.
Main steam pipe		•No crack in Base metal, HAZ(Heat Affected Zone) and weldmetal.
(near the stop valve weld	Replica inspection	• More detail microstructural observation is required in labo.
joint)		TVIOLE detail interest deservation is required in face.


Findings (3) (Unchahar #2)

Components	INSPECTION	Unchahar #2 Brief comment
WATER WALL	VT	Erosion of a number of tubes around short soot blower were found. Erosion of corner tubes at soot blower level.(Thickness measurement 28points (Min.4.2mm)
	THICKNESS MEASUREMENT	Eroded tubes around short soot blower were meareured .(69points measured) Min 5.3mm (2nd short blower rear wall #1 form left)
	VT	Disorder of arrangement at lower part of panel with disjointed slide spacers. Slight erosion of rear tubes at the highest level of short soot blower.
	THICKNESS MEASUREMENT	Rear tubes at the highest level of short soot blower.(29points, Min.9.8mm) 2nd tubes from rear tubes at the highest level of short soot blower.(3points, Min.10.0mm) Rear tubes at the second highest level of short soot blower.(29points, Min.9.8mm)
SUPER HEATER	SAMPLE TUBE INSPECTION *	1 sample tube from Platen-SH in furnace (#3panel- 8th tube from rear) 2 sample tubes from Final-SH in furnace (#1-3rd tube from rear, #119-3rd tube from rear)
	CREEP RUPTURE TEST*	1 sample tube from Platen-SH in furnace (#3panel- 8th tube from rear), 1 sample tubes from Final-SH in furnace (#119-3rd tube from rear)
	SUS SCALE DEPOSITION INSPECTION	3 tubes with 15% fullness and 2 tubes with 10% fullness at front bend portion. 1 tube with 15% fullness and the others with less than 10%.
REHEATER	VT	No abnormality with panel ar r angement Slight erosion of tubes at the highest level of short soot blower.


Findings (4) (Unchahar #2)

Components	INSPECTION	Unchahar #2 Brief comment
	VT	No appearance abnormality in stubs and other weld portion.
	PT(DPT)	3 small circular indication patterns by ark strike at 4th tube from front.
SUPER HEATER HEADER	UT	No detection of flaw which echo exceeds L-line by UT. Continuous indication with fine flaws detected at 80mm depth from surface by TOFD.
	REPLICA INSPECTION	No crack in Base metal, HAZ(Heat Affected Zone) and weld metal. More detail microstructural observation is required in labo.
DE SUPER HEATER PIPE	REPLICA INSPECTION	No crack in Base metal, HAZ(Heat Affected Zone) and weld metal. More detail microstructural observation is required in labo.
	VT	No appearance abnormality in stubs and other weld portion.
REHEATER HEADER	REPLICA INSPECTION	No crack in Base metal, HAZ (Heat Affected Zone) and weld metal. Abnormal microstructure observed in base metal region of right-hand weld of header, which is considered to be the effect of ark during welding. More detail microstructural observation.
MAIN STEAM PIPE (near the stop valve weld joint)	REPLICA INSPECTION	No crack in Base metal, HAZ(Heat Affected Zone) and weld metal. More detail microstructural observation is required in labo.
HOT RHEAT PIPE	REPLICA INSPECTION	No crack in Base metal, HAZ(Heat Affected Zone) and weld metal. More detail microstructural observation is required in labo. Some deposit metal by welding attached to base metal near the weld ring.

Visual inspection (Singrauli #6)



Visual inspection (Unchahar #2)



Thickness (Unchahar #2)

Thickness measurement of tubes

		Designed				Allowable	4	Measured		
Tube	Material	O.D.	t	Pressure	Temperature	Stress	tsr	(Min)	Note	
		D(mm)	(mm)	P (kg/cm2)	(°C)	S (MPa)	(mm)	(mm)		
Water wall	SA-210, GR.A1	63.5	6.3	175.8	404	86.8	6.1	4.2	Erosion around short soot blower	
Platten SH (ELE 1)	SA 213 T 22	51	9.6	175.8	566	39.7	9.4	9.8	Highest soot blower level	
Platten SH (ELE 1)	SA 213 T 22	51	9.6	175.8	566	39.7	9.4	9.8	Second highest soot blower level	
Platten SH (ELE 2)	SA 213 T 22	51	9.6	175.8	566	39.7	9.4	10.0	Highest soot blower level	

O.D.:Outer Diameter

t:Thickness

tsr = PD/(2S+P)+0.005D

Creep life calculation of header and pipe based on disigned condition

			Designed		Allowable		Ноор	D (
Header and Pipe	Material	O.D. D(mm)	t (mm)	Pressure P (kg/cm2)	Temperature (°C)	Stress S (MPa)	tsr (mm)	stress (MPa)	Estimated Life(h) calculated by creep rupture data
Platen SH outlet header	SA 335 P-22	323.9	56	163.8	534	58.2	37.5	35.3	8.58E+06
Re-Heater outlet header	SA 335 P-22	558.8	45	44.1	555	45.4	25.0	23.8	9.19E+06
LTSH outlet header	SA 335 P12	323.9	40	167.6	450	101.0	24.7	60.0	4.81E+08
Links to DESH	SA 335 P12	406.4	45	167.6	450	101.0	31.0	67.6	2.57E+08
DESH	SA 335 P12	406.4	45	167.6	450	101.0	31.0	67.6	2.57E+08
Links from DESH	SA 335 P12	406.4	45	167.6	427	102.8	30.5	67.6	2.25E+09
Platen SH inlet header	SA 335 P12	323.9	40	167.6	427	102.8	24.3	60.0	4.30E+09
Platen SH outlet header	SA 335 P-22	323.9	56	163.8	534	58.2	37.5	35.3	8.58E+06
Links to Final SH	SA 335 P-22	406.4	70	163.4	534	58.2	47.0	35.4	8.49E+06
SH Finish inlet header	SA 335 P-22	406.4	65	163.4	534	58.2	47.0	39.0	5.54E+06
SH Finish outlet header	SA 335 P-22	457.2	100	160.6	555	45.4	63.8	25.0	7.76E+06
Main Steam Pipe	SA 335 P-22	355.6	50.3	160.5	540	54.4	42.8	44.6	1.98E+06
Hot Reheat Pipe	SA 335 P-22	508	28	37.6	540	54.4	16.4	30.9	9.91E+06

tsr = PD /(2S?+2kP)+a (?=1, a=0)

1 _e							
K	≦350	480	510	535	565	590	620
Feritic steel	0.4	0.4	0.5	0.7	0.7	0.7	0.7

Thickness criterion (Unchahar #2)


Thickness measurement of tubes


		Designed				Allowable		Measured		
Tube	Material	O.D.	t	Pressure	Temperature	Stress	tsr	(Min)	Note	
	D(mm) (mm) P (kg/cm2) (°C) S (MPa) (mm) (mm		(mm)							
Water wall	SA-210, GR.A1	63.5	6.3	175.8	404	86.8	6.1	4.2	Erosion around short soot blower	
Platten SH (ELE 1)	SA 213 T 22	51	9.6	175.8	566	39.7	9.4		Highest soot blower level	
Platten SH (ELE 1)	SA 213 T 22	51	9.6	175.8	566	39.7	9.4	9.8	Second highest soot blower level	
Platten SH (ELE 2)	SA 213 T 22	51	9.6	175.8	566	39.7	9.4		Highest soot blower level	

O.D.:Outer Diameter

tsr = PD/(2S+P)+0.005D







Caluculated designed creep life (Unchahar #2)

Creep life calculation of header and pipe based on disigned condition

		Designed				Allowable		Ноор	
Header and Pipe	Material	O.D. D(mm)	t (mm)	Pressure P (kg/cm2)	Temperature (°C)	Stress S (MPa)	tsr (mm)	stress (MPa)	Estimated Life(h) calculated by creep rupture data
Platen SH outlet header	SA 335 P-22	323.9	56	163.8	534	58.2	37.5	35.3	8.58E+06
Re-Heater outlet header	SA 335 P-22	558.8	45	44.1	555	45.4	25.0	23.8	9.19E+06
LTSH outlet header	SA 335 P12	323.9	40	167.6	450	101.0	24.7	60.0	4.81E+08
Links to DESH	SA 335 P12	406.4	45	167.6	450	101.0	31.0	67.6	2.57E+08
DESH	SA 335 P12	406.4	45	167.6	450	101.0	31.0	67.6	2.57E+08
Links from DESH	SA 335 P12	406.4	45	167.6	427	102.8	30.5	67.6	2.25E+09
Platen SH inlet header	SA 335 P12	323.9	40	167.6	427	102.8	24.3	60.0	4.30E+09
Platen SH outlet header	SA 335 P-22	323.9	56	163.8	534	58.2	37.5	35.3	8.58E+06
Links to Final SH	SA 335 P-22	406.4	70	163.4	534	58.2	47.0	35.4	8.49E+06
SH Finish inlet header	SA 335 P-22	406.4	65	163.4	534	58.2	47.0	39.0	5.54E+06
SH Finish outlet header	SA 335 P-22	457.2	100	160.6	555	45.4	63.8	25.0	7.76E+06
Main Steam Pipe	SA 335 P-22	355.6	50.3	160.5	540	54.4	42.8	44.6	1.98E+06
Hot Reheat Pipe	SA 335 P-22	508	28	37.6	540	54.4	16.4	30.9	9.91E+06

tsr = PD /(2S?+2kP)+a (?=1, a=0)

le.							
K	≦350	480	510	535	565	590	620
Feritic steel	0.4	0.4	0.5	0.7	0.7	0.7	0.7

Japanese Boiler RLA Guidline (1)

To extend periodical inspection interval 2 year to 4year after 100,000 hours operation.

- (1) Degradation factor to be evaluated
 - Creep rupture remaining life
 (Designed temperature beyond 450°C)
- (2) Components to be evaluated
 - > Furnace evaporation header
 - > Super heater header or Main steam pipe
 - > Reheater header or High temperature reheat pipe

Representative points among high heat loaded and high stressed portion in these components

Japanese Boiler RLA Guidline (2)

- (3) Method to assess the remaining life
 - More than one method used as shown in table below

	Guid	eline	This study		
Method	Base metal	Weld (HAZ)	Base metal	Weld (HAZ)	
Hardness measuring	_	0			
Electrical resisitance		0			
Chemical composition of carbide	0	0			
Creep cavity evaluation	_	0			
Microstructural comparison	0	0	0	0	
Urtra sonic scattering noise	_	0			
Interparticle spacing	0	_			
Crystal grain deformation	0	_			
Destructive test	0	0			
Analytical method	0	0			

O:applicable, -: not applicable

- (4) Effective (countable) remaining life
 - > 1/2 of remaining life evaluated by above methods

Japanese Boiler Inspection (Water wall, Furnace tube)

Water wall tube / Furnace tube

Inspection measure	Portion	Deterioration factors	Inspection interval
VT	General appearance	Burn out, distortion,	Periodic inspection (every 2years)
	General appearance building scaffolding by the burner level	swelling, ash cut, steam cut etc.	Periodic inspection (every 4years)
	General appearance building scaffolding by the top of furnace at the necessary interval set.		Setting necessary interval.
VT(Endoscopy)	Water tube inside	Corrosion	Setting necessary interval.
Chemical analysis of deposit	Outside deposit	Corrosion	Periodic inspection (every 2years)
PT	Representative weld portion of fin edge	Creep-fatigue	In case of elongation of periodic inspection interval (max. 2years).
	Representative attached metal weld portion	Creep-fatigue	After 80,000 hours operation, depending on necessity
Thickness measurement	Fixed points of tube. Representative portion of ash cut and steam cut with no countermeasure	Thinning with aging. Ash cut and steam cut.	Continuous measurement depending on boiler structure and type. Erosion countermeasure necessary, in case of elongation of periodic inspection interval (max. 2years).
Sampling tube examination	Water wall tube in high heat load portion	Scale deposit	Setting necessary interval.
Residual life assessment	Water wall tube in high heat load portion	Creep	Judge from operation and design condition, depending on necessity.

Japanese Boiler Inspection (SH, RH, Eco tube)

SH, RH, Eco tubes

Inspection measure	Portion	Deterioration factors	Inspection interval
VT	General appearance	Leak, crack, corrosion, erosion	Periodic inspection (every 2years)
Chemical analysis of deposit	Outside deposit	High temperature corrosion	Depending on necessity
	Representative points of SH, RH, Eco tubes with no countermeasures for erosion.	erosion	Periodic inspection (every 2years)
Thickness measurement	High temperature corrosion portion and portion that tends to decrease in thickness	High temperature corrosion	Continuous measurement at constant points.
	Around soot blower	Ash cut and steam cut	Periodic inspection (every 2years)
	Attrition at cross over of tubes		Setting necessary interval.
	Representative weld portion of fin edge	Creep fatigue	In case of elongation of periodic inspection interval (max. 2years).
PT	Representative dissimilar weld portion with no use of Inconel weld metal.	Creep fatigue and creep	Setting necessary interval.
	Representative attached metal weld portion	Creep fatigue	After 80,000 hours operation, depending on necessity
Sampling tube examination	Austenitic steel tube (Austenitic steal used in steam temperature 540°C or more and metal temperature 620°C or more).	SUS scale deposition	In case of elongation of periodic inspection interval (max. 2years).
?-ray inspection etc.	Bottom bend potion of austenitic steel tube	SUS scale deposition	Depending on necessity
Residual life assessment	Low alloy steel used in steam temperature 540°C or more.	Creep	Judge from operation and design condition, depending on necessity.

Japanese Boiler Inspection (Steam drum, water drum)

Steam drum, Water drum

Inspection measure	Portion	Deterioration factors	Inspection interval
VT	•Drum inside with water steam separator	Deposit	Periodic inspection
	equipments detached.	Corrosion	(every 2years)*
		Erosion	
Chemical analysis		Deposit	
DPT	Inner weld lineInner corner of stubSupport and hanging lug	Low cycle fatigue	
MT	External seam and girth weld line Inner weld line of stub	Low cycle fatigue	After 80,000 hours operation

^{*}If the weld of stub inside is smooth finished, periodic inspection every 4years

Desuper

Inspection measure	Portion	Deterioration factors	Inspection interval	
Overhaul VT	Nozzle, Mixing chamber	Thermal fatigue, abrasion	Setting necessary interval.	

Japanese Boiler Inspection (Header (1))

Header (Water wall header, Evaporator header, Economizer header, SH header, RH header)

Inspection measure	Portion	Deterioration factors	Inspection interval
	General appearance	Erosion	Periodic inspection
VT		Corrosion	
VT	, 1	Cracking	
		Leak from weld part	
	Ligament of Furnace header, Economizer header, SH header and RH header inside (including drain and bent tube portion).	Low cycle fatigue	
VT (Endoscope)	Inside of Furnace header, SH header and RH header inside	Corrosion by deteriorated water condition and dead drain during outage	Include in the periodic inspection plan systematically
	Bottom inside of Furnace headers, Economizer headers	Deposition of sludge and initiation of corrosion fatigue crack	
	Final SH header and Final RH header	Exfoliation of steam oxide scale of header inside	
	Representative 2 or more headers inside	Low cycle fatigue Erosion	Periodic inspection (every 4years)
		Deposition	
Chemical analysis of deposit	Bottom inside of Furnace headers, Economizer headers	Deposition of sludge and initiation of corrosion fatigue crack	
VT, Dimension neasurement of corrosion	Stub outside of Economizer header	Low temperature corrosion	Include in the periodic inspection plan systematically
Thickness measurement	Stub tubes of Final SH header and Final RH header	Thinning by high temperature corrosion	

Japanese Boiler Inspection (Header (2))

Header (Water wall header, Evaporator header, Economizer header, SH header, RH header)

Inspection measure	Portion	Deterioration factors	Inspection interval
	Representative stubs with no flexible structure and no rounding of weld end toe	Low cycle fatigue	Periodic inspection (every 2years)
DPT (MPI)	Stub weld of furnace headers, SH headers and RH headers.	Low cycle fatigue	Include in the periodic inspection plan
	Support metal weld of furnace headers, SH headers and RH headers.	Low cycle fatigue	systematically
	Representative header stub weld	Low cycle fatigue	After 80,000 hours operation (Precise
MPI	Representative header girth weld and seam weld	Creep	
Remaining life assessment	Most damaged header or pipe beyond 450°C among furnace headers among SH headers or main steam pipe among RH headers or hot reheat pipe.	Creep	To extend periodical inspection interval 2 year to 4year after 100,000 hours operation
	High temperature Header and pipe	Creep	Include in the periodic inspection plan systematically, taking into consideration of operation hours, start and stop times and designed life.

Japanese Boiler Inspection (Example (1))

Components	Inspected portion	degradation factor	Inspection method	Quantity	Note
Drum	Drum and stub	Corrosion loss, pitching	VT, DPT	1set	
	Stub, longitudinal and circumferential weld	Thermal fatigue crack	VT, DPT	1set	
Furnace	Water wall tube	Erosion thinning	VT、UT	2,000points(*1)	Thickness measurement
					Risidual life asessmer
		High temperature corrosion loss	Sampling tube examionation (tube dimention, hardness, microstructure, adhearing scale volume)	4tubes	Tube sampling
					Risidual life asessmen
	Welding portion of tube with attached metal	Thermal fatigue crack	VT, DPT	200points*(1)	
Furnace header	Headr inside	Scale deposition	VT (Fiber scope)	10 headers	
	Circumferntial weld	Thermal fatigue crack	VT, MPI, Replica	3points	Risidual life asessmen
	Stub, Stub weld portion	Thermal fatigue crack	VT, DPT	360points(* 1)	
SH	Tube	High temperature	VT, UT	300points(*1)	Thickness measurement
		corrosion loss			Risidual life asessmer
		Creep	Sampling tube examionation (tube dimention, hardness, microstructure, adhearing scale volume, creep rupture test)	1 tube	Tube sampling Risidual life asessmen
		SUS scale deposit	Induction method	1200 points (*1)	
	Disimilar weld	Creep fatigue crack	VT, DPT	40points (*1)	
	Welding portion of tube with attached metal	Thermal fatigue crack	VT, DPT	60points (*1)	
SH header	Headr inside	Scale deposition	VT (Fiber scope)	3 headers	
	Circumferntial weld	Thermal fatigue crack	VT, MPI, Replica	3points	Risidual life asessmen
	Stub, Stub weld portion	Thermal fatigue crack	VT, DPT	60points (*1)	

Japanese Boiler Inspection (Example (2))

Components	Inspected portion	degradation factor	Inspection method	Quantity	Note
RH	Tube	High temperature	VT、UT	3000points (*1)	Thickness measurement
		corrosion loss			Risidual life asessment
		Creep	Sampling tube examionation (tube	1 tube	Tube sampling
			dimention, hardness,		
			microstructure, adhearing scale volume, creep rupture		Risidual life asessment
	Disimilar weld	Creep fatigue crack	test) VT, DPT	40points (*1)	
	Welding portion of tube with attached metal	Thermal fatigue crack	VT, DPT	80points (*1)	
RH header	Headr inside	Scale deposition	VI (Fiber scope)	1 header	
	Circumferntial weld	Thermal fatigue crack	VT, MPI, Replica	3points	Risidual life asessment
	Stub, Stub weld portion	Thermal fatigue crack	VT, DPT	680points (*1)	
Economizer	Tube	Erosion thinning	VT, UT	100points (*1)	Thickness measurement
		Corrosion loss			Risidual life asessment
Economizer header	Headr inside	Scale deposition	VT (Fiber scope)	1 header	
	Stub, stub weld	Thermal fatigue crack	VT DPT	40points (*1)	
Main pipe					
Main steam pipe	Longitudinal and circumferential weld	Creep, Creep fatigue	VT, MPI, Replica	3points	Risidual life asessment
Hot reheat pipe	Longitudinal and circumferential weld	Creep, Creep fatigue	VT, MPI, Replica	3points	Risidual life asessment
Boiler circulation	Casing, liner	Corrosion/attrition, thermal fatigue crack	VT、PT、MT	1 pump	
pump	Motor coil (pump in water)	Degradation of electrical insulation	Electrical resistivity measurement	1 pump	
Air heater	Element	Corrosion/attrition	VT, Weight measurement, Pack pressure measurement	4sector	Risidual life asessment

X1: Quantity is 60% of capacity 700MW (Suoer crytical boiler)

The Study on Enhancing Efficiency of Operating Thermal Power Plants in NTPC-India

Boiler Remaining Life Assessment Inspection Report

JICA Study Team (Kyusyu Electric Power Co.,Inc.) Kyudensangyo Co.,Inc

January 2010

Distribution Copy to		Revision			ENVIRONMENT DEPARTMENT		
		Date and Remarks Drawn Checked Approx		Арргочед		mt Group SANGYO CO.,INC	
		June x 2010 Page I-13, I-25 I-1, II-14, II-24, IJ-x9 ferived	S. Nakudiina	K Hotoyan	F Na <i>kashim</i> a		
						Drawn	S. Nakashima
						Checked	K. Motoya ma
						Approved	F. Na kashima
						Initial issue date January 29 2010	
						Report No. 0946-1(3)8-004(Eng)	

Table of content I -1 [Singrauli #6]

[Inspection at site]	
1. Unit for evaluation I -1	
2. Operation condition I -1	
3. Summary of residual life assessment results I -1	
4. Summary of the other inspection results I -2	
5. Components for residual life assessment and inspection I -3	
6. Items for residual life assessment	
7. Results of each observation and quantitative evaluation I -7	
8. Residual life assessment results	
9. The other inspection results I -14	
[Evaluation data]	
Inspection location	
Microstructure observation results I -33	
Creep void observation results	
Precipitates distribution observation results	
Quantitative evaluation of grain boundary precipitates I -36	
Precipitates free band width along grain boundary I -37	
Operational condition of evaluated components I -38	
Evaluation Results	
Residual life assessment results ····· I -47	
[Observation photo]	
Platen-SH Outlet Header-Left	
De-superheater-Left ····· I -65	
De-superheater-Right ····· I -79	
RH Outlet Header-Left I -93	
RH Outlet Header- Right I -107	
Main Steam Pipe-Left(Extrados)	
Main Steam Pipe-Left(Intrados)	
[Inspection record]	
Boiler findings by visual inspection I -149	
Thickness Measurement Results	
Outside Diameter Measurement Results	

Table of content I -2 [Singrauli #6]


[Sample tube inspection]	
1. Unit for evaluation ·····	
2. Sample tube for inspection	
3. Operation condition	I -160
4. Summary of inspection results	I -160
5. Sample tube specification ·····	I -161
6. Inspection item and inspected portion	I -162
7. Inspection results	I -163
(1) Tube appearance	I -163
(2) Tube dimension measurement	I -163
(3) Steam oxide scale adhesion on internal surface	I -165
(4) Hardness measurement	I -166
(5) Metallographic observation	
(6) Creep rupture test ·····	I -168
(7) Residual life assessment by microstructural comparison method	I -172
(Evaluation data)	
Microstructure observation results	
Precipitates distribution observation results·····	
Quantitative evaluation of grain boundary precipitates	I -179
Precipitates free band width along grain boundary	I -180
Evaluation Results	I -181
[Observation photo]	
Tube sampling location	
Tube appearance from outside (boiler front side)	I -185
Tube appearance from inside before and after removal of steam oxide scale ······	
Cross sectional observation of sample tube inside surface	I -192
EPMA analysis results	I -193
Microstructure observation at cross section of sample tube	
Microstructure observation at cross section of sample tube(Platen-SH) ······	I -211
Precipitates along grain boundary by SEM observation(Platen-SH)	I -216
Precipitates distribution by TEM observation(Platen-SH)	I -218
Microstructure observation at cross section of sample tube (RH(in penthouse))	I -222
Precipitates along grain boundary by SEM observation (RH(in penthouse)) ···········	I -227
Precipitates distribution by TEM observation (RH(in penthouse))	I -229
Microstructure observation at cross section of sample tube(RH(in furnace)	I -233
Precipitates along grain boundary by SEM observation(RH(in furnace)	
Precipitates distribution by TEM observation (RH(in furnace))	

Table of content II -1 [Unchahar #2]

[Inspection at site]	
1. Unit for evaluation ·····	П-1
2. Operation condition	· II - 1
3. Summary of residual life assessment results	П-1
4. Summary of the other inspection results	П-2
5. Components for residual life assessment and inspection	· II -3
6. Items for residual life assessment	
7. Results of each observation and quantitative evaluation	· II -7
8. Residual life assessment results	
9. The other inspection results ·····	П-15
[Evaluation data]	
Inspection location	П-31
Microstructure observation results	П-34
Creep void observation results	II -35
Precipitates distribution observation results	II -36
Quantitative evaluation of grain boundary precipitates	П-37
Precipitates free band width along grain boundary	П-38
Operational condition of evaluated components	II -39
Evaluation Results·····	II -40
Residual life assessment results ·····	II -49
[Observation photo]	
Final-SH Outlet Header-Right ·····	П-50
De-superheater-Left ·····	Ⅱ-64
De-superheater-Right ·····	Ⅱ -78
RH Outlet Header-Left	
RH Outlet Header- Right(Top)	II -100
RH Outlet Header- Right(Front)	II -120
Main Steam Pipe- Right (Intrados)	II -134
Main Steam Pipe- Right (Near the stop valve)	Ⅱ-148
Hot Reheat Pipe- Right	II-162
[Inspection record]	
Boiler Findings by visual inspection	II -176
Thickness Measurement Results	II -17
Outside Diameter Messurement Possits	П 19

Table of content II -2 [Unchahar #2]

(Sample tube inspection)	
1. Unit for evaluation	П -188
2. Sample tube for inspection	······ II -188
3. Operation condition	······ II -188
4. Summary of inspection results	····· II -188
5. Sample tube specification ·····	П -189
6. Inspection item and inspected portion	····· II -190
7. Inspection results	····· II -191
(1) Tube appearance	П -191
(2) Tube dimension measurement	····· II -191
(3) Steam oxide scale adhesion on internal surface	∏ -194
(4) Hardness measurement	····· II -195
(5) Metallographic observation	II -197
(6) Creep rupture test ·····	II -197
(7) Residual life assessment by microstructural comparison method	II -202
[Evaluation data]	
Microstructure observation results	II -206
Precipitates distribution observation results	····· II -207
Quantitative evaluation of grain boundary precipitates	II -208
Precipitates free band width along grain boundary	II -209
Evaluation Results····	II -210
(Observation photo)	
Tube sampling location	II -213
Tube appearance from outside (boiler front side)	<i></i>
Tube appearance from inside before and after removal of steam oxide scale	II -215
Cross sectional observation of sample tube inside surface ·····	II -221
EPMAanalysis results	II -222
Microstructure observation at cross section of sample tube	Д -234
Microstructure observation at cross section of sample tube (Platen-SH #3)	П -240
Precipitates along grain boundary by SEM observation (Platen-SH #3)	····· II -245
Precipitates distribution by TEM observation (Platen-SH #3)	····· II - 247
Microstructure observation at cross section of sample tube (Final-SH #1)	II -2 51
Precipitates along grain boundary by SEM observation (Final-SH #1)	II -256
Precipitates distribution by TEM observation (Final-SH #1)	П -258
Microstructure observation at cross section of sample tube (Final-SH #119)	
Precipitates along grain boundary by SEM observation (Final-SH #119)	····· II -267
Precipitates distribution by TEM observation (Final-SH #119)	П -269



Boiler residual life assessment was carried out as one of the activities to improve the efficiency of coal-fired thermal power plants in NTPC-India and transfer to counterpart the technology.

Boiler residual life assessment results are reported as follows.

1. Unit for evaluation

Singrauli Super Thermal Power Station #6 unit

2. Operation condition

(1) Cumulative operation hours: 172,000 hours

(2) Cumulative start and stop times: 309 times

3. Summary of residual life assessment results

The highest creep life consumption ratio among evaluated pipes and headers were 80% at Main Steam Pipe-Left (Circumferential weld, intrados) with the evaluated residual life 21,000 hours and 70% at Main Steam Pipe-Left (Circumferential weld, extrados) with the evaluated residual life 37,000 hours accompanied by microstructural degradation, though no direct creep damage was observed such as creep void and creep strain. The evaluated residual life for the other components was 105,000 hours or more.

It is recommended that the residual life assessment for Main Steam Pipe be carried out again before reaching the evaluated residual life.

Residual life assessment results by microstructural comparison method

Components	Location	Max. creep life consumption ratio (%)	Min. Evaluated residual life (h)	Evaluated region
Platen SH Outlet Header-Left	Circumferential weld at left side	38	140,000	Fine grain HAZ
De-Super heater-Left	Circumferential weld	45	100,000	Coarse grain HAZ
De-Super heater-Right	Circumferential weld	45	100,000	Coarse grain HAZ
RH Outlet Header-Left	Circumferential weld at left side	20	340,000	Coarse grain HAZ
RH Outlet Header-Right	Circumferential weld at right side	6	1,300,000	Base Metal
Main Steam Pipe-Left	Circumferential weld, extrados	70	37,000	Base Metal
Main Steam Pipe-Left	Circumferential weld,intrados	80	21,000	Fine grain HAZ

4. Summary of the other inspection results

(1) Visual inspection

- As results of visual inspection of boiler inside and penthouse, the decrease in thickness by erosion for Water wall tubes around short soot blower and the decrease in thickness by attrition of Platen SH binding tubes and cooling spacer tube in Platen SH were observed.
- Disorder of panel arrangement with distortion was observed at lower part of in Platen SH and RH.
- > No appearance abnormality was observed in stubs and the other weld portions for headers in penthouse.

(2) Thickness measurement

- As a result of thickness measurement for Water wall tubes at erosion area around short soot blowers near each 4 corner (71points in total), the measured thickness for a number of tubes (min. 3.7mm) was less than tsr (thickness required) 5.5mm calculated with designed OD, pressure and allowable stress at the designed temperature.
- As a result of thickness measurement for mainly for outer tubes of rear side portion at soot blower level and outer bottom tubes of Platen SH tube (50points in total), no measured thickness value was found to be below the designed value.

(3) OD measurement

As a result of OD measurement of Platen-SH outlet header-left, De-Super heater (left&right), RH outlet header (left&right) and Main Steam Pipe-left, the increase in measured OD to designed value was less than 1% for each component, indicating no remarkable creep strain

(4) SUS scale deposition inspection

As a result of SUS scale deposition inspection for mainly outermost tubes of Platen-SH and RH 50 points for each, 5 portions were 15% fullness, 3 portions were 10% fullness and the others were less than 10% fullness of SUS scale deposition, indicating no remarkable SUS scale deposition.

(5) Dye penetrant inspection

As a result of Dye penetrant inspection 4 stub weld portions of #5 panel from left of Platen SH inlet, a linear indication was found in tube side, which had disappeared after grinding off 1mm depth from surface.

(6) UT inspection

As a result of UT inspection for RH outlet header-Right, no flaw echo judged as a crack was detected.

(7) TOFD inspection

As a result of TOFD inspection at the location identical to UT inspection in RH outlet header-Right, no flaw echo judged as a crack was detected, although a number of flaw echoes from subtle blow holes and slag inclusions by welding were detected.

5. Components for residual life assessment and inspection

Components for residual life assessment and the other inspections are shown in Table I -1 and Table I -2 respectively.

Location and pictures for each inspection are shown in Fig. I-1 and Photo I-1 \sim 3 respectively.

Table I -1 Components for residual life assessment

		Material		Designed				
Component	Location			O.D.	t	Temperature	Pre	ssure
		ASME	JIS	(mm)	(mm)	(°C)	(MPa)	(kg/cm²)
Platen SH Outlet Header-Left	circumferential weld at left side	SA335P12	STPA22	508.0	80.0	540	17.46	178.0
De-Suerheater-Left	Circumferential weld	SA335P12	STPA22	5000	70.0	406	18.51	188 7
De-Suerheater-Right	Circumferential weld	SA335P12	STPA22	508.0 70.0		0.0 400		100,7
RH Outlet Header-Left	Circumferential weld at left side	SA335P22	STPA24	550.0	50.0	540	406	42.6
RH Outlet Header-Right	Circumferential weld at right side	SA335P22	STPA24	558.8	50.0	540	4.26	43,5
Main Steam Pipe-Left	Circumferential weld, extrados sid	SA335P22	STPA24	520.0	05.0	£40	17.46	170.0
Main Steam Pipe-Left	Circumferential weld, intrados side	SA335P22	STPA24	520.0 85.0		85.0 540	17.46	178.0

Table I -2 Components for the other inspections

Components	Inspection method
Water wall tube	Visual inspection
water wan tube	Thickness measurement of tubes
	Visual inspection
	Thickness measurement of tubes
Platten SH tube	SUS scale deposition inspection
	Tube sampling for sample tube inspection
	Creep rupture test
	Visual inspection
	SUS scale deposition inspection
Reheater tube	Tube sampling for sample tube inspection
	(inspected in Japan).
	Creep rupture test for 1 tube with 1m length.
	Visual inspection
Super heater header	DPT
	Replica inspection
De-Superheater pipe	Replica inspection
	Visual inspection
Dalassas lass de s	Replica inspection
Reheater header	UT
	TOFD
Main steam pipe	Dating in a street
(near the stop valve weld joint)	Replica inspection




Fig. 1-1 Location for each inspection

6. Items for residual life assessment

Items for residual life assessment by microstructural comparison method are shown in Table I -3.

Table I -3 Items for residual life assessment

Components	Location	Material	Area	Microstructure	Carbide precipitation	Creep void grade	Average diameter of grainboundary precipitates	Average volume fraction of grainboundary precipitates	Precipitates free band width along grainboundary
			Base metal	0	0			0	
Platen SH Outlet	circumferential weld		Intercritical zone	0					
Header-Left	at left side	SA335P12	Fine grain HAZ	0	0		0	0	
Treade-Left	at ich side		Coarse grain HAZ	0	0	0		l	
			Weld metal	0	0				
			Base m etal	0	0			0	
			Intercritical zone	0					
De-Suerheater-Left	Circumferential weld	SA335P12	Fine grain HAZ	0	0		0	0	
			Coarse grain HAZ	0	0	0			
			Weld metal	Ô	0				
			Base metal	· O	0			0	
			Intercritical zone	0					
De-Suerheater-Right	Circumferential weld	SA335P12	Fine grain HAZ	0	0		0	0	
			Coarse grain HAZ	0	0	0			
			Weld metal	Ō	0	-	·		
			Base m etal	Ŏ	Ö		0	0	0
	Circumferential weld		Intercritical zone	0					
RH Outlet Header-Left		SA335P22	Fine grain HAZ	0	0		0	0	
	at left side		Coarse grain HAZ	0	-0	0			
			Weld metal	0	0				-
			Base m etal	0	0		0	0	0
	Circumferential weld:	.]	Intercritical zone	0					
RH Outlet Header-Right		SA335P22	Fine grain HAZ	0	0		0	0	
	at right side		Coarse grain HAZ	0	0	0			
			Weld metal	0	0				
			Base m etal	0	0		0	0	0
	Circumferential		Intercritical zone	0					
Main Steam Pipe-Left	weld,extrados	SA335P22	Fine grain HAZ	0	0		0	0	
	weid, extrados		Coarse grain HAZ	0	0	0			
			Weld metal	0	0				
			Base metal	Ö	0		0	0	Ó
	Circumferentia1		Intercritical zone	0					
Main Steam Pipe-Left	weld,intrados	SA335P22	Fine grain HAZ	0	0		0	0	
	weiu,iiiuauos		Coarse grain HAZ	0	0				
			Weld metal	0	0				

(1) Microstructure evaluation

The existence of crack and microstructural degradation was inspected by optical microscope observation.

(Observed region)

Base metal, Intercritical zone, Fine grain HAZ, Coarse grain HAZ, Weld metal (Observed magnification)

 \times 500(2 views), \times 1000(4 views) for each region

(2) Carbide precipitation evaluation

Morphology and distribution of precipitates were inspected by TEM (Transmission Electron Microscope) observation.

(Observed region)

Base metal, Intercritical zone, Fine grain HAZ, Coarse grain HAZ, Weld metal (Observed magnification)

Main steam pipe; ×1000 (2 views), ×5000(3 views), ×10000(2 views)

Other components; ×2000 (2 views), ×10000(4 views)

(3) Creep void grade evaluation

The existence of micro crack and creep void was inspected by SEM (Scanning Electron Microscope) observation.

(Observed region)

Fine grain HAZ, Coarse grain HAZ, Weld metal (Evaluation was focused on Coarse grain HAZ). (Observed magnification)

×500, ×2000 for each region (3 views for each)

(4) Quantitative evaluation of average diameter and volume fraction of grain boundary precipitates

Average diameter and volume fraction of grain boundary precipitates were evaluated quantitatively
by SEM observation.

(Observed region)

Base metal, Fine grain HAZ

(Observed magnification)

Base metal; ×3000, Fine grain HAZ; ×4000 (6 views for each)

(5) Quantitative evaluation of precipitates free band width along grain boundary

Precipitates free band width along grain boundary were evaluated quantitatively by TEM observation.

(Observed region)

Base metal

(Observed magnification)

Base metal; ×2000 (10 points evaluated in 6views)

7. Results of each observation and quantitative evaluation

- 7-1 Replica · extracted replica observation
 - (1) Platen SH Outlet Header-Left (Base metal at left side (SA335P12)

(Microstructure observation)

The results of microstructure observation are shown in Photo I -4-1.

The summary of observation results is shown in Table I -4.

> Precipitates at gain boundary were observed in base metal and intercritical zone.

(Grain boundary precipitates observation)

The results of grain boundary precipitates observation are shown in Photo I -4-10.

> Precipitates on grain boundary were observed in base metal and fine grain HAZ.

(Precipitates distribution observation)

The results of precipitates distribution observation are shown in Photo I -4-13.

The summary of observation results is shown in Table I -6.

- Precipitates free zone along grain boundary and attenuated plate-shaped precipitates were observed in base metal.
- (2) Platen SH Outlet Header-Left (circumferential weld at left side (SA335P12)

(Microstructure observation)

The results of microstructure observation are shown in Photo I -4-2 \sim 6.

The summary of observation results is shown in Table I -4.

- Precipitates at gain boundary were observed in base metal and intercritical zone and fine grain HAZ.
- > Rod-shaped precipitates were observed in ferrite grain of base metal.

(Creep void observation)

The results of creep void observation are shown in Photo I -4- $7\sim9$.

The summary of observation results is shown in Table I -5.

No creep void was observed in fine grain HAZ, coarse grain HAZ and weld metal.

(Grain boundary precipitates observation)

The results of grain boundary precipitates observation are shown in Photo I -4-11 \sim 12.

> Precipitates on grain boundary were observed in base metal and fine grain HAZ.

(Precipitates distribution observation)

The results of precipitates distribution observation are shown in Photo I -4-14 \sim 17.

- > Precipitates free zone along grain boundary and attenuated plate-shaped precipitates were observed in base metal.
- Disintegration of bainite structure was observed in base metal.



(3) De-Suerheater-Left (circumferential weld (SA335P12))

(Microstructure observation)

The results of microstructure observation are shown in Photo I -5-1 \sim 5.

The summary of observation results is shown in Table I -4.

- Precipitates at gain boundary were observed in base metal, intercritical zone, fine grain HAZ and coarse grain HAZ.
- > Coarse granular precipitates were observed in coarse grain HAZ.

(Creep void observation)

The results of creep void observation are shown in Photo I -5-6 \sim 8.

The summary of observation results is shown in Table I -5.

> No creep void was observed in fine grain HAZ, coarse grain HAZ and weld metal.

(Grain boundary precipitates observation)

The results of grain boundary precipitates observation are shown in Photo I -5-9 \sim 10.

Precipitates on grain boundary were observed in base metal and fine grain HAZ.

(Precipitates distribution observation)

The results of precipitates distribution observation are shown in Photo I -5-11 \sim 14.

The summary of observation results is shown in Table I -6.

- > Attenuated plate-shaped precipitates were observed in base metal.
- Fine precipitates had disappeared in fine grain HAZ.
- (4) De-Suerheater-Right (circumferential weld (SA335P12))

(Microstructure observation)

The results of microstructure observation are shown in Photo I -6-1 \sim 5.

The summary of observation results is shown in Table I -4.

- Precipitates at gain boundary were observed in base metal, intercritical zone, fine grain HAZ and coarse grain HAZ.
- > Coarse granular precipitates were observed in coarse grain HAZ.

(Creep void observation)

The results of creep void observation are shown in Photo I -6-6 \sim 8.

The summary of observation results is shown in Table I -5.

➤ No creep void was observed in fine grain HAZ, coarse grain HAZ and weld metal.

(Grain boundary precipitates observation)

The results of grain boundary precipitates observation are shown in Photo I -6-9 \sim 10.

> Precipitates on grain boundary were observed in base metal and fine grain HAZ.

(Precipitates distribution observation)

The results of precipitates distribution observation are shown in Photo I -6-11 \sim 14.

- Attenuated plate-shaped precipitates were observed in base metal.
- > Fine precipitates had disappeared in weld metal.

(5) RH Outlet Header-Left (circumferential weld at left side (SA335P22))

(Microstructure observation)

The results of microstructure observation are shown in Photo I $-7-1 \sim 5$.

The summary of observation results is shown in Table I -4.

Precipitates at gain boundary were observed in base metal, intercritical zone, fine grain HAZ and coarse grain HAZ.

(Creep void observation)

The results of creep void observation are shown in Photo I -7-6 \sim 8.

The summary of observation results is shown in Table I -5.

No creep void was observed in fine grain HAZ, coarse grain HAZ and weld metal.

(Grain boundary precipitates observation)

The results of grain boundary precipitates observation are shown in Photo I -7-9 \sim 10.

Precipitates on grain boundary were observed in base metal and fine grain HAZ.

(Precipitates distribution observation)

The results of precipitates distribution observation are shown in Photo I -7-11 \sim 14.

The summary of observation results is shown in Table I -6.

- > No remarkable degradation of precipitates distribution was observed.
- (6) RH Outlet Header-Right (circumferential weld at right side (SA335P22))

(Microstructure observation)

The results of microstructure observation are shown in Photo I -8-1 \sim 5.

The summary of observation results is shown in Table I -4.

- Precipitates at gain boundary were observed in base metal, intercritical zone and fine grain HAZ.
- > Precipitates free zone along grain boundary was observed in base metal.

(Creep void observation)

The results of creep void observation are shown in Photo I -8-6 \sim 8.

The summary of observation results is shown in Table I -5.

No creep void was observed in fine grain HAZ, coarse grain HAZ and weld metal.

(Grain boundary precipitates observation)

The results of grain boundary precipitates observation are shown in Photo I -8-9 \sim 10.

> Precipitates on grain boundary were observed in base metal and fine grain HAZ.

(Precipitates distribution observation)

The results of precipitates distribution observation are shown in Photo I -8-11~14.

- Precipitates free zone along grain boundary was observed in base metal.
- > No remarkable degradation of precipitates distribution was observed.
- Fine precipitates had disappeared in fine grain HAZ, coarse grain HAZ and weld metal.

(7) Main Steam Pipe-Left (Circumferential weld, extrados (SA335P22))

(Microstructure observation)

The results of microstructure observation are shown in Photo I -9-1 \sim 5.

The summary of observation results is shown in Table I -4.

- > Precipitates at gain boundary were observed in base metal, intercritical zone, fine grain HAZ and coarse grain HAZ.
- Precipitates free zone along grain boundary was observed in base metal and intercritical zone.

(Creep void observation)

The results of creep void observation are shown in Photo I -9-6 \sim 8.

The summary of observation results is shown in Table I -5.

> No creep void was observed in fine grain HAZ, coarse grain HAZ and weld metal.

(Grain boundary precipitates observation)

The results of grain boundary precipitates observation are shown in Photo I -9-9 \sim 10.

> Precipitates on grain boundary were observed in base metal and fine grain HAZ.

(Precipitates distribution observation)

The results of precipitates distribution observation are shown in Photo I -9-11 \sim 14.

The summary of observation results is shown in Table I -6.

- > Precipitates free zone along grain boundary was observed in base metal.
- (8) Main Steam Pipe-Left (Circumferential weld, intrados (SA335P22))

(Microstructure observation)

The results of microstructure observation are shown in Photo I -10-1 \sim 5.

The summary of observation results is shown in Table I -4.

- Precipitates at gain boundary were observed in base metal, intercritical zone and fine grain HAZ.
- Precipitates free zone along grain boundary was observed in base metal and intercritical zone.

(Creep void observation)

The results of creep void observation are shown in Photo I -10-6 \sim 8.

The summary of observation results is shown in Table I -5.

> No creep void was observed in fine grain HAZ, coarse grain HAZ and weld metal.

(Grain boundary precipitates observation)

The results of grain boundary precipitates observation are shown in Photo I -10-9 \sim 10.

> Precipitates on grain boundary were observed in base metal and fine grain HAZ.

(Precipitates distribution observation)


The results of precipitates distribution observation are shown in Photo I -10-11 \sim 14.


- > Precipitates free zone along grain boundary was observed in base metal.
- > Fine precipitates had disappeared in fine grain HAZ, coarse grain HAZ and weld metal.

7-2 Quantitative evaluation of grain boundary precipitates

The results of quantitative evaluation of grain boundary precipitates are shown in Table I -7.

- The Max. value of average diameter of grain boundary precipitates was 0.85 μ m in base metal at De-Superheater-Left, 0.43 μ m in fine grain HAZ at Platen-SH Outlet Header-Left circumferential weld.
- ➤ The max. value of volume fraction of grain boundary precipitates was 0.031 in base metal at Main Steam Pipe-Intrados, 0.031 in fine grain HAZ at Platen-SH Outlet Header-Left circumferential weld.






Quantitative evaluation of grain boundary precipitates [extracted Table I -7]



- 7-3 Quantitative evaluation of precipitates free band width along grain boundary The results of quantitative evaluation of precipitates free band width along grain boundary are shown in Table I -8.
 - > The quantitative evaluation was focused on base metal of SA 335 P22.
 - The Max. value of precipitates free band width along grain boundary was 1.11 μ m at Main Steam Pipe-Extrados.



Precipitates free band width along grain boundary (extracted Table I -8)

8. Residual life assessment results

8-1 Operational condition of evaluated components

Operational condition of evaluated components are shown in Table I -9.

The evaluation stress σ was the hoop stress calculated with designed pressure, designed diameter D and thickness t of each component.

 $\sigma=P(D-t)/2t$

where P: Designed pressure.

8-2 Evaluation results

Evaluation results of residual life assessment for each components by microstructural comparison method are shown in Evaluation Results I $-1 \sim 7$ and Table I -10. The summary of evaluation results are shown in Table I -11

- > The high creep life consumption ratio was evaluated at Main Steam Pipe-Left with high evaluation stress portion.
- ➤ The creep life consumption ratio was 70% and the evaluated residual life was 37,000 hours at Main Steam Pipe-Left (Circumferential weld, extrados) with microstructural degradation that was observed as precipitates free zone along grain boundary in base metal.
- ➤ The creep life consumption ratio was 80% and the evaluated residual life was 21,000 hours at Main Steam Pipe-Left (Circumferential weld, intrados) with microstructural degradation that was observed as disappearance of fine needlelike precipitates.
- > For the other components, the highest creep life consumption ratio was 45% and the evaluated residual life was 100,000 hours at De-Superheater (Left&Right).
- > It is recommended that the residual life assessment for Main Steam Pipe is carried out again before reaching the evaluated residual life.

Table I-11 Summary of residual life evaluation results

Components	Location	Max. creep life consumption ratio (%)	Min. Evaluated residual life (h)	Evaluated region
Platen SH Outlet Header-Left	Circumferential weld at left side	38	140,000	Fine grain HAZ
De-Superheater-Left	Circumferential weld	45	100,000	Coarse grain HAZ
De-Superheater-Right	Circumferential weld	45	100,000	Coarse grain HAZ
RH Outlet Header-Left Circumferential weld at left side		20	340,000	Coarse grain HAZ
RH Outlet Header-Right Circumferential weld at right side		6	1,300,000	Base Metal
Main Steam Pipe-Left Circumferential weld, extrados		70	37,000	Base Metal
Main Steam Pipe-Left	Circumferential weld,intrados	80	21,000	Fine grain HAZ

9. The other inspection results

9-1 Visual inspection, Thickness measurement

Visual inspection results for boiler inside are shown in Table I -12

(Erosion of water wall around short soot blower)

- Erosion by soot blower was observed at a number of Water wall tubes around short soot blower.
- ➤ The thickness measurement was carried out at the representative eroded portion (2nd short soot blower level) as shown in Table I -13~16.
- Min.thickness was 3.7mm at a front wall tube around #1 short soot blower from right, that was less than tsr (thickness required) 5.5mm calculated with designed OD, pressure and allowable stress at the designed temperature.



Erosion of front wall tube (extracted from Table I-12)

(Attrition of Platen-SH binding tube #4 and #5


- Attrition of binding tube #4 and #5 with each other was found.
- > The thickness measurement results are shown in Table I -17.
- Min.thickness was 2.8mm, that was far less than the designed value 6.5mm.



Attrition of binding tube (extracted from Table I-12)

(Thickness measurement of Platen-SH)

- ➤ Thickness was measured mainly for outer tubes of rear side portion at soot blower level and outer bottom tubes as shown in Table I -18.
- ➤ Min.thickness at soot blower level (measurement point A) was 6.3mm, that was not less than the designed value 6.3mm.
- Min.thickness at outer bottom tubes (measurement point B) was 9.8mm, that was larger than the designed value 9.5mm.



Thickness measurement portion of Platen-SH [extracted Table I -18]

(Attrition of cooling spacer tube with Platen-SH front tube of #14 panel)

- > Attrition of a cooling spacer tube with Platen-SH front tube of #14 panel.
- > The thickness measurement results are shown in Table I -17.
- Min.thickness was 5.0mm.



Attrition of cooling spacer tube [extracted Table I -12]

(Erosion of screen tubes near the ceiling between front RH panel and rear RH panel)

> Erosion of screen tubes at front side near the ceiling was found at left side of boiler.



Erosion of rear wall screen tubes [extracted Table I -12]

9-2 OD measurement results

OD measurement results of residual life evaluated portion are shown in Table I $-19 \sim 22$.

> The increase in measured average OD to designed value was less than 1% for each portion, indicating no remarkable creep strain.

Table I -23 OD measurement results of each portion (Increase in measured average OD to designed value)

Components	Location	1	(Averaged measured value- Designed OD) /Designed OD(%)
Platen SH Outlet Header-Left	Circumferential weld at left side	SA335P12	0.10
De-Superheater-Left	Circumferential weld	SA335P12	0.94
De-Superheater-Right	Circumferential weld	SA335P12	0.55
RH Outlet Header-Left	Circumferential weld at left side	SA335P22	0.37
RH Outlet Header-Right	Circumferential weld at right side	SA335P22	0.52
Main Steam Pipe-Left	Circumferential weld, extrados	SA335P22	0.08
Main Steam Pipe-Left	Circumferential weld, intrados	SA335P22	

9-3 SUS scale deposition inspection


Applied equipment and inspection condition are shown in Table I -24.

SUS scale deposition inspection were carried out at outer most tube bend portion and binding tube bottom bend portion of Platen-SH and RH as shown in Fig. I -2.

Table I -24 Applied equipment and inspection condition

	MAKER · TYPE	UNI-ELECTRONICS,Inc. · SSD = 1
CTOR	I.D.№	34A3382(64SCA02101)
DE TE	CHECK DATE PERSON	2009 June 5th · Shinichi Aizawa
	VAIDITY DATE	2010 June 4th
	MAKER · TYPE	HIOKI E. E. CORPORATION · 8205-10
CORDER	I.D.No.	041213164(64SCZ05102)
ECO	CHECK DATE PERSON	2009 May 28th · Shinichi Aizawa
RE-	VAIDITY DATE	2010 May 27th · Shinichi Aizawa

INSPECTION METHOD	Magnetized scale deposition inspection of tube inside with scale detector	
INSPECTION METHOD	Refer to next page	
SENSITIVITY LEVEL	The sensitivity is adjusted at 20mm in amplitude of signal with probe touching right to the reference test piece filled with the w magnetic particle 100% fullness.	
SCANNING SPEED	Approx. 0.3m/sec	
RECORDING RANGE	IV/cm	
RECORDING SPEED	2.5mm/sec	
	Platen SH outer most tube bend portion : φ 54.0× t 9.5 (I.D. No. : 50-21-1)	
DEFENENCE TEAT DIFCE	Platen SH binding tube bottom bend portion : ϕ 47.6× t 6.3 (I.D. No : 40-14-1)	
REFERENCE TEST PIECE	RH outer most tube bend portion : ϕ 54.0× t 4.0 (I.D. No : 50-19-1)	
	RH binding tube bottom bend portion: φ 54.0× t 4.0 (1.D. No: 50-19-	






Fig. I -2 Inspection location

SUS scale deposition inspection results are shown in Table I -25.

- > 15% fullness of SUS scale deposition was detected at 4 outermost tubes of Platen-SH and 1 outermost tube of RH.
- > 10% % fullness of SUS scale deposition was detected at 3 outermost tubes of Platen-SH.
- > The others were less than 10% fullness of SUS scale deposition.

Table I -25 SUS scale deposition inspection results

Platen SH (outermost tube)				RH (outer	most tube)
Fr	Front		ear	Fr	ont
Panel No.	Fullness (%)	Panel No.	Fullness (%)	Panel No.	Fullness (%)
14	15	6	15	3	15
20	10	13	10		
21	15	18	10		
		21	15		

[Remarks]

The signal by magnetization of tube material with heat was recognized at front side outermost tubes in Platen-SH except #1,2,5,7 \sim 11 panel from left and at rear side tubes in Platen-SH except #7 \sim 11 from left.

The representative deposition signal for this inspection is shown in Fig. I -3. The standard curve used is shown in Fig. I -4.




Fig. I -3 The representative deposition signal

Fig. I -3 Representative deposition signal for this inspection




Fig. I -4 Standard curve used for evaluation

9-4 DPT

Applied material and inspection condition are shown in Table I -26.

Inspected location of DPT is shown in Fig. I -5.

DPT inspection were carried out at 4 stub weld portions of #5 panel from left in Platen SH inlet header front side.

Table I -26. Applied material and inspection condition

APPLIED MATERIAL

ij	PENETRANT	BRAND	Eishin Kagaku Co., Ltd.
ERIA		I LIVETRANT	MAKER
MATERIAI	REMOVER	BRAND	Eishin Kagaku Co., Ltd.
		MAKER	R-1S (NT)
APPLIED	DEVELOPER	BRAND	Eishin Kagaku Co., Ltd.
V		MAKER	R-1M (NT)

EXAMINATION CONDITION

EXAMINATION METHOD	Liquid penetrant with removability for solvents - Drying development method	
TIME TO EXAMINATION	at periodic inspection	
TEMPERATURE OF EXAMINATION SURFACE	Normal temperature (10∼50°C)	
EXAMINATION SURFACE CONDITION	As weld	
PRE-TREATMENT	■Rinse with solvents □Others ()	
PENETRATION METHOD	■Spray □Brush painting □Dipping □Others ()	
PENETRATION TIME	10 minutes	
REMOVING OF EXTRA PENETRANT	■ Wipe out with wes (using solvent) □ Others ()	
DEVELOPMENT METHOD	■Spray □Brush painting □Dipping □Others ()	
DEVELOPMENT TIME	10 minutes	
ILLUMINANCE OF EXAMINATION SURFACE/ILLUMINANCE OF ENVIRONMENT	500Lux or more	





Fig. I -5 DPT inspection location

An indication with 2mm in length was found in 3rd stub weld portion from front. The indication disappeared after grinding off the tube 1mm in depth.



9-5 UT

Applied equipment and inspection condition are shown in Table I -27. Inspected location of UT is shown in Fig. I -6.

UT inspection was carried out at circumferential weld of left RH outlet header.

Table I -27 Applied equipment and inspection condition

APPLIED EQUIPMENT AND MATERIAL

	MAKER · TYPE	GE INSPECTIO	N TECHNOLOGIES	· USM35X					
≃	SERIAL No.(I.D.№)	994a(61UAA061	10)						
DETECTOR	AMPLITUDE LINEARITY	within ±3%							
Ĕ	TIME SCALE LINEARITY	within ±1%	within ±1%						
I -	MARGIN OF DETECTION SENSITIVITY	40dB or more							
FLAW	CHECK DATE · PERSON	2008 November 2	2008 November 20th · Hidekazu Ishihara(UT-2)						
	VAIDITY DATE	2009 November	2009 November 19th						
	ТҮРЕ	angle beam probe							
	DESIGNATION	2C14×14A70							
	MAKER	KGK							
	SERIAL No.	XA7424							
	DEAD ZONE	18mm							
PROBE	STB ANGLE OF REFRACTION	70 degree							
PR(ACCESIBLE LIMIT DISTANCE	17mm							
	FAR SURFACE RESOLUTION	7mm							
	CHECK DATE · PERSON	2009 August 26th Ishizaki (UT-2)							
	VAIDITY DATE	2010 February 25th							

EXAMINATION CONDITION

EXAMINATION METHOD	Single angle beam probe technique
TIME TO EXAMINATION	at periodic inspection
SURFACE CONDITION	Grinded surface
COUPLANT	Sonicoat
SPECIFIED SENSITIVITY	RB-41 №2
SENSITIVITY CORRECTION	Non
DISREGARD LEVEL	Regarded as flaw that echo hight is over DAC(H-line)
ACCEPTANCE CRITERIA	Flaw length with t/3 or less
REFERENCE BLOCK OR CALIBRATION BLOCK	RB-41 № 2
ANGLE OF REFRACTION IN TEST OBJECT	ANGLE OF REFRACTION: — CALCULATION METHOD : □ Ratio of sound velocity of STB □ V path technique





Fig. I -6 Inspected location of UT

UT detection results are shown in Table I -28.

No flaw echo exceeded criteria was detected, although 4 flaws exceeded L-line were detected as shown in Table I -28. In Table I -28, symbols are described in the figure shown below.

Table I -28 Detected flaw list

Flaw №	X	Y	W	d	k	Region of echo height	1
1	582	93	104.6	37.5	-4.7	II	10
2	820	122	129.2	46.3	1.4		34
3	° 940	51	26.8 k	9.6	26	I	6
4	1110	101	101.3	36.3	6.4	П	8



9-6 TOFD

Applied equipment and inspection condition are shown in Table I -29.

Table I -29 Applied equipment and inspection condition APPLIED EQUIPMENT AND MATERIAL

AW CTOR	MAKER · TYPE	OLYMPUS NDT μ -Tomoscan					
FL, DETE	SERIAL No.(I.D.№)	23918-15(71UAA96105)					
	DESIGNATION	5MHz、 φ 1/4inch					
PROBE	WEDGES	60°					
PR(MAKER	GE INSPECTION TECHNOLOGIES					
	SERIAL No.	00CP4M,00B25K					

EXAMINATION CONDITION

EXAMINATION METHOD	TOFD technique
TIME TO EXAMINATION	at periodic inspection
SURFACE CONDITION	Grinded surface
COUPLANT	Sonicoat
SPECIFIED SENSITIVITY	φ 4.8mm side cylindrical hole ((d=40mm):80%+6dB
SENSITIVITY CORRECTION	Non
DISREGARD LEVEL	

TOFD inspection was carried out at the location identical to UT inspection.

The range of $X:300\sim600$ mm and $900\sim1200$ mm in circumferential direction was not detectable because of the interference of attached objects.

TOFD detection results are shown in Fig. I -7 \sim 10.

No flaw echo judged as a crack was detected, although a number of flaw echoes from subtle blow holes and slag inclusions by welding were detected.




Fig. I -7 X=0~300mm TOFD detection results




Fig. I -8 X=600~900mm TOFD detection results




Fig. I -9 $X=1200\sim1500$ mm TOFD detection results









Fig. I -10 $X=1500\sim1780$ mm TOFD detection
















Creep rupture test























Table I -4 Microstructure observation resuluts

ম				OM (Optical microscope observation)							
onent		ıtion	Ober				ural features				
Сотропепts		Location	Observed region	Precipitation at gain boundary	Precipitates free zone along grain boundary	Granular precipitates in ferrite grain	Rod-shaped precipitates in ferrite grain	Granular precipitates	Coarse granular precipitates		
		Base	Base metal	Appeared	Not appeared	No precipitation	Not appeared				
eader)	<u>i</u>		Base metal	Appeared	Not appeared	No precipitation	Not appeared				
utlet h 5 P12	et head	ıtial	Intercritical zone	Appeared				Appeared	Not appeared		
Platen SH outlet header (SA 335 P12)	Left outlet header	Circumferential weld	Fine grain HAZ	Appeared					Not appeared		
Platen (Ţ	Circ	Coarse grain HAZ	Not appeared					Not appeared		
			Weld metal					Appeared			
			Base metal	Appeared	Not appeared	No precipitation	Not appeared				
	neater	tial	Intercritical zone	Appeared				Appeared	Not appeared		
	Left de superheater	Circumferential weld	Fine grain HAZ	Appeared					Not appeared		
aire	Left de	Circ	Coarse grain HAZ	Appeared					Appeared		
eater p 5 P12)			Weld metal					Appeared			
De-Superheater pipe (SA 335 P12)			Base metal	Appeared	Not appeared	No precipitation	Not appeared				
De-S	rheater	Circumferential weld	Intercritical zone	Appeared				Appeared	Not appeared		
	Right de superheater		Fine grain HAZ	Appeared					Not appeared		
	čight d	Circu	Coarse grain HAZ	Not appeared					Appeared		
	-		Weld metal					Appeared			
			Base metal	Appeared	Not appeared						
		le il	Intercritical zone	Appeared	Not appeared						
	Left	Circumferential weld	Fine grain HAZ	Appeared							
ader		Circu	Coarse grain HAZ	Appeared							
flet he 5 P22			Weld metal								
Reheater outlet header (SA 335 P22)			Base metal	Appeared	Appeared						
Rehe		ıtial	Intercritical zone	Appeared	Not appeared						
	Right	Circumferential weld	Fine grain HAZ	Appeared							
		Circ	Coarse grain HAZ	Not appeared							
			Weld metal								
		(a.	Base metal	Appeared	Appeared						
		itial op valv de	Intercritical zone	Appeared	Appeared						
		Circumferential (near the stop vextrados side	Fine grain HAZ	Appeared							
ا يو [Circumferential weld (near the stop valve) extrados side	Coarse grain HAZ	Appeared							
am pip 5 P22)	ے	wel	Weld metal								
Main steam pipe (SA 335 P22)	Left	(e)	Base metal	Appeared	Appeared						
¤ º		itial op valv de	Intercritical zone	Appeared	Appeared						
		Circumferential weld (near the stop valve) intrados side	Fine grain HAZ	Appeared							
		Circu d (near intra	Coarse grain HAZ	Not appeared							
		wel	Weld metal								
<u> </u>	Vi	ew nos fi	or each area	×500 (2 views)							
	* 1.	VA 1100, II		×1000 (4 views)							

Table I -5 Creep void observation results


Components		Location	Observed region	SEM (Scanning Electron Microscope observation)
		<u> </u>		Ceep void damage
Platen SH outlet header	neader	ential	Fine grain HAZ	No void
n SH o header	outlet 1	Circumferential weld	Coarse grain HAZ	No void
Plate	Left c	Circ	Weld metal	No void
	erheat	ential	Fine grain HAZ	No void
pipe	Right de superhea Left de superheat Left outlet header	Circumferential weld	Coarse grain HAZ	No void
De-Superheater pipe	Left	Circ	Weld metal	No void
Superl	erhea	ential	Fine grain HAZ	No void
De-	de suj	Circumferential weld	Coarse grain HAZ	No void
	Right	Circ	Weld metal	No void
		Circumferential weld	Fine grain HAZ	No void
eader	Left		Coarse grain HAZ	No void
utlet h		Circ	Weld metal	No void
Reheater outlet header		ıntial	Fine grain HAZ	No void
Rehe	Right	Circumferential weld	Coarse grain HAZ	No void
		Cire	Weld metal	No void
		ential r the re) side	Fine grain HAZ	No void
ъс		Circumferential weld (near the stop valve) extrados side	Coarse grain HAZ	No void
am pi	Left	Circi wel str	Weld metal	No void
Main steam pipc	Ľ	ential r the re) side	Fine grain HAZ	No void
Σ		Circumferential weld (near the stop valve) extrados side	Coarse grain HAZ	No void
		Circ wel ste ext	Weld metal	No void
		View nos. fo	r each area	×500 (3 views)
		7 icw 1103, 10	i caen area	×2000 (3 views)

Table I -6 Precipitates distribution observation results

	T		T	_		TEM (Tra	nsmission Flecti	ron Microscope	observation)		
21					··	1217 (114		tes features	oosei variony		
Components		Location	Observed region	Precipitates free zone along grain boundary	free zone along recipitates and gran			Fine needlelike and granular precipitates in bainite grain	Bainite structure disintegration	Attenuated plate-shaped precipitates	Rod-shaped precipitates, spherodized precipitates
<u>d</u>		Base	Base metal	Appeared		Remaining in ferrite grain			Disintegrated	Appeared	
Platen SH outlet header (SA 335 P12)	eader		Base metal	Not appeared		Remaining in ferrite grain			Disintegrated	Not appeared	
n SH outlet he (SA 335 P12)	Left outlet header	Circumferential weld	Fine grain HAZ			Remaining				Not appeared	Coexist
laten S	Left	Circum	Coarse grain HAZ			Remaining					Coexist
4			Weld metal			Remaining					
	ater	<u></u>	Base metal	Not appeared		Remaining in ferrite grain			Normal structure	Appeared	
	Left de superheater	Circumferential weld	Fine grain HAZ			Disappeared				Not appeared	Coexist
pipe (2)	eft de s	Circum	Coarse grain HAZ			Remaining					Coexist
De-Superheater pipe (SA 335 P12)			Weld metal			Remaining					
Supe (SA 3	eater	ria]	Base metal	Not appeared		Remaining in ferrite grain			Normal structure	Not appeared	
Ĭ Ã	Right de superheater	Circumferential weld	Fine grain HAZ			Remaining				Not appeared	Coexist
			Coarse grain HAZ			Remaining					Coexist
	~		Weld metal			Disappeared					
		[g	Base metal	Not appeared	Remained		No decrease in ferrite grain	Remaining			
	Left	nferent	Fine grain HAZ				Remaining				
Reheater outlet header (SA 335 P22)		Circumferential weld	Coarse grain HAZ			Remaining					
eater outlet hea (SA 335 P22)			Weld metal			Remaining		2			
neater (SA		iai	Base metal	Appeared	Disappeared		No decrease in ferrite grain	Partially disappeared			
Rel	Right	Circumferential weld	Fine grain HAZ				Disappeared				
	ps.	Circur	Coarse grain HAZ			Disappeared					
			Weld metal			Disappeared					
		ial p valve	Base metal	Appeared	Disappeared		No decrease in ferrite grain	Partially disappeared			
		Circumferential weld (near the stop valve) extrados side	Fine grain HAZ				Remaining				\angle
upe 2)		Circun (near 1 extra	Coarse grain HAZ			Remained					
team p	Left	weld	Weld metal			Remained					
Main steam pipe (SA 335 P22)	-	tial p valve e	Base metal	Appeared	Disappeared		No decrease in ferrite grain	Partially disappeared			
		Circumferential weld (near the stop valve) intrados side	Fine grain HAZ				Disappeared				
		Circui I (near intra	Coarse grain HAZ			Disappeared					
		weld	Weld metal			Disappeared					
	Vie	ew nos. fe	or each area	×2000 (2 views)	, ×10000 (4 view	(z					
					•••						

Table I -7 Quantitative evaluation of grain boundary precipitates

	WOTE THE		Average dian	neter (µm)	Volume fraction		
Component	Evaluated location	Material	Base Metal	Fine grain HAZ	Base Metal	Fine grain HAZ	
Platen-SH	Base metal at left side	SA335P12	0.40	_	0.012	-	
OutletHeader-Left	Circumferential weld at left side	SA335P12	0.51	0.43	0.021	0.031	
De-Suerheater-Left	Circumferential weld	SA335P12	0.85	0.33	0.018	0.020	
De-Suerheater- Right	Circumferential weld	SA335P12	0.70	0.35	0.018	0.017	
RH Outlet Header- Left	Circumferential weld at left side	SA335P22	0.43	0.38	0.019	0.025	
RH Outlet Header- Right	Circumferential weld at right side	SA335P22	0.56	0.37	0.024	0.023	
Main Steam Pipe- Left	Circumferential weld, extrados	SA335P22	0.53	0.38	0.022	0.022	
Main Steam Pipe- Left	Circumferential weld,intrados	SA335P22	0.72	0.34	0.031	0.024	






Table I -8 Precipitates free band width along grain boundary

Component	Evaluated location	Material	Precipitates free band width (μm)				
	1000		Base Metal				
RH Outlet Header- Left	Circumferential weld at left side	SA335P22	0.94				
RH Outlet Header- Right	Circumferential weld at right side	SA335P22	1.10				
	Circumferential weld, extrados	SA335P22	1.11				
Main Steam Pipe- Left	Circumferential weld,intrados	SA335P22	0.94				

※1 : Average value of 10 measured points






Table I -9 Operational condition of evaluated components(Singrauli


		Material -		Designed					II. G	
Component	Location			O.D.	t	Temperature	Pressure		Hoop Stress	
		ASME	JIS	(mm)	(mm)	(°C)	(MPa)	(kg/cm ²)	(MPa)	(kg/mm ²)
Platen SH Outlet Header-Left	circumferential weld at left side	SA335P12	STPA22	508.0	80.0	540	17.46	178.0	46.69	4.76
De-Suerheater-Left	Circumferential weld	SA335P12	STPA22	508.0	70.0	406	18.51	188.7	57.89	5.90
De-Suerheater-Right	Circumferential weld	SA335P12	STPA22	308.0						3.90
RH Outlet Header-Left	Circumferential weld at left side	SA335P22	STPA24	5500	50.0	540	4.26	12.5	21.60	0.01
RH Outlet Header-Right	Circumferential weld at right side	SA335P22	STPA24	558.8	50.0	540	4.26	43.5	21.68	2.21
Main Steam Pipe-Left	Circumferential weld, extrados sid	SA335P22	STPA24	520.0	95.0			178.0	44.67	4.55
Main Steam Pipe-Left	Circumferential weld, intrados side	SA335P22	STPA24	520.0	85.0	540	17.46			





Evaluation Results I -1-1 Platen SH Outlet Header-Left Base metal at left side




Evaluation Results I -1-2 Platen SH Outlet Header-Left circumferential weld at left side


















Table I -10 Residual life assessment results

				Evaluation results							
Components	Location	Material Region		Creep life consumption ratio (%)			Residual life (hr)			Evaluated residual life (h)	
	Base Metal at left side		Base Metal	9	~	16	903,000	~	1,739,000		
Platen-SH OutletHeader-		SA 335 P12	Base Metal	9	~	16	903,000	~	1,739,000	140,000	
Left	circumferential weld at left side	SK 333 F12	Fine grain HAZ	34	~	38	281,000	~	334,000	140,000	
	içit side		Coarse grain HAZ	0	~	18	784,000	<			
D 0 1 .			Base Metal	8	~	16	.903,000	~	1,978,000		
De-Suerheater- Left	Circumferential weld	SA 335 P12	Fine grain HAZ	0	~	19	733,000	<		100,000	
Lon			Coarse grain HAZ	19	~	45	210,000	~	733,000		
5 6 1 .	Circumferential weld	SA 335 P12	Base Metal	0	~	1	17,028,000	<]	
De-Suerheater- Right			Fine grain HAZ	0	~	19	733,000	<		100,000	
Kight			Coarse grain HAZ	19	~	45	210,000	~	733,000		
DV. O. 1	Circumferential weld at	SA 335 P22	Base Metal	0	~	1	17,028,000	<		340,000	
RH Outlet Header-Left			Fine grain HAZ	0	~	0.4	42,828,000	<			
Houder-Left	icii side		Coarse grain HAZ	3	~	20	688,000	~	5,561,000		
DU C	61 6 (13 11)		Base Metal	4	~	6	2,695,000	~	4,128,000		
RH Outlet Header-Right	Circumferential weld at right side	SA 335 P22	Fine grain HAZ	0	~	0.4	42,828,000	<		1,300,000	
Treader-Tagin	right side		Coarse grain HAZ	2	~	3	5,561,000	~	8,428,000		
16:5			Base Metal	65	~	70	74,000	~	93,000		
Main Steam Pipe-Left	Circumferential weld, extrados	SA 335 P22	Fine grain HAZ	8	~	21	647,000	~	1,978,000	37,000	
i ipe-Leit	Weld,extrades		Coarse grain HAZ	0	~	20	688,000	<]	
3.4.1.0	C'an Caraci I		Base Metal	65	~	70	74,000	~	93,000		
Main Steam Pipe-Left	Circumferential weld, intrados	SA 335 P22	Fine grain HAZ	78	~	80	43,000	~	49,000	21,000	
i ipo Leit			Coarse grain HAZ	24	~	45	210,000	~	545,000		


^{%1:} Residual life was evaluated with microstructural comparison method of KYUSHYU ELECTRIC POWER CO., INC. RESEARCH LABORATORY.






د لون دهمر


 $\label{lem:photo} Photo \ I \ -4-2 \quad Microstructure \ observation \\ Platen \ SH \ Outlet \ Header-Left \ (Circumferential \ weld \ at \ left \ side \ : Base \ metal \)$




 $Photo\ I\ -4-3\quad Microstructure\ observation$ Platen SH Outlet Header-Left (Circumferential weld at left side : Intercritical zone)



 $Photo\ I\ -4-4\quad Microstructure\ observation$ Platen SH Outlet Header-Left (Circumferential weld at left side : Fine grain NAZ)



 $Photo\ I\ -4-5\quad Microstructure\ observation$ Platen SH Outlet Header-Left (Circumferential weld at left side : Coarse grain HAZ)



 $\label{lem:photo} Photo \ I \ -4-6 \quad Microstructure \ observation \\ Platen \ SH \ Outlet \ Header-Left \ (Circumferential \ weld \ at \ left \ side \ : Weld \ metal \)$




Photo I -4-7 SEM(Scanning electron microscope) observation Platen SH Outlet Header-Left(Circumferential weld at left side: Fine grain HAZ)




Photo I -4-8 SEM(Scanning electron microscope) observation Platen SH Outlet Header-Left(Circumferential weld at left side: Coarse grain HAZ)




Photo I -4-9 SEM(Scanning electron microscope) observation Platen SH Outlet Header-Left(Circumferential weld at left side: Weld metal)




Photo I -4-10 Precipitates along grain boundary by SEM observation Platen SH Outlet Header-Left(Base metal at left side: Base metal)




Photo I -4-11 Precipitates along grain boundary by SEM observation Platen SH Outlet Header-Left(Circumferential weld at left side: Base metal)




Photo I -4-12 Precipitates along grain boundary by SEM observation Platen SH Outlet Header-Left(Circumferential weld at left side: Fine grain HAZ)




Photo I -4-13 Precipitates by TEM (Transmission electron microscope) observation Platen SH Outlet Header-Left (Base metal at left side: Base metal)




Photo I -4-14 Precipitates by TEM (Transmission electron microscope) observation Platen SH Outlet Header-Left(Circumferential weld at left side: Base metal)




Photo I -4-15 Precipitates by TEM (Transmission electron microscope) observation Platen SH Outlet Header-Left (Circumferential weld at left side: Fine grain HAZ)




Photo I -4-16 Precipitates by TEM (Transmission electron microscope) observation Platen SH Outlet Header-Left(Circumferential weld at left side: Coarse grain HAZ)




Photo I -4-17 Precipitates by TEM (Transmission electron microscope) observation Platen SH Outlet Header-Left(Circumferential weld at left side: Weld metal)





Photo I -5-1 Microstructure observation De-Superheater-Left (Circumferential weld : Base metal)



3

 $\begin{array}{cccc} & Photo \ I \ -5-2 & Microstructure \ observation \\ De-Superheater-Left \ (Circumferential \ weld \ : Intercritical \ zone \) \end{array}$





Photo I -5-3 $\,$ Microstructure observation De-Superheater-Left (Circumferential weld : Fine grain HAZ)



13

Photo I -5-4 Microstructure observation De-Superheater-Left (Circumferential weld : Coarse grain HAZ)




Photo I -5-5 Microstructure observation De-Superheater-Left (Circumferential weld : Weld metal)




Photo I -5-6 SEM(Scanning electron microscope) observation De-Superheater-Left(Circumferential weld: Fine grain HAZ)




Photo I -5-7 SEM(Scanning electron microscope) observation De-Superheater-Left(Circumferential weld: Coarse grain HAZ)




Photo I -5-8 SEM(Scanning electron microscope) observation De-Superheater-Left(Circumferential weld: Weld metal)




Photo I -5-9 Precipitates along grain boundary by SEM observation De-Superheater-Left(Circumferential weld: Base metal)




Photo I -5-10 Precipitates along grain boundary by SEM observation De-Superheater-Left (Circumferential weld: Fine grain HAZ)




Photo I -5-11 Precipitates by TEM (Transmission electron microscope) observation De-Superheater-Left(Circumferential weld: Base metal)




Photo I -5-12 Precipitates by TEM (Transmission electron microscope) observation De-Superheater-Left (Circumferential weld: Fine grain HAZ)






Photo I -5-13 Precipitates by TEM (Transmission electron microscope) observation De-Superheater-Left(Circumferential weld: Coarse grain HAZ)






Photo I -5-14 Precipitates by TEM (Transmission electron microscope) observation De-Superheater-Left(Circumferential weld: Weld metal)















720

 $\begin{array}{cccc} Photo \ I \ -6-1 & Microstructure \ observation \\ De-Superheater-Right \ (Circumferential \ weld \ : Base \ metal \) \end{array}$



120

 $\label{lem:photo} Photo\ I\ -6-2\quad Microstructure\ observation \\ \ De-Superheater-Right\ (Circumferential\ weld\ :\ Intercritical\ zone\)$







Photo I -6-3 Microstructure observation De-Superheater-Right (Circumferential weld : Fine grain HAZ)




 $\begin{array}{cccc} Photo \ I - 6 - 4 & Microstructure \ observation \\ De-Superheater-Right \ (Circumferential \ weld \ : Coarse \ grain \ HAZ \) \end{array}$



 $\begin{array}{cccc} Photo \ I -6-5 & Microstructure \ observation \\ De-Superheater-Right \ (Circumferential \ weld \ : \ Weld \ metal \) \end{array}$
















Photo I -6-6 SEM(Scanning electron microscope) observation De-Superheater-Right(Circumferential weld: Fine grain HAZ)




Photo I -6-7 SEM(Scanning electron microscope) observation De-Superheater-Right(Circumferential weld: Coarse grain HAZ)






Photo I -6-8 SEM(Scanning electron microscope) observation De-Superheater-Right(Circumferential weld: Weld metal)




Photo I -6-9 Precipitates along grain boundary by SEM observation De-Superheater-Right(Circumferential weld: Base metal)




Photo I -6-10 Precipitates along grain boundary by SEM observation De-Superheater-Right (Circumferential weld: Fine grain HAZ)




Photo I -6-11 Precipitates by TEM (Transmission electron microscope) observation De-Superheater-Right(Circumferential weld: Base metal)




Photo I -6-12 Precipitates by TEM (Transmission electron microscope) observation De-Superheater-Right (Circumferential weld: Fine grain HAZ)




Photo I -6-13 Precipitates by TEM (Transmission electron microscope) observation De-Superheater-Right (Circumferential weld: Coarse grain HAZ)






Photo I -6-14 Precipitates by TEM (Transmission electron microscope) observation De-Superheater-Right (Circumferential weld: Weld metal)




180

 $\label{lem:photo} Photo\ I\ -7-1\quad Microstructure\ observation \\ RH\ Outlet\ Header-Left\ (Circumferential\ weld\ at\ left\ side\ : Base\ metal\)$




3

 $\label{lem:photo} Photo\ I\ \mbox{-7-2}\quad Microstructure\ observation \\ RH\ Outlet\ Header-Left\ (\mbox{Circumferential weld at left side}\ : Intercritical\ zone\)$



 $\label{lem:photoI-7-3} Photo I -7-3 \quad \mbox{Microstructure observation} \\ \mbox{RH Outlet Header-Left (Circumferential weld at left side : Fine grain HAZ)} \\$



 $\label{lem:photo} Photo\ I\ \mbox{-}7\mbox{-}4\ \ \mbox{Microstructure observation} \\ RH\ Outlet\ Header-Left\ (\mbox{Circumferential weld at left side : Coarse grain HAZ}\)$




Photo I -7-5 Microstructure observation RH Outlet Header-Left (Circumferential weld at left side : Weld metal)




Photo I -7-6 SEM(Scanning electron microscope) observation RH Outlet Header-Left(Circumferential weld at left side: Fine grain HAZ)






Photo I -7-7 SEM(Scanning electron microscope) observation RH Outlet Header-Left(Circumferential weld at left side: Coarse grain HAZ)




Photo I -7-8 SEM(Scanning electron microscope) observation RH Outlet Header-Left(Circumferential weld at left side: Weld metal)




Photo I -7-9 Precipitates along grain boundary by SEM observation RH Outlet Header-Left (Circumferential weld at left side: Base metal)




Photo I -7-10 Precipitates along grain boundary by SEM observation RH Outlet Header-Left (Circumferential weld at left side: Fine grain HAZ)




Photo I -7-11 Precipitates by TEM (Transmission electron microscope) observation RH Outlet Header-Left(Circumferential weld at left side: Base metal)




Photo I -7-12 Precipitates by TEM (Transmission electron microscope) observation RH Outlet Header-Left(Circumferential weld at left side: Fine grain HAZ)




Photo I -7-13 Precipitates by TEM (Transmission electron microscope) observation RH Outlet Header-Left (Circumferential weld at left side: Coarse grain HAZ)






Photo I -7-14 Precipitates by TEM (Transmission electron microscope) observation RH Outlet Header-Left(Circumferential weld at left side: Weld metal)



 $Photo\ I\ -8-1\quad Microstructure\ observation\\ RH\ Outlet\ Header-Right\ (Circumferential\ weld\ at\ right\ side\ : Base\ metal\)$



 $\label{lem:photo} Photo \ I-8-2 \quad Microstructure \ observation \\ RH \ Outlet \ Header-Right \ (Circumferential \ weld \ at \ right \ side \ : Intercritical \ zone \)$





 $\label{lem:contracture} Photo \ I-8-3 \quad Microstructure \ observation \\ RH \ Outlet \ Header-Right \ (Circumferential \ weld \ at \ right \ side \ : Fine \ grain \ HAZ \)$







Photo I -8-4 Microstructure observation RH Outlet Header-Right (Circumferential weld at right side : Coarse grain HAZ)



 $\label{lem:photo} Photo \ I-8-5 \quad Microstructure \ observation \\ \ RH \ Outlet \ Header-Right \ (Circumferential \ weld \ at \ right \ side \ : \ Weld \ metal \)$




Photo I -8-6 SEM(Scanning electron microscope) observation RH Outlet Header-Right(Circumferential weld at right side: Fine grain HAZ)




Photo I -8-7 SEM(Scanning electron microscope) observation RH Outlet Header-Right(Circumferential weld at right side: Coarse grain HAZ)




Photo I -8-8 SEM(Scanning electron microscope) observation RH Outlet Header-Right(Circumferential weld at right side: Weld metal)




Photo I -8-9 Precipitates along grain boundary by SEM observation RH Outlet Header-Right (Circumferential weld at right side: Base metal)




Photo I -8-10 Precipitates along grain boundary by SEM observation RH Outlet Header-Right (Circumferential weld at right side: Fine grain HAZ)




Photo I-8-11 Precipitates by TEM (Transmission electron microscope) observation RH Outlet Header-Right (Circumferential weld at right side: Base metal)




Photo I -8-12 Precipitates by TEM (Transmission electron microscope) observation RH Outlet Header-Right (Circumferential weld at right side: Fine grain HAZ)




Photo I -8-13 Precipitates by TEM (Transmission electron microscope) observation RH Outlet Header-Right(Circumferential weld at right side: Coarse grain HAZ)







Photo I-8-14 Precipitates by TEM (Transmission electron microscope) observation RH Outlet Header-Right(Circumferential weld at right side: Weld metal)




 $\begin{array}{cccc} & Photo \ I - 9 - 1 & Microstructure \ observation \\ Main \ Steam \ Pipe-Left \ (Circumferential \ weld, extrados \ : Base \ metal \) \end{array}$



 $\begin{array}{cccc} & Photo \ I - 9 - 2 & Microstructure \ observation \\ Main \ Steam \ Pipe-Left \ (Circumferential \ weld, extrados \ : Intercritical \ zone \) \end{array}$



 $\begin{array}{ccc} Photo\ I-9-3 & Microstructure\ observation \\ Main\ Steam\ Pipe-Left\ (Circumferential\ weld, extrados\ : Fine\ grain\ HAZ\) \end{array}$



 $\label{lem:photo} Photo \ I \ -9-4 \quad Microstructure \ observation \\ \ Main \ Steam \ Pipe-Left \ (Circumferential \ weld, extrados \ : Coarse \ grain \ HAZ \)$




Photo I -9-5 Microstructure observation Main Steam Pipe-Left (Circumferential weld, extrados : Weld metal)




Photo I -9-6 SEM(Scanning electron microscope) observation Main Steam Pipe-Left(Circumferential weld, extrados: Fine grain HAZ)




Photo I -9-7 SEM(Scanning electron microscope) observation Main Steam Pipe-Left(Circumferential weld, extrados: Coarse grain HAZ)






Photo I -9-8 SEM(Scanning electron microscope) observation Main Steam Pipe-Left(Circumferential weld, extrados: Weld metal)




Photo I -9-9 Precipitates along grain boundary by SEM observation Main Steam Pipe-Left (Circumferential weld, extrados: Base metal)




Photo I -9-10 Precipitates along grain boundary by SEM observation Main Steam Pipe-Left (Circumferential weld, extrados: Fine grain HAZ)






Photo I -9-11 Precipitates by TEM (Transmission electron microscope) observation Main Steam Pipe-Left(Circumferential weld, extrados: Base metal)



20

Photo I -9-12 Precipitates by TEM (Transmission electron microscope) observation Main Steam Pipe-Left(Circumferential weld, extrados: Fine grain HAZ)



3

Photo I -9-13 Precipitates by TEM (Transmission electron microscope) observation Main Steam Pipe-Left(Circumferential weld, extrados : Coarse grain HAZ)








Photo I -9-14 Precipitates by TEM (Transmission electron microscope) observation Main Steam Pipe-Left(Circumferential weld, extrados: Weld metal)






 $\begin{array}{cccc} Photo \ I \ \hbox{--}10 \hbox{--}1 & \ Microstructure observation} \\ Main \ Steam \ Pipe-Left \ (Circumferential \ weld, intrados \ : Base \ metal \) \end{array}$



 $\begin{array}{cccc} & Photo \ I\ -10-2 & Microstructure\ observation \\ Main\ Steam\ Pipe-Left\ (Circumferential\ weld, intrados\ : Intercritical\ zone\) \end{array}$



 $\label{lem:photoI-10-3} Photo\ I\ -10-3\ \ \ Microstructure\ observation$ Main Steam Pipe-Left (Circumferential weld, intrados : Fine grain HAZ)




Photo I -10-4 Microstructure observation

Main Steam Pipe-Left (Circumferential weld, intrados : Coarse grain HAZ)




Photo I -10-5 Microstructure observation Main Steam Pipe-Left (Circumferential weld, intrados : Weld metal)




Photo I -10-6 SEM(Scanning electron microscope) observation Main Steam Pipe-Left(Circumferential weld, intrados : Fine grain HAZ)






Photo I -10-7 SEM(Scanning electron microscope) observation Main Steam Pipe-Left(Circumferential weld, intrados : Coarse grain HAZ)




Photo I -10-8 SEM(Scanning electron microscope) observation Main Steam Pipe-Left(Circumferential weld, intrados: Weld metal)




Photo I -10-9 Precipitates along grain boundary by SEM observation Main Steam Pipe-Left (Circumferential weld, intrados : Base metal)




Photo I -10-10 Precipitates along grain boundary by SEM observation Main Steam Pipe-Left (Circumferential weld, intrados: Fine grain HAZ)






Photo I -10-11 Precipitates by TEM (Transmission electron microscope) observation Main Steam Pipe-Left(Circumferential weld, intrados: Base metal)




Photo I -10-12 Precipitates by TEM (Transmission electron microscope) observation Main Steam Pipe-Left(Circumferential weld, intrados: Fine grain HAZ)




Photo I -10-13 Precipitates by TEM (Transmission electron microscope) observation Main Steam Pipe-Left(Circumferential weld, intrados: Coarse grain HAZ)




Photo I -10-14 Precipitates by TEM (Transmission electron microscope) observation Main Steam Pipe-Left(Circumferential weld, intrados: Weld metal)




Table I -12 Singrauli #6 Boiler findings by visual inspection

Table I-13 (Singrauli) WATER WALL Front wall Thickness Measurement Results

Tube number from sootblower center veiwed from furnace inside 9 10 11 12 13 14 15 15 14 13 12 11 10 Min. value in thin portion (mm) 1000 Distance from sootblower center in vertical direction(mm)




Table I -14 (Singrauli) WATER WALL Rear wall Thickness Measurement Results




Table I -15 (Singrauli) WATER WALL Left side wall Thickness Measurement Results

Tube number from soot blower center veiwed from furnace inside 15 14 13 12 11 10 9 8 7 6 5 4 3 2 1 1 2 7 9 10 11 12 13 14 15 Min. value in thin portion 4.7 5.2 5.4 4.9 5.2 5.5 4.6 4.3 4.6 4.3 4.9 4.9 5.1 4.9 5.3 5.4 4.6 (mm) 1000 900 800 700 600 500 Distance from sootblower center in vertical direction(mm) 400 300 200 100 0 100 200 300 400 500 600 700 800 900




Table I-16 (Singrauli) WATER WALL Rightt side wall Thickness Measurement Results

Tube number from soot blower center veiwed from furnace inside 9 10 11 12 13 14 15 15 14 13 12 11 10 9 4 3 2 Min. value in thin portion 4.6 4.1 3.9 4.6 (mm) 1000 Distance from sootblower center in vertical direction(mm)





Table I-17 (Singrauli) Platen SH Thickness Measurement Results

Binding tube:

SA213TP347H φ47.63×t6.3

5L

Cooling spacer tube:



 Binding tube

 Panel No. (From left)
 Thin point point

 4R
 2.8
 6.5

(unit:mm)

6.6

Cooling spacer tube

Attrition point with	
front tube of #14	5.0

3.3

(unit:mm)



Thining portion of binding tube



Thining portion of cooling spacer tube


Table I -18 (Singrauli) Platen SH Thickness Measurement Results

Tube specification Point A: SA213TP347H φ63.5×t6.3

Point B: SA213TP347H φ54.0×t9.5

ACT CAN	ا ا	3000	March 1987 September
12 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		SB OO Point A	Contraction Contra
CHE TOTAL TOTAL THE T		2012 2012 2012 2012 2012 2012 2012 2012	1966 - m-03-4

D131		
Panel No.	Point A	Point B
(From left)		
1	6.5	10.2
2	6.6	10.0
3 4	6.5	10.0
4	6.6	10.3
5	6.6	10.0
6	6.5	10.4
7	6.8	10.4
8	6.5	10.4
9	6.7	10.5
10	6.5	10.1
11	6.7	10.5
12	6.3	9.8
13	6.4	10.2
14	7.2	10.0
15	6.3	10.0
16	6.4	10.2
17	6.4	10.1
18	6.9	10.4
19	6.6	9.9
20	6.5	10.1
21	7.1	10.0
22	6.4	10.0
23	6.5	10.3
24	6.5	10.1
		(unit:mm)







Table I -19 (Singrauli) PLATEN-SH Outlet Header Outside Diameter Measurement Results

Components	Material	Designed	Position	Panion	-	Measured	value (mm)	Averaged	(Averaged measured
		OD	1.000	Region	1⇔5	2⇔6	3⇔7	4⇔8	(mm)	value-Designed OD) /Designed OD(%)
PLATEN SH	SA335 P.12	508 Omm	(Header side)	Base metal	508.03	508.36	508.75	508.95	508.52	+0.10
Outlet Header	ATEN SH tlet Header SA335 P-12 508.0m		(ricade) side)	HAZ	506.82	508.35	507.85	508.42	507.86	-0.03








Table I -20 (Singrauli) De-Superheater Pipe Outside Diameter Measurement Results


	Designed				Measured	value (mm)	Averaged	(Averaged measured		
Components	Material	OD	Position Region	Region	1005	2⇔6	3⇔7	4⇔8	(mm)	value-Designed OD) /Designed OD(%)	
De-Superheater	C 1 2 2 C D 12 C 0 C 0	rheater SA335 P-12 508.0mm Down	500 0	Downstream side	Base metal	513.22	513.21	512.02	512.72	512.79	+0.94
Pipe (Right)	SA333 F-12	508.0mm	(Straight pipe side)	HAZ	511.85	512.35	511.80	511.60	511.90	+0.77	
De-Superheater	011111011	e00.0	Downstream side	Base metal	509.87	511.60	511.41	510.32	510.80	+0.55	
Pipe(Lefit) SA335 P-12 508	508.0mm	(Straight pipe side)	HAZ	509.17	511.25	511.37	510.06	510.46	+0.48		





Measurement point of right De-superheater pipe

Measurement point of left De-superheater pipe






Table I -21 (Singrauli) Re-Heater Outlet Header Outside Diameter Measurement Results

Components	Material	Designed	Position	Region	Measured value (mm)				Averaged	(Averaged measured
Components	Material	OD	rosmon		1⇔5	2⇔6	3⇔7	4⇔8	(mm)	value-Designed OD) /Designed OD(%)
Re-Heater Outlet	SA335 P-22	550 0mm	(Header side)	Base metal	561.16	561.31	562.16	562.16	561.70	+0.52
Header(Right)	ON333 1-22	558.8mm	(rieader side)	HAZ	560.33	561.16	562.05	561.88	561.36	+0.46
Re-Heater Outlet	SA335 P.22	550 0mm	(Header side)	Base metal	560.40	560.68	561.21	561.10	560.85	+0.37
Header(Left)	ader(Left) SA335 P-22 558.8mm		(ricader side)	HAZ	559.47	560.64	560.55	561.00	560.42	+0.29





Measurement point of left RH outlet header

Measurement point of right RH outlet header





Table I -22 (Singrauli) Main Steam Pipe Outside Diameter Measurement Results

	.0	Designed				Measured	value (mm)	Averaged	(Averaged measured
Components	Material	OD	Position	Region	1⇔5	2⇔6	3⇔7	4⇔8	(mm)	value-Designed OD) /Designed OD(%)
		Upstream side	Base metal	521.45	525.17	527.46	531.70	526.45	+1.24*	
. ren	C 1 222 D 22	***	(Elbow side)	HAZ	520.20	520.80	522.38	521.84	521.31	+0.25*
MSP	SA335 P-22	35 P-22 520.0mm	Downstream side (Straight pipe	Base metal	520.15	520.19	520.58	520.79	520.43	+0.08
				HAZ	520.15	520.52	519.92	520.61	520.30	+0.06

^{*:} Upstream side value is reference because of elbow side.





Sample tube inspection [Singrauli #6]

Sample tube inspection and creep rupture test were carried out as one of the boiler residual life assessment items for Singrauli Super Thermal Power Station #6 unit. The results are reported as follows.

1. Unit for evaluation

Singrauli Super Thermal Power Station #6 unit

2. Sample tube for inspection

- · Platen-SH tube
- · RH tube (Penthouse portion, Furnace portion)

3. Operation condition

(1) Cumulative operation hours: 172,000 hours

(2) Cumulative start and stop times: 309 times

4. Summary of inspection results

- (1) As a result of tube appearance observation after acid cleaning, traces of corrosion at outside surface and slightly rough condition at inside surface were observed for each sample tube.
- (2) As a result of tube dimension measurement, OD of RH tubes in penthouse and in furnace was less than designed value, the thickness of RH tubes in penthouse was less than designed value.
- (3) As a result of steam oxide scale examination, steam oxide scale was adhering evenly by cross sectional observation for RH tube in penthouse and in furnace, unevenly for Platen-SH tube.
 - Average thickness of steam oxide scale mainly consisting of Fe and O was remarkably larger in RH tube (in penthouse) than in Platen-SH tube and RH tube (in furnace).
- (4) As a result of hardness measurement, the hardness values were stable in circumferential direction, though measured values were out of the normal value of virgin material by Japanese steel manufacturer.
- (5) As a result of creep rupture test, the evaluated residual life of Platen-SH tube was 290,000 hours for base metal, 150,000hours for weld joint at equivalent temperature 553℃ estimated by comparison with the average creep rupture data of NIMS.
 - The evaluated residual life of RH tube in furnace was 670,000 hours for base metal and 610,000 hours for weld joint at equivalent temperature 551°C estimated by comparison with the average creep rupture data of NIMS.
 - Each portion has enough evaluated residual life at present, with the min. evaluated residual life of 150,000 hours for weld joint portion of Platen-SH tube.
- (6) As a result of microstructure comparison method, the evaluated residual life was 82,000 hours for RH tube (in furnace), 520,000 hours for RH tube (in penthouse) and 1,300,000 hours for Platen-SH tube.

5. Sample tube specification

Sample tube specification is shown in Table I -30.

Table I -30 Sample tube specification

Sample	Material	Designed OD×t(mm)	Designed Temperature(°C)	Designed Pressure (MPa)
Platen-SH #12-3	SA213T11*	φ 47.63×t8.6	Not available	17.46
1 Idien-311 #12-3	SA213T11	φ 47.63×t10.0	Not available	17.40
RH #3-1	SA213T22**	φ 54.0×t5.6	540	5 27
(in penthouse)	SA213T22	φ 54.0×t5.6	540	5.27
RH #14-5	RH #14-5 SA213T22		Not available	5 27
(in furnace)	SA213T11*	φ 54.0×t4.0	Not available	5.27

Chemical composition analysis was conducted as shown below.
 The material of Platen-SH#12-3 appeared to be SA213T11 by chemical composition analysis, though the material specification was supposed to be SA213T22 for Platen-SH#12-3 according to the drawing.

Chemical composition analysis results by spark discharge optical emission analysis (wt%)

						•	
Sample tube	С	Si	Mn	P	S	Cr	Мо
Platen-SH#12-3	0.10	0.53	0.38	0.026	0.012	1.14	0.46
RH #3-1 (in penthouse)	0.10	0.28	0.45	0.013	0.008	2.20	0.95
RH #14-5 (in furnace)	0.10	0.67	0.41	0.006	0.008	1.30	0.58
SA213T11 (JIS-STBA23)	≦ 0.15	0.50~1.00	0.30~0.60	≦0.030	≦0.030	1.00~1.50	0.45~0.65
SA213T22 (JIS-STBA24)	≦ 0.15	≦0.50	0.30~0.60	≤0.030	≦0.030	1.90~2.60	0.87~1.13

6. Inspection item and inspected portion


Inspection item and inspected portion are shown in Table I -31.

Table I -31 Inspection item

		Inspection item											
	1	2	3	3 4		6	7						
Sample tube	Outer surface appearance	Internal surface appearance	Tube dimension • Hardness	Metallography	Scale analysis	RLA by microstructure degradation	Creep rupture test						
Platen-SH	0	0	0	0	0	0	0						
RH(in penthouse)	0	0	0	0	0	0	_						
RH(in furnace)	0	0	0	0	0	0	0						

Sample tube appearance and sampling location are shown in Photo I -11.

Sampling portion for each inspection item is shown in Fig I -11.



- 1: Outer surface appearance 2: Internal surface appearance 3: Tube dimension Hardness 4: Metallography
- 5: Scale thickness, EPMA analysis, 6: RLA by microstructural comparison method 7: Creep rupture test

Fig I -11 Sampling portion for each inspection item

7. Inspection results

- (1) Tube appearance
 - a. Tube appearance from outside (Photo I -12)
 - ➤ Hard oxide scale was adhering for each sample tube outer surface, with light brown color in Platen-SH tube, red brown color in RH tube (penthouse) and dark brown color in RH tube (furnace).
 - > Traces of corrosion were observed in each sample tube outside surface after acid cleaning.
 - b. Tube appearances of sample tubes from inside after removal of steam oxide scale (Photo I -13 \sim 18) (Platen SH tube)
 - ➤ Internal surface of both front and rear side were covered with gray and red color steam oxide scale.
 - > Slight rough internal surface was observed after acid cleaning.


(RH tube (in penthouse, furnace))

- ➤ Internal surface of both front and rear side were covered with gray color steam oxide scale with scale exfoliation partially observed on rear side.
- > Slightly rough internal surface was observed after acid cleaning.
- (2) Tube dimension measurement (Table I -32, Fig I -12)
 - a. OD measurement
 - OD of RH tubes in penthouse and furnace were measured to be less than designed values.
 - b. Thickness measurement

Thickness of RH tubes in penthouse was measured to be less than designed values.

Table I -32 Tube dimension measurement results

C1- 4-1	6		DD (mm)		Thickness (mm)							
Sample tube	Specification	Direction	OD	ID	1	2	3	4	6	6	7	8
		a	47.85	26.60	10.50				10.70			
Platen-SH	Φ47.63×t10.0	b	47.90	26.60		10.65				10.65		
Fiaten-3H	Ψ47.03^110.0	С	47.80	26.60			10.70				10.50	
		d	47.80	26.60				10.75				10.50
		a	52.95	42.25	5.30				5.45			
RH(in penthouse)	Φ54.0×t5.6	b	52.85	42.25		5.25				5.35		
Kri(iii pentilouse)	Ψ34.0^(3.0	С	53.30	42.15			5.30				5.80	
		d	52.95	42.15				5.35				5.40
		a	53.75	43.65	5.10				5.05			
RH(in furnace)	Φ54.0×t4.5	b	54.00	43.95		4.95				5.10		
Kii(iii iui iiace)	Ψ34.0^ι4.3	C	54.00	43.95			4.90				5.20	
		d	53.75	43.65				4.95				5.15






Fig I -12 Tube dimension measurement results

(3) Steam oxide scale adhesion on internal surface

a. Cross sectional observation of internal surface (Photo I -19)

(Platen SH tube)

- > Steam oxide scale was adhering unevenly by cross sectional observation.
- Corrosion in metal surface was observed with rugged interface between steam oxide scale and metal.

(RH tube in penthouse)

> Steam oxide scale was adhering evenly by cross sectional observation with dual layer consisting of dense inner layer and slightly porous outer layer.


(RH tube in furnace)

- > Steam oxide scale was adhering evenly by cross sectional observation with the thicker scale on left and right side surfaces than the scale on front and rear side.
- b. Thickness measurement of steam oxide scale on internal surface (Table I -33)

 Average thickness of steam oxide scale was remarkably larger in RH tube (in penthouse) than in Platen-SH tube and RH tube (in furnace).

Table I -33 Steam oxide scale thickness measurement results

		Scale thickness	ss (μm)
Sample tube	Position	Average among 90°range	Max. among 90° range
	Front Side	89.2	109.8
Platen-SH	Right Side	85.3	102.4
riatett-Sri	Rear Side	74.7	96.8
	Left Side	82.8	125.0
	Front Side	439.6	475.7
RH	Right Side	447.9	479.0
(in penthouse)	Rear Side	381.4	453.0
	Left Side	458.0	476.0
	Front Side	32.9	41.9
RH	Right Side	68.9	96.8
(in furnace)	Rear Side	65.4	90.3
	Left Side	34.5	41.3





- c. EPMA analysis of steam oxide scale on internal surface (Fig. I -13~24, Table I -34)
 - Mainly iron oxide scale was formed since Fe and O were remarkably detected.
 - ➤ In Platen-SH tube, Fe, Cr and Mo were detected as tube material elements and O, P, Ca, Zn as the other detected elements.
 - In RH tube (in penthouse), Fe, Cr and Mo were detected as tube material elements, and O as the other detected element.
 - In RH tube (in furnace), Fe, Cr and Mo were detected as tube material elements, and O, P, Na, Mn as the other detected element.

Element Sample tube Position Si Ca Mn Fe Ti Cr Ni Zn Mo Front Side Right Side Platen-SH Rear Side Left Side Front Side RH Right Side (in penthouse) Rear Side Left Side Front Side RH Right Side Rear Side (in furnace) Left Side

Table I -34 Elements detected by EPMA analysis


: Elements detected clearly


- (4) Hardness measurement (Fig. 1 -25~24, Table I -35)
 - The hardness of RH tube (in penthouse, SA213T22) was lower than the normal value of virgin material by Japanese steel manufacturer.
 - ➤ The hardness of Platen-SH tube (SA213T11) and RH tube (in furnace, SA213T11) were higher than the normal value of virgin material by Japanese steel manufacturer.

Table I -35 Hardness measurement results

								(unit:HR-B)	
Sample tube	Marterial	-1-	2	3	4	5	6	7	8
Platen-SH	SA 213 T 11	88	88	86	86	87	87	88	87
RH (in penthouse)	SA 213 T 22	70	70	71	72	71	70	70	71
RH (in furnace)	SA 213 T 11	81	82	83	82	82	82	83	82

Hardness value of vigin material by fabricator : SA 213 T 22;76.4~81.6(HR-B) SA 213 T 11:73.4~78.4(HR-B)








Fig 1 -25 Hardness measurement results

(5) Metallographic observation

Microstructure observation results at cross section of sample tube were shown in Photo I -20 \sim 25.

(Platen-SH tube (SA 213 T11))

➤ Microstructural degradation with disintegration of pearlite structure and precipitation in ferrite grain was not observed.

(RH tube in penthouse and furnace (SA 213 T11))

> Microstructural degradation with disintegration of pearlite structure was observed.

(6) Creep rupture test

a. Test condition

Ġ.


The creep test condition is shown in Table I -36. The shape of test specimens is shown in Fig. I -26

3 specimens were cut out from each of base metal portion and weld portion in Platen-SH tube and RH tube(in furnace) with a set of three test conditions for each portion.

As the shape of test specimens, ϕ 6mm round bar specimen was applied for Platen-SH tube and arc shaped specimen with the weld reinforcement left for RH thin-walled tube (in furnace).

Test condition Shape Sample tube Portion Material of Tem. Stress (°C) (MPa) specimen 665 49.0 Base Metal SA213T11 63.7 665 700 38.3 φ6mm Platen-SH 665 49.0 round bar Weld Metal SA213T11 665 63.7 700 38.3 665 44.1 Base Metal SA213T11 58.8 665 700 27.9 Arc RH(in furnace) 665 44.1 shaped Weld Metal SA213T11 665 58.8 700 27.9

Table I -36 Creep test condition







Fig I -26 Shape of creep rupture test specimens

Test specimens before and after creep rupture test in Platen-SH tube

Before machining ⇒






After machining 1


After creep rupture test 1

Test specimens before and after creep rupture test in RH tube (in furnace)

Before machining ⇒







Creep rupture testing machine \Rightarrow

b. Test results

Test result is shown in Table I -37-1. All specimens had ruptured for each test condition.

Table I -37-1 Creep rupture test results (Platen-SH)

			Test co	ondition	Rupture	LMP*	Fracture	Reduction
Compo	onent	Material	Temp. T(°C)	Stress (MPa)	time t (h)	C=19.95	elongation (%)	of area (%)
			665	49.0	187.7	20,852	102	97
	Base Metal	SA 213 T11	665	63.7	48.7	20,302	87	94
Platen-SH			700	38.3	76.1	21,248	88	94
r lateir-Si i			665	49.0	149.0	20,758	36	92
	Weld Meta	SA 213 T11	665	63.7	39.0	20,212	44	92
			700	38.3	43.5	21,012	35	95

* LMP=(273.15+T) (C+log t)

Table I -37-2 Creep rupture test results (RH in furnace)


	Component		Test co	ondition	Rupture	LMP*	Fracture	Reduction
Compo			Temp, T(℃)	Stress (MPa)	time t (h)	C=17.52	elongation (%)	of area ** (%)
				44.1	457.0	18,933	53	57
	Base Metal	SA 213 T11	665	58.8	139.2	18,448	62	63
RH(in furnace)			700	27.9	319.4	19,488	39	55
Kri(iii iuinace)		Weld Metal SA 213 T11	665	44.1	310.9	18,776	20	52
	Weld Metal		665	58.8	69.3	18,164	13	53
			700	27.9	296.8	19,457	16	56

* LMP=(273.15+T) (C+log t)

^{**} Reduction of area for RH tube is regarded as reference, because the value was evaluated by reduction of width of arc shaped specimen.

The comparison of the test results with the creep rupture data of virgin materials by NIMS (National Institute for Materials Science) is shown in Fig. 1 -27.

The test results for base metal and weld joint in Platen-SH tube indicate the lower creep rupture strength than NIMS data, and those in RH tube (in furnace) indicate almost same creep rupture strength as NIMS data.






Fig I -27 The comparison of the test results with the creep rupture data of virgin materials by NIMS (National Institute for Materials science)

c. Residual life evaluation results

Residual life evaluation results of creep rupture test by parameter -method are shown in Table I -38.

The stress condition for the evaluation was calculated as the hoop stress with the measured OD, thickness of the test sample tube and the designed pressure. As for the temperature condition for the evaluation, two conditions were used for evaluation, those are the case of evaluation at the designed temperature and the other one at equivalent temperature estimated by comparison with the average creep rupture data of NIMS.

(Platen-SH tube)

The evaluated residual life (half of residual life evaluated by creep rupture test) of Platen-SH tube was 750,000 hours for base metal, 380,000 hours for weld joint portion at designed temperature 540°C of Platen-SH outlet header.

In case of evaluation at equivalent temperature 553°C, the evaluated residual life of Platen-SH tube was 290,000 hours for base metal, 150,000 hours for weld joint portion.

(RH tube in furnace)

The evaluated residual life (half of residual life evaluated by creep rupture test) of RH tube in furnace was 1,300,000 hours for base metal, 1,200,000 hours for weld joint portion at designed temperature 540°C of RH outlet header.

In case of evaluation at equivalent temperature 551°C, the evaluated residual life of RH tube in furnace was 670,000 hours for base metal, 610,000 hours for weld joint portion.

Each portion has enough evaluated residual life at present, with the min. evaluated residual life of 150,000 hours for weld joint portion of Platen-SH tube.

Table I -38 Residual life evaluation results of creep rupture test by parameter -method

	Parameter method (evaluated at designed temp.)							
Component		Material	Operation hours	Hoop Stress	Designed temp.	Residual life	Creep life consumption	Evaluated residual life
			(h)	(MPa)	(℃)	(h)	ratio	(h)
Platen-SH	Base Metal	SA 213 T11	172,000	38.3	540(※1)	1,505,000	0.10	750,000
1 taten-311	Weld Metal	SA 213 T11	172,000	38.3	540(※1)	770,000	0.18	380,000
RH(in furnace)	Base Metal	SA 213 T11	172,000	27.9	540(※2)	2,783,000	0.06	1,300,000
Kri(m minace)	Weld Metal	SA 213 T11	172,000	27.9	540(※2)	2,549,000	0.06	1,200,000

	Parameter method (evaluated at equivalent temp.)							
Component		ent Material		Hoop Stress	Equivalent temperature	Residual life	Creep life consumption	Evaluated residual life
			(h) (MPa)	(℃)	(h)	ratio	(h)	
Platen-SH	Base Metal	SA 213 T11	172,000	38.3	553	598,000	0.22	290,000
riatell-SH	Weld Metal	SA 213 T11	172,000	38.3	553(※3)	309,000	0.36	150,000
RH(in furnace)	Base Metal	SA 213 T11	172,000	27.9	551	1,347,000	0.11	670,000
	Weld Metal	SA 213 T11	172,000	27.9	551(※3)	1,235,000	0.12	610,000

X 1; Designed temp. at Platen-SH Outlet Header

^{※2;} Designed temp. at RH Outlet Header

^{3;} Equivalent temperature evaluated at base metal

(7) Residual life assessment by microstructural comparison method

a. Platen-SH tube

(Microstructure observation)

The results of microstructure observation are shown in Photo I $-26 \sim 30$.

The summary of observation results is shown in Table I -39.

> Precipitates at gain boundary were observed in base metal, intercritical zone, fine grain HAZ and weld metal.

(Grain boundary precipitates observation)

The results of grain boundary precipitates by SEM observation are shown in Photo I $-31 \sim 32$.

> Precipitates at gain boundary were observed in base metal and fine grain HAZ.

(Precipitates distribution observation of extracted replica)

The results of precipitates distribution observation by TEM observation are shown in Photo I $-33\sim36$.

The summary of observation results is shown in Table I -40.

- ➤ Fine needlelike precipitates had disappeared in base metal, fine grain HAZ, coarse grain HAZ and weld metal.
- > Rod-shaped precipitates and attenuated plate-shaped precipitates were observed in fine grain HAZ.

b. RH tube (in penthouse)

(Microstructure observation)

The results of microstructure observation are shown in Photo I $-37 \sim 41$.

The summary of observation results is shown in Table I -39.

- > Precipitates free zone along grain boundary was observed in base metal, intercritical zone and fine grain HAZ.
- > Granular precipitates in grain were observed in each region...

(Grain boundary precipitates observation)

The results of grain boundary precipitates by SEM observation are shown in Photo I $-42 \sim 43$.

➤ Precipitates at gain boundary were observed in base metal and fine grain HAZ.

(Precipitates distribution observation of extracted replica)

The results of precipitates distribution observation by TEM observation are shown in Photo I $-44\sim47$.

The summary of observation results is shown in Table I -40.

- ➤ Precipitates free zone along grain boundary, rod-shaped precipitates and disintegration of pearlite structure were observed in base metal.
- > Fine needlelike precipitates had disappeared in fine grain HAZ, coarse grain HAZ and weld metal.

c. RH tube (in furnace)

(Microstructure observation)

The results of microstructure observation are shown in Photo I -48~52.

The summary of observation results is shown in Table I -39.

- > Precipitates at gain boundary were observed in base metal and fine grain HAZ.
- > Granular precipitates in grain were observed in each region.
- > Granular precipitates in grain were observed in each region.

(Grain boundary precipitates observation)

The results of grain boundary precipitates by SEM observation are shown in Photo I -53~54.

> Precipitates at gain boundary were observed in base metal and fine grain HAZ.

(Precipitates distribution observation of extracted replica)


The results of precipitates distribution observation by TEM observation are shown in Photo I -55~58.

The summary of observation results is shown in Table I -40.

- > Precipitates free zone along grain boundary was observed in base metal.
- Disintegration of pearlite like structure was observed in fine grain HAZ.
- > Attenuated plate-shaped precipitates were observed in coarse grain HAZ.
- d. Quantitative evaluation of grain boundary precipitates

The results of quantitative evaluation of grain boundary precipitates are shown in Table 1-41.

- The max. value of average diameter of grain boundary precipitates was 0.62 μ m in base metal at RH tube(in penthouse), 0.42 μ m in fine grain HAZ at RH tube(in penthouse).
- ➤ The max. value of volume fraction of grain boundary precipitates was 0.028 in base metal at RH tube(in penthouse), 0.027 in fine grain HAZ at RH tube(in penthouse).



Quantitative evaluation of grain boundary precipitates [extracted Table I -41]

e. Quantitative evaluation of precipitates free band width along grain boundary

The results of quantitative evaluation of precipitates free band width along grain boundary are shown in Table I -42.

- ➤ The quantitative evaluation was focused on base metal of SA 213 T22 for RH tube (in penthouse).
- \triangleright The precipitates free band width along grain boundary was 1.15 μ m.

f. Operational condition of residual life evaluation portion

Operational condition of evaluated components are shown in Table I -43.

The evaluation stress σ was the hoop stress calculated with designed pressure, designed diameter D and thickness t of each component.

$$\sigma = P(D-t)/2t$$

where P: Designed pressure.

Table I -43 Operational condition of evaluated components

		Operational condition						
Commonant	Matarial	OD ^{%1}	t ^{*1}	Designe	Ноор			
Component	Material	OD	l t	Temperature ^{**2} Pressure		Stress		
		mm	mm	$^{\circ}$	MPa	MPa		
Platen-SH	SA213T11	48.5	9.0	540	17.5	38.3		
RH(in penthouse)	SA213T22	53.0	5.4	540	5.3	23.2		
RH(in furnace)	SA213T11	53.9	5.1	540	5.3	25.2		

※1: Measured value

※2 : Designed temperature at Outlet Header

g. Residual life evaluation results by microstructure comparison method

Evaluation figures of residual life assessment for each components by microstructural comparison method are shown in Fig. I -28 \sim 30 and evaluation results are shown in Table I -44.

The highest creep life consumption ratio was evaluated at RH tube (in furnace) with 51% and evaluated residual creep life (half of residual life evaluated microstructure comparison method) was 82,000 hours.

Table I -44 Residual life evaluation results

						Residual life evaluation results			
Component	Material	Region	coi	reep l nsump atio(%	tion	Residual life(Hr)	Evaluated residual life (Hr)		
		Base Metal	1	~	2	8,428,000 ~ 17,028,00	0		
Platen-SH	SA213T11	Fine grain HAZ	3	~	6	2,695,000 ~ 5,561,00	0 1,300,000		
		Coarse grain HAZ	0	~	1	17,028,000 <			
		Base Metal	11	~	14	1,057,000 ~ 1,392,00	0		
RH(in penthouse)	SA213T22	Fine grain HAZ	9 1,739,000				520,000		
		Coarse grain HAZ	4	~	6	2,695,000 ~ 4,128,00	0		
RH(in furnace)	SA213T11	Base Metal	1	~	2	8,428,000 ~ 17,028,00	0		
		Fine grain HAZ	3	~	4	4,128,000 ~ 5,561,00	82,000		
		Coarse grain HAZ	6	~	51	165,000 ~ 2,695,00	0		

Table I -39 Microstructure observation resuluts


S						OM (Optical i	nicroscope obser	vation)					
nen		io			Microstructural features								
Components	,000	Observed area		Precipitation at gain boundary	Precipitates free zone along grain boundary	Precipitation Granular precipitates	in ferite grain Rod-shaped precipitates	Pearlite structure	Subgrain boundary	Ferrite grain			
			Base metal	Appeared	Not appeared	Appeared	Not appeared	Normal					
tube	Ê	ential	Intercritical zone	Appeared		Appeared	Not appeared	Normal	Normal				
Platen SH tube	#12-3	Circumferential weld	Fine grain HAZ	Appeared		Appeared	Not appeared						
Plat	(SA	Circ	Coarse grain HAZ	Not appeared		Not appeared							
			Weld metal	Appeared		Appeared				Appeared			
	T22)		Base metal	Appeared	Appeared	Appeared	Not appeared	Disintegrated					
	eftside \ 213 '	ential	Intercritical zone	Appeared		Appeared	Appeared						
	#3-1 from leftside in penthouse (SA 213 T22)	Circumferential weld	Fine grain HAZ	Appeared		Appeared	Appeared						
ده	#3-1 a	Circ	Coarse grain HAZ	Not appeared		Appeared							
Reheater tube	d mi		Weld metal	Not appeared		Appeared							
Reheat	e '11)		Base metal	Appeared	Not appeared	Appeared	Not appeared	Normal					
_	om rearside (SA 213 T11)	ential	Intercritical zone	Not appeared		Appeared	Not appeared	Normal	Normal				
		Circumferential weld	Fine grain HAZ	Appeared		Appeared	Not appeared						
	#14-5 from rearside in furnace (SA 213 T1	Circ	Coarse grain HAZ	Not appeared		Appeared							
	in f		Weld metal	Not appeared		Appeared				Appeared			
	Via	v noc	for each area	×500 (2 views)									
	V IC	w HOS.	tor edeti dred	×1000 (4 views)									

Table I -40 Precipitates distribution observation results

				TEM (Transmission	n Electron M	icroscope ob	servation)	
Components		E 0				Precipitates f	eatures		
nodi		Location	Observed area	Precipitates free	ļ	itation in ferit	grain		Aggromerate
Com		ន		zone along grain boundary	Fine needlelike and granular	Rod-shaped precipitates	Atenuated plate-shaped precipitates	Pearlite structure	d precipitates structure
		_	Base metal	Not appeared	Disappeared	Not appeared	Not appeared	Disintegrated	
Platen SH tube	#12-3 (SA 213 T11)	Circumferential weld	Fine grain HAZ		Disappeared	Appeared	Appeared	Normal	
Platen	#1 (SA 2	Circum	Coarse grain HAZ		Disappeared	Not appeared	Not appeared		Normal
			Weld metal		Disappeared				
	de 3 T22)	_	Base metal	Appeared	Remaining	Appeared	Not appeared	Remarkably disintegrated	
	m leftsi (SA 21	Circumferential weld	Fine grain HAZ		Disappeared		Not appeared		
	#3-1 from leftside in penthouse (SA 213 T22)	Circum	Coarse grain HAZ		Disappeared		Disappeared		
Reheater tube	in pel		Weld metal		Disappeared				
Rehea	ide ; T11)	ı	Base metal	Appeared	Remaining	Not appeared	Not appeared	Normal	
	#14-5 from rearside urnace (SA 213 T11)	Circumferential weld	Fine grain HAZ		Remaining	Not appeared	Not appeared	Disintegrated	
	#14-5 fro in furnace	Circum w	Coarse grain HAZ		Remaining	Not appeared	Appeared		Disintegrated
	# in fu		Weld metal		Remaining				
	View	nos. fo	or each area	×2000 (2 views)					
				×1000 (4 views)					

Table I -41 Quantitative evaluation of grain boundary precipitates

		Average dian	neter (µm)	Volume fraction		
Component	Material	Base Metal	Fine grain HAZ	Base Metal	Fine grain HAZ	
Platen-SH	SA213T11	0.38	0.31	0.008	0.009	
RH(in penthouse)	SA213T22	0.62	0.42	0.028	0.027	
RH(in furnace)	SA213T11	0.42	0.41	0.014	0.020	








Table I-42 Precipitates free band width along grain boundary

Sample tube	Material	Precipitates free band width (μm) **1
Sample tube	Material	Base Metal
RH(in penthouse)	SA213T22	1.15

※1 : Average value of 10 measured points








1-18

Fig I -28 Evaluation Results

Platen SH





1-182