

Water Supply Secondary Network Length (Km) by Sub-sector and Material Type

SubSector	Type of Material				Total (Km)
	AC	ACER	FOFO	PVC	
83 A-1	9,29			1,87	11,16
83 A-2	18,75			2,60	21,35
83 B-1	10,06			0,19	10,25
83 B-2	29,84			5,78	35,62
84 A-1	15,70			18,39	34,09
84 A-2	20,42			4,05	24,47
84 B-1	26,10			3,76	29,86
84 B-2	3,79			9,60	13,39
85 A	11,25			6,13	17,38
85 B-1	4,78		0,03	4,46	9,27
85 B-2	8,34			0,26	8,6
85 B-3	5,51			0,41	5,92
85 C	13,10			2,52	15,62
212 A-1	3,62			26,69	30,31
212 A-2	6,76			13,31	20,07
212 B-1	0,92			13,55	14,47
212 B-2	0,54			12,10	12,64
213-1	12,65			22,69	35,34
213-2				0,62	0,62
213-3	0,03			1,05	1,08
253				0,21	0,21
256				4,32	4,32
259	12,40	0,22		1,43	14,05
345	0,06			13,31	13,37
346-1	4,67			4,68	9,35
346-2	9,25			6,38	15,63
347-1	3,92			14,44	18,36
347-2	11,61			19,84	31,45
348 A	7,64			7,64	15,28
348 B-1	17,37			3,22	20,59
348 B-2	0,24		0,13	0,01	0,38
349 A-1	12,90	0,70		3,51	17,11
349 A-2	1,61			2,11	3,72
349 A-3	0,84	0,06		7,63	8,53
349 B-1	0,71			8,71	9,42
349 B-2	3,03			6,12	9,15
349 B-3	5,63			2,19	7,82
350-1	34,81				34,81
350-2	22,65			14,43	37,08
351-1	0,93			2,06	2,99
351-2				2,63	2,63
351-3			0,19	0,46	0,65
361				26,9	26,9
368 A-1	0,02			21,96	21,98
368 A-2	0,01			5,59	5,6
368 B	0,06			33,85	33,91
369 A	0,23			25,11	25,34
369 B	0,48			27,95	28,43
370	8,90			1,62	10,52
Total	361,42	0,98	0,35	410,70	773,45
Percentage	46,73%	0,13%	0,05%	53,10%	100,00%

LEGEND

- PIPES MATERIAL-SECONDARY NETWORK WATER SUPPLY
 - AC (Asbest Cement)
 - ACER (Steel)
 - FOFO (Ductile Iron)
 - PVC (Polychloride of Vinyl)
- STUDY AREA
- DISTRICT BOUNDARY
- SECTOR BOUNDARY
- ROADS
- GREEN AERA
- BLOCKS
- RIVERS
- COAST


0 0,5 1 2 km

1:50.000
Projection: UTM
Datum: WGS-84
Zone: 18 sur

sedapal **REPUBLICA DEL PERU** **jica**
SERVICIO DE AGUA POTABLE Y ALCANTARILLADO DE LIMA


GRAFICO 2.5.8-14: RED SECUNDARIA DE AGUA POTABLE POR TIPO DE MATERIAL

FIGURE 2.5.8-14: DISTRIBUTION OF SECONDARY PIPES BY MATERIAL



Length of Secondary Network of Water Supply by Age and Sub-sector

Sub-Sector	No data	< 5 years	{ 5 - 10>	{ 10 - 15>	{ 15 Y 20 >	{ 20 - 25>	{ 25 - 30 >	{ 30 - 35 >	> 35 years	Total (Km)
83 A-1				5,27	0,07	0,44		5,38		11,16
83 A-2			1,11	5,08	1,42	7,38		6,36		21,35
83 B-1					0,13	6,50	0,03		3,62	10,28
83 B-2			0,05	12,36	0,01	10,42		8,25	4,53	35,62
84 A-1		0,20	1,44	28,07	4,34	0,04				34,09
84 A-2				24,40	0,07					24,47
84 B-1		0,30	1,69	22,13	4,43			1,31		29,86
84 B-2			3,01	8,29	1,20			0,89		13,39
85 A		0,28	5,26	3,23	4,41	4,20				17,38
85 B-1		0,30	0,88	3,33	0,40					9,24
85 B-2	1,00	0,23				4,33				8,60
85 B-3	0,28		0,61		0,41	0,52				5,92
85 C	0,17		0,17	3,10	3,59	1,70	6,89	4,10		15,62
212 A-1		0,78	15,86	13,67						30,31
212 A-2			13,13	6,94						20,07
212 B-1			0,25	14,05	0,17					14,47
212 B-2			1,83	10,81						12,64
213-1		3,11	21,66	9,70	0,87					35,34
213-2			0,62							0,62
213-3			1,08							1,08
253		0,21								0,21
256				4,32						4,32
259					13,83					14,05
345		7,14	6,23				0,22			13,37
346-1					9,26	0,09				9,35
346-2			0,41	7,46	5,01	2,75				15,63
347-1			0,42	8,07		9,87				18,36
347-2	0,83	0,16	13,47	16,38	0,61					31,45
348 A						7,64				7,64
348 B-1		0,07	0,04	1,12	4,14	14,15		1,07		20,59
348 B-2			0,02			0,23	0,13			0,38
349 A-1		0,10	0,28	1,03	5,41	9,59	0,70			17,11
349 A-2			0,18		3,54					3,72
349 A-3					8,47		0,06			8,53
349 B-1			2,14		7,28					9,42
349 B-2			2,55		6,60					9,15
349 B-3	0,74		0,22		6,86					7,82
350-1	0,23			0,15		4,22		1,28	28,93	34,81
350-2		3,01	8,78	2,49	1,42	1,96	1,09	18,33		37,08
351-1	0,17	1,73	0,24		0,20					2,99
351-2		0,62	2,01							2,63
351-3		0,46					0,19			0,65
361	0,04	24,29	2,57							26,90
368 A-1		12,41	9,57							21,98
368 A-2		2,17	3,43							5,60
368 B		31,56	2,35							33,91
369 A		20,69	4,65							25,34
369 B		26,43	1,96		0,04					28,43
370		0,78	0,02	1,54	0,07			8,11		10,52
Total	3,46	137,03	130,19	212,99	94,26	94,05	9,31	54,01	38,15	773,45
Percentage	0,45%	17,72%	16,83%	27,54%	12,19%	12,16%	1,20%	6,98%	4,93%	100,00%




LEGEND

- WATER SUPPLY NETWORK**
 - No data
 - Less than 10 years old
 - 10 Y 15 years old
 - 15 Y 20 years old
 - 20 Y 25 years old
 - 25 Y 30 years old
 - 30 Y 35 years old
 - Over 35 years old
- STUDY AREA**
- DISTRICT BOUNDARY**
- SECTOR BOUNDARY**
- ROADS**
- GREEN AREA**
- BLOCKS**
- RIVERS**
- COAST**

sedapal **REPUBLICA DEL PERU** **jica**
 SERVICIO DE AGUA POTABLE Y ALCANTARILLADO DE LIMA

GRAFICO 2.5.8-15: REDES SECUNDARIAS DE AGUA POTABLE SEGUN ANTIGUEDAD DE TUBERIAS
FIGURE 2.5.8-15: DISTRIBUTION OF SECONDARY PIPES BY AGE



Length (Km) of AC (Asbest Cement) Secondary Network of Water Supply by Age and Sub-sector

Sub-Sector	No data	< 5 years	{ 5 - 10 }	{ 10 - 15 }	{ 15 Y 20 >	{ 20 - 25 }	{ 25 - 30 >	{ 30 - 35 >	> a 35 years	Total (Km)
83 A-1				3,44	0,03	0,44		5,38		9,29
83 A-2				4,63	1,08	6,68		6,36		18,75
83 B-1						6,44			3,62	10,06
83 B-2				6,80		10,26		8,25	4,53	29,84
84 A-1			0,33	11,03	4,33	0,01				15,70
84 A-2				20,35	0,07					20,42
84 B-1		0,15	1,13	19,08	4,43			1,31		26,10
84 B-2				1,71	1,19			0,89		3,79
85 A			0,86	1,96	4,23		4,20			11,25
85 B-1		0,00	0,05	0,05	0,40		4,28			4,78
85 B-2	1,00					7,34				8,34
85 B-3	0,28		0,61			0,52		4,10		5,51
85 C	0,17			1,29	3,26	1,49	6,89			13,10
212 A-1			0,98	2,64						3,62
212 A-2			0,93	5,83						6,76
212 B-1			0,02	0,78	0,12					0,92
212 B-2				0,54						0,54
213-1		0,41	2,00	9,37	0,87					12,65
213-2										0,00
213-3			0,03							0,03
253										0,00
256										0,00
259					12,40					12,40
345			0,06		0,00					0,06
346-1					4,58	0,09				4,67
346-2			0,41	5,66	0,81	2,37				9,25
347-1			0,20	0,10		3,62				3,92
347-2	0,83		1,07	9,12	0,59					11,61
348 A						7,64				7,64
348 B-1					2,38	13,92		0,00	1,07	17,37
348 B-2			0,01		0,00	0,23				0,24
349 A-1					3,31	9,59				12,90
349 A-2			0,18		1,43					1,61
349 A-3					0,84					0,84
349 B-1					0,71					0,71
349 B-2					3,03					3,03
349 B-3	0,62				5,01					5,63
350-1	0,23			0,15		4,22		1,28	28,93	34,81
350-2		0,03	0,08	1,12	0,04	1,96	1,09	18,33		22,65
351-1	0,17		0,07		0,04	0,65				0,93
351-2										0,00
351-3										0,00
361										0,00
368 A-1			0,02							0,02
368 A-2		0,00	0,01							0,01
368 B			0,06							0,06
369 A		0,23								0,23
369 B		0,07	0,41							0,48
370		0,70	0,00	0,09				8,11		8,90
Total	3,30	1,59	9,52	105,74	55,18	85,95	7,98	54,01	38,15	361,42
Percentage	0,91%	0,44%	2,63%	29,26%	15,27%	23,78%	2,21%	14,94%	10,56%	100,00%

LEGEND

AC PIPELINE (Asbest Cement)

Age

- No data
- Less than 5 years old
- 5 and 10 years old
- 10 and 15 years old
- 15 and 20 years old
- 20 and 25 years old
- 25 and 30 years old
- 30 and 35 years old
- Over 35 years old

STUDY AREA
 DISTRICT BOUNDARY
 SECTOR BOUNDARY
 ROADS
 GREEN AREA
 BLOCKS
 RIVERS
 COAST


0 0,5 1 2 km

1:50.000
Proyección: UTM
Datum: WGS-84
Zona: 18 sur

sedapal **REPUBLICA DEL PERU** **jica**
SERVICIO DE AGUA POTABLE Y ALCANTARILLADO DE LIMA


GRAFICO 2.5.8-16: DISTRIBUCION DE TUBERIAS DE AC (ASBESTO CEMENTO) POR EDADES

FIGURE 2.5.8-16: DISTRIBUTION OF AC (ASBEST CEMENT) IN THE SECONDARY NETWORKS



Length (Km) of PVC Secondary Network of Water Supply (Vinyl Polychloride) by Age and Sub-sector

Sub-Sector	Sin dato	Menor 5 años	5 y 10 años	10 y 15 años	15 y 20 años	20 y 25 años	Total (Km)
83 A-1				1,83	0,04		1,87
83 A-2			1,11	0,45	0,34	0,70	2,60
83 B-1					0,13	0,06	0,19
83 B-2			0,05	5,56	0,01	0,16	5,78
84 A-1	0,20		1,11	17,04	0,01	0,03	18,39
84 A-2				4,05			4,05
84 B-1	0,15		0,56	3,05			3,76
84 B-2			3,01	6,58	0,01		9,60
85 A	0,28		4,40	1,27	0,18		6,13
85 B-1	0,30		0,83	3,28		0,05	4,46
85 B-2	0,23					0,03	0,26
85 B-3					0,41		0,41
85 C			0,17	1,81	0,33	0,21	2,52
212 A-1	0,78		14,88	11,03			26,69
212 A-2			12,20	1,11			13,31
212 B-1	0,00		0,23	13,27	0,05		13,55
212 B-2			1,83	10,27			12,10
213-1	2,70		19,66	0,33			22,69
213-2			0,62				0,62
213-3			1,05				1,05
253	0,21						0,21
256				4,32			4,32
259					1,43		1,43
345	7,14	6,17			4,68		13,31
346-1				1,80	4,20	0,38	6,38
346-2				7,97	6,25		14,44
347-1			0,22	7,26	0,02		19,84
347-2	0,16	12,40					0,00
348 A							0,00
348 B-1	0,07	0,04	1,12	1,76	0,23		3,22
348 B-2			0,01				0,01
349 A-1	0,10	0,28	1,03	2,10			3,51
349 A-2				2,11			2,11
349 A-3				7,63			7,63
349 B-1			2,14	6,57			8,71
349 B-2			2,55	3,57			6,12
349 B-3	0,12	0,22		1,85			2,19
350-1							0,00
350-2	2,98	8,70	1,37	1,38			14,43
351-1	1,73	0,17		0,16			2,06
351-2	0,62	2,01					2,63
351-3	0,46						0,46
361	0,04	24,29	2,57				26,90
368 A-1		12,41	9,55				21,96
368 A-2	0,00	2,17	3,42				5,59
368 B		31,56	2,29				33,85
369 A	0,00	20,46	4,65				25,11
369 B		26,36	1,55		0,04		27,95
370		0,08	0,02	1,45	0,07		1,62
Total	0,16	135,44	120,67	107,25	39,08	8,10	410,70
Percentage	0,04%	32,98%	29,38%	26,11%	9,52%	1,97%	100,00%



LEGEND

- █ STUDY AREA
- █ DISTRICT BOUNDARY
- █ SECTOR BOUNDARY
- █ ROADS
- █ GREEN AREA
- █ BLOCKS
- █ RIVERS
- █ COAST

PVC PIPELINE (Vinyl Polychloride)

Age

- No data
- Less than 5 years old
- 5 and 10 years old
- 10 and 15 years old
- 15 and 20 years old
- 20 and 25 years old
- 25 and 30 years old
- 30 and 35 years old
- Over 35 years old

sedapal REPUBLICA DEL PERU
SERVICIO DE AGUA POTABLE Y ALCANTARILLADO DE LIMA **jica**


GRAFICO 2.5.8-17: DISTRIBUCION DE TUBERIAS DE PVC (POLICLORURO DE VINILO) POR EDADES

FIGURE 2.5.8-17: DISTRIBUTION OF PVC (POLYVINYL CHLORIDE) IN THE SECONDARY NETWORKS

(b) Diagnosis of AC Pipes

Diagnosis of AC pipes can be summarized as follows:

- About 50 % of AC pipes were installed more than 20 years ago, but more than 30 %, on the other hand, have been installed in the last 15 years.
- AC pipes are distributed throughout the whole Study Area except in the newly developed area in Puente Piedra.
- Asbestos cement is a kind of cement reinforced by asbestos. According to the Rehabilitation Guideline (2005, Japan Waterworks Association), the strength of asbestos cement deteriorates over time. As shown below, the tensile strength of asbestos cement deteriorates by 30% in 20 years and by 50% in 30 years. Moreover, ratio of accidents of asbestos cement tends to increase, especially 25 years after installation.



Source: 2005, Rehabilitation Guideline, Japan Waterworks Association

Figure 2.5.8-18: Increase of Accidents and Deterioration of Strength of AC Pipe

In addition to strength of the material, water tightness at the joints also deteriorates because of its inflexible structure and degradation of rubber ring.

However, the record of the incidents on secondary pipes shows different situation. The sector 259, 351, 349a and 349b are the worst four sectors in number of incidents on secondary water pipes. However, these sectors don't have more than 25 years old asbestos pipes, as shown in Table 2.5.8-26. The sector 350, 83b, 83a and 85c are major four sectors where long lengths of old asbestos pipes are installed, as shown in Table 2.5.8-20-27. However, incidents of these areas are less than the average in the Study Area. It does not show any relationship between pipe age/ AC pipes ratio and frequency of incidents.

Table 2.5.8-26 Worst Four Sectors in Ratios of Incidents on Secondary Pipes

Sector	Incidents Ratios (km/year)	Total length of pipes (km)	Asbestos Pipes (km)	Ratio of Asbestos Pipes	more than 25years pipes (km)
259	1.26	14.05	12.40	88%	0
351	1.17	6.27	0.93	15%	0
349a	0.58	29.30	15.35	52%	0
349b	0.49	26.45	9.37	36%	0


Source: JICA Study Team

Table 2.5.8-27 Four Sectors with Old Asbestos Pipes

Sector	Incidents Ratios (km/year)	Total length of pipes (km)	Asbestos Pipes (km)	Ratio of Asbestos Pipes	more than 25years pipes (km)
350	0.13	71.89	57.46	84%	49.63
83b	0.17	45.85	39.903	87%	16.40
83a	0.14	35.513	28.04	91%	11.74
85c	0.29	15.62	13.10	86%	6.89

Source: JICA Study Team

Figure 2.5.8-19 shows NRW ratio of five sectorized area in the Study Area. In NRW ratio, the Sector 213 has the highest NRW (average 57%), which is more than the average, and the Sector 84 (average 30%) has the lowest NRW, which sometime almost achieve the target of 25%. However, as shown in Table 2.5.8-28, the worst area, Sector 213 has AC pipes (34%) and PVC pipes (66%), and the best area, Sector 84 has AC pipes (65%) and PVC pipes (35%). Sector 83, where 37% of pipes are more than 25 years AC pipes, has much lower NRW ratio than Sector 213. It does not show any relationship between NRW and ratio of AC pipe ratio/ pipe age, also.



Source: JICA Study Team

Figure 2.5.8-19 Non Revenue Water Ratio in Five Sectorized Area

Table 2.5.8-28 Non Revenue Water Ration in Five Sectorized Area

Sector	Total length of pipes (km)	Asbestos Pipes (km)	Ratio of AC	More than 25 years	Non Revenue Water
83	78.38	67.94	89%	37%	44.0%
84	100.81	66.01	65%	2%	30.0%
85	56.79	42.98	74%	17%	50.1%
212	77.49	11.84	12%	0%	38.0%
213	37.04	12.68	34%	0%	57.0%

Source: JICA Study Team

Even in the above situation, it can be said that the old AC pipes have high risk of incident and leakage. At present, AC pipe does not show significant deterioration in the Study Area. Considering its characteristics of material, however, frequency of incidence and water leakage caused by AC pipe can increase year by year, which will raise maintenance cost and water production cost of SEDAPAL.

Photograph No.1: AC Pipe
Broken asbestos-concrete pipes.



(c) Diagnosis of PVC

Diagnosis of PVC pipes can be summarized as follows:

- Most of the PVC pipes have been installed in the last 15 years.
- PVC pipes are distributed throughout the whole Study Area, especially in the newly developed area in Puente Piedra.
- There are two (2) types of PVC pipelines installed in the Study Area: ITINTEC pipe (product which complies with old Peruvian standard, ITINTEC, hereinafter “ITINTEC”) and ISO pipe (products which complies with standards of ISO: NTP-ISO-4422, hereinafter “ISO”).
- “ITINTEC” pipes have turned out to have quality problems, especially with the joint glue, the spigot, the welded accessories, and the inflexible structure of pipe joints, which is causing many accidents and water loss. Therefore, current SEDAPAL regulations state that pipeline to be installed must be manufactured in compliance with Regulation NTP-ISO-4422. In addition, SEDAPAL states that pipeline joints must be flexible.
- “ITINTEC” pipes were often used in construction works executed by third parties, and they are mostly distributed in the high areas of Collique, namely, original sectors 348 and 349.

Photograph No.2: PVC Pipe of "TTINTEC"

Glued PVC pipeline with a rigid structure. Mostly found in the Collique sector.



- "ISO" pipes are manufactured in compliance with Regulation NTP-ISO 4422. These pipelines have not shown any assembling problems or serious accidents in the area constructed or supervised by SEDAPAL.
- "ISO" pipes have been mostly installed in the last 10 years and are located in sectors 361, 368A, 368B, 369A and 369B; they are partially installed in sectors 212A, 212B, 213 and 350.

(d) Diagnosis of Iron (ACERO) and Galvanized Iron (FOFO) Pipe

Diagnosis of iron pipe and galvanized iron pipe can be summarized as follows:

- Low quality iron pipe and galvanized iron pipe are located in the secondary pipelines in sectors 85B, 259 (Márquez), 348B, 349A and 351.
- Low quality pipes with these kinds of material had better to be replaced because they are subject to oxidization.

3) Unsuitable Pipe Installations

In some areas, unsuitable pipe installations have been carried out by the third parties (municipalities, housing associations, NGOs and local population). In such constructions, due to the unsuitable installation, there are the following problems:

- There are some pipes which do not satisfy technical requirements such as supporting bed, filling, compacting, and minimum earth cover. Such pipes, especially the pipes without enough earth cover (earth cover is less than 1.0 m), have been damaged by load of the vehicles, causing water leakage or other incidents.



Photograph-3:
Reduction with lead from asbestos cement to PVC in Comas. No suitable accessory.

Photograph-4:
Unproper perforation in AC pipe for corporation valve. Not suitable accessories neither tools.



- There are pipelines installed in private property. Although such pipes were originally located in backyards, existing houses were later expanded on the pipes without relocation of the pipes. This situation disturbs proper maintenance works and also can promote illegal water consumption.



Photograph-5 and 6:

Secondary network pipeline inside a property - - Av. Los Alisos Urb. Previ, Los Olivos district.



- Distribution networks originally executed by municipalities, NGOs, associations, etc., and later incorporated to SEDAPAL show that they had not been maintained in proper way because of lack of skill and manpower.

4) Sediment in Pipe caused by Groundwater

In some specific areas, mainly in Collique, pipes are partially or totally clogged to an irreparable level and it is disturbing the water flow significantly. The sediment, which caused the clogging, comes from groundwater. Although groundwater is no longer used in the area, existing clogged pipes should be replaced. Because the clog is found mainly in Collique, most of the clogged pipes are "ITINTEC".

As mentioned above, present secondary networks have problems on type of material, improper installation and sedimentation. In Table 2.5.8-29 is shown the length of pipes which have the mentioned problems.



Photograph-7:

A sample of a PVC pipeline that is totally OBSTRUCTED by incrustations that show high salt and groundwater contents, in the 4th and 5th sectors of Collique



Table 2.5.8-29: Length (Km) of Pipes with Problems

Sub-sector	Problem of Material		Problem of Installation ^{*2}	Total
	Steel/FoFo	ITINTEC ^{*1}	Installed in Private Property	
83B-1		0.13		0.13
83B-2		0.13	3.85	3.98
85B-1	0.03			0.03
259	0.22			0.22
348B-2	0.13			0.13
349A-1	0.70			0.70
349A-2		2.10		2.10
349A-3	0.06	6.23		6.29
349B-1		5.63		5.63
349B-2		2.91		2.91
349B-3		0.45		0.45
351-3	0.19			0.19
Total	1.33	17.58	3.85	22.76

*: Pipes clogged by sediment, which were observed in Collique as well as ITINTEC, are included.

Source: JICA Study Team

5) Pipe Conditions Survey

The JST carried out a survey of existing water supply pipes. The summary of the survey is given below, and more detailed information regarding the survey is given in Appendix A5.2.

(a) Purpose of the Survey

The Consultant carried out an investigation of the actual condition of existing pipes by visual inspection. It was carried out in order to grasp the actual status of degradation of the existing pipes, to justify the historical data of SEDAPAL of incidents such as pipe breakage and water leakage, and to identify degradation trends by condition such as material, age, or area, which was expected to provide useful information for the rehabilitation plan.

(b) Location of samples

In the survey, 30 samples for visual inspection were distributed in the Study Area so that the samples would vary in pipe material, age, entity who supervised the installation work, and frequency of incidence. The Table 2.5.8-30 shows number of the samples by material, age and entity of supervision of the installation works, which are the main conditions for their distribution.

Table 2.5.8-30: Number of Samples by Pipe Material and Age

Pipe Material		Conditions			Entity of Supervision		Number of Samples
		Age (A)			SEDAPAL	Third Party	
AC	PVC	A≤10	10<A≤25	30<A			
√			√		√		5
√			√			√	7
√				√	√		4
√				√		√	4
	√	√			√		2
	√	√				√	2
	√		√		√		3
	√		√			√	3
TOTAL NUMBER							30

Source: JICA Study Team

(c) Methodology of Survey

Visual inspections of the existing pipes were implemented by excavating test pits. Excavation was carried out so that the pipe joints could be observed. Data of the inspected pipes and result of the inspection were compiled in an inspection sheet prepared for each sample. The inspection result indicates observed backfill material, condition of installation, actual condition of the pipe material, observed problems of the pipeline, and total evaluation of the inspected pipe.

(d) Survey Results

Results of the visual inspection and evaluation of the pipes based on the inspection and cadastre data of SEDAPAL are explained below;

- At only one out of the thirty locations, soil around the pipe joint was humid, which implies water leakage at the point.
- Backfilling material was basically the original soil at the site except for the sites in Márquez and Collique, in which transported sand with small stones were used. Original soil would not be used in Márquez because the site is located close to the sea, and in Collique because the original soil was rocky; both of these are conditions not suitable for backfilling.
- Earth covers of the pipes were not deep and backfills were carried out with ordinary compaction.
- Beds of the pipes were also basically prepared by the original soils.
- PVC pipes were in good condition.
- Pipe material itself of AC pipe were observed to be good condition but there was one sample of AC pipe, out of 20, with water leakage at the pipe joint. It suggests that water leakages on AC pipe are mainly caused at pipe joints.
- Inside AC pipes, brown-colored fouling was observed, whose constituent is unknown.
- At many of the house connections, water leakages were observed.
- No serious pipe damage or construction failure was observed in the survey. However,


many failures and water leakages were identified at connections, which support SEDAPAL's maintenance record and suggests that most of water leakages are caused at connections.

6) Problems of Secondary Networks

Through the diagnoses above, problems in the secondary networks can be summarized as follows:

- There are some pipes whose materials have been proved not to be suitable for distribution, such as iron pipe, galvanized iron pipe and a type of PVC pipe ("ITINTEC").
- Some pipes are not satisfying technical requirements for minimum earth cover, supporting bed, compaction and backfilling.
- Some pipes are installed in private properties.
- Some pipes in Collique are seriously clogged by sediments derived from groundwater.
- AC pipes, which account for 47% of the total pipe length, do not yet show serious degradation in the Study Area, though 50% of them were installed more than 20 years ago. However, their strength can be deteriorated and start to cause many incidents.

In Figure 2.5.8-20 other executed and on-going studies and projects is shown.



LEGEND	
SYMBOL	DESCRIPTION
[Red outline]	LÍMITE DE ÁREA DE ESTUDIO BOUNDARY OF THE STUDY AREA
[Red dashed line]	LÍNEA IMPULSIÓN PROYECTADA (HD) PROJECTED PUMPING LINE
[Blue dashed line]	LÍNEA CONDUCCIÓN PROYECTADA (HD) PROJECTED GRAVITY PRESSURE LINE
[Blue solid line]	LÍNEA MATRIZ EXISTENTE EXISTING MAIN PIPELINE
[Green solid line]	LÍNEA CONDUCCIÓN OTROS PROYECTOS GRAVITY PRESSURE LINE OF OTHER PROJECTS
[Light green solid line]	LÍNEA CONDUCCIÓN LIMA NORTE I GRAVITY PRESSURE LINE OF LIMA NORTH I

REMARKS:	
[Pink shaded area]	Preparation of Profile Study of the Project of Enlargement and Improvement of the Water and Sewerage System, Las Antillas hill and attachment scheme
[Light blue shaded area]	Project of Sanitation Enlargement of the Socially Excluded Area of Lima Loan Agreement PE-F08
[Light green shaded area]	Let 30 District of Puente Piedra, Works of Water and Sewerage Secondary Networks, Valle Chillon Gardens - La Esmeralda - Chillon Housing Association Schemes
[Light purple shaded area]	Project of Sanitation Improvement of Socially Excluded Areas of Lima, Loan Agreement PE-F09 Lot 7
[Light blue shaded area]	Preparation of the Profile Study of the Project: "Installation of the Water and Sewerage System for Oquendo, Santa Rosa and Noroeste Schemes" (sectors 251, 252, 256 and 257). This project involves Comas and Marquises drainage areas
[Black dashed line]	Execution of General Works of Water and Sewerage that are executed by J.P.N. 0029-2003 "General Works of Water and Sewerage for Oquendo, Santa Rosa and Noroeste Schemes" (sectors 251, 252, 256 and 257) executed by "Santa Rosa" Joint Venture.
[Red shaded area]	Contract of Work 023-2007-CW-31060HED-REDAPAL. Enlargement of Water and Sewerage Networks by Condominium Systems in Several Districts of North Area Package 2
[Brown shaded area]	PAC Works - Package 4 Comas, Carabayllo, Independencia, Puente Piedra.
[Orange shaded area]	Works For Networks Outside Villa Calderon Shanty Town
[Grey shaded area]	PROMESAL Works Lot 6-8B Valle Chillon, Promavera, Aso Nuevo Independencia Comas-Carabayllo Sector Scheme
[Green shaded area]	Works in Las Magnolias Shanty Town

(12) House Connections and Micrometers

1) Number of House Connections and Status of Micrometer Installation

House connections consist of a PVC corporation, 15, 20 or 25 mm connection pipe (Domestic connections are usually 15mm.), concrete pipeline (protection), a meter box, and 1.5 or 2 mm thick FoG (galvanized iron) or plastic top. A micrometer is installed in the meter box, which is normally a jet water meter.

The connections are classified in six categories: social, domestic, commercial, industrial, state or public, and multifamily (communal). The number of connections by category is presented in Table 2.5.8-31, and number of household connections equipped with micrometer is shown in Table 2.5.8-32. Figure 2.5.8-21 presents the status of installation of micrometers in the Study Area.

The Study Area's total number of existing connections is 77,573 (41 sectors). Excluding the sectors without secondary networks and those with secondary networks recently rehabilitated/to be rehabilitated soon by SEDAPAL (connections are rehabilitated at the same time of secondary network), there are 70,291 connections. Micrometers were installed in 73.7% of the total connections as of 2009.

Table 2.5.8-31: Categories and Numbers of House Connections by District


Code	Category	Quantity of Connections			Quantity of Connections by Districts						
		With Micrometer	Without Micrometer	Total	Callao	Cara-baylo	Comas	Los Olivos	Puente Piedra	San Martín	Ventana
T-01	Social	93	235	328	8	20	93	48	137	22	
T-02	Domestic	46,228	15,526	61,754	2135	3365	16406	19780	10868	9195	5
T-03	Commercial	736	484	1,220	34	75	256	478	98	273	6
T-04	Industrial	155	56	211	24	3	67	61	30	22	4
T-05	Estate	241	11	252	6	30	110	60	31	15	
T-06	Multiple families	9,686	4,122	13,808	123	1058	3950	6313	251	2113	
TOTAL		57,139	20,434	77,573	2330	4551	20882	26740	11415	11640	15

Source: SEDAPAL Cadastre

Table 2.5.8-32: Status of Micrometer Installation in the Study Area

Sector	Sub-sector	Connection			Unit of Use
		With Meter	Without Meter	Total	
83 A	83 A-1	1,398	211	1,609	2,316
	83 A-2	1,958	529	2,487	3,968
83 B	83 B-1	1,160	113	1,273	2,236
	83 B-2	3,220	848	4,068	5,933
84 A	84 A-1	4,121	356	4,477	4,963
	84 A-2	2,784	325	3,109	3,527
84 B	84 B-1	3,420	601	4,021	4,858
	84 B-2	1,469	200	1,669	2,159
85 A	85 A	1,810	374	2,184	2,746
85 B	85 B-1	659	259	918	1,650
	85 B-2	640	254	894	1,344
	85 B-3	65	222	287	339
85 C	85 C	1,288	369	1,657	2,286
212 A	212 A-1	2,815	529	3,344	3,936
	212 A-2	1,819	265	2,084	2,571
212 B	212 B-1	1,387	225	1,612	2,179
	212 B-2	1,207	151	1,358	1,800
213	213-1	2,416	587	3,003	3,382
	213-2	62	6	68	69
	213-3	124	6	130	130
251	251	2	1	3	4
252	252	0	2	2	2
253	253	18	9	27	40
254	254	2	2	4	4
255	255	1	1	2	2
256	256	8	7	15	163
257	257	2	2	4	4
258	258	26	6	32	33
259	259	1,530	752	2,282	2,404
260	260	4	1	5	5
261	261	5	0	5	10
262	262	1	0	1	1
263	263	1	0	1	1
264	264	1	0	1	1
265	265	1	0	1	1
266	266	1	0	1	1
345	345	337	78	415	462
346	346-1	620	239	859	1,107
	346-2	1,169	577	1,746	2,152
347	347-1	1,123	927	2,050	2,633
	347-2	1,325	470	1,795	2,053
348 A	348 A	14	827	841	938
348 B	348 B-1	17	2,017	2,034	2,306
	348 B-2	140	38	178	178
349 A	349 A-1	185	1,564	1,749	1,956
	349 A-2	3	337	340	347
	349 A-3	2	892	894	964
349 B	349 B-1	95	689	784	878
	349 B-2	125	639	764	794
	349 B-3	183	564	747	758
	349 B-4	1	1	2	2
350	350-1	2,610	1,229	3,839	5,359
	350-2	2,588	860	3,448	4,285
351	351-1	554	44	598	641
	351-2	358	3	361	362
	351-3	73	3	76	76
361	361	1,274	81	1,355	1,386
368 A	368 A-1	1,590	171	1,761	1,836
	368 A-2	290	7	297	300
368 B	368 B	2,892	36	2,928	2,946
369 A	369 A	1,630	549	2,179	2,231
369 B	369 B	2,456	188	2,644	2,665
370	370	60	191	251	288
TOTAL		57,139	20,434	77,573	94,971

Source: JICA Study Team



LEGEND

MICROMETERING	STUDY AREA
WITH METER	DISTRICT BOUNDARY
WITHOUT METER	SECTOR BOUNDARY
WITHOUT COVERAGE	ROADS
	GREEN AREA
	BLOCKS
	RIVERS
	COAST

0 0,375 0,75 1,5 km

1:50,000
 Projection: UTM
 Datum: WGS-84
 Zone: 18 sur

REPUBLICA DEL PERU
 SERVICIO DE AGUA POTABLE Y ALCANTARILLADO DE LIMA

GRAFICO 2.5.8-21: CONEXIONES DE AGUA POTABLE CON MEDIDORES Y SIN MEDIDORES

FIGURE 2.5.8-21: HOUSE CONNECTIONS WITH AND WITHOUT MICROMETERS

2) Conditions of Connections and Micrometers

(a) Incidents and Water Leakage at House Connections

As explained in “(2) Service Conditions”, many incidents have occurred where the secondary distribution networks connect to house connection pipes. Large amounts of water leakage are produced at these connection points. Leakages at connections were also observed in the test pits prepared for the pipe condition survey of secondary pipes.

Many incidences on house connections are caused by oxidized galvanized iron or cast iron connection joints between distribution pipes and house connection pipes, in comparison with existing PVC and polyethylene connection joints. Replacement of all oxidized galvanized iron connection joints is considered.

Picture 8:

Broken PVC pipeline with cast iron clamp. Oxide accumulation brought about pressure on the pipeline to the point of breaking it.



(b) Incomplete Installation of Micrometer and Meter Error

The installation ratio of micrometers in the Study Area is estimated to be around 73.7% at present. Moreover, it is generally believed that a large percentage of existing micrometers don't operate well.

This situation prevents SEDAPAL from accurately measuring total water consumption, which makes it impossible to know the exact amount of the Non-Revenue Water (NRW).

On the other hand, existence of micrometers which are not working properly gives the habitants a feeling that they might be charged excessively for their actual water use. This “feeling of unfairness” can disturb acceleration of micrometers’ installation, and can sometimes lead to the intentional breaking of micrometers by habitants or to illegal water use.

These problems mentioned above, as well as the situation that the macrometer is not installed properly in the primary network, are very important problems, because water consumption and NRW of each area are fundamental data needed for a water supply business to form a development plan for a water supply system.

(c) Illegal Connection

It is estimated that there is a high amount of illegal water use in the Study Area. It is difficult to estimate the amount of illegal use because NRW cannot be monitored, and technical loss is high in the Study Area. However, it is estimated by SEDAPAL that about 5 to 15% of total distributed water is consumed illegally.

In order to eliminate illegal use, thorough inventory connection surveys shall be carried out and an exact user cadastre shall be prepared and maintained. Moreover, an educational program for the habitants in critical areas is also recommended.

3) Ongoing Project for Micrometer Installation

A SEDAPAL project called “Sistema Integral de Actividades Comerciales - SIAC” began in July 2010. It proposes an aggressive plan of micro meter implementation, upgrading the commercial cadastre and detecting illegal connections. The project is scheduled to be completed in three years.

The target area of the project is the whole area of SEDAPAL’s administration. It will rehabilitate the existing micrometers and install new micrometers at the non-metered connections which currently offer a 24-hour ongoing water supply. Detailed contents of the project are to be decided through a discussion between the SIAC and the contractor after an inventory survey of existing commercial conditions and micrometers.

4) Problems with House Connection and Micrometers

According to the diagnoses above, problems of the house connections and micrometers can be summarized as follows:

- Many incidents and much water leakage are caused at house connections, especially at the corporation with the distribution pipes.
- Micrometers are not installed completely, and moreover, many of the installed micrometers are not functioning adequately.
- It is assumed that an non ignorable percentage of the distributed water is consumed by illegal consumptions.

(13) Automation and SCADA System

1) Objectives of the Diagnosis

It is proposed that all water supply service related facilities, such as reservoirs, wells, valve pits, pressure reducing chambers, and lift pumping stations will be brought under automation and will be integrated with SEDAPAL’s current SCADA (Supervisory Control And Data Acquisition) system. With this, all the facilities could be supervised and remotely controlled in real time.

This scenario allows for qualitatively and quantitatively optimizing the water distribution system. In addition, the combined use of surface and groundwater can be regulated efficiently. Further, this will also help efficient operation of the primary distribution network.

The JICA Study Team carried out a field investigation by engaging local Consultant on automation and the SCADA system in 23 wells, 26 reservoirs, 4 pumping stations and 11 valve pits. The results can be found in Appendix B3. Through that investigation, a diagnosis has been carried out for the control and communications automation systems and their interrelation to the La Atarjea main control center. This involved checking the equipment conditions and recommending all necessary actions to solve any problems.

2) Activities and Location of the Target Facilities

The field investigation has been carried out in the following manner:

- Data collection from SEDAPAL.
- Field inspection and reconnaissance survey.
- Data gathering from the supplementary works and Lima Norte 1 files.
- Coordination with SEDAPAL technical staff.

The location of the target facilities investigated is given in the Table 2.5.8-33:

Table 2.5.8-33: Target Facilities of SCADA Diagnosis

Districts	Wells	Reservoirs	Valve pits
Callao	-	R-522	-
Carabayllo	-	RP-4, RP-3-	-
Comas	-	R-927, R-820, R-926, R-925	350, (345-346), (347-346)
Los Olivos	280, 351, 423, 474, 498, 618, 688, 691, 692, 693, 694, 695, 696, 704, 716, 717,720.	R-1 Villa Sol R1 Villa del Norte R-1 Parque el Naranjal R-1 Cueto Fernandini, R-1 Olivos de Pro R-2 Programa Confraternidad R-1 Programa Confraternidad Comité Aposte, R-1 Puerta de Pro R-1 Rio Santa, Pro R1- Santa Luisa.	N° 83, 84, 85
Puente Piedra	-	-	361, 368, 369
San Martín	569, 687, 689, 727, 728, 729	R-986, R-1 Virgen del Rosario Rosario del Norte R3 Jazmines del Naranjal R-2 Vipol Naranjal R-1 Cerro el Choclo R2 Cerro el Choclo R-1	212, 213
Number	23	26	11

Source: JICA Study Team

3) Evaluation and Diagnosis

The SCADA Control system of SEDAPAL, at the present, is located in La Atarjea plant. This system matches the international standards established by the control organizations and the Institute of Electrical and Electronics Engineers (IEE). At present, it works through microwaves, UHF radios, wireless connection (wide spectrum) and mobile phones GPRS. In summary, the communication system can be serially integrated and could be used over several protocols, such as TCP/IP, MODBUS (serial and TCP), DNP3 (Serial and TCP/IP), and Ethernet.

At present, for SCADA system of SEDAPAL is using two kinds of softwares:

- The SURVALENT software, which controls the pumping system of SEDAPAL. This software controls 279 hydraulic stations, including reservoirs, pressure reducing valves and valve pits. These remote stations are managed by EOSBA and/or EMEBA teams (Pumping System Operation and Water Pumping Maintenance Equipment Team).

- The INFOPLUS software has been installed for gravity system control. This software monitors and controls 220 Hydraulic Stations through serial radio. These remote stations are managed by the Primary Distribution Team.

At present, several projects on SCADA system integration and optimization are being developed, which includes:

- Complementary Network Project
- Huachipa Project
- Lima North 1 Project

These projects will be integrated to SCADA software in the following way:

i) INFOPLUS

It will be upgraded to INFOPLUS21. This new software version will be able to collect, manage and save large data volume on the hydraulic system of the primary distribution water network of SEDAPAL in order to carry out operating Hydraulic Models analysis and preparing reports. It will allow the management improvement and could allow distribution operation, increasing the system flexibility.

This will integrate the following remote stations:

- Lima North 1 Project: 26 of 30 remote stations of this Project
- Complementary Works project: 51 remote stations

ii) Integration of Survalent System

- Lima North 1 Project: 6 remote stations of this Project
- Complementary Works project: 4 remote stations

4) SCADA system of Lima North II Project

In compliance with the technical regulations and industrial standards (set by the Institute of Electrical and Electronics Engineers, IEE), the facilities should have the following equipment, so that they can be controlled and supervised from SEDAPAL's automated control center and Comas Service Center:

- Electronic instrumentation for pressure, level, flow, and other parameter measurements. This instrumentation must have the Profibus communication protocols currently used by SEDAPAL. Likewise, it must work at an automation level that allows for quick access and tele-control operations (without on-site assistance.)
- Valves with electronic control.
- Communications system from each site to the control center.
- Panel board with PLC and communications modules.
- Electronic starting systems with high efficiency and low harmonic contents

Based on the standards described above, the existing SCADA systems of the target facilities were evaluated as follows:

(a) Reservoirs

None of the reservoirs have any equipment required for SCADA operation. Currently, all valves are manually operated and must be upgraded and/or replaced to automated valves.

(b) Wells


None of the wells have any equipment required for SCADA operation. Power panel boards are in very poor conditions; they lack electronic starters with speed variations. Some of the wells have incomplete panel boards with a 12-year old technology that lacks Ethernet communications. All valves are manually operated.

(c) Valve pits

Among the eleven valve pits at the entrances of the sectors, only five valve pits have instrumentation and automated systems. But the control of these five valve pits, as mentioned earlier, will be replaced and will be controlled by the head reservoirs of the sector.

Figure 2.5.8-22 shows the SCADA System Remote Stations of the project area belonging to the projects: Lima North I, Lima North II, Complementary Works and Huachipa Plant. Annex B3 shows more specifically on how the Remote Stations are integrated with SCADA software managed by SEDAPAL.

It must be mentioned that if the valve pits would not be replaced, the existing instrumentation should be replaced because they do not fulfill new standard of SEDAPAL that have been introduced for this kind of instrumentation. In previous projects, SEDAPAL accepted any kind of communication protocol of the PLC instrumentation. Communications such as Modbus, Hart and others were accepted if a gateway is installed before to PLC. But, the gateway or protocol converter had many failures on field signals, and for that reason SEDAPAL has defined new standard. These are field buses with Profibus DP protocol, which can manage the maintenance assets by remote control.



LEGEND

Lima Norte II	STUDY AREA	ROADS
Lima Norte I	DISTRICT BOUNDARY	RIVERS
Huachipa Plant	SECTOR BOUNDARY	COAST
Complementary Works	SERVICE CENTER	

0 1 2 4 km

1:80,000
 Projection: UTM
 Datum: WGS-84
 Zone: 18 sur

REPUBLICA DEL PERU
 SERVICIO DE AGUA POTABLE Y ALCANTARILLADO DE LIMA

GRAFICO_2.5.8-22: INFRAESTRUCTURA PROYECTADA PARA INTEGRACION DEL SISTEMA SCADA

FIGURE_2.5.8-22: PLANNED INFRASTRUCTURE FOR THE INTEGRATION OF SCADA SYSTEM