







(8) Presentation Materials for Seminar Held on 28th February, 2012








Valve installation & placing Condition of boundary valves which are needed for the Isolation of the sub zone were checked. If they cannot completely close, they were replaced. Installed additional valves when required. Data sheet shall be filled. Valves detected by using valve locator, Metal pipes by using Pipe locator & PVC pipes by using leak detection instrument.






































(8) Presentation Materials for Seminar Held on 28th February, 2012


Meter testing > Out of total, at least 10% of water meters will be tested randomly at site with the help of calibrated(50l) bucket (Ex. 60 meters for zone B1) > Additionally, another few meters (mostly doubted once) will be checked through meter testing unit








Key items of leak detection The portion between ferrule to house meter point will be checked by using Eco-stick. All other areas will be checked by using Leak Detection Instrument. Pin-point or confirmation survey can be introduces if required.


























		Det	ails o	f NR	W	reduc	ction	in B1		
	Customer	Stand post	Replacement/ Non-working meter	Elimination /Illegal connection	Leak repair		Initial	After "Primary Activities"	Second "Primary Activities"	
							It has done for the intial rate of NRW in the subzone.	It has done after leak repair and meter replacement.	It has done after leak detection by the step test and repaired.	
							Date:	June 3-12,2010	Aug25-Sep2,2010	Feb 2,2011
ı	584	2 (1/2)	Non_working (7/7) Unmetered (9/12)	8/8	1st (10/34) 2nd (0/12)		653.13	579.64	549	
			Unmettered (9/12)		Total (10/46)		390.12	449.35	449.35	
ı							12	12	7	
							312	249	206	
							40.27	22.48	16.31	

	Det	ails o	TNK	W	reau	ction	IN BZ	4
Customer	Stand post	Replacement/ Non-working meter	Elimination /Illegal connection	Leak repair		Initial	After "Primary Activities"	Second "Primary Activities"
					Action	It has done for the infal rate of NRW in the subzone.	It has done after leak repair and meter replacement.	It has done after lea detection by the step test and repaired.
					Date:	16 th Feb 2012		
624	6 (0/6)	Nonworking (3/3)	15/0	Still not	Inflow:(m3/D)	1154		
024	0 (0.0)	Unmetered (3/2)	100	confirmed	Consumption: (m3/D)	441.86		
						10.6		
					MNF:(L/Min)	655		
					NRW ratio:(%)	61		

[Det	ails o	f NR	W	reduc	ction	in B3	3		
Customer	Stand post	Replacement/ Non-working meter	Elimination /Illegal connection	Leak repair		Initial	After "Primary Activities"	Second "Primary Activities"		
					Action	It has done for the initial rate of NRW in the subzone.	It has done after ball valve replacement.	It has done after lea detection by the step test and repaired.		
							Date:	Nov 18-19,2010	Jan20-21,2011	Sep20,2011
360		Non_working (7/7)	8/8	1st (10/34) 2nd (0/12)		1183	376.83	282		
		Unmetered (9/12)		Total (10/46)		186.19	186.19	201.29		
						-		-		
					MNF:(L/Min)	106		54.53		
					NRW ratio:(%)	84.26	50.59	28.62		

	Det	ails o	f NR	W	reduc	tion	in B4]
Customer	Stand post	Replacement/ Non-working meter	Elimination /Illegal connection	Leak repair		Initial	After "Primary Activities"	Second "Primary Activities"
							repair and meter	It has done after leak detection by the step test and repaired.
					Date:	Oct 27-28,2011	Jan 18-19, 2012	
453	25 (25/25)	Non_working (15/15) Unmetered (17/16)	13/0	1st (34/32)	Inflow:(m3/D)	987	707	653
		Unineteled (1770)			Consumption: (m3/D)	353	353	353
						76	76	76
						366	252	223
					NRW ratio:(%)	64.24	50.07	41.8

	Det	ails o	f NR	W	reduc	ction	in B5	1
Customer	Stand post	Replacement/ Non-working meter	Elimination /Illegal connection	Leak repair		Initial	After "Primary Activities"	Second "Primary Activities"
					Action	It has done for the intial rate of NRW in the subzone.	It has done after leak repair and meter replacement.	It has done after leak detection by the step test and repaired.
					Date:	12 Feb 2012		
814	Not finalized	Not finalized	Not finalized	Not detected	Inflow (m3/D)	1351		
						510		
						N/C		
						862		
						62		

70	Borella 1	Borella 2	Rorella 3	Borella 4	Borella 5	Borella	
No. of consume	ers	584	624	360	453	814	1109
Commen taps	No. common taps	2	6	0	25		
Commentaps	consumption(m3/day)	12	10	0	76		
No. of working	meters	543	596	289	435		
No. of unmeter	rdetected	12	3	1	17		
No. of defectiv	e detected	15	2	13	15		
No. of difficult	to read	0	0	2	0		
No. of disconne	ected premises	0	0	3	0		
No. of houses of	dosed	7	23	47	12		
No. of illegal re	ectified	8	15	25	13		190
No. of service I	eaks found	35	N/C	16	26		
No. of main lea	ks found	12	N/C	2	8		

Accomplishment
■ B1 - Initial & Final NRW determined
■ B2 - Initial NRW established & improvements are now in Progress
■ B3 - Initial & Final NRW determine
■ B4 - Initial & interim NRW established
■ B5 - Initial NRW established & improvements are now in Progress
■ B6 - Initial NRW to be finalized & improvements are now in Progress
■ B7 - Initial NRW still not established
Comparison with Program
-2009Commencement of Project Nov. 2009
Physical Progress 55%

Out (Physical progress	Com	e of	the	Pro	ojec	t	
Zone	B1	B2	В3	B4	B5	В6	
No of illegal connections removed		8	15	25	13		25
No of looks renaired	Main	10	43(N/C)	2	8		
No. of leaks repaired	Service	46		19	26		
Over flow from tank		1		1	0		
No of unmeterd places me	tered	9	5	14	16		
No. of defective meters cha	anged	7		14	15		
No of commen taps remov	ed	1	Ţ	0			
No. of new conections give	en	8		3			
Meter sealing proceses		550		350			

(8) Presentation Materials for Seminar Held on 28th February, 2012

zone name		Borella 1	Borella 2	Borella 3	Borella 4	Borella 5	Borella 6	Tota
7700	12"ф		2			- 1		3
No. of sluse-valves & wash-out(FH)	6"ф	-						0
trace & surfaced	4"ф	8	3		4	5	7	27
	2"ф	1						1
No. of new sluse-valves & wash-	6"ф	-		1				
out(FH) installed	4"ф	5	5	4	7=	2	4	
out(FH) ilistalled	2"ф	2	-					
Length of newly layed commen mains	3"ф	-	90					
(m)	2"ф	60	H	į			400	460
Meter Chambers installed		2	4	1	2	2		
No. of connections transferred		3	21					
Replaced length of bunddle pipes(m)		15	840					565
Double line disconnection work (No. of I subjected)	houses						450	450
Elimination length of CI line from our sys	stem(4"φ) in	100					2000	210



Amount of water saved m ³ /day	1339
Amount of Money Saved per year Rs.	

Problems Encountered Inaccuracy of the current drawings Lack of valve location details Burried and non function condition of the existing valves Difficulty of gaining approval from local authorities (Presently RDA not giving approval to excavate their roads) Consumer relation problems Old & complicated service Distribution & High Leak System Scaling of old Distribution network Work with restriction due to Motor Traffic and City Congestion

How to Overcome

- Regular meeting helps to share the experience, gain new knowledge and change bad attitudes
- Consumer related problems minimized by acknowledging the community about NRW activities
- Initiation of a leak detection and repairs
- Programme for routine night survey
- Implementation of meter sealing process (to minimized illegal activities)

Obtain benefits

- Findings further considered for ,
 (1) NRW engineering study, master plan update (JICA)
 (2) Colombo water supply service improvement project (ADB)

- Methodical approach to identify the way of reduction of NRW. Use of modern equipment for asset management. Pressure improvements(in B1, some area's pressure increase from 2m to 6m)
- Capacity development of engaged personnel.

(8) Presentation Materials for Seminar Held on 28th February, 2012

- Able to implement new re-numbering system to valve network, starting of maintaining valve tie-measurements and updating of existing drawings.

 Encourage an improved service level to consumer.

 Able to include new consumers in to the billing system (By eliminating common taps and giving new connections to surround people as well as elimination of illegal connections).

- $\hfill \ensuremath{\hbox{$\scriptstyle \square$}}$ Improvement of consumer satisfaction as well as their relationship.
- Control of illegal connections, vandalism and misuse of supply.

Reasons for success of the project

- Given valuable guidance by the JICA
- · Scope of the project able to tackle both Real & appare losses (↑)

The effort implement during last two years

Engage personnel (both O&M and NRW sections), who spent their valuable time for the success of the project with their normal daily routine works.

Future Expectations


- Implementation of same procedure for other areas which are not covered through this project.
- Implementation of regular monitoring activities for minimized estimated bills.
- Introduction of valve operating routine system, specially for washouts.
- Implementation of Meter sealing work for other areas which are still not covered.
- Regular monitoring system of NRW variation in completed sub-zones


Lesson Learn

It is found that the major reason for the NRW is due to the leaks of the existing pipe network


- Systamatic night leak survey is very important
- Rapid engagement to leak repair works is a must








Activities Implemented Under JICA Project in Kotahena Pilot Zone




Development of Sub Zones Sub Zone Kı - Number of Customers 397 - Distribution Length - 3"CI - 155.2 m - 253 m 5"CI -298.9 m 160 mm PVC - 716.7 m Sub Zone K2 - Number of Customers 410 - Distribution Length 3"CI 4"CI -742.2 m 5"CI -397.3 m 63 mm PVC - 245.1 m


Work Flow of Activities Sub Zone Isolation Map Updating Consumer Survey Leakage Management Development of Further Sub Zones





























Summary	of W	/ork	Imp	leme	ente	d in I	<1
Component	Water Balance Initially	After Activity 1	service leaks 14	4" CI pipe abondond connection transferred to PVC		Bundle pipes removed in 17 locations	Bundle pipes removed in 11 locations & 6 connections given
Total System Input (m3/d)	1295	1041	918	925	869	585	571
Billed Authorized consumption (m3/d)	190.88	248.29	248	248	248	248	248
NRW %	85.26	76.15	72.98	73.19	71.46	57.61	56.57
MNF (I/min)	690	480	330	330	300	120	120







Benefits

- Pressure Improvement in Kotahena Area
- Familiarizing with New Technology
- Methodical approach to address Water Loss Management
- Team Work Effects
- Sharing Knowledge With Japanese Experts
- In depth information about the existing system
- Supplying a good service for consumers


Saved 911 m3/day equivalent to LKR 8.98m/year

Learning....

- Importance of Valve and its Workability
- Importance of Realistic Map
- Leak Repair is not effective in a deteriorated system.
 - Replace Bundle Pipes
 - Replace Deteriorated CI Pipes
- Abundant pipe to be Completely Removed
- House to house survey gave more information for O&M activities
- Effectiveness of Weekly Meeting

: Similar Activities in Other Areas

SIMILAR ACTIVITIES IN OTHER AREAS **UNDER CAPACITY DEVELOPMENT** PROJECT FOR NON **REVENUE WATER (NRW)** REDUCTION IN COLOMBO CITY



Main Work Flow

Sub zone Isolation

Map Updating

Consumer Survey

Leak Management

SUB ZONE ISOLATION AT

ARAMAYA ROAD

Identification of pipe lines According to existing drawings. There are two Nos.

of 4" Dia CI lines and

4" Dia PVC line.

After the Physical survey we found that 6" PVC main and 2 Nos. of 4" Dia PVC and CI Mains

Length of Main Line : 4.5 Km

No of Connections: 895

Total Consumptions :15400 m³

Identification of valves drawing shows 2 Nos.of main vales at the starting point.

Only one valve could be found at the starting point.

We used valve tracing equipments to locate the valves.



VALVE CONDITION

We operated the valve and check the working Condition. It was satisfied

: Similar Activities in Other Areas



FUTURE WORK PLAN FOR MONTH OF MARCH 2012

Hydraulic Isolation

Flow measurement

Consumer Survey

Repairing of visual leaks

Leak detection using pin point survey

We hope to continue our work with the guidance and direction of pilot zone officers and JET.

THANKING YOU

: PR Activities

Capacity Development Project for
Non Revenue Water Reduction in
Calombo City Area

Public Relations Activities in
Selected Schools


National Water Supply & Drainage Board
Regional Support Centre (Western - Central)

hy Public Relations Activities in Schools? > To educate the future generation > To make them a part of this project > To send the message to their homes











: PR Activities







What children gained? > Awareness on water coservation > Knowledge on Reduction of Non Revenue Water How we appritiated them? > Participatory Certificates & Drawing -kits. > Special Certificates & gifts for winners.









: PR Activities











Water Board & JICA Achivements > Knowledge given to children. > We got the opportunity to send the good message to their homes & schoolmates. > Opportunity to display the winning posters in public places & schools with a message from the Water Board & JICA.





































(8) Presentation Materials for Seminar Held on 28th February, 2012


			F	Records	s for V	alve Co	ndition			
			Valve cond	ition checkir	ng list			Name of Pilot		
item	No.	Size(mm)	Pipe material	Location (Existence, Buried)	Valve cover (OK, Non.)	Direction (Clockwise, Anticlockwise)	Operable (C, NC)	Number of rotation to be closed	Need for a replacement	Remarks
	V-1									
	V-2									
	V-3									
	V-4									
Valve	V-5									
2	V-6									
	V-7									
	V-8									
	V-9									
	V-10									
	H-1									
#	H-2									
ğ	H-3									
Fire Hydrant	H-4									
8	H-5									
ŭ.	H-6									
6	W-1									_
Wash	W-2									
	W-3									
	No.	Size	Material	Meter(Y, N)	Condition			Remarks		
8	PT-1									
Stand	PT-2									
	PT-3									























(9) Presentation Materials for Public Seminar Held on 15th October, 2012 Training Materials

<u>List of Materials</u>

- ①: Briefing of the Project and Results and Findings
- ②: Pilot Activities in Borella
- ③: Pilot Activities in Kotahena
- 4: Outline of Execution Plan and Recommendation
- ⑤: Improvement of GIS for O&M in entire CMC
- 6: Reduction of Real Losses (Leakage)
- ⑦: PR Activities
- **®**: Recommended Action Plan

Annex -3 Training Materials (9)

1. Briefing of the Project and Results and Findings

THE CAPACITY
DEVELOPMENT PROJECT
FOR NRW REDUCTION IN
COLOMBO CITY

S.G.G RAJKUMAR ASSISTANT GENERAL MANAGER (WATER LOSS MANAGEMENT SECTION) B.SC. ENG. (HONS), C.ENG., FIE (SL), M.SC. (DENMARK). MBA (PIM - USJ), M.ENG (MORATUWA)


Purpose of the Project

• NWSDB Capacity to implement NRW reduction activity in Colombo City is Strengthened


Outcome of the Project


- Management Capacity of Senior Officers of RSC (W-C) to Plan and Supervise NRW Reduction Activities is Enhanced
- Technical and Operational Capacity to Conduct NRW reduction activities by officer / Staff of RSC (W-C) is Developed






1. Briefing of the Project and Results and Findings







- Methodology
 Selection of small segment of distribution for close activity for reduction of losses
- Isolation of the section having one or two inflows
- Collection of Available customer information within the area
- Visit each premises and verify legal consumption, leaks, check administrative errors

NRW Reduction Activity


- Regular meeting to encourage interaction between field staff and managerial staff
- Confirm the available information on valves, pipelines at site
- Locate leaks visually and by using equipment
- Updating of Maps
- Measurement of Initial Pressure

MONITORING


1. Briefing of the Project and Results and Findings














1. Briefing of the Project and Results and Findings





REDUCTION OF LOSSES


Rectification


- Identification of leaks and repairs
- Replacement of defective meters
- Regularization of unauthorized connections
- Replacement of bundle pipes
- Reduction of free water outlets
- Installation of meters to free water outlets







1. Briefing of the Project and Results and Findings









					Oı	utco	me Ko	otahe	na				
ſ	Sub	Lengt	n of Mai	n Pipe	No of	Initial	Final Flow	Amount of	Initial	Final	Nun	nber of Le	aks
I.	Zone	Material	Length	Total Length	coustomers	Flow (m3/d)	(m3/d) - After completing	Saving (m3/ d)	NRW (%)	NRW (%)	Main	Service	Total
K	1	PVC Cl	692 707	1,399	397	1,295	571	724	85	56	4	86	90
K	2	PVC CI	0 1,468	1,468	426	1,245	933	312	78	72	0	93	93
K	3&K4	PVC Cl	173 7,160	7,333	1,383	4,240	3,989	251	73	71	7	29	36
		M	1,100										

Contd				-C)				
Sub-zone	K1	K2	K3&K4	K5	К6	K7	K8	К9	K10
leaks per 100 connection	21.7	21.8	2.1	7.0	-	1.7	8.7	5.0	3.7
Identified illegal	53	23	5	1	_	0	-	1	-

1. Briefing of the Project and Results and Findings

Savings

- Amount of Water Saved 2,928 m3/day (0.64 mgd)
- Equivalent in Rs 45 million/year

Constraints Encountered

- Existing Drawings not Accurate
- · Lack of valve location details
- Buried and non function condition of the existing valves
- Consumer relation problems
- · Old & complicated service Distribution
- Scaling of old Distribution network
- Work with restriction due to Motor Traffic and City Congestion
- Existence of unknown/unexpected pipes
- Some Houses Connected to numerous distribution pipes
- Houses constructed above the pipes
- · Low Pressure in the system

Conclusion


- Suggest to use PE pipe for service connection to reduce service leaks & Unauthorized Connections
- Solution to Each Area has to be Case by Case Basis
- Replacement of Pipe has to Ensure Old System is Fully Discontinued by use of Pipe Material that is not Used Presently (Blue Colour PE pipe is suggested)
- · Bundle pipe service connections avoided
- PVC pipe which show more leaks to be replaced with increased cover




FURTHER IMPROVEMENT


Geographic information system (GIS)

- Update Base Maps
- Location of Customer Meter
- Asset Management
- Record Leak Repair
- Record Unauthorized Consumption
- Use/update of GIS by Zone officers



1. Briefing of the Project and Results and Findings





Public Relation Activity

- Creation of Awareness of the Project to Residence
- Discourage Unauthorized Consumption Explain the Penalty
- Discourage Customer Rearrange Service Connection
- Reduction of Wastage in Free Water Outlet
- Educate the school Children








1. Briefing of the Project and Results and Findings

Audio Visual

Obtained benefits

- Team gained practical experience to address on reduction of losses
- Able to update existing drawings
- Increase in system Pressure
- Improved service level to customers
- Minimized billing errors
- Increasing of customer relationship
- · Control of illegal connections, vandalism and misuse of supply
- · Increasing of customer satisfaction





• Customers being aware on conservation of water

- NWSDB staff attitude change
- Updated map


GIS (Since Dec 2011)


- Base Map preparation using Satellite Image Completed
- Field Data Collection and entering

 - Borella 70%Kotahena 40%
 - × Thimbrigasaya Initiated
- Inclusion of Free Water Outlets and Leak locations in progress

1. Briefing of the Project and Results and Findings

			utsid	Areas			
Zone	Sub Zone	No of coustomers	Initial Flow (m3/Day)	Final Flow(m3/Day)- After completing NRW activities	Amount of Saving (m3/ Day)	Initial NRW %	Final NRW 9
Kent Road		216	334	256	78	53.00	38.00
Handala Frerry	Road	219				18.00	
Kirullapone		537	456	427	29	19.00	7.00





Valve Condition Survey

- Condition of boundary valves which are needed for the Isolation of the sub zone were checked.
- If they cannot completely close, they were replaced.
- > Installed additional valves when required.
- > Data sheet shall be filled.

