

VOLUME 3

RESULTS OF EXISTING CONDITION  
SURVEY



## APPENDIX 3-A


# GEOLOGICAL DATA (LOCATION OF BOREHOLES, BORING LOGS, AND GEOLOGICAL PROFILES)






(1) Package B

1) Delpan Bridge











2) Nagtahan Bridge










STATION	0+000	0+100	0+200	0+300	0+400	0+500	0+600
PROFILE NO. 1	15.00	14.50	14.00	13.50	13.00	12.50	12.00
PROFILE NO. 2	14.50	14.00	13.50	13.00	12.50	12.00	11.50
PROFILE NO. 3	14.00	13.50	13.00	12.50	12.00	11.50	11.00
PROFILE NO. 4	13.50	13.00	12.50	12.00	11.50	11.00	10.50
PROFILE NO. 5	13.00	12.50	12.00	11.50	11.00	10.50	10.00

SURVEYED BY: <b>ASA ENGINEERING</b> No. 8, 1st Floor, Victoria Park, Quezon City 1106 TEL: (632) 8750-1234 FAX: (632) 8750-5678 WWW.ASAENGINEERING.COM	SURVEYED FOR: <b>RODRIGO ANGLAS S. ALBERO</b> LIC. 4048 DATE: 3-10-14 PRO. NO. 007500 DATE: 1-20-12	PROJECT & LOCATION: CTI Engineering International Co., Ltd.	LEGEND: AS-BUILT SURVEY OF NAGTAHAN BRIDGE MAGSAYSAN, MANILA CITY	NOTE: 1. CONSIDERED & BASED ON SPAN CONTROL, POINT 88+310 AND PRE-10 COORDINATES 2. AS-BUILT SURVEY IS BASED ON SPAN CONTROL, POINT 88+310, 88+320 & 88+330 3. DATE OF SURVEY: MARCH 10, 2012 4. PRELIMINARY AS-BUILT PLAN AS OF MARCH 8, 2012	SHEET CONTENTS: PRELIMINARY BRIDGE & ROAD PROFILE PROFILE 1 - 4	SCALE: H 1:1000 V 1:100	SHT. NO. 74
--	--	--	--	---	--	-------------------------------	----------------


3) Lambingan Bridge












- BF Backfill soil
- As Alluvial sand
- Ac Alluvial cohesive soil
- Ds Diluvial sand
- GF Guadalupe Formation (rock)

STATION	0+000	0+100	0+200	0+300	0+400	0+500
PROFILE NO. 1						
PROFILE NO. 2	2.821	2.816	2.812	2.808	2.804	2.800
PROFILE NO. 3						
PROFILE NO. 4						
PROFILE NO. 5						
PROFILE NO. 6						
PROFILE NO. 7	4.08	4.07	4.06	4.05	4.04	4.03
PROFILE NO. 8						

SURVEYED BY: 	SURVEYED FOR: CTI Engineering International Co., Ltd.	PROJECT & LOCATION: TOPOGRAPHIC & AS-BUILT SURVEY OF LAMBINGAN BRIDGE STA. ANA, MINDAO CITY	LEGEND: (Empty legend box)	NOTE: 1. COORDINATES IS BASED ON MARIAS CONTROL POINT 344-345 2. ELEVATION IS BASED ON MARIAS CONTROL POINT 344-345 3. ELEVATION IS BASED ON MARIAS CONTROL POINT 344-345 4. PLAN IS OF OCTOBER 18, 2012.	SHEET CONTENTS: PRELIMINARY BRIDGE & ROAD PROFILE	SCALE: H 1:1000 V 1:100	SHEET NO.: 
------------------	--	--	-------------------------------	---	---	-------------------------------	----------------


4) Guadalupe Bridge












5) Marikina Bridge














- (2) Package C
  - 1) Buntun Bridge































PROFILE NO.	0+000	0+100	0+200	0+300	0+400	0+500	0+600	0+700	0+800	0+900	1+000	1+100	1+200	1+300
PROFILE NO. 1	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00
PROFILE NO. 2	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00
PROFILE NO. 3	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00

<p>ASA Geotechnical Engineering</p>	<p>DESIGNED BY: <b>SHARAD JINDAL &amp; PARTNERS</b></p>	<p>SUPERVISOR: <b>CTI Engineering International Co., Ltd.</b></p>	<p>PROJECT &amp; LOCATION: <b>SHIVOLE DPT, CDW</b></p>	<p>LEGEND:</p>	<p>NOTE:</p> <ol style="list-style-type: none"> <li>1. CONSULT THE RECORD.</li> <li>2. EXAMINE IT CAREFULLY FOR ANY DISCREPANCY.</li> <li>3. PROCEED TO THE NEXT PAGE AS OF APPROVAL BY THE CLIENT.</li> </ol>	<p>SHEET CONTENTS:</p>	<p>SCALE: <b>1:1000</b></p>	<p>DATE: <b>11/2012</b></p>
---	---	---	--	----------------	--	------------------------	-----------------------------	-----------------------------


3) Palanit Bridge











4) Mawo Bridge





















5) Biliran Bridge



Depth (m)	Technical log & Sampling	Ground water table	Stratigraphy	Soil description & Classification	Classification	Depth (m)	Standard Penetration Test					Grain size analysis					Atterberg lim.			Physical Characteristics					Vane Test		Shear Test		Triaxial Compression Test				1D Consolidation Test				Depth (m)		
							Blows per 15cm	N (blows/30cm)				Gravel	Sand	Fines < 75 µm	Clay < 2 µm	% Organics	Liquid limit WL	Plastic limit WP	Plasticity index IP	Water content w%	Bulk density g	Dry density gd	Spec. density G	Void ratio e	Saturat. degree Sr%	Cu	Cu,r (remoulded)	Strength (kPa) qu	phi' deg	c' kPa	Test type	phi deg	c kPa	phi' deg	c' kPa	Cc		Cs	Cv cm <sup>2</sup> /s
1	N1			Consolidated clay with gravel	-	1	30	50	0	50	3.1	94.7	2.2					31.3																				1	
2	N2			Andesite (lava) between -1 m and -7 m: slightly weathered below -7 m: relatively fresh medium hard to hard rock Blakish-gray/dark-gray colored CL-CH class		2	0	50	0	50																												2	
3	N3						3	0	50	0	50																												3
4	N4						4	0	50	0	50																												4
5	N5						5	0	50	0	50																												5
6	N6						6	0	50	0	50																												6
7	N7						7	0	50	0	50																												7
8	N8						8	0	50	0	50																												8
9	N9						9	0	50	0	50																												9
10	N10						10	0	50	0	50																												10
11	N11						11	0	50	0	50																												11
12	N12						12	0	50	0	50																												12
13	N13						13	0	50	0	50																												13
14	N14						14	0	50	0	50																												14
15	N15						15	0	50	0	50																												15
16	N16					16	0	50	0	50																												16	
17	N17			Basalt mainly auto-breccia dark-green/dark-gray colored medium hard rock CM-CH class		17	0	50	0	50																												17	
18	N18						18	0	50	0	50																												18
19	N19						19	0	50	0	50																												19
20	N20						20	0	50	0	50																												20
21	N21						21	0	50	0	50																												21
22	N22						22	0	50	0	50																												22
23	N23						23	0	50	0	50																												23
24	N24						24	0	50	0	50																												24
25	N25						25	0	50	0	50																												25
26	N26						26	0	50	0	50																												26
27	N27						27	0	50	0	50																												27
28	N28						28	0	50	0	50																												28
29	N29						29	0	50	0	50																												29
30	N30						30	0	50	0	50																												30

30.00 m : End of borehole.

Drawing scale: 1/200

**ABBREVIATIONS**

D: Disturbed core barrel sample  
 C: Dry core barrel sample  
 U: Undisturbed stationary double tube sample  
 N: Split spoon sample

g: Bulk density (kN/m<sup>3</sup>)  
 gd: Dry density (kN/m<sup>3</sup>)  
 G: Specific density (kN/m<sup>3</sup>)  
 Cu - Cu,r: Undrained strength form VST (kPa)  
 qu: Unconfined compression strength (kPa)


CU: Consolidated sample, undrained loading conditions  
 UU: Unconsolidated sample, undrained loading conditions  
 CU: Consolidated sample, undrained loading conditions with pore pressure measurements  
 CD: Consolidated sample, drained loading conditions  
 phi, c: Friction angle, cohesion (total values)

phi', c': Friction angle, cohesion (effective values)  
 Cc, Cs: Compression index (loading, unloading)  
 Cv: Consolidation coefficient  
 M: Compression modulus  
 Pc: Effective preconsolidation stress









STATION	0+000	0+100	0+200	0+300	0+400	0+500	0+600	0+700	0+800
PROFILE NO. 1	23.50	21.80	20.50	19.20	18.00	17.00	16.00	15.00	14.00
PROFILE NO. 2	18.50	17.00	15.50	14.00	13.00	12.00	11.00	10.00	9.00
PROFILE NO. 3	13.50	12.00	10.50	9.00	8.00	7.00	6.00	5.00	4.00

SURVEYED BY: <b>ASA</b>	SURVEYED FOR: <b>CTI Engineering International Co., Ltd.</b>	PROJECT & LOCATION: <b>TOPOGRAPHIC &amp; AS-BUILT SURVEY OF BILIRAN BRIDGE, BILIRAN, LEYTE</b>	LEGEND: <b>— PROFILE NO. 1 — PROFILE NO. 2 — PROFILE NO. 3</b>	NOTE: <b>1. CONFORM TO B.M. 1000 2. B.M. 1000 IS A BENCH MARK (B.M.) OF THE BUREAU OF SURVEYING, DEPT. OF AGRI. &amp; FIS.</b>	SHEET CONTENTS: <b>BRIDGE &amp; ROAD PROFILE</b>	SCALE: <b>H 1:1000 V 1:1000</b>	DWG. NO.: <b>3-A-39</b>
-------------------------	--	--	--	--	--	-------------------------------------	-------------------------

















- Asg Alluvial sand and gravel
- Dsg1 Diluvial sand and gravel (1)
- Dsg2 Diluvial sand and gravel (2)
- CL1 Limestone (silty clay; strongly weathered rock)
- CL2 Coralline limestone

7) Wawa Bridge



4-1  
 = 973790.611  
 = 577693.499  
 = 47.083m.

BM-2  
 N.= 973614.767  
 E.= 577847.339  
 EL.= 47.195m.



Depth (m)	Technical log & Sampling	Ground water table	Stratigraphy	Soil description & Classification	Classification	Depth (m)	Standard Penetration Test		Grain size analysis					Atterberg lim.			Physical Characteristics					Vane Test		Shear Test		Triaxial Compression Test				1D Consolidation Test				Depth (m)				
							Blows per 15cm	N (blows/30cm)	Gravel	Sand	Fines < 75 µm	Clay < 2 µm	% Organics	Liquid limit WL	Plastic limit WP	Plasticity index IP	Water content w%	Bulk density g	Dry density gd	Spec. density G	Void ratio e	Saturat. degree Sr%	Cu	Cu,r (remoulded)	Strength (kPa) qu	phi' deg	c' kPa	Test type	phi deg	c kPa	phi' deg	c' kPa	Cc		Cs	Cv cm <sup>2</sup> /s	M MPa	Pc kPa
1	N1			Clay with gravel relatively low water content including gravels of 10-40 mm in diameter brownish-gray colored	-	1	7	9	11	20	11.8	88.0	0.2					20.3																			1	
2	N2					2	8	10	15	25	26.3	73.3	0.4					20.2																			2	
3	N3					3	7	10	17	27	0.9	96.6	2.5					22.0																			3	
4	N4					4	10	12	18	30	2.4	97.4	0.2					18.3																			4	
5	N5			Clay with gravel including gravel of 20-30 mm in diameter relatively low water content blackish-brown colored	-	5	8	11	19	30	0.0	99.5	0.5					29.5																			5	
6	N6					6	9	10	20	30	3.7	95.8	0.5					27.4																			6	
7	N7			Clay with gravel relatively high-moderate water content dark-gray/blackish-gray colored	-	7	10	15	25	40	0.0	11.1	89.0					32.3																			7	
8	N8					8	10	19	30	49	0.0	99.5	0.5					41.1																			8	
9	N9					9	0	50	0	50	0.0	99.7	0.3					43.8																			9	
10	N10			Clay with gravel relatively high-moderate water content dark-gray/blackish-gray colored medium soft/hard	-	10	12	15	35	50	0.0	99.7	0.3					42.4																			10	
11	N11					11	11	17	33	50	0.0	5.6	94.5					19.0																			11	
12	N12					12	0	50	0	50	0.0	8.8	91.2					10.0																			12	
13	N13			Clay with gravel relatively high-moderate water content dark-gray/blackish-gray colored relatively hard	-	13	0	50	0	50	0.0	3.4	96.6					30.0																			13	
14	N14					14	0	50	0	50	0.0	1.9	98.1					14.0																			14	
15	N15					15	0	50	0	50	0.0	1.6	98.4					11.0																			15	
16	N16			Clay relatively high water content greenish-gray colored	-	16	10	11	30	41	0.0	3.0	97.0					22.0																			16	
17	N17					17	10	10	35	45	0.0	1.3	98.7					11.0																			17	
18	N18			Clay relatively low water content bluish-gray/greenish-gray colored soft-hard, sometime consolidated	-	18	12	14	30	44	0.0	3.3	96.8					12.0																				18
19	N19					19	12	15	27	42	0.0	11.7	88.3					11.0																			19	
20	N20					20	15	15	35	50	0.0	33.3	66.7					18.0																			20	
21	N21			Clay sometime with gravel medium-soft hard dark-greenish-gray colored moderate water content relatively consolidated below -29 m	-	21	20	21	32	53	0.0	31.4	68.6					8.0																			21	
22	N22					22	21	23	30	53	0.0	89.2	10.8					47.8																			22	
23	N23					23	20	25	27	52	0.0	5.3	94.8					5.0																			23	
24	N24					24	21	26	25	51	0.0	8.7	91.3					9.0																			24	
25	N25					25	22	25	33	58	0.0	6.4	93.6					4.0																			25	
26	N26					26	23	27	34	61	0.0	9.7	90.3					6.0																			26	
27	N27					27	25	25	30	55	0.0	5.6	94.4					17.0																			27	
28	N28					28	20	26	25	51	0.0	10.5	89.5					14.0																			28	
29	N29					29	22	27	36	63	0.0	99.6	0.4					7.0																			29	
30	N30					30	25	36	35	71	0.0	97.4	2.6					22.0																			30	

**ABBREVIATIONS**


D: Disturbed core barrel sample  
C: Dry core barrel sample  
U: Undisturbed stationary double tube sample  
N: Split spoon sample

g: Bulk density (kN/m<sup>3</sup>)  
gd: Dry density (kN/m<sup>3</sup>)  
G: Specific density (kN/m<sup>3</sup>)  
Cu - Cu,r: Undrained strength from VST (kPa)  
qu: Unconfined compression strength (kPa)

CU: Consolidated sample, undrained loading conditions  
UU: Unconsolidated sample, undrained loading conditions  
CUPP: Consolidated sample, undrained loading conditions with pore pressure measurements  
CD: Consolidated sample, drained loading conditions  
phi, c: Friction angle, cohesion (total values)

phi', c': Friction angle, cohesion (effective values)  
Cc, Cs: Compression Index (loading, unloading)  
Cv: Consolidation coefficient  
M: Compression modulus  
Pc: Effective preconsolidation stress







## APPENDIX 3-B

# DETAILED RESULTS FOR FIRST SCREENING OF CANDIDATE BRIDGES



**(1) Package B**

**1) Delpan Bridge**

BRIDGE SEISMIC INVENTORY DATA										
<b>A. GENERAL</b>										
(1) Bridge Name:	<i>Delpan Bridge (Downstream)</i>					(2) Posted Load Limit	<i>20</i>	tons		
(3) Location:	km.:	Route:	<i>Bonifacio Drive</i>			Prov./ City	<i>Port Area</i>			
(4) Crossing Condition:	<input checked="" type="radio"/> Crossing River, ( ) Railway, ( ) Roadway, ( ) Valley, ( ) Others ( )									
(5) AADT:		(6) Detour Distance:		(7) Essential Bridge?	Yes ( ) No ( )					
(8) Alignment:	Straight , Curved, (Radius) _____m <input checked="" type="radio"/> Skewed, (Skew Angle) <i>30°</i>									
(9) No. of Spans:	<i>5</i>	(10) Span Lengths	<i>26.65+46.0+57.60+46.0+26.65</i>			(11) Total Length:	<i>202.9</i>			
(12) Left Sidewalk Width:	<i>1.6</i>	(13) Carriageway Width:	<i>17.32</i>	(14) Right Sidewalk Width:	<i>1.6</i>					
(15) Overall Width (including sidewalk):						(16) Year Built:	<i>1965(1988)</i>			
(17) As-builts or design drawings available?					Yes <input type="radio"/>	No <input checked="" type="radio"/>				
(18) Design calculations available?					Yes <input type="radio"/>	No <input checked="" type="radio"/>				
(19) Structure hydraulically adequate?					<input checked="" type="radio"/> Yes	<input type="radio"/> No	Don't know ( )			
(21) Seismically Retrofitted?					<input checked="" type="radio"/> Yes	<input type="radio"/> No	Description (But some are stolen)			
<b>B. SUPERSTRUCTURE</b>										
(23) Superstructure Type:	Steel Truss, Steel Girder, RCDG, <input checked="" type="radio"/> PSCG (Gerber Box Girder), Others ( )									
(24) Number of Girders/Span:	<i>Box Girder 1, PCI Girder 7</i>			(25) Continuous?	Yes <input type="radio"/>					No <input checked="" type="radio"/>
(26) Number of Expansion Joints:	<i>6</i>	(27) Type of Expansion Joints:	Steel, Rubber, Seam			<i>-</i>				
<b>C. BEARINGS</b>										
(28) Bearing Type:	Roller, Rocker, <input checked="" type="radio"/> Rubber, Others ( Pier: Steel )				Condition:	Functioning ( ) Not Functioning ( )				
(29) Type of Restraint (Transverse):				(30) Type of Restraint (Longitudinal):						
(31) Seating Length (Longi, Trans) :	Abutments:	<i>1.3, 0.7</i>	Piers:		Hinges:	<i>1</i>				
<b>D. ABUTMENTS</b>										
(32) Type:	<i>Wall Type</i>				(33) Height:	<i>4.8</i>				
(34) Foundation Type:	Spread Footing, <input checked="" type="radio"/> On Piles, Others (RCP)			(35) Wingwall Lengths	L:		R:			



E. COLUMNS AND PIERS			
(36) Column Type:	<i>Wall type</i>		
(37) Min. Transverse Cross-Section Dimension:		(38) Min. Longitudinal Cross-Section Dimension	
(39) Height Range:		(40) Fixity:	Top Bottom Both
(41) Percentage of Longitudinal Reinforcement:			
(42) Transverse Reinforcements:	Bar Size:	Spacing:	Tied Spiral
(43) Foundation Type:	Spread Footing	<u>On Piles</u>	Others ( )

F. SITE	
(44) Estimated Peak Ground Acceleration (0.4-0.7g):	
(45) Soil Profile Type:	I II <u>III</u> IV Don't Know
(46) Liquefaction Potential:	<u>Yes</u> No Don't Know ( )
(47) Boring Data Available:	Yes <u>No</u>


G. OTHER ITEMS			
(48) Approach Slab: Yes ( ) Length		(47) Embankment Side-slope type(Approach Road):	(H:V):
(49) Slope Bank Protection Type:			

PHOTOGRAPHS / SKETCHES (Use additional sheets if necessary)





# Bridge Profile



# Main Features of the Bridge





## 2) Jones Bridge


BRIDGE SEISMIC INVENTORY DATA										
<b>A. GENERAL</b>										
(1) Bridge Name:	<i>Jones Bridge</i>					(2) Posted Load Limit				tons
(3) Location:	km.:		Route:				Prov./ City			
(4) Crossing Condition:	<input checked="" type="radio"/> Crossing River, ( ) Railway, ( ) Roadway, ( ) Valley, ( ) Others ( )									
(5) AADT:		(6) Detour Distance:		(7) Essential Bridge?	Yes( ) No( )					
(8) Alignment:	<input checked="" type="radio"/> Straight, <input type="radio"/> Curved, (Radius) _____ m <input type="radio"/> Skewed, (Skew Angle) °									
(9) No. of Spans:	<b>3</b>	(10) Span Lengths	<b>35.51+43.40+35.50</b>			(11) Total Length:	<b>114.41</b>			
(12) Left Sidewalk Width:	<b>2.35</b>	(13) Carriageway Width:	<b>16.5</b>	(14) Right Sidewalk Width:	<b>2.35</b>					
(15) Overall Width (including sidewalk):	<b>21.2</b>				(16) Year Built:	<b>1948</b>				
(17) As-builts or design drawings available?					Yes	<input checked="" type="radio"/> No				
(18) Design calculations available?					Yes	<input checked="" type="radio"/> No				
(19) Structure hydraulically adequate?					<input checked="" type="radio"/> Yes	No	Don't know ( )			
(21) Seismically Retrofitted?					Yes	<input checked="" type="radio"/> No Description				
<b>B. SUPERSTRUCTURE</b>										
(23) Superstructure Type:	Steel Truss, <input checked="" type="radio"/> Steel Girder, <input type="radio"/> RCDG, <input type="radio"/> PSCG, Others( )									
(24) Number of Girders/Span:	<b>8</b>	(25) Continuous?	<input checked="" type="radio"/> Yes <input type="radio"/> No							
(26) Number of Expansion Joints:	<b>2</b>	(27) Type of Expansion Joints:	<input checked="" type="radio"/> Steel, <input type="radio"/> Rubber, <input type="radio"/> Seam							
<b>C. BEARINGS</b>										
(28) Bearing Type:	Roller, <input checked="" type="radio"/> Rocker, <input type="radio"/> Rubber, Others ( )				Condition:	Functioning( ) Not Functioning ( )				
(29) Type of Restraint (Transverse):	<b>Concrete Block</b>			(30) Type of Restraint (Longitudinal):						
(31) Seating Length (Longi, Trans) :	Abutments:	<b>0.9, 0.8</b>	Piers:	<b>0.7, 1.0</b>	Hinges:					
<b>D. ABUTMENTS</b>										
(32) Type:	<b>Wall</b>				(33) Height:					
(34) Foundation Type:	<input checked="" type="radio"/> Spread Footing, <input type="radio"/> On Piles, Others (RCP)				(35) Wingwall Lengths	L:		R:		











E. COLUMNS AND PIERS			
(36) Column Type:	<i>Wall</i>		
(37) Min. Transverse Cross-Section Dimension:		(38) Min. Longitudinal Cross-Section Dimension	
(39) Height Range:		(40) Fixity:	Top      Bottom      Both
(41) Percentage of Longitudinal Reinforcement:			
(42) Transverse Reinforcements:	Bar Size:	Spacing:	Tied      Spiral
(43) Foundation Type:	Spread Footing	On Piles	Others ( <i>Caisson</i> )

F. SITE			
(44) Estimated Peak Ground Acceleration (0.4-0.7g):			
(45) Soil Profile Type:	I	II	III <u>IV</u> Don't Know
(46) Liquefaction Potential:	<u>Yes</u>	No	Don't Know ( )
(47) Boring Data Available:	<u>Yes</u>	No	

G. OTHER ITEMS			
(48) Approach Slab: Yes ( ) Length		(47) Embankment Side-slope type (Approach Road):	(H:V):
(49) Slope Bank Protection Type:			





PHOTOGRAPHS / SKETCHES (Use additional sheets if necessary)









<p>1.</p> 	<p>2.</p> 
<p>3.</p> 	<p>4.</p> 
<p>5.</p> 	<p>6.</p> 
<p>7.</p> 	<p>8.</p> 
<p>9.</p> 	<p>10.</p> 



Main Viewpoints of the Bridge



Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Deck Slab (Primary)	Cracking		Most of cracks are less than width 0.3mm but several cracks are long and more than 1mm are observed.
	Water leaking		At several cracks portion or cold joints, water leaking is observed.
Steel Beam/ Truss Member (Bracings, etc.) (Primary)	Corrosion		Corrosion is occurred at end girder portion.
	Paint Peel off		Paint peel off is entirely progressing on steel girders.

Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Shoe/Bearing	Corrosion		All steel bearings are considerably corroded.
Abutments	Cracking concrete		Many vertical clacks are observed.
Piers	Cracking concrete		A few vertical cracks are observed on concrete wall between pier columns
Curb and Railing (Secondary)	Cracking		Many cracks are occurred on newly repaired walkway.

Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Expansion Joint	Water leaking		Water leaking from expansion joint at both abutments is observed.
	Displacement		Cover of expansion joint is displaced.



### Bridge Profile



Appendix 3-B-11

### Main Features of the Bridge



### 3) McArthur Bridge

BRIDGE SEISMIC INVENTORY DATA										
<b>A. GENERAL</b>										
(1) Bridge Name:	<i>McArthur Bridge</i>					(2) Posted Load Limit				tons
(3) Location:	km.:		Route:	<i>Rizal St.</i>			Prov./ City	<i>Manila</i>		
(4) Crossing Condition:	<input checked="" type="radio"/> Crossing River, ( ) Railway, ( ) Roadway, ( ) Valley, ( ) Others ( )									
(5) AADT:		(6) Detour Distance:		(7) Essential Bridge?	Yes ( ) No ( )					
(8) Alignment:	<input checked="" type="radio"/> Straight, ( ) Curved, (Radius) _____ m Skewed, (Skew Angle) °									
(9) No. of Spans:	<b>3</b>	(10) Span Lengths	<b>37.3+40.3+37.0</b>			(11) Total Length:	<b>114.6</b>			
(12) Left Sidewalk Width:	<b>1.8</b>	(13) Carriageway Width:	<b>6.70+6.70</b>		(14) Right Sidewalk Width:	<b>1.8</b>				
(15) Overall Width (including sidewalk):	<b>17.6</b>				(16) Year Built:	<b>1948</b>				
(17) As-builts or design drawings available?					Yes	<input checked="" type="radio"/> No				
(18) Design calculations available?					Yes	<input checked="" type="radio"/> No				
(19) Structure hydraulically adequate?					<input checked="" type="radio"/> Yes	<input type="radio"/> No	Don't know ( )			
(21) Seismically Retrofitted?					Yes	<input checked="" type="radio"/> No Description				
<b>B. SUPERSTRUCTURE</b>										
(23) Superstructure Type:	Steel Truss, <input checked="" type="radio"/> Steel Girder, RCDG, PSCG, Others( )									
(24) Number of Girders/Span:	<b>7</b>			(25) Continuous?	<input checked="" type="radio"/> Yes No					
(26) Number of Expansion Joints:	<b>2</b>		(27) Type of Expansion Joints:	<input checked="" type="radio"/> Steel, Rubber, Seam						
<b>C. BEARINGS</b>										
(28) Bearing Type:	Roller, Rocker, Rubber, <input checked="" type="radio"/> Others ( Abut: Fix, Pier: Pin)			Condition:	Functioning( ) Not Functioning ( )					
(29) Type of Restraint (Transverse):	<b>Concrete Block</b>			(30) Type of Restraint (Longitudinal):						
(31) Seating Length (Longi, Trans) :	Abutments:	<b>1.2, 0.8</b>		Piers:	<b>0.7, 0.7</b>		Hinges:	<b>-</b>		
<b>D. ABUTMENTS</b>										
(32) Type:	<b>Wall</b>				(33) Height:					
(34) Foundation Type:	Spread Footing, On Piles, Others (RCP)				(35) Wingwall Lengths	L:		R:		

<b>E. COLUMNS AND PIERS</b>			
(36) Column Type:	<i>Wall</i>		
(37) Min. Transverse Cross-Section Dimension:		(38) Min. Longitudinal Cross-Section Dimension	
(39) Height Range:		(40) Fixity:	Top      Bottom      Both
(41) Percentage of Longitudinal Reinforcement:			
(42) Transverse Reinforcements:	Bar Size:	Spacing:	Tied      Spiral
(43) Foundation Type:	Spread Footing	On Piles	Others (      )











<b>F. SITE</b>			
(44) Estimated Peak Ground Acceleration (0.4-0.7g):			
(45) Soil Profile Type:	I	II	III <b>IV</b> Don't Know
(46) Liquefaction Potential:	<b>Yes</b>	No	Don't Know (      )
(47) Boring Data Available:	<b>Yes</b>	No	

<b>G. OTHER ITEMS</b>			
(48) Approach Slab: Yes (      ) Length		(47) Embankment Side-slope type(Approach Road):	(H:V):
(49) Slope Bank Protection Type:			





PHOTOGRAPHS / SKETCHES (Use additional sheets if necessary)













<p>1.</p> 	<p>2.</p> 
<p>3.</p> 	<p>4.</p> 
<p>5.</p> 	<p>6.</p> 
<p>7.</p> 	<p>8.</p> 
<p>9.</p> 	<p>10.</p> 




Main Viewpoints of the Bridge

Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Deck Slab (Primary)	Cracking		Cracks with width less than 1mm are observed in a ratio of 20% of deck slab and water leaking is occurred on a part of cracks.
Steel Beam/ Truss Member (Bracings, etc.) (Primary)	Corrosion		Corrosion on steel members is progressing, especially; Gusset plates and lower flanges are severely corroded.
	Deformation/B uckling		Lower flange of Plate girder is deformed due to impact of ship.
	Paint Peel off		Paint peel off is entirely observed on the steel plate girders. (Poor Condition)



Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Shoe/Bearing	Corrosion		Steel bearings are severely corroded and stopped sliding function properly.
	Abnormal Displacement		Some of steel bearings are displaced abnormally.
Abutments	Cracking concrete		Several long cracks with width more than 1mm are observed horizontally.
	Honeycomb		A few honeycombs caused by unskilled workman ship are observed.

Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Pier	Spalling, Scaling,Disintegration		Scaling due to scratching by ship on the pier concrete surface is observed.
	Cracking concrete		Many cracks with width less than 1mm are observed vertically.
	Exposure/Corrosion of Reinf.		At some parts of spalling, Exposure/ Corrosion of Rebars is observed.
Expansion Joint (Primary)	Water leaking		Water leaking is observed at expansion joints.



Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Expansion Joint (Primary)	Displacement		Expansion joints are displaced.
Painting Cond. (Primary)	Discoloration		Discoloration due to paint peel off is observed.
	Rust		After Paint peel off, rusting is starting on the steel plate girders.

### Bridge Profile



### Main Features of the Bridge



#### 4) Quezon Bridge

BRIDGE SEISMIC INVENTORY DATA										
<b>A. GENERAL</b>										
(1) Bridge Name:	Quezon Bridge					(2) Posted Load Limit				tons
(3) Location:	km.:		Route:	Quezon Blvd.		Prov./ City	Quezon City			
(4) Crossing Condition:	<input checked="" type="checkbox"/> Crossing River, ( ) Railway, ( ) Roadway, ( ) Valley, ( ) Others ( )									
(5) AADT:		(6) Detour Distance:		(7) Essential Bridge?	Yes ( ) No ( )					
(8) Alignment:	<input checked="" type="checkbox"/> Straight, <input type="checkbox"/> Curved, (Radius) _____ m <input type="checkbox"/> Skewed, (Skew Angle) °									
(9) No. of Spans:	1	(10) Span Lengths	102.4		(11) Total Length:	102.4				
(12) Left Sidewalk Width:	3	(13) Carriageway Width:	7.70+7.70		(14) Right Sidewalk Width:	3				
(15) Overall Width (including sidewalk):	21.9				(16) Year Built:	1946				
(17) As-builts or design drawings available?					Yes	<input checked="" type="radio"/> No				
(18) Design calculations available?					Yes	<input checked="" type="radio"/> No				
(19) Structure hydraulically adequate?					<input checked="" type="radio"/> Yes	No	Don't know ( )			
(21) Seismically Retrofitted?					Yes	<input checked="" type="radio"/> No Description				
<b>B. SUPERSTRUCTURE</b>										
(23) Superstructure Type:	Steel Truss, Steel Girder, RCDG, PSCG, <input checked="" type="checkbox"/> Others ( Steel Type Arch )									
(24) Number of Girders/Span:	3	(25) Continuous?	Yes <input checked="" type="radio"/> No							
(26) Number of Expansion Joints:	2	(27) Type of Expansion Joints:	<input checked="" type="checkbox"/> Steel, Rubber, Seam							
<b>C. BEARINGS</b>										
(28) Bearing Type:	Roller, Rocker, Rubber, <input checked="" type="checkbox"/> Others ( Anchor )				Condition:	Functioning ( ) Not Functioning ( )				
(29) Type of Restraint (Transverse):				(30) Type of Restraint (Longitudinal):						
(31) Seating Length :	Abutments:		Piers:		Hinges:					
<b>D. ABUTMENTS</b>										
(32) Type:	Wall				(33) Height:					
(34) Foundation Type:	Spread Footing, On Piles, Others (RCP)				(35) Wingwall Lengths	L:		R:		

<b>E. COLUMNS AND PIERS</b>			
(36) Column Type:	-		
(37) Min. Transverse Cross-Section Dimension:		(38) Min. Longitudinal Cross-Section Dimension	
(39) Height Range:		(40) Fixity:	Top      Bottom      Both
(41) Percentage of Longitudinal Reinforcement:			
(42) Transverse Reinforcements:	Bar Size:	Spacing:	Tied      Spiral
(43) Foundation Type:	Spread Footing	On Piles	Others (      )


<b>F. SITE</b>			
(44) Estimated Peak Ground Acceleration (0.4-0.7g):			
(45) Soil Profile Type:	I	II	III      IV      Don't Know
(46) Liquefaction Potential:	Yes	No	Don't Know (      )
(47) Boring Data Available:	Yes	No	

<b>G. OTHER ITEMS</b>			
(48) Approach Slab: Yes (      ) Length		(47) Embankment Side-slope type (Approach Road):	(H:V):
(49) Slope Bank Protection Type:			





PHOTOGRAPHS / SKETCHES (Use additional sheets if necessary)













## Main Viewpoints of the Bridge

Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Deck Slab (Primary)	Cracking		Deck slab on main bridge is quite good condition but some cracks are detected.
	Waterleaking		At end portion of deck slab, waterleaking is detected.
Concrete Beam/ Girder (Approach Bridge) (Primary)	Cracking		Many cracks with width more than 1mm are observed on approach bridge girders.
Steel Beam/ Truss Member (Bracings, etc.) (Primary)	Corrosion		Many gusset plates are corroded but members of arch bridge are good condition.

Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Steel Beam/ Truss Member (Bracings, etc.) (Primary)	Deformation/Bu ckling		Gusset plate is deformed due to impact of bridge.
	Loose Connection		Some bolts are missing and losing connection.
	Paint Peel off		Paint peels off on some arch members are deserved.
Abutments	Cracking concrete		Some cracks with width less than 1mm are observed vertically on abutment.

### Bridge Profile



### Main Features of the Bridge





**5) Ayala Bridge**

BRIDGE SEISMIC INVENTORY DATA										
<b>A. GENERAL</b>										
(1) Bridge Name:		<i>Ayala Bridge</i>					(2) Posted Load Limit			tons
(3) Location:		km.:	Route:				Prov./ City			
(4) Crossing Condition:		<input checked="" type="radio"/> Crossing River, ( <input type="radio"/> Railway, ( <input type="radio"/> Roadway, ( <input type="radio"/> Valley, ( <input type="radio"/> Others (                    )								
(5) AADT:		(6) Detour Distance:				(7) Essential Bridge?		Yes( )	No( )	
(8) Alignment:		<input checked="" type="radio"/> Straight, <input type="radio"/> Curved, (Radius) _____ m <input type="radio"/> Skewed, (Skew Angle) °								
(9) No. of Spans:		<b>2</b>	(10) Span Lengths		<b>61560+(4265)+73650</b>			(11) Total Length:		<b>139475</b>
(12) Left Sidewalk Width:		<b>2335</b>	(13) Carriageway Width:		<b>8570+8550</b>		(14) Right Sidewalk Width:		<b>3685</b>	
(15) Overall Width (including sidewalk):			<b>25350</b>				(16) Year Built:			
(17) As-builts or design drawings available?					Yes <input type="radio"/> No <input checked="" type="radio"/>					
(18) Design calculations available?					Yes <input type="radio"/> No <input checked="" type="radio"/>					
(19) Structure hydraulically adequate?					Yes <input checked="" type="radio"/> No <input type="radio"/> Don't know ( ) <input type="radio"/>					
(21) Seismically Retrofitted?					Yes <input checked="" type="radio"/> No <input type="radio"/> Description (Retrofitted in 1999)					
<b>B. SUPERSTRUCTURE</b>										
(23) Superstructure Type:		<input checked="" type="radio"/> Steel Truss, <input type="radio"/> Steel Girder, <input type="radio"/> RCDG, <input type="radio"/> PSCG, Others(                    )								
(24) Number of Girders/Span:		<b>3</b>		(25) Continuous?		Yes <input type="radio"/> No <input checked="" type="radio"/>				
(26) Number of Expansion Joints:		<b>3</b>		(27) Type of Expansion Joints: <input checked="" type="radio"/> Steel, <input type="radio"/> Rubber, <input type="radio"/> Seam						
<b>C. BEARINGS</b>										
(28) Bearing Type:		<input checked="" type="radio"/> Roller, <input type="radio"/> Rocker, <input type="radio"/> Rubber, Others (                    )				Condition:		Functioning( <input type="radio"/> )		Not Functioning ( <input checked="" type="radio"/> )
(29) Type of Restraint (Transverse):						(30) Type of Restraint (Longitudinal):				
(31) Seating Length (Longi, Trans) :		Abutments:	<b>1.8, 1.2</b>		Piers:		Hinges:			
<b>D. ABUTMENTS</b>										
(32) Type:					(33) Height:					
(34) Foundation Type:		Spread Footing, On Piles, Others (RCP)			(35) Wingwall Lengths		L:		R:	


<b>E. COLUMNS AND PIERS</b>			
(36) Column Type:			
(37) Min. Transverse Cross-Section Dimension:		(38) Min. Longitudinal Cross-Section Dimension	
(39) Height Range:		(40) Fixity:	Top      Bottom      Both
(41) Percentage of Longitudinal Reinforcement:			
(42) Transverse Reinforcements:	Bar Size:	Spacing:	Tied      Spiral
(43) Foundation Type:	Spread Footing	On Piles	Others (      )

<b>F. SITE</b>			
(44) Estimated Peak Ground Acceleration (0.4-0.7g):			
(45) Soil Profile Type:	I	II	III      IV      Don't Know
(46) Liquefaction Potential:	Yes	No	Don't Know (      )
(47) Boring Data Available:	Yes	No	





<b>G. OTHER ITEMS</b>			
(48) Approach Slab: Yes (      ) Length		(47) Embankment Side-slope type (Approach Road):	(H:V):
(49) Slope Bank Protection Type:			

PHOTOGRAPHS / SKETCHES (Use additional sheets if necessary)















Main Viewpoints of the Bridge

Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Deck Slab (Primary)	Cracking		Many cracks with width less than 0.3mm are observed on deck slab.
	Scaling/Spalling		Several small spallings are observed on the deck slab.
	Water leaking		Some portion of deck slab, cracks are combined with water leaking
Steel Beam/ Truss Member (Bracings, etc.) (Primary)	Corrosion		Joints and bracing members are severely corroded and main truss members are also progressing corrosion.




Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Steel Beam/ Truss Member (Bracings, etc.) (Primary)	Cracking/Fracture		Bracing members are fractured or cracking or missing due to impact of ship, especially flooring system.
	Deformation/Buckling		Many bracing members are deformed due to impact of ship.
	Loose Connection		Same bracing members are missing due to loose connection or broken by impact of ship.
	Paint Peel off		Paint of steel truss members are progressing peel off entirely.

Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Shoe/Bearing	Corrosion		Steel bearings, especially base plate and connection to truss members are severely corroded.
	Displacement		Slightly displacement of steel bearing is observed horizontally.
Abutments	Spalling, Scaling,Disintegration		Many spillings or scalings are observed on abutment.
	Cracking concrete		Many cracks with width less than 1mm are observed vertically and horizontally.

Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Piers	Spalling, Scaling,Disintegration		Large spillings/ disintegrations are observed on pier and degrade of concrete strength is predicted.
	Cracking concrete		Same cracks with width more than 1mm are observed vertically but crack is a little crack entirely.

## Bridge Profile



## Main Features of the Bridge





## 6) Nagtahan Bridge


BRIDGE SEISMIC INVENTORY DATA										
<b>A. GENERAL</b>										
(1) Bridge Name:	<i>Nagtahan Bridge</i>					(2) Posted Load Limit				tons
(3) Location:	km.:		Route:	<i>Nagtahan St.</i>			Prov./ City	<i>Sta. Mesa. Manila</i>		
(4) Crossing Condition:	<input checked="" type="radio"/> Crossing River, ( <input type="radio"/> Railway, ( <input type="radio"/> Roadway, ( <input type="radio"/> Valley, ( <input type="radio"/> Others ( ) )									
(5) AADT:		(6) Detour Distance:		(7) Essential Bridge?	Yes( ) No( )					
(8) Alignment:	Straight , Curved, (Radius) _____ m <input checked="" type="radio"/> Skewed, <i>11°</i>									
(9) No. of Spans:	<b>3</b>	(10) Span Lengths	<i>45.60+57.73+45.60</i>			(11) Total Length:	<b>148.93</b>			
(12) Left Sidewalk Width:	<b>1</b>	(13) Carriageway Width:	<i>11.1+11.1</i>		(14) Right Sidewalk Width:	<b>1</b>				
(15) Overall Width (including sidewalk):	<b>24.7</b>					(16) Year Built:	<b>1966</b>			
(17) As-builts or design drawings available?					Yes	<input checked="" type="radio"/> No				
(18) Design calculations available?					Yes	<input checked="" type="radio"/> No				
(19) Structure hydraulically adequate?					<input checked="" type="radio"/> Yes	No	Don't know ( )			
(21) Seismically Retrofitted?					<input checked="" type="radio"/> Yes	No	Description			
<b>B. SUPERSTRUCTURE</b>										
(23) Superstructure Type:	<input checked="" type="radio"/> Steel Truss, <input type="radio"/> Steel Girder, <input type="radio"/> RCDG, <input type="radio"/> PSCG, Others( )									
(24) Number of Girders/Span:	<b>10</b>			(25) Continuous?	<input checked="" type="radio"/> Yes No					
(26) Number of Expansion Joints:	<b>2</b>		(27) Type of Expansion Joints:	Steel, Rubber, Seam			<b>-</b>			
<b>C. BEARINGS</b>										
(28) Bearing Type:	Roller, Rocker, Rubber, <input checked="" type="radio"/> Others ( Steel )				Condition:	Functioning( ) Not Functioning ( )				
(29) Type of Restraint (Transverse):	<b>Concrete Block</b>			(30) Type of Restraint (Longitudinal):						
(31) Seating Length (Longi, Trans) :	Abutments:	<b>1.0, 1.0</b>		Piers:		Hinges:				
<b>D. ABUTMENTS</b>										
(32) Type:	<b>Wall</b>				(33) Height:					
(34) Foundation Type:	<input checked="" type="radio"/> Spread Footing, <input type="radio"/> On Piles, Others (RCP)				(35) Wingwall Lengths	L:		R:		










<b>E. COLUMNS AND PIERS</b>			
(36) Column Type:	<i>Wall</i>		
(37) Min. Transverse Cross-Section Dimension:		(38) Min. Longitudinal Cross-Section Dimension	
(39) Height Range:		(40) Fixity:	Top      Bottom      Both
(41) Percentage of Longitudinal Reinforcement:			
(42) Transverse Reinforcements:	Bar Size:	Spacing:	Tied      Spiral
(43) Foundation Type:	Spread Footing	On Piles	Others (      )

<b>F. SITE</b>			
(44) Estimated Peak Ground Acceleration (0.4-0.7g):			
(45) Soil Profile Type:	I	II	<u>III</u> IV      Don't Know
(46) Liquefaction Potential:	<u>Yes</u>	No	Don't Know (      )
(47) Boring Data Available:	<u>Yes</u>	No	





<b>G. OTHER ITEMS</b>			
(48) Approach Slab: Yes (      ) Length		(47) Embankment Side-slope type (Approach Road):	(H:V):
(49) Slope Bank Protection Type:			

PHOTOGRAPHS / SKETCHES (Use additional sheets if necessary)











<p>1.</p> 	<p>2.</p> 
<p>3.</p> 	<p>4.</p> 
<p>5.</p> 	<p>6.</p> 
<p>7.</p> 	<p>8.</p> 
<p>9.</p> 	<p>10.</p> 

## Main Viewpoints of the Bridge



Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Deck Slab (Primary)	Cracking		Most of cracks are less than width 0.3mm but several cracks are long and more than 1mm are observed.
	Waterleaking		Waterleaking are observed at some parts of cracks at end of deck slab.
Concrete Beam/ Girder (Primary)	Cracking		Cracks with width less than 1mm are observed on half of girders.
	Spalling, Scaling, Disintegration		Spalling is observed at the connection between concrete girder and slab.



Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Concrete Beam/ Girder (Primary)	Delamination		Some delaminations are observed at the bottom of girders.
Steel Beam/ Truss Member (Bracings, etc.) (Primary)	Corrosion		After paint peel off, some parts are corroded especially gusset plates.
	Paint Peel off		Paint peel off is observed overall steel truss members.
Shoe/Bearing	Corrosion		Steel bearing is slightly corroded.

Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Pier	Cracking concrete		Several cracks with width less than 1mm are observed.
	Spalling, Scaling,Disinte gration		Some spallings are detected on pier.
	Exposure/Corro sion of Reinf.		Exposure of rebars due to scaling are observed pier wall.
Expansion Joint (Primary)	Water leaking		Water leaking from expansion joint at pier is observed.

# Bridge Profile



## Main Features of the Bridge



**7) Pandacan Bridge**

BRIDGE SEISMIC INVENTORY DATA										
<b>A. GENERAL</b>										
(1) Bridge Name:		<i>Pandacan Bridge (Nagtahan Link)</i>				(2) Posted Load Limit				tons
(3) Location:		km.:	Route:		<i>PACO-STA. MESA Road</i>		Prov./ City		<i>Pandacan</i>	
(4) Crossing Condition:		<input checked="" type="radio"/> Crossing River, ( ) Railway, ( ) Roadway, ( ) Valley, ( ) Others ( )								
(5) AADT:		(6) Detour Distance:		(7) Essential Bridge?		Yes( ) No( )				
(8) Alignment:		<input checked="" type="radio"/> Straight, <input type="radio"/> Curved, (Radius) _____ m <input type="radio"/> Skewed, (Skew Angle) °								
(9) No. of Spans:		<b>5</b>		(10) Span Lengths		<b>2 3.80+25.00+46.00+25.10+27.50</b>		(11) Total Length:		<b>147.4</b>
(12) Left Sidewalk Width:		<b>1.2</b>		(13) Carriageway Width:		<b>6.5+6.5</b>		(14) Right Sidewalk Width:		<b>1.2</b>
(15) Overall Width (including sidewalk):		<b>16.6</b>				(16) Year Built:		<b>1997</b>		
(17) As-builts or design drawings available?				<input checked="" type="radio"/> Yes <input type="radio"/> No						
(18) Design calculations available?				<input checked="" type="radio"/> Yes <input type="radio"/> No						
(19) Structure hydraulically adequate?				<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> Don't know ( )						
(21) Seismically Retrofitted?				Yes <input checked="" type="radio"/> No <input type="radio"/> Description						
<b>B. SUPERSTRUCTURE</b>										
(23) Superstructure Type:		Steel Truss, Steel Girder, RCDG, <input checked="" type="radio"/> PSCG, Others( )								
(24) Number of Girders/Span:		<b>6</b>		(25) Continuous?		Yes <input type="radio"/> No <input checked="" type="radio"/>				
(26) Number of Expansion Joints:				(27) Type of Expansion Joints:		Steel, Rubber, Seam		-		
<b>C. BEARINGS</b>										
(28) Bearing Type:		Roller, Rocker, Rubber, Others ( )				Condition:		Functioning( ) Not Functioning ( )		
(29) Type of Restraint (Transverse):				(30) Type of Restraint (Longitudinal):						
(31) Seating Length :		Abutments:		Piers:		Hinges:		-		
<b>D. ABUTMENTS</b>										
(32) Type:		<b>Column Bent with Diaphragm Wall</b>				(33) Height:				
(34) Foundation Type:		Spread Footing, On Piles, Others (RCP)				(35) Wingwall Lengths		L: R:		



**E. COLUMNS AND PIERS**

(36) Column Type:	<i>Column Bent</i>		
(37) Min. Transverse Cross-Section Dimension:		(38) Min. Longitudinal Cross-Section Dimension	
(39) Height Range:		(40) Fixity:	Top      Bottom      Both
(41) Percentage of Longitudinal Reinforcement:			
(42) Transverse Reinforcements:	Bar Size:	Spacing:	Tied      Spiral
(43) Foundation Type:	Spread Footing	On Piles	Others (      )

**F. SITE**










(44) Estimated Peak Ground Acceleration (0.4-0.7g):			
(45) Soil Profile Type:	I	II	III      IV      Don't Know
(46) Liquefaction Potential:	Yes	No	Don't Know (      )
(47) Boring Data Available:	Yes	No	

**G. OTHER ITEMS**





(48) Approach Slab: Yes (      ) Length		(47) Embankment Side-slope type (Approach Road):	(H:V):
(49) Slope Bank Protection Type:			




PHOTOGRAPHS / SKETCHES (Use additional sheets if necessary)







<p>1.</p> 	<p>2.</p> 
<p>3.</p> 	<p>4.</p> 
<p>5.</p> 	<p>6.</p> 
<p>7.</p> 	<p>8.</p> 
<p>9.</p>  <p>NAGTCHAN LINK  CTA LIMIT 4: 250  LOAD LIMIT 1055</p>	<p>10. no load limit id</p>

## Main Viewpoints of the Bridge


Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Deck Slab (Primary)	Cracking		Most of cracks are less than width 0.3mm but several cracks are long and more than 1mm are observed.
	Scaling/Spalling		A few spallings are observed on deck slab.
	Water leaking		At some parts of cracks, water leaking are observed
Concrete Beam/ Girder (Primary)	Cracking		A few Cracks with width less than 0.3mm are observed.

Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Concrete Beam/ Girder (Primary)	Exposure/Corrosion of Rebars		Exposure/Corrosion of Rebars caused by unskilled workmanship is observed.
Abutments	Cracking concrete		Many cracks are observed horizontally and vertically on abutment.
	Exposure/Corrosion of Reinf.		A few Exposure/Corrosion of Rebar is observed on piers
Pier	Spalling, Scaling, Disintegration		Several spillings are observed on piers.



Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Pier	Cracking concrete		Shear crack is observed on pier wall.
	Exposure/Corro sion of Reinf.		Exposure/Corrosion of Rebars due to impact of ship is detected at pile cap.
Expansion Joint (Primary)	Waterleaking		Waterleaking is observed at expansion joints.
	Difference in elevation		Difference in elevation is occurred between bridge and approach slab.

### Bridge Profile



### Main Features of the Bridge



### 8) Lambingan Bridge

BRIDGE SEISMIC INVENTORY DATA										
<b>A. GENERAL</b>										
(1) Bridge Name:	<i>Lambingan Bridge</i>					(2) Posted Load Limit	<i>15</i>	tons		
(3) Location:	km.:		Route:	<i>New Panaderos St.</i>			Prov./ City	<i>Manila</i>		
(4) Crossing Condition:		<input checked="" type="radio"/> Crossing River, ( ) Railway, ( ) Roadway, ( ) Valley, ( ) Others ( )								
(5) AADT:		(6) Detour Distance:		(7) Essential Bridge?	Yes ( ) No ( )					
(8) Alignment:		<input checked="" type="radio"/> Straight, Curved, (Radius) _____ m		Skewed, (Skew Angle) °						
(9) No. of Spans:	<i>3</i>	(10) Span Lengths	<i>18.50+61.10+18.50</i>			(11) Total Length:	<i>98.1</i>			
(12) Left Sidewalk Width:	<i>1.5</i>	(13) Carriageway Width:	<i>10.0+10.0</i>		(14) Right Sidewalk Width:	<i>1.5</i>				
(15) Overall Width (including sidewalk):			<i>24</i>			(16) Year Built:	<i>1979</i>			
(17) As-builts or design drawings available?				Yes <input type="radio"/> No <input checked="" type="radio"/>						
(18) Design calculations available?				<input checked="" type="radio"/> Yes <input type="radio"/> No						
(19) Structure hydraulically adequate?				<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> Don't know ( )						
(21) Seismically Retrofitted?				Yes <input type="radio"/> No <input checked="" type="radio"/> Description						
<b>B. SUPERSTRUCTURE</b>										
(23) Superstructure Type:		Steel Truss, Steel Girder, RCDG, <input checked="" type="radio"/> PSCG(Gerber), Others ( )								
(24) Number of Girders/Span:		<i>12</i>	(25) Continuous?		Yes <input type="radio"/> No <input checked="" type="radio"/>					
(26) Number of Expansion Joints:			(27) Type of Expansion Joints:		Steel, Rubber, Seam			<i>-</i>		
<b>C. BEARINGS</b>										
(28) Bearing Type:		Roller, Rocker, <input checked="" type="radio"/> Rubber, Others ( )			Condition: Functioning ( ) Not Functioning ( )					
(29) Type of Restraint (Transverse):			(30) Type of Restraint (Longitudinal):							
(31) Seating Length :		Abutments:	<i>0.85</i>	Piers:		Hinges:	<i>0.5</i>			
<b>D. ABUTMENTS</b>										
(32) Type:		<i>Wall</i>			(33) Height:		<i>4.83</i>			
(34) Foundation Type:		Spread Footing, On Piles, Others (RCP)			(35) Wingwall Lengths		L:		R:	

<b>E. COLUMNS AND PIERS</b>			
(36) Column Type:	<i>Wall</i>		
(37) Min. Transverse Cross-Section Dimension:		(38) Min. Longitudinal Cross-Section Dimension	
(39) Height Range:		(40) Fixity:	Top      Bottom      Both
(41) Percentage of Longitudinal Reinforcement:			
(42) Transverse Reinforcements:	Bar Size:	Spacing:	Tied      Spiral
(43) Foundation Type:	Spread Footing	On Piles	Others (      )

<b>F. SITE</b>					
(44) Estimated Peak Ground Accelaration (0.4-0.7g):					
(45) Soil Profile Type:	I	II	<b>III</b>	IV	Don't Know
(46) Liquefaction Potential:	<b>Yes</b>	No	Don't Know (      )		
(47) Boring Data Available:	<b>Yes</b>	No			





<b>G. OTHER ITEMS</b>			
(48) Approach Slab: Yes (      ) Length		(47) Embankment Side-slope type(Approach Road):	(H:V):
(49) Slope Bank Protection Type:			




PHOTOGRAPHS / SKETCHES (Use additional sheets if necessary)










## Main Viewpoints of the Bridge

Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Deck Slab (Primary)	Cracking		<p>Cracks on deck slab of PC girder are mostly observed on bottom side.</p> <p>Cracks are not serious but developing on entire deck slab.</p>
	Water leaking		<p>At some parts of cracks, water leaking are observed in transverse direction.</p>
Concrete Beam/ Girder (Primary)	Cracking concrete		<p>Many cracks are observed on the outside girder. Especially, On the all hinge portion, shear cracks are observed that are considered to be fatal cracks</p>
	Spalling, Scaling,Disinte gration		<p>A few spallings caused by collision by ship are observed. The damage is serious.</p>

Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Concrete Beam/ Girder (Primary)	Honeycomb		A few honeycombs caused by unskilled workmanship are observed.
Abutments	Spalling, Scaling,Disi ntegration		A few spillings are observed at shear key block.
	Cracking concrete		Many vertical clacks are observed near the joint between wing wall and retaining wall.
Pier	Spalling, Scaling,Disi ntegration		Scaling on surface of concrete is scraped due to ship.

Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Pier	Cracking concrete		Many cracks with less than 0.3mm observed horizontally and vertically.
Curb and Railing (Secondary)	Cracking/Corrosion		Severe corrosion is occurred on steel railing.
Expansion Joint (Primary)	Water leaking		Water leaking is observed at all expansion of hinge joints.
	Difference in elevation		Difference in elevation is observed between girders and approach slab.

Bridge Profile



Main Features of the Bridge





**9) Makati Mandaluyong Bridge**


BRIDGE SEISMIC INVENTORY DATA										
<b>A. GENERAL</b>										
(1) Bridge Name:		<i>Makati-Mandaluyong Bridge</i>				(2) Posted Load Limit				tons
(3) Location:		km.:	Route:		<i>Burgos St.</i>		Prov./ City	<i>Makati City</i>		
(4) Crossing Condition:		<input checked="" type="radio"/> Crossing River, ( ) Railway, ( ) Roadway, ( ) Valley, ( ) Others ( )								
(5) AADT:		(6) Detour Distance:		(7) Essential Bridge?		Yes ( ) No ( )				
(8) Alignment:		<input checked="" type="radio"/> Straight, <input type="radio"/> Curved, (Radius) _____ m <input type="radio"/> Skewed, (Skew Angle) <sup>o</sup>								
(9) No. of Spans:		<b>3</b>		(10) Span Lengths		<b>30.0+50.0+30.0</b>		(11) Total Length:		<b>110</b>
(12) Left Sidewalk Width:		<b>1.5</b>		(13) Carriageway Width:		<b>7.4+7.4</b>		(14) Right Sidewalk Width:		<b>1.5</b>
(15) Overall Width (including sidewalk):		<b>18.8</b>				(16) Year Built:		<b>1986</b>		
(17) As-builts or design drawings available?				<input checked="" type="radio"/> Yes		No				
(18) Design calculations available?				<input checked="" type="radio"/> Yes		No				
(19) Structure hydraulically adequate?				<input checked="" type="radio"/> Yes		No		Don't know ( )		
(21) Seismically Retrofitted?				Yes		<input checked="" type="radio"/> No		Description		
<b>B. SUPERSTRUCTURE</b>										
(23) Superstructure Type:		Steel Truss, Steel Girder, RCDG, <input checked="" type="radio"/> PSCG (Gerber), Others ( )								
(24) Number of Girders/Span:		<b>9 (Center)</b>		(25) Continuous?		Yes <input checked="" type="radio"/> No				
(26) Number of Expansion Joints:		<b>4</b>		(27) Type of Expansion Joints:		<input checked="" type="radio"/> Steel,		Rubber, Seam		<i>finger</i>
<b>C. BEARINGS</b>										
(28) Bearing Type:		Roller, Rocker, Rubber, <input checked="" type="radio"/> Others ( Steel )			Condition:		Functioning ( )			Not Functioning ( )
(29) Type of Restraint (Transverse):				(30) Type of Restraint (Longitudinal):						
(31) Seating Length :		Abutments:		Piers:		Hinges:		<b>0.8</b>		
<b>D. ABUTMENTS</b>										
(32) Type:		<b>Column Bent with Diaphragm Wall</b>				(33) Height:				
(34) Foundation Type:		Spread Footing, On Piles, Others (RCP)				(35) Wingwall Lengths		L:		R:










<b>E. COLUMNS AND PIERS</b>			
(36) Column Type:	<i>Column Bent</i>		
(37) Min. Transverse Cross-Section Dimension:		(38) Min. Longitudinal Cross-Section Dimension	
(39) Height Range:		(40) Fixity:	Top      Bottom      Both
(41) Percentage of Longitudinal Reinforcement:			
(42) Transverse Reinforcements:	Bar Size:	Spacing:	Tied      Spiral
(43) Foundation Type:	Spread Footing	On Piles	Others (      )

<b>F. SITE</b>			
(44) Estimated Peak Ground Acceleration (0.4-0.7g):			
(45) Soil Profile Type:	I	II	III      IV      Don't Know
(46) Liquefaction Potential:	Yes	No	Don't Know (      )
(47) Boring Data Available:	Yes	No	





<b>G. OTHER ITEMS</b>			
(48) Approach Slab: Yes (      ) Length		(47) Embankment Side-slope type (Approach Road):	(H:V):
(49) Slope Bank Protection Type:			

PHOTOGRAPHS / SKETCHES (Use additional sheets if necessary)











<p>1.</p> 	<p>2.</p> 
<p>3.</p> 	<p>4.</p> 
<p>5.</p> 	<p>6.</p> 
<p>7.</p> 	<p>8.</p> 
<p>9.</p> 	<p>10. no load limit id</p>

## Main Viewpoints of the Bridge



Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Deck Slab (Primary)	Cracking		Cracks with width less than 1mm are entirely observed on bottom deck slab.
Concrete Beam/ Girder (Primary)	Cracking concrete		Many cracks on concrete surface of both sides of box girder are observed. Especially at the end box girders cracks are severely developed.
	Exposure/Corrosion of Rebars		A few exposure/Corrosion of rebar is observed due to delamination.
	Spalling, Scaling,Disintegration		A few small spillings are observed on bottom of box girder.



Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Concrete Beam/ Girder (Primary)	Honeycomb		Several honeycombs caused by unskilled workmanship are observed.
Shoe Bearing (Primary)	Corrosion		Steel bearing plates are severely corroded by waterleaking from expansion joint.
	Abnormal Displacement		Steel bearings located at curved section are displaced outward.
	Bulging/Rupture		Rubber bearing pads are bulging and gaps are caused at expansion joints. The rubber pads are not recognized but bearing height (space) is shorting toward outside.

Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Abutments	Cracking concrete		Several cracks are observed on abutment.
Pier	Spalling, Scaling,Disinte gration		Spalling and scaling caused by ship are observed on piers in the river.
	Cracking concrete		Many cracks with less than 0.3mm are observed but covered by painting.
	Exposure/Corr osion of Reinf.		A few Exposure/Corrosion of Rebars are observed on piers, which caused by ship.

Bridge Profile



Main Features of the Bridge



### 10) Guadalupe Bridge

BRIDGE SEISMIC INVENTORY DATA										
<b>A. GENERAL</b>										
(1) Bridge Name:	<i>Guadalupe Bridge (Central)</i>					(2) Posted Load Limit		tons		
(3) Location:	km.:		Route:	<i>EDSA</i>			Prov./ City	<i>Makati City / Mandaluyong City</i>		
(4) Crossing Condition:	<input checked="" type="radio"/> Crossing River, <input type="radio"/> Railway, <input type="radio"/> Roadway, <input type="radio"/> Valley, <input type="radio"/> Others ( )									
(5) AADT:		(6) Detour Distance:		(7) Essential Bridge?	Yes( ) No( )					
(8) Alignment:	<input checked="" type="radio"/> Straight, <input type="radio"/> Curved, (Radius) _____ m Skewed, (Skew Angle) <sup>o</sup>									
(9) No. of Spans:	<b>3</b>	(10) Span Lengths	<b>35.7+42.8+35.94</b>			(11) Total Length:	<b>144.44</b>			
(12) Left Sidewalk Width:	<b>—</b>	(13) Carriageway Width:	<b>12.3+12.5</b>			(14) Right Sidewalk Width:	<b>—</b>			
(15) Overall Width (including sidewalk):	<b>25.4</b>					(16) Year Built:	<b>1962</b>			
(17) As-builts or design drawings available?					Yes	<input checked="" type="radio"/> No				
(18) Design calculations available?					Yes	<input checked="" type="radio"/> No				
(19) Structure hydraulically adequate?					<input checked="" type="radio"/> Yes	No	Don't know ( )			
(21) Seismically Retrofitted?					Yes	<input checked="" type="radio"/> No Description				
<b>B. SUPERSTRUCTURE</b>										
(23) Superstructure Type:	<input checked="" type="radio"/> Steel Truss, <input type="radio"/> Steel Girder, <input type="radio"/> RCDG, <input type="radio"/> PSCG, Others( )									
(24) Number of Girders/Span:	<b>10 / 3</b>			(25) Continuous?	<input checked="" type="radio"/> Yes No					
(26) Number of Expansion Joints:	<b>2</b>		(27) Type of Expansion Joints:	<input checked="" type="radio"/> Steel, <input type="radio"/> Rubber, <input type="radio"/> Seam						
<b>C. BEARINGS</b>										
(28) Bearing Type:	Roller, Rocker, Rubber, Others ( )				Condition:	Functioning( ) Not Functioning ( )				
(29) Type of Restraint (Transverse):				(30) Type of Restraint (Longitudinal):						
(31) Seating Length :	Abutments:		Piers:		Hinges:	<b>—</b>				
<b>D. ABUTMENTS</b>										
(32) Type:	<b>Wall Type</b>				(33) Height:					
(34) Foundation Type:	Spread Footing, On Piles, Others (RCP)			(35) Wingwall Lengths	L:		R:			













<b>E. COLUMNS AND PIERS</b>			
(36) Column Type:	<i>Wall Type</i>		
(37) Min. Transverse Cross-Section Dimension:		(38) Min. Longitudinal Cross-Section Dimension	
(39) Height Range:		(40) Fixity:	Top      Bottom      Both
(41) Percentage of Longitudinal Reinforcement:			
(42) Transverse Reinforcements:	Bar Size:	Spacing:	Tied      Spiral
(43) Foundation Type:	Spread Footing	On Piles	Others (      )

<b>F. SITE</b>			
(44) Estimated Peak Ground Acceleration (0.4-0.7g):			
(45) Soil Profile Type:	I	II	III      IV      Don't Know
(46) Liquefaction Potential:	Yes	No	Don't Know (      )
(47) Boring Data Available:	Yes	No	





<b>G. OTHER ITEMS</b>			
(48) Approach Slab: Yes (      ) Length		(47) Embankment Side-slope type (Approach Road):	(H:V):
(49) Slope Bank Protection Type:			





PHOTOGRAPHS / SKETCHES (Use additional sheets if necessary)







<p>1.</p> 	<p>2.</p> 
<p>3.</p> 	<p>4. no access</p>
<p>5.</p> 	<p>6.</p> 
<p>7.</p> 	<p>8.</p> 
<p>9.</p> 	<p>10.</p> 





## Main Viewpoints of the Bridge




Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Deck Slab (Primary)	Cracking		Cracks on deck slab of PC girder are mostly observed on bottom side.
	Water leaking		At some parts of cracks, water leaking are observed.
Concrete Beam/ Girder (Primary)	Cracking		Many cracks are observed on the outside girder. Especially, On the all hinge portion, shear cracks are observed that are considered to be fatal cracks
	Delamination		A few delaminations are observed on bottom of girders.

Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Steel Beam/ Truss Member (Bracings, etc.) (Primary)	Loose Connection		A few missing steel bracings are observed.
	Paint Peel off		Paints of Steel truss bridge is quite good condition but paint peel off is observed at some places.
Abutments	Delamination		A few delaminations are observed on abutment.
	Cracking concrete		A few cracks are observed on abutment.




Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Piers	Spalling, Scaling,Disinte gration		Many spillings and scaling due to impact of ships are observed.
	Cracking concrete		Cracks are occurred on wall concrete between rectangular piles
	Exposure/Corro sion of Reinf.		Many exposure /corrosion of rebars due to impact of ships are observed.
Curb and Railing (Secondary)	Cracking		Cracks on railing are observed.

Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Curb and Railing (Secondary)	Spalling/Delamination		Several spalling and delamination are observed.
Expansion Joint	Water leaking		Water leaking is observed at all expansion of hinge joints.
	Abnormal Space/Noise		Normal spaces are occurred on expansion joint at all hinge joints, because of deflection of center girders.
Painting Cond. (Primary)	Discoloration		Discoloration is entirely progressing.

Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Slope Protection (Secondary)	Cracks		Many cracks are occurred on concrete facing slope.
Approach Road	Cracking		Many asphalt cracks are observed.
River Condition (Secondary)	Others		River course is slightly bent so ships are often hit pier body. Strong protects are necessary.

Bridge Profile



Main Features of the Bridge





### 11) C-5 Bridge


BRIDGE SEISMIC INVENTORY DATA										
<b>A. GENERAL</b>										
(1) Bridge Name:	<i>C-5 Bridge (Makati-Pasig Bridge)</i>					(2) Posted Load Limit		tons		
(3) Location:	km.:		Route:	<i>C-5</i>			Prov./ City	<i>Pasig City</i>		
(4) Crossing Condition:	<input checked="" type="checkbox"/> Crossing River, ( ) Railway, ( ) Roadway, ( ) Valley, ( ) Others ( )									
(5) AADT:		(6) Detour Distance:		(7) Essential Bridge?	Yes ( ) No ( )					
(8) Alignment:	<input checked="" type="checkbox"/> Straight, <input type="checkbox"/> Curved, (Radius) _____ m <input type="checkbox"/> Skewed, (Skew Angle) °									
(9) No. of Spans:	<i>10</i>	(10) Span Lengths	<i>24.85+24.95+25.12+25.00+24.85 +45.88+22.21+26.95+26.70+26.45</i>			(11) Total Length:	<i>272.96</i>			
(12) Left Sidewalk Width:	<i>2</i>	(13) Carriageway Width:	<i>11.25+11.25</i>		(14) Right Sidewalk Width:	<i>2</i>				
(15) Overall Width (including sidewalk):	<i>27.7</i>					(16) Year Built:	<i>1998</i>			
(17) As-builts or design drawings available?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No									
(18) Design calculations available?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No									
(19) Structure hydraulically adequate?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Don't know ( )									
(21) Seismically Retrofitted?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No				Description (Seismic Design is applied)					
<b>B. SUPERSTRUCTURE</b>										
(23) Superstructure Type:	Steel Truss, Steel Girder, RCDG, <input checked="" type="checkbox"/> PSCG, Others ( )									
(24) Number of Girders/Span:	<i>12 / 10</i>			(25) Continuous?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No					
(26) Number of Expansion Joints:	<i>8</i>		(27) Type of Expansion Joints:	<input checked="" type="checkbox"/> Steel, <input type="checkbox"/> Rubber, <input type="checkbox"/> Seam						
<b>C. BEARINGS</b>										
(28) Bearing Type:	Roller, Rocker, <input checked="" type="checkbox"/> Rubber, Others ( )				Condition:	<input checked="" type="checkbox"/> Functioning ( ) <input type="checkbox"/> Not Functioning ( )				
(29) Type of Restraint (Transverse):				(30) Type of Restraint (Longitudinal):						
(31) Seating Length :	Abutments:		Piers:		Hinges:	<i>—</i>				
<b>D. ABUTMENTS</b>										
(32) Type:	<i>Wall Type</i>					(33) Height:				
(34) Foundation Type:	Spread Footing, On Piles, <input checked="" type="checkbox"/> Others (Bored Pile)			(35) Wingwall Lengths	L:	<i>3.8</i>	R:			










<b>E. COLUMNS AND PIERS</b>			
(36) Column Type:	<i>Pier Pile Bent</i>		
(37) Min. Transverse Cross-Section Dimension:		(38) Min. Longitudinal Cross-Section Dimension	
(39) Height Range:		(40) Fixity:	Top      Bottom      Both
(41) Percentage of Longitudinal Reinforcement:			
(42) Transverse Reinforcements:	Bar Size:	Spacing:	Tied      Spiral
(43) Foundation Type:	Spread Footing	On Piles	Others ( <i>Bored Pile</i> )

<b>F. SITE</b>			
(44) Estimated Peak Ground Acceleration (0.4-0.7g):			
(45) Soil Profile Type:	I	II	<b>III</b> IV      Don't Know
(46) Liquefaction Potential:	<b>Yes</b>	No	Don't Know ( )
(47) Boring Data Available:	<b>Yes</b>	No	





<b>G. OTHER ITEMS</b>			
(48) Approach Slab: Yes ( ) Length		(47) Embankment Side-slope type(Approach Road):	(H:V):
(49) Slope Bank Protection Type:			

PHOTOGRAPHS / SKETCHES (Use additional sheets if necessary)











<p>1.</p> 	<p>2.</p> 
<p>3.</p> 	<p>4.</p> 
<p>5.</p> 	<p>6.</p> 
<p>7.</p> 	<p>8.</p> 
<p>9.</p> 	<p>10. no load limit id</p>

Main Viewpoints of the Bridge


Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Deck Slab (Primary)	Cracking		Crackings width less than 0.3mm is observed on some part.
	Water leaking		Cracks with water leaking are at end of slab but only one place.
Concrete Beam/ Girder (Primary)	Exposure/Corrosion of Rebars		Exposure/Corrosion of rebars is observed on flange of girder but only this place.
	Spalling, Scaling, Disintegration		Several spalling are observed on girders.



Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Concrete Beam/ Girder (Primary)	Honeycomb		Few honeycombs are observed on cross beams.
Piers (Primary)	Spalling, Scaling,Disintegration		Spalling and scaling are observed on pier concrete due to intentionally impact
	Cracking concrete		Some Cracks less than 1mm are observed on interval wall between Circular piles at several piers.
Curb and Railing (Secondary)	Cracking		Small cracks are observed on end post of railings.

Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Curb and Railing (Secondary)	Impact Damaged		One hand railing is damaged due to impact of car.
Expansion Joint (Primary)	Water leaking		Water leaking from expansion joint is observed.
	Abnormal Space/Noise		Abnormal space is occurred which should be covered.
	Displacement		Covers of expansion joint are displaced. It is caused by water leaking.

### Bridge Profile



### Main Features of the Bridge



## 12) Bambang Bridge

BRIDGE SEISMIC INVENTORY DATA										
<b>A. GENERAL</b>										
(1) Bridge Name:	<i>Bambang Bridge</i>					(2) Posted Load Limit		tons		
(3) Location:	km.:		Route:	<i>A.Luna</i>			Prov./ City	<i>Pasig City</i>		
(4) Crossing Condition:		<input checked="" type="radio"/> Crossing River, ( ) Railway, ( ) Roadway, ( ) Valley, ( ) Others ( )								
(5) AADT:		(6) Detour Distance:		(7) Essential Bridge?	Yes ( ) No ( )					
(8) Alignment:		<input checked="" type="radio"/> Straight, <input type="radio"/> Curved, (Radius) _____ m <input type="radio"/> Skewed, (Skew Angle) <sup>o</sup>								
(9) No. of Spans:	<b>9</b>	(10) Span Lengths	<i>( 12.0+11.65+11.7)+(25.9+40.19 +25.93)+(12.15+11.95+11.85)</i>			(11) Total Length:	<b>163.32</b>			
(12) Left Sidewalk Width:	<b>1.5</b>	(13) Carriageway Width:	<b>3.4+3.4</b>			(14) Right Sidewalk Width:	<b>1.5</b>			
(15) Overall Width (including sidewalk):		<b>10.35</b>				(16) Year Built:	<b>1992</b>			
(17) As-builts or design drawings available?				<input checked="" type="radio"/> Yes <input type="radio"/> No						
(18) Design calculations available?				<input checked="" type="radio"/> Yes <input type="radio"/> No						
(19) Structure hydraulically adequate?				<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> Don't know ( )						
(21) Seismically Retrofitted?				<input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> Description (Seismic design is applied)						
<b>B. SUPERSTRUCTURE</b>										
(23) Superstructure Type:	Steel Truss, Steel Girder, RCDG, <input checked="" type="radio"/> PSCG, Others ( )									
(24) Number of Girders/Span:	<b>8 / 6, 4 / 3</b>			(25) Continuous?	Yes <input type="radio"/> No <input checked="" type="radio"/>					
(26) Number of Expansion Joints:	<b>-</b>		(27) Type of Expansion Joints:	Steel, Rubber, Seam			<b>-</b>			
<b>C. BEARINGS</b>										
(28) Bearing Type:	Roller, Rocker, <input checked="" type="radio"/> Rubber, Others ( )				Condition:	<input checked="" type="radio"/> Functioning ( ) <input type="radio"/> Not Functioning ( )				
(29) Type of Restraint (Transverse):	<b>-</b>			(30) Type of Restraint (Longitudinal):	<b>-</b>					
(31) Seating Length (Longitudinal):	Abutments:	<b>0.6</b>		Piers:			Hinges:			
<b>D. ABUTMENTS</b>										
(32) Type:	<b>Wall Type</b>				(33) Height:	<b>1</b>				
(34) Foundation Type:	Spread Footing, <input checked="" type="radio"/> On Piles, Others (RCP)			(35) Wingwall Lengths	L:		R:			




<b>E. COLUMNS AND PIERS</b>			
(36) Column Type:	<i>Column Type</i>		
(37) Min. Transverse Cross-Section Dimension:		(38) Min. Longitudinal Cross-Section Dimension	
(39) Height Range:		(40) Fixity:	Top      Bottom      Both
(41) Percentage of Longitudinal Reinforcement:			
(42) Transverse Reinforcements:	Bar Size:	Spacing:	Tied      Spiral
(43) Foundation Type:	Spread Footing	<u>On Piles</u>	Others (      )

<b>F. SITE</b>			
(44) Estimated Peak Ground Acceleration (0.4-0.7g):			
(45) Soil Profile Type:	I	II	<u>III</u> IV      Don't Know
(46) Liquefaction Potential:	<u>Yes</u>	No	Don't Know (      )
(47) Boring Data Available:	<u>Yes</u>	No	





<b>G. OTHER ITEMS</b>			
(48) Approach Slab: Yes (      ) Length		(47) Embankment Side-slope type(Approach Road):	(H:V):
(49) Slope Bank Protection Type:			

PHOTOGRAPHS / SKETCHES (Use additional sheets if necessary)






Main Viewpoints of the Bridge

Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Deck Slab (Primary)	Cracking		Cracking width about 1mm on slab is covered with 30%.
	Scaling/Spalling		Scaling on the deck slab is observed entirely but its condition is not bad.
Concrete Beam/ Girder (Primary)	Exposure/Corrosion of Rebars		Few Exposure/Corrosion of rebars are observed on concrete girders.
	Spalling, Scaling, Disintegration		Few spalling and scaling are observed on concrete girders.

Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Concrete Beam/ Girder (Primary)	Delamination		One Delamination is observed on concrete girder.
Abutments	Spalling, Scaling,Disintegration		Several Spallings and disintegration are observed on abutment.
	Cracking concrete		Cracks on side of pile bent abutment are appeared.
Slope Protection (Secondary)	Erosion		Slope protection on A1 abutment is heavily damaged.



### Bridge Profile



### Main Features of the Bridge



### 13) Vargas Bridge (Upstream)

BRIDGE SEISMIC INVENTORY DATA										
<b>A. GENERAL</b>										
(1) Bridge Name:	<i>Vargas Bridge (Upstream)</i>					(2) Posted Load Limit	<i>20</i>	tons		
(3) Location:	km.:	Route:	<i>Pasig Boulevard Extension</i>			Prov./ City	<i>Pasig City</i>			
(4) Crossing Condition:	<input checked="" type="radio"/> Crossing River, ( ) Railway, ( ) Roadway, ( ) Valley, ( ) Others ( )									
(5) AADT:		(6) Detour Distance:		(7) Essential Bridge?	Yes ( ) No ( )					
(8) Alignment:	<input checked="" type="radio"/> Straight, <input type="radio"/> Curved, (Radius) _____ m <input type="radio"/> Skewed, (Skew Angle) <sup>o</sup>									
(9) No. of Spans:	<i>4</i>	(10) Span Lengths	<i>1 9.3+30.5+50.6+22.04</i>			(11) Total Length:	<i>122.44</i>			
(12) Left Sidewalk Width:	<i>0.5</i>	(13) Carriageway Width:	<i>7.32</i>	(14) Right Sidewalk Width:	<i>0.9</i>					
(15) Overall Width (including sidewalk):	<i>8.72</i>				(16) Year Built:	<i>1992</i>				
(17) As-builts or design drawings available?					<input checked="" type="radio"/> Yes	<input type="radio"/> No				
(18) Design calculations available?					Yes	<input checked="" type="radio"/> No				
(19) Structure hydraulically adequate?					<input checked="" type="radio"/> Yes	<input type="radio"/> No	Don't know ( )			
(21) Seismically Retrofitted?					<input checked="" type="radio"/> Yes	<input type="radio"/> No	Description (Seismic design is applied)			
<b>B. SUPERSTRUCTURE</b>										
(23) Superstructure Type:	Steel Truss, Steel Girder, RCDG, <input checked="" type="radio"/> PSCG, Others ( )									
(24) Number of Girders/Span:	<i>4 / 4</i>			(25) Continuous?	Yes <input checked="" type="radio"/> No					
(26) Number of Expansion Joints:	<i>5</i>	(27) Type of Expansion Joints:	<input checked="" type="radio"/> Steel, <input type="radio"/> Rubber, <input type="radio"/> Seam							
<b>C. BEARINGS</b>										
(28) Bearing Type:	Roller, Rocker, <input checked="" type="radio"/> Rubber, Others ( )				Condition:	Functioning ( ) Not Functioning ( )				
(29) Type of Restraint (Transverse):	<i>Concrete Block</i>			(30) Type of Restraint (Longitudinal):	<i>(missing)</i>					
(31) Seating Length :	Abutments:		Piers:		Hinges:	<i>0.8</i>				
<b>D. ABUTMENTS</b>										
(32) Type:	<i>Wall Type</i>				(33) Height:					
(34) Foundation Type:	Spread Footing, On Piles, <input checked="" type="radio"/> Others (Steel Pipe Pile)			(35) Wingwall Lengths	L:		R:			










<b>E. COLUMNS AND PIERS</b>			
(36) Column Type:	<i>Column Type</i>		
(37) Min. Transverse Cross-Section Dimension:		(38) Min. Longitudinal Cross-Section Dimension	
(39) Height Range:		(40) Fixity:	Top      Bottom      Both
(41) Percentage of Longitudinal Reinforcement:			
(42) Transverse Reinforcements:	Bar Size:	Spacing:	Tied      Spiral
(43) Foundation Type:	Spread Footing	On Piles	<u>Others (Steel Pipe Pile)</u>

<b>F. SITE</b>			
(44) Estimated Peak Ground Acceleration (0.4-0.7g):			
(45) Soil Profile Type:	I	II	<u>III</u> IV      Don't Know
(46) Liquefaction Potential:	<u>Yes</u>	No	Don't Know ( )
(47) Boring Data Available:	<u>Yes</u>	No	

<b>G. OTHER ITEMS</b>			
(48) Approach Slab: Yes ( ) Length		(47) Embankment Side-slope type (Approach Road):	(H:V):
(49) Slope Bank Protection Type:			





PHOTOGRAPHS / SKETCHES (Use additional sheets if necessary)








<p>1.</p> 	<p>2.</p> 
<p>3.</p> 	<p>4.</p> 
<p>5.</p> 	<p>6.</p> 
<p>7.</p> 	<p>8.</p> 
<p>9. no bridge id</p>	<p>10.</p> 




Main Viewpoints of the Bridge

Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Deck Slab (Primary)	Cracking		Small cracks are visible but deck slab is good condition.
	Scaling/Spalling		Small spillings are visible but deck slab is good condition.
Abutment	Cracking concrete		A few Cracks with width less than 0.3mm are observed
Pier	Cracking concrete		Some vertical cracks are visible but maintain good condition.

Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Pier	Exposure/Corrosion of Reinf.		Only one Exposure/Corrosion of Rebars is observed at pile cap.
Expansion Joint (Primary)	Water leaking		Water leaking from expansion joint is observed.
Slope Protection	Material Loss		Slope protection is maintained properly but material losses are observed.
Approach Road	Settlement		Many pot-holes are observed on approach road.

Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
River Condition	Scouring		A few local scouring around piers is observed.

## Bridge Profile



## Main Features of the Bridge





**14) Vargas Bridge (Downstream)**

BRIDGE SEISMIC INVENTORY DATA										
<b>A. GENERAL</b>										
(1) Bridge Name:		<i>Vargas Bridge (Downstream)</i>				(2) Posted Load Limit				tons
(3) Location:		km.:	Route:		<i>Pasig Boulevard Extension</i>		Prov./ City	<i>Pasig City</i>		
(4) Crossing Condition:		<input checked="" type="radio"/> Crossing River,( ) Railway,( ) Roadway,( ) Valley,( ) Others ( )								
(5) AADT:		(6) Detour Distance:		(7) Essential Bridge?		Yes( ) No( )				
(8) Alignment:		<input checked="" type="radio"/> Straight, <input type="radio"/> Curved, (Radius) _____m <input type="radio"/> Skewed, (Skew Angle) <sup>o</sup>								
(9) No. of Spans:		<b>4</b>		(10) Span Lengths		<b>30.62+30.83+50.70+30.65</b>		(11) Total Length:		<b>142.8</b>
(12) Left Sidewalk Width:		<b>0.75</b>		(13) Carriageway Width:		<b>7.4</b>		(14) Right Sidewalk Width:		<b>0.75</b>
(15) Overall Width (including sidewalk):		<b>8.9</b>				(16) Year Built:		<b>1973</b>		
(17) As-builts or design drawings available?					Yes <input type="radio"/> No <input checked="" type="radio"/>					
(18) Design calculations available?					Yes <input type="radio"/> No <input checked="" type="radio"/>					
(19) Structure hydraulically adequate?					Yes <input checked="" type="radio"/> No <input type="radio"/> Don't know ( )					
(21) Seismically Retrofitted?					Yes <input type="radio"/> No <input checked="" type="radio"/> Description (Preventing bridge Falls are Stolen)					
<b>B. SUPERSTRUCTURE</b>										
(23) Superstructure Type:		Steel Truss, <input checked="" type="radio"/> Steel Girder, <input type="radio"/> RCDG, <input type="radio"/> PSCG, Others( )								
(24) Number of Girders/Span:		<b>3 / 4</b>		(25) Continuous?		Yes <input type="radio"/> No <input checked="" type="radio"/>				
(26) Number of Expansion Joints:		<b>5</b>		(27) Type of Expansion Joints:		<input checked="" type="radio"/> Steel, <input type="radio"/> Rubber, <input type="radio"/> Seam				
<b>C. BEARINGS</b>										
(28) Bearing Type:		Roller, Rocker, Rubber, <input checked="" type="radio"/> Others ( Slide )				Condition:		Functioning( ) Not Functioning ( )		
(29) Type of Restraint (Transverse):		<b>Concrete Block</b>		(30) Type of Restraint (Longitudinal):		<b>(missing)</b>				
(31) Seating Length :		Abutments:		Piers:		Hinges:				
<b>D. ABUTMENTS</b>										
(32) Type:		<b>Wall Type</b>				(33) Height:				
(34) Foundation Type:		Spread Footing, On Piles, <input checked="" type="radio"/> Others (PSC Pile)				(35) Wingwall Lengths		L:	R:	










<b>E. COLUMNS AND PIERS</b>			
(36) Column Type:	<i>Column Type</i>		
(37) Min. Transverse Cross-Section Dimension:		(38) Min. Longitudinal Cross-Section Dimension	
(39) Height Range:		(40) Fixity:	Top      Bottom      Both
(41) Percentage of Longitudinal Reinforcement:			
(42) Transverse Reinforcements:	Bar Size:	Spacing:	Tied      Spiral
(43) Foundation Type:	Spread Footing	On Piles	<u>Others (PSC Pile)</u>

<b>F. SITE</b>			
(44) Estimated Peak Ground Acceleration (0.4-0.7g):			
(45) Soil Profile Type:	I	II	<u>III</u> IV      Don't Know
(46) Liquefaction Potential:	<u>Yes</u>	No	Don't Know ( )
(47) Boring Data Available:	<u>Yes</u>	No	





<b>G. OTHER ITEMS</b>			
(48) Approach Slab: Yes ( ) Length		(47) Embankment Side-slope type (Approach Road):	(H:V):
(49) Slope Bank Protection Type:			

PHOTOGRAPHS / SKETCHES (Use additional sheets if necessary)






<p>1.</p> 	<p>2.</p> 
<p>3.</p> 	<p>4.</p> 
<p>5.</p> 	<p>6.</p> 
<p>7.</p> 	<p>8.</p> 
<p>9. no bridge id</p>	<p>10.</p> 


Main Viewpoints of the Bridge

Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Deck Slab (Primary)	Cracking		Cracks with width less than 1mm are observed on a half of deck slab.
	Water leaking		Water leaking are observed from the cracks with width more than 1mm.
Steel Beam/ Truss Member (Bracings, etc.) (Primary)	Corrosion		Lower flanges of steel I-girders are corroded but corrosion is limited.
	Loose Connection		Some H.T.Bolts are missing or loose connection.



Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Steel Beam/ Truss Member (Bracings, etc.) (Primary)	Paint Peel off		Paint peel off is progressing entirely steel plates.
Pier	Cracking concrete		Some cracks with width more than 1mm are observed on bottom of pile cap.
Slope Protection (Secondary)	Erosion		Slope protection is scoured by flood and approximately a half of protection is damaged.
Approach Road	others		Many pot-holes are observed on approach road.

### Bridge Profile



### Main Features of the Bridge



### 15) Rosario Bridge

BRIDGE SEISMIC INVENTORY DATA										
<b>A. GENERAL</b>										
(1) Bridge Name:	<i>Rosario Bridge</i>					(2) Posted Load Limit		tons		
(3) Location:	km.:		Route:	<i>Ortigas Ave. Extension</i>			Prov./ City	<i>Brgy. Rosario Pasig City</i>		
(4) Crossing Condition:		<input checked="" type="radio"/> Crossing River, ( ) Railway, ( ) Roadway, ( ) Valley, ( ) Others ( )								
(5) AADT:		(6) Detour Distance:		(7) Essential Bridge?	Yes ( ) No ( )					
(8) Alignment:		<input checked="" type="radio"/> Straight, <input type="radio"/> Curved, (Radius) _____ m <input type="radio"/> Skewed, (Skew Angle) <sup>o</sup>								
(9) No. of Spans:	<b>6</b>	(10) Span Lengths	<b>25.50+31.20+31.19+30.98+31.07+25.41</b>			(11) Total Length:	<b>175.35</b>			
(12) Left Sidewalk Width:		(13) Carriageway Width:		(14) Right Sidewalk Width:						
(15) Overall Width (including sidewalk):					(16) Year Built:	<b>1952 / 1978</b>				
(17) As-builts or design drawings available?				Yes	<input checked="" type="radio"/> No					
(18) Design calculations available?				Yes	<input checked="" type="radio"/> No					
(19) Structure hydraulically adequate?				<input checked="" type="radio"/> Yes	No	Don't know ( )				
(21) Seismically Retrofitted?				<input checked="" type="radio"/> Yes	No	Description				
<b>B. SUPERSTRUCTURE</b>										
(23) Superstructure Type:	Steel Truss, Steel Girder, RCDG, <input checked="" type="radio"/> PSCG, <i>PCI Girder</i> Others ( )									
(24) Number of Girders/Span:	<b>10 / 6</b>			(25) Continuous?	Yes <input checked="" type="radio"/> No					
(26) Number of Expansion Joints:	<b>7</b>		(27) Type of Expansion Joints:	<input checked="" type="radio"/> Steel, Rubber, Seam						
<b>C. BEARINGS</b>										
(28) Bearing Type:	Roller, <input checked="" type="radio"/> Rocker, Rubber, Others ( )				Condition:	Functioning ( ) Not Functioning ( )				
(29) Type of Restraint (Transverse):	<b>Concrete Block</b>			(30) Type of Restraint (Longitudinal):						
(31) Seating Length (Longitudinal) :	Abutments:	<b>1</b>		Piers:	<b>1</b>		Hinges:	<b>—</b>		
<b>D. ABUTMENTS</b>										
(32) Type:	<b>Wall Type</b>				(33) Height:	<b>3.127</b>				
(34) Foundation Type:	Spread Footing, On Piles, <input checked="" type="radio"/> Others ( )			(35) Wingwall Lengths	L:	<b>3.8</b>		R:	<b>—</b>	

<b>E. COLUMNS AND PIERS</b>			
(36) Column Type:	<i>Wall Type</i>		
(37) Min. Transverse Cross-Section Dimension:		(38) Min. Longitudinal Cross-Section Dimension	
(39) Height Range:		(40) Fixity:	Top      Bottom      Both
(41) Percentage of Longitudinal Reinforcement:			
(42) Transverse Reinforcements:	Bar Size:	Spacing:	Tied      Spiral
(43) Foundation Type:	Spread Footing	On Piles	<u>Others (      )</u>










<b>F. SITE</b>			
(44) Estimated Peak Ground Acceleration (0.4-0.7g):			
(45) Soil Profile Type:	I	II	<u>III</u> IV      Don't Know
(46) Liquefaction Potential:	<u>Yes</u>	No	Don't Know (      )
(47) Boring Data Available:	<u>Yes</u>	No	

<b>G. OTHER ITEMS</b>			
(48) Approach Slab: Yes (      ) Length		(47) Embankment Side-slope type (Approach Road):	(H:V):
(49) Slope Bank Protection Type:			





PHOTOGRAPHS / SKETCHES (Use additional sheets if necessary)













<p>1.</p> 	<p>2.</p> 
<p>3. no access</p>	<p>4.</p> 
<p>5.</p> 	<p>6.</p> 
<p>7.</p> 	<p>8.</p> 
<p>9.</p> 	<p>10.</p> 





Main Viewpoints of the Bridge

Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Deck Slab (Primary)	Cracking		Cracks with width less than 1mm observed entirely on deck slab. Some cracks are over 1mm.
	Exposure/Corrosion of Rebars		At end of deck slab, Exposure/Corrosion of Rebars due to spalling is detected.
	Scaling/Spalling		Several spallings are observed on the bottom of deck slab.
Concrete Beam/ Girder (Primary)	Cracking		


Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Concrete Beam/ Girder (Primary)	Exposure/Corrosion of Rebars		Exposure/Corrosion of Rebars is detected at the deep spallings.
	Delamination		Delamination is observed at hunch.
Abutments	Spalling, Scaling, Disintegration		Spallings caused by unskilled workmanship are observed.
	Cracking concrete		Many cracks are detected on abutment.

Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Pier	Cracking concrete		A few Cracks are observed on the interval wall of pier.
	Exposure/Corrosion of Reinf.		At a few piers, Exposure/Corrosion of Rebars due to impact of ship is observed.
Curb and Railing (Secondary)	Impact Damaged		Railing is damaged due to impact of traffic.
Expansion Joint (Primary)	Water leaking		Water leaking from expansion joint is observed.



Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Expansion Joint (Primary)	Difference in elevation		Difference in elevation at expansion joint is occurred due to displacement of girders.
	Displacement		Due to displacement of girders, portion of expansion joint is closed and bottom of girders are opened.
Slope Protection	Erosion		At Abutment A1, erosion of slope protection is observed.
	Material Loss		At abutment A2, material losses are observed.

### Bridge Profile



### Main Features of the Bridge



### 16) Marikina Bridge

BRIDGE SEISMIC INVENTORY DATA											
<b>A. GENERAL</b>											
(1) Bridge Name:	<i>Marikina Bridge</i>					(2) Posted Load Limit		tons			
(3) Location:	km.:		Route:	<i>A.Bonifacio Ave. / E.Rodriguez Ave.</i>			Prov./ City	<i>Marikina City</i>			
(4) Crossing Condition:	<input checked="" type="radio"/> Crossing River, ( ) Railway, ( ) Roadway, ( ) Valley, ( ) Others ( )										
(5) AADT:		(6) Detour Distance:		(7) Essential Bridge?	Yes ( ) No ( )						
(8) Alignment:	<input checked="" type="radio"/> Straight <input type="radio"/> Curved, (Radius) _____ m <input type="radio"/> Skewed, (Skew Angle) <sup>o</sup>										
(9) No. of Spans:	<i>5</i>	(10) Span Lengths	<i>24.20+3@30.00+24.00</i>			(11) Total Length:	<i>138.2</i>				
(12) Left Sidewalk Width:	<i>1.15</i>	(13) Carriageway Width:	<i>8.30+8.30</i>			(14) Right Sidewalk Width:	<i>1.15</i>				
(15) Overall Width (including sidewalk):	<i>20.3</i>					(16) Year Built:	<i>1980</i>				
(17) As-builts or design drawings available?						Yes	<input checked="" type="radio"/> No				
(18) Design calculations available?						Yes	<input checked="" type="radio"/> No				
(19) Structure hydraulically adequate?						<input checked="" type="radio"/> Yes	No	Don't know ( )			
(21) Seismically Retrofitted?						<input checked="" type="radio"/> Yes	No	Description (All Piers have been retrofitted)			
<b>B. SUPERSTRUCTURE</b>											
(23) Superstructure Type:	Steel Truss, Steel Girder, RCDG, <input checked="" type="radio"/> PSCG PCI Girder, Others ( )										
(24) Number of Girders/Span:	<i>12 / 5</i>			(25) Continuous?	<input checked="" type="radio"/> Yes No						
(26) Number of Expansion Joints:	<i>2</i>		(27) Type of Expansion Joints:	<input checked="" type="radio"/> Steel, Rubber, Seam			<i>Fingers</i>				
<b>C. BEARINGS</b>											
(28) Bearing Type:	Roller, Rocker, <input checked="" type="radio"/> Rubber, Others ( )				Condition:	<input checked="" type="radio"/> Functioning ( ) Not Functioning ( )					
(29) Type of Restraint (Transverse):	<i>Concrete Block</i>			(30) Type of Restraint (Longitudinal):	<i>—</i>						
(31) Seating Length (Longitudinal):	Abutments:	<i>0.65</i>		Piers:	<i>—</i>		Hinges:	<i>—</i>			
<b>D. ABUTMENTS</b>											
(32) Type:	<i>Wall Type</i>				(33) Height:	<i>1.545</i>					
(34) Foundation Type:	Spread Footing, On Piles, <input checked="" type="radio"/> Others (RCP)			(35) Wingwall Lengths	L:	<i>27~49</i>		R:	<i>63</i>		

<b>E. COLUMNS AND PIERS</b>			
(36) Column Type:	<i>Column Type</i>		
(37) Min. Transverse Cross-Section Dimension:		(38) Min. Longitudinal Cross-Section Dimension	
(39) Height Range:		(40) Fixity:	Top      Bottom      Both
(41) Percentage of Longitudinal Reinforcement:			
(42) Transverse Reinforcements:	Bar Size:	Spacing:	Tied      Spiral
(43) Foundation Type:	Spread Footing	On Piles	<u>Others ( RC Piles )</u>









<b>F. SITE</b>			
(44) Estimated Peak Ground Acceleration (0.4-0.7g):			
(45) Soil Profile Type:	I	II	<u>III</u> IV      Don't Know
(46) Liquefaction Potential:	<u>Yes</u>	No	Don't Know ( )
(47) Boring Data Available:	<u>Yes</u>	No	

<b>G. OTHER ITEMS</b>			
(48) Approach Slab: Yes ( ) Length		(47) Embankment Side-slope type(Approach Road):	(H:V):
(49) Slope Bank Protection Type:			





PHOTOGRAPHS / SKETCHES (Use additional sheets if necessary)











<p>1.</p> 	<p>2.</p> 
<p>3. no photo</p>	<p>4.</p> 
<p>5.</p> 	<p>6. no photo</p>
<p>7.</p> 	<p>8.</p> 
<p>9.</p> 	<p>10.</p> 

Main Viewpoints of the Bridge


Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Deck Slab (Primary)	Cracking		Cracks with width less than 1mm observed entirely on deck slab. Some cracks are over 1mm. (Poor condition)
	Scaling/Spalling		Many but small spalling are observed on the deck slab.
	Water leaking		Cracks combined water leaking are observed at several parts.
Concrete Beam/ Girder (Primary)	Exposure/Corrosion of Rebars		Exposure/Corrosion of Rebars is observed on cross beams.

Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Concrete Beam/ Girder (Primary)	Honeycomb		A few honeycombs caused by unskilled workmanship are observed.
Shoe/Bearing	Bulging/Rupture		Rubber pads are ruptured.
Pier (Primary)	Spalling, Scaling,Disinte gration		Several spallings are observed on piers.
	Cracking concrete		Many cracks are observed horizontally and vertically on pier.

Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Expansion Joint (Primary)	Water leaking		Water leaking is observed from expansion joints.
	Displacement		



### Bridge Profile



### Main Features of the Bridge



**17) San Jose Bridge**

BRIDGE SEISMIC INVENTORY DATA										
<b>A. GENERAL</b>										
(1) Bridge Name:	<i>San Jose Bridge</i>					(2) Posted Load Limit		tons		
(3) Location:	km.:		Route:	<i>Rodrigues Highway</i>			Prov./ City	<i>Rizal</i>		
(4) Crossing Condition: <input checked="" type="radio"/> Crossing River, ( ) Railway, ( ) Roadway, ( ) Valley, ( ) Others ( )										
(5) AADT:		(6) Detour Distance:		(7) Essential Bridge?	Yes ( ) No ( )					
(8) Alignment: <input checked="" type="radio"/> Straight, Curved, (Radius) _____ m Skewed, (Skew Angle) _____										
(9) No. of Spans:	<b>8</b>		(10) Span Lengths	<b>24.90+24.97+24.95+24.97+ 25.00+24.97+24.96+24.95</b>			(11) Total Length:	<b>199.67</b>		
(12) Left Sidewalk Width:	<b>1.45</b>		(13) Carriageway Width:	<b>7.50+7.50</b>		(14) Right Sidewalk Width:	<b>1.45</b>			
(15) Overall Width (including sidewalk):				<b>19.1</b>			(16) Year Built:	<b>1980</b>		
(17) As-builts or design drawings available?					Yes	<input checked="" type="radio"/> No				
(18) Design calculations available?					Yes	<input checked="" type="radio"/> No				
(19) Structure hydraulically adequate?					<input checked="" type="radio"/> Yes	No	Don't know ( )			
(21) Seismically Retrofitted?					Yes	<input checked="" type="radio"/> No Description				
<b>B. SUPERSTRUCTURE</b>										
(23) Superstructure Type:			Steel Truss, Steel Girder, RCDG, <input checked="" type="radio"/> PSCG, Others ( )							
(24) Number of Girders/Span:			<b>8 / 8</b>		(25) Continuous?		Yes <input checked="" type="radio"/> No			
(26) Number of Expansion Joints:			<b>9</b>		(27) Type of Expansion Joints:			<input checked="" type="radio"/> Steel, Rubber, Seam <i>Angular</i>		
<b>C. BEARINGS</b>										
(28) Bearing Type:			Roller, <input checked="" type="radio"/> Rocker, Rubber, Others ( )			Condition: <input checked="" type="radio"/> Functioning ( ) Not Functioning ( )				
(29) Type of Restraint (Transverse):			—			(30) Type of Restraint (Longitudinal):		—		
(31) Seating Length (Longitudinal):			Abutments: <b>0.8</b>		Piers: <b>0.7</b>		Hinges: —			
<b>D. ABUTMENTS</b>										
(32) Type:			<b>Wall Type</b>			(33) Height:		<b>1.2</b>		
(34) Foundation Type:			Spread Footing, On Piles, <input checked="" type="radio"/> Others ( RC Pile )			(35) Wingwall Lengths		L: <b>3.6</b>	R: <b>3.7</b>	











<b>E. COLUMNS AND PIERS</b>			
(36) Column Type:	<i>Wall Type</i>		
(37) Min. Transverse Cross-Section Dimension:		(38) Min. Longitudinal Cross-Section Dimension	
(39) Height Range:		(40) Fixity:	Top      Bottom      Both
(41) Percentage of Longitudinal Reinforcement:			
(42) Transverse Reinforcements:	Bar Size:	Spacing:	Tied      Spiral
(43) Foundation Type:	Spread Footing	On Piles	<u>Others ( RC Pile )</u>

<b>F. SITE</b>			
(44) Estimated Peak Ground Acceleration (0.4-0.7g):			
(45) Soil Profile Type:	I	<u>II</u>	III      IV      Don't Know
(46) Liquefaction Potential:	Yes	<u>No</u>	Don't Know ( )
(47) Boring Data Available:	<u>Yes</u>	No	

<b>G. OTHER ITEMS</b>			
(48) Approach Slab: Yes ( ) Length		(47) Embankment Side-slope type(Approach Road):	(H:V):
(49) Slope Bank Protection Type:			





PHOTOGRAPHS / SKETCHES (Use additional sheets if necessary)










<p>1.</p> 	<p>2.</p> 
<p>3.</p> 	<p>4.</p> 
<p>5.</p> 	<p>6.</p> 
<p>7.</p> 	<p>8.</p> 
<p>9.</p> 	<p>10.</p> 




Main Viewpoints of the Bridge

Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Concrete Beam/ Girder (Primary)	Cracking		Crack with width more than 1mm is detected o flange of PC T-girder. Length is approximately 3m.
	Spalling, Scaling,Disinte gration		Several small spallings are observed.
Shoe/Bearing	Corrosion		Steel bearings are severely corroded but not yet section loss.
	Loose Connection		Connection of Steel bearing may be loosed and the bearing is slightly moved ahead.

Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Pier	Delamination		Delamination of concrete may be occurred at pile cap.
	Spalling, Scaling, Disintegration		Small spallings are observed on pier concrete.
	Cracking concrete		A few vertical cracks with width more than 1mm are observed on each pier.
Expansion Joint (Primary)	Water leaking		Water leaking is observed from expansion joints.

Component/ Material/ Classification	Type of Damages	Picture of the Damage	Reasoning for the Evaluation
Expansion Joint (Primary)	Abnormal Space/Noise		Space of expansion joints are closed abnormally.
Drainage Pipe	Clogged		Drainage pipes are completely clogged with dusts and sand.
River Condition (Secondary)	Scouring		Pile foundations are exposed by local scoring and its piles are projected.

Bridge Profile



Main Features of the Bridge

