


7. Landslide Recording Sheet

# General Information Sheet (Other)


Management number	000000001	Reporter's name:	Tomoharu IWASAKI	Date of report :	June 14, 2012
Address	Temple Road, Creve Coeur	Type*	Damage of wall	latitude	-20.149417
			longitude	57.582472	

Schematic sketch


plan view



cross section



Location map (Scale: 1:25,000)




## \* Description of "Type"

### Damage of wall

The disaster of the retaining wall doesn't have the sudden mutation like the rockfall etc. , and deformation does comparatively spending long time. The survey content is shown below.

- Investigation of condition around retaining wall
- Investigation concerning main body of retaining wall
- Investigation concerning history




### Damage of house

The crack that occurs on the wall in the house has the following causes.

- Landslide movement
- Lack of bearing capacity
- Subsidence of foundation ground
- Shoddy workmanship
- Other


It is preferable to search for length, width, and the direction of the crack, and to do the continuance observation.



### cavern

The Cavern occur by the following causes.

- Infiltration of water from soak away
- Infiltration of water from improved pit
- other



Mangement number	0	0	0	0	0	0	0	0	0	0	1
------------------	---	---	---	---	---	---	---	---	---	---	---

## Evaluation sheet

Reporter's name:	Tomoharu IWASAKI
------------------	------------------

[check Point]

Category		Record / check
Retaining wall	Type of the retaining wall	Concrete block / Concrete Stone masonry / Other
	H : Height of the retaining wall	1.2 m
	L : Length of the retaining wall	5.0 m
	D : Thickness of the retaining wall	0.3 m
	Type of the damage	Collapse / Inclination Hair crack / Open crack other
House	Type of the damage	Collapse / Inclination Hair crack / Open crack other
	Cause of damage	Landslide movement
		Lack of bearing capacity
		Subsidence of foundation ground
		Shoddy workmanship other / not clear
cavern	W : width of the cavern	m
	L : Length of the cavern	m
	D : Depth of the cavern	m
	Situation above the cavern	improved pit / soak away /other
	Water	Spring water / Ground water

Category		Check✓	
History	Existing record of damage on wall (documents or patrimony)	Obvious	
		slight	
	none	✓	
	Existing record of damage on house (documents or patrimony)	Obvious	
Slight			
Countermeasure	There is no Countermeasure		✓
	Effectiveness of Countermeasure	No effect	
		Some effect	
		High effect	

[Description]

Deformation on the concrete block wall and house caused by embankment deformation at the front yard (parking area) was confirmed. Another problem was inadequate surface drainage causing surface water from mountains to flow directly at houses during heavy rain.

The further detail of these two problems are described as below.

(1) The damage of the concrete block wall


The cracks on the concrete block wall occurred during the hurricane of 2005 or 2004. The structure of the wall is weak and has been damaged by the pressure of the embankment and groundwater.

(2) Flow of intense surface water

A large amount of water flows down from the mountain and hit the house which is located at the waterway during heavy rain.



Ph-1 Full view of concrete block wall



Ph-2 The damage of the concrete block wall



Ph-3 The course that the surface water flows through (1)



Ph-4 The course that the surface water flows through (2)



Ph-5 Damage of the drainage of the roadside

# Survey on Structural/Non-structural Measures

Management number 

0	0	0	0	0	0	0	0	0	0	1
---	---	---	---	---	---	---	---	---	---	---



Reporter's name: Tomoharu IWASAKI      Date of report : June 14, 2012

Structural Measures (Hard-Component)		
Existing countermeasures	The kinds of countermeasure	Number
		<i>Retaining wall</i>

Non-structural Measure (Soft-Component)		
Monitoring Equipment	The kinds of Monitoring / Spec	
Warning Threshold	Rainfall	
	Movement/displacement	
	communication means	
	evacuation support	

[ The Photo of Countermeasure ]

[ The Photo of Monitoring Equipment ]



[Description]  
There are two problems in this site.

(1) The damage of the concrete block wall  
The structure of the wall is weak and has been damaged by the pressure of the embankment and groundwater. It is necessary to change the wall to the stronger structure (e.g., the gravity retaining wall).

(2) Flow of intense surface water  
A large amount of water flows down from the mountain and hit the house which is located at the waterway during heavy rain. It is necessary to carry out surface drainage work.

[Resident's awareness and relocation]

[Land use restrictions in hazard areas]

[Description]

# General Information Sheet (Other)

Management number	0 0 0 0 0 0 0 0 2	Reporter's name:	Tomoharu IWASAKI	Date of report :	June 29, 2012
Address	Congomah Village Council (Ramlakhan)	Type*	Stream erosion	latitude	-20.153333
				longitude	57.597389

<p>Schematic sketch</p> <div style="border: 1px solid black; padding: 5px; margin-bottom: 10px;"> <p><b>plan view</b></p> </div> <div style="border: 1px solid black; padding: 5px; margin-bottom: 10px;"> <p><b>cross section</b></p> </div>	<p>Location map (Scale: 1:25,000)</p>
---	---------------------------------------

**\* Description of "Type"**

<p style="text-align: center;"><u>River bank erosion</u></p> <p>The Stream erosion is the phenomenon that the soil of the bank is removed by the flow of the river. It occurs in the part which a flow of the water crashes into mainly. Water might overflow when the amount of the stream increases.</p>	<p style="text-align: center;"><u>Damage of Embankment</u></p> <p>The collapse of the road embankment is often generated by a rainfall, infiltration of underground water, erosion by surface water, and a partial catchment. Therefore, it pays attention to the possibility of the catchment. The embankment material might be weak, and it cause by lack of soil compaction.</p>
--	---

Mangement number	0	0	0	0	0	0	0	0	0	2
------------------	---	---	---	---	---	---	---	---	---	---


## Evaluation sheet

Reporter's name:	Tomoharu IWASAKI
------------------	------------------


[check Point]

Category			Record
Stream	Figure / size	W1 : Width of the river	2.0 m
		W2 : Width of the riverbed	1.0 m
		D : Depth of the river	1.8 m
	Type	Right bank	Soil or Natural ground <u>Artificial structure</u>
		Left bank	Soil or Natural ground <u>Artificial structure</u>
	Box culvert	W : Width	m
		H : Height	m
Pipe culvert	D : Diameter	0.5 m	
Type of the damage	<u>Erosion</u>		
	Overflow stream		
	Other		
Embankment	Type of the embankment		
	Embankment		
	Cutting and embankment		
	Structural crack / Open crack		
	Scour under the slope		
	Erosion of the slope		
Type of the damage	A lot of repair parts		
	Other		


Category			Check ✓
History	Existing record of Stream erosion or overflow stream (documents or patrimony)	Obvious	
		slight	
		none	✓
	Existing record of damage on embankment (documents or patrimony)	Obvious	
Slight			
None			
Countermeasure	There is no Countermeasure		
	Effectiveness of Countermeasure	No effect	✓
		Some effect	
		High effect	



Structure of a river



Box culvert




Pipe culvert

[Description]

A small stream flows under the road through a concrete pipe culvert, however, because it is too small it causes flooding and bank erosion during heavy rain. The stone masonry wall built at the both side of riverbanks was destroyed by erosion. Therefore, it is necessary to build a retaining wall for both side of riverbanks and increase the diameter of the pipe culvert.

Five kinds of countermeasure



Ph-1 Full view (Upper stream)



Ph-2 Full view (Down stream)



Ph-3 Upper stream



Ph-4 Down stream



# Survey on Structural/Non-structural Measures

Management number 0 0 0 0 0 0 0 0 0 2

Reporter's name: Tomoharu IWASAKI Date of report : June 29, 2012

Structural Measures (Hard-Component)	
	The kinds of countermeasure
Existing countermeasures	Number
	Stone masonry wall
	1

Non-structural Measure (Soft-Component)	
	The kinds of Monitoring / Spec
Landslide Monitoring Equipment	Number
Warning Threshold	Rainfall
	Movement/displacement
communication means	
evacuation support	

[ The Photo of Countermeasure ]

[ The Photo of Monitoring Equipment ]



Stone masonry walls are broken






Stone masonry walls are broken

[Description]  
 A concrete pipe culvert is installed under the road crossing the small river. However, the size of the pipe culvert is small which causing the flood during heavy rain and bank erosion.  
 The stone masonry wall built at the both side of riverbanks was destroyed by erosion. Therefore, it is necessary to build a retaining wall for both side of riverbanks and increase the diameter of the pipe culvert.

[Resident's awareness and relocation]  
  
 [Land use restrictions in hazard areas]  
  
 [Description]

# General Information Sheet (Other)


Management number	000000003	Reporter's name:	Tomoharu IWASAKI	Date of report :	June 29, 2012
Address	Congomah Village Council (Leekraj)	Type*	Damage of wall	latitude	-20.149
Schematic sketch			longitude	57.597667	
<p><b>plan view</b></p>  <p><b>cross section</b></p> 			<p>Location map (Scale: 1:25,000)</p>  <p>0 500 1,000m 1/25,000</p>		

## \* Description of "Type"

### Damage of wall

The disaster of the retaining wall doesn't have the sudden mutation like the rockfall etc. , and deformation does comparatively spending long time. The survey content is shown below.

- Investigation of condition around retaining wall
- Investigation concerning main body of retaining wall
- Investigation concerning history




### Damage of house

The crack that occurs on the wall in the house has the following causes.

- Landslide movement
- Lack of bearing capacity
- Subsidence of foundation ground
- Shoddy workmanship
- Other


It is preferable to search for length, width, and the direction of the crack, and to do the continuance observation.



### cavern

The Cavern occur by the following causes.

- Infiltration of water from soak away
- Infiltration of water from improved pit
- other



Mangement number	0	0	0	0	0	0	0	0	0	0	3
------------------	---	---	---	---	---	---	---	---	---	---	---

## Evaluation sheet

Reporter's name:	Tomoharu IWASAKI
------------------	------------------

[check Point]

Category		Record / check	
Retaining wall	Type of the retaining wall	Concrete block / Concrete <del>Stone masonry</del> / Other	
	H : Height of the retaining wall	2.0 m	
	L : Length of the retaining wall	15.0 m	
	D : Thickness of the retaining wall	0.2 m	
	Type of the damage	Collapse / Inclination <del>Hair crack</del> / Open crack other	
House	Type of the damage	<del>Collapse / Inclination Hair crack / Open crack other</del>	
	Cause of damage	<del>Landslide movement Lack of bearing capacity Subsidence of foundation ground Shoddy workmanship other / not clear</del>	
	cavern	W : width of the cavern	m
		L : Length of the cavern	m
		D : Depth of the cavern	m
Situation above the cavern		improved pit / soak away /other	
Water	Spring water / Ground water		

Category		Check✓	
History	Existing record of damage on wall (documents or patrimony)	Obvious	
		slight	
	Existing record of damage on house (documents or patrimony)	none	✓
		Obvious	
Countermeasure	Effectiveness of Countermeasure	Slight	
		None	
	There is no Countermeasure		
	Effectiveness of Countermeasure		No effect
		Some effect	
		High effect	✓

[Description]

A 1m high retaining wall that was constructed to build the road was reported to be leaning but it was found to be stable and no slope failure was observed. Therefore, It is not necessary to investigate in detail.



Ph-1 Full view (Retaining wall)



Ph-2 Retaining wall



Ph-3 Retaining wall

# Survey on Structural/Non-structural Measures

Management number 0 0 0 0 0 0 0 0 0 3

Reporter's name: Tomoharu IWASAKI Date of report : June 29, 2012

Structural Measures (Hard-Component)	
	The kinds of Countermeasure
Existing countermeasures	Number
	Stone masonry
	1

Non-structural Measure (Soft-Component)	
	The kinds of Monitoring / Spec
Monitoring Equipment	Number
Warning Threshold	Rainfall
	Movement/displacement
communication means	
evacuation support	

[ The Photo of Countermeasure ]

[ The Photo of Monitoring Equipment ]



Ph-1 The retaining wall

[Description]  
A 1m height retaining wall that has been constructed to build the road was reported leaning but it was stable and no slope failure has been observed. Therefore, It is not necessary to investigate in detail.



[Resident's awareness and relocation]

[Land use restrictions in hazard areas]

[Description]

# General Information Sheet (Other)

Management number	000000004	Reporter's name:	Youji /KASAHARA	Date of report :	June 29, 2012
Address	Congomah Village Council (Frederick)	Type*	Damage of wall	latitude	-20.147333
				longitude	57.597444



## \* Description of "Type"

Damage of wall	Damage of house	cavern
<p>The disaster of the retaining wall doesn't have the sudden mutation like the rockfall etc. , and deformation does comparatively spending long time. The survey content is shown below.</p> <ul style="list-style-type: none"> <li>Investigation of condition around retaining wall</li> <li>Investigation concerning main body of retaining wall</li> <li>Investigation concerning history</li> </ul>	<p>The crack that occurs on the wall in the house has the following causes.</p> <ul style="list-style-type: none"> <li>Landslide movement</li> <li>Lack of bearing capacity</li> <li>Subsidence of foundation ground</li> <li>Shoddy workmanship</li> <li>Other</li> </ul> <p>It is preferable to search for length, width, and the direction of the crack, and to do the continuance observation.</p>	<p>The Cavern occur by the following causes.</p> <ul style="list-style-type: none"> <li>Infiltration of water from soak away</li> <li>Infiltration of water from improved pit</li> <li>other</li> </ul>
	<p>settling</p>	<p>Ground level</p> <p>improved pit</p> <p>Soak away</p> <p>Cavern</p>

Mangement number	0	0	0	0	0	0	0	0	0	0	4
------------------	---	---	---	---	---	---	---	---	---	---	---

## Evaluation sheet

Reporter's name:	Youji /KASAHARA
------------------	-----------------

[check Point]

Category		Record / check	
Retaining wall	Type of the retaining wall	Concrete block / Concrete <u>Stone masonry</u> / Other	
	H : Height of the retaining wall	1.0 m	
	L : Length of the retaining wall	15.0 m	
	D : Thickness of the retaining wall	0.3 m	
	Type of the damage	<u>Collapse</u> / Inclination Hair crack / Open crack other	
House	Type of the damage	<del>Collapse / Inclination Hair crack / Open crack other</del>	
	Cause of damage	<del>Landslide movement Lack of bearing capacity Subsidence of foundation ground Shoddy workmanship other / not clear</del>	
	cavern	W : width of the cavern	m
		L : Length of the cavern	m
		D : Depth of the cavern	m
Situation above the cavern		improved pit / soak away /other	
Water	Spring water / Ground water		

Category		Check✓	
History	Existing record of damage on wall (documents or patrimony)	Obvious	
		slight	
	none	✓	
	Existing record of damage on house (documents or patrimony)	Obvious	
Slight			
Countermeasure	There is no Countermeasure		
	Effectiveness of Countermeasure	No effect	✓
		Some effect	
	High effect		

[Description]

The 1m high retaining wall along the road was found to have collapsed due to erosion by surface water flow during rainy season.



Ph-1 Full view of damage of retaining wall



Ph-2 damage in retaining wall by erosion



Ph-3 damage in retaining wall by erosion



Ph-4 Retaining wall that comes off

Ph-6 Sutiation in the back of School (fill-up ground)



# Survey on Structural/Non-structural Measures

Management number 0 0 0 0 0 0 0 0 0 4

Reporter's name: Youji /KASAHARA Date of report : June 29, 2012

Structural Measures (Hard-Component)	
	The kinds of Countermeasure
Existing countermeasures	Number
	Stone masonry
	1

Non-structural Measure (Soft-Component)	
	The kinds of Monitoring / Spec
Monitoring Equipment	Number
Warning Threshold	Rainfall
	Movement/displacement
communication means	
evacuation support	

[ The Photo of Countermeasure ]



None

None

[Description]  
The 1m height retaining wall along the road collapsed due to the erosion of surface water flow during rainy season.

[ The Photo of Monitoring Equipment ]



[Resident's awareness and relocation]

[Land use restrictions in hazard areas]

[Description]

[Description]

[Description]

# General Information Sheet (Other)

Management number	0 0 0 0 0 0 0 0 5	Reporter's name:	Ai Togami	Date of report :	June 29, 2012
Address	Congomah Village Council (Blackburn Lanes)	Type*	Damage of Embankment	latitude	-20.152611
Schematic sketch			Location map (Scale: 1:25,000)		
<div style="display: flex; justify-content: space-around;"> <div style="border: 1px solid black; padding: 5px;">plan view</div> <div style="border: 1px solid black; padding: 5px;">cross section</div> </div>					

**\* Description of "Type"**

<p style="text-align: center;"><u>River bank erosion</u></p> <p>The Stream erosion is the phenomenon that the soil of the bank is removed by the flow of the river. It occurs in the part which a flow of the water crashes into mainly. Water might overflow when the amount of the stream increases.</p>	<p style="text-align: center;"><u>Damage of Embankment</u></p> <p>The collapse of the road embankment is often generated by a rainfall, infiltration of underground water, erosion by surface water, and a partial catchment. Therefore, it pays attention to the possibility of the catchment. The embankment material might be weak, and it cause by lack of soil compaction.</p> <div style="display: flex; justify-content: space-around;"> <div style="text-align: center;"> <p>Cross section</p> </div> <div style="text-align: center;"> <p>Signs of stream</p> </div> </div>
--	--

Mangement number	0	0	0	0	0	0	0	0	0	0	5
------------------	---	---	---	---	---	---	---	---	---	---	---


## Evaluation sheet

Reporter's name:	Ai Togami
------------------	-----------


[check Point]

Category			Record	
Stream	Figure / size	W1 : Width of the river	m	
		W2 : Width of the riverbed	m	
		D : Depth of the river	m	
	Type	Right bank	Soil or Natural ground / Artificial structure	
		Left bank	Soil or Natural ground / Artificial structure	
	Box culvert	W : Width	m	
		H : Height	m	
	Pipe culvert	D : Diameter	m	
	Type of the damage			Erosion
				Overflow stream
			Other	
Embankment	Type of the embankment		Embankment	
			Cutting and embankment	
			Structural crack / Open crack	
			Scour under the slope	
	Type of the damage		Erosion of the slope	
			A lot of repair parts	
		Other ( collapse )		


Category			Check ✓
History	Existing record of Stream erosion or overflow stream (documents or patrimony)	Obvious	
		slight	
		none	
	Existing record of damage on embankment (documents or patrimony)	Obvious	
Slight			
None		✓	
Countermeasure	There is no Countermeasure		✓
	Effectiveness of Countermeasure	No effect	
		Some effect	
		High effect	



Structure of a river



Box culvert



Pipe culvert

[Description]

A slope failure was confirmed on the side of the road.  
 Slope failure is characterized as follows; W=2m, L=2m.  
 There is a possibility of slope failure in future.  
 It is necessary to undertake works regarding this road. And, it will be necessary to construct a retaining wall.  
 Also, there is slope failure in another site. But, the road has been already repaired.



Ph-1 Full view



Ph-2 slope failure



Ph-3 Transverse Cracks



Ph-3 repaired road of another site


# Survey on Structural/Non-structural Measures

Management number 0 0 0 0 0 0 0 0 0 5

Reporter's name: Ai Togami Date of report : June 29, 2012

Structural Measures (Hard-Component)	
	The kinds of countermeasure
Existing countermeasures	None


[ The Photo of Countermeasure ]



[Description]  
 There is a possibility to expand slope failure in future. It is necessary for the road to be repaired. And, it will be necessary to construct a retaining wall. Also, there is slope failure in another site. But, the road has been already repaired.

Non-structural Measure (Soft-Component)	
	The kinds of Monitoring / Spec
Monitoring Equipment	
Warning Threshold	Rainfall
	Movement/displacement
communication means	
evacuation support	

[ The Photo of Monitoring Equipment ]



[Resident's awareness and relocation]  
  
 [Land use restrictions in hazard areas]  
  
 [Description]

# General Information Sheet (Slope)

Management number	000000006	Reporter's name:	Ai Togami	Date of report :	June 14, 2012
Address	Les Mariannes Community Centre (Road area)	Type*	Slope-failure	latitude	-20.168667
			longitude	57.590306	
Schematic sketch			Location map (Scale: 1:25,000)		
<p><b>plan view</b></p> <p><b>cross section</b></p>					

\* Description of "Type"

Rock fall	Slope failure	Landslide	Debris flow
<p>Rock Fall : Rock fall is a phenomenon where foliated rocks and gravel due to enlarged cracks in the bedrock or outcropped rocks start to fall down a slope.</p>	<p>Slope Failure : The slope failures mass detached from steep slope/cliff along surface with little or no shear displacement. Compared to landslides, the quick slope moves on a small-scale, the inclination angle of the slope failure is a relatively high angle (over 30 degrees ).</p>	<p>A landslide is a phenomenon where the soil mass on failure surfaces deep in the ground gradually shifts downward, triggered by heavy rain or earthquake, river erosion, earthworks. Compared to slope failure, the gentler slope moves on a large, the inclination angle of the landslides slope is a relatively low angle (about 5-30 degrees ).</p>	<p>A Debris flow is a phenomenon where soil and boulders are liquefied by surface water or groundwater and tend to flow downward rapidly through a mountain torrent.</p>


Mangement number	0	0	0	0	0	0	0	0	0	0	6
------------------	---	---	---	---	---	---	---	---	---	---	---

## Evaluation sheet


Reporter's name:	Ai Togami
------------------	-----------

[check Point]

Category		Check ✓	
Phenomenon on the Site	Scarp (Main or Minor , Horse shoe shape)	✓	
	Transverse Cracks (Tension or Compression)		
	Pond and Swamp		
	Spring Water		
	Topography with the Step	✓	
	Eembankment at the upper		
	Cut Slope at the toe	✓	
	Wash out by rivers		
	Damage on construction and houses	obvious (name: , number: )	
		Slight (name: road , number: 1 )	✓
None			
Monitoring Equipment	There is it (name: , number: )		
	There is it (name: , number: )		
	none		
History	Existing record of Landslide (documents or patrimony)	Obvious slight none	
		Obvious	
		slight	
Countermeasure	There is no Countermeasure		
	Effectiveness of Countermeasure	No effect	
		Some effect	✓
High effect			




Structure of a landslide



Schematic diagram of landslide landforms

[Description]

There are a few slope failures and a landslide in this site. The slope at the roadside collapsed during heavy rain in 2010 and a section of road was washed away. Since then, a retaining wall has been constructed and the site is currently stable.



Schematic cross section of inducing factor and artificial cause



Ph-1 Full view of landslide



Ph-2 Main Scarp



Ph-3 landslide



Ph-4 slope failure



Ph-5 slope failure



Ph-6 rocks and gravel by slope failure



# Survey on Structural/Non-structural Measures

Management number 0 0 0 0 0 0 0 0 0 6

Reporter's name: Ai Togami Date of report : June 14, 2012

Structural Measures (Hard-Component)	
	The kinds of landslide countermeasure
Existing landslide countermeasures	retaining wall
	2

Non-structural Measure (Soft-Component)	
	The kinds of Landslide Monitoring / Spec
Landslide Monitoring Equipment	None
	3

[ The Photo of Countermeasure ]

[ The Photo of Monitoring Equipment ]



[Description]  
There are few slope failure and a lanslide in this site.The slope at the roadside collapsed during heavy rain in 2010 and washed away the road. Since that, the retaining wall has been constructed and stable at this moment.

[The Photo of Monitoring Equipment]

[Resident's awareness and relocation]  
  
[Land use restrictions in hazard areas]  
  
[Description]

[The Photo of Countermeasure]



[Description]  
There are few slope failure and a lanslide in this site.The slope at the roadside collapsed during heavy rain in 2010 and washed away the road. Since that, the retaining wall has been constructed and stable at this moment.

[The Photo of Monitoring Equipment]



[Resident's awareness and relocation]  
  
[Land use restrictions in hazard areas]  
  
[Description]

# General Information Sheet (Other)

Management number	000000007	Reporter's name:	Tomoharu IWASAKI	Date of report :	June 14, 2012
Address	Les Mariannes Community Centre (Resident area)	Type*	Stream erosion	latitude	-20.168722
				longitude	57.590222



\* Description of "Type"



Mangement number	0	0	0	0	0	0	0	0	0	0	7
------------------	---	---	---	---	---	---	---	---	---	---	---


## Evaluation sheet

Reporter's name:	Tomoharu IWASAKI
------------------	------------------


[check Point]

Category			Record
Stream	Figure / size	W1 : Width of the river	2.5 m
		W2 : Width of the riverbed	1.5 m
		D : Depth of the river	2.5 m
	Type	Right bank	Soil or Natural ground / Artificial structure
		Left bank	Soil or Natural ground / Artificial structure
	Box culvert	W : Width	m
		H : Height	m
Pipe culvert	D : Diameter	m	
Type of the damage			Erosion Overflow stream Other
Embankment	Type of the embankment		Embankment Cutting and embankment
	Type of the damage		Structural crack / Open crack Scour under the slope Erosion of the slope A lot of repair parts Other


Category			Check ✓
History	Existing record of Stream erosion or overflow stream (documents or patrimony)	Obvious	
		slight	
		none	✓
	Existing record of damage on embankment (documents or patrimony)	Obvious	
Slight			
None			
Countermeasure	There is no Countermeasure		✓
	Effectiveness of Countermeasure	No effect	
		Some effect	
High effect			



Structure of a river



Box culvert



Pipe culvert

[Description]

There appeared to be bank erosion on the left bank above the bridge. The upper bank has not been covered by anything while the retaining wall was constructed at the lower bank. In addition, the water level rises in the wet season causing the bank erosion.



Ph-1 Full view of the river



Ph-2 Eroded area



Ph-3 Concrete wall

# Survey on Structural/Non-structural Measures

Management number 0 0 0 0 0 0 0 0 0 7



Reporter's name: Tomoharu IWASAKI      Date of report : June 14, 2012

Structural Measures (Hard-Component)	
	The kinds of countermeasure
Existing countermeasures	None

Non-structural Measure (Soft-Component)	
	The kinds of Monitoring / Spec
Monitoring Equipment	
Warning Threshold	Rainfall
	Movement/displacement
communication means	
evacuation support	

[ The Photo of Countermeasure ]




[ The Photo of Monitoring Equipment ]





[Description]  
It is necessary to carry out the countermeasures in the left bank of the upper side of the bridge.

[Resident's awareness and relocation]  
  
[Land use restrictions in hazard areas]  
  
[Description]

# General Information Sheet (Other)

Management number	000000008	Reporter's name:	Youji /KASAHARA	Date of report :	June 29, 2012
Address	L'Eau Bouillie	Type*	Damage of embankment	latitude	-20.171583
				longitude	57.594167
Schematic sketch	<div data-bbox="224 351 380 391" data-label="Text"> <p>plan view</p> </div> 		<div data-bbox="1120 303 1433 335" data-label="Text"> <p>Location map (Scale: 1:25,000)</p> </div> 		
	<div data-bbox="224 782 436 821" data-label="Text"> <p>cross section</p> </div> 				

\* Description of "Type"

<p style="text-align: center;"><u>River bank erosion</u></p> <p>The Stream erosion is the phenomenon that the soil of the bank is removed by the flow of the river. It occurs in the part which a flow of the water crashes into mainly. Water might overflow when the amount of the stream increases.</p> 	<p style="text-align: center;"><u>Damage of Embankment</u></p> <p>The collapse of the road embankment is often generated by a rainfall, infiltration of underground water, erosion by surface water, and a partial catchment. Therefore, it pays attention to the possibility of the catchment. The embankment material might be weak, and it cause by lack of soil compaction.</p> 
---	---

Mangement number	0	0	0	0	0	0	0	0	0	0	8
------------------	---	---	---	---	---	---	---	---	---	---	---


## Evaluation sheet

Reporter's name:	Youji /KASAHARA
------------------	-----------------


[check Point]

Category			Record	
Stream	Figure / size	W1 : Width of the river	m	
		W2 : Width of the riverbed	m	
		D : Depth of the river	m	
	Type	Right bank	Soil or Natural ground / Artificial structure	
		Left bank	Soil or Natural ground / Artificial structure	
	Box culvert	W : Width	m	
		H : Height	m	
	Pipe culvert	D : Diameter	m	
	Type of the damage			Erosion
				Overflow stream
			Other	
Embankment	Type of the embankment		Embankment	
			Cutting and embankment	
			Structural crack / Open crack	
	Type of the damage		Scour under the slope	
			Erosion of the slope	
			A lot of repair parts	
			Other	


Category			Check ✓
History	Existing record of Stream erosion or overflow stream (documents or patrimony)	Obvious	
		slight	
		none	
	Existing record of damage on embankment (documents or patrimony)	Obvious	
Slight			
None		✓	
Countermeasure	There is no Countermeasure		✓
	Effectiveness of Countermeasure	No effect	
		Some effect	
High effect			



Structure of a river



Box culvert




Pipe culvert

[Description]


The cracks have been spotted on the road surface due to the deterioration of bearing capacity of the roadbed. The cracks have been repaired although the soil compaction on the roadbed and the strength confirmation of the road body will be necessary.




Ph-1 Full view of of damaged road



Ph-2 Repair mark on road



Ph-3 Repair mark on road



Ph-4 Damage of shoulder



# Survey on Structural/Non-structural Measures

Management number 0 0 0 0 0 0 0 0 0 8

Reporter's name: Youji /KASAHARA Date of report : June 29, 2012

Structural Measures (Hard-Component)	
	The kinds of countermeasure
Existing countermeasures	None

Non-structural Measure (Soft-Component)	
	The kinds of Monitoring / Spec
Monitoring Equipment	
Warning Threshold	Rainfall
	Movement/displacement
communication means	
evacuation support	

[ The Photo of Countermeasure ]

[ The Photo of Monitoring Equipment ]

None	None
------	------

--	--


None	<p>[Description] This phenomenon is the lack of the bearing capacity and is not a landslide.</p>
------	--

	<p>[Resident's awareness and relocation]</p> <p>[Land use restrictions in hazard areas]</p> <p>[Description]</p>
--	--



# General Information Sheet (Slope)

Management number	000000009	Reporter's name:	Tomoharu IWASAKI	Date of report :	June 6, 2012
Address	Chitrakoot, Vallee des Pretres	Type*	Landslide	latitude	-20.18496
				longitude	57.544498

Schematic sketch




Location map (Scale: 1:25,000)




## Landslide

A landslide is a phenomenon where the soil mass on failure surfaces deep in the ground gradually shifts downward, triggered by heavy rain or earthquake, river erosion, earthworks. Compared to slope failure, the gentler slope moves on a large, the inclination angle of the landslides slope is a relatively low angle (about 5-30 degrees).



## Debris flow

A Debris flow is a phenomenon where soil and boulders are liquefied by surface water or groundwater and tend to flow downward rapidly through a mountain torrent.




Mangement number	0	0	0	0	0	0	0	0	0	0	9
------------------	---	---	---	---	---	---	---	---	---	---	---

## Evaluation sheet


Reporter's name:	Tomoharu IWASAKI
------------------	------------------

[check Point]

Category		Check ✓	
Phenomenon on the Site	Scarp (Main or Minor , Horse shoe shape)	✓	
	Transverse Cracks (Tension or Compression)	✓	
	Pond and Swamp		
	Spring Water		
	Topography with the Step	✓	
	Eembankment at the upper		
	Cut Slope at the toe		
	Wash out by rivers		
	Damage on construction and houses	obvious ( number : over 10 houses )	✓
		Slight ( number : )	
None			
Monitoring Equipment	There is it (name: Extensometer , number: 3 )	✓	
	There is it (name: , number: )		
	none		
History	Existing record of Landslide (documents or patrimony)	Obvious (Document, 2007)	
		slight	
		none	
Countermeasure	There is no Countermeasure	✓	
	Effectiveness of Countermeasure	No effect	
		Some effect	
		High effect	



Structure of a landslide




Schematic diagram of landslide landforms

[Description]

A clear landslide was confirmed in this site and the characteristics are as follows;  
 (1) Main Scarp (Horse shoe Scarp),  
 (2) Some Minor Scarps,  
 (3) Steps and Tension Cracks.

A clear landslide was confirmed. A landslide was reported to have damaged houses and a school after heavy rain in 2005. Boring investigation and monitoring have been carried out, but not sufficiently. No countermeasures have been implemented. Therefore, a detailed investigation and monitoring are necessary while the countermeasures are expected in future. L=1500m ,W=700m

Existing record of Landslide(documents) : GEOTECHNICAL INVESTIGATION AT CHITRAKOOT VALLEE DES PRETRES, FOR MINISTRY OF ENVIRONMENT & NATIONAL DEVELOPMENT UNIT. 2007



Schematic cross section of inducing factor and artificial cause



Ph-1 Main scarp



Ph-2 Minor Scarp



Ph-3 Minor Scarp



Ph-4 Damage on school  
(By the damage of the landslide, a part of the school cannot use)



Ph-5 Damage on house  
(It's relocated)



Ph-6 Damage on house  
(It's relocated)

# Survey on Structural/Non-structural Measures

Management number 

0	0	0	0	0	0	0	0	0	9
---	---	---	---	---	---	---	---	---	---

Reporter's name: Tomoharu IWASAKI Date of report : June 6, 2012

Structural Measures (Hard-Component)		
	The kinds of landslide countermeasure	Number
Existing landslide countermeasures	None	

Non-structural Measure (Soft-Component)		
	The kinds of Landslide Monitoring / Spec	Number
Landslide Monitoring Equipment	Extesometer	3
Warning Threshold	Rainfall	
	Movement/displacement	
	communication means	
	evacuation support	


[ The Photo of Countermeasure ]

None	None
------	------

[ The Photo of Monitoring Equipment ]

	
--	--

None	<p>[Description]</p> <p>The Structural Measure (Hard-Component) was carried out. The landslide is not stable. Therefore, a detailed investigation and monitoring are necessary while the countermeasures are expected in future.</p>
------	--

	<p>[Resident's awareness and relocation] Some houses relocated. By the damage of the landslide, a part of the school cannot use.</p> <p>[Land use restrictions in hazard areas] The land use of the hazard area is regulated, because of the landslide in 2005.</p> <p>[Description] Three extesometer were confirmed, and as for two expansion and contraction meters, a measurement is carried out by a local construction company.</p>
---	---

# General Information Sheet (Slope)

Management number	000000010	Reporter's name:	YoujiKASAHARA	Date of report :	June 22, 2012
Address	Vallee Pitot (near Eidgah)	Type*	Landslide	latitude	-20.18496
Schematic sketch			longitude	57.544498	
<p><b>Plan view</b></p> <p><b>Cross section</b></p>			<p>Location map (Scale: 1:25,000)</p> <p>0 500 1,000m 1/25,000</p>		

\* Description of "Type"

Rock fall	Slope failure	Landslide	Debris flow
<p>Rock Fall : Rock fall is a phenomenon where foliated rocks and gravel due to enlarged cracks in the bedrock or outcropped rocks start to fall down a slope.</p>	<p>Slope Failure : The slope failures mass detached from steep slope/cliff along surface with little or no shear displacement. Compared to landslides, the quick slope moves on a small-scale, the inclination angle of the slope failure is a relatively high angle (over 30 degrees ).</p>	<p>A landslide is a phenomenon where the soil mass on failure surfaces deep in the ground gradually shifts downward, triggered by heavy rain or earthquake, river erosion, earthworks. Compared to slope failure, the gentler slope moves on a large, the inclination angle of the landslides slope is a relatively low angle (about 5-30 degrees ).</p>	<p>A Debris flow is a phenomenon where soil and boulders are liquefied by surface water or groundwater and tend to flow downward rapidly through a mountain torrent.</p>


Mangement number	0	0	0	0	0	0	0	0	0	1	0
------------------	---	---	---	---	---	---	---	---	---	---	---

## Evaluation sheet

Reporter's name:	YoujiKASAHARA
------------------	---------------

[check Point]

		Category	Check ✓	
Phenomenon on the Site	Scarp (Main or Minor , Horse shoe shape)		✓	
	Transverse Cracks (Tension or Compression)		✓	
	Pond and Swamp			
	Spring Water			
	Topography with the Step		✓	
	Eembankment at the upper			
	Cut Slope at the toe		✓	
	Wash out by rivers			
	Damage on construction and houses	obvious	( number : 3 houses )	✓
		Slight	( number : )	
None				
Monitoring Equipment	There is it	(name: Extensometer , number: )		
	There is it	(name: , number: )		
	none		✓	
History	Existing record of Landslide (documents or patrimony)		✓	
	Obvious	(Newspaper)		
	slight			
Countermeasure	There is no Countermeasure		✓	
	Effectiveness of Countermeasure	No effect		
		Some effect		
High effect				




Structure of a landslide



[Description]

Lately, housing developments are growing rapidly in this area. A landslide boundary of 35m x 20m was clearly detected. Several houses have been damaged and some cracks were observed. The situation of the damage was also reported in the newspaper. The type of landslide is debris-slide caused by house construction in the upper slope and cut-slope at the toe. In addition, the incompleteness of the surface drainage is a problem. The landslide is not stable. A landslide investigation and monitoring are necessary while the countermeasures are expected in future.

L=35m ,W=20m



Schematic cross section of inducing factor and artificial cause



Ph-1 Main scarp



Ph-2 The broken steps



Ph-3 Observed cracks



Ph-4 Damage on house  
(Caused by landslide)



Ph-5 Direction of landslide movement



Ph-6 Cracks at bank protection



# Survey on Structural/Non-structural Measures

Management number 0 0 0 0 0 0 0 0 1 0

Reporter's name: YoujiKASAHARA Date of report : June 22, 2012

Structural Measures (Hard-Component)	
	The kinds of landslide countermeasure
Existing landslide countermeasures	None

Non-structural Measure (Soft-Component)	
	The kinds of Landslide Monitoring / Spec
Landslide Monitoring Equipment	
Warning Threshold	Rainfall
	Movement/displacement
	communication means
	evacuation support

[ The Photo of Countermeasure ]

[ The Photo of Monitoring Equipment ]

None	None
------	------

--	--

None	<p>[Description]</p> <p>The landslide is not stable. A landslide investigation and monitoring are necessary while the countermeasures are expected in future.</p>
------	---

	<p>[Resident's awareness and relocation]</p> <p>[Land use restrictions in hazard areas]</p> <p>[Description]</p> <p>The landslide is not stable. A landslide investigation and monitoring are necessary.</p>
--	--


# General Information Sheet (Other)

Management number	0 0 0 0 0 0 0 1 1	Reporter's name:	Youji KASAHARA	Date of report :	June 26, 2012
Address	LePouce Street	Type*	Stream erosion	latitude	-20.179253
				longitude	57.512669


  

Schematic sketch


Plan view




Cross section






Location map (Scale: 1:25,000)





1/25,000

**\* Description of "Type"**

<p style="text-align: center;"><u>River bank erosion</u></p> <p>The Stream erosion is the phenomenon that the soil of the bank is removed by the flow of the river. It occurs in the part which a flow of the water crashes into mainly. Water might overflow when the amount of the stream increases.</p> 	<p style="text-align: center;"><u>Damage of Embankment</u></p> <p>The collapse of the road embankment is often generated by a rainfall, infiltration of underground water, erosion by surface water, and a partial catchment. Therefore, it pays attention to the possibility of the catchment. The embankment material might be weak, and it cause by lack of soil compaction.</p> <div style="display: flex; justify-content: space-around;"> <div style="text-align: center;">  <p>Cross section</p> </div> <div style="text-align: center;">  <p>Signs of stream</p> </div> </div>
---	--

Mangement number	0	0	0	0	0	0	0	0	0	1	1
------------------	---	---	---	---	---	---	---	---	---	---	---


## Evaluation sheet

Reporter's name:	Youji KASAHARA
------------------	----------------


[check Point]

Category			Record
Stream	Figure / size	W1 : Width of the river	1.5 m
		W2 : Width of the riverbed	1.5 m
		D : Depth of the river	0.5 m
	Type	Right bank	Soil or Natural ground / Artificial structure
		Left bank	Soil or Natural ground / Artificial structure
	Box culvert	W : Width	m
		H : Height	m
	Pipe culvert	D : Diameter	m
Type of the damage		Erosion	
		Overflow stream	
		Other	
Embankment	Type of the embankment		Embankment
			Cutting and embankment
			Structural crack / Open crack
	Type of the damage		Scour under the slope
			Erosion of the slope
			A lot of repair parts
		Other	


Category			Check ✓
History	Existing record of Stream erosion or overflow stream (documents or patrimony)	Obvious	
		slight	
		none	✓
	Existing record of damage on embankment (documents or patrimony)	Obvious	
Slight			
None			
Countermeasure	There is no Countermeasure		✓
	Effectiveness of Countermeasure	No effect	
		Some effect	
		High effect	



Structure of a river



Box culvert



Pipe culvert

[Description]

Insufficient surface drainage means rain water concentrates in low area and erodes roads and houses in its path. Damage is negligible at present, although the maintenance of the surface drainage will be necessary.



Ph-1 Full view of the depressions



Ph-2 House around the depressions



Ph-3 Channel of the depressions (upstream)



Ph-4 Channel of the depressions

# Survey on Structural/Non-structural Measures

Management number 0 0 0 0 0 0 0 0 1 1

Reporter's name: Youji KASAHARA Date of report : June 26, 2012

Structural Measures (Hard-Component)	
	The kinds of countermeasure
Existing countermeasures	None

Non-structural Measure (Soft-Component)	
	The kinds of Monitoring / Spec
Monitoring Equipment	
Warning Threshold	Rainfall
	Movement/displacement
communication means	
evacuation support	

[ The Photo of Countermeasure ]

[ The Photo of Monitoring Equipment ]

None	None
------	------

--	--

None	<p>[Description]                      Imperfection of the surface drainage causing the rain water to concentrate at the low area while erodes the road and houses in its path. There is a slight damage for now although the maintenance of the surface drainage will be necessary.</p>
------	---

	<p>[Resident's awareness and relocation]</p> <p>[Land use restrictions in hazard areas]</p> <p>[Description]</p>
--	--

# General Information Sheet (Other)

Management number	000000012	Reporter's name:	Ai Togami	Date of report :	June 15, 2012
Address	Justice Street (near Kalimata Mandir)	Type*	Damage of wall	latitude	-20.177
Schematic sketch			longitude	57.508222	
<p><b>plan view</b></p> <p><b>cross section</b></p>			<p>Location map (Scale: 1:25,000)</p>		

**\* Description of "Type"**

Damage of wall	Damage of house	cavern
<p>The disaster of the retaining wall doesn't have the sudden mutation like the rockfall etc. , and deformation does comparatively spending long time. The survey content is shown below.</p> <ul style="list-style-type: none"> <li>Investigation of condition around retaining wall</li> <li>Investigation concerning main body of retaining wall</li> <li>Investigation concerning history</li> </ul>	<p>The crack that occurs on the wall in the house has the following causes.</p> <ul style="list-style-type: none"> <li>Landslide movement</li> <li>Lack of bearing capacity</li> <li>Subsidence of foundation ground</li> <li>Shoddy workmanship</li> <li>Other</li> </ul> <p>It is preferable to search for length, width, and the direction of the crack, and to do the continuance observation.</p>	<p>The Cavern occur by the following causes.</p> <ul style="list-style-type: none"> <li>Infiltration of water from soak away</li> <li>Infiltration of water from improved pit</li> <li>other</li> </ul>

Mangement number	0	0	0	0	0	0	0	0	0	1	2
------------------	---	---	---	---	---	---	---	---	---	---	---

## Evaluation sheet

Reporter's name:	Tomoharu IWASAKI
------------------	------------------

[check Point]

Category		Record / check	
Retaining wall	Type of the retaining wall	Concrete block / Concrete Stone masonry / Other	
	H : Height of the retaining wall	1.9 m	
	L : Length of the retaining wall	38.0 m	
	D : Thickness of the retaining wall	0.3 m	
	Type of the damage	Collapse / Inclination Hair crack / Open crack other	
House	Type of the damage	Collapse / Inclination Hair crack / Open crack other	
	Cause of damage	Landslide movement Lack of bearing capacity Subsidence of foundation ground Shoddy workmanship other / not clear	
	cavern	W : width of the cavern	m
		L : Length of the cavern	m
		D : Depth of the cavern	m
Situation above the cavern		improved pit / soak away /other	
Water	Spring water / Ground water		

Category		Check✓	
History	Existing record of damage on wall (documents or patrimony)	Obvious	
		slight	
	none	✓	
	Existing record of damage on house (documents or patrimony)	Obvious	
Slight			
Countermeasure	There is no Countermeasure		✓
	Effectiveness of Countermeasure	No effect	
		Some effect	
	High effect		

[Description]

An embankment has been constructed to build up the road, which caused an adjacent retaining wall to be pushed out and deformed. Insufficient surface drainage causing accumulation of groundwater could also be a factor causing this deformation. It is necessary to reconsider the construction of the retaining wall and drainage.



Ph-1 Full view of Embankments



Ph-2 Slope in the retaining wall upper part



Ph-3 Inclined the retaining wall



Ph-4 The Gully by flow of surface water



Ph-5 Flow of surface water



# Survey on Structural/Non-structural Measures

Management number 0 0 0 0 0 0 0 0 1 2

Reporter's name: Ai Togami Date of report : June 15, 2012

Structural Measures (Hard-Component)	
	The kinds of countermeasure
Existing countermeasures	retaining wall

Non-structural Measure (Soft-Component)	
	The kinds of Monitoring / Spec
Monitoring Equipment	
Warning Threshold	Rainfall
	Movement/displacement
communication means	
evacuation support	

[ The Photo of Countermeasure ]

[ The Photo of Monitoring Equipment ]




[Description]  
 The Structural Measure (Hard-Component) was carried out.  
 The imperfection of the surface drainage is one of the factor that causing the accumulation of groundwater at the rear bank and pressurize the retaining wall.  
 It is necessary to reconsider the construction of the retaining wall and drainage.

[Resident's awareness and relocation]  
  
 [Land use restrictions in hazard areas]  
  
 [Description]


# General Information Sheet (Slope)

Management number	000000013	Reporter's name:	Tomoharu IWASAKI	Date of report :	June 6, 2012
Address	Mgr. Leen Street and nearby vicinity, La Butte	Type*	Landslide	latitude	-20.167111
			longitude	57.492569	

Schematic sketch



Location map (Scale: 1:25,000)



\* Description of "Type"


### Rock fall

Rock Fall : Rock fall is a phenomenon where foliated rocks and gravel due to enlarged cracks in the bedrock or outcropped rocks start to fall down a slope.




### Slope failure

Slope Failure : The slope failures mass detached from steep slope/cliff along surface with little or no shear displacement. Compared to landslides, the quick slope moves on a small-scale, the inclination angle of the slope failure is a relatively high angle (over 30 degrees ).




### Landslide

A landslide is a phenomenon where the soil mass on failure surfaces deep in the ground gradually shifts downward, triggered by heavy rain or earthquake, river erosion, earthworks. Compared to slope failure, the gentler slope moves on a large, the inclination angle of the landslides slope is a relatively low angle (about 5-30 degrees ).



### Debris flow

A Debris flow is a phenomenon where soil and boulders are liquefied by surface water or groundwater and tend to flow downward rapidly through a mountain torrent.




Mangement number	0	0	0	0	0	0	0	0	0	1	3
------------------	---	---	---	---	---	---	---	---	---	---	---

## Evaluation sheet


Reporter's name:	Tomoharu IWASAKI
------------------	------------------

[check Point]

Category		Check ✓	
Phenomenon on the Site	Scarp (Main or Minor , Horse shoe shape)	✓	
	Transverse Cracks (Tension or Compression)		
	Pond and Swamp		
	Spring Water		
	Topography with the Step		
	Eembankment at the upper		
	Cut Slope at the toe		
	Wash out by rivers		
	Damage on construction and houses	obvious ( number : )	
		Slight ( number : 1 , wall )	✓
None			
Monitoring Equipment	There is it (name: Extensometer , number: 3 )		
	There is it (name: , number: )		
	none		
History	Existing record of Landslide (documents or patrimony)	Obvious ✓ slight none	
	Countermeasure	There is no Countermeasure	
		Effectiveness of Countermeasure	No effect
Some effect			
High effect	✓		



Structure of a landslide




Schematic diagram of landslide landforms

[Description]

The landslide of La Butte occurred in 1986, and many houses and a school were damaged. As for this landslide, countermeasures were carried out in 1998, therefore further investigation of the landslide is unnecessary. However, Port Louis City wants to continue the monitoring on this landslide in the future.

L=350m ,W=600m




Schematic cross section of inducing factor and artificial cause



Ph-1 Drainage Well (W-2)





Ph-2 Horizontal drain work



Landslide countermeasure in Mauritius - La Butte landslide, Port Louis City : SABO, Vol64, pp3-9, Jan. 2000

# Survey on Structural/Non-structural Measures

Management number	0 0 0 0 0 0 0 0 1 3	Reporter's name:	Tomoharu IWASAKI	Date of report :	June 6, 2012
<b>Structural Measures (Hard-Component)</b>		<b>Non-structural Measure (Soft-Component)</b>			
Existing landslide countermeasures	The kinds of landslide countermeasure	Number	The kinds of Landslide Monitoring / Spec		
	<i>Piles</i>	6 Lines	Number		
	<i>Drainage well</i>	4	<i>Extesometer</i>		
	<i>Horizontal drain work</i>	42	<i>Water level meter</i>		
			<i>Inclinometers</i>		
		Warning Threshold	Rainfall		
			Movement/displacement		
			communication means		
			evacuation support		
[ The Photo of Countermeasure ]		[ The Photo of Monitoring Equipment ]			
					
Drainage well	Horizontal drain Work				
	<p>[Description]                  The structural Measure (Hard-Component) was carried out in 1998.                  Now, the landslide is stable.                  It is not necessary to add the structural measures.</p>	<p>[Resident's awareness and relocation]</p> <p>[Land use restrictions in hazard areas]                  Non</p> <p>[Description]                  As of 2006, as for 2 of 16 extesometer, 3 of 7 inclinometers, 2 of 10 groundwater level meters, a measurement was in a possible. However, it is not measured now.</p>			

# General Information Sheet (Other)

Management number	000000014	Reporter's name:	Youji KASAHARA	Date of report :	June 26, 2012
Address	Pouce Stream	Type*	Stream erosion	latitude	-20.176108
				longitude	57.509739
Schematic sketch			Location map (Scale: 1:25,000)		

\* Description of "Type"

<p style="text-align: center;"><u>River bank erosion</u></p> <p>The Stream erosion is the phenomenon that the soil of the bank is removed by the flow of the river. It occurs in the part which a flow of the water crashes into mainly. Water might overflow when the amount of the stream increases.</p>	<p style="text-align: center;"><u>Damage of Embankment</u></p> <p>The collapse of the road embankment is often generated by a rainfall, infiltration of underground water, erosion by surface water, and a partial catchment. Therefore, it pays attention to the possibility of the catchment. The embankment material might be weak, and it cause by lack of soil compaction.</p>
--	---

Mangement number	0	0	0	0	0	0	0	0	0	1	4
------------------	---	---	---	---	---	---	---	---	---	---	---


## Evaluation sheet

Reporter's name:	Youji KASAHARA
------------------	----------------


[check Point]

Category			Record
Stream	Figure / size	W1 : Width of the river	11.2 m
		W2 : Width of the riverbed	11.2 m
		D : Depth of the river	1.5 m
	Type	Right bank	Soil or Natural ground <u>Artificial structure</u>
		Left bank	Soil or Natural ground <u>Artificial structure</u>
	Box culvert	W : Width	m
		H : Height	m
Pipe culvert	D : Diameter	m	
Type of the damage	Erosion		
	Overflow stream		
	<u>Other</u> (none)		
Embankment	Type of the embankment		
	Embankment		
	Cutting and embankment		
	Structural crack / Open crack		
	Scour under the slope		
	Erosion of the slope		
Type of the damage	A lot of repair parts		
	Other		


Category			Check ✓
History	Existing record of Stream erosion or overflow stream (documents or patrimony)	Obvious	
		slight	
		none	✓
	Existing record of damage on embankment (documents or patrimony)	Obvious	
Slight			
None			
Countermeasure	There is no Countermeasure		
	Effectiveness of Countermeasure	No effect	
		Some effect	
		High effect	✓



Structure of a river



Box culvert



Pipe culvert

[Description]

Every side of the channel is covered by concrete. The water level rises until the upper edge of the channel and erode beyond this point in the rainy season. The gabion has been set up at the lower part of slope at the channel and no damage has been reported yet. However, the deterioration of the concrete wall is remarkable and the extension of the wall height will be necessary. Therefore, further investigation and countermeasures are advisable.



Ph-1 Full view of the channel consolidation works



Ph-2 Stream of the channel consolidation works



Ph-3 Gabion set up in channel consolidation works left bank



Ph-4 There is no damage



Ph-5 End of the gabion



Ph-6 The channel works downstream



# Survey on Structural/Non-structural Measures

Management number 0 0 0 0 0 0 0 0 1 4

Reporter's name: Youji KASAHARA      Date of report : June 26, 2012

Structural Measures (Hard-Component)	
	The kinds of countermeasure
Existing countermeasures	Number
	Gabion(H=1.5m,L=80m)
	1

Non-structural Measure (Soft-Component)	
	The kinds of Monitoring / Spec
Landslide Monitoring Equipment	Number
Warning Threshold	Rainfall
	Movement/displacement
communication means	
evacuation support	

[ The Photo of Countermeasure ]

[ The Photo of Monitoring Equipment ]



None

[Description]  
The gabion has been set up at the lower part of natural slope at the channel to avoid an erosion.



[Resident's awareness and relocation]

[Land use restrictions in hazard areas]

[Description]

[Resident's awareness and relocation]

[Land use restrictions in hazard areas]

[Description]

# General Information Sheet (Slope)

Management number	0 0 0 0 0 0 0 1 5	Reporter's name:	Tomoharu IWASAKI	Date of report :	June 26, 2012
Address	Old Moka Road, Camp Chapelon	Type*	Landslide	latitude	-20.180186
				longitude	57.481508

**Schematic sketch**

**plan view**

**cross section**

**Location map (Scale: 1:25,000)**

**\* Description of "Type"**

	<u>Rock fall</u>	<u>Slope failure</u>	<u>Landslide</u>
<p>Rock Fall : Rock fall is a phenomenon where foliated rocks and gravel due to enlarged cracks in the bedrock or outcropped rocks start to fall down a slope.</p>	<p><b>Rock Fall</b></p>	<p><b>Slope Failure</b></p>	<p><b>Landslide</b></p>
<p>Slope Failure : The slope failures mass detached from steep slope/cliff along surface with little or no shear displacement. Compared to landslides, the quick slope moves on a small-scale, the inclination angle of the slope failure is a relatively high angle (over 30 degrees ).</p>	<p>A landslide is a phenomenon where the soil mass on failure surfaces deep in the ground gradually shifts downward, triggered by heavy rain or earthquake, river erosion, earthworks. Compared to slope failure, the gentler slope moves on a large, the inclination angle of the landslides slope is a relatively low angle (about 5-30 degrees ).</p>	<p>A Debris flow is a phenomenon where soil and boulders are liquefied by surface water or groundwater and tend to flow downward rapidly through a mountain torrent.</p>	<p><b>Debrid Flow</b></p>


Mangement number	0	0	0	0	0	0	0	0	0	1	5
------------------	---	---	---	---	---	---	---	---	---	---	---

## Evaluation sheet


Reporter's name:	Tomoharu IWASAKI
------------------	------------------

[check Point]

Category		Check ✓	
Phenomenon on the Site	Scarp (Main or Minor , Horse shoe shape)		
	Transverse Cracks (Tension or Compression)	✓	
	Pond and Swamp		
	Spring Water	✓	
	Topography with the Step		
	Eembankment at the upper		
	Cut Slope at the toe	✓	
	Wash out by rivers		
	Damage on construction and houses	obvious ( number : )	
		Slight ( number : 5 Houses, 2 Retaining walls )	✓
None			
Monitoring Equipment	There is it (name: Extensometer , number: 3 )	✓	
	There is it (name: , number: )		
	none		
History	Existing record of Landslide (documents or patrimony)	Obvious	
		slight	
		none	
Countermeasure	There is no Countermeasure	✓	
	Effectiveness of Countermeasure	No effect	
		Some effect	
		High effect	



Structure of a landslide




Schematic diagram of landslide landforms

[Description]

The landslide topography is not clear, but five houses and two retaining walls were damaged while the spring water was spotted in two places. There are two possible causes of this, creep transformation of weak surface soil or a shallow landslide. Therefore, landslide investigation and monitoring are necessary while the countermeasures are expected in future.

L=200m ,W=100m



Schematic cross section of inducing factor and artificial cause



Ph-1 Full view



Ph-2 Retaining walls incline



Ph-3 Damage on house



Ph-4 Damage on house



Ph-5 Spring waters



Ph-6 Main scarp

# Survey on Structural/Non-structural Measures

Management number 

0	0	0	0	0	0	0	0	0	1	5
---	---	---	---	---	---	---	---	---	---	---



Reporter's name: Tomoharu IWASAKI      Date of report : June 26, 2012

Structural Measures (Hard-Component)		
	The kinds of landslide countermeasure	Number
Existing landslide countermeasures	None	

Non-structural Measure (Soft-Component)		
	The kinds of Landslide Monitoring / Spec	Number
Warning Threshold	Rainfall	
	Movement/displacement	
communication means		
evacuation support		

[ The Photo of Countermeasure ]

[ The Photo of Monitoring Equipment ]



[Description]  
 The landslide topography is not clear, but five houses and two retaining walls were damaged while the spring water was spotted in two places. There is two possibility for this case which is to be the creep transformation of weak surface soil or the shallow landslides.  
 Therefore, landslide investigation and monitoring are necessary while the countermeasures are expected in future.

[Resident's awareness and relocation]  
  
 [Land use restrictions in hazard areas]  
  
 [Description]

# General Information Sheet (Other)

Management number	000000016	Reporter's name:	Tomoharu IWASAKI	Date of report :	June 15, 2012
Address	Boulevard Victria, Montague Coupe	Type*	Damage of wall	latitude	-20.167972
				longitude	57.514944

Schematic sketch

**plan view**

**cross section**

Location map (Scale: 1:25,000)

**\* Description of "Type"**

Damage of wall	Damage of house	cavern
<p>The disaster of the retaining wall doesn't have the sudden mutation like the rockfall etc. , and deformation does comparatively spending long time. The survey content is shown below.</p> <ul style="list-style-type: none"> <li>Investigation of condition around retaining wall</li> <li>Investigation concerning main body of retaining wall</li> <li>Investigation concerning history</li> </ul>	<p>The crack that occurs on the wall in the house has the following causes.</p> <ul style="list-style-type: none"> <li>• Landslide movement</li> <li>• Lack of bearing capacity</li> <li>• Subsidence of foundation ground</li> <li>• Shoddy workmanship</li> <li>• Other</li> </ul> <p>It is preferable to search for length, width, and the direction of the crack, and to do the continuance observation.</p>	<p>The Cavern occur by the following causes.</p> <ul style="list-style-type: none"> <li>• Infiltration of water from soak away</li> <li>• Infiltration of water from improved pit</li> <li>• other</li> </ul>

Mangement number	0	0	0	0	0	0	0	0	0	1	6
------------------	---	---	---	---	---	---	---	---	---	---	---

## Evaluation sheet

Reporter's name:	Tomoharu IWASAKI
------------------	------------------

[check Point]

Category		Record / check	
Retaining wall	Type of the retaining wall	Concrete block / Concrete Stone masonry <del>(Other (Gabion))</del>	
	H : Height of the retaining wall	West 7 m, East 8 m	
	L : Length of the retaining wall	West 61 m, East 120 m	
	D : Thickness of the retaining wall	West - m, East - m	
	Type of the damage	Collapse / Inclination Hair crack / Open crack other (none)	
House	Type of the damage	<del>Collapse / Inclination Hair crack / Open crack other</del>	
	Cause of damage	<del>Landslide movement Lack of bearing capacity Subsidence of foundation ground Shoddy workmanship other / not clear</del>	
	cavern	W : width of the cavern	m
		L : Length of the cavern	m
		D : Depth of the cavern	m
Situation above the cavern		improved pit / soak away /other	
	Water	Spring water / Ground water	

Category		Check✓	
History	Existing record of damage on wall (documents or patrimony)	Obvious slight none	✓
	Existing record of damage on house (documents or patrimony)	Obvious Slight None	
Countermeasure	There is no Countermeasure		
	Effectiveness of Countermeasure	No effect	
		Some effect	
	High effect	✓	

[Description]

The gabion was installed on the cut-slope when the road was constructed. The height of the each gabion is 1m with a total height on the east side of 8m, and 7m on the west side. There is no record of damage for this site but the angle of the wall is steep. Therefore, the observation of this wall is advisable.




Ph-1 Full view of Gabion wall (East side)



Ph-2 Full view of Gabion wall (West side)



Ph-3 The upper part and the rear of the Gabion wall (East side)  
There is not the abnormality



Ph-4 Dimensions of the Gabion (1m x 2m x 1m)



# Survey on Structural/Non-structural Measures

Management number 0 0 0 0 0 0 0 0 1 6

Reporter's name: Tomoharu IWASAKI Date of report : June 15, 2012

Structural Measures (Hard-Component)	
	The kinds of countermeasure
Existing countermeasures	Number
	Gabion wall


Non-structural Measure (Soft-Component)	
	The kinds of Monitoring / Spec
Monitoring Equipment	Number
Warning Threshold	Rainfall
	Movement/displacement
communication means	
evacuation support	

[ The Photo of Countermeasure ]


[ The Photo of Monitoring Equipment ]



Ph-1 Full view of Gabion wall



Ph-2 cross section



Ph-3 Dimensions of the Gabion (1m×2m×1m)

[Description]

The gabion was piled on the cutted slope when the road was constructed. The height of the each gabion is 1m with a total height on the east side of 8m, and 7m on the west side and the angle of the gabion wall is 1/10.

There is no record of damage for this site but the angle of the wall is steep. Therefore, the observation of this wall is advisable.

[Resident's awareness and relocation]

[Land use restrictions in hazard areas]

[Description]

# General Information Sheet (Slope)

Management number	000000017	Reporter's name:	Ai Togami	Date of report :	June 22, 2012
Address	Pailles : (i) access road to Les Guibies and along motorway, near flyover bridge	Type*	Slope failure	latitude	-20.1855
Schematic sketch			longitude	57.48175	
<p><b>plan view</b></p> <p><b>cross section</b></p>			<p>Location map (Scale: 1:25,000)</p>		

\* Description of "Type"


Rock fall

Rock Fall : Rock fall is a phenomenon where foliated rocks and gravel due to enlarged cracks in the bedrock or outcropped rocks start to fall down a slope.




Slope failure

Slope Failure : The slope failures mass detached from steep slope/cliff along surface with little or no shear displacement. Compared to landslides, the quick slope moves on a small-scale, the inclination angle of the slope failure is a relatively high angle (over 30 degrees ).




Landslide

A landslide is a phenomenon where the soil mass on failure surfaces deep in the ground gradually shifts downward, triggered by heavy rain or earthquake, river erosion, earthworks. Compared to slope failure, the gentler slope moves on a large, the inclination angle of the landslides slope is a relatively low angle (about 5-30 degrees ).



Debris flow

A Debris flow is a phenomenon where soil and boulders are liquefied by surface water or groundwater and tend to flow downward rapidly through a mountain torrent.




Mangement number	0	0	0	0	0	0	0	0	0	1	7
------------------	---	---	---	---	---	---	---	---	---	---	---

## Evaluation sheet


Reporter's name:	Ai Togami
------------------	-----------

[check Point]

Category		Check ✓	
Phenomenon on the Site	Scarp (Main or Minor , Horse shoe shape)	✓	
	Transverse Cracks (Tension or Compression)	✓	
	Pond and Swamp		
	Spring Water		
	Topography with the Step	✓	
	Embankment at the upper		
	Cut Slope at the toe		
	Wash out by rivers		
	Damage on construction and houses	obvious (name: , number: )	
		Slight (name: crack of a wall , number: 1)	✓
None			
Monitoring Equipment	There is it (name: , number: )		
	There is it (name: , number: )		
	none	✓	
History	Existing record of Landslide (documents or patrimony)	Obvious	
		slight	
		none	✓
Countermeasure	Effectiveness of Countermeasure	There is no Countermeasure	✓
		No effect	
		Some effect	
		High effect	



Structure of a landslide




Schematic diagram of landslide landforms

[Description]

The slope failure has been spotted along the cut-slope (5m height) at the roadside of highway. The surface of the cut-slope has been weathered, and it is eroded by rain.

The slope (①~③) is characterized as follows;

- ①The shallow slope failure has been occurred, and this slope has loose stones. It will be necessary to reconsider the retaining wall.
- ②The shallow slope failure has been occurred.
- ③The shallow slope failure has been occurred in this slope. Because the retaining wall keep back a rock, it is safe.



Schematic cross section of inducing factor and artificial cause



Ph-1 Full view of slope failure



Ph-2



Ph-3 upper of slope



Ph-4



Ph-5 crack



Ph-6 slope failure and retaining wall

# Survey on Structural/Non-structural Measures

Management number 0 0 0 0 0 0 0 0 1 7

Reporter's name: Ai Togami Date of report : June 22, 2012

Structural Measures (Hard-Component)	
	The kinds of landslide countermeasure
Existing landslide countermeasures	retaining wall
	3

Non-structural Measure (Soft-Component)					
	The kinds of Landslide Monitoring / Spec				
Landslide Monitoring Equipment					
Warning Threshold	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Rainfall</td> <td></td> </tr> <tr> <td>Movement/displacement</td> <td></td> </tr> </table>	Rainfall		Movement/displacement	
Rainfall					
Movement/displacement					
	communication means				
	evacuation support				

[ The Photo of Countermeasure ]

[ The Photo of Monitoring Equipment ]



[Description]  
 The slope failure has been spotted along the cutting(5m height) at the roadside of highway. Weather on the surface layer causing the erosion it rains. The slope (①~③) is characterized as follows;  
 ①The slope has occurred shallow slope failure and has loose stones. It will be necessary to reconsider the retaining wall.  
 ②The slope is not slope failure and stability by the retaining wall.  
 ③The slope has occurred shallow slope failure. But, the retaining wall keep back rock fall.

[Resident's awareness and relocation]


[Land use restrictions in hazard areas]

[Description]



# General Information Sheet (Other)

Management number	000000018	Reporter's name:	Ai Togami	Date of report :	June 22, 2012
Address	Pailles : (ii) access road Morcellement des Aloes from Avenue M.Leal (on hillside)	Type*	Stream erosion	latitude	-20.2
			longitude	57.483861	

Schematic sketch



Location map (Scale: 1:25,000)



\* Description of "Type"

River bank erosion	Damage of Embankment
<p>The Stream erosion is the phenomenon that the soil of the bank is removed by the flow of the river. It occurs in the part which a flow of the water crashes into mainly. Water might overflow when the amount of the stream increases.</p>	<p>The collapse of the road embankment is often generated by a rainfall, infiltration of underground water, erosion by surface water, and a partial catchment. Therefore, it pays attention to the possibility of the catchment. The embankment material might be weak, and it cause by lack of soil compaction.</p>

Mangement number	0	0	0	0	0	0	0	0	0	1	8
------------------	---	---	---	---	---	---	---	---	---	---	---


## Evaluation sheet

Reporter's name:	Ai Togami
------------------	-----------


[check Point]

Category			Record
Stream	Figure / size	W1 : Width of the river	- m
		W2 : Width of the riverbed	- m
		D : Depth of the river	- m
	Type	Right bank	Soil or Natural ground / Artificial structure
		Left bank	Soil or Natural ground / Artificial structure
	Box culvert	W : Width	m
		H : Height	m
Pipe culvert	D : Diameter	m	
Type of the damage			Erosion Overflow stream Other
Embankment	Type of the embankment		Embankment Cutting and embankment Structural crack / Open crack
	Type of the damage		Scour under the slope Erosion of the slope A lot of repair parts Other


Category			Check ✓
History	Existing record of Stream erosion or overflow stream (documents or patrimony)	Obvious	
		slight	
		none	✓
	Existing record of damage on embankment (documents or patrimony)	Obvious	
Slight			
None			
Countermeasure	There is no Countermeasure		✓
	Effectiveness of Countermeasure	No effect	
		Some effect	
		High effect	



Structure of a river



Box culvert



Pipe culvert

[Description]

Insufficient drainage is causing erosion at the base of the water tank. Immediate remedial work is needed.



Ph-1 Full view



Ph-2 erosion of the groundwork



Ph-3 flow of surface water



# Survey on Structural/Non-structural Measures

Management number 0 0 0 0 0 0 0 0 1 8

Reporter's name: Ai Togami Date of report : June 22, 2012

Structural Measures (Hard-Component)	
	The kinds of countermeasure
Existing countermeasures	concrete

Non-structural Measure (Soft-Component)	
	The kinds of Monitoring / Spec
Monitoring Equipment	
Warning Threshold	Rainfall
	Movement/displacement
communication means	
evacuation support	

[ The Photo of Countermeasure ]

[ The Photo of Monitoring Equipment ]



[Description]  
Imperfection of the drainage causing the erosion at the base of water tank. The maintenace will be the necessary immediately.

[Resident's awareness and relocation]  
  
[Land use restrictions in hazard areas]  
  
[Description]

[Resident's awareness and relocation]  
  
[Land use restrictions in hazard areas]  
  
[Description]

[The Photo of Countermeasure]

[Description]  
Imperfection of the drainage causing the erosion at the base of water tank. The maintenace will be the necessary immediately.

[The Photo of Monitoring Equipment]

[Resident's awareness and relocation]  
  
[Land use restrictions in hazard areas]  
  
[Description]

# General Information Sheet (Slope)

Management number	000000019	Reporter's name:	Tomoharu IWASAKI	Date of report :	June 16, 2012
Address	Pailles : (iii) soreze regin	Type*	Slope failure	latitude	-20.205556
				longitude	57.486583

<p>Schematic sketch</p> <div style="border: 1px solid black; padding: 5px; margin-bottom: 10px;"> <p><b>plan view</b></p> </div> <div style="border: 1px solid black; padding: 5px;"> <p><b>cross section</b></p> </div>	<p>Location map (Scale: 1:25,000)</p>
--	---------------------------------------

\* Description of "Type"

	<u>Rock fall</u>	<u>Slope failure</u>	<u>Landslide</u>
<p>Rock Fall : Rock fall is a phenomenon where foliated rocks and gravel due to enlarged cracks in the bedrock or outcropped rocks start to fall down a slope.</p>			
<p>Slope Failure : The slope failures mass detached from steep slope/cliff along surface with little or no shear displacement. Compared to landslides, the quick slope moves on a small-scale, the inclination angle of the slope failure is a relatively high angle (over 30 degrees ).</p>		<p>A landslide is a phenomenon where the soil mass on failure surfaces deep in the ground gradually shifts downward, triggered by heavy rain or earthquake, river erosion, earthworks. Compared to slope failure, the gentler slope moves on a large, the inclination angle of the landslides slope is a relatively low angle (about 5-30 degrees ).</p>	
			<p>A Debris flow is a phenomenon where soil and boulders are liquefied by surface water or groundwater and tend to flow downward rapidly through a mountain torrent.</p>


Mangement number	0	0	0	0	0	0	0	0	0	1	9
------------------	---	---	---	---	---	---	---	---	---	---	---

## Evaluation sheet


Reporter's name:	Tomoharu IWASAKI
------------------	------------------

[check Point]

Category		Check ✓	
Phenomenon on the Site	Scarp (Main or Minor , Horse shoe shape)		
	Transverse Cracks (Tension or Compression)	✓	
	Pond and Swamp		
	Spring Water		
	Topography with the Step	✓	
	Eembankment at the upper		
	Cut Slope at the toe	✓	
	Wash out by rivers		
	Damage on construction and houses	obvious ( number : )	
		Slight ( number : 2 houses )	✓
None			
Monitoring Equipment	There is it (name: Extensometer , number: )		
	There is it (name: , number: )		
	none	✓	
History	Existing record of Landslide (documents or patrimony)	Obvious	
		slight	
		none	
Countermeasure	There is no Countermeasure	✓	
	Effectiveness of Countermeasure	No effect	
		Some effect	
		High effect	



Structure of a landslide




Schematic diagram of landslide landforms

[Description]

Falling rocks at the upper slope and shallow slope failure at the middle and lower slope occurred in an area of housing. There is only slight damage for now, although shallow slope failure and cracks have been confirmed.

The cause of shallow slope failure is supposed as follows ;

- (1) The inclination of the slope is relatively a steep angle
- (2) The surface soil is weak colluvium which weathered
- (3) Cut earthwork with the toe of the slope
- (4) Construction of the house at the upper part of slope



Schematic cross section of inducing factor and artificial cause



Ph-1 Full view



Ph-2 Rock Fall



Ph-3 Cracks on the road (Upper road)



Ph-4 Damage on house



Ph-5 Toe of the slope



Ph-6 Cracks on the road (Lower road)

# Survey on Structural/Non-structural Measures

Management number 

0	0	0	0	0	0	0	0	0	1	9
---	---	---	---	---	---	---	---	---	---	---



Reporter's name: Tomoharu IWASAKI      Date of report : June 16, 2012

Structural Measures (Hard-Component)		
	The kinds of landslide countermeasure	Number
Existing landslide countermeasures	None	

Non-structural Measure (Soft-Component)		
	The kinds of Landslide Monitoring / Spec	Number
Landslide Monitoring Equipment		
Warning Threshold	Rainfall	
	Movement/displacement	
	communication means	
	evacuation support	

[ The Photo of Countermeasure ]

[ The Photo of Monitoring Equipment ]



[Description]  
 Falling rock at the upper slope and shallow slope failure at the middle and lower slope occurred at the housing area. There are slight damage for now although the shallow slope failure and cracks has been confirmed.

[Resident's awareness and relocation]  
  
 [Land use restrictions in hazard areas]  
  
 [Description]

# General Information Sheet (Slope)

Management number	0 0 0 0 0 0 0 2 0	Reporter's name :	Tomoharu IWASAKI	Date of report :	June 27, 2012		
Address	Plaine Champagne Road, opposite "Musee Touche Dubois"	Type*	Slope failure	latitude	-20.424294	longitude	57.417614

<p>Schematic sketch</p> <p><b>plan view</b></p> <p><b>cross section</b></p>	<p>Location map (Scale: 1:25,000)</p>
---	---------------------------------------

\* Description of "Type"

Rock fall	Slope failure	Landslide	Debris flow
<p>Rock Fall : Rock fall is a phenomenon where foliated rocks and gravel due to enlarged cracks in the bedrock or outcropped rocks start to fall down a slope.</p>	<p>Slope Failure : The slope failures mass detached from steep slope/cliff along surface with little or no shear displacement. Compared to landslides, the quick slope moves on a small-scale, the inclination angle of the slope failure is a relatively high angle (over 30 degrees ).</p>	<p>Landslide is a phenomenon where the soil mass on failure surfaces deep in the ground gradually shifts downward, triggered by heavy rain or earthquake, river erosion, earthworks. Compared to slope failure, the gentler slope moves on a large, the inclination angle of the landslides slope is a relatively low angle (about 5-30 degrees ).</p>	<p>A Debris flow is a phenomenon where soil and boulders are liquefied by surface water or groundwater and tend to flow downward rapidly through a mountain torrent.</p>


Mangement number	0	0	0	0	0	0	0	0	0	2	0
------------------	---	---	---	---	---	---	---	---	---	---	---

## Evaluation sheet


Reporter's name:	Tomoharu IWASAKI
------------------	------------------

[check Point]

Category		Check ✓	
Phenomenon on the Site	Scarp (Main or Minor , Horse shoe shape)	✓	
	Transverse Cracks (Tension or Compression)		
	Pond and Swamp		
	Spring Water		
	Topography with the Step		
	Eembankment at the upper		
	Cut Slope at the toe	✓	
	Wash out by rivers		
	Damage on construction and houses	obvious ( number : )	
		Slight ( number : 2 cracks of walls )	✓
None			
Monitoring Equipment	There is it ( name: , number: )		
	There is it ( name: , number: )		
	none	✓	
History	Existing record of Landslide (documents or patrimony)	Obvious	
		slight	
		none	
Countermeasure	There is no Countermeasure		
	Effectiveness of Countermeasure	No effect	
		Some effect	✓
High effect			




Structure of a landslide



Schematic diagram of landslide landforms

[Description]

Retaining walls have been constructed as countermeasures where the slope failure has been confirmed. It is currently stable, although there were a few cracks spotted in the retaining walls which are believed to be due to substandard construction.



Schematic cross section of inducing factor and artificial cause



Ph-1 Full view (Retaining wall)



Ph-2 Trace of past slope failure



Ph-3 Trace of past slope failure



Ph-4 Cracks on retaining wall



Ph-5 Cracks on retaining wall



# Survey on Structural/Non-structural Measures

Management number 0 0 0 0 0 0 0 0 2 0

Reporter's name: Tomoharu IWASAKI Date of report : June 27, 2012

Structural Measures (Hard-Component)	
	The kinds of landslide countermeasure
Existing landslide countermeasures	Retaining wall

Non-structural Measure (Soft-Component)	
	The kinds of Landslide Monitoring / Spec
Landslide Monitoring Equipment	
Warning Threshold	Rainfall
	Movement/displacement
communication means	
evacuation support	

[ The Photo of Countermeasure ]

[ The Photo of Monitoring Equipment ]



Ph-1 Countermeasure (Retaining walls)

[Description]  
The retaining walls was constructed as countermeasures where the slope failure has been confirmed. It is stable although there were a few cracks spotted within retaining walls which is believed to be the construction failure.  
It is not necessary to take a countermeasure immediately, but should be observed.

[The Photo of Monitoring Equipment]

[Resident's awareness and relocation]  
  
[Land use restrictions in hazard areas]  
  
[Description]

[The Photo of Countermeasure]



[Description]  
The retaining walls was constructed as countermeasures where the slope failure has been confirmed. It is stable although there were a few cracks spotted within retaining walls which is believed to be the construction failure.  
It is not necessary to take a countermeasure immediately, but should be observed.

[The Photo of Monitoring Equipment]

[Resident's awareness and relocation]  
  
[Land use restrictions in hazard areas]  
  
[Description]

# General Information Sheet (Other)

Management number	000000021	Reporter's name:	YojiKASAHARA	Date of report :	June 27, 2012
Address	Chamarel : (i) near Reataurant Le Chamarel	Type*	Damage of Embankment	latitude	-20.421694
			longitude	57.386336	



\* Description of "Type"

<p><u>River bank erosion</u></p> <p>The Stream erosion is the phenomenon that the soil of the bank is removed by the flow of the river. It occurs in the part which a flow of the water crashes into mainly. Water might overflow when the amount of the stream increases.</p> <p>water colliding</p> <p>Past riverbed</p> <p>Present riverbed</p>	<p><u>Damage of Embankment</u></p> <p>The collapse of the road embankment is often generated by a rainfall, infiltration of underground water, erosion by surface water, and a partial catchment. Therefore, it pays attention to the possibility of the catchment. The embankment material might be weak, and it cause by lack of soil compaction.</p> <p>Rainfall</p> <p>Surface water</p> <p>Cross section</p> <p>Concentration of surface water</p> <p>Signs of stream</p>
--	--

Mangement number	0	0	0	0	0	0	0	0	0	2	1
------------------	---	---	---	---	---	---	---	---	---	---	---


## Evaluation sheet

Reporter's name:	YoujiKASAHARA
------------------	---------------


[check Point]

Category			Record	
Stream	Figure / size	W1 : Width of the river	m	
		W2 : Width of the riverbed	m	
		D : Depth of the river	m	
	Type	Right bank	Soil or Natural ground / Artificial structure	
		Left bank	Soil or Natural ground / Artificial structure	
	Box culvert	W : Width	m	
		H : Height	m	
	Pipe culvert	D : Diameter	m	
	Type of the damage			Erosion
				Overflow stream
			Other	
Embankment	Type of the embankment		Embankment	
			Cutting and embankment	
			Structural crack Open crack	
	Type of the damage		Scour under the slope	
			Erosion of the slope	
			A lot of repair parts	
		Other		


Category		Check ✓	
History	Existing record of Stream erosion or overflow stream (documents or patrimony)	Obvious	
		slight	
		none	
	Existing record of damage on embankment (documents or patrimony)	Obvious	
Slight		✓	
None			
Countermeasure	There is no Countermeasure		✓
	Effectiveness of Countermeasure	No effect	
		Some effect	
		High effect	



Structure of a river



Box culvert




Pipe culvert

[Description]

Cracks in the road shoulder have occurred due to a lack of bearing capacity .  
 The crack is located in the vicinity of the boundary of the cutting ground and the fill.  
 The subsidence of the road is 10-15cm.  
 The soil compaction is insufficient.  
 The fill material is soft.

It is caused by insufficient soil compaction.



Ph-1 Crack on road side



Ph-2 Crack on road side



Ph-3 The crack occurred in the road sea side shoulder. (By the damage of differential settlement)



Ph-4 Slope under shoulder



Ph-5 Waterway under slope



Ph-6 Road constructed with fill

# Survey on Structural/Non-structural Measures

Management number 

0	0	0	0	0	0	0	0	2	1
---	---	---	---	---	---	---	---	---	---

Reporter's name: YoujiKASAHARA      Date of report : June 27, 2012

Structural Measures (Hard-Component)		
Existing countermeasures	The kinds of countermeasure	Number
	<i>Retaining wall</i>	1

Non-structural Measure (Soft-Component)		
Monitoring Equipment	The kinds of Monitoring / Spec	Number
Warning Threshold	Rainfall	
	Movement/displacement	
communication means		
evacuation support		

[ The Photo of Countermeasure ]

[ The Photo of Monitoring Equipment ]

None	None
------	------

--	--

Non	<p>[Description] The road of the cliff side submerged(10-15cm) causing cracks on the asphalt surface. It is caused by insufficient soil compaction. Further observation will be necessary.</p>
-----	--

	<p>[Resident's awareness and relocation]</p> <p>[Land use restrictions in hazard areas]</p> <p>[Description]</p>
--	--

# General Information Sheet (Other)

Management number	0 0 0 0 0 0 0 0 2 2	Reporter's name:	Tomoharu IWASAKI	Date of report :	June 27, 2012
Address	Chamarel : (ii) Roadside	Type*	Damage of Embankment	latitude	-20.416861
Schematic sketch			Location map (Scale: 1:25,000)		
<div style="display: flex; justify-content: space-around;"> <div style="border: 1px solid black; padding: 5px; width: 45%;"> <p><b>plan view</b></p> </div> <div style="border: 1px solid black; padding: 5px; width: 45%;"> <p><b>cross section</b></p> </div> </div>					

**\* Description of "Type"**

<p style="text-align: center;"><u>River bank erosion</u></p> <p>The Stream erosion is the phenomenon that the soil of the bank is removed by the flow of the river. It occurs in the part which a flow of the water crashes into mainly. Water might overflow when the amount of the stream increases.</p>	<p style="text-align: center;"><u>Damage of Embankment</u></p> <p>The collapse of the road embankment is often generated by a rainfall, infiltration of underground water, erosion by surface water, and a partial catchment. Therefore, it pays attention to the possibility of the catchment. The embankment material might be weak, and it cause by lack of soil compaction.</p>
--	---

Mangement number	0	0	0	0	0	0	0	0	0	2	2
------------------	---	---	---	---	---	---	---	---	---	---	---


## Evaluation sheet

Reporter's name:	Tomoharu IWASAKI
------------------	------------------


[check Point]

Category			Record	
Stream	Figure / size	W1 : Width of the river	m	
		W2 : Width of the riverbed	m	
		D : Depth of the river	m	
	Type	Right bank	Soil or Natural ground / Artificial structure	
		Left bank	Soil or Natural ground / Artificial structure	
	Box culvert	W : Width	m	
		H : Height	m	
	Pipe culvert	D : Diameter	m	
	Type of the damage			Erosion
				Overflow stream
			Other	
Embankment	Type of the embankment		Embankment	
			<del>Cutting and embankment</del>	
			<del>Structural crack</del> / Open crack	
	Type of the damage		Scour under the slope	
			<del>Erosion of the slope</del>	
			A lot of repair parts	
			Other	


Category			Check ✓
History	Existing record of Stream erosion or overflow stream (documents or patrimony)	Obvious	
		slight	
		none	
	Existing record of damage on embankment (documents or patrimony)	Obvious	
Slight			
None		✓	
Countermeasure	There is no Countermeasure		
	Effectiveness of Countermeasure	No effect	✓
		Some effect	
		High effect	



Structure of a river



Box culvert



Pipe culvert

[Description]

Deformation of the road has been confirmed at the shoulder of the road due to a lack of bearing capacity.  
 The embankment of stone masonry wall and retaining wall were constructed but it is insufficient.  
 Therefore, the re-construction of the retaining wall and stone masonry wall will be necessary in the near future.



Ph-2 Retaining wall of the road shoulder (A-A' cross section)



Ph-3 Stone masonry wall of the road shoulder (B-B' cross section)

Ph-1 Full view (Cracks and subsidence on the road)



# Survey on Structural/Non-structural Measures

Management number 0 0 0 0 0 0 0 0 2 2

Reporter's name: Tomoharu IWASAKI Date of report : June 27, 2012

Structural Measures (Hard-Component)	
	The kinds of countermeasure
Existing countermeasures	Number
	Retaining wall
	Stone masonry wall

Non-structural Measure (Soft-Component)	
	The kinds of Monitoring / Spec
Monitoring Equipment	Number
Warning Threshold	Rainfall
	Movement/displacement
communication means	
evacuation support	

[ The Photo of Countermeasure ]

[ The Photo of Monitoring Equipment ]



Ph-1 Retaining wall



Ph-2 Stone masonry wall





[Description]  
 Deformation of the road has been confirmed at the cliff side of the road due to the lack of bearing capacity. The embankment of stone masonry wall and retaining wall are constructed but it is insufficient. Therefore, the re-construction of the retaining wall and stone masonry wall will be necessary in the near future.

[Resident's awareness and relocation]  
  
 [Land use restrictions in hazard areas]  
  
 [Description]




# General Information Sheet (Other)

Management number	000000023	Reporter's name:	Youji /KASAHARA	Date of report :	June 27, 2012
Address	Grande Riviere Noire Village Hall	Type*	Damage of house	latitude	-20.359844
				longitude	57.371564

<p>Schematic sketch</p> <div style="border: 1px solid black; padding: 5px; margin-bottom: 10px;">plan view</div>  <div style="border: 1px solid black; padding: 5px; margin-bottom: 10px;">cross section</div> 	<p>Location map (Scale: 1:25,000)</p>  <div style="text-align: center;">  <p>1/25,000</p> </div>
---	---

**\* Description of "Type"**

<u>Damage of wall</u>	<u>Damage of house</u>	<u>cavern</u>
<p>The disaster of the retaining wall doesn't have the sudden mutation like the rockfall etc. , and deformation does comparatively spending long time. The survey content is shown below.</p> <ul style="list-style-type: none"> <li>Investigation of condition around retaining wall</li> <li>Investigation concerning main body of retaining wall</li> <li>Investigation concerning history</li> </ul>	<p>The crack that occurs on the wall in the house has the following causes.</p> <ul style="list-style-type: none"> <li>Landslide movement</li> <li>Lack of bearing capacity</li> <li>Subsidence of foundation ground</li> <li>Shoddy workmanship</li> <li>Other</li> </ul> <p>It is preferable to search for length, width, and the direction of the crack, and to do the continuance observation.</p>	<p>The Cavern occur by the following causes.</p> <ul style="list-style-type: none"> <li>Infiltration of water from soak away</li> <li>Infiltration of water from improved pit</li> <li>other</li> </ul>
		

Mangement number	0	0	0	0	0	0	0	0	0	2	3
------------------	---	---	---	---	---	---	---	---	---	---	---

## Evaluation sheet

Reporter's name:	Youji /KASAHARA
------------------	-----------------

[check Point]

Category		Record / check
Retaining wall	Type of the retaining wall	Concrete block / Concrete Stone masonry / Other
	H : Height of the retaining wall	m
	L : Length of the retaining wall	m
	D : Thickness of the retaining wall	m
	Type of the damage	Collapse / Inclination Hair crack / Open crack other
House	Type of the damage	Collapse / Inclination Hair crack / <u>Open crack</u> other
	Cause of damage	Landslide movement
		<u>Lack of bearing capacity</u>
		Subsidence of foundation ground
		Shoddy workmanship other / not clear
cavern	W : width of the cavern	m
	L : Length of the cavern	m
	D : Depth of the cavern	m
	Situation above the cavern	improved pit / soak away /other
	Water	Spring water / Ground water

Category		Check✓	
History	Existing record of damage on wall (documents or patrimony)	Obvious	
		slight	
	Existing record of damage on house (documents or patrimony)	none	
		Obvious	
Countermeasure	Effectiveness of Countermeasure	Slight	
		None	✓
		There is no Countermeasure	✓
	Effectiveness of Countermeasure	No effect	
Some effect			
High effect			

[Description]

The crack at the base of village hall area and edge of concrete basketball court has been confirmed. However, the surrounding structures are not affected, therefore it is considered unlikely this damaged was caused by landslides. Rather it is likely to be caused by lack of bearing capacity of the ground or a problem with the structure itself.



Ph-1 Full view of Black River Government School



Ph-2 Cracks of wall (by differential settlement)



Ph-3 Horizontal crack of the Concrete step



Ph-4 Full view on sea side



Ph-5 Non dimensions in the wall



Ph-6 Sutiation in the back of School (fill-up ground)

# Survey on Structural/Non-structural Measures

Management number 0 0 0 0 0 0 0 0 2 3

Reporter's name: Youji /KASAHARA Date of report : June 27, 2012

Structural Measures (Hard-Component)	
	The kinds of countermeasure
Existing countermeasures	None

Non-structural Measure (Soft-Component)	
	The kinds of Monitoring / Spec
Monitoring Equipment	
Warning Threshold	Rainfall
	Movement/displacement
communication means	
evacuation support	

[ The Photo of Countermeasure ]

[ The Photo of Monitoring Equipment ]




None	None
------	------

--	--

None	<p>[Description] The crack at the base of village hall area and edge of concrete basketball court has been confirmed. However, the surrounding structure are not affected and unlikely to think the damaged was caused by lanslides. It would rather caused by lack of bearing capacity of the ground or problem on structure itself.</p>
------	---

	<p>[Resident's awareness and relocation]</p> <p>[Land use restrictions in hazard areas]</p> <p>[Description]</p>
--	--

# General Information Sheet (Slope)

Management number	000000024	Reporter's name:	Youji KASAHARA	Date of report :	June 28, 2012
Address	Baie du Cap : (i) Near St Francois d'Assise Church	Type*	Debris flow	latitude	-20.496442
Schematic sketch			Location map (Scale: 1:25,000)		
 <p>Labels in sketch: School, House (Non deformation), Block Wall, Deposit, Channel consolidation works.</p>			 <p>Scale: 0 500 1,000m 1/25,000</p>		
<p><b>Cross section</b></p>  <p>Labels in cross-section: School, House (Non deformation), Concreat Wall, Block Wall, Water level in rainy season, 3.5m, Deposit, 1.5m, Channel consolidation works.</p>					

\* Description of "Type"


Rock fall

Rock Fall : Rock fall is a phenomenon where foliated rocks and gravel due to enlarged cracks in the bedrock or outcropped rocks start to fall down a slope.




Slope failure

Slope Failure : The slope failures mass detached from steep slope/cliff along surface with little or no shear displacement. Compared to landslides, the quick slope moves on a small-scale, the inclination angle of the slope failure is a relatively high angle (over 30 degrees ).




Landslide

A landslide is a phenomenon where the soil mass on failure surfaces deep in the ground gradually shifts downward, triggered by heavy rain or earthquake, river erosion, earthworks. Compared to slope failure, the gentler slope moves on a large, the inclination angle of the landslides slope is a relatively low angle (about 5-30 degrees ).



Debris flow

A Debris flow is a phenomenon where soil and boulders are liquefied by surface water or groundwater and tend to flow downward rapidly through a mountain torrent.




Mangement number	0	0	0	0	0	0	0	0	0	2	4
------------------	---	---	---	---	---	---	---	---	---	---	---

## Evaluation sheet


Reporter's name:	Youji KASAHARA
------------------	----------------

[check Point]

Category		Check ✓	
Phenomenon on the Site	Scarp (Main or Minor , Horse shoe shape)		
	Transverse Cracks (Tension or Compression)		
	Pond and Swamp		
	Spring Water		
	Topography with the Step		
	Eembankment at the upper		
	Cut Slope at the toe		
	Wash out by rivers		
	Damage on construction and houses	obvious (name: road , number: 1 )	✓
		Slight (name: , number: )	
None			
Monitoring Equipment	There is it (name: , number: )		
	There is it (name: , number: )		
	none		
History	Existing record of Landslide (documents or patrimony)	Obvious slight none	
		Obvious	
		slight	
Countermeasure	There is no Countermeasure		
	Effectiveness of Countermeasure	No effect	
		Some effect	✓
High effect			




Structure of a landslide



Schematic diagram of landslide landforms

[Description]

A debris flow has occurred in the past and a block wall has since been constructed. The water level rises considerably in the rainy season, soil and gravel might flow out on the road. Also, small surface failures have been observed frequently in this area.



Schematic cross section of inducing factor and artificial cause



Ph-1 Full view of the channel works



Ph-2 Unstable deposit in channel works



Ph-3 The upstream of channel works



Ph-4 Box culvert



Ph-5 Discharged sediment at the mouth of stream



Ph-6 Discharged sediment at the mouth of stream





Ph-1 Full view of overcrowded house



Ph-2 Shore terrace where it faces road



Ph-3 Shore terrace where it faces road



Ph-4 Slope where outflow of gravel and soil are expected



Ph-5 Surface collapse of slope

# Survey on Structural/Non-structural Measures

Management number 

0	0	0	0	0	0	0	0	2	4
---	---	---	---	---	---	---	---	---	---

Reporter's name: Youji KASAHARA Date of report : June 28, 2012

Structural Measures (Hard-Component)	
	The kinds of countermeasure
Existing countermeasures	Channel consolidation works

Non-structural Measure (Soft-Component)	
	The kinds of Monitoring / Spec
Landslide Monitoring Equipment	
Warning Threshold	Rainfall
	Movement/displacement
communication means	
evacuation support	

[ The Photo of Countermeasure ]

[ The Photo of Monitoring Equipment ]



[Description]  
It is not enough though the valley shore erosion is prevented by channel works.  
There is a possibility that the stream begins to overflow from channel works in the rainy season. It is necessary to extend the upstream side channel works in the future.

[Resident's awareness and relocation]

[Land use restrictions in hazard areas]

[Description]

# General Information Sheet (Slope)

Management number	000000025	Reporter's name:	Tomoharu IWASAKI	Date of report :	June 28, 2012
Address	Baie du Cap :(ii) Maconde Region	Type*	Rock fall	latitude	-20.490014
				longitude	57.371461

<p>Schematic sketch</p> <div style="border: 1px solid black; padding: 5px; margin-bottom: 10px;"> <p><b>plan view</b></p> </div> <div style="border: 1px solid black; padding: 5px;"> <p><b>cross section</b></p> </div>	<p>Location map (Scale: 1:25,000)</p>
--	---------------------------------------

\* Description of "Type"

	<u>Rock fall</u>	<u>Slope failure</u>	<u>Landslide</u>
<p>Rock Fall : Rock fall is a phenomenon where foliated rocks and gravel due to enlarged cracks in the bedrock or outcropped rocks start to fall down a slope.</p>	<p>Slope Failure : The slope failures mass detached from steep slope/cliff along surface with little or no shear displacement. Compared to landslides, the quick slope moves on a small-scale, the inclination angle of the slope failure is a relatively high angle (over 30 degrees ).</p>	<p>A landslide is a phenomenon where the soil mass on failure surfaces deep in the ground gradually shifts downward, triggered by heavy rain or earthquake, river erosion, earthworks. Compared to slope failure, the gentler slope moves on a large, the inclination angle of the landslides slope is a relatively low angle (about 5-30 degrees ).</p>	<p>A Debris flow is a phenomenon where soil and boulders are liquefied by surface water or groundwater and tend to flow downward rapidly through a mountain torrent.</p>
	<p><b>Rock Fall</b></p>	<p><b>Slope Failure</b></p>	<p><b>Landslide</b></p>
			<p><b>Debris Flow</b></p>


Mangement number	0	0	0	0	0	0	0	0	2	5
------------------	---	---	---	---	---	---	---	---	---	---

## Evaluation sheet


Reporter's name:	Tomoharu IWASAKI
------------------	------------------

[check Point]

Category		Check ✓	
Phenomenon on the Site	Scarp (Main or Minor , Horse shoe shape)		
	Transverse Cracks (Tension or Compression)		
	Pond and Swamp		
	Spring Water		
	Topography with the Step		
	Eembankment at the upper		
	Cut Slope at the toe		
	Wash out by rivers		
	Damage on construction and houses	obvious ( number : )	
		Slight ( number : )	
None		✓	
Monitoring Equipment	There is it (name: , number: )		
	There is it (name: , number: )		
	none		
History	Existing record of Landslide (documents or patrimony)	Obvious	
		slight	
		none	
Countermeasure	There is no Countermeasure		
	Effectiveness of Countermeasure	No effect	
		Some effect	
		High effect	




Structure of a landslide



Schematic diagram of landslide landforms

[Description]

A new road was built to reduce the damage from rock falls. However, rock falls and small rock failures are also a frequent occurrence along the new road. The rocks are weathered, and there is a high possibility of rock fall in future.




Schematic cross section of inducing factor and artificial cause



Ph-1 Full view



Ph-2 The rock constituting a cliff (many cracks and weathering intensely)



Ph-3 Example of the rock fall




Ph-4 Rock fall



Ph-5 Rock fall

# Survey on Structural/Non-structural Measures

Management number	0 0 0 0 0 0 0 0 2 5	Reporter's name:	Tomoharu IWASAKI	Date of report :	June 28, 2012	
<b>Structural Measures (Hard-Component)</b>		<b>Non-structural Measure (Soft-Component)</b>				
Existing landslide countermeasures	The kinds of landslide countermeasure	Number	The kinds of Landslide Monitoring / Spec			Number
	None					
[ The Photo of Countermeasure ]		[ The Photo of Monitoring Equipment ]				
<p>[Description] The falling rock and small bedrock decay occurs frequently at the bedrock cliffs along the road. The rocks are weathered and there is a high possibility of rock falling in future. As countermeasures of the falling rock, you should consider the setting such as rock nets.</p> <div style="text-align: right;">  </div> <p>(Sample of the rock net)</p>		<p>[Resident's awareness and relocation]</p> <p>[Land use restrictions in hazard areas]</p> <p>[Description]</p>				

# General Information Sheet (Other)

Management number	0 0 0 0 0 0 0 2 6	Reporter's name:	Ai Togami	Date of report :	June 18, 2012
Address	Riviere des Anguilles, near the bridge	Type*	Stream erosion	latitude	-20.49375
				longitude	57.55578
Schematic sketch			Location map (Scale: 1:25,000)		
<div data-bbox="212 367 851 1053"> <p><b>cross section</b></p> </div>			<div data-bbox="1142 367 2038 1117"> </div>		

\* Description of "Type"

<p style="text-align: center;"><u>River bank erosion</u></p> <p>The Stream erosion is the phenomenon that the soil of the bank is removed by the flow of the river. It occurs in the part which a flow of the water crashes into mainly. Water might overflow when the amount of the stream increases.</p>	<p style="text-align: center;"><u>Damage of Embankment</u></p> <p>The collapse of the road embankment is often generated by a rainfall, infiltration of underground water, erosion by surface water, and a partial catchment. Therefore, it pays attention to the possibility of the catchment. The embankment material might be weak, and it cause by lack of soil compaction.</p>
--	---

Mangement number	0	0	0	0	0	0	0	0	0	2	6
------------------	---	---	---	---	---	---	---	---	---	---	---


## Evaluation sheet

Reporter's name:	Tomoharu IWASAKI
------------------	------------------


[check Point]

Category			Record
Stream	Figure / size	W1 : Width of the river	- m
		W2 : Width of the riverbed	- m
		D : Depth of the river	40-50 m
	Type	Right bank	Soil or Natural ground / Artificial structure
		Left bank	Soil or Natural ground / Artificial structure
	Box culvert	W : Width	m
		H : Height	m
Pipe culvert	D : Diameter	m	
Type of the damage	Erosion		
	Overflow stream		
	Other		
Embankment	Type of the embankment		
	Embankment		
	Cutting and embankment		
	Structural crack / Open crack		
	Type of the damage		
	Scour under the slope		
Erosion of the slope			
A lot of repair parts			
Other			


Category			Check ✓
History	Existing record of Stream erosion or overflow stream (documents or patrimony)	Obvious	
		slight	
		none	✓
	Existing record of damage on embankment (documents or patrimony)	Obvious	
Slight			
None			
Countermeasure	There is no Countermeasure		✓
	Effectiveness of Countermeasure	No effect	
		Some effect	
		High effect	



Structure of a river



Box culvert



Pipe culvert

[Description]

There are many houses built on the cliff here. The cliff is weathered severely and stream erosion occurs frequently. Therefore, the house will need to be relocated.





Ph-1 Full view



Ph-2 cave in slope



Ph-3



Ph-4 relation slope and house

# Survey on Structural/Non-structural Measures

Management number 0 0 0 0 0 0 0 0 2 6

Reporter's name: *Ai Togami* Date of report : *June 18, 2012*

Structural Measures (Hard-Component)		
	The kinds of landslide countermeasure	Number
Existing landslide countermeasures	None	

Non-structural Measure (Soft-Component)		
	The kinds of Landslide Monitoring / Spec	Number
Landslide Monitoring Equipment		
Warning Threshold	Rainfall	
	Movement/displacement	
communication means		
evacuation support		

[ The Photo of Countermeasure ]

[ The Photo of Monitoring Equipment ]









None	None
------	------

--	--

None	<p>[Description] There were many houses built on a cliff. The cliff are weathered severely and the stream erosion occurs frequently. Therefore, the relocation of the houses will be necessary</p>
------	--

	<p>[Resident's awareness and relocation]</p> <p>[Land use restrictions in hazard areas]</p> <p>[Description]</p>
--	--

# General Information Sheet (Slope)

Management number	000000027	Reporter's name:	Tomoharu IWASAKI	Date of report :	June 18, 2012
Address	Quatre Soeurs, Marie Jeanne, Jhummah Streert, Old Grand Port	Type*	Landslide	latitude	-20.424294
Schematic sketch			Location map (Scale: 1:25,000)		
 <p>  Scarp or step   Heavy damage on slope   Trial Pit   Hand excavated Trial Pit   Borehole   Thalweg         </p> <p>約350m</p> <p>Existing borehole for the manual monitoring of ground water</p>			 <p>0 500 1,000m 1/25,000</p>		

\* Description of "Type"


Rock fall

Rock Fall : Rock fall is a phenomenon where foliated rocks and gravel due to enlarged cracks in the bedrock or outcropped rocks start to fall down a slope.




Slope failure

Slope Failure : The slope failures mass detached from steep slope/cliff along surface with little or no shear displacement. Compared to landslides, the quick slope moves on a small-scale, the inclination angle of the slope failure is a relatively high angle (over 30 degrees ).




Landslide

A landslide is a phenomenon where the soil mass on failure surfaces deep in the ground gradually shifts downward, triggered by heavy rain or earthquake, river erosion, earthworks. Compared to slope failure, the gentler slope moves on a large, the inclination angle of the landslides slope is a relatively low angle (about 5-30 degrees ).



Debris flow

A Debris flow is a phenomenon where soil and boulders are liquefied by surface water or groundwater and tend to flow downward rapidly through a mountain torrent.




Mangement number	0	0	0	0	0	0	0	0	2	7
------------------	---	---	---	---	---	---	---	---	---	---

## Evaluation sheet


Reporter's name:	Tomoharu IWASAKI
------------------	------------------

[check Point]

Category		Check ✓	
Phenomenon on the Site	Scarp (Main or Minor , Horse shoe shape)	✓	
	Transverse Cracks (Tension or Compression)	✓	
	Pond and Swamp		
	Spring Water		
	Topography with the Step	✓	
	Eembankment at the upper		
	Cut Slope at the toe	✓	
	Wash out by rivers		
	Damage on construction and houses	obvious ( number : 5 houses )	✓
		Slight ( number : )	
None			
Monitoring Equipment	There is it (name: Borehole for Ground Water Level, number: 6 )	✓	
	There is it (name: , number: )		
	none		
History	Existing record of Landslide (documents or patrimony)	Obvious (Document, 2011)	
		slight	
		none	
Countermeasure	There is no Countermeasure	✓	
	Effectiveness of Countermeasure	No effect	
		Some effect	
High effect			



Structure of a landslide



Schematic diagram of landslide landforms


[Description]

Landslide activity has been confirmed at the Quatre Soeurs area where many houses have been damaged. This landslide shows some typical characteristics as follows,

- (1) Scarps (Horse shoe Scarp),
- (2) Steps on Tension Cracks.
- (3) Cut Slope at toe (for road and house)

The groundwater level at the lower part of the landslide is high and is causing instability in the landslide. Drilling investigation and monitoring have been carried out, but not sufficiently. Further investigation and monitoring are necessary while the countermeasures are expected in future. L=350m ,W=400m

Existing record of Landslide(documents) : GEOTECHNICAL REPORT FOR SUSPECTED LANDSLIDE AT QUATRE SOEURS. MPI. 2011



Schematic cross section of inducing factor and artificial cause



Ph-1 Full view



Ph-2 Scarps of the landslide upper part



Ph-3 Scarps of the landslide upper part



Ph-4 Head crack of a small landslide of the lower part












Ph-5 Existing borehole for the manual monitoring of ground water level



Ph-6 Heavy damage on house

# Survey on Structural/Non-structural Measures

Management number	0 0 0 0 0 0 0 0 2 7	Reporter's name:	Tomoharu IWASAKI	Date of report :	June 18, 2012	
<b>Structural Measures (Hard-Component)</b>			<b>Non-structural Measure (Soft-Component)</b>			
Existing landslide countermeasures	The kinds of landslide countermeasure	Number	Landslide Monitoring Equipment	The kinds of Landslide Monitoring / Spec		Number
	None			Existing borehole for ground water level monitoring		6
[ The Photo of Countermeasure ]			[ The Photo of Monitoring Equipment ]			
<div style="display: flex; justify-content: space-around;">   </div>			<div style="display: flex; justify-content: space-around;">    </div>			
			<div style="display: flex; justify-content: space-around;">   </div>			
[Description] The landslide is not stable. The countermeasures are expected in future.			[Resident's awareness and relocation] Residents feel danger, and hope for landslide measures or relocation.			
<div style="display: flex; justify-content: space-around;">   </div>			[Land use restrictions in hazard areas] Non			
[Description] There are 6 existing boreholes for the monitoring of ground water level (Boreohole-No. : BH-1,2,3,4,5,6), However, it is not measured now.			[Description] There are 6 existing boreholes for the monitoring of ground water level (Boreohole-No. : BH-1,2,3,4,5,6), However, it is not measured now.			

# General Information Sheet (Slope)

Management number	0 0 0 0 0 0 0 2 8	Reporter's name:	Ai Togami	Date of report :	June 18, 2012
Address	Bambous Virieux, Rajiv Gandhi Street (near Bhavaavy House), Impasse Bholoa	Type*	Slope failure	latitude	-20.349139
			longitude	57.7645	

<p>Schematic sketch</p> <div style="border: 1px solid black; padding: 5px; margin-bottom: 10px;"> <p><b>plan view</b></p> </div> <div style="border: 1px solid black; padding: 5px;"> <p><b>cross section</b></p> </div>	<p>Location map (Scale: 1:25,000)</p>
--	---------------------------------------

**\* Description of "Type"**

	<u>Rock fall</u>	<u>Slope failure</u>	<u>Landslide</u>
<p>Rock Fall : Rock fall is a phenomenon where foliated rocks and gravel due to enlarged cracks in the bedrock or outcropped rocks start to fall down a slope.</p>	<p>Slope Failure : The slope failures mass detached from steep slope/cliff along surface with little or no shear displacement. Compared to landslides, the quick slope moves on a small-scale, the inclination angle of the slope failure is a relatively high angle (over 30 degrees ).</p>	<p>A landslide is a phenomenon where the soil mass on failure surfaces deep in the ground gradually shifts downward, triggered by heavy rain or earthquake, river erosion, earthworks. Compared to slope failure, the gentler slope moves on a large, the inclination angle of the landslides slope is a relatively low angle (about 5-30 degrees ).</p>	<p>A Debris flow is a phenomenon where soil and boulders are liquefied by surface water or groundwater and tend to flow downward rapidly through a mountain torrent.</p>
	<p><b>Rock Fall</b></p>	<p><b>Slope Failure</b></p>	<p><b>Landslide</b></p>
			<p><b>Debrid Flow</b></p>


Mangement number	0	0	0	0	0	0	0	0	0	2	8
------------------	---	---	---	---	---	---	---	---	---	---	---

## Evaluation sheet


Reporter's name:	Ai Togami
------------------	-----------

[check Point]

Category		Check ✓	
Phenomenon on the Site	Scarp (Main or Minor , Horse shoe shape)	✓	
	Transverse Cracks (Tension or Compression)		
	Pond and Swamp		
	Spring Water		
	Topography with the Step		
	Eembankment at the upper		
	Cut Slope at the toe	✓	
	Wash out by rivers		
	Damage on construction and houses	obvious (name: Wall , number: 1 )	✓
		Slight (name: , number: )	
None			
Monitoring Equipment	There is it (name: , number: )		
	There is it (name: , number: )		
	none	✓	
History	Existing record of Landslide (documents or patrimony)	Obvious	
		slight	
		none	
Countermeasure	There is no Countermeasure		
	Effectiveness of Countermeasure	No effect	
		Some effect	✓
High effect			




Structure of a landslide



Schematic diagram of landslide landforms

[Description]

Slope failure was confirmed at the backyard of the house. No damage on the house was reported although the soil of the slope approached near the house. A retaining wall has been constructed independently.



Schematic cross section of inducing factor and artificial cause





Ph-1 main scarp



Ph-2 retaining wall



Ph-3 relation retaining wall and house

# Survey on Structural/Non-structural Measures

Management number 

0	0	0	0	0	0	0	0	2	8
---	---	---	---	---	---	---	---	---	---

Reporter's name: Ai Togami      Date of report : June 18, 2012

Structural Measures (Hard-Component)	
	The kinds of landslide countermeasure
Existing landslide countermeasures	retaining wall


Non-structural Measure (Soft-Component)	
	The kinds of Landslide Monitoring / Spec
Landslide Monitoring Equipment	
Warning Threshold	Rainfall
	Movement/displacement
	communication means
	evacuation support

[ The Photo of Countermeasure ]



[Description]  
The retaining wall is constructed independently at the moment. It will be necessary to reinforce a retaining wall.

[ The Photo of Monitoring Equipment ]



[Resident's awareness and relocation]

[Land use restrictions in hazard areas]

[Description]

# General Information Sheet (Other)

Management number	0 0 0 0 0 0 0 2 9	Reporter's name:	Ai Togami	Date of report :	June 28, 2012
Address	Cave in at Union Park, Rose Belle	Type*	Cavern	latitude	-20.390558
				longitude	57.582067
Schematic sketch			Location map (Scale: 1:25,000)		
<p><b>plan view</b></p> <p><b>cross section</b></p>			<p>0 500 1.000m 1/25,000</p>		

## \* Description of "Type"

Damage of wall	Damage of house	cavern
<p>The disaster of the retaining wall doesn't have the sudden mutation like the rockfall etc. , and deformation does comparatively spending long time. The survey content is shown below.</p> <ul style="list-style-type: none"> <li>Investigation of condition around retaining wall</li> <li>Investigation concerning main body of retaining wall</li> <li>Investigation concerning history</li> </ul>	<p>The crack that occurs on the wall in the house has the following causes.</p> <ul style="list-style-type: none"> <li>Landslide movement</li> <li>Lack of bearing capacity</li> <li>Subsidence of foundation ground</li> <li>Shoddy workmanship</li> <li>Other</li> </ul> <p>It is preferable to search for length, width, and the direction of the crack, and to do the continuance observation.</p>	<p>The Cavern occur by the following causes.</p> <ul style="list-style-type: none"> <li>Infiltration of water from soak away</li> <li>Infiltration of water from improved pit</li> <li>other</li> </ul>

Mangement number	0	0	0	0	0	0	0	0	0	2	9
------------------	---	---	---	---	---	---	---	---	---	---	---

## Evaluation sheet

Reporter's name:	Ai Togami
------------------	-----------

[check Point]

Category		Record / check	
Retaining wall	Type of the retaining wall	Concrete block / Concrete Stone masonry / Other	
	H : Height of the retaining wall	m	
	L : Length of the retaining wall	m	
	D : Thickness of the retaining wall	m	
	Type of the damage	Collapse / Inclination Hair crack / Open crack other	
House	Type of the damage	Collapse / Inclination Hair crack / Open crack other	
	Cause of damage	Landslide movement Lack of bearing capacity Subsidence of foundation ground Shoddy workmanship other / not clear	
	cavern	W : width of the cavern	0.5 m (conclusion)
		L : Length of the cavern	1.0 m (conclusion)
		D : Depth of the cavern	0.5-1.0m (conclusion)
Situation above the cavern		improved pit / soak away / other	
	Water	Spring water / Ground water	

Category		Check ✓	
History	Existing record of damage on wall (documents or patrimony)	Obvious	
		slight	
		none	
	Existing record of damage on house (documents or patrimony)	Obvious	
		Slight	
		None	
Countermeasure	There is no Countermeasure		✓
	Effectiveness of Countermeasure	No effect	
		Some effect	
		High effect	

[Description]

A cave (4m x 4m x 3m depth) due to land subsidence was observed in the residential area. No damage was caused to the houses and the cave was filled in with soil. Soakaway have to be replaced by the sewer in future. Similar situation was confirmed nearby.



Ph-1 Full view



Ph-2 cave by groundwater



Ph-3 filled cave



Ph-4 site of another cave



Ph-5 another cave

# Survey on Structural/Non-structural Measures

Management number 

0	0	0	0	0	0	0	0	2	9
---	---	---	---	---	---	---	---	---	---



Reporter's name: Ai Togami Date of report : June 28, 2012

Structural Measures (Hard-Component)		
	The kinds of landslide countermeasure	Number
Existing landslide countermeasures	None	

Non-structural Measure (Soft-Component)		
	The kinds of Landslide Monitoring / Spec	Number
Landslide Monitoring Equipment		
Warning Threshold	Rainfall	
	Movement/displacement	
communication means		
evacuation support		

[ The Photo of Countermeasure ]

[ The Photo of Monitoring Equipment ]



[Description]  
It is important to diffuse simplified soakaway to prevent a cave occurrence. Replacement of soakaway by the sewer in future will be advisable.

[Resident's awareness and relocation]  
  
[Land use restrictions in hazard areas]  
  
[Description]

# General Information Sheet (Slope)

Management number	0 0 0 0 0 0 0 3 0	Reporter's name:	Ai Togami	Date of report :	June 12, 2012
Address	Trou-AUX-Cerfs	Type*	Slope failure	latitude	-20.316389
				longitude	57.510639

<p>Schematic sketch</p> <div style="display: flex; justify-content: space-around;"> <div style="text-align: center;"> <p><b>plan view</b></p> </div> <div style="text-align: center;"> <p><b>cross section</b></p> </div> </div>	<p>Location map (Scale: 1:25,000)</p>
--	---------------------------------------

**\* Description of "Type"**

	<u>Rock fall</u>	<u>Slope failure</u>	<u>Landslide</u>
<p>Rock Fall : Rock fall is a phenomenon where foliated rocks and gravel due to enlarged cracks in the bedrock or outcropped rocks start to fall down a slope.</p>	<p><b>Rock Fall</b></p>	<p>Slope Failure : The slope failures mass detached from steep slope/cliff along surface with little or no shear displacement. Compared to landslides, the quick slope moves on a small-scale, the inclination angle of the slope failure is a relatively high angle (over 30 degrees ).</p> <p><b>Slope Failure</b></p>	<p>A landslide is a phenomenon where the soil mass on failure surfaces deep in the ground gradually shifts downward, triggered by heavy rain or earthquake, river erosion, earthworks. Compared to slope failure, the gentler slope moves on a large, the inclination angle of the landslides slope is a relatively low angle (about 5-30 degrees ).</p> <p><b>Landslide</b></p>
			<p>A Debris flow is a phenomenon where soil and boulders are liquefied by surface water or groundwater and tend to flow downward rapidly through a mountain torrent.</p> <p><b>Debrid Flow</b></p>


Mangement number	0	0	0	0	0	0	0	0	0	3	0
------------------	---	---	---	---	---	---	---	---	---	---	---

## Evaluation sheet


Reporter's name:	Ai Togami
------------------	-----------

[check Point]

Category		Check ✓	
Phenomenon on the Site	Scarp (Main or Minor , Horse shoe shape)	✓	
	Transverse Cracks (Tension or Compression)	✓	
	Pond and Swamp		
	Spring Water		
	Topography with the Step	✓	
	Eembankment at the upper		
	Cut Slope at the toe		
	Wash out by rivers		
	Damage on construction and houses	obvious (name: , number: )	
		Slight (name: Fence , number: 1 )	✓
None			
Monitoring Equipment	There is it (name: , number: )		
	There is it (name: , number: )		
	none	✓	
History	Existing record of Landslide (documents or patrimony)	Obvious	
		slight	
		none	
Countermeasure	There is no Countermeasure	✓	
	Effectiveness of Countermeasure	No effect	
		Some effect	
High effect			



Structure of a landslide




Schematic diagram of landslide landforms

[Description]

The slope failure in the crater of the volcano occurred during heavy rainfall in 2005.  
 B=35m, L=30m, D=2~3m

Also, the around area of the slope failure shows some characteristic as follows,  
 (1)Topography with the step continuously  
 (2)Some small slope failure

The possibility of slope failure on the rear side is low. However, the slope failure on both sides can be expected.



Schematic cross section of inducing factor and artificial cause





Ph-1 Full view of the slope failure



Ph-2 the slope failure  
B=35m, L=30m, D=2~3m



Ph-3 the fence in the back of slope failure  
It is damaged by slope failure



Ph-4 the back of the slope failure



Ph-5 the around of the slope failure  
Topography with the Step continuously



Ph-6 the around of the slope failure  
small slope failure

# Survey on Structural/Non-structural Measures

Management number 

0	0	0	0	0	0	0	0	0	3	0
---	---	---	---	---	---	---	---	---	---	---



Reporter's name: Ai Togami      Date of report : June 12, 2012

Structural Measures (Hard-Component)		
	The kinds of landslide countermeasure	Number
Existing landslide countermeasures	None	

Non-structural Measure (Soft-Component)		
	The kinds of Landslide Monitoring / Spec	Number
Landslide Monitoring Equipment		
Warning Threshold	Rainfall	
	Movement/displacement	
communication means		
evacuation support		

[ The Photo of Countermeasure ]

[ The Photo of Monitoring Equipment ]



[Description]

[Resident's awareness and relocation]

[Land use restrictions in hazard areas]

[Description]

# General Information Sheet (Other)

Management number	0 0 0 0 0 0 0 3 1	Reporter's name:	Tomoharu IWASAKI	Date of report :	June 12, 2012
Address	River Bank at Cite L'Oiseau	Type*	Stream erosion	latitude	-20.300922
				longitude	57.510595
Schematic sketch			Location map (Scale: 1:25,000)		

\* Description of "Type"

<p style="text-align: center;"><u>River bank erosion</u></p> <p>The Stream erosion is the phenomenon that the soil of the bank is removed by the flow of the river. It occurs in the part which a flow of the water crashes into mainly. Water might overflow when the amount of the stream increases.</p>	<p style="text-align: center;"><u>Damage of Embankment</u></p> <p>The collapse of the road embankment is often generated by a rainfall, infiltration of underground water, erosion by surface water, and a partial catchment. Therefore, it pays attention to the possibility of the catchment. The embankment material might be weak, and it cause by lack of soil compaction.</p>
--	---

Mangement number	0	0	0	0	0	0	0	0	0	3	1
------------------	---	---	---	---	---	---	---	---	---	---	---


## Evaluation sheet

Reporter's name:	Tomoharu IWASAKI
------------------	------------------


[check Point]

Category			Record
Stream	Figure / size	W1 : Width of the river	10.0 m
		W2 : Width of the riverbed	4.0 m
		D : Depth of the river	3.0 m
	Type	Right bank	Soil or Natural ground / Artificial structure
		Left bank	Soil or Natural ground / Artificial structure
	Box culvert	W : Width	m
		H : Height	m
Pipe culvert	D : Diameter	m	
Type of the damage	Erosion		
	Overflow stream		
	Other		
Embankment	Embankment		
	Cutting and embankment		
	Structural crack / Open crack		
	Scour under the slope		
	Erosion of the slope		
	A lot of repair parts		
Other			


Category			Check ✓
History	Existing record of Stream erosion or overflow stream (documents or patrimony)	Obvious	
		slight	
		none	✓
	Existing record of damage on embankment (documents or patrimony)	Obvious	
Slight			
None			
Countermeasure	There is no Countermeasure		
	Effectiveness of Countermeasure	No effect	
		Some effect	✓
		High effect	



Structure of a river



Box culvert



Pipe culvert

[Description]

Bank erosion and flooding is common in the rainy season when the river water level rises. There are more damage on the left side of the riverbank due to the strong collision of water. However, past damage has been restored by constructing a retaining wall.



Ph-1 Full view of the river



Ph-2 Full view from the upper side of the river



Ph-3 High water level in the rain season

# Survey on Structural/Non-structural Measures

Management number 0 0 0 0 0 0 0 0 3 1

Reporter's name: Tomoharu IWASAKI Date of report : June 12, 2012

Structural Measures (Hard-Component)	
	The kinds of countermeasure
Existing countermeasures	Number
	Stone masonry retaining wall (left bank)
	1

Non-structural Measure (Soft-Component)	
	The kinds of Monitoring / Spec
Monitoring Equipment	Number
Warning Threshold	Rainfall
	Movement/displacement
communication means	
evacuation support	


[ The Photo of Countermeasure ]

[ The Photo of Monitoring Equipment ]



Stone masonry retaining wall (left bank)

[Description]  
The past damage is restored now.  
It is not necessary to carry out the countermeasures.



[Resident's awareness and relocation]  
  
[Land use restrictions in hazard areas]  
  
[Description]

# General Information Sheet (Other)

Management number	000000032	Reporter's name:	Tomoharu IWASAKI	Date of report :	June 12, 2012
Address	Louis de Rochecouste (Riviere Seche)	Type*	Stream erosion	latitude	-20.323943
Schematic sketch			Location map (Scale: 1:25,000)		

\* Description of "Type"

<p style="text-align: center;"><u>River bank erosion</u></p> <p>The Stream erosion is the phenomenon that the soil of the bank is removed by the flow of the river. It occurs in the part which a flow of the water crashes into mainly. Water might overflow when the amount of the stream increases.</p>	<p style="text-align: center;"><u>Damage of Embankment</u></p> <p>The collapse of the road embankment is often generated by a rainfall, infiltration of underground water, erosion by surface water, and a partial catchment. Therefore, it pays attention to the possibility of the catchment. The embankment material might be weak, and it cause by lack of soil compaction.</p>
--	---

Mangement number	0	0	0	0	0	0	0	0	0	3	2
------------------	---	---	---	---	---	---	---	---	---	---	---


## Evaluation sheet

Reporter's name:	Tomoharu IWASAKI
------------------	------------------


[check Point]

Category			Record
Stream	Figure / size	W1 : Width of the river	6.0 m
		W2 : Width of the riverbed	2.5 m
		D : Depth of the river	3.0 m
	Type	Right bank	Soil or Natural ground / Artificial structure
		Left bank	Soil or Natural ground / Artificial structure
	Box culvert	W : Width	m
		H : Height	m
Pipe culvert	D : Diameter	m	
Type of the damage	Erosion		
	Overflow stream		
	Other		
Embankment	Type of the embankment		
	Embankment		
	Cutting and embankment		
	Structural crack / Open crack		
	Scour under the slope		
	Erosion of the slope		
Type of the damage	A lot of repair parts		
	Other		


Category			Check ✓
History	Existing record of Stream erosion or overflow stream (documents or patrimony)	Obvious	
		slight	
		none	✓
	Existing record of damage on embankment (documents or patrimony)	Obvious	
Slight			
None			
Countermeasure	There is no Countermeasure		✓
	Effectiveness of Countermeasure	No effect	
		Some effect	
		High effect	



Structure of a river



Box culvert



Pipe culvert

[Description]

The bank erosion and flood are common in the rainy season. The base of the houses have been eroded and the retaining wall of the houses are inclined.





Ph-1 Full view of the river



Ph-2 Eroded area



Ph-3 Eroded area (zoom up photo)



Ph-4 Eroded area  
The eroded depth is 50cm



Ph-5 The inclined concrete block wall

# Survey on Structural/Non-structural Measures

Management number 0 0 0 0 0 0 0 0 3 2

Reporter's name: Tomoharu IWASAKI Date of report : June 12, 2012

Structural Measures (Hard-Component)	
	The kinds of countermeasure
Existing countermeasures	None

Non-structural Measure (Soft-Component)	
	The kinds of Monitoring / Spec
Monitoring Equipment	
Warning Threshold	Rainfall
	Movement/displacement
communication means	
evacuation support	

[ The Photo of Countermeasure ]

[ The Photo of Monitoring Equipment ]

None	None
------	------

--	--

None	<p>[Description]</p> <p>It is necessary to carry out the countermeasures.</p>
------	---

	<p>[Resident's awareness and relocation]</p> <p>[Land use restrictions in hazard areas]</p> <p>[Description]</p>
--	--

# General Information Sheet (Other)

Management number	000000033	Reporter's name:	Tomoharu IWASAKI	Date of report :	June 12, 2012
Address	Piper Morcellement Piat	Type*	Stream erosion	latitude	-20.330301
Schematic sketch			longitude		
			Location map (Scale: 1:25,000)		

\* Description of "Type"

<p style="text-align: center;"><u>River bank erosion</u></p> <p>The Stream erosion is the phenomenon that the soil of the bank is removed by the flow of the river. It occurs in the part which a flow of the water crashes into mainly. Water might overflow when the amount of the stream increases.</p>	<p style="text-align: center;"><u>Damage of Embankment</u></p> <p>The collapse of the road embankment is often generated by a rainfall, infiltration of underground water, erosion by surface water, and a partial catchment. Therefore, it pays attention to the possibility of the catchment. The embankment material might be weak, and it cause by lack of soil compaction.</p>
--	---

Mangement number	0	0	0	0	0	0	0	0	0	3	3
------------------	---	---	---	---	---	---	---	---	---	---	---


## Evaluation sheet

Reporter's name:	Tomoharu IWASAKI
------------------	------------------


[check Point]

Category			Record
Stream	Figure / size	W1 : Width of the river	3.5 m
		W2 : Width of the riverbed	2.0 m
		D : Depth of the river	4.0 m
	Type	Right bank	Soil or Natural ground / Artificial structure
		Left bank	Soil or Natural ground / Artificial structure
	Box culvert	W : Width	m
		H : Height	m
Pipe culvert	D : Diameter	m	
Type of the damage	Erosion		
	Overflow stream		
	Other		
Embankment	Type of the embankment		
	Embankment		
	Cutting and embankment		
	Structural crack / Open crack		
	Scour under the slope		
	Erosion of the slope		
Type of the damage	A lot of repair parts		
	Other		


Category			Check ✓
History	Existing record of Stream erosion or overflow stream (documents or patrimony)	Obvious	
		slight	
		none	✓
	Existing record of damage on embankment (documents or patrimony)	Obvious	
Slight			
None			
Countermeasure	There is no Countermeasure		
	Effectiveness of Countermeasure	No effect	
		Some effect	✓
		High effect	



Structure of a river



Box culvert



Pipe culvert

[Description]

The bank erosion and flood are remarkable in the rainy season. However, the past damage has been restored by constructing the retaining wall.

Management Number 0 0 0 0 0 0 0 0 3 3

# Photo sheet

Date June 12, 2012



Ph-1 Full view of the river

The left river bank which a flow of the water crashes. It is eroded area. The past damage is restored now.



Ph-2 Trace of the destruction and the retaining wall

# Survey on Structural/Non-structural Measures

Management number 0 0 0 0 0 0 0 0 3 3

Reporter's name: Tomoharu IWASAKI Date of report : June 12, 2012

Structural Measures (Hard-Component)	
	The kinds of countermeasure
Existing countermeasures	Number
	Stone masonry retaining wall
	1

Non-structural Measure (Soft-Component)	
	The kinds of Monitoring / Spec
Monitoring Equipment	Number
Warning Threshold	Rainfall
	Movement/displacement
communication means	
evacuation support	

[ The Photo of Countermeasure ]

[ The Photo of Monitoring Equipment ]



Stone masonry retaining wall of left bank

[Description]

The past damage is restored now (retaining wall).

[Resident's awareness and relocation]

[Land use restrictions in hazard areas]

[Description]

[Resident's awareness and relocation]

[Land use restrictions in hazard areas]

[Description]

# General Information Sheet (Slope)

Management number	0 0 0 0 0 0 0 3 4	Reporter's name:	YoujiKASAHARA
Date of report :		June 26, 2012	
Address	Candos Hill at LalBahadoor Shastri and Mahatma Gandhi Avenues	Type*	Landslide
Latitude	-20.277536	Longitude	57.482172

<p>Schematic sketch</p> <p style="text-align: center;"><b>Cross section</b></p>	<p>Location map (Scale: 1:25,000)</p>
---	---------------------------------------

**\* Description of "Type"**

	<u>Rock fall</u>	<u>Slope failure</u>	<u>Landslide</u>
<p>Rock Fall : Rock fall is a phenomenon where foliated rocks and gravel due to enlarged cracks in the bedrock or outcropped rocks start to fall down a slope.</p>	<p style="text-align: center;"><b>Rock Fall</b></p>	<p>Slope Failure : The slope failures mass detached from steep slope/cliff along surface with little or no shear displacement. Compared to landslides, the quick slope moves on a small-scale, the inclination angle of the slope failure is a relatively high angle (over 30 degrees ).</p>	<p>A landslide is a phenomenon where the soil mass on failure surfaces deep in the ground gradually shifts downward, triggered by heavy rain or earthquake, river erosion, earthworks. Compared to slope failure, the gentler slope moves on a large, the inclination angle of the landslides slope is a relatively low angle (about 5-30 degrees ).</p>
	<p style="text-align: center;"><b>Slope Failure</b></p>	<p style="text-align: center;"><b>Landslide</b></p>	<p>A Debris flow is a phenomenon where soil and boulders are liquefied by surface water or groundwater and tend to flow downward rapidly through a mountain torrent.</p>
			<p style="text-align: center;"><b>Debrid Flow</b></p>


Mangement number	0	0	0	0	0	0	0	0	0	3	4
------------------	---	---	---	---	---	---	---	---	---	---	---

## Evaluation sheet


Reporter's name:	YoujiKASAHARA
------------------	---------------

[check Point]

Category		Check ✓	
Phenomenon on the Site	Scarp (Main or Minor , Horse shoe shape)	✓	
	Transverse Cracks (Tension or Compression)		
	Pond and Swamp		
	Spring Water	✓	
	Topography with the Step		
	Eembankment at the upper		
	Cut Slope at the toe		
	Wash out by rivers		
	Damage on construction and houses	obvious ( number : )	
		Slight ( number : 1 concreat wall )	✓
None			
Monitoring Equipment	There is it (name: Extensometer , number: )		
	There is it (name: , number: )		
	none	✓	
History	Existing record of Landslide (documents or patrimony)	Obvious	
		slight	
		none	
Countermeasure	There is no Countermeasure	✓	
	Effectiveness of Countermeasure	No effect	
		Some effect	
High effect			




Structure of a landslide



Schematic diagram of landslide landforms

[Description]

A clear landslide site was confirmed at the backyard of the house. The landslide topography and slope are clear while the spring water has been observed. The scale of this landslide is small (40m x 35m) and no house on the landslide area. Only slight crack has been confirmed on the retaining wall. It is not emergency, It is preferable to observe the crack of the retaining wall continuously in future.



Schematic cross section of inducing factor and artificial cause






Ph-1 Full view



Ph-2 Collapse site



Ph-3 Falling rock



Ph-4 Crack of retaining wall



Ph-5 Crack of concrete wall



Ph-6 Spring water

# Survey on Structural/Non-structural Measures

Management number 

0	0	0	0	0	0	0	0	0	3	4
---	---	---	---	---	---	---	---	---	---	---

Reporter's name: YoujiKASAHARA      Date of report : June 26, 2012

Structural Measures (Hard-Component)		
	The kinds of landslide countermeasure	Number
Existing landslide countermeasures	None	

Non-structural Measure (Soft-Component)		
	The kinds of Landslide Monitoring / Spec	Number
Landslide Monitoring Equipment		
Warning Threshold	Rainfall	
	Movement/displacement	
communication means		
evacuation support		

[ The Photo of Countermeasure ]

[ The Photo of Monitoring Equipment ]

None	None
------	------

--	--

None	<p>[Description]                  There is no countemeasure works.                  The damage of the retaining wall is also a little.                  However, the main scarp is clarity, old collapse mark.                  Immediate countermeasures are unnecessary now. It is preferable to observe the crack of the retaining wall continuously.</p>
------	--


	<p>[Resident's awareness and relocation]</p> <p>[Land use restrictions in hazard areas]</p> <p>[Description]</p>
--	--

# General Information Sheet (Other)


Management number	000000035	Reporter's name:	Ai Togami	Date of report :	July 5, 2012
Address	Cavernous Area at Mgr Leen Avenue and Bassin	Type*	Cavern	latitude	-20.277089
				longitude	57.471856

Schematic sketch



plan view



cross section



Location map (Scale: 1:25,000)




## \* Description of "Type"

### Damage of wall

The disaster of the retaining wall doesn't have the sudden mutation like the rockfall etc. , and deformation does comparatively spending long time. The survey content is shown below.

- Investigation of condition around retaining wall
- Investigation concerning main body of retaining wall
- Investigation concerning history




### Damage of house

The crack that occurs on the wall in the house has the following causes.

- Landslide movement
- Lack of bearing capacity
- Subsidence of foundation ground
- Shoddy workmanship
- Other


It is preferable to search for length, width, and the direction of the crack, and to do the continuance observation.



### cavern

The Cavern occur by the following causes.

- Infiltration of water from soak away
- Infiltration of water from improved pit
- other



Mangement number	0	0	0	0	0	0	0	0	0	3	5
------------------	---	---	---	---	---	---	---	---	---	---	---

## Evaluation sheet

Reporter's name:	Ai Togami
------------------	-----------

[check Point]

Category		Record / check
Retaining wall	Type of the retaining wall	Concrete block / Concrete Stone masonry / Other
	H : Height of the retaining wall	m
	L : Length of the retaining wall	m
	D : Thickness of the retaining wall	m
	Type of the damage	Collapse / Inclination Hair crack / Open crack other
House	Type of the damage	Collapse / Inclination Hair crack / Open crack other
	Cause of damage	Landslide movement
		Lack of bearing capacity
		Subsidence of foundation ground
		Shoddy workmanship
other / not clear		
cavern	W : width of the cavern	0.5-1.5 m (conclusion)
	L : Length of the cavern	0.5-1.5 m (conclusion)
	D : Depth of the cavern	1.0m (conclusion)
	Situation above the cavern	improved pit / soak away / other
	Water	Spring water / Ground water

Category		Check✓	
History	Existing record of damage on wall (documents or patrimony)	Obvious	
		slight	
		none	
	Existing record of damage on house (documents or patrimony)	Obvious	
	Slight		
	None		
Countermeasure	There is no Countermeasure		✓
	Effectiveness of Countermeasure	No effect	
		Some effect	
High effect			

[Description]

A cave was reported during the house construction but it was filled with concrete. There is no further danger at this site.

Management Number 0 0 0 0 0 0 0 0 3 5

# Photo sheet

Date July 5, 2012



Ph-1 Full view



Ph-2 Full view



Ph-3 filled cave

# Survey on Structural/Non-structural Measures


Management number 

0	0	0	0	0	0	0	0	3	5
---	---	---	---	---	---	---	---	---	---

Reporter's name: Ai Togami      Date of report : July 5, 2012

Structural Measures (Hard-Component)	
	The kinds of countermeasure
Existing countermeasures	None


[ The Photo of Countermeasure ]



[Description]

Non-structural Measure (Soft-Component)	
	The kinds of Monitoring / Spec
Monitoring Equipment	
Warning Threshold	Rainfall
	Movement/displacement
communication means	
evacuation support	

[ The Photo of Monitoring Equipment ]



[Resident's awareness and relocation]

[Land use restrictions in hazard areas]

[Description]

# General Information Sheet (Slope)

Management number	000000036	Reporter's name:	Tomoharu IWASAKI	Date of report :	June 25, 2012
Address	Morcellement Hermitage, Coromandel	Type*	Landslide	latitude	-20.192628
				longitude	57.472272
Schematic sketch			Location map (Scale: 1:25,000)		

\* Description of "Type"

Rock fall	Slope failure	Landslide	Debris flow
<p>Rock Fall : Rock fall is a phenomenon where foliated rocks and gravel due to enlarged cracks in the bedrock or outcropped rocks start to fall down a slope.</p>	<p>Slope Failure : The slope failures mass detached from steep slope/cliff along surface with little or no shear displacement. Compared to landslides, the quick slope moves on a small-scale, the inclination angle of the slope failure is a relatively high angle (over 30 degrees ).</p>	<p>Landslide</p> <p>A landslide is a phenomenon where the soil mass on failure surfaces deep in the ground gradually shifts downward, triggered by heavy rain or earthquake, river erosion, earthworks. Compared to slope failure, the gentler slope moves on a large, the inclination angle of the landslides slope is a relatively low angle (about 5-30 degrees ).</p>	<p>Debris flow</p> <p>A Debris flow is a phenomenon where soil and boulders are liquefied by surface water or groundwater and tend to flow downward rapidly through a mountain torrent.</p>


Mangement number	0	0	0	0	0	0	0	0	0	3	6
------------------	---	---	---	---	---	---	---	---	---	---	---

## Evaluation sheet


Reporter's name:	Tomoharu IWASAKI
------------------	------------------

[check Point]

Category		Check ✓	
Phenomenon on the Site	Scarp (Main or Minor , Horse shoe shape)		
	Transverse Cracks (Tension or Compression)	✓	
	Pond and Swamp		
	Spring Water		
	Topography with the Step		
	Eembankment at the upper		
	Cut Slope at the toe	✓	
	Wash out by rivers		
	Damage on construction and houses	obvious ( number : )	
		Slight ( number : 1 houses )	✓
None			
Monitoring Equipment	There is it (name: Extensometer , number: 3 )		
	There is it (name: , number: )		
	none	✓	
History	Existing record of Landslide (documents or patrimony)	Obvious	✓
		slight	
		none	
Countermeasure	Effectiveness of Countermeasure	There is no Countermeasure	
		No effect	
		Some effect	✓
		High effect	




Structure of a landslide



Schematic diagram of landslide landforms

[Description]

At this slope, slope failure occurred in 2010, and a road was destroyed. After a retaining wall was made as a countermeasure, large-scale slope failures have not been found. However, the stone blocks from on top of the retaining wall have fallen down. This is likely caused by the ground behind the retaining wall sinking due to lack of compaction of the backfilling soil. It is necessary to investigate it in detail.



Schematic cross section of inducing factor and artificial cause





Ph-1 Full view (Retaining wall)



Ph-2 Cracks on Stone block



Ph-3 Cracks on Stone block



Ph-4 Full view (upper end of retaining wall)





Ph-5 Damage on house



Ph-6 Cracks around the house


# Survey on Structural/Non-structural Measures

Management number	0 0 0 0 0 0 0 0 3 6	Reporter's name:	Tomoharu IWASAKI	Date of report :	June 25, 2012	
<b>Structural Measures (Hard-Component)</b>		<b>Non-structural Measure (Soft-Component)</b>				
Existing landslide countermeasures	The kinds of landslide countermeasure	Number	The kinds of Landslide Monitoring / Spec			Number
	<i>Retaining wall + Embankment</i>	1				
[ The Photo of Countermeasure ]		[ The Photo of Monitoring Equipment ]				
						
		<p>A slope failure occurred and destroyed the road in 2010. A retaining wall was constructed by the local consultant(GIBB) as countermeasure. There are cracks at the upper part of stone block but it is believe to be caused by submerged soil below the stone block. No deformation at the front part of retaining wall and the retaining wall remain stable at present. Further investigation is advisable.</p>		<p>[Resident's awareness and relocation]</p> <p>[Land use restrictions in hazard areas]</p> <p>[Description]</p>		



# General Information Sheet (Other)

Management number	000000037	Reporter's name:	Youji KASAHARA	Date of report :	June 21, 2012
Address	Montee S, GRNW	Type*	Stream erosion	latitude	-20.330301
				longitude	57.529221

Schematic sketch




Location map (Scale: 1:25,000)



\* Description of "Type"


River bank erosion

The Stream erosion is the phenomenon that the soil of the bank is removed by the flow of the river. It occurs in the part which a flow of the water crashes into mainly. Water might overflow when the amount of the stream increases.



Damage of Embankment

The collapse of the road embankment is often generated by a rainfall, infiltration of underground water, erosion by surface water, and a partial catchment. Therefore, it pays attention to the possibility of the catchment. The embankment material might be weak, and it cause by lack of soil compaction.



Mangement number	0	0	0	0	0	0	0	0	0	3	7
------------------	---	---	---	---	---	---	---	---	---	---	---


## Evaluation sheet

Reporter's name:	Youji KASAHARA
------------------	----------------


[check Point]

Category			Record
Stream	Figure / size	W1 : Width of the river	8.5 m
		W2 : Width of the riverbed	8.0 m
		D : Depth of the river	5.5 m
	Type	Right bank	Soil or Natural ground / Artificial structure
		Left bank	Soil or Natural ground / Artificial structure
	Box culvert	W : Width	m
		H : Height	m
Pipe culvert	D : Diameter	m	
Type of the damage	Erosion		
	Overflow stream		
	Other		
Embankment	Embankment		
	Cutting and embankment		
	Structural crack / Open crack		
	Scour under the slope		
	Erosion of the slope		
	A lot of repair parts		
Type of the damage		Other	


Category			Check ✓
History	Existing record of Stream erosion or overflow stream (documents or patrimony)	Obvious	
		slight	
		none	✓
	Existing record of damage on embankment (documents or patrimony)	Obvious	
Slight			
None			
Countermeasure	There is no Countermeasure		✓
	Effectiveness of Countermeasure	No effect	
		Some effect	
		High effect	



Structure of a river



Box culvert



Pipe culvert

[Description]

Weathered outcrops were detected on both sides of the bank. The erosion is remarkable in the rainy season.

Management Number 0 0 0 0 0 0 0 0 3 7

# Photo sheet

Date

June 21, 2012



Ph-1 Full view of the bridge



Ph-2 Bank erosion around bridge abutment



Ph-3 river bed and side erosion



Ph-4 bank erosion

# Survey on Structural/Non-structural Measures

Management number	0 0 0 0 0 0 0 0 3 7	Reporter's name:	Youji KASAHARA	Date of report :	June 21, 2012
-------------------	---------------------	------------------	----------------	------------------	---------------

Structural Measures (Hard-Component)		Non-structural Measure (Soft-Component)	
	The kinds of countermeasure		The kinds of Monitoring / Spec
Existing countermeasures	None		
[ The Photo of Countermeasure ]		[ The Photo of Monitoring Equipment ]	
	[Description] Weathered outcrops were detected at the bothsides of the bank. The erosion is remarkable in the rainy season.		[Resident's awareness and relocation]  [Land use restrictions in hazard areas]  [Description]