Appendices

2.3. 2nd Seminar

(1) Minutes of the Meeting

Minutes of the meeting with:

DOTC, PPA, LGUs

<u>Date:</u>	September 29, 2015.
<u>Venue:</u>	DOTC Headquarters 16/F Unit167 Columbia Tower Ortigas Avenue, Mandaluyong City 1555 Philippines
<u>Purpose:</u>	 i. Explanation of the policy on compiling a Draft Final Report ii. Explanation of the method to prioritize a port to be implemented iii. Explanation of the standard design model of disaster-resilient ports, cost estimation
Participants:	See attached attendance sheet
<u>Handout</u> materials:	i. Agendaii. Presentation Papers

The Study Team met with the representatives of DOTC, PPA and other partner agencies on September 29, 2015 at the DOTC Headquarters in Mandaluyong City, Philippines, at 9:00. The purpose of the meeting was to explain following topics in accordance with the following agenda:

Agenda		
1. Opening Remarks	DOTC	
2. Tentative Draft for Discussion on Guidelines for Selecting Social Ports in	JICA	Study
Target Area	Team	
3. Features of Transportation Through Ports in the Target Area	JICA	Study
	Team	
4. Tentative Draft for Discussion on Guidelines for Selecting Disaster Resilient	JICA	Study
Ports in Target Area	Team	
5. Tentative Draft for Discussion on Standard Design Models of Disaster	JICA	Study
Resilient Port Facilities	Team	
6. Wrap up and Closing Remarks	JICA	Study
	Team	

The meeting adjourned at 12:00.

(2) Attendance Sheet

Attendance Sheet

Venue: 16/F Unit166 Columbia Tower Ortigas Avenue, Mandaluyong City 1555 Philippines

No.	Name	Organization/ Department	Position/ Title
1	ROLANDO T. RODOLFO	PPA - Manila	
2	RENATO L. YUMANG	РРА	Principal Engineer
3	ALBERT TAYABAS	РРА	Envi Specialist
4	MARCELO C. INDIC	PPA- Taeloban	Division Mananger A
5	GLENN S. LAGUNAY	PPA-Tacloban	Division Mananger A
6	FLEAZER U. PIEL	PPA, PMO Bohol	
7	TESALONICA A. BOYBOY	LGU-CP Garcia, Bohol	Municipal Mayor
8	GLENN ALAN G. BOYLES	LGU-CP Garcia, Bohol	Disaster Risk Reduction Management Officer
9	GEORMA Z. CAVERO	LGU - Hindang, Leyte	MSWDv
10	RICARDO M. RENEGADO JR	LGU - Hindang, Leyte	MPDC.
11	MARIO FREDERICK D. MONTERO	LGU - Hindang, Leyte	ME
12	DEXTER R. SARCON	LGU - Hindang, Leyte	MCR
13	REINERIO A. BOGLOSA	LGU - Banate	Municipal Engineer (OIC) Engineer I
14	HONRADO M. PINEDA	DOTC- PDS	Engineer 1

Attendance Sheet

Venue: 16/F Unit166 Columbia Tower Ortígas Avenue, Mandaluyong City 1555 Philippines

No.	Name	Organization/ Department	Position/ Title
15	ELENITA D. ASUNCION	DOTC-WIPD	Sr. TDO
16	BELINDA C. SALVOSA	DOTC-WIPD	Sr. TDO
17	MANNY LADIZABAL	DOTC-WIPD	Sr. CDO
18	ENRICO C. FERRE	DOTC - WIPD	Chief, WIPD
19	DENNIS M. ALBANO	DOTC - WIPD	Sr. CDO
20	MENCHIF D. BOGNALOS	DOTC - WIPD	
21	MYRA B. MEDINA	DOTC - WTPD	
22	FRANCISCO TAMPUS	DOTC - WTPD	
23	EMMA RIVERO	DOTC-WIPD	
24	ABELARDO D. SIRE JR.	DOTC	Project Manager
25	FELICISIMO PANGILINAN JR.	DOTC - Planning	OIC
26	MILKY BABILONIA	DOTC - Planning	
27	HOMER T. DE LA PAZ	DOTC - Planning	
28	SHANICA SOLLEGUE	DOTC - Planning	

Appendices

Attendance Sheet

No.	Name	Organization/ Department	Position/ Title
29	ERNESTO CRUZ	JICA-Study Team	Civil Engineer
30	SUZANNE Z. TORRES	JICA-Study Team	
31	SHISHIDO TATSUYUKI	ЛСА-Study Team	Team Leader
32	SHIMADA TAKASHI	ЛСА-Study Team	T
33	HINO ISAO	ЛСА-Study Team	
34	SAITO KEN	JICA-Study Team	
35			
35	- -		
36			
37			
38	1		
39			
40		- 11	

Venue: 16/F Unit166 Columbia Tower Ortigas Avenue, Mandaluyong City 1555 Philippines

(3) **Presentation Materials**

1) Tentative draft for Discussion on Guidelines for Selecting Social Ports in the Target Area

Screening Criteria and Guideline for Social Ports Development

On 29 & 30 Sept. 2015 JICA Study Team for Disaster – Resilient Feeder Ports & Logistics Network

SHIMADA/JICA * OCDI




Takashi SHIMADA Principal Researcher, OCDI

- In 1981, I started working in the Ministry of Transport (MOT) in Japan as a Civil Engineer.
- I have been engaged in transport planning and engineering for more than 33 years.
- I have also taken part in overseas projects such as in Algeria, Vietnam, the Philippines and Cambodia over a 10-year period.
- In 2004, I was also a lecturer of port and airport development policy at Kobe National University.
- I took an early retirement option of Ministry of Land, Infrastructure and Transport (MLIT) and have been working in OCDI since 2014 as a principal researcher.

SHIMADA/IICA # OCDI

Contact Add.= t-shimada@ocdi.or.jp



Appendices




- Since 1992, the DOTC has took over the development of government ports (feeder port, social port) from DPWH.
- After this, Feeder Ports by ODA were developed based on JICA Mater Plans Studied in 2000 and 2004.
- Social ports developed by the national government budget are mainly based on LGU request or regional political will.

SHIMADA/IICA = (ICD)

2-2 Current Budgetary System to develop Social Ports


- 1. Management Commission by Central Government=DoTC, DA,
- 2. Grant Budget by Central Government
- 3. IRA(Internal Revenue Allotment)=80%Project Cost
- Funding Assistance=Budget Shear between Authority and LGU. Auditor' check for Specification and Financial Aspects is required
- 5. Invested fully by LGU= Highly Urbanized City
- 6. PPP or BOT


SUIMADA/IICA = QCDI




Excludin	ng Cebu	and Ne	egros			
Norman and	~ 7/1				00 2010	Area Den Km2 per
A starting	There are a second	lloilo (exclu lloilo City Bohol	ding loilo City)	309,505 36	9,182 1,805,576 6,391 424,619 9,130 1,255,128	5,079.17 4,820.95
一一百百	2	Leyte (excl Tacloban C	uding Tacloban City) Sity	1,230,925 1,41	13,697 1,567,984 78,639 221,174	6,515.05
XIII-	Post destant					
	SID.					
Legend 0: Existing Ro-Ro Terminal (☆Base Key Cty Ro-Ro Term	(a)					
On-going Ro-Ro Terminal Development O: Terminal Port O: CY2015 Social and Tourism ports development project						
		SHIMADA/	JICA * OCDI			
2	2.6				-	
3 Ports I	-3 Cur Devel	rent	Situa			еа
		rent	Situa			ea
Ports Classification Population	Devel	rent opmo	Situa ent in	Targ	et Ar	ea
Ports I	Devel	rrent opme Iolio Prov. 2,230	Situa ent in Bohol Prov. 1,255	Leyte Prov. 1,789	et Ar	ea
Classification Population 2010 (,000)	Devel	Frent Opme Iloila Prov. 2,230 10	Situa ent in Bohol Prov. 1,255 6	Leyte Prov. 1,789 10	et Ar ^{Total} 5,274 26	ea
Classification Classification 2010 (,000) Private Base / Terminal	Devel	Errent Opme I olio Prov. 2,230 10 3	Situa ent in Bohol Prov. 1,255 6 6	Leyte Prov. 1,789 10 5	et Ar 5,274 26 14	ea
Classification Classification 2010 (,000) Private Base / Terminal Social	Devel	Frent Opme Iloila Prov. 2,230 10	Situa ent in Bohol Prov. 1,255 6	Leyte Prov. 1,789 10	et Ar ^{Total} 5,274 26	ea
Classification Classification 2010 (,000) Private Base / Terminal	Devel	Errent Opme I olio Prov. 2,230 10 3	Situa ent in Bohol Prov. 1,255 6 6	Leyte Prov. 1,789 10 5	et Ar 5,274 26 14	ea
Ports Classification Population 2010 (,000) Private Base / Terminal Social Public Total One Port	Devel	Itelia Prov. 2,230 10 3 21 24 45	Situa ent in Bohol Prov. 1,255 6 6 6 6 8 74 25	Leyte Prov. 1,789 10 5 39 44 35	et Ar	ea
Ports Classification 2010 (,000) Private Base / Terminal Social Public Total	Devel	Trent Opme Iolio Prov. 2,230 10 3 21 21 24	Situa ent in Bohol Prov. 1,255 6 6 6 6 8 74	Leyte Prov. 1,789 10 5 39 44	et Ar Total 5,274 26 14 128 142	ea
Classification Classification 2010 (,000) Private Base / Terminal Social Public Total One Port /50,000 per	Devel	Itelia Prov. 2,230 10 3 21 24 45	Situa ent in Bohol Prov. 1,255 6 6 6 6 8 74 25	Leyte Prov. 1,789 10 5 39 44 35	et Ar	ea














```
Appendices
```









































































3) Tentative Draft for Discussion on Guidelines for Selecting Disaster Resilient Ports in Target Area

















4) Tentative Draft for Discussion on Standard Design Models of Disaster Resilient Port Facilities

Data Collection Survey on Disaster - resilient Feeder Ports and Logistics Network in the Republic of Philippines **Results of Field Survey and Standard Design Model of Disaster Resilient Ports** 29 September 2015 JICA Survey Team 1 Summary of the Investigation of Port Facilities in Leyte Area TACLOBAN PALOMPON ISABEL BAYBAY HILONGOS BATO BABATUGON Unit ORMOC **Port Facilities** 428.2 (3.98 m) 375 (3.19 m) 793(5.91 m) 150 Cargo Berthing length (depth, m) m 922 (10.0m) 235, (6.78 m) 84 (3.0 m) None 10 berths 3 berths 5 berths 5 berths Degree of damage Flood only

		the second s							
RORO Facilities	Unit	2	1	None	3	1	2	1	None
Total port area	m ²	45,000	18,399	2,106	18,132	7,997	14,119	1,800	None
Worrking area	m²	7,756				None	574	1 I I	
Open Storage	m²	6,553	8,297	×	4,733	834	6,944	900	None
Warehouse or Transit shed	m²	540.00	675	- X -					None
Degree of damage		Transit shed, snull buldgs and 1 crane totally damaged	Roof, ceiling damage						
Marshalling Area	m²	1. TA (1.	1,814	÷	1,373	540	558	None	None
Vehicle Parking Areas	m²		1,240		3,337, (61 vehicles)	45, (12 vehicles)	132	None	None
Passenger Terminal Building	m²	1	150	None	1,412	315	271	None	None
Degree of damage			Roof, ceiling damage			Roof, ceiling dumage	Roof, ceding damage		
A dimin Bldg, etc	m ²	686 x 3 stories	166	104	281	58	58	None	None
Degree of damage		Totally Dameged	Roof, ceiling damage		PMO and othe buildg damaged				1
Degree of total damage		Serious damage	Midum Damage.	Very Minor	Midium Damage	Minor Danage	Minor Damage	Very Minor	None
Rehabilitated date, cost(mil. Peso)		2014/12/30, (25.9)	2015/3/31, (5.6)		2014/12/30, (4.0)	2014/3/14, (1.5)	2014/3/14, (2.1)		

		Taclob	an Port	
Damaged Conditions by Typhoon	PPA	PA		PP
Yolanda	storm surge of typhoon Yolanda but the Ty column structure was not damaged. do by	phoon. Windows doors furniture	Condition of the wharf after typhoon(left). Wharf struc surge and waves. Storm surge overflow the wharf and PCG vessel at the open space near entrance gate (righ	remaining debris.
Rehabilitation				
	Survey Team	Survey Team	Marcine -	Survey Tea
	Renovated Warehouse (Wall material change Re to CHB)		It was not found the damage caused by typhoon during Condition of the wharf deck and piles are basically sou by mean of steel pipe sheet pile.	

Summary of the investigation of Port Facilities in Donoi Are	Summary	ation of Port Facilities in Bohol Ar	'ea
--	---------	--------------------------------------	-----

Port Facilities	Unit	TAGBILARAN	JAGNA	UBAY	TUBIGON	CATAGBACAN	GETAFE	TAPAL	POPOO	Guindluman
Cargo Berthing length (depth, m)	m	705.3(8.0 m)	153.00 (11.0m)	222.00 (3.0m)	396.00 (5.2m)	144.00 (4.00-6.00m)	46.5 (6.5 m)	36.00 (4.00m)	21.8(1.5m)	66 (1.0 m)
Degree of damage		Edge of pier damaged			Pier blocks move 5cm	Totally damaged Pier removed				Stair landing damaged
RORO Facilities	Unit	2	2	3	2	2	2	1	None	None
Degree of damage					Settlement by 30 cm	Totally damaged Ramp settled	Settlement by 30 cm			
Total port area	m ²	53,150	7,309	33,909	19,421	3,304	3,217	3,985	Cause way 222m	2,400
Open Storage	m²	5,688	390	19,873	2,813	441	600	1,725	None	Fish market
Degree of damage		Pavement crack and elevation gap 40cm			Pavement & access road crack 20 to 30cm	Pavement crack 30 to 40cm				
Warehouse or Transit shed	m ²	600					1			
Working area	m ²	20,705	4,693	7,202	1,951	849	926	1,182	None	None
Vehicle Parking Areas	m^2	5,336	300	1,520	2,957	None	400	None	None	None
Passenger Terminal Building	m²	623.4	240	210	1,472	None	None	30	100	None
Degree of damage		Totally damaged								
ADM Buildg	m²	760.2	Tran. Shed300	120	68	60	60	30	None	None
Degree of damage		Totally damaged			Leaning 15 degrees	Gate house settled				
Degree of total damage		Serious damage	Very Minor	Very Minor	Medium damage	Serious damage	Medium damage	Very Minor	Very Minor	Damaged by Yolanda
Rehabilitated date, cost(mil. Peso)										


Damaged		= 4	in the second		_		Tubigon		(Loon)		Getafe
Conditions by Typhoon	(H)			St.				The seal			
I f ((Top) Broken landsid piles of the Berths (I funded) Down) Broken Pile concrete for steel pip PPA funded)	IBRD cap	e Settlement a	elevation gap)	PPA Cracks on floor and of Administration a abandoned.	8 9 Y K C C T C T C C C C C C C C C C C C C C	the pier pavem	e and access	The super structur the cruise ship ber which moved outv Cruise berth was demolished and removed.	th of oper	on the paveme a storage and
Rehabilitation			1			Survey Team		Survey Team			
1	No repair yet		Rehabilitated under repair)		New PT Building (1 construction)	Paveme are not Port Ma	ent are repaired but t yet. anager info: Ground l acan and settle 1m a	he piles of pier level raise 1m at	No repair yet	ramp we	ted piles at RORO re broken. was filled in the cra
	Sum	mar	v of tl	he Inve	stigatio	n of Por	rt Facili	ties in]	loilo A	rea	
1.5.5.5				ILOILO	0		ESTANCIA				
Port F	acilities U		nmercial ntainer)	San Pedoro (General Cargo	0) River Wharf	DUMANGAS	(PPA)	ESTANCIA (Fish Port)	BANATE	GUIMBAL	CULASI


5 C 10 C 1 C			ILOILO		(TORING)	DOT & MOLA	ESTANCIA	C.C.C.			
Port Facilities	Unit	Commercial (Container)	San Pedoro (General Cargo)	River Wharf	DUMANGAS	ESTANCIA (PPA)	(Fish Port)	BANATE	GUIMBAL	CULASI	
Cargo Berthing length (depth, m)	m	526 (10.5 m)	634.3 (6.0 m)	980 (5.0 m)	108 (4.5 m, 6.0 m)	117 (6.0 m)	160	Causeway 300	39 (16.0 m)	33 (2.5 m)	
Degree of damage						Pier slab damaged by uplift of wave					
RORO Facilities	Unit	1	Ľ	3	2	None	None	None	None	1	
Total port area	m²	222,000	35,976		Approx. 22,000	Approx. 8,000	Approx. 20,000	Approx. 1,000	Approx. 7,300	Approx. 2,50	
Open Storage	m²	86,192	3,800	· ·		4,490	÷.	None	None	None	
Warehouse or Transit shed	m²	CFS 7,500		-	None	None	Market hall 500	None	None	None	
Degree of damage						Rock mound & pavement repair	Flood up to roof				
Marshalling Area	m²	27,500	2,366		1,800	None		None	None	None	
Vehicle Parking Areas	m²	Equipment shed 525	None	2	Approx. 2,000	None		None	None	None	
Passenger Terminal Building	m²	None	2,100		750	480	None	None	None	Approx80	
ADM buildg	m ²	*	2.473	4	60	48	4	None	None	None	
Degree of total damage		Very Minor	Very Minor	Very Minor	Very Minor	Midium Damage	Minor Damage	Very Minor	Very Minor	Very Minor	
Rehabilitated date, cost(mil. Peso)						2014/12/10, (7.0)					
										6	


		Iloilo						
	Container Terminal		n Pedro(Gen Cargo)	Duman	gas	Estancia (PP	A)	Estancia (LGU)
Damaged Conditions by						The second	-	R Handrack
Typhoon Yolanda	Damage by	r Typhoon Yolanda i	is minor.	Damage by Ty Yolanda is m	phoon inor. damaged pier was e window of	iles at landside of appro by typhoon. Revetment roded by typhoon. Stor f ground floor. Damage om grounded generator	near approach b m surge up to roo d by oil	Minor damage for erthing facilities bu of of market hall w damaged by storm surge by typhoon.
								~
Rehabilitation								A L
1.1	Concrete condition under th	Relatively doo	od condition except few		due to been repair	iles at landside of appro ired. Revetment have b	een	Damage has been
	slab could not inspect due t wave conditions.		piles are damaged.	high tide		ed. (portion of white con damage for buildings.		rehabilitated.
Su	and the second	o concrete		saster Re	structural	damage for buildings.	for DO	
Su	wave conditions.	o concrete	Yolanda Di Bohol Reha	saster Re	structural	damage for buildings.	for DO Yolanda I Albuera Port	FC Rehabilitation Banate Port
	wave conditions.	o concrete	Yolanda Di Bohol Reha Baclayon	saster Re	structural	damage for buildings. ion Project Buenavista	for DO	CC Rehabilitation Banate Port (Iloilo)
Population No. of Baranga	wave conditions. mmary of Bo Guindulman 31,789	o concrete	Yolanda Di Bohol Reha	saster Re	structural	damage for buildings.	for DO Yolanda I Albuera Port (Leyte)	FC Rehabilitation Banate Port
Population	wave conditions. mmary of Bo Guindulman 31,789 ys 19	o concrete hol and Y Inabanga 43,291	Yolanda Di Bohol Reha Baclayon 18,630	saster Re bilitation Mribojoc 20,491	structural	damage for buildings. ion Project Buenavista 27,031	for DOT Yolanda I Albuera Port (Leyte)	CC Rehabilitation Banate Port (Iloito) 29,543
Population No. of Baranga Source of Livelih Handling carg	wave conditions.	o concrete hol and Y Inabanga 43,291 50	Yolanda Di Bohol Reha Baclayon 18,630 17	saster Re bilitation Mribojoc 20,491 22	structural habilitat Clarin 20.296 24	ion Project Buenavista 27,031 35	for DO7 Yolanda H Albuera Port (Leyte) - -	CC Rehabilitation Banate Port (floito) 29,543 18
Population No. of Baranga Source of Liveli Handling carg Damaged facilit	wave conditions.	o concrete hol and Y Inabanga 43,291 50	Yolanda Di Bohol Reha Baclayon 18,630 17	saster Re bilitation Mribojoc 20,491 22	structural habilitat Clarin 20.296 24	ion Project Buenavista 27,031 35	for DO7 Yolanda H Albuera Port (Leyte) - -	CC Rehabilitation Bannte Port (Iloilo) 29,543 18 Fish and Agri.
Population No. of Baranga Source of Livelih Handling carg	wave conditions.	o concrete bhol and M Inabanga 43,291 50 Fish and Agri.	Volanda Di Bohol Reha Baclayon 18,630 17 Fishing and Farming	saster Re bilitation Mribojoc 20,491 22 Fish and Agri.	structural	damage for buildings. ion Project Buenavista 27,031 35 -	for DO7 Yolanda I Albuera Port (Leyte) - - - - - - - - - - - -	FC Rehabilitation Banate Port (Itolio) 29,543 18 Fish and Agri. Fish, shell, etc
Population No. of Baranga Source of Livelit Handling carg Damaged facilit -Causeway -Landing faciliti Estimated cost f	wave conditions.	o concrete hol and Y Inabanga 43,291 50 Fish and Agri. Settlement	Volanda Di Bohol Reha Baclayon 18,630 17 Fishing and Farming Erosion	saster Re bilitation Mribojoc 20,491 22 Fish and Agri. Erosion	structural shabilitat 20,296 24 - Erosion	damage for buildings. ion Project Buenavista 27,031 35 - Erosion	for DO7 Yolanda I Albuera Port (Leyte) - - - - Erosion	FC Rehabilitation Banate Port (Itoilo) 29,543 18 Fish and Agri. Fish, shell, etc Shoulder
Population No. of Baranga Source of Livelih Handling carg Damaged facilit -Causeway -Landing facilitie	wave conditions.	o concrete concrete hol and y Inabanga 43,291 50 Fish and Agri. Settlement Settlement	Yolanda Dia Bohol Reha Baclayon 18,630 17 Fishing and Farming Erosion	saster Ree bilitation Mribojoc 20,491 22 Fish and Agri. Erosion	structural habilitat Clarin 20,296 24 - Erosion -	damage for buildings. ion Project Buenavista 27,031 35 - Erosion -	for DOT Yolanda I Albuera Port (Leyte) - - - Erosion Stair landing	CC Rehabilitation Banate Port (Iloilo) 29,543 18 Fish and Agri. Fish, shell, etc Shoulder Stair landing

Type of Sinucture	Finger F Most piers in Phi are supported by			Pier				Sheet I ne	Queywall	S	Conservay	
	Most piers in Phi	Pler	and the second second	Open-type	Steel Pipe 1	Plles	Concret	e Sheet Piles	Steel She	ret Piles	Canseway	
			Concrete Piles	Vertical & Raking		Vertical Piles						
Sincture piles.			are adopted for	In case of deep water wharves and quay en- the deck, coupled rak may be required due large horizontal force study, the container w Hoilo Port is the one th disaster resilient.	anes on select ing piles for con- to the They is In this con- wharf in rake	tical steel pipe piles ar cted to resist the horiz res by vertical piles on y have the feature of struction procedure the rd piles.	ontal selected f iy. cases of s easier wharves i an due to les treatment Anchor w		In case of me m water dept sheet piles an pipe piles are instead of cor piles. Most or anchors are s piles (vertical coupled rakin	th, steel ad/or steel used ncrete sheet f the steel pipe l piles or	Small-scale wha for shallow draft vessels	
LEYTE (Total 9 ports)	EYTE Palempon(7°),		Tacloban, Palompon. Ormoc				ijpe,			Tacloban (Steel Pipe Sheet Pile)		
BOHOL Total 10 ports)	Tagbilaran Passe berths(10°), Catagbacan(15°) Ubay(15°), Tubig Talibon(N/C), C	'), igon (N/C) ,	Tagbilaran	Tagbilaran					RoRo ramp ù	RoRo ramp in Tagbilaran		
ILOILO (Total 7 ports)	CAUDORI(19/C-7, A JUY(5)		lloilo FSP (Fort San Pedro Terminal), Iloilo IRW (Iloilo River Wharf)	floilo ICPC (floilo Commercial Port Cor		o ICPC (Iloilo Comme (Complex)	Pedro Te	FSP (Fort San minal), but sheet pile in	floilo FSP (Fe Pedro Tennii		DOTC Estancia Banate,	
Percentage	54%		18%	28		45		-	71	8		
										_		
			Fype and A	rea of Buil	dinos fe	or Disaster	Resilier	nt Ports				
Name of	bnidings	-7 Unit	Type and A	rea of Buil		or Disaster BILARAN	Resilier	nt Ports		PPA E	STANCIA	
Name of Administrat					TAGI Mixed	BILARAN		1.12.00.000	(ICPC)	RC Bui	STANCIA Iding w/ GI pofing	
	tion/ Office		TACLOBAN RC Building w	ORMOC RC Building w/	TAGI Mixed Roofing	BILARAN Mat'ls w/ GL	TAPAL RC Building w/ Roof	ILOILO RC Buil	(ICPC) ding w/ Deck	RC Bui	lding w/ GI	
Administral	tion/ Office		TACLOBAN RC Building w Roof Deck	ORMOC RC Building w/ GLRoofing	TAGI Mixed Roofing 2	BILARAN Mat'ls w/ GI (Temporary)	TAPAL RC Building w/ Roof Deck	ILOILO RC Buil Roof 4 Sto 435	(ICPC) ding w/ Deck rrey x4	RC Bui R	lding w/ GI poling	
Administrat Buil	tion/ Office	Unit	TACLOBAN RC Building w Roof Deck 3 Storey	ORMOC RC Building w/ GLRoofing 1 Storey 281	TAGI Mixed Roofing 2 26	BILARAN Mat'ls w/ GI (Temporary) Storey 1.45 x 2	TAPAL RC Building w/ Roof Deck 1 Storey	ILOILO RC Buil Roof 4 Sto	(ICPC) ding w/ Deck rrey x4 ing w/ CI	RC Bui R(2 S 240 (2n	lding w/ GI oofing Storey d Fir. only)	
Administral	tion/ Office	Unit	TACLOBAN RC Building w Roof Deck 3 Storey	ORMOC RC Building w/ GLRoofing 1 Storey	TAGI Mixed Roofing 2 26	BILARAN Mat'ls w/ CI (Temporary) Storey	TAPAL RC Building w/ Roof Deck 1 Storey	ILOILO RC Buil Roof 4 Sto 435 RC Build	ding w/ Deck prey x4 ling w/ Ci 0ng	RC Bui R(2 S 240 (2n	lding w/ GL oofing Storey	
Administrat Buil	tion/ Office	Unit m ²	TACLOBAN RC Building w Roof Deck 3 Storey 686 x 3 None	ORMOC RC Building w/ GLRoofing 1 Storey 281	TAGI Mixed Roofing 2/ 26	BILARAN Mat'ls w/ GI (Temporary) Storey 1.45 x 2 None	TAPAL RC Building w/ Roof Deck 1 Storey 30	ILOILO RC Buil Roof 4 Sto 435 RC Build Roo	ding w/ Deck rey x4 Ing w/ CI 0ng rey	RC Bui R(2 S 240 (2n	lding w/ GI oofing Storey d Fir. only)	
Administrat Buil	tion/ Office	Unit m ²	TACLOBAN RC Building w Roof Deck 3 Storey 686 x 3 None RC Building w/	ORMOC RC Building w/ GLRoofing 1 Storey 281	TAGI Mixed Roofing 2 261	BILARAN Mat'ls w/ GI (Temporary) Storey 1.45 x 2 None ddling w/ GI	TAPAL RC Building w/ Roof Deck 1 Storey 30	ILOILO RC Buil Roof 4 Stc 435 RC Build Roo 1 Stc 746 RC Build	ding w/ Deck rrey x4 ing w/ Ci ling rrey 7.4 ing w/ Gi	RC Bui R(2 S 240 (2n	lding w/ GI oofing Storey d Fir. only)	
Administrat Buil	tion/ Office	Unit m ²	TACLOBAN RC Building w Roof Deck 3 Storey 686 x 3 None	ORMOC RC Building w/ GLRoofing 1 Storey 281	TAGI Mixed Roofing 2 26 26 1 1 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	BILARAN Mat'ls w/ GI (Temporary) Storey 1.45 x 2 None	TAPAL RC Building w/ Roof Deck 1 Storey 30	ILOILO RC Buil Roof 4 Sto 435 RC Build Roo 1 Sto 746	e (ICPC) ding w/ Deck mey x4 ing w/ Cl Ong mey 7.4 ing w/ Gl Ong Mag w/ Gl	RC Bui R 2 ! 2 40 (2n	lding w/ GI oofing Storey d Fir. only)	
Administrat Buil Cl	tion/ Office	Unit m ²	TACLOBAN RC Building w Roof Deck 3 Storey 686 x 3 None RC Building w/ GI Roofing	ORMOC RC Building w/ GLRoofing 1 Storey 281 None	TAGI Mixed Roofing 2 26 26 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	BILARAN Mat'ls w/ GI (Temporary) Storey 1.45 x 2 None diding w/ GI cooling	TAPAL RC Building w/ Roof Deck 1 Storey 30 Noné	ILOILO RC Buil Roof 4 Sto 435 RC Build Roo 1 Sto 746 RC Build RC Build ROO	(ICPC) ding w/ Deck rey x4 ing w/ GI 0hg rey 7.4 ing w/ GI fing mg rey	RC Bui R 2 ! 2 40 (2n	lding w/ GI boofing Storey d Ffr. only) Noné	
Adhinistrat Buil Cl	tion/ Office	Unit m ²	TACLOBAN RC Building w Roof Deck 3 Storey 686 x 3 None RC Building w GI Roofing 1 Storey	ORMOC RC Building w/ GLRoofing 281 None None RC Building w/	TAGI Mixed Roofing 2 26: 1 1	BILARAN Mat'ls w/ GI (Temporary) Storey 1.45 x 2 None diding w/ GI cooling Storey	TAPAL RC Building w/ Roof Deck 1 Storey 30 Noné	ILOILO RC Build Roof 4 Sto 435 RC Build Roo 1 Sto 746 RC Build Roo 1 Sto	(ICPC) ding w/ Deck rey x4 ing w/ GI 0hg rey 7.4 ing w/ GI fing mg rey	RC Bui R 2 to 2 to 2 to 2 to 2 to 2 to 2 to 2 to	lding w/ GI pooling storey d FIr. only) None None lding w/ GI	
Adhinistrat Buil Cl	tion/ Office	Unit m ²	TACLOBAN RC Building w Roof Deck 3 Storey 686 x 3 None RC Building w GI Roofing 1 Storey	ORMOC RC Building w/ GL Roofing 1 Storey 281 None None	TAGI Mixed Roofing 2 26 1 RC Bu RC Bu RC Bu	BILARAN Mat'ls w/ GI (Temporary) Storey 1.45 x 2 None ddding w/ GF cooling Storey 300	TAPAL RC Building w/ Roof Deck 1 Storey 30 Noné	ILOILO RC Build Roof 4 Sto 435 RC Build Roo 1 Sto 746 RC Build Roo 1 Sto	(ICPC) ding w/ Deck orey x4 ing w/ CI fing mrey 7.4 ing w/ CI ling mrey 7.8	RC Bui Ri 240 (2n P P RC Bui R	lding w/ GI poofing Storey d FIr. only) None	

0 & 15 Slab: Precast type Beam (W50xH40cm) No damage	Palompon Open type wharf RC (40cm x 40cm) 0 & 7 Partialy under repairing slab concrete Cone. Sheet Piles		lsebel Pier Ocm x 40cm)	Om	-		1	Not operational, la	ess than 40% operation
PSC (40cm x 40cm) 0 & 15 Slab: Precast type Beam (W50xH40cm) No damage Conc. Sheet Piles A No damage	RG (40cm x 40cm) 0 & 7 Partialy under repairing slab concrete Conc. Sheet Piles			Pi	mee	Bayb	bay	Hilonges	Buto
0 & 15 Slab: Precast type Beem (W50xH40cm) No. damage Conc. Sheet Piles A No damage	0 & 7 Partialy under repairing slab concrete Conc. Sheet Piles		RG (40cm x 40cm)		ler	Pie	ar i	Pier	Pier
Slab: Precast type Beam (W50xH40cm) No damage Conc. Sheet Piles A No damage	Partialy uncer repairing slab concrete Conc. Sheet Piles	N		RG (40cm	n x 40cm)	RC (40cm RC(45cm		RC	RC
Beem (W50xH40cm) <u>No damage</u> Conc. Sheet Piles A No damage	repairing slab concrete Conc. Sheet Piles	N	0 & 5	0 &	15	8 0	15	0 & ?	0 & ?
A No damage	Cutario a Chicarda	1.1	o damage	(W40xH Partisly	sam H30cm) damaged recairing	Sleb bot partialy d		No damage	No damage
No damage	A	Con	crete Walls	1	-			Concrete Walls	Concrete Walls
			A	E	B	В	P.	A	A
Tagolleran	No damage No damage		damaged piles	es Damaged slab		Damage	d slab No damage		No damage
Tagbileran Ubay		Tubigon		Catebacen	(Loon)	Clerin		Gotafo	Tabal
Open type wherf	Pier	Pier		Pier		Pier		Pier	Pier
SPP Ø50cm, RC40cm	RC (40cm x 40cm)	RC (40em x 40em) Pt		PSC (45em	x 45cm) F	C (40cm x	40cm) R	C (40cm x 40cm)	RC (40cm x 40cm)
0.8.10 0.8.15			0 8 7	0 & 15		0		067	
Pile caps are portialy demoged.	Sieb concrete is		wased py	are cestro	oled by	All weaked	ewey.	1.1.1.1	
Under constructing concrete walls due to damaged by certiqueko	Cons. Sheet pilos		Damaged by earthquakes barthquakes				Concrete Walls		
B	Ð	e e		D		٥		B	A
Partiely demaged piles	and the second second	red Reking piles are		Seriously demaged		Seriously dan	meged fe	w piles are broke	No demage
ion of Exist		demag	ed by quske.					Minor damage, 80	Description 9 to 100% operational 50 to 80% operational
ion of Exist		demag	ed by quske.				-	Minor damage, 80 Midium damage, 9 Big damage, 40 to) to 100%o operational 60 to 80% operational
ion of Exist	ing Berthi	demag	ed by quske.	for Su		Ports	E	Minor damage, 80 Midium damage, 9 Big damage, 40 to) to 100% operational 60 to 80% operational 60% operational
	r) Iloilo (Gen	demag ng Fa	acilities	for Su	irvey]	Ports	E	Minor damage, St Midium damage, St Big damage, 40 to Not operational, le	0 to 100% operational 50 to 80% operational 60% operational css than 40% operation
lloilo (Containe	r) Iloilo (Gen rf Open type aRD) PA) BC (40cm x	demes ng F; Cargo) wharf	acilities Iloilo (Rive	for Su r Whar() s wharf icm, PSC	rvey]	Ports neas	Esta	Minor damage, 80 Midium damage, Big damage, 40 to Not operational, lo meia (PPA)) to 100% operational 50 to 80% operational 60% operational ess than 40% operation Ajuy Culasi
Iloilo (Containe Open type what SPP #1020mm (IE SPP #600mm (PI RC (50cm x 50cm	r) Iloilo (Gen rf Open type aRD) PA) BC (40cm x	demes ng F: Cargo) wharf 40om)	acilities Iloilo (Rive Open type RC 40em 48	for Su r Whar() s wharf icm, PSC	Duma Pi	Ports neas	Esta RG (40	Minor damage, 80 Midlinu damage, Big damage, 40 to Not operational, la meia (PPA) Pier) to 100% operational 50 to 80% operational 60% operational ess than 40% operation Ajuy Culasi Pier
lloilo (Containe Open type what SPP ¢1020mm (IE SPP ¢600mm (PI RC (50cm x 50cm (PPA)	r) Iloilo (Gen rf Open type BRD) PA) RG (40om x 0 & ?	demes ng F: Cargo) wharf 40om)	acilities Iloilo (Rive Open type RC 40em 48	for Su r Whar() s wharf icm, PSC	Duma Pi	Ports ngas sr x 40om	Esta RG (40 Pile cap	Minor damage, Si Midlanu damage, Big damage, 40 to Not operational, la meia (PPA) Pier Dam x 40 cm)	to 100% operational 50 to 80% operational 60% operational ess than 40% operation Ajuy Culasi Pier RC (40em x 40en
lloilo (Containe Open type what SPP ¢1020mm (IE SPP ¢600mm (PI RC (S0cm x 50cn (PPA) 0 & 15 & 20	r) Iloilo (Gen rf Open type BRD) PA) RG (40om x 0 & ?	demes ng F: Cargo) wharf 40om)	acilities Iloilo (Rive Open type RC 40em 48	for Su r Whar() s wharf icm, PSC	Duma Pi	Ports ngas sr x 40om	Esta RG (40 Pile cap	Minor damage, St Midlam damage, J Big damage, 40 to Not operational, I nois (PPA) Pier Dam x 40 cm) D & 10 st damaged by	to 100% operational 50 to 80% operational 60% operational ess than 40% operation Ajuy Cutlasi Pier RC (40em x 40en 0 & 10
lloilo (Containe Open type what SPP ¢1020mm (IE SPP ¢600mm (PI RC (S0cm x 50cn (PPA) 0 & 15 & 20	r) Iloilo (Gen rf Open type BRD) PA) RG (40om x 0 & ?	demes ng F: Cargo) wharf 40om)	acilities Iloilo (Rive Open type RC 40em 48	for Su r Wharf) e wharf icm, PSC	Duma Pi	Ports	Esta RG (40 Pile cap	Minor damage, St Midlam damage, J Big damage, 40 to Not operational, I nois (PPA) Pier Dam x 40 cm) D & 10 st damaged by	to 100% operational 50 to 80% operational 50% operational ess than 40% operation Ajuy Culasi Pier RC (40em x 40en 0 & 10 Ne damage L-shaped Conc.
	0.8.10 Pilo caos are partisly damaged. Under constructing concrete walls due to damaged by perthicuske B	0 & 10 0 & 15 Pilo cause are partially damaged. Sisb concrete is partially damaged du to hit by ahigh to hit by ahigh Under constructing damaged by serthquake Conc. Sheet siles B B	0 & 10 0 & 15 Pile case are partiely demaged. Slab concrete is partiely demaged due to hit by ship De sar Under constructing concrete walls due to damaged by serthqueke Conc. Sheet piles B De Berling	0 & 10 0 & 15 0 & ? Pilo capa are partially damaged. Stab concrete is partially damaged due to hit by ship Damaged by earthquekes Under constructing damaged by pertriqueke Conc. Sheet pilos generation Damaged by partiquekes B B B	0 & 10 0 & 15 0 & ? 0 & 1 Pilo waps are partially damaged. Siab concrete is partially damaged due to hi by ship Dumaged by sarthquakes Most of the are destri- sarthquakes Most of the are destri- oerthquakes Under constructing damaged by serthquakes Cone, Sheet pilos Damaged by oarthquakes Cones, oarthquakes B B D D	0 & 10 0 & 15 0 & 7 0 & 15 Pile europ ere pertially demeged. Siab concrete is partially damaged due to hit by ship Dumaged by sarthquekes Most of the functions are destroid by serthquekes. Under constructing damaged by serthquekes Cone. Sheet piles Dumaged by sarthquekes. Consoway under copier due to earthqueke B B D Partially damaged Raking piles are Sarthqueke are Sarthqueke are sarthqueke	0 & 10 0 & 15 0 & 7 0 & 15 0 Pile euros are pertially demaged. Sinb concrete is partially damaged due to hit by ahlo Dumaged by sarthquakes Most of the facilities are dostroidd by oarthquakes. All washed Under constructing concrete walls due to damaged by serthquakes Cone. Sheet piles Damaged by conthquakes. Consoway under repair due to earthquakes All washed B B B D D Partially damaged Raking piles are stripting and the stripting and	0 & 10 0 & 15 0 & 2 0 & 15 0 Pilo euror ere partialy demaged. Sisb concrete is partialy demaged due to hit by ahip Damaged by sarthoukes Most of the facilities are destroided by serthoukes. All weahed away Under constructing concrete wells due do gene. Sheet pilos Damaged by carthoukes Conceway Under repair due te sarthoukes Conceway Under repair due te sarthoukes Conceway Under repair due te sarthoukes Conceway B B D D Imaged by carthoukes Conceway	0 & 10 0 & 15 0 & ? 0 & 15 0 0 & 2 Pile ease are partially demaged. Under constructing concrete walls due to damaged by serthquakes Side concrete is partially demaged due to hit By ahip Demaged by serthquakes Most of the fucilities are destroided by serthquakes. All washed away Imaged by concrete walls concrete walls due to hit By ahip Under constructing damaged by serthquakes Cons. Sheet piles Damaged by carthouskes Causeway Concrete Walls B B D D B Print B B D D B












Method	Case-1 Installation of Coupled Raking Piles in Soud of Beeth Bar	Case-2 Removal of Deck and Installation of Coupled Raking	Case 3 Removal of Beck and Installation of Submerged	Case-4 Installation of Tie Rod, Anchor Wall and Scalari	Case-5 factabilities of Ground Anchor and Joint Scalani	Case-6 Installation of Submergred Steel Beams	Case-7 Installation of Retailorced Concrete Beams	
Typical Section	AH	-Al	Strut	anti-	Artimeter Artificial	AN ARCHINGTON OF	- and a state of the state of t	
General Description	*Additional (adorg piles resist against the between a sense forces. *Alatag piles and coping concrete are notable in front of the anatog berth. *The borth fine as shifted sense and.		*Additional atom attochuse reside againet the horisontal seismic. Greco. **Sistonergo di atros are sumithet visitonergo di attochi attochi ununual of all disci consecte: *Granting mortae is injected horisone attatis and pilos in bu ingegatod firmi). *After atting atruta, new deck conservete is reconstrationd.	¹ Additional inchers with the rock model against the scowerd horizontal actionic flowane. Victomating wall motions the landward horizontal actionate forces through paint acclust. ¹ Land ack deck concrete is removed partially and the rock and motion walk ¹ After installation of ancience walk ¹ After installation.	⁴ Addatused ground archeor resist against the warward herboard warms: Forces. ⁴ Relating ward results the landward herboard actimite forces through just scalau. ² Land adde dock emercies in reserved partially and ground ancless are historic provider and "Dock concrete in relationed with restriction of proved archeors."	 Additional advances of the answer of the second seco	Additional readinced concrete beams robact the stress of the existing piles and increase the resistances against the borboard segme forces. Concrete beams are constructed anderneath the existing concrete beams.	
Special Consideration for Rehabilitation	 Firstlivation is treatly stronged due to construction of new concrete deck. - Due to by equipment for construction, it is not recommendable for small size of berth (deph and knyth). 	Hurth utilization in scally integral due to demokrism and reconstruction of the contex of concretic deck. "Due to big equipment for construction, it is not recommendable for small size of berth (depth and length).	 Term unliggtes is touchy atopped that is demolitimized, reconstruction of all concrete: dock Due to big equipment for construction, it is not recommendable for small size of berth (depth and length). 	necessary behind the pier to resist horizontal scientic force. •The space for construction area of anchor wall with the rod is necessary.	 Firm retaining well structure is necessary behind the pire to resist bericontal science force. The space for construction area of ground anchor on the pier is necessary. Berth utilization is partially possible due to the small construction area. m concrete dock. 	Inerth uniformitien during construction to possible due too no construction work on hand. • Due to special equipment/tool such as floater, Special experience is necessary. • It is applicable for large scale structure due to flexibility of large size of beam.	Herth artination during construction is possible that to no construction work on land. • Due to minimal equipment for construction, no special experience is necessary. • It is applicable for small scale structure only due to additional beam under the concrete deck.	
Main Materials	* Steel pipe piles have more resilience than PC piles. * Steel pipe piles can be driven with 20-25 degrees of slope.	 Steel pipe piles have more resilience than PC piles. Steel pipe piles can be driven with 20-25 degrees of slope. 	* Submerged struts are fabricated in the suitable factory. * Grouting mortar is necessary:	*Tie rods are available in the Philippine.	•Ground anchors are to be imported from foreign countries.		•Rebars and concrete only	
Quality Control	* No special skill is necessary.	 No special skill is necessary. 	 Special experience for installation is required to construct submerged struts. 	•No special skill is necessary:	 Special experience for installation is required to construct ground anchors. 	 Special experience for installation is required to construct submerged beams. 	*No special skill is necessary.	
Workability	 Phantag pilag burge is required to be able to drive a raking pile. No special skilled works is needed. 	A special stage to be able to instal ranking pile is set on the deck. Normal construction methods are adopted except above stage. No offshore equipment is required.	Demolition of all deck concrete is required. "The dimensions of struts are to be adjusted by measuring the existing pile locations." Special engineering know-hows are required for installation of struts. "Many kinds of works are to be carried out and construction period will be the huperst.	The deck side of ite wire should be liked limitly with deck concrete to retain the borizontal forces. Joint sealant is installed between deck concrete and coping of revetment.	Busically all works are onshore. Drilling equipment is required to set the ground archer into burning layer. The deck side of ground anchor should be fixed firmly with deck concrete to retain the horizontal forces. Joint scalant is installed between deck concrete and coping of reventment.	Special technical know-hows are required to install the saltenerged sized beams below the deck concrete. "The keigh of each beam are determined by he leadin of the existing piles. "Most of works are carried out under water. "Special Datater is necessary to install soltmerged beam.	Large temporary stagings under water are required because most of works should be carried out below bwy tike kvel. 'Inderware concrete alsould be placed with securing the good quality of concrete. 'iligh-early-atrength concent may use to utike the borth atter concrete placing.	
	Note : For all of type of above r	elafocing structure, Environmen		nagement Plan (EPRM P) is required.			1 154	
			al Performance Report and Ma	espended Plan (EPRMP) is required			19	


		Cas	æ-1	Cas	æ-2	Cas	æ-3	Cas	se-4	Cas	se-5	Cas	se-6	Cas	e-7
Me tho	Installation of Coupled Raking Piles in front of Berthline		Remuval of Deck and Installation of Coupled Raking Piles		Remuval of Deck and Installation of Submerged Struts			n of Anchor 1 Sealant		of Ground and Joint lant		ition of ged Steel anus	Installtion of Reinforced Concrete Beams		
Item	Priority Weights	Rank	Score	Rank	Score	Rank	Score	Rank	Score	Rank	Store	Rank	Store	Rank	Store
Quality Control	3	2	6	2	6	3	9	1	3	3	9	3	9	2	6
Workability	3	3	9	3	9	4	12	1	3	2	6	3	9	2	6
Construction Period	3	4	12	4	12	5	15	2	6	2	6	1	3	3	9
Work Suspension Period	2	3	6	3	6	4	8	2	4	2	4	1	2	1	2
Construction Cost	1	5 (1.00)	5	5 (1.03)	5	4 (0.75)	4	1 (0.32)	1	2 (0.39)	2	4 (0.70)	4	- <u>3</u> (0.61)	3
To tal Sc	ore	3	8	3	8	4	8	1	7	2	7	2	7	2	6
Rank		4	5	3		4		j	L	3	2	13	2	4	











2.4. Consultation Meeting

(1) Minutes of the Meeting

Minutes of Meeting of

Consultation Meeting on Data Collection Survey on Disaster-resilient Feeder Ports and Logistics Network in the Republic of the Philippines

Date:	September 30, 2015
Venue:	DOTC Headquarters
	16/F Unit166 Columbia Tower Ortigas Avenue, Mandaluyong City
	1555 Philippines
Purpose:	Explanation of the Intermediate Report by the JICA Study Team
Participants:	See attached attendance sheet
Handout	Presentation paper
materials:	Scope of the Study and Survey Method

1. The consultation meeting on Data Collection Survey on Disaster-resilient Feeder Ports and Logistics Network in the Republic of the Philippines was held on September 30, 2015 at the meeting room Unit 166 of the Department of Transportation and Communications (herein after referred to DOTC) under the participation of personnel of DOTC, PPA, NEDA, DBM, DOF, DILG, DPWH and PHIVOLCS. The attendees are shown in the attached attendance sheet

- 2. The JICA study team made presentations on intermediate results of main subjects of the survey: the disaster resilient ports in the target area and guidelines on disaster resilient ports; guidelines of social ports and trial selection in the target area; and standard model design of disaster resilient port facilities of the disaster resilient ports in the target area. In addition, findings on port activities and port network in the target area and budgetary system of Philippines related to Disaster Risk Reduction Management were presented.
- 3. The following discussion points were tackled during the question and answer sessions.

Mr. Paul Irineo P. Montano, Local Government Operations Officer IV, representative from DILG, raised clarification under Item 4-2 (Screening Criteria based on Basic concept of Social Port), why put the title 'Regional Economy' while what you needed is the population of the municipality? He also asked whether the criteria could be applied in prioritizing from a viewpoint of LGU.

Mr. Shimada answered that the method of prioritizing the social port under LGU could be

applied when LGU intended to give the priority. He added it was better to add local factors.

Mr. Maximo M. Montana II, representative form DPWH made also the following observations on Item 4-2.

- Item a (Municipality Income Grade) under #1 Human Security should be well described in #3 Regional Economy;
- Item a (Population of Municipality) under # 3 Regional Economy can well describe the extent of population served by the social port under #1 Human Security; and
- Under #2 Transportation, would term "access" from National Highway be more appropriate than distance from National Highway considering that the port is available through an access road to national highway?

Mr. Shimada explained that the word of accessibility included several factors such as time, pavement condition. Such detail factors shall be discussed in the second screening meeting. Simple indicator is better as a criterion.

Ms. Consuelo Beltran, Director IV and representative from DBM, commented that the project by PPP or ODA needs to be submitted and approved by NEDA ICC and Board.

This was confirmed by Ms Hazel Palapus, Repesentative form NEDA-Infrastructure Staff, but added that only those projects that cost P1 Billion and above need to be approved by the NEDA Board. Other infrastructure projects below the P1B will just need to be included in CIIP. Ms. Ellen explained that the budget of the project on social ports may be appropriated in normal process.

Ms. Dolly Asere, representative form DOF, made a comment on applying insurance to port facilities in case they are damaged due to typhoon, earthquake and tsunami, such that the LGUs or port administrator/operator can claim to rehabilitate the port. She also added that PPA rehabilitate its own port facilities using its own funds but that there are cases that PPA uses government fund in case there is a large scale disaster. Mr. Shishido said that the situation of ports in other countries would be checked whether this is being practised or not. Engr. Renato L. Yumang, a principal engineer of PPA, informed the Meeting that he will to confirm first with the Head Office whether PPA applies insurance or not.

Mr. Montano said that he will also look for a document on application of insurance scheme to public infrastructure and send the information to DOTC as soon as possible.

Mr. Montano further asked if the level of the LGU prioritization for port maintenance was considered in the selection criteria for social ports. He was of the view that the LGU may have included in their annual or multi-year investment plan the maintenance and/or construction of their own port/s and the LGU may have also different prioritization parameters. He then thought of the need to have a balance project selection methodology or

criteria.

Mr. Ferre of DOTC, informed that in the past and the current situation for ports programming, the Department used to receive various requests for port development coming from the different LGUs nationwide. Because of the extensive number of requests coming in but limited budget allocated for ports in a certain year, prioritization process is applied to select which ports need to be funded first and implemented. The existing selection criteria that we presently use is the subject of assessment by this Study to come up with an improved and more rational selection process/criteria.

Mr. Hayato Nakamura, representative from JICA, suggested that location of airport is one of important factors for disaster management and it should be mentioned in the report.

4. The participants acknowledge the contents of the presentations and agreed the basic direction of preparing guidelines for disaster resilient ports and social ports. The ports selected as disaster resilient ports are Iloilo port, Estancia Port, Tagbilaran Port, Tapal Port, Tacloban Port and Ormoc Port in the study and the direction of preparing standard design model for the proposed port facilities.

5. The study team will proceed to the finalization based on the result of the meeting.

6. Next consultation meeting will be held in the middle of November.

Date September 30, 2015

ENRICO C. FERRE

Division Chief Water Transport Planning Division Department of Transportation and Communications

Tatsuyuki SHISHIDO

0 1 20 2015

(2) Attendance Sheet

Attendance Sheet

Venue: 16/F Unit166 Columbia Tower Ortigas Avenue, Mandaluyong City 1555 Philippines Date: September 30, 2015

No.	Name	Organization/ Department	Position/ Title
1	RACHELLE RABINO	DPWH	OJT-PPD/Planning Service
2	GLORIA V. CUNANAN	DPWH	E-IV DPD.PS
3	RALPH JOED DELA CRUZ	DPWH	E-II , DPD, PS
4	MAXIMO M. MONTANA II	DPWH	POIV
5	CONSUELO BELTRAN	DBM	CBMS
6	SHIELA YECLA	DBM	BMS
7	PAUL IRENEO P. MONTANO	DILG	LGOO IV
8	RENATO L. YUMANG	PPA	Municipal Engineer
9	FROILAN S. DE VERA	DOF	Finance Analyst
10	DOLLY ASERRE	DOF	Finance Analyst V
n	VICTOR B. PAMI	PHILVOLCS	POI
12	HAYATO NAKAMURA	JICA Philippines Office	Project Formulation Adviser on DRRM
13	CORINA ISABEL C. ALCANTARA	DOTC- Office of the Undersecretary for Planning	Project Development Office
14	MILKY BABILONIA	DOTC- Office of the Undersecretary for Planning	Project Development Office
15	SHANICA SEN V. SOLLEGUE	DOTC- Office of the Undersecretary for Planning	Project Development Office

Attendance Sheet

Venue: 16/F Unit166 Columbia Tower Ortigas Avenue, Mandaluyong City 1555 Philippines

No.	Name	Organization/ Department	Position/ Title
16	HAZEL PALAPUS	NEDA	Senior EDS
17	FELICISIMO C. PANGILINAN	DOTC	Deputy and OIC, Planning Service
18	ENRICO FERRE	DOTC - WTPD	Chief
19	ELENITA D. ASUNCION	DOTC - WTPD	Sr TDO
20	HOMER DELA PAZ	DOTC - WTPD	
21	DENNIS M. ALBANO	DOTC - WTPD	Sr TDO
22	BELINDA C. SALVOSA	DOTC - WIPD	SCDO
23	EMMA P. RIVERO	DOTC - WIPD	STDO
24	MENCHIE D. BOGNALOS	DOTC - WTPD	
25	MYRA B. MEDINA	DOTC - WIPD	
26	TATSUYUKI SHISHIDO	JICA Study Team	Team Leader
27	TAKASHI SHIMADA	ЛСА Study Team	
28	ISAO HINO	ЛСА Study Team	
29	KEN SAITO	JICA Study Team	
30	SUZANNE TORRES	ЛСА Study Team - Support Staff	

Appendices

Attendance Sheet

No.	Name	Organization/ Department	Position/ Title
31 ERNES	STO CRUZ	ЛСА Study Team - Support Staff	C.E
32			
33			
34			
35			
36			
37			
38			
39			
40			
41			
42			
43			
44			
45			

Venue: 16/F Unit166 Columbia Tower Ortigas Avenue, Mandaluyong City 1555 Philippines

(3) **Presentation Materials**

1) Tentative draft for Discussion on Guidelines for Selecting Social Ports in the Target Area



On 30 Sept. 2015 JICA Study Team for Disaster –Resilient Feeder Ports & Logistics Network

SHIMADA/JICA * OCDI



Takashi SHIMADA Principal Researcher, OCDI

- 2

- In 1981, I started working in the Ministry of Transport (MOT) in Japan as a Civil Engineer.
- I have been engaged in transport planning and engineering for more than 33 years.
- I have also taken part in overseas projects such as in Algeria, Vietnam, the Philippines and Cambodia over a 10-year period.
- In 2004, I was also a lecturer of port and airport development policy at Kobe National University.
- I took an early retirement option of Ministry of Land, Infrastructure and Transport (MLIT) and have been working in OCDI since 2014 as a principal researcher.

SHIMADA/JICA # OCDI

Contact Add.= t-shimada@ocdi.or.jp

Appendices

Table of Contents

- 1. Ports in the Philippines
- 2. Current Situation and Issues for Social Port Development
- 3. Study Scope and Current Situation of Target Area
- 4. Basic Concept of Social Port Development
- 5. Trial Screening
- **6. Important Points**

1. Ports in the Philippines

SHIMADA/JICA = CICDI

- Total Number of Philippine Ports= 2,035
- Public Ports= 1,612
 - Base Port & Terminal Ports = Relevant Port Authority
 - Other Governmental Ports
 - ✓ Social Port = National Fund (DoTC and Port Authority)
 - Feeder Ports = Foregin Fund (DoTC), part of social ports
 - ✓ Tourism Port = Natonal Fund planned by DoT and DoTC
 - ✓ Fishing Ports = National Fund (PFDA)
- Private Ports= 423
 - Private Commercial Ports= Public Use
 - Private Non Commercial Ports= Particular Use

SUIMADA/JICA × OCDI

Appendices




- 2. After this, Feeder Ports by ODA were developed based on JICA Mater Plans Studied in 2000 and 2004.
- Social ports developed by the national government budget are mainly based on LGU request or regional political will.

SHIMADA/IICA = (ICD)

2-2 Current Budgetary System to develop Social Ports


- 1. Construction by Central Government=DoTC, DA, and Management Commission to LGU
- 2. Grant Budget by Central Government
- IRA(Internal Revenue Allotment)=80%Project Cost
- Funding Assistance=Budget Shear between Authority and LGU. Auditor' check for Specification and Financial Aspects is required
- 5. Invested fully by LGU= Highly Urbanized City
- 6. PPP or BOT


SUIMADA/IICA × OCDI





LACIUUII	ig Cebu	and Ne	egros			
Leged		lloilo City Bohol	iding Tailo City) luding Tacloban City) Xiy	1990 20 1,337,981 1,55 309,505 36 948,403 1,13 1,230,925 1,41	lation 00 2010 9142 1.805.576 86,391 424,619 91,130 1.255,284 1,869 1.567,284 78,639 221,174	Area D. Km2 1 5,079.17 4,820.95 6,515.05
9 Existing Ro-Ro Terminal (\$2 Base Key Cby Ro-Ro Term) On-pion Ro-Ro Terminal Development) Terminal Port) CY2015 Social and Tourism ports development project	38()					
3-	-3 Cu		Situa	tion	of	
Ports I		rrent	Situa			ea
Ports C		rrent opme	Situa ent in	Targ	et Ar	ea
Ports C Classification Population 2010 (,000)	Devel	rrent opme Ilollo Prov. 2,230	Situa ent in Bohol Prov. 1,255	Leyte Prov. 1,789	et Ar Total 5,274	ea
Classification Classification 2010 (,000) Private	Devel	rrent opme <u>lloilo Prov.</u> 2,230 10	Situa ent in Bohol Prov. 1,255 6	Leyte Prov. 1,789 10	et Ar ^{Total} 5,274 26	ea
Classification Classification 2010 (,000) Private Base / Terminal	Devel	rrent opme lloilo Prov. 2,230 10 3	Situa ent in Bohol Prov. 1,255 6 6	Leyte Prov. 1,789 10 5	et Ar 5,274 26 14	ea
Classification Classification 2010 (,000) Private Base / Terminal Social	Devel	rrent opme loilo Prov. 2,230 10 3 21	Situa ent in Bohol Prov. 1,255 6 6 6 6	Targ Leyte Prov. 1,789 10 5 39	et Ar Total 5,274 26 14 128	ea
Classification Classification 2010 (,000) Private Base / Terminal	Devel	rrent opme lloilo Prov. 2,230 10 3	Situa ent in Bohol Prov. 1,255 6 6	Leyte Prov. 1,789 10 5	et Ar 5,274 26 14	ea






































































Appendices


3) Tentative Draft for Discussion on Guidelines for Selecting Disaster Resilient Ports in Target Area













Prov.	Strategic Disaster Resilient Port		Points in assessing the numerical result
lloilo	lloilo	Estancia	Relation to neighborir
Bohol	Tagbilaran	Tapal , Jagna Ubay, Tubigon	Prov. Investment cost Natural conditions
Leyte	Tacloban		Location Location (west/East)
Ме	asures	to be take	en in a
Pre-Disa Physica	aster Re ster Phase I Measures	to be take esilient Por	d Post Disaster Phase
Pre-Disa Physica - Disaste maste - Constr	ster Phase I Measures er resilient port r planning ruction of er resilient port	- Temporary strengthening for approaching typho - Installation of faciliti for emergency operation as	d Post Disaster Phase -Procurement of facilities for provisior use of damaged
Pre-Disa Physica - Disaste maste - Constr disaste	ster Phase I Measures r resilient port r planning ruction of er resilient port es	- Temporary strengthening for approaching typho - Installation of faciliti for emergency	 Post Disaster Phase Procurement of facilities for provision use of damaged facilities - Rehabilitation of





Appendices

Financial Resources

	Government-	Local Government-	GOCC-owned
	owned facilities	owned facilities	facilities
Disaster resilient port facility construction	NDRRMF, GAA	LDRRMF, LGU's Budget, DMAF	GOCC's fund, NDRRMF
Reinforcement for	QRF, NDRRMF	LDRRMF, LGU's	GOCC's fund,
Provisional Use		Budget, DMAF	NDRRMF
Rehabilitation of Damaged Facilities	QRF, NDRRMF, GAA	LDRRMF, LGU's Budget, DMAF	GOCC's fund, NDRRMF

Note:

1) Donor fund may be applied according to donor's policy

2) Budgets for disaster resilient port master planning and operational cost which is necessary for disaster management shall be required. The fund in the table can be applied to the budget

3) DOTC or PPA may financially support to LGUs in case of serious damages as necessary

Rehabilitation of Port Facilities

Rehabilitation of facilities damaged by Yolanda (DOTC)

Port	Amount (P)	Fund
21 ports 32 spots	329,600,000.00	Government Fund
15 ports 22 spots	248,600,000.00	QRF 2014
6 ports 10 spots	81,000,000.00	RRF


Rehabilitation of facilities damaged by Bohol Earthquake (PPA)

the set that a set of the set of
635,602.70 PPA Corporate func
1


REF: Budget for port in GAA (2015 in Peso)

Ports, Lighthouses and Harbor


(CI	. budger for pointin GA	udger for poir in GAA (2013 in Peso			Harbors		
DC	DTC	45,945,422,000	Year	Budget	Numbe		
1	Program	6,541,184,000			of Spot		
1	Project	39,404,238,000	2012 (12)	502,000	8		
	Foreign assisted Project(s)	10,516, 754,000	2013 112)	217,500			
	Locally-Funded Project(s)	28,887,484,,000	2014 112)	1.079.500	4		
	Non Road Transportation	20,573,070,000	2015 2)	1,631,453			
	Ports, Lighthouses and Harbors	1,631,453,000	2013 2016 ^{2]*}	1,031,500			
Se	burce: GAA 2015		* Proposal an Source:1) We	nount bsite of DOTC ,	2) WTPD		





4) Tentative Draft for Discussion on Standard Design Models of Disaster Resilient Port Facilities























```
Appendices
```



Appendices

END OF PRESENTATION

THANK YOU FOR YOUR ATTENTION