

添付 5

ムンバイ市跨線橋架替えプロジェクト説明資料

Data Collection Survey on Road/Railway Bridge Sector

Explanatory Material of Reconstruction Project of ROBs in Mumbai

**August 2016
Mumbai**

**JAPAN INTERNATIONAL COOPERATION AGENCY
Oriental Consultants Global Co., Ltd.**

1

Contents

- I. Introduction**
- II. Results of Site Inspection**
- III. Proposal for Reconstruction**
- IV. Study for Next Step**
- V. Application of High-Elasticity CFRP**
- VI. Schedule**

2

I . Introduction

ORIENTAL CONSULTANTS GLOBAL CO., LTD.

**Based on discussion with Western Railway, MOR,
Reconstruction of several Railway Bridges
were requested.**



Interim Study Result is presented by this meeting.

3

II . Results of Site Inspection

ORIENTAL CONSULTANTS GLOBAL CO., LTD.

1. List of Target Damaged Bridges


Type of Bridge	Location	Number (18 Bri.)	Bridge Name
ROB	Mumbai	7	(1) Ferere ROB (No. 1) (2) Belasis ROB (No. 2) (3) Mahalaxmi ROB (No. 3) (4) Delise ROB (No. 4) (5) Tilak ROB (No. 5) (6) Mahim ROB (No. 6) (7) Goregaon ROB (No. 7)
	Vadodara	2	(8) LC No. 5/A (No. 8) (9) LC No. 2/X (No. 9)
Railway Bridge	Mumbai	4	(1)No.73 (Vasai Creek) (2)No.75(Vasai Creek) (3)No.92 (Vasai Creek) (4)No.93 (Vasai Creek)
	Ratlam	5	(5) No. 114 (6) No. 129 (7) No. 132 (8) No. R5 (9) No. R8

4

II . Results of Site Inspection

ORIENTAL CONSULTANTS GLOBAL CO., LTD.

2. Location of Target Damaged Bridges




5

II . Results of Site Inspection

ORIENTAL CONSULTANTS GLOBAL CO., LTD.

2. Location of Target Damaged Bridges




6

II . Results of Site Inspection

ORIENTAL CONSULTANTS GLOBAL CO., LTD.

2. Location of Target Damaged Bridges




7

II . Results of Site Inspection

ORIENTAL CONSULTANTS GLOBAL CO., LTD.

3. Summary of Inspection Results (ROB)

No.	Bridge Name	Length [m]	Span No.	Const. Year	Superstructure Type	Comments/ Next Step
Road over Bridge (ROB)						
1	Ferere ROB	25.36	1	1921	2 Main Steel I-Girder with cross girders	Most of bridges were constructed nearly 100 years ago ↓ <u>Reconstruction</u>
2	Balasis ROB	31.50	5	1893	Steel I-Girder	
3	Mahalaxmi ROB	77.00	5	1920	Steel I-Girder	
4	Delise ROB	63.20	3	1921	2 Main Steel I-Girder with cross girders	
5	Tilak ROB	226.20	3	1925	2 Main Steel I-Girder with cross girders	
6	Mahim ROB	80.00	3	1993	PC I-Shaped Girder	
7	Goregaon ROB	79.00	2	1993	PC I-Shaped Girder	
8	LC No. 5/A	85.00	2	2012	PC Box Girder	<u>Non-Destructive Survey</u>
9	LC No. 2/A	35.08	1	2008	PC Box Girder	



9 ROB's are selected for next step

8

II . Results of Site Inspection

ORIENTAL CONSULTANTS GLOBAL CO., LTD.

3. Summary of Inspection Results (Railway Bridge)


No.	Bridge Name	Length [m]	Span No.	Const. Year	Superstructure Type	Comments/ Next Step
Railway Bridge						
1	No. 73	1,450	29	1993	PC Box Girder	NO Next step Because of minor damage
2	No. 75	550	11	1993	PC Box Girder	
3	No. 92	380	20	1963	Steel I-Girder	
4	No. 93	410	22	1963	Steel I-Girder	
5	No. 114	80	4	1960	PC I-Shaped Girder	NO Next step Because, repaired by CFRP already
6	No. 129	60	3	1960	PC I-Shaped Girder	
7	No. 132	20	1	1960	PC I-Shaped Girder	
8	No. R5	20	1	1960	PC I-Shaped Girder	
9	No. R8	20	1	1960	PC I-Shaped Girder	

9

III . Proposal for Reconstruction

ORIENTAL CONSULTANTS GLOBAL CO., LTD.

1. Feature of this Project



10

III. Proposal for Reconstruction

2. Advanced Technology can be Adopted

Construction

- ✓ To reduce the Height of Road Surface
- ✓ To make thin the Girder Height


Applicable Superstructure Type

- ① Bi-Prestressing PC System
- ② Pre-flexed PC Beam
- ③ Composite Floor Slab
- ④ Steel I Girder with Steel Deck Plate
- ⑤ Pony Truss

III. Proposal for Reconstruction

2. Advanced Technology can be Adopted

Type of Superstructure



III. Proposal for Reconstruction

ORIENTAL CONSULTANTS GLOBAL CO., LTD.


2. Advanced Technology to be Adopted

Type of Superstructure

① Bi-Prestressing PC System

This construction method is to combine a conventional prestressed method (give compressive force to concrete by pulling PC Strand) with a Post-compression method (give tension force to concrete by pushing PC strand). It is possible to reduce girder height and extend span length.

◆ Ratio of Span Length and Girder Height
= approx. 1/32



13


III. Proposal for Reconstruction

ORIENTAL CONSULTANTS GLOBAL CO., LTD.

2. Advanced Technology to be Adopted

Type of Superstructure

② Pre-flexed PC Beam




This is composite girder of steel girder and concrete.

Steel girder is added pre-flexion in advance by vertical force and introduce pre-stress by release after casting concrete at lower flange.

It is possible to construct under very low girder height compared to other method.

◆ Ratio of Span Length and Girder Height
= Approx. 1/35



14

Ⅲ. Proposal for Reconstruction

ORIENTAL CONSULTANTS GLOBAL CO., LTD.

2. Advanced Technology to be Adopted


Type of Superstructure

③ Composite Floor Slab

Main girder is simple structure that comprises of T-shape steel, bottom plate and filling concrete as main cross section.

To suppress an increase in girder height by using T-shaped steel with projections as shear key.

- ◆ Ratio of Span Length and Girder Height = Approx. 1/30 ~ 1/42 (extremely thin structure)



15

Ⅲ. Proposal for Reconstruction

ORIENTAL CONSULTANTS GLOBAL CO., LTD.

2. Advanced Technology to be Adopted

Type of Superstructure

④ Steel I Girder with Steel Deck Plate

It is possible to reduce the self weight of deck slab by using steel deck plate to Steel I girder. And longitudinal reinforcing member is installed at steel deck plate. Steel deck plate bears the role as a upper flange of main girder reinforced with reinforcing member, therefore the girder height is suppressed.



- ◆ Ratio of Span Length and Girder Height = Approx. 1/30

16


Ⅲ. Proposal for Reconstruction

ORIENTAL CONSULTANTS GLOBAL CO., LTD.

2. Advanced Technology to be Adopted

Type of Superstructure

⑤ Pony Truss



This method is to reduce a structure height under road by applying pony truss type.

Only reinforcing member is installed under deck slab, therefore, regardless of span length, structure height under road is about 1m.

◆ Ratio of Span Length and Girder Height = Approx. over 75m

17

Ⅲ. Proposal for Reconstruction

ORIENTAL CONSULTANTS GLOBAL CO., LTD.

2. Advanced Technology can be Adopted

Construction

- ✓ To reduce the space
- ✓ To save the time

Applicable Foundation Type

- ① Cast-in-place Concrete Pile under low clearance
- ② Rotary Penetration Steel Pile
- ③ Steel Pipe Socket Connection Method

18


Ⅲ. Proposal for Reconstruction

ORIENTAL CONSULTANTS GLOBAL CO., LTD.

2. Advanced Technology to be Adopted

Applicable Foundation Type

① Cast-in-place Concrete Pile under low clearance



This technique employs turntable type for driving system of excavation rod. It is possible to construct at the height under 2m by combining a special type of kelly rod.

Construction of Cast-in-situ pile under low clearance (under existing bridge) becomes possible used by this special type of equipment.

19


Ⅲ. Proposal for Reconstruction

ORIENTAL CONSULTANTS GLOBAL CO., LTD.

2. Advanced Technology to be Adopted

Applicable Foundation Type

② Rotary Penetration Steel Pile



It is Steel Pipe Foundation which is welded a spiral processed steel plate (Wing) to the tip of steel pipe together. The pile penetrates/screws into the ground with propulsion of wing.

It is obtained large bearing force by the base enlarging effect of Wing. And, due to penetration method, there is no excavated soil at site. Therefore, it will be possible to be eco-friendly construction with non-emission, low-vibration and reducing pile number.

20


III. Proposal for Reconstruction

ORIENTAL CONSULTANTS GLOBAL CO., LTD.

2. Advanced Technology to be Adopted

Applicable Foundation Type

③ Steel Pipe Socket Connection Method



Connection part at tip of pier column



Construction of Caisson Structure

Steel Pipe Socket Connection Method is the jointing technique of inserting a Steel Column into Steel Pipe Socket which is constructed at the top of foundation, and filling up a concrete inside the gap of it. It is possible to reduce construction period by omitting Pile Cap and Anchor Frame used in conventional method.

21


III. Proposal for Reconstruction

ORIENTAL CONSULTANTS GLOBAL CO., LTD.

3. Construction Process

3.1 Type of Existing Superstructure


A 2-Main Girder Type



※ Impossible for Step Construction ⇒ Quick Construction is Required

1. Ferere ROB
4. Delise ROB
5. Tilak ROB

B Conventional I/T-Girder Type



※ Possible for Step Construction

2. Balasis ROB
3. Mahalaxmi ROB
6. Mahim ROB
7. Goregaon ROB

22

III. Proposal for Reconstruction


ORIENTAL CONSULTANTS GLOBAL CO., LTD.

3. Construction Process

3.2 Proposal for Construction Steps for (A)

Step-1


Install Cofferdam and Temporary Bridge and Construction of Abutment. (Secure existents traffic)



Construction Period: 2 – 3 months

Step-2

Demolition of Deck Slab. (Close existing traffic)



23

III. Proposal for Reconstruction


ORIENTAL CONSULTANTS GLOBAL CO., LTD.

3. Construction Process

3.2 Proposal for Construction Steps for (A)


Step-3

Removal of Steel Girder. (Close existing traffic)



Step-4

Construction New Superstructure. (Close existing traffic)



24

III. Proposal for Reconstruction



ORIENTAL CONSULTANTS GLOBAL CO., LTD.

3. Construction Process

3.3 Proposal for Construction Steps for (B)

Step-1


Removal of HALF of Superstructure (Secure existing traffic, but by limited width)



Construction Period: 1 week

Step-2

Demolition of HALF of existing Abutment and Construction of HALF of New Abutment. (secure existing traffic but by limited width)



Construction Period: 2 – 3 months

25

III. Proposal for Reconstruction



ORIENTAL CONSULTANTS GLOBAL CO., LTD.

3. Construction Process

3.3 Proposal for Construction Steps for (B)

Step-3



Erection of HALF of New Superstructure. (Secure existing traffic, but by limited width)



Construction Period: 3 days

Step-4

Removal of remained Superstructure. (Secure existing traffic at New Superstructure part)



Construction Period: 10 days

26

III. Proposal for Reconstruction


ORIENTAL CONSULTANTS GLOBAL CO., LTD.

3. Construction Process

3.3 Proposal for Construction Steps for **B**

Step-5

Demolition of Remained of existing Abutment and construction of HALF of New Abutment. (Secure existing traffic but by limited width)




Demolition and Construction

Construction Period: 1 week

Step-6

Erection of Remained of New Superstructure. (Secure existing traffic, but by limited width)



New Superstructure

Construction Period: 2 – 3 months




27

III. Proposal for Reconstruction

ORIENTAL CONSULTANTS GLOBAL CO., LTD.

3. Construction Process

3.4 Comparison of Bridge Type

	Plan - 1 Bi - Prestressing PC Beam	Plan - 2 Pre-fixed PC Beam	Plan - 3 Composite Floor Slab
Side View & Cross Section			
Cost (Super Structure)	1.17	1.06	1.03
Comment	<ul style="list-style-type: none"> • Transversal Prestressing is necessary, Step Construction is difficult. (Moderate) • Maintenance for re-coating is unnecessary. (Good) • Due to requirement of high-strength concrete, fabrication shall be done at specialized factory (Bad). 	<ul style="list-style-type: none"> • Step Construction is possible. (Good) • Maintenance for re-coating is unnecessary. (Good) • Easy for erection of girder, however, construction of cross beam and deck slab shall be done at site (Moderate). 	<ul style="list-style-type: none"> • Step Construction is possible. (Good) • Re-coating is necessary only for Lower Deck Slab. (Moderate), but, by applying of weathering Steel, no maintenance work is required (Good) • Due to all fabricate in Factory, easy for erection at site (Good)



28

III. Proposal for Reconstruction

ORIENTAL CONSULTANTS GLOBAL CO., LTD.

3. Construction Process

3.4 Comparison of Bridge Type

	Plan - 4 Steel I Girder with Steel Deck Plate	Plan - 5 Pony Truss
Side View & Cross Section		
Cost (Super Structure)	1.22	1.00
Comment	<ul style="list-style-type: none"> ▪ Step Construction is possible. (Good) ▪ Re-coating is necessary for Main Girder and lower face of deck slab. (Moderate), but, by applying of weathering Steel, no maintenance work is required (Good) ▪ Due to all fabricate in Factory, easy for erection at site (Good) 	<ul style="list-style-type: none"> ▪ Step Construction is impossible. (Bad) ▪ Re-coating is necessary for Truss structure. (Moderate) , but, by applying of weathering Steel, no maintenance work is required (Good) ▪ Due to large number of members, period of work at site will be longer than other types. (Bad)

29

III. Proposal for Reconstruction

ORIENTAL CONSULTANTS GLOBAL CO., LTD.

3. Construction Process

3.5 Recommendation

◆ For Bridge Type **(A)**

Due to an economic advantage and easy work at site is preferable for type A, because short construction period at site is required.

⇒ **Plan-3 (Composite Floor Slab) are preferable.**

◆ For Bridge Type **(B)**

Due to an economic advantage and requirement of Step Construction for type B,

⇒ **Plan-3 (Composite Floor Slab) are preferable.**


30

III. Proposal for Reconstruction


ORIENTAL CONSULTANTS GLOBAL CO., LTD.

4. Case Study

4.1 For Type (A)



- 2. Ferere ROB
- 4. Delise ROB
- 5. Tilak ROB




31

III. Proposal for Reconstruction


ORIENTAL CONSULTANTS GLOBAL CO., LTD.

4. Case Study

4.2 For Type (B)



- 2. Balasis ROB
- 3. Mahalaxmi ROB
- 6. Mahim ROB
- 7. Goregaon ROB



32

III. Results of Site Inspection

ORIENTAL CONSULTANTS GLOBAL CO., LTD.

5. Summary of Study Result

No.	Bridge Name	Proposed Plan					
		Length [m]	Width [m]	Span No.	Superstructure Type	Construction Method	Cost Estimation (Approx.)
Road over Bridge (ROB)							
1	Ferere ROB	36.00	19.50	1	Composite Floor Slab	One Time Construction	Rs. 260 million
2	Balasis ROB	31.50	19.50	5	Composite Floor Slab	Step Construction	Rs. 230 million
3	Mahalaxmi ROB	77.00	25.00	5	Composite Floor Slab	Step Construction	Rs. 700 million
4	Delise ROB	100.20	24.80	1	Composite Floor Slab	One Time Construction	Rs. 900 million
5	Tilak ROB	236.00	20.00	3	Composite Floor Slab	One Time Construction	Rs. 1,700 million
6	Mahim ROB	80.00	28.30	3	Composite Floor Slab	Step Construction	Rs. 820 million
7	Goregaon ROB	79.00	27.50	2	Composite Floor Slab	Step Construction	Rs. 900 million

33

IV. Study for Next Step

ORIENTAL CONSULTANTS GLOBAL CO., LTD.

2. Non-Destructive Survey

Target Bridges for Non-Destructive Survey		
Type of Bridge	Location	Bridge Name
ROB (Concrete)	Mumbai	Mahim ROB (No.6)
	Vadodara	LC No. 5/A (No.8)
		LC No.2/X (No.9)

Concrete Member



Schmidt Hammer



Electromagnetic Wave Radar



34

V. Application of High-Elasticity CFRP

ORIENTAL CONSULTANTS GLOBAL CO., LTD.

Recently, High-module CFRP is used in JAPAN.

Advantage of High-module CFRP



Can reduce number of sheet

2 Num. (230 kN/mm²)



1 Num. (640 kN/mm²)

Specification of Replakr

Elasticity

品名(品番)	目付量 (g/m ²)	厚み (mm)	引張強度 (N/mm ²)	引張弾性率 (kN/mm ²)	含浸接着樹脂の標準使用量	
リペラーク® 高強度グレード (1方向)	20タイプ (MRK-M2-20)	200	0.111	3,400	230 (245)	0.6kg/m ²
	30タイプ (MRK-M2-30)	300	0.167	3,400	230 (245)	0.8kg/m ²
	40タイプ (MRK-M2-40)	400	0.222	3,400	230 (245)	1.0kg/m ²
	45タイプ (MRK-M2-45)	450	0.250	3,400	230 (245)	1.1kg/m ²
	60タイプ (MRK-M2-60)	600	0.333	3,400	230 (245)	1.2kg/m ²
リペラーク® 中弾性グレード (1方向)	MMタイプ (MRK-M4-30)	300	0.165	2,900	390	0.8kg/m ²
	MM2タイプ (MRK-M5-30)	300	0.163	2,400	440	0.8kg/m ²
リペラーク® 高弾性グレード (1方向)	HMタイプ (MRK-M6-30)	300	0.143	1,900	640	0.8kg/m ²
	HM40タイプ (MRK-M6-40)	400	0.190	1,900	640	1.0kg/m ²
	HM45タイプ (MRK-M6-45)	450	0.214	1,900	640	1.1kg/m ²
	HM60タイプ (MRK-M6-60)	600	0.286	1,900	640	1.4kg/m ²
リペラーク® (2方向)	2方向 20タイプ (MRK-2D2-20)	200 (縦100/横100)	0.0556/0.0556	2,900	230	0.6kg/m ²

High-module Type

More Economical and Easy for installation.

35

VI. Schedule

ORIENTAL CONSULTANTS GLOBAL CO., LTD.

1. Major Work Items and Schedule

Deliverables	Submission Date
Inception Report	Done April, 2016
Interim Report	Done July, 2016
Draft Final Report	Beginning of October, 2016
Final Report	End of November, 2016

36

THANK YOU



Oriental Consultants Global Co., Ltd.

添付 6

西部鉄道における損傷橋梁調査シート

Bridge Survey Record (1/6)

Date & Time: 07 Jun,2016 12:30

Bridge No.	Ser.No.1	Division	Mumbai
Bridge Name	Ferere ROB	Year of Construction	1921
GPS Data	N 18 ° 57 ' 43"	Station	Grant Road Station
	E 72 ° 48 ' 55 "		-

Bridge Length	25.36m	Span Arrangement	Number 1
Bridge Width	19.50m	Type of Substructure	Stone Masonry Abutment
Type of Superstructure	2 Main Steel I-Girder with cross girders		

Overview of the Bridge

Side View



Up View



Bridge Survey Record (2/6) Right Side

Date & Time: 07 Jun,2016 12:30

Bridge No.	Ser.No.1	Station	Grant Road Station
Bridge Name	Ferere ROB		-
Photoes			

Photo R1



Photo R2



Photo R5



Photo R8



Photo R10



Photo R



Bridge Survey Record (3/6) Left Side

Date & Time: 07 Jun,2016 12:30

Bridge No.	Ser.No.1	Station	Mumbai
Bridge Name	Ferere ROB		1921
Photoes			



Bridge Survey Record (4/6)

Date & Time: 07 Jun,2016 12:30

Bridge No.	Ser.No.1	Division	Mumbai
Bridge Name	Ferere ROB	Year of Construction	1921
GPS Data	N 18 °57 ' 43"	Station	Grant Road Station
	E 72°48 ' 55 "		-

General Description of Damages

Member	Kind of the Damage
	Ex. Concrete : Cracking, Spalling, etc. Steel : Cracking, Rusting, Fracture, etc.
1. Superstructure	
(1) Concrete Member	N/A
- Girder	
- Cross Beam	
- Slab	
(2) Steel Member	
- Girder	Rusting (slightly)
- Vertical Girder (stringer)	N/A
- Cross Beam	Rusting (slightly)
- Sway Bracing	N/A
(3) Bearing Shoe	No Check
(4) Drainage Pipe	N/A
(5) Others	-
2. Substructure	
- Pier	N/A
- Abutment	Good
- Wing Wall	N/A
- Approach Road Condition	Good
- Obstruction	-
- Scouring	N/A
4.Evaluation	

Bridge Survey Record (5/6)

Date & Time: 07 Jun,2016 12:30

Bridge No.	Ser.No.1	Division	Mumbai
Bridge Name	Ferere ROB	Year of Construction	1921
GPS Data	N 18 °57 ' 43"	Station	Grant Road Station
	E 72°48 ' 55 "		-

Detailed Description of Damages

Object Member	
Kind of Damage	Good Condition
Sketch or Photo	



Bridge Survey Record (6/6)

Date & Time: 07 Jun,2016 12:30

Bridge No.	Ser.No.1	Location (State)	Mumbai
Bridge Name	Ferere ROB	Year of Construction	1921
GPS Data	N 18 °57 ' 43"	Station	Grant Road Station
	E 72°48 ' 55 "		-

Evaluation index

1	Cosistency with the upper plan, verification og Indian Railway priority bridges	Yes No
2	Application of Japanese advanced technology	See below
3	Confirmation of other projects by Japanese ODA	Yes No
4	Confirmation of other donor's projects and local project	Yes No
5	Impact on the surrounding society and economy	Much Less
6	Access to the bridge sites	Good Not Good
7	Collecting information from japanese companies, and estimation of project effects	See below

2 Application of Japanese advanced technology



7 Collecting information from japanese companies, and estimation of project effects

Bridge Survey Record (1/6)

Date & Time: 07 Jun,2016 12:00

Bridge No.	Ser.No.2	Division	Mumbai
Bridge Name	Belasis ROB	Year of Construction	1893
GPS Data	N 18 ° 58 ' 08"	Station	Mumbai central
	E 72° 49 ' 06 "		-

Bridge Length	31.50m	Span Arrangement	Number 5
Bridge Width	19.50m	Type of Substructure	Stone Masonry Abutment and Steel Pier Column
Type of Superstructure	Steel I-Girder (15 girders)		

Overview of the Bridge	Side View
	
Up View	
	

Bridge Survey Record (2/6) Right Side

Date & Time: 07 Jun,2016 12:00

Bridge No.	Ser.No.2	Station	Mumbai central
Bridge Name	Belasis ROB		-
Photoes			

Photo R1



Photo R2



Photo R4



Photo R5



Photo R8



Photo R9



Bridge Survey Record (3/6) Left Side

Date & Time: 07 Jun,2016 12:00

Bridge No.	Ser.No.2	Station	Mumbai
Bridge Name	Belasis ROB		1893
Photoes			



Bridge Survey Record (4/6)

Date & Time: 07 Jun,2016 12:00

Bridge No.	Ser.No.2	Division	Mumbai
Bridge Name	Belasis ROB	Year of Construction	1893
GPS Data	N 18 °58 ' 08"	Station	Mumbai central
	E 72°49 ' 06 "		-

General Description of Damages





Member	Kind of the Damage
	Ex. Concrete : Cracking, Spalling, etc. Steel : Cracking, Rusting, Fracture, etc.
1. Superstructure	
(1) Concrete Member	N/A
- Girder	
- Cross Beam	
- Slab	
(2) Steel Member	
- Girder	Rusting (slightly)
- Vertical Girder (stringer)	N/A
- Cross Beam	Rusting (slightly)
- Sway Bracing	N/A
(3) Bearing Shoe	No Check
(4) Drainage Pipe	N/A
(5) Others	-
2. Substructure	
- Pier	Good
- Abutment	Good
- Wing Wall	N/A
3. Miscellaneous	
- Approach Road Condition	Good
- Obstruction	-
- Scouring	N/A
4. Evaluation	

Bridge Survey Record (5/6)

Date & Time: 07 Jun,2016 12:00

Bridge No.	Ser.No.2	Division	Mumbai
Bridge Name	Belasis ROB	Year of Construction	1893
GPS Data	N 18 °58 ' 08"	Station	Mumbai central
	E 72°49 ' 06 "		-

Detailed Description of Damages

Object Member	Steel I-Girder
Kind of Damage	Rusting
Sketch or Photo	<div style="display: flex; justify-content: space-around;">   </div> <div style="display: flex; justify-content: space-around; margin-top: 20px;">   </div>

Bridge Survey Record (6/6)

Date & Time: 07 Jun,2016 12:00

Bridge No.	Ser.No.2	Location (State)	Mumbai
Bridge Name	Belasis ROB	Year of Construction	1893
GPS Data	N 18 °58 ' 08"	Station	Mumbai central
	E 72°49 ' 06 "		-

Evaluation index

1	Cosistency with the upper plan, verification og Indian Railway priority bridges	Yes	No
2	Application of Japanese advanced technology	See below	
3	Confirmation of other projects by Japanese ODA	Yes	No
4	Confirmation of other donor's projects and local project	Yes	No
5	Impact on the surrounding society and economy	Much	Less
6	Access to the bridge sites	Good	Not Good
7	Collecting information from japanese companies, and estimation of project effects	See below	

2 Application of Japanese advanced technology

7 Collecting information from japanese companies, and estimation of project effects

Bridge Survey Record (1/6)

Date & Time: 07 Jun,2016 12:00

Bridge No.	Ser.No.3	Division	Mumbai
Bridge Name	Mahalaxmi ROB	Year of Construction	1920
GPS Data	N 18 ° 58 ' 56"	Station	Mahalaxmi
	E 72 ° 49 ' 27 "		-

Bridge Length	77.00m	Span Arrangement	Number 5
Bridge Width	25.00m		
Type of Superstructu	Steel I-Girder (15 girders)	Type of Substructure	Stone Masonry Abutment and Steel Pier Column

Overview of the Bridge

Side View



Up View



Bridge Survey Record (2/6) Right Side

Date & Time: 07 Jun,2016 12:00

Bridge No.	Ser.No.3	Station	Mahalaxmi
Bridge Name	Mahalaxmi ROB		-
Photoes			
Photo R2		Photo R3	
Photo R5		Photo R6	
Photo R7		Photo R10	

Bridge Survey Record (3/6) Left Side

Date & Time: 07 Jun,2016 12:00

Bridge No.	Ser.No.3	Station	Mumbai
Bridge Name	Mahalaxmi ROB		1920
Photos			
Photo L5			
Photo L6			
Photo L			
Photo L			
Photo L			
Photo L			

Bridge Survey Record (4/6)

Date & Time: 07 Jun,2016 12:00

Bridge No.	Ser.No.3	Division	Mumbai
Bridge Name	Mahalaxmi ROB	Year of Construction	1920
GPS Data	N 18 °58 ' 56"	Station	Mahalaxmi
	E 72°49 ' 27 "		-

General Description of Damages

Member	Kind of the Damage
	Ex. Concrete : Cracking, Spalling, etc. Steel : Cracking, Rusting, Fracture, etc.
1. Superstructure	
(1) Concrete Member	N/A
- Girder	
- Cross Beam	
- Slab	
(2) Steel Member	
- Girder	Rusting
- Vertical Girder (stringer)	N/A
- Cross Beam	Rusting
- Sway Bracing	N/A
(3) Bearing Shoe	No Check
(4) Drainage Pipe	N/A
(5) Others	-
2. Substructure	
- Pier	Good
- Abutment	Good
- Wing Wall	N/A
3. Miscellaneous	
- Approach Road Condition	Good
- Obstruction	-
- Scouring	N/A
4. Evaluation	

Bridge Survey Record (5/6)

Date & Time: 07 Jun,2016 12:00

Bridge No.	Ser.No.3	Division	Mumbai
Bridge Name	Mahalaxmi ROB	Year of Construction	1920
GPS Data	N 18 °58 ' 56"	Station	Mahalaxmi
	E 72°49 ' 27 "		-

Detailed Description of Damages

Object Member	
Kind of Damage	Good Condition
Sketch or Photo	



Bridge Survey Record (6/6)

Date & Time: 07 Jun,2016 12:00

Bridge No.	Ser.No.3	Location (State)	Mumbai
Bridge Name	Mahalaxmi ROB	Year of Construction	1920
GPS Data	N 18 °58 ' 56"	Station	Mahalaxmi
	E 72°49 ' 27 "		-

Evaluation index

1	Cosistency with the upper plan, verification og Indian Railway priority bridges	Yes No
2	Application of Japanese advanced technology	See below
3	Confirmation of other projects by Japanese ODA	Yes No
4	Confirmation of other donor's projects and local project	Yes No
5	Impact on the surrounding society and economy	Much Less
6	Access to the bridge sites	Good Not Good
7	Collecting information from japanese companies, and estimation of project effects	See below

2 Application of Japanese advanced technology

7 Collecting information from japanese companies, and estimation of project effects

Bridge Survey Record (1/6)

Date & Time: 07 Jun,2016 11:00

Bridge No.	Ser.No.4	Division	Mumbai
Bridge Name	Delise ROB	Year of Construction	1921
GPS Data	N 18 ° 59 ' 51"	Station	Lower Parel
	E 72 ° 49 ' 53 "		-

Bridge Length	63.20m	Span Arrangement	Number 3
Bridge Width	24.80m	Type of Substructure	Stone Masonry Abutment and Steel Pier Column
Type of Superstructure	2 Main Steel I-Girder with cross girders		

Overview of the Bridge

Side View



Up View



Bridge Survey Record (2/6) Right Side

Date & Time: 07 Jun,2016 11:00

Bridge No.	Ser.No.4	Station	Lower Parel
Bridge Name	Delise ROB		-
Photoes			
Photo R5			
Photo R5			
Photo R6			
Photo R			
Photo R			
Photo R			

Bridge Survey Record (3/6) Left Side

Date & Time: 07 Jun,2016 11:00

Bridge No.	Ser.No.4	Station	Mumbai
Bridge Name	Delise ROB		1921
Photos			

Photo L2



Photo L3



Photo L5



Photo L6



Photo 8



Photo L10



Bridge Survey Record (4/6)

Date & Time: 07 Jun,2016 11:00

Bridge No.	Ser.No.4	Division	Mumbai
Bridge Name	Delise ROB	Year of Construction	1921
GPS Data	N 18 °59 ' 51"	Station	Lower Parel
	E 72°49 ' 53 "		-

General Description of Damages

Member	Kind of the Damage
	Ex. Concrete : Cracking, Spalling, etc. Steel : Cracking, Rusting, Fracture, etc.
1. Superstructure	
(1) Concrete Member	
- Girder	N/A
- Cross Beam	N/A
- Slab	Crecking and Spalling
(2) Steel Member	
- Girder	Rusting
- Vertical Girder (stringer)	N/A
- Cross Beam	Rusting
- Sway Bracing	N/A
(3) Bearing Shoe	No Check
(4) Drainage Pipe	N/A
(5) Others	-
2. Substructure	
- Pier	Good
- Abutment	Stone Masonary
- Wing Wall	N/A
3. Miscellaneous	
- Approach Road Condition	Good
- Obstruction	-
- Scouring	N/A
4.Evaluation	

Bridge Survey Record (5/6)

Date & Time: 07 Jun,2016 11:00

Bridge No.	Ser.No.4	Division	Mumbai
Bridge Name	Delise ROB	Year of Construction	1921
GPS Data	N 18 °59 ' 51"	Station	Lower Parel
	E 72°49 ' 53 "		-

Detailed Description of Damages

Object Member	RC Slub
Kind of Damage	Spalling and exposed Rebar
Sketch or Photo	




Bridge Survey Record (5/6)

Date & Time: 07 Jun,2016 11:00

Bridge No.	Ser.No.4	Division	Mumbai
Bridge Name	Delise ROB	Year of Construction	1921
GPS Data	N 18 °59 ' 51"	Station	Lower Parel
	E 72°49 ' 53 "		-

Detailed Description of Damages

Object Member	Concrete Base
Kind of Damage	Cracking and spalling
Sketch or Photo	



Bridge Survey Record (5/6)

Date & Time: 07 Jun,2016 11:00

Bridge No.	Ser.No.4	Division	Mumbai
Bridge Name	Delise ROB	Year of Construction	1921
GPS Data	N 18 °59 ' 51"	Station	Lower Parel
	E 72°49 ' 53 "		-

Detailed Description of Damages

Object Member	Cross Bream
Kind of Damage	Runsting
Sketch or Photo	



Bridge Survey Record (6/6)

Date & Time: 07 Jun,2016 11:00

Bridge No.	Ser.No.4	Location (State)	Mumbai
Bridge Name	Delise ROB	Year of Construction	1921
GPS Data	N 18 °59 ' 51"	Station	Lower Parel
	E 72°49 ' 53 "		-

Evaluation index

1	Cosistency with the upper plan, verification og Indian Railway priority bridges	Yes	No
2	Application of Japanese advanced technology	See below	
3	Confirmation of other projects by Japanese ODA	Yes	No
4	Confirmation of other donor's projects and local project	Yes	No
5	Impact on the surrounding society and economy	Much	Less
6	Access to the bridge sites	Good	Not Good
7	Collecting information from japanese companies, and estimation of project effects	See below	

2 Application of Japanese advanced technology

7 Collecting information from japanese companies, and estimation of project effects

Bridge Survey Record (1/6)

Date & Time: 08 Jun,2016 10:30

Bridge No.	Ser.No.5	Division	Mumbai
Bridge Name	Tilak ROB	Year of Construction	1925
GPS Data	N 19° 01' 13"	Station	Dadar
	E 72° 50' 38"		-

Bridge Length	226.20m	Span Arrangement	Number 3
Bridge Width	20.00m	Type of Substructure	Stone Masonry Abutment and Steel Pier Column
Type of Superstructure	2 Main Steel I-Girder with cross girders		

Overview of the Bridge

Side View



Up View



Bridge Survey Record (2/6) Right Side

Date & Time: 08 Jun,2016 10:30

Bridge No.	Ser.No.5	Station	Dadar
Bridge Name	Tilak ROB		-
Photoes			

Photo R2



Photo R6



Photo R4



Photo R7



Photo R8



Photo R9



Bridge Survey Record (3/6) Left Side

Date & Time: 08 Jun,2016 10:30

Bridge No.	Ser.No.5	Station	Mumbai
Bridge Name	Tilak ROB		1925
Photos			
Photo L3			
Photo L6			
Photo L8			
Photo L9			
Photo L			
Photo L			

Bridge Survey Record (4/6)

Date & Time: 08 Jun,2016 10:30

Bridge No.	Ser.No.5	Division	Mumbai
Bridge Name	Tilak ROB	Year of Construction	1925
GPS Data	N 19 °01 ' 13"	Station	Dadar
	E 72°50 ' 38 "		-

General Description of Damages

Member	Kind of the Damage
	Ex. Concrete : Cracking, Spalling, etc. Steel : Cracking, Rusting, Fracture, etc.
1. Superstructure	
(1) Concrete Member	N/A
- Girder	
- Cross Beam	
- Slab	
(2) Steel Member	Good
- Girder	
- Vertical Girder (stringer)	
- Cross Beam	
- Sway Bracing	
(3) Bearing Shoe	No check
(4) Drainage Pipe	No check
(5) Others	-
2. Substructure	
- Pier	N/A
- Abutment	Good
- Wing Wall	Good
3. Miscellaneous	
- Approach Road Condition	
- Obstruction	
- Scouring	N/A
4. Evaluation	



Bridge Survey Record (5/6)

Date & Time: 08 Jun,2016 10:30

Bridge No.	Ser.No.5	Division	Mumbai
Bridge Name	Tilak ROB	Year of Construction	1925
GPS Data	N 19 °01 ' 13"	Station	Dadar
	E 72°50 ' 38 "		-

Detailed Description of Damages

Object Member	
Kind of Damage	Good Condition
Sketch or Photo	



Bridge Survey Record (6/6)

Date & Time: 08 Jun,2016 10:30

Bridge No.	Ser.No.5	Location (State)	Mumbai
Bridge Name	Tilak ROB	Year of Construction	1925
GPS Data	N 19 °01 ' 13"	Station	Dadar
	E 72°50 ' 38 "		-

Evaluation index

1	Cosistency with the upper plan, verification og Indian Railway priority bridges	Yes	No
2	Application of Japanese advanced technology	See below	
3	Confirmation of other projects by Japanese ODA	Yes	No
4	Confirmation of other donor's projects and local project	Yes	No
5	Impact on the surrounding society and economy	Much	Less
6	Access to the bridge sites	Good	Not Good
7	Collecting information from japanese companies, and estimation of project effects	See below	

2 Application of Japanese advanced technology

7 Collecting information from japanese companies, and estimation of project effects

Bridge Survey Record (1/6)

Date & Time: 08 Jun,2016 11:40

Bridge No.	Ser.No.6	Division	Mumbai
Bridge Name	Mahim ROB	Year of Construction	1993
GPS Data	N 19° 02' 41"	Station	Mahim Junction
	E 72° 50' 41"		-

Bridge Length	80.00m	Span Arrangement	Number 3
Bridge Width	28.30m	Type of Substructure	RC Abutment and RC Pier Column
Type of Superstructure	PC I-Shaped Girder		

Overview of the Bridge Side View



Up View



Bridge Survey Record (2/6) Right Side

Date & Time: 08 Jun,2016 11:40

Bridge No.	Ser.No.6	Station	Mahim Junction
Bridge Name	Mahim ROB		-
Photoes			

Photo R3



Photo R6



Photo R4



Photo R7



Photo R8



Photo R10



Bridge Survey Record (3/6) Left Side

Date & Time: 08 Jun,2016 11:40

Bridge No.	Ser.No.6	Station	Mumbai
Bridge Name	Mahim ROB		1993
Photos			
Photo L3	Photo L5		
Photo L7	Photo L9		
Photo L	Photo L		

Bridge Survey Record (4/6)

Date & Time: 08 Jun,2016 11:40

Bridge No.	Ser.No.6	Division	Mumbai
Bridge Name	Mahim ROB	Year of Construction	1993
GPS Data	N 19 °02 ' 41"	Station	Mahim Junction
	E 72°50 ' 41 "		-

General Description of Damages

Member	Kind of the Damage
	Ex. Concrete : Cracking, Spalling, etc. Steel : Cracking, Rusting, Fracture, etc.
1. Superstructure	
(1) Concrete Member	
- Girder	Spalling
- Cross Beam	Spalling
- Slab	Spalling
(2) Steel Member	N/A
- Girder	
- Vertical Girder (stringer)	
- Cross Beam	
- Sway Bracing	
(3) Bearing Shoe	No Check
(4) Drainage Pipe	None
(5) Others	
2. Substructure	
- Pier	Cracking and Spalling
- Abutment	Good
- Wing Wall	N/A
3. Miscellaneous	
- Approach Road Condition	
- Obstruction	
- Scouring	N/A
4. Evaluation	

Bridge Survey Record (5/6)

Date & Time: 08 Jun,2016 11:40

Bridge No.	Ser.No.6	Division	Mumbai
Bridge Name	Mahim ROB	Year of Construction	1993
GPS Data	N 19 °02 ' 41"	Station	Mahim Junction
	E 72°50 ' 41 "		-

Detailed Description of Damages

Object Member	PC I-Girder and RC slab
Kind of Damage	Spalling
Sketch or Photo	



Bridge Survey Record (5/6)

Date & Time: 08 Jun,2016 11:40

Bridge No.	Ser.No.6	Division	Mumbai
Bridge Name	Mahim ROB	Year of Construction	1993
GPS Data	N 19 °02 ' 41"	Station	Mahim Junction
	E 72°50 ' 41 "		-

Detailed Description of Damages

Object Member	PC cable
Kind of Damage	Fracture
Sketch or Photo	







Bridge Survey Record (5/6)

Date & Time: 08 Jun,2016 11:40

Bridge No.	Ser.No.6	Division	Mumbai
Bridge Name	Mahim ROB	Year of Construction	1993
GPS Data	N 19 °02 ' 41"	Station	Mahim Junction
	E 72°50 ' 41 "		-

Detailed Description of Damages

Object Member	RC Pier
Kind of Damage	Cracking and Spalling
Sketch or Photo	<div style="display: flex; flex-wrap: wrap; justify-content: space-around;"> <div style="width: 45%; text-align: center;">  </div> <div style="width: 45%; text-align: center;">  </div> <div style="width: 45%; text-align: center;">  </div> <div style="width: 45%; text-align: center;">  </div> </div>

Bridge Survey Record (6/6)

Date & Time: 08 Jun,2016 11:40

Bridge No.	Ser.No.6	Location (State)	Mumbai
Bridge Name	Mahim ROB	Year of Construction	1993
GPS Data	N 19 °02 ' 41"	Station	Mahim Junction
	E 72°50 ' 41 "		-

Evaluation index

1	Cosistency with the upper plan, verification og Indian Railway priority bridges	Yes No
2	Application of Japanese advanced technology	See below
3	Confirmation of other projects by Japanese ODA	Yes No
4	Confirmation of other donor's projects and local project	Yes No
5	Impact on the surrounding society and economy	Much Less
6	Access to the bridge sites	Good Not Good
7	Collecting information from japanese companies, and estimation of project effects	See below

2 Application of Japanese advanced technology

7 Collecting information from japanese companies, and estimation of project effects

Bridge Survey Record (1/6)

Date & Time: 08 Jun,2016 15:10

Bridge No.	Ser.No.7	Division	Mumbai
Bridge Name	Goregaon ROB	Year of Construction	1993
GPS Data	N 19 ° 10 ' 26"	Station	Goregaon
	E 72 ° 50 ' 56 "		Malad

Bridge Length	79.00m	Span Arrangement	Number 2
Bridge Width	27.50m	Type of Substructure	RC Abutment and RC Pier Column
Type of Superstructu	PC I-Shaped Girder		

Overview of the Bridge

Side View







Up View



Bridge Survey Record (2/6) Right Side

Date & Time: 08 Jun,2016 15:10

Bridge No.	Ser.No.7	Station	Goregaon
Bridge Name	Goregaon ROB		Malad
Photoes			
Photo R1	Photo R6		
			
Photo R8	Photo R9		
			
Photo R	Photo R		

Bridge Survey Record (3/6) Left Side

Date & Time: 08 Jun,2016 15:10

Bridge No.	Ser.No.7	Station	Mumbai
Bridge Name	Goregaon ROB		1993
Photos			
Photo L5			
Photo L7			
Photo L8			
Photo L			
Photo L			
Photo L			

Bridge Survey Record (4/6)

Date & Time: 08 Jun,2016 15:10

Bridge No.	Ser.No.7	Division	Mumbai
Bridge Name	Goregaon ROB	Year of Construction	1993
GPS Data	N 19 °10 ' 26"	Station	Goregaon
	E 72° 50 ' 56 "		Malad

General Description of Damages

Member	Kind of the Damage
	Ex. Concrete : Cracking, Spalling, etc. Steel : Cracking, Rusting, Fracture, etc.
1. Superstructure	
(1) Concrete Member	Good
- Girder	
- Cross Beam	
- Slab	
(2) Steel Member	N/A
- Girder	
- Vertical Girder (stringer)	
- Cross Beam	
- Sway Bracing	
(3) Bearing Shoe	No Check
(4) Drainage Pipe	N/A
(5) Others	
2. Substructure	
- Pier	Good
- Abutment	Good
- Wing Wall	N/A
3. Miscellaneous	
- Approach Road Condition	Bad
- Obstruction	
- Scouring	N/A
4. Evaluation	

Bridge Survey Record (5/6)

Date & Time: 08 Jun,2016 15:10

Bridge No.	Ser.No.7	Division	Mumbai
Bridge Name	Goregaon ROB	Year of Construction	1993
GPS Data	N 19 °10 ' 26"	Station	Goregaon
	E 72° 50 ' 56 "		Malad

Detailed Description of Damages

Object Member	
Kind of Damage	Good Condition
Sketch or Photo	



Bridge Survey Record (6/6)

Date & Time: 08 Jun,2016 15:10

Bridge No.	Ser.No.7	Location (State)	Mumbai
Bridge Name	Goregaon ROB	Year of Construction	1993
GPS Data	N 19 °10 ' 26"	Station	Goregaon
	E 72° 50 ' 56 "		Malad

Evaluation index

1	Cosistency with the upper plan, verification og Indian Railway priority bridges	Yes	No
2	Application of Japanese advanced technology	See below	
3	Confirmation of other projects by Japanese ODA	Yes	No
4	Confirmation of other donor's projects and local project	Yes	No
5	Impact on the surrounding society and economy	Much	Less
6	Access to the bridge sites	Good	Not Good
7	Collecting information from japanese companies, and estimation of project effects	See below	

2 Application of Japanese advanced technology

7 Collecting information from japanese companies, and estimation of project effects

Bridge Survey Record (1/6)

Date & Time: 13 Jun,2016 12:30

Bridge No.	Ser.No.8	Division	Vadodara
Bridge Name	LC No.5/A	Year of Construction	2011-2012
GPS Data	N 21 ° 42 ' 20"	Station	Bharuch
	E 72 ° 57 ' 59 "		Sami

Bridge Length	85.00m	Span Arrangement	Number 2
Bridge Width	27.50m	Type of Substructure	RC Abutment and RC Pier Column
Type of Superstructure	PSC Box Type		

Overview of the Bridge

Side View



Up View



Bridge Survey Record (2/6) Right Side

Date & Time: 13 Jun,2016 12:30

Bridge No.	Ser.No.8	Station	Bharuch
Bridge Name	LC No.5/A		Sami
Photoes			
Photo R3	Photo R6		
Photo R	Photo R		
Photo R	Photo R		

Bridge Survey Record (3/6) Left Side

Date & Time: 13 Jun,2016 12:30

Bridge No.	Ser.No.8	Station	Vadodara
Bridge Name	LC No.5/A		2011-2012
Photos			



Bridge Survey Record (4/6)

Date & Time: 13 Jun,2016 12:30

Bridge No.	Ser.No.8	Division	Vadodara
Bridge Name	LC No.5/A	Year of Construction	2011-2012
GPS Data	N 21 °42 ' 20"	Station	Bharuch
	E 72° 57 ' 59 "		Sami

General Description of Damages

Member	Kind of the Damage
	Ex. Concrete : Cracking, Spalling, etc. Steel : Cracking, Rusting, Fracture, etc.
1. Superstructure	
(1) Concrete Member	
- Girder	N/A
- Cross Beam	N/A
- Slab	Cracking
(2) Steel Member	N/A
- Girder	
- Vertical Girder (stringer)	
- Cross Beam	
- Sway Bracing	
(3) Bearing Shoe	No Check
(4) Drainage Pipe	No Check
(5) Others	
2. Substructure	
- Pier	Good
- Abutment	N/A
- Wing Wall	N/A
3. Miscellaneous	
- Approach Road Condition	Good
- Obstruction	
- Scouring	N/A
4. Evaluation	


Bridge Survey Record (5/6)

Date & Time: 13 Jun,2016 12:30

Bridge No.	Ser.No.8	Division	Vadodara
Bridge Name	LC No.5/A	Year of Construction	2011-2012
GPS Data	N 21 °42 ' 20"	Station	Bharuch
	E 72° 57 ' 59 "		Sami

Detailed Description of Damages

Object Member	PSC Box
Kind of Damage	Cracking
Sketch or Photo	



Bridge Survey Record (6/6)

Date & Time: 13 Jun,2016 12:30

Bridge No.	Ser.No.8	Location (State)	Vadodara
Bridge Name	LC No.5/A	Year of Construction	2011-2012
GPS Data	N 21 °42 ' 20"	Station	Bharuch
	E 72° 57 ' 59 "		Sami

Evaluation index

1	Cosistency with the upper plan, verification og Indian Railway priority bridges	Yes	No
2	Application of Japanese advanced technology	See below	
3	Confirmation of other projects by Japanese ODA	Yes	No
4	Confirmation of other donor's projects and local project	Yes	No
5	Impact on the surrounding society and economy	Much	Less
6	Access to the bridge sites	Good	Not Good
7	Collecting information from japanese companies, and estimation of project effects	See below	

2 Application of Japanese advanced technology

7 Collecting information from japanese companies, and estimation of project effects

Bridge Survey Record (1/6)

Date & Time: 13 Jun,2016 09:30







Bridge No.	Ser.No.9	Division	Vadodara
Bridge Name	LC No.2/X (North)	Year of Construction	2008
GPS Data	N 22 ° 03 ' 22"	Station	Miyagam
	E 73 ° 07 ' 46 "		Daboi-Malsar

Bridge Length	35.08m	Span Arrangement	Number 1
Bridge Width	6.35m	Type of Superstructure	RC Abutment and RC Pier Column
Type of Substructure	PSC Box Type	Type of Substructure	



Bridge Survey Record (2/6) Right Side

Date & Time: 13 Jun,2016 09:30

Bridge No.	Ser.No.9	Station	Miyagam
Bridge Name	LC No.2/X (North)		Daboi-Malsar
Photoes			
Photo R2	Photo R3		
			
Photo R5	Photo R6		
			
Photo R8	Photo R		
			

Bridge Survey Record (3/6) Left Side

Date & Time: 13 Jun,2016 09:30

Bridge No.	Ser.No.9	Station	Vadodara
Bridge Name	LC No.2/X (North)		2008
Photos			



Bridge Survey Record (4/6)

Date & Time: 13 Jun,2016 09:30

Bridge No.	Ser.No.9	Division	Vadodara
Bridge Name	LC No.2/X (North)	Year of Construction	2008
GPS Data	N 22 °03 ' 22"	Station	Miyagam
	E 73° 07 ' 46 "		Daboi-Malsar

General Description of Damages

Member	Kind of the Damage
	Ex. Concrete : Cracking, Spalling, etc. Steel : Cracking, Rusting, Fracture, etc.
1. Superstructure	
(1) Concrete Member	
- Girder	N/A
- Cross Beam	N/A
- Slab	Repair for Cracking
(2) Steel Member	N/A
- Girder	
- Vertical Girder (stringer)	
- Cross Beam	
- Sway Bracing	
(3) Bearing Shoe	No Check
(4) Drainage Pipe	N/A
(5) Others	
2. Substructure	
- Pier	No Check
- Abutment	Good
- Wing Wall	Good
3. Miscellaneous	
- Approach Road Condition	Bad
- Obstruction	
- Scouring	N/A
4. Evaluation	



Bridge Survey Record (5/6)

Date & Time: 13 Jun,2016 09:30

Bridge No.	Ser.No.9	Division	Vadodara
Bridge Name	LC No.2/X (North)	Year of Construction	2008
GPS Data	N 22 °03 ' 22"	Station	Miyagam
	E 73° 07 ' 46 "		Daboi-Malsar

Detailed Description of Damages

Object Member	Deck Slab
Kind of Damage	Repair Work for Cracking
Sketch or Photo	



Bridge Survey Record (6/6)

Date & Time: 13 Jun,2016 09:30

Bridge No.	Ser.No.9	Location (State)	Vadodara
Bridge Name	LC No.2/X (North)	Year of Construction	2008
GPS Data	N 22 °03 ' 22"	Station	Miyagam
	E 73° 07 ' 46 "		Daboi-Malsar

Evaluation index

1	Cosistency with the upper plan, verification og Indian Railway priority bridges	Yes	No
2	Application of Japanese advanced technology	See below	
3	Confirmation of other projects by Japanese ODA	Yes	No
4	Confirmation of other donor's projects and local project	Yes	No
5	Impact on the surrounding society and economy	Much	Less
6	Access to the bridge sites	Good	Not Good
7	Collecting information from japanese companies, and estimation of project effects	See below	

2 Application of Japanese advanced technology

7 Collecting information from japanese companies, and estimation of project effects

Bridge Survey Record (1/6)

Date & Time: 13 Jun,2016 09:30

Bridge No.	Ser.No.9	Division	Vadodara
Bridge Name	LC No.2/X (South)	Year of Construction	2008
GPS Data	N 22 ° 02 ' 14 "	Station	Miyagam
	E 73 ° 07 ' 24 "		Daboi-Malsar

Bridge Length	35.08m	Span Arrangement	Number 1
Bridge Width	6.35m		
Type of Superstructu	PSC Box Type	Type of Substructure	RC Abutment and RC Pier Column

Overview of the Bridge Side View










Up View



Bridge Survey Record (2/6) Right Side

Date & Time: 13 Jun,2016 09:30

Bridge No.	Ser.No.9	Station	Miyagam
Bridge Name	LC No.2/X (South)		Daboi-Malsar
Photoes			
Photo R2	Photo R5		
			
Photo R6	Photo R8		
			
Photo R10	Photo R		
			

Bridge Survey Record (3/6) Left Side

Date & Time: 13 Jun,2016 09:30

Bridge No.	Ser.No.9	Station	Vadodara
Bridge Name	LC No.2/X (South)		2008
Photos			



Bridge Survey Record (4/6)

Date & Time: 13 Jun,2016 09:30

Bridge No.	Ser.No.9	Division	Vadodara
Bridge Name	LC No.2/X (South)	Year of Construction	2008
GPS Data	N 22 °02 ' 14"	Station	Miyagam
	E 73° 07 ' 24 "		Daboi-Malsar

General Description of Damages







Member	Kind of the Damage
	Ex. Concrete : Cracking, Spalling, etc. Steel : Cracking, Rusting, Fracture, etc.
1. Superstructure	
(1) Concrete Member	
- Girder	N/A
- Cross Beam	N/A
- Slab	Cracking
(2) Steel Member	N/A
- Girder	
- Vertical Girder (stringer)	
- Cross Beam	
- Sway Bracing	
(3) Bearing Shoe	No Check
(4) Drainage Pipe	N/A
(5) Others	-
2. Substructure	
- Pier	No Check
- Abutment	Good
- Wing Wall	Good
3. Miscellaneous	
- Approach Road Condition	Good
- Obstruction	-
- Scouring	N/A
4.Evaluation	

Bridge Survey Record (5/6)

Date & Time: 13 Jun,2016 09:30

Bridge No.	Ser.No.9	Division	Vadodara
Bridge Name	LC No.2/X (South)	Year of Construction	2008
GPS Data	N 22 °02 ' 14"	Station	Miyagam
	E 73° 07 ' 24 "		Daboi-Malsar

Detailed Description of Damages

Object Member	Deck Slab
Kind of Damage	Cracking
Sketch or Photo	
 <p>ROB MYG (S) NH-8 Span 1x 35.8m EAST SIDE PSC BOX GIRDER HAIRLINE CRACK ON BRC END DIAPHRAGM.</p>	 <p>ROB MYG (S) NH-8 Span 1x 35.8m WEST SIDE PSC BOX GIRDER HAIRLINE CRACK ON DECK SLAB.</p>
 <p>ROB MYG (S) NH-8 Span 1x 35.8m WEST SIDE PSC BOX GIRDER HAIRLINE CRACK ON DECK SLAB.</p>	 <p>ROB MYG (S) NH-8 Span 1x 35.8m WEST SIDE PSC BOX GIRDER HAIRLINE CRACK ON DECK SLAB.</p>
 <p>ROB MYG (S) NH-8 Span 1x 35.8m WEST SIDE PSC BOX GIRDER HAIRLINE CRACK ON DECK SLAB.</p>	 <p>ROB MYG (S) NH-8 Span 1x 35.8m WEST SIDE PSC BOX GIRDER HAIRLINE CRACK ON DECK SLAB.</p>

Bridge Survey Record (6/6)

Date & Time: 13 Jun,2016 09:30

Bridge No.	Ser.No.9	Location (State)	Vadodara
Bridge Name	LC No.2/X (South)	Year of Construction	2008
GPS Data	N 22 °02 ' 14"	Station	Miyagam
	E 73° 07 ' 24 "		Daboi-Malsar

Evaluation index

1	Cosistency with the upper plan, verification og Indian Railway priority bridges	Yes	No
2	Application of Japanese advanced technology	See below	
3	Confirmation of other projects by Japanese ODA	Yes	No
4	Confirmation of other donor's projects and local project	Yes	No
5	Impact on the surrounding society and economy	Much	Less
6	Access to the bridge sites	Good	Not Good
7	Collecting information from japanese companies, and estimation of project effects	See below	

2 Application of Japanese advanced technology

7 Collecting information from japanese companies, and estimation of project effects

Bridge Survey Record (1/6)

Date & Time: 09 Jun,2016 11:00

Bridge No.	73	Division	Mumbai
Bridge Name	-	Year of Construction	1993
GPS Data	N 19° 19' 20"	Station	Bhayandar
	E 72° 59' 08 "		Naigaon

Bridge Length	1450m	Span Arrangement	Number 29
Bridge Width	6.7 m		
Type of Superstructu	PC Box Girder	Type of Substructure	RC Abutment and RC Pier Column

Overview of the Bridge

Side View



Up View










Bridge Survey Record (2/6) Right Side

Date & Time: 09 Jun,2016 11:00

Bridge No.	73	Station	Bhayandar
Bridge Name	-		Naigaon
Photoes			
Photo R			
Photo R			
Photo R			
Photo R			

Bridge Survey Record (3/6) Left Side

Date & Time: 09 Jun,2016 11:00

Bridge No.	73	Station	Mumbai
Bridge Name	-		1993
Photoes			
Photo L3			
Photo L5			
Photo L9			
Photo L6			
Photo L7			
Photo L			

Bridge Survey Record (4/6)

Date & Time: 09 Jun,2016 11:00

Bridge No.	73	Division	Mumbai
Bridge Name	-	Year of Construction	1993
GPS Data	N 19 °19 ' 20"	Station	Bhayandar
	E 72°59 ' 08 "		Naigaon

General Description of Damages

Member	Kind of the Damage
	Ex. Concrete : Cracking, Spalling, etc. Steel : Cracking, Rusting, Fracture, etc.
1. Superstructure	
(1) Concrete Member	
- Girder	Cracking
- Cross Beam	N/A
- Slab	Good
(2) Steel Member	N/A
- Girder	
- Vertical Girder (stringer)	
- Cross Beam	
- Sway Bracing	
(3) Bearing Shoe	No Check
(4) Drainage Pipe	N/A
(5) Others	-
2. Substructure	
- Pier	No Check
- Abutment	Good
- Wing Wall	N/A
3. Miscellaneous	
- Approach Road Condition	Good
- Obstruction	-
- Scouring	
4. Evaluation	



Bridge Survey Record (5/6)

Date & Time: 09 Jun,2016 11:00

Bridge No.	73	Division	Mumbai
Bridge Name	-	Year of Construction	1993
GPS Data	N 19 °19 ' 20"	Station	Bhayandar
	E 72°59 ' 08 "		Naigaon

Detailed Description of Damages

Object Member	PSC Box Girder
Kind of Damage	Horizontal and Inclined Cracks in Web
Sketch or Photo	



Bridge Survey Record (6/6)

Date & Time: 09 Jun,2016 11:00

Bridge No.	73	Location (State)	Mumbai
Bridge Name	-	Year of Construction	1993
GPS Data	N 19 °19 ' 20"	Station	Bhayandar
	E 72°59 ' 08 "		Naigaon

Evaluation index

1	Cosistency with the upper plan, verification og Indian Railway priority bridges	Yes	No
2	Application of Japanese advanced technology	See below	
3	Confirmation of other projects by Japanese ODA	Yes	No
4	Confirmation of other donor's projects and local project	Yes	No
5	Impact on the surrounding society and economy	Much	Less
6	Access to the bridge sites	Good	Not Good
7	Collecting information from japanese companies, and estimation of project effects	See below	

2 Application of Japanese advanced technology

7 Collecting information from japanese companies, and estimation of project effects

Bridge Survey Record (1/6)

Date & Time: 09 Jun,2016

Bridge No.	75	Division	Mumbai
Bridge Name	-	Year of Construction	1993
GPS Data	N 19 °20 ' 24"	Station	Bhayandar
	E 72°51 ' 01 "		Natgaon

Bridge Length	550m	Span Arrangement	Number 11
Bridge Width	- m		
Type of Superstructure	PC Box Girder	Type of Substructure	RC Abutment and RC Pier Column

Overview of the Bridge	Side View
Up View	

Bridge Survey Record (2/6) Right Side

Date & Time: 09 Jun,2016

Bridge No.	75	Station	Bhayandar
Bridge Name	-		Natgaon
Photoes			
Photo R2	Photo R3		
Photo R5	Photo R		
Photo R	Photo R		

Bridge Survey Record (3/6) Left Side

Date & Time: 09 Jun,2016

Bridge No.	75	Station	Mumbai
Bridge Name	-		1993
Photos			
Photo L2	Photo L5		
Photo L6	Photo L8		
Photo L	Photo L		

Bridge Survey Record (4/6)

Date & Time: 09 Jun,2016

Bridge No.	75	Division	Mumbai
Bridge Name	-	Year of Construction	1993
GPS Data	N 19 °20 ' 24"	Station	Bhayandar
	E 72°51 ' 01 "		Natgaon

General Description of Damages

Member	Kind of the Damage
	Ex. Concrete : Cracking, Spalling, etc. Steel : Cracking, Rusting, Fracture, etc.
1. Superstructure	
(1) Concrete Member	
- Girder	
- Cross Beam	
- Slab	
(2) Steel Member	
- Girder	
- Vertical Girder (stringer)	
- Cross Beam	
- Sway Bracing	
(3) Bearing Shoe	
(4) Drainage Pipe	
(5) Others	
2. Substructure	
- Pier	
- Abutment	
- Wing Wall	
3. Miscellaneous	
- Approach Road Condition	
- Obstruction	
- Scouring	
4. Evaluation	

Bridge Survey Record (5/6)

Date & Time: 09 Jun,2016

Bridge No.	75	Division	Mumbai
Bridge Name	-	Year of Construction	1993
GPS Data	N 19 °20 ' 24"	Station	Bhayandar
	E 72°51 ' 01 "		Natgaon

Detailed Description of Damages

Object Member	
Kind of Damage	
Sketch or Photo	

Bridge Survey Record (6/6)

Date & Time: 09 Jun,2016

Bridge No.	75	Location (State)	Mumbai
Bridge Name	-	Year of Construction	1993
GPS Data	N 19 °20 ' 24"	Station	Bhayandar
	E 72°51 ' 01 "		Natgaon

Evaluation index

1	Cosistency with the upper plan, verification og Indian Railway priority bridges	Yes	No
2	Application of Japanese advanced technology	See below	
3	Confirmation of other projects by Japanese ODA	Yes	No
4	Confirmation of other donor's projects and local project	Yes	No
5	Impact on the surrounding society and economy	Much	Less
6	Access to the bridge sites	Good	Not Good
7	Collecting information from japanese companies, and estimation of project effects	See below	

2 Application of Japanese advanced technology

7 Collecting information from japanese companies, and estimation of project effects

Bridge Survey Record (1/6)

Date & Time: 09 Jun,2016 13:30

Bridge No.	92	Division	Mumbai
Bridge Name	-	Year of Construction	1963
GPS Data	N 19° 31' 28"	Station	Vaitama
	E 72° 51' 02"		Saphale

Bridge Length	380m	Span Arrangement	Number 20
Bridge Width	-m		
Type of Superstructure	Type: Steel I-Girder	Type of Substructure	Abutment RC Abutment and RC Pier Column

Overview of the Bridge Side View



Up View



Bridge Survey Record (2/6) Right Side

Date & Time: 09 Jun,2016 13:30

Bridge No.	92	Station	Vaitama
Bridge Name	-		Saphale
Photoes			

Photo R2



Photo R3



Photo R5



Photo R



Photo R



Photo R



Bridge Survey Record (3/6) Left Side

Date & Time: 09 Jun,2016 13:30

Bridge No.	92	Station	Mumbai
Bridge Name	-		1963
Photos			
Photo R1			
Photo L5			
Photo L6			
Photo L8			
Photo L			
Photo L			

Bridge Survey Record (4/6)

Date & Time: 09 Jun,2016 13:30

Bridge No.	92	Division	Mumbai
Bridge Name	-	Year of Construction	1963
GPS Data	N 19 °31 ' 28"	Station	Vaitama
	E 72°51 ' 02 "		Saphale

General Description of Damages

Member	Kind of the Damage
	Ex. Concrete : Cracking, Spalling, etc. Steel : Cracking, Rusting, Fracture, etc.
1. Superstructure	
(1) Concrete Member	N/A
- Girder	
- Cross Beam	
- Slab	
(2) Steel Member	
- Girder	Good
- Vertical Girder (stringer)	N/A
- Cross Beam	N/A
- Sway Bracing	N/A
(3) Bearing Shoe	No Check
(4) Drainage Pipe	N/A
(5) Others	-
2. Substructure	
- Pier	Cracking
- Abutment	Good
- Wing Wall	Good Condition
3. Miscellaneous	
- Approach Road Condition	Good
- Obstruction	-
- Scouring	No Check
4. Evaluation	


Bridge Survey Record (5/6)

Date & Time: 09 Jun,2016 13:30

Bridge No.	92	Division	Mumbai
Bridge Name	-	Year of Construction	1963
GPS Data	N 19 °31 ' 28"	Station	Vaitama
	E 72°51 ' 02 "		Saphale

Detailed Description of Damages

Object Member	Pier
Kind of Damage	Cracking
Sketch or Photo	



Bridge Survey Record (6/6)

Date & Time: 09 Jun,2016 13:30

Bridge No.	92	Location (State)	Mumbai
Bridge Name	-	Year of Construction	1963
GPS Data	N 19 °31 ' 28"	Station	Vaitama
	E 72°51 ' 02 "		Saphale

Evaluation index

1	Cosistency with the upper plan, verification og Indian Railway priority bridges	Yes	No
2	Application of Japanese advanced technology	See below	
3	Confirmation of other projects by Japanese ODA	Yes	No
4	Confirmation of other donor's projects and local project	Yes	No
5	Impact on the surrounding society and economy	Much	Less
6	Access to the bridge sites	Good	Not Good
7	Collecting information from japanese companies, and estimation of project effects	See below	

2 Application of Japanese advanced technology

7 Collecting information from japanese companies, and estimation of project effects

Bridge Survey Record (1/6)

Date & Time: 09 Jun,2016

Bridge No.	93	Division	Mumbai
Bridge Name	-	Year of Construction	1963
GPS Data	N 19 °32 ' 20"	Station	Vaitama
	E 72°51 ' 05 "		Saphale

Bridge Length	410 m	Span Arrangement	Number 22
Bridge Width	-m		
Type of Superstructure	Type: Steel I-Girder	Type of Substructure	AbutmentRC Abutment and RC Pier Column

Overview of the Bridge	Side View
Up View	

Bridge Survey Record (2/6) Right Side

Date & Time: 09 Jun,2016

Bridge No.	93	Station	Vaitama
Bridge Name	-		Saphale
Photoes			
Photo R1	Photo R2		
Photo R5	Photo R8		
Photo R10	Photo R		

Bridge Survey Record (3/6) Left Side

Date & Time: 09 Jun,2016

Bridge No.	93	Station	Mumbai
Bridge Name	-		1963
Photos			
Photo L5	Photo L7		
Photo L8	Photo L		
Photo L	Photo L		

Bridge Survey Record (4/6)

Date & Time: 09 Jun,2016

Bridge No.	93	Division	Mumbai
Bridge Name	-	Year of Construction	1963
GPS Data	N 19 °32 ' 20"	Station	Vaitama
	E 72°51 ' 05 "		Saphale

General Description of Damages

Member	Kind of the Damage
	Ex. Concrete : Cracking, Spalling, etc. Steel : Cracking, Rusting, Fracture, etc.
1. Superstructure	
(1) Concrete Member	
- Girder	
- Cross Beam	
- Slab	
(2) Steel Member	
- Girder	
- Vertical Girder (stringer)	
- Cross Beam	
- Sway Bracing	
(3) Bearing Shoe	
(4) Drainage Pipe	
(5) Others	
2. Substructure	
- Pier	
- Abutment	
- Wing Wall	
3. Miscellaneous	
- Approach Road Condition	
- Obstruction	
- Scouring	
4. Evaluation	

Bridge Survey Record (5/6)

Date & Time: 09 Jun,2016

Bridge No.	93	Division	Mumbai
Bridge Name	-	Year of Construction	1963
GPS Data	N 19 °32 ' 20"	Station	Vaitama
	E 72°51 ' 05 "		Saphale

Detailed Description of Damages

Object Member	
Kind of Damage	
Sketch or Photo	



Bridge Survey Record (6/6)

Date & Time: 09 Jun,2016

Bridge No.	93	Location (State)	Mumbai
Bridge Name	-	Year of Construction	1963
GPS Data	N 19 °32 ' 20"	Station	Vaitama
	E 72°51 ' 05 "		Saphale

Evaluation index

1	Cosistency with the upper plan, verification og Indian Railway priority bridges	Yes	No
2	Application of Japanese advanced technology	See below	
3	Confirmation of other projects by Japanese ODA	Yes	No
4	Confirmation of other donor's projects and local project	Yes	No
5	Impact on the surrounding society and economy	Much	Less
6	Access to the bridge sites	Good	Not Good
7	Collecting information from japanese companies, and estimation of project effects	See below	

2 Application of Japanese advanced technology

7 Collecting information from japanese companies, and estimation of project effects

Bridge Survey Record (1/6)

Date & Time: 14 Jun,2016 12:20

Bridge No.	114	Division	Ratlam
Bridge Name	-	Year of Construction	1958-60
GPS Data	N 22 ° 50 ' 46" 06	Station	Dahod
	E 74 ° 17 ' 30 "		Dhamarda

Bridge Length	80.00m	Span Arrangement	Number 4
Bridge Width	4.30m		
Type of Superstructure	PSC I-Girder	Type of Substructure	Stone Masonry Abutment

Overview of the Bridge Side View



Up View



Bridge Survey Record (2/6) Right Side

Date & Time: 14 Jun,2016 12:20

Bridge No.	114	Station	Dahod
Bridge Name	-		Dhamarda
Photoes			
Photo R	Photo R		
Photo R	Photo R		
Photo R10	Photo R		

Bridge Survey Record (3/6) Left Side

Date & Time: 14 Jun,2016 12:20

Bridge No.	114	Station	Ratlam
Bridge Name	-		1958-60
Photos			



Bridge Survey Record (4/6)

Date & Time: 14 Jun,2016 12:20

Bridge No.	114	Division	Ratlam
Bridge Name	-	Year of Construction	1958-60
GPS Data	N 22 °50 ' 46" 06	Station	Dahod
	E 74°17 ' 30 "		Dhamarda

General Description of Damages





Member	Kind of the Damage
	Ex. Concrete : Cracking, Spalling, etc. Steel : Cracking, Rusting, Fracture, etc.
1. Superstructure	
(1) Concrete Member	Good
- Girder	
- Cross Beam	
- Slab	
(2) Steel Member	N/A
- Girder	
- Vertical Girder (stringer)	
- Cross Beam	
- Sway Bracing	
(3) Bearing Shoe	No Check
(4) Drainage Pipe	N/A
(5) Others	-
2. Substructure	
- Pier	No Check
- Abutment	Good
- Wing Wall	Good
3. Miscellaneous	
- Approach Road Condition	Good
- Obstruction	-
- Scouring	N/A
4. Evaluation	

Bridge Survey Record (5/6)

Date & Time: 14 Jun,2016 12:20

Bridge No.	114	Division	Ratlam
Bridge Name	-	Year of Construction	1958-60
GPS Data	N 22 °50 ' 46" 06	Station	Dahod
	E 74°17 ' 30 "		Dhamarda

Detailed Description of Damages

Object Member	Prestressed I-Girder
Kind of Damage	After Repairing CFRP, Now in Good Condition
Sketch or Photo	<div style="display: flex; flex-wrap: wrap; justify-content: space-around;">   </div> <div style="display: flex; flex-wrap: wrap; justify-content: space-around; margin-top: 20px;">   </div>

Bridge Survey Record (6/6)

Date & Time: 14 Jun,2016 12:20

Bridge No.	114	Location (State)	Ratlam
Bridge Name	-	Year of Construction	1958-60
GPS Data	N 22 °50 ' 46" 06	Station	Dahod
	E 74°17 ' 30 "		Dhamarda

Evaluation index

1	Cosistency with the upper plan, verification og Indian Railway priority bridges	Yes	No
2	Application of Japanese advanced technology	See below	
3	Confirmation of other projects by Japanese ODA	Yes	No
4	Confirmation of other donor's projects and local project	Yes	No
5	Impact on the surrounding society and economy	Much	Less
6	Access to the bridge sites	Good	Not Good
7	Collecting information from japanese companies, and estimation of project effects	See below	

2 Application of Japanese advanced technology

7 Collecting information from japanese companies, and estimation of project effects

Bridge Survey Record (1/6)

Date & Time: 14 Jun,2016 11:40

Bridge No.	129	Division	Ratlam
Bridge Name	-	Year of Construction	1958-60
GPS Data	N 22 °51 ' 54"	Station	Bordi
	E 74°22 ' 32 "		Anas

Bridge Length	60.00m	Span Arrangement	Number 3
Bridge Width	4.30m		
Type of Superstructure	PSC I-Girder	Type of Substructure	Stone Masonry Abutment

Overview of the Bridge Side View



Up View



Bridge Survey Record (2/6) Right Side


Date & Time: 14 Jun,2016 11:40

Bridge No.	129	Station	Bordi
Bridge Name	-		Anas
Photoes	<p>The diagram illustrates the layout of a bridge with two main spans. On the left span, photo points R1 through R9 are marked with blue arrows indicating the direction of photography. On the right span, points L1 through L10 are marked. A central section between the spans shows points R4, R5, R6, L4, L5, and L6. Dashed lines connect R1 to R2, R2 to R3, R3 to R4, R4 to R5, R5 to R6, R6 to R7, R7 to R8, and R8 to R9. Similarly, dashed lines connect L1 to L2, L2 to L3, L3 to L4, L4 to L5, L5 to L6, L6 to L7, L7 to L8, L8 to L9, and L9 to L10.</p>		
Photo R	<p>A photograph showing several workers in orange safety gear standing on the top surface of the bridge deck. The bridge is supported by stone piers, and the surrounding area is a dry, dusty landscape.</p>		
Photo R	<p>A close-up view of the bridge's structural elements, showing concrete beams and extensive scaffolding used for construction or maintenance work.</p>		
Photo R	<p>A side view of the bridge structure, showing the concrete beams and the scaffolding that covers a significant portion of the bridge's length.</p>		
Photo R	<p>A view of the bridge piers and the deck structure, showing the stone masonry of the piers and the concrete deck above them.</p>		
Photo R	<p>This section is currently empty, intended for a photograph.</p>		
Photo R	<p>This section is currently empty, intended for a photograph.</p>		

Bridge Survey Record (3/6) Left Side

Date & Time: 14 Jun,2016 11:40

Bridge No.	129	Station	Ratlam
Bridge Name	-		1958-60
Photos			



Bridge Survey Record (4/6)

Date & Time: 14 Jun,2016 11:40

Bridge No.	129	Division	Ratlam
Bridge Name	-	Year of Construction	1958-60
GPS Data	N 22 °51 ' 54"	Station	Bordi
	E 74°22 ' 32 "		Anas

General Description of Damages

Member	Kind of the Damage
	Ex. Concrete : Cracking, Spalling, etc. Steel : Cracking, Rusting, Fracture, etc.
1. Superstructure	
(1) Concrete Member	Good
- Girder	
- Cross Beam	
- Slab	
(2) Steel Member	N/A
- Girder	
- Vertical Girder (stringer)	
- Cross Beam	
- Sway Bracing	
(3) Bearing Shoe	No Check
(4) Drainage Pipe	N/A
(5) Others	-
2. Substructure	
- Pier	N/A
- Abutment	Good
- Wing Wall	Good
3. Miscellaneous	
- Approach Road Condition	Good
- Obstruction	-
- Scouring	N/A
4. Evaluation	

Bridge Survey Record (5/6)

Date & Time: 14 Jun,2016 11:40

Bridge No.	129	Division	Ratlam
Bridge Name	-	Year of Construction	1958-60
GPS Data	N 22 °51 ' 54"	Station	Bordi
	E 74°22 ' 32 "		Anas

Detailed Description of Damages

Object Member	Prestressed I-Girders
Kind of Damage	After Repairing CFRP, Now in Good Condition
Sketch or Photo	



Bridge Survey Record (6/6)

Date & Time: 14 Jun,2016 11:40

Bridge No.	129	Location (State)	Ratlam
Bridge Name	-	Year of Construction	1958-60
GPS Data	N 22 °51 ' 54"	Station	Bordi
	E 74°22 ' 32 "		Anas

Evaluation index

1	Cosistency with the upper plan, verification og Indian Railway priority bridges	Yes	No
2	Application of Japanese advanced technology	See below	
3	Confirmation of other projects by Japanese ODA	Yes	No
4	Confirmation of other donor's projects and local project	Yes	No
5	Impact on the surrounding society and economy	Much	Less
6	Access to the bridge sites	Good	Not Good
7	Collecting information from japanese companies, and estimation of project effects	See below	

2 Application of Japanese advanced technology

7 Collecting information from japanese companies, and estimation of project effects

Bridge Survey Record (1/6)

Date & Time: 14 Jun,2016 10:40

Bridge No.	132	Division	Ratlam
Bridge Name	-	Year of Construction	1958-60
GPS Data	N 22 °52 ' 06"	Station	Bordi
	E 74°23 ' 35 "		Anas

Bridge Length	20.00m	Span Arrangement	Number 1
Bridge Width	4.30m		
Type of Superstructure	PSC I-Girder	Type of Substructure	Stone Masonry Abutment

Overview of the Bridge Side View



Up View



Bridge Survey Record (2/6) Right Side

Date & Time: 14 Jun,2016 10:40

Bridge No.	132	Station	Bordi
Bridge Name	-		Anas
Photoes			

Photo R1



Photo R2



Photo R3



Photo R5



Photo R8




Photo R10



Bridge Survey Record (3/6) Left Side

Date & Time: 14 Jun,2016 10:40

Bridge No.	132	Station	Ratlam
Bridge Name	-		1958-60
Photos			



Bridge Survey Record (4/6)

Date & Time: 14 Jun,2016 10:40

Bridge No.	132	Division	Ratlam
Bridge Name	-	Year of Construction	1958-60
GPS Data	N 22 °52 ' 06"	Station	Bordi
	E 74°23 ' 35 "		Anas

General Description of Damages

Member	Kind of the Damage
	Ex. Concrete : Cracking, Spalling, etc. Steel : Cracking, Rusting, Fracture, etc.
1. Superstructure	
(1) Concrete Member	Good
- Girder	
- Cross Beam	
- Slab	
(2) Steel Member	N/A
- Girder	
- Vertical Girder (stringer)	
- Cross Beam	
- Sway Bracing	
(3) Bearing Shoe	No Check
(4) Drainage Pipe	N/A
(5) Others	-
2. Substructure	
- Pier	N/A
- Abutment	Good
- Wing Wall	Good
3. Miscellaneous	
- Approach Road Condition	Good
- Obstruction	-
- Scouring	N/A
4. Evaluation	

Bridge Survey Record (5/6)

Date & Time: 14 Jun,2016 10:40

Bridge No.	132	Division	Ratlam
Bridge Name	-	Year of Construction	1958-60
GPS Data	N 22 °52 ' 06"	Station	Bordi
	E 74°23 ' 35 "		Anas

Detailed Description of Damages

Object Member	Prestressed I-Girders
Kind of Damage	After Repairing CFRP, Now in Good Condition
Sketch or Photo	



Bridge Survey Record (6/6)

Date & Time: 14 Jun,2016 10:40

Bridge No.	132	Location (State)	Ratlam
Bridge Name	-	Year of Construction	1958-60
GPS Data	N 22 °52 ' 06"	Station	Bordi
	E 74°23 ' 35 "		Anas

Evaluation index

1	Cosistency with the upper plan, verification og Indian Railway priority bridges	Yes	No
2	Application of Japanese advanced technology	See below	
3	Confirmation of other projects by Japanese ODA	Yes	No
4	Confirmation of other donor's projects and local project	Yes	No
5	Impact on the surrounding society and economy	Much	Less
6	Access to the bridge sites	Good	Not Good
7	Collecting information from japanese companies, and estimation of project effects	See below	

2 Application of Japanese advanced technology

7 Collecting information from japanese companies, and estimation of project effects

Bridge Survey Record (1/6)

Date & Time: 15 Jun,2016 10:40

Bridge No.	R5	Division	Ratlam
Bridge Name	-	Year of Construction	1958-60
GPS Data	N 22° 49' 18"	Station	Limkheda
	E 74° 02' 38"		Mangal Mahudi

Bridge Length	20.00m	Span Arrangement	Number 1
Bridge Width	4.30m		
Type of Superstructure	PSC I-Girder	Type of Substructure	Stone Masonry Abutment

Overview of the Bridge

Side View








Up View



Bridge Survey Record (2/6) Right Side

Date & Time: 15 Jun,2016 10:40

Bridge No.	R5	Station	Limkheda
Bridge Name	-		Mangal Mahudi
Photoes			
Photo R2	Photo R5		
			
Photo R6	Photo R7		
			
Photo R10	Photo R		
			

Bridge Survey Record (3/6) Left Side

Date & Time: 15 Jun,2016 10:40

Bridge No.	R5	Station	Ratlam
Bridge Name	-		1958-60
Photos			



Bridge Survey Record (4/6)

Date & Time: 15 Jun,2016 10:40

Bridge No.	R5	Division	Ratlam
Bridge Name	-	Year of Construction	1958-60
GPS Data	N 22 °49 ' 18"	Station	Limkheda
	E 74°02 ' 38 "		Mangal Mahudi

General Description of Damages





Member	Kind of the Damage
	Ex. Concrete : Cracking, Spalling, etc. Steel : Cracking, Rusting, Fracture, etc.
1. Superstructure	
(1) Concrete Member	
- Girder	Cracking
- Cross Beam	Good
- Slab	Cracking , Reinforcement Bar Exposed
(2) Steel Member	N/A
- Girder	
- Vertical Girder (stringer)	
- Cross Beam	
- Sway Bracing	
(3) Bearing Shoe	No Check
(4) Drainage Pipe	N/A
(5) Others	-
2. Substructure	
- Pier	N/A
- Abutment	Good
- Wing Wall	Good
3. Miscellaneous	
- Approach Road Condition	Good
- Obstruction	-
- Scouring	N/A
4. Evaluation	

Bridge Survey Record (5/6)

Date & Time: 15 Jun,2016 10:40

Bridge No.	R5	Division	Ratlam
Bridge Name	-	Year of Construction	1958-60
GPS Data	N 22 °49 ' 18"	Station	Limkheda
	E 74°02 ' 38 "		Mangal Mahudi

Detailed Description of Damages

Object Member	Prestressed I-Girders
Kind of Damage	Cracking
Sketch or Photo	<div style="display: flex; flex-wrap: wrap; justify-content: space-around;">   </div> <div style="display: flex; flex-wrap: wrap; justify-content: space-around; margin-top: 20px;">   </div>

Bridge Survey Record (6/6)

Date & Time: 15 Jun,2016 10:40

Bridge No.	R5	Location (State)	Ratlam
Bridge Name	-	Year of Construction	1958-60
GPS Data	N 22 °49 ' 18"	Station	Limkheda
	E 74°02 ' 38 "		Mangal Mahudi

Evaluation index

1	Cosistency with the upper plan, verification og Indian Railway priority bridges	Yes	No
2	Application of Japanese advanced technology	See below	
3	Confirmation of other projects by Japanese ODA	Yes	No
4	Confirmation of other donor's projects and local project	Yes	No
5	Impact on the surrounding society and economy	Much	Less
6	Access to the bridge sites	Good	Not Good
7	Collecting information from japanese companies, and estimation of project effects	See below	

2 Application of Japanese advanced technology

7 Collecting information from japanese companies, and estimation of project effects

Bridge Survey Record (1/6)

Date & Time: 15 Jun,2016 11:40

Bridge No.	R8	Division	Ratlam
Bridge Name	-	Year of Construction	1958-60
GPS Data	N 22 °49 ' 40"	Station	Limkheda
	E 74°03 ' 20 "		Mangal Mahudi

Bridge Length	20.00m	Span Arrangement	Number 1
Bridge Width	4.30m		
Type of Superstructure	PSC I-Girder	Type of Substructure	Stone Masonry Abutment

Overview of the Bridge Side View



Up View



Bridge Survey Record (2/6) Right Side


Date & Time: 15 Jun,2016 11:40

Bridge No.	R8	Station	Limkheda
Bridge Name	-		Mangal Mahudi
Photoes			
Photo R1	Photo R2		
Photo R5	Photo R6		
Photo R8	Photo R10		

Bridge Survey Record (3/6) Left Side

Date & Time: 15 Jun,2016 11:40

Bridge No.	R8	Station	Ratlam
Bridge Name	-		1958-60
Photos			



Bridge Survey Record (4/6)

Date & Time: 15 Jun,2016 11:40

Bridge No.	R8	Division	Ratlam
Bridge Name	-	Year of Construction	1958-60
GPS Data	N 22 °49 ' 40"	Station	Limkheda
	E 74°03 ' 20 "		Mangal Mahudi

General Description of Damages





Member	Kind of the Damage
	Ex. Concrete : Cracking, Spalling, etc. Steel : Cracking, Rusting, Fracture, etc.
1. Superstructure	
(1) Concrete Member	
- Girder	Cracking
- Cross Beam	Good
- Slab	Cracking , Reinforcement Bar Exposed
(2) Steel Member	N/A
- Girder	
- Vertical Girder (stringer)	
- Cross Beam	
- Sway Bracing	
(3) Bearing Shoe	No Check
(4) Drainage Pipe	N/A
(5) Others	-
2. Substructure	
- Pier	N/A
- Abutment	Good
- Wing Wall	Good
3. Miscellaneous	
- Approach Road Condition	Good
- Obstruction	-
- Scouring	N/A
4. Evaluation	

Bridge Survey Record (5/6)

Date & Time: 15 Jun,2016 11:40

Bridge No.	R8	Division	Ratlam
Bridge Name	-	Year of Construction	1958-60
GPS Data	N 22 °49 ' 40"	Station	Limkheda
	E 74°03 ' 20 "		Mangal Mahudi

Detailed Description of Damages

Object Member	Prestressed I-Girders
Kind of Damage	Cracking
Sketch or Photo	<div style="display: flex; justify-content: space-around; align-items: flex-start;"> <div style="width: 45%;">  <p>A photograph showing the side view of a bridge structure under construction or repair. Scaffolding is visible around the concrete girders. The bridge is supported by a stone masonry abutment on the right.</p> </div> <div style="width: 45%;">  <p>A close-up photograph of a concrete surface, likely a prestressed I-girder, showing a distinct vertical crack. A measuring tape is visible in the background for scale.</p> </div> </div> <div style="display: flex; justify-content: space-around; align-items: flex-start; margin-top: 20px;"> <div style="width: 45%;">  <p>A close-up photograph of a concrete surface, showing a vertical crack. A wooden plank is visible in the foreground, possibly used for access or support.</p> </div> <div style="width: 45%;">  <p>A photograph showing a bridge structure with scaffolding. The bridge is supported by a stone masonry abutment. The image is somewhat dark and blurry.</p> </div> </div>

Bridge Survey Record (6/6)

Date & Time: 15 Jun,2016 11:40

Bridge No.	R8	Location (State)	Ratlam
Bridge Name	-	Year of Construction	1958-60
GPS Data	N 22 °49 ' 40"	Station	Limkheda
	E 74°03 ' 20 "		Mangal Mahudi

Evaluation index

1	Cosistency with the upper plan, verification of Indian Railway priority bridges	Yes	No
2	Application of Japanese advanced technology	See below	
3	Confirmation of other projects by Japanese ODA	Yes	No
4	Confirmation of other donor's projects and local project	Yes	No
5	Impact on the surrounding society and economy	Much	Less
6	Access to the bridge sites	Good	Not Good
7	Collecting information from japanese companies, and estimation of project effects	See below	

2 Application of Japanese advanced technology

7 Collecting information from japanese companies, and estimation of project effects