

Minchin Flood Bund RD 90+000

Creation Date: 3/3/2024





Province	Zone	Division	Circle
Punjab	Bahawalpur Zone	Punjnad Headworks Division	Punjnad Canal Circle
Sr. No.	River Name	River System	Bank
P-001	Indus River	Indus River	Left
Bund Name		R.D.	GPS Coordinates
Minchin Flood Bund		RD 90+000 to 100+000	29°08'78.33"N, 70°76'66.67"E
Name of Vulnerable Point	Minchin Flood Bund RD 90+000 to 100+000		
Reason for the Vulnerability	<ul style="list-style-type: none"> In 2010 flood, seepage water crossed this bund at this reach and approx. 10 feet. deep pit was formed on the country side of the bund. During 2015 flood, the River Indus impacted the same reach once again 		
Flow Condition ¹	<ul style="list-style-type: none"> There is no flow at this location due to shift in the river's direction away from the bund. River is approx. 4 km away from the said reach. 		
Site Condition in the Country Side ²	<ul style="list-style-type: none"> Cultivated land is located on the countryside side of the bund, supporting agricultural activities in the area.. 		
Layout Plan (Source of Satellite Image: Google Earth)			
Evaluation ³			
Category	Quality Score		
Emergent Type C	4/9		







¹ Water Flow Direction and Conditions During Floods Around the Listed Vulnerable Points

² Site Condition Around the Vulnerable Points (Rough Distance Between Main Water Channel and the Bund, Land Use Behind the Point, Important Facility Adjacent to the Point)


³ Emergent Type R: Emergent Phase Requiring Robust Countermeasures, Emergent Type C: Emergent Phase Requiring Common Countermeasures, Proactive Type R: Proactive Phase Requiring Robust Countermeasures, Proactive Type C: Proactive Phase Requiring Common Countermeasures, Monitoring: Monitoring Phase

Basic Information of the Bund			
Basic Dimensions and Materials	Item	Existing	Proposed
	Top Elevation	326.57 feet.	Not Applicable —
	H.F. L	321.42 feet	
	Free Board Height	5.15 feet	
	Top Width	25 feet	
	River Side Slope	1:3	
	Country Side Slope	1:2	
	Longitudinal Length	1000 feet	
	Slope Protection Material	Earthen (Silty clay)	
	Covering Material/ Pavement on the Top	Earthen (Silty clay)	
	Embankment Material	Earthen (Silty clay)	
Ancillary Structure (Drainage Ditch, and Spurs)	Nil		
Typical Cross Section			
	<p style="text-align: center;">PREVENTING EROSION OF RIVER INDUS ALONG MINCHIN FLOOD BUND RD 6+700 TO RD 122+000 (TAUNSA-GUDDU REACH D/S PANJNAD HEADWORKS)</p> <p style="text-align: center;">MINCHIN FLOOD BUND X-SECTION AT RD:90+000</p>		
History of Damages			
MM/YYYY	Type of Damage	Description	
	Nil		
Record of Rehabilitation/ Improvement			
MM/YYYY	Project Name with its Description	Cost	Source of Funding
	Nil		
Plan for Rehabilitation/ Improvement			
MM/YYYY	Project Name with its Description	Cost	Source of Funding
	Preventing erosion of River Indus along Minchin Flood Bund Rd 6+700 to Rd 122+000 (Taunsa-Guddu Reach D/S Panjnad Headworks)	Rs. 669.77 Million	ADB

Site Photo	
Vulnerable Section	General View of River Side
	Facing Downstream and Side
	
	Facing Upstream Side
	
	General View of Top
	Facing Downstream and Side
	
	Facing Upstream Side
	
	General View of Landside
	Facing Downstream and Side
	
Facing Upstream Side	
	
Close View of Deformation	
	
Road crossing by cutting the bund	
Close View of Damages	
Not Applicable	

	<p>Photo with 360° angles</p> 	
<p>Typical Section (Adjacent to the Vulnerable Point)</p>	<p>General View of River Side</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
	<p>General View of Top</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
	<p>General View of Landside</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
	<p>Photo with 360° angles</p> 	

Downstream End of the Bund	General View (Not Available)
	Photo with 360 ⁰ angles (Not Available)
Upstream End of the Bund	General View (In the case that the VP is located near the end) (Not Applicable)
	Photo with 360 ⁰ angles (Not Applicable)

Observation Record ⁴ (Current status, effect of countermeasure, development of erosion, deformation, and deterioration)			
DD/MM/YYYY	Inspection Type	Description and Photo	Damage ⁵
03/3/2024	Visual Inspection	<ul style="list-style-type: none"> • Top level is bumpy and uneven. • Natural surface level is approximately 28 feet below the top level. • Cultivated areas are present on the countryside side of the bund. • Seepage was observed in the past flood.  <p>Cropped area towards country side</p>	L

⁴ Current Status, Effect of the Existing Structural Countermeasure Such As Spurs/studs, Sheet Piles for Seepage Control etc and Development of Erosion, Deformation, Deterioration of the Existing Bund

⁵ a: No Deformation, b: No deformations are observed on the bund body, except for gully erosion caused by raindrops or the detachment of the bund's stone pitching, c: The bund or the apron has been damaged, and L: Leakage from the bund has been identified

Evaluation Process					
DD/MM/YYYY	Item		Result	Reason	
	Criteria For Evaluation Flow	Flood Damage		Yes	The inundation analysis indicates that the flood damage is severe
		Bund Damage		YES	Seepage was observed.
		Bund Dimension	Bund Height	Fail	Free board height is 5.1 feet.
			Bund Width	Pass	The soil cover thickness over HGL exceeds the guideline value (Soil Depth \geq 2 feet)
			Flood Plain Length	Pass	Floodplain length is about 15900 feet.
		Topographic Feature	Breach Record	No	There is no breach record.
			Flow Impact	NO	It hasn't been affected by strong water flow since before 2010 flood.
	Category			Emergent Type C	
	For Evaluation Score	Bund Damage		3	Seepage was observed.
		Bund Dimension	Bund Height	1	Free board height is 5.1 feet.
			Bund Width	0	The soil cover thickness over HGL exceeds the guideline value (Soil Depth \geq 2 feet)
			Flood Plain Length	0	Floodplain length is about 15900 feet.
	Quality Score			4/9	

Note) HGL: hydraulic gradient line

Minchin Flood Bund RD 105+000

Creation Date: 30/3/2024









Province	Zone	Division	Circle
Punjab	Bahawalpur Zone	Punjnad Headworks Division	Punjnad Canal Circle
Sr. No.	River Name	River System	Bank
P-002	Indus River	Indus River	Left
Bund Name		R.D.	GPS Coordinates
Minchin Flood Bund		RD 105+000 - 122 +000	29°07'38.33"N, 70°74'83.33"E
Name of Vulnerable Point	REACH RD: 105+000 - 122 +000		
Reason for the Vulnerability	<ul style="list-style-type: none"> During flood 2010, the backwater of river Indus impacted the Minchin Bund RD: 122+000 to 60+000, causing seepages at different locations, which were managed and protected by providing earthen backfill (pushta). 		
Flow Condition ¹	<ul style="list-style-type: none"> There is no flow at this location because the river has changed its direction away from the bund. River is approximately 4 km away from the said reach. 		
Site Condition in the Country Side ²	<ul style="list-style-type: none"> Cultivated areas and human settlements are located on the countryside side of the bund. 		
Layout Plan (Source of Satellite Image: Google Earth)			
Evaluation ³			
Category	Quality Score		
Proactive Type C	2/9		





¹ Water Flow Direction and Conditions During Floods Around the Listed Vulnerable Points



² Site Condition Around the Vulnerable Points (Rough Distance Between Main Water Channel and the Bund, Land Use Behind the Point, Important Facility Adjacent to the Point)

³ Emergent Type R: Emergent Phase Requiring Robust Countermeasures, Emergent Type C: Emergent Phase Requiring Common Countermeasures, Proactive Type R: Proactive Phase Requiring Robust Countermeasures, Proactive Type C: Proactive Phase Requiring Common Countermeasures, Monitoring: Monitoring Phase

Basic Information of the Bund														
Basic Dimensions and Materials	Item	Existing	Proposed											
	Top Elevation	326.8 feet.	Not Applicable											
	H.F. L	320.57 feet												
	Free Board Height	6.23 feet												
	Top Width	40 ft. with back dowel bund												
	River Side Slope	1:3												
	Country Side Slope	1:2												
	Longitudinal Length	1000 feet.												
	Slope Protection Material	Earthen (Silty clay)												
	Covering Material/ Pavement on the Top	Earthen (Silty clay)												
	Embankment Material	Earthen (Silty clay)												
	Ancillary Structure (Drainage Ditch, and Spurs)	No												
Typical Cross Section	<p>PREVENTING EROSION OF RIVER INDUS ALONG MINCHIN FLOOD BUND RD 6+700 TO RD 122+000 (TAUNSA GUDDU REACH D/S PANJNAD HEADWORKS)</p> <p><u>MINCHIN FLOOD BUND</u></p> <p><u>X-SECTION AT RD:110+000</u></p>													
	<p>History of Damages</p> <table border="1"> <thead> <tr> <th>MM/YYYY</th> <th>Type of Damage</th> <th>Description</th> </tr> </thead> <tbody> <tr> <td></td> <td>Nil</td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> </tr> </tbody> </table>			MM/YYYY	Type of Damage	Description		Nil						
MM/YYYY	Type of Damage	Description												
	Nil													
Record of Rehabilitation/ Improvement														
MM/YYYY	Project Name with its Description	Cost	Source of Funding											
	Nil													
Plan for Rehabilitation/ Improvement														
MM/YYYY	Project Name with its Description	Cost	Source of Funding											
	Preventing erosion of River Indus along Minchin Flood Bund Rd 6+700 to Rd 122+000 (Taunsa-Guddu Reach D/S Panjnad Headworks)	Rs. 669.77 Million	ADB											

Site Photo		
Vulnerable Section	General View of River Side	
	Facing Downstream and Side	Facing Upstream Side
		
	General View of Top	
	Facing Downstream and Side	Facing Upstream Side
		
	General View of Landside	
	Facing Downstream and Side	Facing Upstream Side
		
	Close View of Deformation	
Not Applicable		
Close View of Damages		
Not Applicable		
Photo with 360° angles		
Typical Section (Adjacent to the Vulnerable Point)	General View of River Side	
	Facing Downstream and Side	Facing Upstream Side
		

	General View of Top	
	Facing Downstream and Side 	Facing Upstream Side 
	General View of Landside	
	Facing Downstream and Side 	Facing Upstream Side 
	360 Degrees Photo	
Downstream End of the Bund	General View (Not Available)	
	Photo with 360 ⁰ angles (Not Available)	
Upstream End of the Bund	General View (In the case that the VP is located near the end) (Not Applicable)	
	Photo with 360 ⁰ angles (Not Applicable)	

Observation Record ⁴ (Current status, effect of countermeasure, development of erosion, deformation, and deterioration)			
DD/MM/YYYY	Inspection Type	Description and Photo	Damage ⁵
03/3/2024	Visual Inspection	<ul style="list-style-type: none"> • A metaled road runs along the top of the bund. • Natural surface level is approximately 15 feet below the top of the bund. • Cultivated areas are present on both side of the bund.  <p>29.07386, 70.74961, 281.2ft 16/03/2024 05:02:47 PM</p> <p>Metaled road on top of the bund</p>  <p>29.05354, 70.73278, 295.8ft 16/03/2024 04:47:55 PM</p> <p>Cropped area on either side of the bund</p>	A

⁴ Current Status, Effect of the Existing Structural Countermeasure Such As Spurs/studs, Sheet Piles for Seepage Control etc and Development of Erosion, Deformation, Deterioration of the Existing Bund

⁵ a: No Deformation, b: No deformations are observed on the bund body, except for gully erosion caused by raindrops or the detachment of the bund's stone pitching, c: The bund or the apron has been damaged, and L: Leakage from the bund has been identified

Evaluation Process					
DD/MM/YYYY	Item		Result	Reason	
	Criteria For Evaluation Flow	Flood Damage		Yes	The inundation analysis indicates that the flood damage is severe
		Bund Damage		NO	There is no significant damage at present.
		Bund Dimension	Bund Height	Fail	Free board height is 6.2 feet.
			Bund Width	Fail	The HGL isn't exposed above the ground, but the soil cover thickness over HGL is less than the guideline value (2 feet > Soil Depth \geq 0 feet).
			Flood Plain Length	Pass	Floodplain length is about 13,000 feet.
		Topographic Feature	Breach Record	No	There is no breach record.
			Flow Impact	NO	It hasn't been affected by strong water flow since before 2010 flood.
	Category			Proactive Type C	
	For Evaluation Score	Bund Damage		0	There is no significant damage at present.
		Bund Dimension	Bund Height	1	Free board height is 6.2 feet.
			Bund Width	1	The HGL isn't exposed above the ground, but the soil cover thickness over HGL is less than the guideline value (2 feet > Soil Depth \geq 0 feet).
			Flood Plain Length	0	Floodplain length is about 13000 feet.
		Quality Score			2/9

Note) HGL: hydraulic gradient line

Minchin Flood Bund RD 207+000 (Ahmad Kuddan)

Creation Date: 02/3/2024








Province	Zone	Division	Circle
Punjab	Bahawalpur Zone	Rahim Yar Khan Canal Division	Rahim Yar Khan Canal Circle
Sr. No.	River Name	River System	Bank
P-003a	Indus River	Indus River	Left
Bund Name		R.D.	GPS Coordinates
Minchin Flood Bund		RD 206+000-224+000	28°91'2."N, 70°53'5."E
Name of Vulnerable Point	Reach RD 206+000-224+000 (Reach Ahmad Kuddan) _1		
Reason for the Vulnerability	<ul style="list-style-type: none"> The river's flow is directed toward this reach. Four studs were previously constructed in 2022, which were directly exposed to the river's erosive action. Significant erosion has been observed along the flood bund at this RD. There is proposal of providing stone pitching from RD 207+000 to RD 212+000 towards Riverside to prevent further erosion of the river. 		
Flow Condition ¹	<ul style="list-style-type: none"> Sever turbulent flow has been observed along the flood bund. 		
Site Condition in the Country Side ²	<ul style="list-style-type: none"> 5/R Chahchran Disty. is observed towards the country side of the above said reach. Cultivatwed area observed beyond the Disty. Which 22 feet. beneath the top level of the said reach. 		
Layout Plan (Source of Satellite Image: Google Earth)			
Evaluation ³			
Category	Quality Score		
Emergent Type C	5/9		

¹ Water Flow Direction and Conditions During Floods Around the Listed Vulnerable Points




² Site Condition Around the Vulnerable Points (Rough Distance Between Main Water Channel and the Bund, Land Use Behind the Point, Important Facility Adjacent to the Point)




³ Emergent Type R: Emergent Phase Requiring Robust Countermeasures , Emergent Type C: Emergent Phase Requiring Common Countermeasures, Proactive Type R: Proactive Phase Requiring Robust Countermeasures, Proactive Type C: Proactive Phase Requiring Common Countermeasures, Monitoring: Monitoring Phase

Basic Information of the Bund			
Basic Dimensions and Materials	Item	Existing	Proposed
	Top Elevation	317.23 feet	Not Applicable
	H.F. L	307.48 feet	
	Free Board Height	9.75 feet	
	Top Width	30 feet	
	River Side Slope	1:3	
	Country Side Slope	1:2	
	Longitudinal Length	1000 feet	
	Slope Protection Material	Earthen (clay)	
	Covering Material/ Pavement on the Top	Earthen (clay)	
	Embankment Material	Earthen (clay)	
Ancillary Structure (Drainage Ditch, and Spurs)	No		
Typical Cross Section			
History of Damages			
MM/YYYY	Type of Damage	Description	
2021	River side slop damaged	Slope damaged due to erosion of the river	
Record of Rehabilitation/ Improvement			
MM/YYYY	Project Name with its Description	Cost	Source of Funding
2022	4 No. studs constructed	Not provided by field staff	Maintenance and repair work by the PID
Plan for Rehabilitation/ Improvement			
MM/YYYY	Project Name with its Description	Cost	Source of Funding
	Nil		

Site Photo		
Vulnerable Section	General View of River Side	
	Facing Downstream and Side	Facing Upstream Side
		
	General View of Top	
	Facing Downstream and Side	Facing Upstream Side
		
	General View of Landside	
	Facing Downstream and Side	Facing Upstream Side
		
	Close View of Deformation	
		

	<p>Close View of Damages</p> 	
	<p>Photo with 360° angles</p> 	
<p>Typical Section (Adjacent to the Vulnerable Point)</p>	<p>General View of River Side</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
	<p>General View of Top</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 

	General View of Landside	
	Facing Downstream and Side 	Facing Upstream Side 
	Photo with 360° angles 	
Downstream End of the Bund	General View (Not Applicable)	
	Photo with 360° angles (Not Applicable)	
Upstream End of the Bund	General View (In the case that the VP is located near the end) (Not Applicable)	
	Photo with 360° angles (Not Applicable)	

Observation Record ⁴ (Current status, effect of countermeasure, development of erosion, deformation, and deterioration)			
DD/MM/YYYY	Inspection Type	Description and Photo	Damage ⁵
02/3/2024	Visual Inspection	<ul style="list-style-type: none"> • Extreme erosion has been observed along the flood bund at this RD. • Top level is bumpy and uneven. • 5/R Chahchran Disty. is observed towards the country side of the said RD. • Cultivated area has been observed beyond the Disty. Which 22 feet. beneath the top level of the said reach.  <p>Extreme erosive action</p>  <p>5/R Chahchran Disty. is observed towards the country side</p>  <p>Cropped area observed beyond the Disty.</p>	c

⁴ Current Status, Effect of the Existing Structural Countermeasure Such As Spurs/studs, Sheet Piles for Seepage Control etc and Development of Erosion, Deformation, Deterioration of the Existing Bund

⁵ a: No Deformation, b: No deformations are observed on the bund body, except for gully erosion caused by raindrops or the detachment of the bund's stone pitching, c: The bund or the apron has been damaged, and L: Leakage from the bund has been identified

Evaluation Process					
DD/MM/YYYY	Item		Result	Reason	
	Criteria For Evaluation Flow	Flood Damage		Yes	The inundation analysis indicates that the flood damage is severe
		Bund Damage		YES	The bund body is currently damaged.
		Bund Dimension	Bund Height	Pass	Free board height is 9.8 feet.
			Bund Width	Pass	The soil cover thickness over HGL exceeds the guideline value (Soil Depth \geq 2 feet)
			Flood Plain Length	Fail	The river touch the bund
		Topographic Feature	Breach Record	No	There is no breach record.
			Flow Impact	NO	It hasn't been affected by strong water flow since before 2010 flood.
	Category			Emergent Type C	
	For Evaluation Score	Bund Damage		3	The bund body is currently damaged.
		Bund Dimension	Bund Height	0	Free board height is 9.8 feet.
			Bund Width	0	The soil cover thickness over HGL exceeds the guideline value (Soil Depth \geq 2 feet)
			Flood Plain Length	2	The river touches the bund
	Quality Score			5/9	

Note) HGL: hydraulic gradient line

Minchin Flood Bund RD 214+000 (Ahmad Kuddan)

Creation Date: 02/3/2024

Province	Zone	Division	Circle
Punjab	Bahawalpur Zone	Rahim Yar Khan Canal Division	Rahim Yar Khan Canal Circle
Sr. No.	River Name	River System	Bank
P-003b	Indus River	Indus River	Left
Bund Name		R.D.	GPS Coordinates
Minchin Flood Bund		RD 206+000-224+000	28°89'83.33"N, 70°52'.E
Name of Vulnerable Point	Reach RD 206+000-224+000 (Reach Ahmad Kuddan) _2		
Reason for the Vulnerability	<ul style="list-style-type: none"> The said reach was previously vulnerable as the river's flow was directed towards the bund. However, after construction of J head spur, now river has shifted approximately 2 km away from the bund. 		
Flow Condition ¹	<ul style="list-style-type: none"> Small creek / standing water, and populated areas observed on the riverside of the newly constructed J head spur and the bund. 		
Site Condition in the Country Side ²	<ul style="list-style-type: none"> River bed is present on the both sides of the J head spur. On the country side areas of the bund, there is cultivated lands and dense population 		
Layout Plan (Source of Satellite Image: Google Earth)			
Evaluation ³			
Category		Quality Score	
Proactive Type C		2/9	

¹ Water Flow Direction and Conditions During Floods Around the Listed Vulnerable Points


² Site Condition Around the Vulnerable Points (Rough Distance Between Main Water Channel and the Bund, Land Use Behind the Point, Important Facility Adjacent to the Point)



³ Emergent Type R: Emergent Phase Requiring Robust Countermeasures, Emergent Type C: Emergent Phase Requiring Common Countermeasures, Proactive Type R: Proactive Phase Requiring Robust Countermeasures, Proactive Type C: Proactive Phase Requiring Common Countermeasures, Monitoring: Monitoring Phase

Basic Information of the Bund			
Basic Dimensions and Materials	Item	Existing	Proposed
	Top Elevation	317.23 feet	Not Applicable
	H.F. L	306.50 feet	
	Free Board Height	10.73 feet	
	Top Width	30 feet	
	River Side Slope	1:2	
	Country Side Slope	1:2	
	Longitudinal Length	3087 feet	
	Slope Protection Material	Stone pitched on river side and 150 feet. stone pitched on the downstream side	
	Covering Material/ Pavement on the Top	Shingle and reserve stock of stones	
Embankment Material	Earthen (clay)		
Ancillary Structure (Drainage Ditch, and Spurs)	No		
Typical Cross Section	<p align="center"><u>PROTECTION OF IRRIGATION INFRASTRUCTURES AND ABADIES BETWEEN RD 206-224 OF MINCHIN FLOOD BUND NEAR AHMAD KUDAN.</u></p> <p align="center"><u>X-SECTION AT RD 1+955 OF J-HEAD SPUR RD214+000 OF MINCHIN FLOOD BUND .</u></p>		
	History of Damages		
MM/YYYY	Type of Damage	Description	
Record of Rehabilitation/ Improvement			
MM/YYYY	Project Name with its Description	Cost	Source of Funding
2024	A J-head spur was proposed and is under construction for the Minchin flood bund and allied irrigation infrastructure, with a reserve stock of stones on top of the spur remaining at the time of the inspection.	1210 M	Annual Development Program (ADP)
Plan for Rehabilitation/ Improvement			
MM/YYYY	Project Name with its Description	Cost	Source of Funding
	Nil		

Site Photo		
Vulnerable Section	General View of River Side	
	Facing Downstream and Side	Facing Upstream Side
		
	General View of Top	
	Facing Downstream and Side	Facing Upstream Side
		
	General View of Landside	
	Facing Downstream and Side	Facing Upstream Side
		
	Close View of Deformation	
(Not Available)		
Close View of Damages		
(Not Available)		

	<p>Photo with 360° angles</p> 	
<p>Typical Section (Adjacent to the Vulnerable Point)</p>	<p>General View of River Side</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
	<p>General View of Top</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
	<p>General View of Landside</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 

	<p>Photo with 360° angles</p> 
<p>Downstream End of the Bund</p>	<p>General View</p> <p>(Not Applicable)</p>
	<p>Photo with 360° angles</p> <p>(Not Applicable)</p>
<p>Upstream End of the Bund</p>	<p>General View (In the case that the VP is located near the end)</p> <p>(Not Applicable)</p>
	<p>Photo with 360° angles</p> <p>(Not Applicable)</p>

Observation Record ⁴ (Current status, effect of countermeasure, development of erosion, deformation, and deterioration)			
DD/MM/YYYY	Inspection Type	Description and Photo	Damage ⁵
02/3/2024	Visual Inspection	<ul style="list-style-type: none"> • Small creeks / standing waters have been observed along the said reach. • At this RD, 5/R distributary (Small canal) is flowing along the country side.  <p>Small creek / standing water observed along the said reach</p>  <p>5/R distributary (Small canal) is flowing along the country side</p>	a

⁴ Current Status, Effect of the Existing Structural Countermeasure Such As Spurs/studs, Sheet Piles for Seepage Control etc and Development of Erosion, Deformation, Deterioration of the Existing Bund

⁵ a: No Deformation, b: No deformations are observed on the bund body, except for gully erosion caused by raindrops or the detachment of the bund's stone pitching, c: The bund or the apron has been damaged, and L: Leakage from the bund has been identified

Evaluation Process					
DD/MM/YYYY	Item		Result	Reason	
	Criteria For Evaluation Flow	Flood Damage		Yes	The inundation analysis indicates that the flood damage is severe
		Bund Damage		NO	There is no significant damage at present.
		Bund Dimension	Bund Height	Pass	Free board height is 10.7 feet.
			Bund Width	Pass	The soil cover thickness over HGL exceeds the guideline value (Soil Depth \geq 2 feet)
			Flood Plain Length	Fail	The river touch the bund
		Topographic Feature	Breach Record	No	There is no breach record.
			Flow Impact	NO	It hasn't been affected by strong water flow since before 2010 flood.
	Category			Proactive Type C	
	For Evaluation Score	Bund Damage		0	There is no significant damage at present.
		Bund Dimension	Bund Height	0	Free board height is 10.7 feet.
			Bund Width	0	The soil cover thickness over HGL exceeds the guideline value (Soil Depth \geq 2 feet)
			Flood Plain Length	2	The river touch the bund
	Quality Score			2/9	


Note) HGL: hydraulic gradient line

Minchin Flood Bund RD 220+000 (Ahmad Kuddan)

Creation Date: 02/3/2024

Province	Zone	Division	Circle
Punjab	Bahawalpur Zone	Rahim Yar Khan Canal Division	Rahim Yar Khan Canal Circle
Sr. No.	River Name	River System	Bank
P-003c	Indus River	Indus River	Left
Bund Name		R.D.	GPS Coordinates
Minchin Flood Bund		RD 206+000-224+000	28°88'91.67"N, 70°51'."E
Name of Vulnerable Point	Reach RD 206+000-224+000 (Reach Ahmad Kuddan)_3		
Reason for the Vulnerability	<ul style="list-style-type: none"> River Indus was directly impacting the said reach, and that was the reason to consider it as vulnerable. As a result, the construction of the J-head spur was proposed and completed to address this issue. 		
Flow Condition ¹	<ul style="list-style-type: none"> Small creek has been observed on the riverside of the newly constructed J head spur. 		
Site Condition in the Country Side ²	<ul style="list-style-type: none"> River bed on the both sides of the J head spur. Cultivated area and dense population are observed on both side of the bund. 		

Layout Plan (Source of Satellite Image: Google Earth)



Evaluation³

Category	Quality Score
Proactive Type C	3/9

¹ Water Flow Direction and Conditions During Floods Around the Listed Vulnerable Points


² Site Condition Around the Vulnerable Points (Rough Distance Between Main Water Channel and the Bund, Land Use Behind the Point, Important Facility Adjacent to the Point)



³ Emergent Type R: Emergent Phase Requiring Robust Countermeasures, Emergent Type C: Emergent Phase Requiring Common Countermeasures, Proactive Type R: Proactive Phase Requiring Robust Countermeasures, Proactive Type C: Proactive Phase Requiring Common Countermeasures, Monitoring: Monitoring Phase

Basic Information of the Bund			
Basic Dimensions and Materials	Item	Existing	Proposed
	Top Elevation	317.23 feet.	Not Applicable
	H.F. L	305.66 feet	
	Free Board Height	11.57 feet	
	Top Width	30 feet	
	River Side Slope	1:2	
	Country Side Slope	1:2	
	Longitudinal Length	2717 feet	
	Slope Protection Material	Stone pitched on river side and 150 feet. stone pitched on the downstream side	
	Covering Material/ Pavement on the Top	Shingle and reserve stock of stones	
	Embankment Material	Earthen (clay)	
Ancillary Structure (Drainage Ditch, and Spurs)	Nil		
Typical Cross Section	<p style="text-align: center;"><u>PROTECTION OF IRRIGATION INFRASTRUCTURES AND ABADIES BETWEEN RD 206-224 OF MINCHIN FLOOD BUND NEAR AHMAD KUDAN.</u></p> <p style="text-align: center;">X-SECTION AT RD 0+300 OF INVERTED HOCKEY SPUR RD206+000 OF MINCHIN FLOOD BUND (RIVER)</p>		
	History of Damages		
MM/YYYY	Type of Damage	Description	
Record of Rehabilitation/ Improvement			
MM/YYYY	Project Name with its Description	Cost	Source of Funding
2024	To protect Basti Hayyat Muhmmad, and Basti Arshad Khan, a J-head spur was proposed and is under construction, with a stone stacking remaining at the time of inspection	1210 M	Annual Development Program (ADP)
Plan for Rehabilitation/ Improvement			
MM/YYYY	Project Name with its Description	Cost	Source of Funding
	Nil		

Site Photo		
Vulnerable Section	General View of River Side	
	Facing Downstream and Side	Facing Upstream Side
		
	General View of Top	
	Facing Downstream and Side	Facing Upstream Side
		
	General View of Landside	
	Facing Downstream and Side	Facing Upstream Side
		
	Close View of Deformation	
	(Not Applicable)	
	Close View of Damages	
(Not Applicable)		

	<p>Photo with 360° angles</p> 	
<p>Typical Section (Adjacent to the Vulnerable Point)</p>	<p>General View of River Side</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
	<p>General View of Top</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
<p>General View of Landside</p>		
<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 	

	<p>Photo with 360° angles</p> 
Downstream End of the Bund	<p>General View</p> <p>(Not Applicable)</p>
	<p>Photo with 360° angles</p> <p>(Not Applicable)</p>
Upstream End of the Bund	<p>General View (In the case that the VP is located near the end)</p> <p>(Not Applicable)</p>
	<p>Photo with 360° angles</p> <p>(Not Applicable)</p>

Observation Record ⁴ (Current status, effect of countermeasure, development of erosion, deformation, and deterioration)			
DD/MM/YYYY	Inspection Type	Description and Photo	Damage ⁵
02/3/2024	Visual Inspection	<ul style="list-style-type: none"> • Small creek are flowing along the said reach. • Reserve stock of stones was found at the top of spur.  <p>Small creek flowing along the said reach</p>  <p>Reserve stock of stones was present at the top of spur</p>	a

⁴ Current Status, Effect of the Existing Structural Countermeasure Such As Spurs/studs, Sheet Piles for Seepage Control etc and Development of Erosion, Deformation, Deterioration of the Existing Bund

⁵ a: No Deformation, b: No deformations are observed on the bund body, except for gully erosion caused by raindrops or the detachment of the bund's stone pitching, c: The bund or the apron has been damaged, and L: Leakage from the bund has been identified

Evaluation Process					
DD/MM/YYYY	Item		Result	Reason	
	Criteria For Evaluation Flow	Flood Damage		Yes	The inundation analysis indicates that the flood damage is severe
		Bund Damage		NO	There is no significant damage at present.
		Bund Dimension	Bund Height	Pass	Free board height is 11.6 feet.
			Bund Width	Fail	Evaluation is not possible based on the typical cross-section.
			Flood Plain Length	Fail	The river touch the bund
		Topographic Feature	Breach Record	No	There is no breach record.
			Flow Impact	NO	It hasn't been affected by strong water flow since before 2010 flood.
	Category			Proactive Type C	
	For Evaluation Score	Bund Damage		0	There is no significant damage at present.
		Bund Dimension	Bund Height	0	Free board height is 11.6 feet.
			Bund Width	1	Evaluation is not possible based on the typical cross-section.
			Flood Plain Length	2	The river touch the bund
	Quality Score			3/9	

Note) HGL: hydraulic gradient line

J-Head Spur Number 1 at RD 230+000

Creation Date: 2/3/2024

Province	Zone	Division	Circle
Punjab	Bahawalpur Zone	Rahim Yar Khan Canal Division	Rahim Yar Khan Canal Circle
Sr. No.	River Name	River System	Bank
P-004	Indus River	Indus River	Left
Bund Name		R.D.	GPS Coordinates
Minchin Flood Bund		RD 230+000	28°88'43.33"N, 70°47'83.33"E
Name of Vulnerable Point	J-Head Spur No. 1 at RD 230+000		
Reason for the Vulnerability	<ul style="list-style-type: none"> • River Indus is directly impacting the J-head spur. • Restoration work was in progress at the time of inspection. • River Indus is striking the nose point and stone pitching of the spur. 		
Flow Condition ¹	<ul style="list-style-type: none"> • Extreme turbulent flow observed on the riverside of the spur. • The water was flowing just below the top level of apron. 		
Site Condition in the Country Side ²	<ul style="list-style-type: none"> • Deep pit is present on the country side. The depth was measured at approximately 45 feet at the time of observation. • Cultivated area and human settlement were also observed. 		

Layout Plan (Source of Satellite Image: Google Earth)



Evaluation ³	
Category	Quality Score
Emergent Type C	4/9















¹ Water Flow Direction and Conditions During Floods Around the Listed Vulnerable Points

² Site Condition Around the Vulnerable Points (Rough Distance Between Main Water Channel and the Bund, Land Use Behind the Point, Important Facility Adjacent to the Point)



³ Emergent Type R: Emergent Phase Requiring Robust Countermeasures, Emergent Type C: Emergent Phase Requiring Common Countermeasures, Proactive Type R: Proactive Phase Requiring Robust Countermeasures, Proactive Type C: Proactive Phase Requiring Common Countermeasures, Monitoring: Monitoring Phase

Basic Information of the Bund														
Basic Dimensions and Materials	Item	Existing	Proposed											
	Top Elevation	317.23 feet	Not Applicable											
	H.F. L	304.26 feet												
	Free Board Height	12.97 feet												
	Top Width	30 feet												
	River Side Slope	1:2												
	Country Side Slope	1:2												
	Longitudinal Length	7912 feet												
	Slope Protection Material	Stone pitched												
	Covering Material/ Pavement on the Top	Earthen (Silty clay)												
Embankment Material	Earthen (Silty clay)													
Ancillary Structure (Drainage Ditch, and Spurs)	Nil													
Typical Cross Section														
	<table border="1"> <thead> <tr> <th colspan="2">DESIGN DATA</th> </tr> </thead> <tbody> <tr> <td>Top Level</td> <td>317.23</td> </tr> <tr> <td>Top Width</td> <td>30.0 ft</td> </tr> <tr> <td>Apron Level</td> <td>297.50</td> </tr> <tr> <td>Apron Width</td> <td>20.0 ft</td> </tr> <tr> <td>Side Slopes</td> <td>1:2, 1:3</td> </tr> </tbody> </table>			DESIGN DATA		Top Level	317.23	Top Width	30.0 ft	Apron Level	297.50	Apron Width	20.0 ft	Side Slopes
DESIGN DATA														
Top Level	317.23													
Top Width	30.0 ft													
Apron Level	297.50													
Apron Width	20.0 ft													
Side Slopes	1:2, 1:3													
History of Damages														
MM/YYYY	Type of Damage	Description												
2022	Apron and shank damage	970 feet of apron and shank portion damaged in 2022 flood.												
Record of Rehabilitation/ Improvement														
MM/YYYY	Project Name with its Description	Cost	Source of Funding											
2024	Restoration of apron and shank portion of J Head spur	472.352 M	Maintenance and repair works by the PID											
Plan for Rehabilitation/ Improvement														
MM/YYYY	Project Name with its description	Cost	Source of Funding											
	Nil													

Site Photo	
Vulnerable Section	General View of River Side
	Facing Downstream and Side
	
	Facing Upstream Side
	
	General View of Top
	Facing Downstream and Side
	
	Facing Upstream Side
	
	General View of Landside
	Facing Downstream and Side
	
Facing Upstream Side	
	
Close View of Deformation	
	

	<p>Close View of Damages</p> 			
	<p>Photo with 360° angles</p> 			
<p>Typical Section (Adjacent to the Vulnerable Point)</p>	<p>General View of River Side</p> <table border="1" data-bbox="408 1115 1361 1491"> <tr> <td data-bbox="408 1115 935 1491"> <p>Facing Downstream and Side</p>  </td> <td data-bbox="935 1115 1361 1491"> <p>Facing Upstream Side</p>  </td> </tr> </table>		<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 			
	<p>General View of Top</p> <table border="1" data-bbox="408 1543 1361 1971"> <tr> <td data-bbox="408 1543 935 1971"> <p>Facing Downstream and Side</p>  </td> <td data-bbox="935 1543 1361 1971"> <p>Facing Upstream Side</p>  <p>28.87435, 70.48407, 51.9m, 105°</p> </td> </tr> </table>		<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p>  <p>28.87435, 70.48407, 51.9m, 105°</p>
<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p>  <p>28.87435, 70.48407, 51.9m, 105°</p>			

	General View of Landside	
	Facing Downstream and Side 	Facing Upstream Side 
	Photo with 360° angles 	
Downstream End of the Bund	General View (Not Applicable)	
	Photo with 360° angles (Not Applicable)	
Upstream End of the Bund	General View (In the case that the VP is located near the end) (Not Applicable)	
	Photo with 360° angles (Not Applicable)	

Observation Record ⁴ (Current status, effect of countermeasure, development of erosion, deformation, and deterioration)			
DD/MM/YYYY	Inspection Type	Description and Photo	Damage ⁵
02/3/2024	Visual Inspection	<ul style="list-style-type: none"> • Deep pit was formed during 2022 flood, with a depth of 45 feet, caused by the river's erosive action. • After restoration, J-head portion again damaged at nose which disturbed the pitching too.  <p>Deep pit formed in 2022 flood with 45 feet sounding</p>  <p>Damaged nose portion</p>	c

⁴ Current Status, Effect of the Existing Structural Countermeasure Such As Spurs/studs, Sheet Piles for Seepage Control etc and Development of Erosion, Deformation, Deterioration of the Existing Bund

⁵ a: No Deformation, b: No deformations are observed on the bund body, except for gully erosion caused by raindrops or the detachment of the bund's stone pitching, c: The bund or the apron has been damaged, and L: Leakage from the bund has been identified

Evaluation Process					
DD/MM/YYYY	Item		Result	Reason	
	Criteria For Evaluation Flow	Flood Damage		Yes	The inundation analysis indicates that the flood damage is severe
		Bund Damage		YES	The bund body is currently damaged.
		Bund Dimension	Bund Height	Pass	Free board height is 13 feet.
			Bund Width	Pass	The soil cover thickness over HGL exceeds the guideline value (Soil Depth \geq 2 feet)
			Flood Plain Length	Fail	Floodplain length is about 200 feet.
		Topographic Feature	Breach Record	No	There is no breach record.
			Flow Impact	NO	It hasn't been affected by strong water flow since before 2010 flood.
	Category			Emergent Type C	
	For Evaluation Score	Bund Damage		3	The bund body is currently damaged.
		Bund Dimension	Bund Height	0	Free board height is 13 feet.
			Bund Width	0	The soil cover thickness over HGL exceeds the guideline value (Soil Depth \geq 2 feet)
			Flood Plain Length	1	Floodplain length is about 200 feet.
	Quality Score			4/9	

Note) HGL: hydraulic gradient line

Extension Minchin Flood Bund RD 465+500

Creation Date: 03/1/2024

Province	Zone	Division	Circle
Punjab	Bahawalpur Zone	Dalas Canal Division	Rahim Yar Khan Canal Circle
Sr. No.	River Name	River System	Bank
P-005a	Indus River	Indus River	Left
Bund Name		R.D.	GPS Coordinates
Extension Minch in Flood Bund		RD: 458+000-465+000 & RD: 450-453	28°53'28.33"N, 69°96'33.33"E
Name of Vulnerable Point	RD: 458+000-465+000 & RD: 450-453 of Extension Minchin Flood Bund 1		
Reason for the Vulnerability	<ul style="list-style-type: none"> • There are 5 hockey studs and solid stone studs at RD 463 +800, RD 463+000, RD 462+500, RD 462+000 and RD 460 +500 respectively. • These structures caused the river to drift approximately 200 feet away from the bund; however, it shifted downstream at RD 466+000, causing damage to the bund. 		
Flow Condition ¹	<ul style="list-style-type: none"> • Extreme turbulent flow approximately 200 feet away from the bund along the allied above said structures. 		
Site Condition in the Country Side ²	Cultivated area was found towards country side.		
Layout Plan (Source of Satellite Image: Google Earth)			
Evaluation ³			
Category		Quality Score	
Proactive Type R		3/9	



¹ Water Flow Direction and Conditions During Floods Around the Listed Vulnerable Points




² Site Condition Around the Vulnerable Points (Rough Distance Between Main Water Channel and the Bund, Land Use Behind the Point, Important Facility Adjacent to the Point)

³ Emergent Type R: Emergent Phase Requiring Robust Countermeasures , Emergent Type C: Emergent Phase Requiring Common Countermeasures, Proactive Type R: Proactive Phase Requiring Robust Countermeasures, Proactive Type C: Proactive Phase Requiring Common Countermeasures, Monitoring: Monitoring Phase

Basic Information of the Bund			
Basic Dimensions and Materials	Item	Existing	Proposed
	Top Elevation	281.14 feet	Not Applicable
	H.F. L	274.83 feet	
	Free Board Height	6.31 feet	
	Top Width	25 feet	
	River Side Slope	1:2	
	Country Side Slope	1:3	
	Longitudinal Length	1000 feet	
	Slope Protection Material	Earthen (clay)	
	Covering Material/ Pavement on the Top	Earthen (clay)	
	Embankment Material	Earthen (clay)	
	Ancillary Structure (Drainage Ditch, and Spurs)	Nil	
Typical Cross Section	<p style="text-align: center;">X-SECTION AT RD: 465500 OF EXTENSION MINCHEN BUND</p>		
History of Damages			
MM/YYYY	Type of Damage	Description	
	Nil		
Record of Rehabilitation/ Improvement			
MM/YYYY	Project Name with its Description	Cost	Source of Funding
	Nil		
Plan for Rehabilitation/ Improvement			
MM/YYYY	Project Name with its Description	Cost	Source of Funding
	Nil		

Site Photo			
Vulnerable Section	<p data-bbox="475 185 790 219">General View of River Side</p> <table border="1" data-bbox="475 219 1361 595"> <tr> <td data-bbox="475 219 911 595"> <p data-bbox="475 219 810 253">Facing Downstream and Side</p>  </td> <td data-bbox="911 219 1361 595"> <p data-bbox="927 219 1182 253">Facing Upstream Side</p>  </td> </tr> </table>	<p data-bbox="475 219 810 253">Facing Downstream and Side</p> 	<p data-bbox="927 219 1182 253">Facing Upstream Side</p> 
	<p data-bbox="475 219 810 253">Facing Downstream and Side</p> 	<p data-bbox="927 219 1182 253">Facing Upstream Side</p> 	
<p data-bbox="475 595 715 629">General View of Top</p> <table border="1" data-bbox="475 629 1361 1005"> <tr> <td data-bbox="475 629 911 1005"> <p data-bbox="475 629 810 663">Facing Downstream and Side</p>  </td> <td data-bbox="911 629 1361 1005"> <p data-bbox="927 629 1182 663">Facing Upstream Side</p>  </td> </tr> </table>	<p data-bbox="475 629 810 663">Facing Downstream and Side</p> 	<p data-bbox="927 629 1182 663">Facing Upstream Side</p> 	
<p data-bbox="475 629 810 663">Facing Downstream and Side</p> 	<p data-bbox="927 629 1182 663">Facing Upstream Side</p> 		
<p data-bbox="475 1005 778 1039">General View of Landside</p> <table border="1" data-bbox="475 1039 1361 1417"> <tr> <td data-bbox="475 1039 911 1417"> <p data-bbox="475 1039 810 1072">Facing Downstream and Side</p>  </td> <td data-bbox="911 1039 1361 1417"> <p data-bbox="927 1039 1182 1072">Facing Upstream Side</p>  </td> </tr> </table>	<p data-bbox="475 1039 810 1072">Facing Downstream and Side</p> 	<p data-bbox="927 1039 1182 1072">Facing Upstream Side</p> 	
<p data-bbox="475 1039 810 1072">Facing Downstream and Side</p> 	<p data-bbox="927 1039 1182 1072">Facing Upstream Side</p> 		
<p data-bbox="475 1417 794 1451">Close View of Deformation</p> 			

	<p>Close View of Damages</p>  <p>Erosive action 200 feet away from bund inside the river bed</p>	
	<p>Photo with 360° angles</p> 	
<p>Typical Section (Adjacent to the Vulnerable Point)</p>	<p>General View of River Side</p>	
	<p>Facing Downstream and Side (photography was restricted due to security reasons)</p>	<p>Facing Upstream Side (photography was restricted due to security reasons)</p>
	<p>General View of Top</p>	
	<p>Facing Downstream and Side (photography was restricted due to security reasons)</p>	<p>Facing Upstream Side (photography was restricted due to security reasons)</p>
	<p>General View of Landside</p>	
	<p>Facing Downstream and Side (photography was restricted due to security reasons)</p>	<p>Facing Upstream Side (photography was restricted due to security reasons)</p>
<p>Downstream End of the Bund</p>	<p>General View (Not Applicable)</p>	
	<p>Photo with 360° angles (Not Available)</p>	
<p>Upstream End of the Bund</p>	<p>General View (In the case that the VP is located near the end) (Not Applicable)</p>	
	<p>Photo with 360° angles (Not Applicable)</p>	

Observation Record ⁴ (Current status, effect of countermeasure, development of erosion, deformation, and deterioration)			
DD/MM/YYYY	Inspection Type	Description and Photo	Damage ⁵
03/1/2024	Visual Inspection	<ul style="list-style-type: none"> • Continuous Erosion was observed along the allied river training structures. • Top level is bumpy and uneven. • Natural surface level is 15 feet below the top level. • Cultivated area was found towards country side. • Stone dumped at this reach for the restoration works at RD 466+000.  <p>Continuous Erosion observed along the allied river training structures</p>  <p>Cropped area towards country side</p>  <p>Stone dumped at this reach for the restoration works</p>	a

⁴ Current Status, Effect of the Existing Structural Countermeasure Such As Spurs/studs, Sheet Piles for Seepage Control etc and Development of Erosion, Deformation, Deterioration of the Existing Bund

⁵ a: No Deformation, b: No deformations are observed on the bund body, except for gully erosion caused by raindrops or the detachment of the bund's stone pitching, c: The bund or the apron has been damaged, and L: Leakage from the bund has been identified

Evaluation Process					
DD/MM/YYYY	Item		Result	Reason	
	Criteria For Evaluation Flow	Flood Damage		Yes	The inundation analysis indicates that the flood damage is severe
		Bund Damage		NO	There is no significant damage at present.
		Bund Dimension	Bund Height	Fail	Free board height is 6.3 feet.
			Bund Width	Pass	The soil cover thickness over HGL exceeds the guideline value (Soil Depth \geq 2 feet)
			Flood Plain Length	Fail	The river touch the bund
		Topographic Feature	Breach Record	No	There is no breach record.
			Flow Impact	YES	It's been affected by strong water flow since before 2010 flood.
	Category			Proactive Type R	
	For Evaluation Score	Bund Damage		0	There is no significant damage at present.
		Bund Dimension	Bund Height	1	Free board height is 6.3 feet.
			Bund Width	0	The soil cover thickness over HGL exceeds the guideline value (Soil Depth \geq 2 feet)
			Flood Plain Length	2	The river touch the bund
	Quality Score			3/9	

Note) HGL: hydraulic gradient line

Extension Minchin Flood Bund RD 466+000

Creation Date: 03/1/2024








Province	Zone	Division	Circle
Punjab	Bahawalpur Zone	Dalas Canal Division	Rahim Yar Khan Canal Circle
Sr. No.	River Name	River System	Bank
P-005b	Indus River	Indus River	Left
Bund Name		R.D.	GPS Coordinates
Extension Minchin Flood Bund		RD: 458+000-465+000 & RD: 450-453	28°53'16.67"N, 69°95'83.33"E
Name of Vulnerable Point	RD: 458+000-465+000 & RD: 450-453 of Extension Minchin Flood Bund_2		
Reason for the Vulnerability	<ul style="list-style-type: none"> River drifted rapidly towards this reach, prompting an emergency was declared on December 23, 2023, with work started on December 29, 2023. There is severe erosive action in this reach. 		
Flow Condition ¹	<ul style="list-style-type: none"> Extreme turbulent flow along the bund in the immediate vicinity in this reach. 		
Site Condition in the Country Side ²	Cultivated area was found towards country side.		
Layout Plan (Source of Satellite Image: Google Earth)			
Evaluation ³			
Category	Quality Score		
Emergent Type R	5/9		



¹ Water Flow Direction and Conditions During Floods Around the Listed Vulnerable Points


² Site Condition Around the Vulnerable Points (Rough Distance Between Main Water Channel and the Bund, Land Use Behind the Point, Important Facility Adjacent to the Point)

³ Emergent Type R: Emergent Phase Requiring Robust Countermeasures, Emergent Type C: Emergent Phase Requiring Common Countermeasures, Proactive Type R: Proactive Phase Requiring Robust Countermeasures, Proactive Type C: Proactive Phase Requiring Common Countermeasures, Monitoring: Monitoring Phase

Basic Information of the Bund											
Basic Dimensions and Materials	Item	Existing	Proposed								
	Top Elevation	282.0 feet	Not Applicable								
	H.F. L	274.83 feet									
	Free Board Height	7.17 feet									
	Top Width	28.00 feet									
	River Side Slope	1:2									
	Country Side Slope	1:3									
	Longitudinal Length	1000 feet									
	Slope Protection Material	Earthen (clay)									
	Covering Material/ Pavement on the Top	Earthen (clay)									
	Embankment Material	Earthen (clay)									
	Ancillary Structure (Drainage Ditch, and Spurs)	No									
Typical Cross Section	<p style="text-align: center;">X-SECTION AT RD: 466000 OF EXTENSION MINCHEN BUND</p>										
	<p style="text-align: center;">History of Damages</p> <table border="1"> <thead> <tr> <th>MM/YYYY</th> <th>Type of Damage</th> <th>Description</th> </tr> </thead> <tbody> <tr> <td>12/2023</td> <td>Erosive action at the bund</td> <td>There is severe erosive action in this reach at the time of visit</td> </tr> <tr> <td> </td> <td> </td> <td> </td> </tr> </tbody> </table>			MM/YYYY	Type of Damage	Description	12/2023	Erosive action at the bund	There is severe erosive action in this reach at the time of visit		
MM/YYYY	Type of Damage	Description									
12/2023	Erosive action at the bund	There is severe erosive action in this reach at the time of visit									
Record of Rehabilitation/ Improvement											
MM/YYYY	Project Name with its Description	Cost	Source of Funding								
12/2023	Providing 3 solid stone studs in this reach to avoid erosion on the bund	79 M	Maintenance and repair works by the PID								
Plan for Rehabilitation/ Improvement											
MM/YYYY	Project Name with its Description	Cost	Source of Funding								
	In progress										

Site Photo		
Vulnerable Section	<p>General View of River Side</p> <p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
	<p>General View of Top</p> <p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
	<p>General View of Landside</p> <p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
	<p>Close View of Deformation</p> 	

	<p>Close View of Damages</p> 	
	<p>Photo with 360° angles</p> 	
<p>Typical Section (Adjacent to the Vulnerable Point)</p>	<p>General View of River Side</p>	
	<p>Facing Downstream and Side (photography was restricted due to security reasons)</p>	<p>Facing Upstream Side (photography was restricted due to security reasons)</p>
	<p>General View of Top</p>	
	<p>Facing Downstream and Side (photography was restricted due to security reasons)</p>	<p>Facing Upstream Side (photography was restricted due to security reasons)</p>
	<p>General View of Landside</p>	
	<p>Facing Downstream and Side (photography was restricted due to security reasons)</p>	<p>Facing Upstream Side (photography was restricted due to security reasons)</p>
	<p>Photo with 360° angles (photography was restricted due to security reasons)</p>	
<p>Downstream End of the Bund</p>	<p>General View (Not Applicable)</p>	
	<p>Photo with 360° angles (Not Available)</p>	
<p>Upstream End of the Bund</p>	<p>General View (In the case that the VP is located near the end) (Not Applicable)</p>	
	<p>Photo with 360° angles (Not Applicable)</p>	

Observation Record ⁴ (Current status, effect of countermeasure, development of erosion, deformation, and deterioration)			
DD/MM/YYYY	Inspection Type	Description and Photo	Damage ⁵
03/1/2024	Visual Inspection	<ul style="list-style-type: none"> • Continuous erosion was observed along river side. • Top level is bumpy and uneven. • Natural surface level is 12 feet. below the top level.  <p>Continuous erosion observed along river side</p>	c

⁴ Current Status, Effect of the Existing Structural Countermeasure Such As Spurs/studs, Sheet Piles for Seepage Control etc and Development of Erosion, Deformation, Deterioration of the Existing Bund

⁵ a: No Deformation, b: No deformations are observed on the bund body, except for gully erosion caused by raindrops or the detachment of the bund's stone pitching, c: The bund or the apron has been damaged, and L: Leakage from the bund has been identified

Evaluation Process					
DD/MM/YYYY	Item		Result	Reason	
	Criteria For Evaluation Flow	Flood Damage		Yes	The inundation analysis indicates that the flood damage is severe
		Bund Damage		YES	The bund body is currently damaged.
		Bund Dimension	Bund Height	Pass	Free board height is 7.2 feet.
			Bund Width	Pass	The soil cover thickness over HGL exceeds the guideline value (Soil Depth \geq 2 feet)
			Flood Plain Length	Fail	The river touch the bund
		Topographic Feature	Breach Record	No	There is no breach record.
			Flow Impact	YES	It's been affected by strong water flow since before 2010 flood.
	Category			Emergent Type R	
	For Evaluation Score	Bund Damage		3	The bund body is currently damaged.
		Bund Dimension	Bund Height	0	Free board height is 7.2 feet.
			Bund Width	0	The soil cover thickness over HGL exceeds the guideline value (Soil Depth \geq 2 feet)
			Flood Plain Length	2	The river touch the bund
	Quality Score			5/9	


Note) HGL: hydraulic gradient line

Extension Minchin Flood Bund RD 467+000 and RD 468 +000

Creation Date: 03/1/2024

Province	Zone	Division	Circle
Punjab	Bahawalpur Zone	Dalas Canal Division	Rahim Yar Khan Canal Circle
Sr. No.	River Name	River System	Bank
P-005c	Indus River	Indus River	Left
Bund Name		R.D.	GPS Coordinates
Extension Minchin Flood Bund		RD 458+000 to 465+000 and RD 450 to 453	28°53'06.67"N, 69°95'66.67"E
Name of Vulnerable Point	RD 458+000 to 465+000 and RD 450 to 453 of Extension Minchin Flood Bund_3		
Reason for the Vulnerability	<ul style="list-style-type: none"> River drifted towards this reach, now flowing just 100 feet away from the bund, which is the major cause of vulnerability. 		
Flow Condition ¹	<ul style="list-style-type: none"> Extreme turbulent flow along the bund 100 feet away from the bund in this reach. 		
Site Condition in the Country Side ²	<ul style="list-style-type: none"> Cropped area towards country side. 		

Layout Plan (Source of Satellite Image: Google Earth)



Evaluation³

Category	Quality Score
Proactive Type R	2/9

¹ Water Flow Direction and Conditions During Floods Around the Listed Vulnerable Points.



² Site Condition Around the Vulnerable Points (Rough Distance Between Main Water Channel and the Bund, Land Use Behind the Point, Important Facility Adjacent to the Point).

³ Emergent Type R: Emergent Phase Requiring Robust Countermeasures, Emergent Type C: Emergent Phase Requiring Common Countermeasures, Proactive Type R: Proactive Phase Requiring Robust Countermeasures, Proactive Type C: Proactive Phase Requiring Common Countermeasures, Monitoring: Monitoring Phase

Basic Information of the Bund																			
Basic Dimensions and Materials	Item	Existing	Proposed																
	Top Elevation	281.69 feet	Not Applicable —																
	H.F.L	274.83 feet																	
	Free Board Height	6.86 feet																	
	Top Width	25 feet																	
	River Side Slope	1:2																	
	Country Side Slope	1:3																	
	Longitudinal Length	1000 ft.																	
	Slope Protection Material	Earthen (Clay)																	
	Covering Material/ Pavement on the Top	Earthen (Clay)																	
	Embankment Material	Earthen (Clay)																	
Ancillary Structure (Drainage Ditch, and Spurs)	Not Applicable																		
Typical Cross Section	<p style="text-align: center;">X-SECTION AT RD: 467500 OF EXTENSION MINCHEN BUND</p>																		
	<p style="text-align: center;">History of Damages</p> <table border="1"> <thead> <tr> <th>MM/YYYY</th> <th>Type of Damage</th> <th>Description</th> </tr> </thead> <tbody> <tr> <td></td> <td>Nil</td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> </tr> </tbody> </table>			MM/YYYY	Type of Damage	Description		Nil											
MM/YYYY	Type of Damage	Description																	
	Nil																		
<p style="text-align: center;">Record of Rehabilitation/ Improvement</p> <table border="1"> <thead> <tr> <th>MM/YYYY</th> <th>Project Name and its Description</th> <th>Cost</th> <th>Source of Funding</th> </tr> </thead> <tbody> <tr> <td></td> <td>Nil</td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>				MM/YYYY	Project Name and its Description	Cost	Source of Funding		Nil										
MM/YYYY	Project Name and its Description	Cost	Source of Funding																
	Nil																		
<p style="text-align: center;">Plan for Rehabilitation/ Improvement</p> <table border="1"> <thead> <tr> <th>MM/YYYY</th> <th>Project Name and its Description</th> <th>Cost</th> <th>Source of Funding</th> </tr> </thead> <tbody> <tr> <td></td> <td>Nil</td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>				MM/YYYY	Project Name and its Description	Cost	Source of Funding		Nil										
MM/YYYY	Project Name and its Description	Cost	Source of Funding																
	Nil																		

Site Photo		
Vulnerable Section	General View of River Side	
	Facing Downstream and Side	Facing Upstream Side
		
	General View of Top	
	Facing Downstream and Side	Facing Upstream Side
		
	General View of Landside	
Facing Downstream and Side	Facing Upstream Side	
		
Close View of Deformation (Not Applicable)		
Close View of Damages (Not Applicable)		
Photo with 360° angles		
		
Typical Section (Adjacent to the Vulnerable Point)	General View of River Side	
	Facing Downstream and Side (Photographs were not permitted due to security restrictions)	Facing Downstream and Side (Photographs were not permitted due to security restrictions)

	General View of Top	
	Facing Downstream and Side (Photographs were not permitted due to security restrictions)	Facing Downstream and Side (Photographs were not permitted due to security restrictions)
	General View of Landside	
	Facing Downstream and Side (Photographs were not permitted due to security restrictions)	Facing Downstream and Side (Photographs were not permitted due to security restrictions)
	Photo with 360 ⁰ angles (Photographs were not permitted due to security restrictions)	
Downstream End of the Bund	General View (Not Applicable)	
	Photo with 360 ⁰ angles (Not Available)	
Upstream End of the Bund	General View (In the case that the VP is located near the end) (Not Applicable)	
	Photo with 360 ⁰ angles (Not Applicable)	

Observation Record ⁴ (Current status, effect of countermeasure, development of erosion, deformation, deterioration)			
DD/MM/YYYY	Inspection Type	Description and Photo	Damage ⁵
03/1/2024	Visual Inspection	<ul style="list-style-type: none"> • Continuous roasion observed along river side which was 100 feet away from the bund. • Top level is bumpy and uneven. • Natural surface level is 15 feet below the top level. • Cropped area towards country side  <p>Continuous erosion observed along river side</p>  <p>Cropped area towards country side</p>	a

⁴ Current Status, Effect of the Existing Structural Countermeasure Such as Spurs/studs, Sheet Piles for Seepage Control etc. and Development of Erosion, Deformation, Deterioration of the Existing Bund

⁵ a: No Deformation, b: No deformations are observed on the bund body, except for gully erosion caused by raindrops or the detachment of the bund's stone pitching, c: The bund or the apron has been damaged, and L: Leakage from the bund has been identified

Evaluation Process					
DD/MM/YYYY	Item		Result	Reason	
	Criteria For Evaluation Flow	Flood Damage		Yes	The inundation analysis indicates that the flood damage is severe
		Bund Damage		NO	There is no significant damage at present.
		Bund Dimension	Bund Height	Fail	Free board height is 6.9 feet.
			Bund Width	Pass	The soil cover thickness over HGL exceeds the guideline value (Soil Depth \geq 2 feet)
			Flood Plain Length	Fail	Floodplain length is about 100 feet.
		Topographic Feature	Breach Record	No	There is no breach record.
			Flow Impact	YES	It's been affected by strong water flow since before 2010 flood.
	Category			Proactive Type R	
	For Evaluation Score	Bund Damage		0	There is no significant damage at present.
		Bund Dimension	Bund Height	1	Free board height is 6.9 feet.
			Bund Width	0	The soil cover thickness over HGL exceeds the guideline value (Soil Depth \geq 2 feet)
			Flood Plain Length	1	Floodplain length is about 100 feet.
	Quality Score			2/9	

Note) HGL: hydraulic gradient line

Left Bank of Link No. 1 RD 138+000

Creation Date: 01/3/2024

Province	Zone	Division	Circle
Punjab	Dera Ghazi Khan Zone	DG Khan Construction Division	Project Circle DG Khan
Sr. No.	River Name	River System	Bank
P-006a	Indus River	Indus River	Right
Bund Name		R.D	GPS Coordinates
Left Bank of Link No. 1		RD 138+000 to 165+000 and 165+000to 194+000 1	30°01'37.38"N, 70°77'30.99"E
Name of Vulnerable Point	Left Bank of Link No. 1 RD 138+000 to 165+000 and 165+000 to194+000_1		
Reason for the Vulnerability	<ul style="list-style-type: none"> The said reach is no longer vulnerable, as the river is now 4300 feet away from the Left bank of Link Canal No. 1 at this RD. There is no history of breaching along the left bank of Link number 1 at this RD. 		
Flow Condition ¹	<ul style="list-style-type: none"> No flow conditions. River flows approximately 4300 feet away from this cross spur. 		
Site Condition in the Country Side ²	<ul style="list-style-type: none"> There is a cultivated lands and populated area along country side. 		

Layout Plan (Source of Satellite Image: Google Earth)




Evaluation³



















Category	Quality Score
Monitoring	3/9






¹ Water Flow Direction and Conditions During Floods Around the Listed Vulnerable Points


² Site Condition Around the Vulnerable Points (Rough Distance Between Main Water Channel and the Bund, Land Use Behind the Point, Important Facility Adjacent to the Point)



³ Emergent Type R: Emergent Phase Requiring Robust Countermeasures , Emergent Type C: Emergent Phase Requiring Common Countermeasures, Proactive Type R: Proactive Phase Requiring Robust Countermeasures, Proactive Type C: Proactive Phase Requiring Common Countermeasures, Monitoring: Monitoring Phase

Basic Information of the Bund																																																																												
Basic Dimensions and Materials	Item	Existing	Proposed																																																																									
	Top Elevation	401.62 feet	Not Applicable —																																																																									
	H.F. L	395 feet																																																																										
	Free Board Height	6.62 feet																																																																										
	Top Width	25 feet																																																																										
	River Side Slope	1:2																																																																										
	Country Side Slope	Left bank of link No. 1																																																																										
	Longitudinal Length	204500 feet																																																																										
	Slope Protection Material	Stone pitched on river side																																																																										
	Covering Material/ Pavement on the Top	Earthen (Clay)																																																																										
	Embankment Material	Earthen (Clay)																																																																										
Ancillary Structure (Drainage Ditch, and Spurs)	Not Applicable																																																																											
Typical Cross Section																																																																												
	<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>L BANK</th> <th>DESIGN</th> <th>AS BUILT</th> <th>R BANK</th> <th>DESIGN</th> <th>AS BUILT</th> </tr> </thead> <tbody> <tr> <td>CUT</td> <td>0</td> <td>0</td> <td>CUT</td> <td>0</td> <td>0</td> </tr> <tr> <td>FILL</td> <td>0</td> <td>0</td> <td>FILL</td> <td>0</td> <td>0</td> </tr> </tbody> </table> <table border="1" style="width: 100%; border-collapse: collapse; text-align: center;"> <tr> <td>401.63</td> <td>401.63</td> <td>401.48</td> <td>398.53</td> <td>401.42</td> <td>398.92</td> <td>398.92</td> <td>395.72</td> <td>398.19</td> <td>398.43</td> <td>391.06</td> <td>396.83</td> <td>401.42</td> <td>401.42</td> </tr> <tr> <td>401.63</td> <td>401.48</td> <td>398.53</td> <td>394.06</td> <td>398.92</td> <td>398.92</td> <td>395.72</td> <td>398.11</td> <td>398.19</td> <td>391.06</td> <td>396.83</td> <td>401.42</td> <td>401.42</td> <td>401.42</td> </tr> <tr> <td>401.63</td> <td>401.48</td> <td>398.53</td> <td>394.06</td> <td>398.92</td> <td>398.92</td> <td>395.72</td> <td>398.11</td> <td>398.19</td> <td>391.06</td> <td>396.83</td> <td>401.42</td> <td>401.42</td> <td>401.42</td> </tr> <tr> <td>401.63</td> <td>401.48</td> <td>398.53</td> <td>394.06</td> <td>398.92</td> <td>398.92</td> <td>395.72</td> <td>398.11</td> <td>398.19</td> <td>391.06</td> <td>396.83</td> <td>401.42</td> <td>401.42</td> <td>401.42</td> </tr> </table>			L BANK	DESIGN	AS BUILT	R BANK	DESIGN	AS BUILT	CUT	0	0	CUT	0	0	FILL	0	0	FILL	0	0	401.63	401.63	401.48	398.53	401.42	398.92	398.92	395.72	398.19	398.43	391.06	396.83	401.42	401.42	401.63	401.48	398.53	394.06	398.92	398.92	395.72	398.11	398.19	391.06	396.83	401.42	401.42	401.42	401.63	401.48	398.53	394.06	398.92	398.92	395.72	398.11	398.19	391.06	396.83	401.42	401.42	401.42	401.63	401.48	398.53	394.06	398.92	398.92	395.72	398.11	398.19	391.06	396.83	401.42	401.42
L BANK	DESIGN	AS BUILT	R BANK	DESIGN	AS BUILT																																																																							
CUT	0	0	CUT	0	0																																																																							
FILL	0	0	FILL	0	0																																																																							
401.63	401.63	401.48	398.53	401.42	398.92	398.92	395.72	398.19	398.43	391.06	396.83	401.42	401.42																																																															
401.63	401.48	398.53	394.06	398.92	398.92	395.72	398.11	398.19	391.06	396.83	401.42	401.42	401.42																																																															
401.63	401.48	398.53	394.06	398.92	398.92	395.72	398.11	398.19	391.06	396.83	401.42	401.42	401.42																																																															
401.63	401.48	398.53	394.06	398.92	398.92	395.72	398.11	398.19	391.06	396.83	401.42	401.42	401.42																																																															
History of Damages																																																																												
MM/YYYY	Type of Damage	Description																																																																										
	Nil																																																																											
Record of Rehabilitation/ Improvement																																																																												
MM/YYYY	Project Name with its Description	Cost	Source of Funding																																																																									
	Nil																																																																											
Plan for Rehabilitation/ Improvement																																																																												
MM/YYYY	Project Name with its Description	Cost	Source of Funding																																																																									
	Nil																																																																											

Site Photo					
Vulnerable Section	General View of River Side				
	<table border="1"> <tr> <td>Facing Downstream and Side</td> <td>Facing Upstream Side</td> </tr> <tr> <td></td> <td></td> </tr> </table>	Facing Downstream and Side	Facing Upstream Side		
	Facing Downstream and Side	Facing Upstream Side			
					
	General View of Top				
	<table border="1"> <tr> <td>Facing Downstream and Side</td> <td>Facing Upstream Side</td> </tr> <tr> <td></td> <td></td> </tr> </table>	Facing Downstream and Side	Facing Upstream Side		
	Facing Downstream and Side	Facing Upstream Side			
					
	General View of Landside				
	<table border="1"> <tr> <td>Facing Downstream and Side</td> <td>Facing Upstream Side</td> </tr> <tr> <td></td> <td></td> </tr> </table>	Facing Downstream and Side	Facing Upstream Side		
Facing Downstream and Side	Facing Upstream Side				
					
Close View of Deformation	Not Applicable				
Close View of Damages	Not Applicable				

	<p>Photo with 360° angles</p> 	
<p>Typical Section (Adjacent to the Vulnerable Point)</p>	<p>General View of River Side</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
	<p>General View of Top</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
	<p>General View of Landside</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 

	<p>Photo with 360° angles</p> 
<p>Downstream End of the Bund</p>	<p>General View</p> <p>(Not Applicable)</p>
	<p>Photo with 360° angles</p> <p>(Not Applicable)</p>
<p>Upstream End of the Bund</p>	<p>General View (In the case that the VP is located near the end)</p> <p>(Not Applicable)</p>
	<p>Photo with 360° angles</p> <p>(Not Applicable)</p>

Observation Record ⁴ (Current status, effect of countermeasure, development of erosion, deformation, and deterioration)			
DD/MM/YYYY	Inspection Type	Description and Photo	Damage ⁵
01/3/2024	Visual Inspection	<ul style="list-style-type: none"> • River is approximately 4300 feet away from the spur. • cultivated land is situated on country side and canal on the right side of the embankment.  <p>Cropped area on country side</p>  <p>Canal on the right side of the embankment</p>	a

⁴ Current Status, Effect of the Existing Structural Countermeasure Such as Spurs/studs, Sheet Piles for Seepage Control etc. and Development of Erosion, Deformation, Deterioration of the Existing Bund

⁵ a: No Deformation, b: No deformations are observed on the bund body, except for gully erosion caused by raindrops or the detachment of the bund's stone pitching, c: The bund or the apron has been damaged, and L: Leakage from the bund has been identified

Evaluation Process					
DD/MM/YYYY	Item		Result	Reason	
	Criteria For Evaluation Flow	Flood Damage		No	The inundation analysis indicates that the flood damage is not severe.
		Bund Damage		NO	There is no significant damage at present.
		Bund Dimension	Bund Height	Fail	Free board height is 6.6 feet.
			Bund Width	Fail	Evaluation is not possible based on the typical cross-section.
			Flood Plain Length	Fail	Floodplain length is about 4300 feet.
		Topographic Feature	Breach Record	No	There is no breach record.
			Flow Impact	NO	It hasn't been affected by strong water flow since before 2010 flood.
	Category			Monitoring	
	For Evaluation Score	Bund Damage		0	There is no significant damage at present.
		Bund Dimension	Bund Height	1	Free board height is 6.6 feet.
			Bund Width	1	Evaluation is not possible based on the typical cross-section.
			Flood Plain Length	1	Floodplain length is about 4300 feet.
	Quality Score			3/9	


Note) HGL: hydraulic gradient line

Left Bank of Link Number 1 RD 150+000

Creation Date: 01/3/2024

Province	Zone	Division	Circle
Punjab	Dera Ghazi Khan Zone	DG Khan Construction Division	Project Circle DG Khan
Sr. No.	River Name	River System	Bank
P-006b	Indus River	Indus River	Right
Bund Name		R.D.	GPS Coordinates
Left Bank of Link No. I		RD 138+000 to 165+000 and 165+000 to 194+000	29° 58.745 N 70° 45.681 E
Name of Vulnerable Point	Left Bank of Link No. I RD 138+000 to 165+000 and 165+000 to 194+000_2		
Reason for the Vulnerability	<ul style="list-style-type: none"> The said reach is no longer vulnerable, as the river is approximately 3300 feet. away from the Left bank of Link Canal number 1 at this RD. There is no breach history of the Left bank of Link number 1 at this RD. 		
Flow Condition ¹	<ul style="list-style-type: none"> No flow conditions. River flows approximately 3300 feet. away from this cross spur. 		
Site Condition in the Country Side ²	<ul style="list-style-type: none"> There is a cultivated land on country side. Village (Basti) bhai is situated on the right side of the Link Number 1. 		

Layout Plan (Source of Satellite Image: Google Earth)



Evaluation³





Category	Quality Score
Proactive Type C	3/9








¹ Water Flow Direction and Conditions During Floods Around the Listed Vulnerable Points.


² Site Condition Around the Vulnerable Points (Rough Distance Between Main Water Channel and the Bund, Land Use Behind the Point, Important Facility Adjacent to the Point).



³ Emergent Type R: Emergent Phase Requiring Robust Countermeasures, Emergent Type C: Emergent Phase Requiring Common Countermeasures, Proactive Type R: Proactive Phase Requiring Robust Countermeasures, Proactive Type C: Proactive Phase Requiring Common Countermeasures, Monitoring: Monitoring Phase

Basic Information of the Bund																																																																																			
Basic Dimensions and Materials	Item	Existing	Proposed																																																																																
	Top Elevation	394.92 feet	Not Applicable —																																																																																
	H.F. L	392.28 feet																																																																																	
	Free Board Height	2.64 feet																																																																																	
	Top Width	25 feet																																																																																	
	River Side Slope	1:2																																																																																	
	Country Side Slope	Left bank of link number 1																																																																																	
	Longitudinal Length	204500 feet																																																																																	
	Slope Protection Material	Earthen (Clay)																																																																																	
	Covering Material/ Pavement on the Top	Pavement on the Top																																																																																	
	Embankment Material	Earthen (Clay)																																																																																	
Ancillary Structure (Drainage Ditch, and Spurs)	Not Applicable																																																																																		
Typical Cross Section	<table border="1"> <thead> <tr> <th colspan="2">DESIGN</th> <th colspan="2">AS BUILT</th> </tr> <tr> <th>CUT</th> <th>FLL</th> <th>CUT</th> <th>FLL</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>0</td> <td>0</td> <td>0</td> </tr> <tr> <td>0</td> <td>0</td> <td>0</td> <td>0</td> </tr> </tbody> </table> <table border="1"> <thead> <tr> <th rowspan="2">STATION</th> <th colspan="2">DESIGN</th> <th colspan="2">AS BUILT</th> </tr> <tr> <th>LEVEL</th> <th>OFFSET</th> <th>LEVEL</th> <th>OFFSET</th> </tr> </thead> <tbody> <tr> <td>0+00</td> <td>394.92</td> <td>0</td> <td>394.92</td> <td>0</td> </tr> <tr> <td>0+10</td> <td>394.92</td> <td>0</td> <td>394.92</td> <td>0</td> </tr> <tr> <td>0+20</td> <td>394.92</td> <td>0</td> <td>394.92</td> <td>0</td> </tr> <tr> <td>0+30</td> <td>394.92</td> <td>0</td> <td>394.92</td> <td>0</td> </tr> <tr> <td>0+40</td> <td>394.92</td> <td>0</td> <td>394.92</td> <td>0</td> </tr> <tr> <td>0+50</td> <td>394.92</td> <td>0</td> <td>394.92</td> <td>0</td> </tr> <tr> <td>0+60</td> <td>394.92</td> <td>0</td> <td>394.92</td> <td>0</td> </tr> <tr> <td>0+70</td> <td>394.92</td> <td>0</td> <td>394.92</td> <td>0</td> </tr> <tr> <td>0+80</td> <td>394.92</td> <td>0</td> <td>394.92</td> <td>0</td> </tr> <tr> <td>0+90</td> <td>394.92</td> <td>0</td> <td>394.92</td> <td>0</td> </tr> <tr> <td>0+100</td> <td>394.92</td> <td>0</td> <td>394.92</td> <td>0</td> </tr> </tbody> </table>			DESIGN		AS BUILT		CUT	FLL	CUT	FLL	0	0	0	0	0	0	0	0	STATION	DESIGN		AS BUILT		LEVEL	OFFSET	LEVEL	OFFSET	0+00	394.92	0	394.92	0	0+10	394.92	0	394.92	0	0+20	394.92	0	394.92	0	0+30	394.92	0	394.92	0	0+40	394.92	0	394.92	0	0+50	394.92	0	394.92	0	0+60	394.92	0	394.92	0	0+70	394.92	0	394.92	0	0+80	394.92	0	394.92	0	0+90	394.92	0	394.92	0	0+100	394.92	0	394.92	0
	DESIGN		AS BUILT																																																																																
CUT	FLL	CUT	FLL																																																																																
0	0	0	0																																																																																
0	0	0	0																																																																																
STATION	DESIGN		AS BUILT																																																																																
	LEVEL	OFFSET	LEVEL	OFFSET																																																																															
0+00	394.92	0	394.92	0																																																																															
0+10	394.92	0	394.92	0																																																																															
0+20	394.92	0	394.92	0																																																																															
0+30	394.92	0	394.92	0																																																																															
0+40	394.92	0	394.92	0																																																																															
0+50	394.92	0	394.92	0																																																																															
0+60	394.92	0	394.92	0																																																																															
0+70	394.92	0	394.92	0																																																																															
0+80	394.92	0	394.92	0																																																																															
0+90	394.92	0	394.92	0																																																																															
0+100	394.92	0	394.92	0																																																																															
History of Damages																																																																																			
MM/YYYY	Type of Damage	Description																																																																																	
	Nil																																																																																		
Record of Rehabilitation/ Improvement																																																																																			
MM/YYYY	Project Name and its Description	Cost	Source of Funding																																																																																
	Nil																																																																																		
Plan for Rehabilitation/ Improvement																																																																																			
MM/YYYY	Project Name and its Description	Cost	Source of Funding																																																																																
	Nil																																																																																		

Site Photo		
Vulnerable Section	General View of River Side	
	Facing Downstream and Side	Facing Upstream Side
		
	General View of Top	
	Facing Downstream and Side	Facing Upstream Side
		
	General View of Landside	
	Facing Downstream and Side	Facing Upstream Side
		
	Close View of Deformation (Not Applicable)	
Close View of Damages (Not Applicable)		

	<p>Photo with 360° angles</p> 	
<p>Typical Section (Adjacent to the Vulnerable Point)</p>	<p>General View of River Side</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
<p>General View of Top</p>		
<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 	
<p>General View of Landside</p>		
<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 	

	<p>Photo with 360° angles</p> 
<p>Downstream End of the Bund</p>	<p>General View</p> <p>(Not Applicable)</p>
	<p>Photo with 360° angles</p> <p>(Not Applicable)</p>
<p>Upstream End of the Bund</p>	<p>General View (In the case that the VP is located near the end)</p> <p>(Not Applicable)</p>
	<p>Photo with 360° angles</p> <p>(Not Applicable)</p>

Observation Record ⁴ (Current status, effect of countermeasure, development of erosion, deformation, and deterioration)			
DD/MM/YYYY	Inspection Type	Description and Photo	Damage ⁵
01/3/2024	Visual Inspection	<ul style="list-style-type: none"> • River is approximately 3300 feet away from this RD. • Cultivated areas is situated on country side and empty canal on the right side of the embankment.  <p>Cropped area on country side</p>  <p>Empty canal on the right side of the embankment</p>	a

⁴ Current Status, Effect of the Existing Structural Countermeasure Such as Spurs/studs, Sheet Piles for Seepage Control etc. and Development of Erosion, Deformation, Deterioration of the Existing Bund

⁵ a: No Deformation, b: No deformations are observed on the bund body, except for gully erosion caused by raindrops or the detachment of the bund's stone pitching, c: The bund or the apron has been damaged, and L: Leakage from the bund has been identified

Evaluation Process					
DD/MM/YYYY	Item		Result	Reason	
	Criteria For Evaluation Flow	Flood Damage		Yes	The inundation analysis indicates that the flood damage is severe
		Bund Damage		NO	There is no significant damage at present.
		Bund Dimension	Bund Height	Fail	Free board height is 2.6 feet.
			Bund Width	Fail	Evaluation is not possible based on the typical cross-section.
			Flood Plain Length	Fail	Floodplain length is about 3,300 feet.
		Topographic Feature	Breach Record	NO	There is no breach record.
			Flow Impact	NO	It hasn't been affected by strong water flow since before 2010 flood.
	Category			Proactive Type C	
	For Evaluation Score	Bund Damage		0	There is no significant damage at present.
		Bund Dimension	Bund Height	1	Free board height is 2.6 feet.
			Bund Width	1	Evaluation is not possible based on the typical cross-section.
			Flood Plain Length	1	Floodplain length is about 3,300 feet.
	Quality Score			3/9	

Note) HGL: hydraulic gradient line

The inundation analysis indicates that the flood damage is severe

Left Bank of Link Number 1 RD 165+000

Creation Date: 01/3/2024




Province	Zone	Division	Circle
Punjab	Dera Ghazi Khan Zone	DG Khan Construction Division	Project Circle DG Khan
Sr. No.	River Name	River System	Bank
P-006c	Indus River	Indus River	Right
Bund Name		R.D.	GPS Coordinates
Left Bank of Link No. 1		RD 138+000 to 165+000 and RD 165+000 to 194+000	29°95'11.67"N, 70°74'66.67"E
Name of Vulnerable Point	Left Bank of Link No. 1 RD 138+000 to 165+000 and 165+000 to 194+000_3		
Reason for the Vulnerability	<ul style="list-style-type: none"> The said reach is no longer vulnerable, as the river is approximately 4600 feet. away from the left bank of link canal number 1 at this RD. There is no breach history of the left bank of link canal number 1 at this RD. 		
Flow Condition ¹	<ul style="list-style-type: none"> No flow conditions. River flows approximately 4600 feet. away from this cross spur. 		
Site Condition in the Country Side ²	<ul style="list-style-type: none"> There is a cropped area on country side. 		
Layout Plan (Source of Satellite Image: Google Earth)			
Evaluation ³			
Category		Quality Score	
Proactive Type C		3/9	








¹ Water Flow Direction and Conditions During Floods Around the Listed Vulnerable Points.


² Site Condition Around the Vulnerable Points (Rough Distance Between Main Water Channel and the Bund, Land Use Behind the Point, Important Facility Adjacent to the Point).



³ Emergent Type R: Emergent Phase Requiring Robust Countermeasures, Emergent Type C: Emergent Phase Requiring Common Countermeasures, Proactive Type R: Proactive Phase Requiring Robust Countermeasures, Proactive Type C: Proactive Phase Requiring Common Countermeasures, Monitoring: Monitoring Phase

Basic Information of the Bund																																																																																																																																												
Basic Dimensions and Materials	Item	Existing	Proposed																																																																																																																																									
	Top Elevation	392.22 feet	Not Applicable —																																																																																																																																									
	H.F.L	391.2 feet																																																																																																																																										
	Free Board Height	1.02 feet																																																																																																																																										
	Top Width	25 feet																																																																																																																																										
	River Side Slope	1:2																																																																																																																																										
	Country Side Slope	Left bank of Link number 1																																																																																																																																										
	Longitudinal Length	204500 feet																																																																																																																																										
	Slope Protection Material	Earthen (Clay)																																																																																																																																										
	Covering Material/ Pavement on the Top	Pavement on the top																																																																																																																																										
	Embankment Material	Earthen (Clay)																																																																																																																																										
Ancillary Structure (Drainage Ditch, and Spurs)	Not Applicable																																																																																																																																											
Typical Cross Section																																																																																																																																												
	<table border="1"> <thead> <tr> <th colspan="2">L BANK</th> <th colspan="2">DESIGN</th> <th colspan="2">AS BUILT</th> </tr> <tr> <th>CUT</th> <th>FILL</th> <th>CUT</th> <th>FILL</th> <th>CUT</th> <th>FILL</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> </tr> <tr> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> </tr> </tbody> </table> <table border="1"> <thead> <tr> <th colspan="2">R BANK</th> <th colspan="2">DESIGN</th> <th colspan="2">AS BUILT</th> </tr> <tr> <th>CUT</th> <th>FILL</th> <th>CUT</th> <th>FILL</th> <th>CUT</th> <th>FILL</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> </tr> <tr> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> </tr> </tbody> </table> <table border="1"> <thead> <tr> <th colspan="2">EXISTING</th> <th colspan="2">DESIGN</th> <th colspan="2">AS BUILT</th> </tr> <tr> <th>LEVEL</th> <th>OFFSET</th> <th>LEVEL</th> <th>OFFSET</th> <th>LEVEL</th> <th>OFFSET</th> </tr> </thead> <tbody> <tr> <td>392.22</td> <td>-63</td> <td>392.22</td> <td>-63</td> <td>392.22</td> <td>-63</td> </tr> <tr> <td>392.22</td> <td>-45</td> <td>392.22</td> <td>-45</td> <td>392.22</td> <td>-45</td> </tr> <tr> <td>392.22</td> <td>-41.5</td> <td>392.22</td> <td>-41.5</td> <td>392.22</td> <td>-41.5</td> </tr> <tr> <td>392.22</td> <td>-30</td> <td>392.22</td> <td>-30</td> <td>392.22</td> <td>-30</td> </tr> <tr> <td>392.22</td> <td>-34</td> <td>392.22</td> <td>-34</td> <td>392.22</td> <td>-34</td> </tr> <tr> <td>392.22</td> <td>-20</td> <td>392.22</td> <td>-20</td> <td>392.22</td> <td>-20</td> </tr> <tr> <td>392.22</td> <td>0</td> <td>392.22</td> <td>0</td> <td>392.22</td> <td>0</td> </tr> <tr> <td>392.22</td> <td>28</td> <td>392.22</td> <td>28</td> <td>392.22</td> <td>28</td> </tr> <tr> <td>392.22</td> <td>30</td> <td>392.22</td> <td>30</td> <td>392.22</td> <td>30</td> </tr> <tr> <td>392.22</td> <td>41.5</td> <td>392.22</td> <td>41.5</td> <td>392.22</td> <td>41.5</td> </tr> <tr> <td>392.22</td> <td>65</td> <td>392.22</td> <td>65</td> <td>392.22</td> <td>65</td> </tr> <tr> <td>392.22</td> <td>71</td> <td>392.22</td> <td>71</td> <td>392.22</td> <td>71</td> </tr> <tr> <td>392.22</td> <td>80</td> <td>392.22</td> <td>80</td> <td>392.22</td> <td>80</td> </tr> </tbody> </table>			L BANK		DESIGN		AS BUILT		CUT	FILL	CUT	FILL	CUT	FILL	0	0	0	0	0	0	0	0	0	0	0	0	R BANK		DESIGN		AS BUILT		CUT	FILL	CUT	FILL	CUT	FILL	0	0	0	0	0	0	0	0	0	0	0	0	EXISTING		DESIGN		AS BUILT		LEVEL	OFFSET	LEVEL	OFFSET	LEVEL	OFFSET	392.22	-63	392.22	-63	392.22	-63	392.22	-45	392.22	-45	392.22	-45	392.22	-41.5	392.22	-41.5	392.22	-41.5	392.22	-30	392.22	-30	392.22	-30	392.22	-34	392.22	-34	392.22	-34	392.22	-20	392.22	-20	392.22	-20	392.22	0	392.22	0	392.22	0	392.22	28	392.22	28	392.22	28	392.22	30	392.22	30	392.22	30	392.22	41.5	392.22	41.5	392.22	41.5	392.22	65	392.22	65	392.22	65	392.22	71	392.22	71	392.22	71	392.22	80	392.22	80	392.22
L BANK		DESIGN		AS BUILT																																																																																																																																								
CUT	FILL	CUT	FILL	CUT	FILL																																																																																																																																							
0	0	0	0	0	0																																																																																																																																							
0	0	0	0	0	0																																																																																																																																							
R BANK		DESIGN		AS BUILT																																																																																																																																								
CUT	FILL	CUT	FILL	CUT	FILL																																																																																																																																							
0	0	0	0	0	0																																																																																																																																							
0	0	0	0	0	0																																																																																																																																							
EXISTING		DESIGN		AS BUILT																																																																																																																																								
LEVEL	OFFSET	LEVEL	OFFSET	LEVEL	OFFSET																																																																																																																																							
392.22	-63	392.22	-63	392.22	-63																																																																																																																																							
392.22	-45	392.22	-45	392.22	-45																																																																																																																																							
392.22	-41.5	392.22	-41.5	392.22	-41.5																																																																																																																																							
392.22	-30	392.22	-30	392.22	-30																																																																																																																																							
392.22	-34	392.22	-34	392.22	-34																																																																																																																																							
392.22	-20	392.22	-20	392.22	-20																																																																																																																																							
392.22	0	392.22	0	392.22	0																																																																																																																																							
392.22	28	392.22	28	392.22	28																																																																																																																																							
392.22	30	392.22	30	392.22	30																																																																																																																																							
392.22	41.5	392.22	41.5	392.22	41.5																																																																																																																																							
392.22	65	392.22	65	392.22	65																																																																																																																																							
392.22	71	392.22	71	392.22	71																																																																																																																																							
392.22	80	392.22	80	392.22	80																																																																																																																																							
History of Damages																																																																																																																																												
MM/YYYY	Type of Damage	Description																																																																																																																																										
	Nil																																																																																																																																											
Record of Rehabilitation/ Improvement																																																																																																																																												
MM/YYYY	Project Name and its Description	Cost	Source of Funding																																																																																																																																									
	Nil																																																																																																																																											
Plan for Rehabilitation/ Improvement																																																																																																																																												
MM/YYYY	Project Name and its Description	Cost	Source of Funding																																																																																																																																									
	Nil																																																																																																																																											

Site Photo		
Vulnerable Section	General View of River Side	
	Facing Downstream and Side	Facing Upstream Side
		
	General View of Top	
	Facing Downstream and Side	Facing Upstream Side
		
	General View of Landside	
	Facing Downstream and Side	Facing Upstream Side
		
	Close View of Deformation (Not Applicable)	
Close View of Damages (Not Applicable)		

	<p>Photo with 360° angles</p> 	
<p>Typical Section (Adjacent to the Vulnerable Point)</p>	<p>General View of River Side</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
	<p>General View of Top</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
	<p>General View of Landside</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 

	<p>Photo with 360° angles</p> 
<p>Downstream End of the Bund</p>	<p>General View</p> <p>(Not Applicable)</p>
	<p>Photo with 360° angles</p> <p>(Not Applicable)</p>
<p>Upstream End of the Bund</p>	<p>General View (In the case that the VP is located near the end)</p> <p>(Not Applicable)</p>
	<p>Photo with 360° angles</p> <p>(Not Applicable)</p>

Observation Record ⁴ (Current status, effect of countermeasure, development of erosion, deformation, deterioration)			
DD/MM/YYYY	Inspection Type	Description and Photo	Damage ⁵
01/3/2024	Visual Inspection	<ul style="list-style-type: none"> • River is situated approximately 4600 feet away from this RD. • Cultivated area is situated on country side and canal on the right side of the embankment. • There is a J-Head spur having length of 6275 feet at this RD.  <p>Cropped area on country side</p>  <p>Canal on the right side of the embankment</p>	a

⁴ Current Status, Effect of the Existing Structural Countermeasure Such as Spurs/studs, Sheet Piles for Seepage Control etc. and Development of Erosion, Deformation, Deterioration of the Existing Bund

⁵ a: No Deformation, b: No deformations are observed on the bund body, except for gully erosion caused by raindrops or the detachment of the bund's stone pitching, c: The bund or the apron has been damaged, and L: Leakage from the bund has been identified

Evaluation Process					
DD/MM/YYYY	Item		Result	Reason	
	Criteria For Evaluation Flow	Flood Damage		Yes	The inundation analysis indicates that the flood damage is severe
		Bund Damage		NO	There is no significant damage at present.
		Bund Dimension	Bund Height	Fail	Free board height is 1 feet.
			Bund Width	Fail	Evaluation is not possible based on the typical cross-section.
			Flood Plain Length	Fail	Floodplain length is about 4,600 feet.
		Topographic Feature	Breach Record	NO	There is no breach record.
			Flow Impact	NO	It hasn't been affected by strong water flow since before 2010 flood.
	Category			Proactive Type C	
	For Evaluation Score	Bund Damage		0	There is no significant damage at present.
		Bund Dimension	Bund Height	1	Free board height is 1 feet.
			Bund Width	1	Evaluation is not possible based on the typical cross-section.
			Flood Plain Length	1	Floodplain length is about 4,600 feet.
	Quality Score			3/9	

Note) HGL: hydraulic gradient line

Left Bank of Link Number 1 RD 175+000

Creation Date: 01/3/2024



















Province	Zone	Division	Circle
Punjab	Dera Ghazi Khan Zone	DG Khan Construction Division	Project Circle DG Khan
Sr. No.	River Name	River System	Bank
P-006d	Indus River	Indus River	Right
Bund Name		R.D	GPS Coordinates
Left Bank of Link No. 1		RD 138+000 to 165+000 and 165+000 to 194+000	29°92'03.33"N, 70°75'5."E
Name of Vulnerable Point	Left Bank of Link No. 1 RD 138+000 to 165+000 and 165+000 194+000_4		
Reason for the Vulnerability	<ul style="list-style-type: none"> The said reach is no longer vulnerable, as the river is approximately 2400 feet. away from the left bank of link canal number 1 at this RD. There is no breach history of the left bank of link number 1 at this RD. 		
Flow Condition ¹	<ul style="list-style-type: none"> No flow conditions. River flows approximately 2400 feet away from this cross spur. 		
Site Condition in the Country Side ²	<ul style="list-style-type: none"> The cultivated area is situated on country side. There is a village Nurpur on the country side of the right bank of the link number 1. 		
Layout Plan (Source of Satellite Image: Google Earth)			
Evaluation ³			
Category	Quality Score		
Proactive Type C	3/9		








¹ Water Flow Direction and Conditions During Floods Around the Listed Vulnerable Points.


² Site Condition Around the Vulnerable Points (Rough Distance Between Main Water Channel and the Bund, Land Use Behind the Point, Important Facility Adjacent to the Point).



³ Emergent Type R: Emergent Phase Requiring Robust Countermeasures, Emergent Type C: Emergent Phase Requiring Common Countermeasures, Proactive Type R: Proactive Phase Requiring Robust Countermeasures, Proactive Type C: Proactive Phase Requiring Common Countermeasures, Monitoring: Monitoring Phase

Basic Information of the Bund																																																																																																																																																																																																																																																																																																																																																																																																																																						
Basic Dimensions and Materials	Item	Existing	Proposed																																																																																																																																																																																																																																																																																																																																																																																																																																			
	Top Elevation	393.93 feet	Not Applicable —																																																																																																																																																																																																																																																																																																																																																																																																																																			
	H.F.L	388.5 feet																																																																																																																																																																																																																																																																																																																																																																																																																																				
	Free Board Height	5.43 feet																																																																																																																																																																																																																																																																																																																																																																																																																																				
	Top Width	25 feet																																																																																																																																																																																																																																																																																																																																																																																																																																				
	River Side Slope	1:2																																																																																																																																																																																																																																																																																																																																																																																																																																				
	Country Side Slope	Left bank of link																																																																																																																																																																																																																																																																																																																																																																																																																																				
	Longitudinal Length	204500 feet																																																																																																																																																																																																																																																																																																																																																																																																																																				
	Slope Protection Material	Earthen (Clay)																																																																																																																																																																																																																																																																																																																																																																																																																																				
	Covering Material/ Pavement on the Top	Pavement on the top																																																																																																																																																																																																																																																																																																																																																																																																																																				
	Embankment Material	Earthen (clay)																																																																																																																																																																																																																																																																																																																																																																																																																																				
Ancillary Structure (Drainage Ditch, and Spurs)	Not Applicable																																																																																																																																																																																																																																																																																																																																																																																																																																					
Typical Cross Section																																																																																																																																																																																																																																																																																																																																																																																																																																						
	<table border="1"> <thead> <tr> <th colspan="2">L BANK</th> <th colspan="2">DESIGN</th> <th colspan="2">AS BUILT</th> <th colspan="2">R BANK</th> <th colspan="2">DESIGN</th> <th colspan="2">AS BUILT</th> </tr> <tr> <th>CUT</th> <th>FILL</th> <th>06.15</th> <th>0</th> <th>0</th> <th>0</th> <th>10.31</th> <th>0</th> <th>0</th> <th>0</th> <th>0</th> <th>0</th> </tr> </thead> <tbody> <tr> <td colspan="12">Scale 1:11 - Prim Area 0.00</td> </tr> <tr> <td colspan="12"> <table border="1"> <thead> <tr> <th colspan="2">EXISTING</th> <th colspan="2">DESIGN</th> <th colspan="2">AS BUILT</th> <th colspan="2">EXISTING</th> <th colspan="2">DESIGN</th> <th colspan="2">AS BUILT</th> </tr> <tr> <th>LEVEL</th> <th>OFFSET</th> <th>LEVEL</th> <th>OFFSET</th> <th>LEVEL</th> <th>OFFSET</th> <th>LEVEL</th> <th>OFFSET</th> <th>LEVEL</th> <th>OFFSET</th> <th>LEVEL</th> <th>OFFSET</th> </tr> </thead> <tbody> <tr> <td>393.93</td> <td>-57</td> <td>393.93</td> <td>-57</td> <td>393.93</td> <td>-57</td> <td>393.93</td> <td>-57</td> <td>393.93</td> <td>-57</td> <td>393.93</td> <td>-57</td> </tr> <tr> <td>393.93</td> <td>-46</td> <td>393.93</td> <td>-46</td> <td>393.93</td> <td>-46</td> <td>393.93</td> <td>-46</td> <td>393.93</td> <td>-46</td> <td>393.93</td> <td>-46</td> </tr> <tr> <td>393.93</td> <td>-42</td> <td>393.93</td> <td>-42</td> <td>393.93</td> <td>-42</td> <td>393.93</td> <td>-42</td> <td>393.93</td> <td>-42</td> <td>393.93</td> <td>-42</td> </tr> <tr> <td>393.93</td> <td>-34</td> <td>393.93</td> <td>-34</td> <td>393.93</td> <td>-34</td> <td>393.93</td> <td>-34</td> <td>393.93</td> <td>-34</td> <td>393.93</td> <td>-34</td> </tr> <tr> <td>393.93</td> <td>-29</td> <td>393.93</td> <td>-29</td> <td>393.93</td> <td>-29</td> <td>393.93</td> <td>-29</td> <td>393.93</td> <td>-29</td> <td>393.93</td> <td>-29</td> </tr> <tr> <td>393.93</td> <td>-25</td> <td>393.93</td> <td>-25</td> <td>393.93</td> <td>-25</td> <td>393.93</td> <td>-25</td> <td>393.93</td> <td>-25</td> <td>393.93</td> <td>-25</td> </tr> <tr> <td>393.93</td> <td>-21</td> <td>393.93</td> <td>-21</td> <td>393.93</td> <td>-21</td> <td>393.93</td> <td>-21</td> <td>393.93</td> <td>-21</td> <td>393.93</td> <td>-21</td> </tr> <tr> <td>393.93</td> <td>-17</td> <td>393.93</td> <td>-17</td> <td>393.93</td> <td>-17</td> <td>393.93</td> <td>-17</td> <td>393.93</td> <td>-17</td> <td>393.93</td> <td>-17</td> </tr> <tr> <td>393.93</td> <td>-13</td> <td>393.93</td> <td>-13</td> <td>393.93</td> <td>-13</td> <td>393.93</td> <td>-13</td> <td>393.93</td> <td>-13</td> <td>393.93</td> <td>-13</td> </tr> <tr> <td>393.93</td> <td>-9</td> <td>393.93</td> <td>-9</td> <td>393.93</td> <td>-9</td> <td>393.93</td> <td>-9</td> <td>393.93</td> <td>-9</td> <td>393.93</td> <td>-9</td> </tr> <tr> <td>393.93</td> <td>-5</td> <td>393.93</td> <td>-5</td> <td>393.93</td> <td>-5</td> <td>393.93</td> <td>-5</td> <td>393.93</td> <td>-5</td> <td>393.93</td> <td>-5</td> </tr> <tr> <td>393.93</td> <td>-1</td> <td>393.93</td> <td>-1</td> <td>393.93</td> <td>-1</td> <td>393.93</td> <td>-1</td> <td>393.93</td> <td>-1</td> <td>393.93</td> <td>-1</td> </tr> <tr> <td>393.93</td> <td>3</td> <td>393.93</td> <td>3</td> <td>393.93</td> <td>3</td> <td>393.93</td> <td>3</td> <td>393.93</td> <td>3</td> <td>393.93</td> <td>3</td> </tr> <tr> <td>393.93</td> <td>7</td> <td>393.93</td> <td>7</td> <td>393.93</td> <td>7</td> <td>393.93</td> <td>7</td> <td>393.93</td> <td>7</td> <td>393.93</td> <td>7</td> </tr> <tr> <td>393.93</td> <td>11</td> <td>393.93</td> <td>11</td> <td>393.93</td> <td>11</td> <td>393.93</td> <td>11</td> <td>393.93</td> <td>11</td> <td>393.93</td> <td>11</td> </tr> <tr> <td>393.93</td> <td>15</td> <td>393.93</td> <td>15</td> <td>393.93</td> <td>15</td> <td>393.93</td> <td>15</td> <td>393.93</td> <td>15</td> <td>393.93</td> <td>15</td> </tr> <tr> <td>393.93</td> <td>19</td> <td>393.93</td> <td>19</td> <td>393.93</td> <td>19</td> <td>393.93</td> <td>19</td> <td>393.93</td> <td>19</td> <td>393.93</td> <td>19</td> </tr> <tr> <td>393.93</td> <td>23</td> <td>393.93</td> <td>23</td> <td>393.93</td> <td>23</td> <td>393.93</td> <td>23</td> <td>393.93</td> <td>23</td> <td>393.93</td> <td>23</td> </tr> <tr> <td>393.93</td> <td>27</td> <td>393.93</td> <td>27</td> <td>393.93</td> <td>27</td> <td>393.93</td> <td>27</td> <td>393.93</td> <td>27</td> <td>393.93</td> <td>27</td> </tr> <tr> <td>393.93</td> <td>31</td> <td>393.93</td> <td>31</td> <td>393.93</td> <td>31</td> <td>393.93</td> <td>31</td> <td>393.93</td> <td>31</td> <td>393.93</td> <td>31</td> </tr> <tr> <td>393.93</td> <td>35</td> <td>393.93</td> <td>35</td> <td>393.93</td> <td>35</td> <td>393.93</td> <td>35</td> <td>393.93</td> <td>35</td> <td>393.93</td> <td>35</td> </tr> <tr> <td>393.93</td> <td>39</td> <td>393.93</td> <td>39</td> <td>393.93</td> <td>39</td> <td>393.93</td> <td>39</td> <td>393.93</td> <td>39</td> <td>393.93</td> <td>39</td> </tr> <tr> <td>393.93</td> <td>43</td> <td>393.93</td> <td>43</td> <td>393.93</td> <td>43</td> <td>393.93</td> <td>43</td> <td>393.93</td> <td>43</td> <td>393.93</td> <td>43</td> </tr> <tr> <td>393.93</td> <td>47</td> <td>393.93</td> <td>47</td> <td>393.93</td> <td>47</td> <td>393.93</td> <td>47</td> <td>393.93</td> <td>47</td> <td>393.93</td> <td>47</td> </tr> <tr> <td>393.93</td> <td>51</td> <td>393.93</td> <td>51</td> <td>393.93</td> <td>51</td> <td>393.93</td> <td>51</td> <td>393.93</td> <td>51</td> <td>393.93</td> <td>51</td> </tr> <tr> <td>393.93</td> <td>55</td> <td>393.93</td> <td>55</td> <td>393.93</td> <td>55</td> <td>393.93</td> <td>55</td> <td>393.93</td> <td>55</td> <td>393.93</td> <td>55</td> </tr> </tbody> </table> </td> </tr> <tr> <td colspan="4">History of Damages</td> </tr> <tr> <td>MM/YYYY</td> <td>Type of Damage</td> <td colspan="2">Description</td> </tr> <tr> <td></td> <td>Nil</td> <td colspan="2"></td> </tr> <tr> <td colspan="4">Record of Rehabilitation/ Improvement</td> </tr> <tr> <td>MM/YYYY</td> <td>Project Name and its Description</td> <td>Cost</td> <td>Source of Funding</td> </tr> <tr> <td></td> <td>Nil</td> <td></td> <td></td> </tr> <tr> <td colspan="4">Plan for Rehabilitation/ Improvement</td> </tr> <tr> <td>MM/YYYY</td> <td>Project Name and its Description</td> <td>Cost</td> <td>Source of Funding</td> </tr> <tr> <td></td> <td>Nil</td> <td></td> <td></td> </tr> </tbody> </table>			L BANK		DESIGN		AS BUILT		R BANK		DESIGN		AS BUILT		CUT	FILL	06.15	0	0	0	10.31	0	0	0	0	0	Scale 1:11 - Prim Area 0.00												<table border="1"> <thead> <tr> <th colspan="2">EXISTING</th> <th colspan="2">DESIGN</th> <th colspan="2">AS BUILT</th> <th colspan="2">EXISTING</th> <th colspan="2">DESIGN</th> <th colspan="2">AS BUILT</th> </tr> <tr> <th>LEVEL</th> <th>OFFSET</th> <th>LEVEL</th> <th>OFFSET</th> <th>LEVEL</th> <th>OFFSET</th> <th>LEVEL</th> <th>OFFSET</th> <th>LEVEL</th> <th>OFFSET</th> <th>LEVEL</th> <th>OFFSET</th> </tr> </thead> <tbody> <tr> <td>393.93</td> <td>-57</td> <td>393.93</td> <td>-57</td> <td>393.93</td> <td>-57</td> <td>393.93</td> <td>-57</td> <td>393.93</td> <td>-57</td> <td>393.93</td> <td>-57</td> </tr> <tr> <td>393.93</td> <td>-46</td> <td>393.93</td> <td>-46</td> <td>393.93</td> <td>-46</td> <td>393.93</td> <td>-46</td> <td>393.93</td> <td>-46</td> <td>393.93</td> <td>-46</td> </tr> <tr> <td>393.93</td> <td>-42</td> <td>393.93</td> <td>-42</td> <td>393.93</td> <td>-42</td> <td>393.93</td> <td>-42</td> <td>393.93</td> <td>-42</td> <td>393.93</td> <td>-42</td> </tr> <tr> <td>393.93</td> <td>-34</td> <td>393.93</td> <td>-34</td> <td>393.93</td> <td>-34</td> <td>393.93</td> <td>-34</td> <td>393.93</td> <td>-34</td> <td>393.93</td> <td>-34</td> </tr> <tr> <td>393.93</td> <td>-29</td> <td>393.93</td> <td>-29</td> <td>393.93</td> <td>-29</td> <td>393.93</td> <td>-29</td> <td>393.93</td> <td>-29</td> <td>393.93</td> <td>-29</td> </tr> <tr> <td>393.93</td> <td>-25</td> <td>393.93</td> <td>-25</td> <td>393.93</td> <td>-25</td> <td>393.93</td> <td>-25</td> <td>393.93</td> <td>-25</td> <td>393.93</td> <td>-25</td> </tr> <tr> <td>393.93</td> <td>-21</td> <td>393.93</td> <td>-21</td> <td>393.93</td> <td>-21</td> <td>393.93</td> <td>-21</td> <td>393.93</td> <td>-21</td> <td>393.93</td> <td>-21</td> </tr> <tr> <td>393.93</td> <td>-17</td> <td>393.93</td> <td>-17</td> <td>393.93</td> <td>-17</td> <td>393.93</td> <td>-17</td> <td>393.93</td> <td>-17</td> <td>393.93</td> <td>-17</td> </tr> <tr> <td>393.93</td> <td>-13</td> <td>393.93</td> <td>-13</td> <td>393.93</td> <td>-13</td> <td>393.93</td> <td>-13</td> <td>393.93</td> <td>-13</td> <td>393.93</td> <td>-13</td> </tr> <tr> <td>393.93</td> <td>-9</td> <td>393.93</td> <td>-9</td> <td>393.93</td> <td>-9</td> <td>393.93</td> <td>-9</td> <td>393.93</td> <td>-9</td> <td>393.93</td> <td>-9</td> </tr> <tr> <td>393.93</td> <td>-5</td> <td>393.93</td> <td>-5</td> <td>393.93</td> <td>-5</td> <td>393.93</td> <td>-5</td> <td>393.93</td> <td>-5</td> <td>393.93</td> <td>-5</td> </tr> <tr> <td>393.93</td> <td>-1</td> <td>393.93</td> <td>-1</td> <td>393.93</td> <td>-1</td> <td>393.93</td> <td>-1</td> <td>393.93</td> <td>-1</td> <td>393.93</td> <td>-1</td> </tr> <tr> <td>393.93</td> <td>3</td> <td>393.93</td> <td>3</td> <td>393.93</td> <td>3</td> <td>393.93</td> <td>3</td> <td>393.93</td> <td>3</td> <td>393.93</td> <td>3</td> </tr> <tr> <td>393.93</td> <td>7</td> <td>393.93</td> <td>7</td> <td>393.93</td> <td>7</td> <td>393.93</td> <td>7</td> <td>393.93</td> <td>7</td> <td>393.93</td> <td>7</td> </tr> <tr> <td>393.93</td> <td>11</td> <td>393.93</td> <td>11</td> <td>393.93</td> <td>11</td> <td>393.93</td> <td>11</td> <td>393.93</td> <td>11</td> <td>393.93</td> <td>11</td> </tr> <tr> <td>393.93</td> <td>15</td> <td>393.93</td> <td>15</td> <td>393.93</td> <td>15</td> <td>393.93</td> <td>15</td> <td>393.93</td> <td>15</td> <td>393.93</td> <td>15</td> </tr> <tr> <td>393.93</td> <td>19</td> <td>393.93</td> <td>19</td> <td>393.93</td> <td>19</td> <td>393.93</td> <td>19</td> <td>393.93</td> <td>19</td> <td>393.93</td> <td>19</td> </tr> <tr> <td>393.93</td> <td>23</td> <td>393.93</td> <td>23</td> <td>393.93</td> <td>23</td> <td>393.93</td> <td>23</td> <td>393.93</td> <td>23</td> <td>393.93</td> <td>23</td> </tr> <tr> <td>393.93</td> <td>27</td> <td>393.93</td> <td>27</td> <td>393.93</td> <td>27</td> <td>393.93</td> <td>27</td> <td>393.93</td> <td>27</td> <td>393.93</td> <td>27</td> </tr> <tr> <td>393.93</td> <td>31</td> <td>393.93</td> <td>31</td> <td>393.93</td> <td>31</td> <td>393.93</td> <td>31</td> <td>393.93</td> <td>31</td> <td>393.93</td> <td>31</td> </tr> <tr> <td>393.93</td> <td>35</td> <td>393.93</td> <td>35</td> <td>393.93</td> <td>35</td> <td>393.93</td> <td>35</td> <td>393.93</td> <td>35</td> <td>393.93</td> <td>35</td> </tr> <tr> <td>393.93</td> <td>39</td> <td>393.93</td> <td>39</td> <td>393.93</td> <td>39</td> <td>393.93</td> <td>39</td> <td>393.93</td> <td>39</td> <td>393.93</td> <td>39</td> </tr> <tr> <td>393.93</td> <td>43</td> <td>393.93</td> <td>43</td> <td>393.93</td> <td>43</td> <td>393.93</td> <td>43</td> <td>393.93</td> <td>43</td> <td>393.93</td> <td>43</td> </tr> <tr> <td>393.93</td> <td>47</td> <td>393.93</td> <td>47</td> <td>393.93</td> <td>47</td> <td>393.93</td> <td>47</td> <td>393.93</td> <td>47</td> <td>393.93</td> <td>47</td> </tr> <tr> <td>393.93</td> <td>51</td> <td>393.93</td> <td>51</td> <td>393.93</td> <td>51</td> <td>393.93</td> <td>51</td> <td>393.93</td> <td>51</td> <td>393.93</td> <td>51</td> </tr> <tr> <td>393.93</td> <td>55</td> <td>393.93</td> <td>55</td> <td>393.93</td> <td>55</td> <td>393.93</td> <td>55</td> <td>393.93</td> <td>55</td> <td>393.93</td> <td>55</td> </tr> </tbody> </table>												EXISTING		DESIGN		AS BUILT		EXISTING		DESIGN		AS BUILT		LEVEL	OFFSET	LEVEL	OFFSET	LEVEL	OFFSET	LEVEL	OFFSET	LEVEL	OFFSET	LEVEL	OFFSET	393.93	-57	393.93	-57	393.93	-57	393.93	-57	393.93	-57	393.93	-57	393.93	-46	393.93	-46	393.93	-46	393.93	-46	393.93	-46	393.93	-46	393.93	-42	393.93	-42	393.93	-42	393.93	-42	393.93	-42	393.93	-42	393.93	-34	393.93	-34	393.93	-34	393.93	-34	393.93	-34	393.93	-34	393.93	-29	393.93	-29	393.93	-29	393.93	-29	393.93	-29	393.93	-29	393.93	-25	393.93	-25	393.93	-25	393.93	-25	393.93	-25	393.93	-25	393.93	-21	393.93	-21	393.93	-21	393.93	-21	393.93	-21	393.93	-21	393.93	-17	393.93	-17	393.93	-17	393.93	-17	393.93	-17	393.93	-17	393.93	-13	393.93	-13	393.93	-13	393.93	-13	393.93	-13	393.93	-13	393.93	-9	393.93	-9	393.93	-9	393.93	-9	393.93	-9	393.93	-9	393.93	-5	393.93	-5	393.93	-5	393.93	-5	393.93	-5	393.93	-5	393.93	-1	393.93	-1	393.93	-1	393.93	-1	393.93	-1	393.93	-1	393.93	3	393.93	3	393.93	3	393.93	3	393.93	3	393.93	3	393.93	7	393.93	7	393.93	7	393.93	7	393.93	7	393.93	7	393.93	11	393.93	11	393.93	11	393.93	11	393.93	11	393.93	11	393.93	15	393.93	15	393.93	15	393.93	15	393.93	15	393.93	15	393.93	19	393.93	19	393.93	19	393.93	19	393.93	19	393.93	19	393.93	23	393.93	23	393.93	23	393.93	23	393.93	23	393.93	23	393.93	27	393.93	27	393.93	27	393.93	27	393.93	27	393.93	27	393.93	31	393.93	31	393.93	31	393.93	31	393.93	31	393.93	31	393.93	35	393.93	35	393.93	35	393.93	35	393.93	35	393.93	35	393.93	39	393.93	39	393.93	39	393.93	39	393.93	39	393.93	39	393.93	43	393.93	43	393.93	43	393.93	43	393.93	43	393.93	43	393.93	47	393.93	47	393.93	47	393.93	47	393.93	47	393.93	47	393.93	51	393.93	51	393.93	51	393.93	51	393.93	51	393.93	51	393.93	55	393.93	55	393.93	55	393.93	55	393.93	55	393.93	55	History of Damages				MM/YYYY	Type of Damage	Description			Nil			Record of Rehabilitation/ Improvement				MM/YYYY	Project Name and its Description	Cost	Source of Funding		Nil			Plan for Rehabilitation/ Improvement				MM/YYYY	Project Name and its Description	Cost	Source of Funding		Nil	
L BANK		DESIGN		AS BUILT		R BANK		DESIGN		AS BUILT																																																																																																																																																																																																																																																																																																																																																																																																																												
CUT	FILL	06.15	0	0	0	10.31	0	0	0	0	0																																																																																																																																																																																																																																																																																																																																																																																																																											
Scale 1:11 - Prim Area 0.00																																																																																																																																																																																																																																																																																																																																																																																																																																						
<table border="1"> <thead> <tr> <th colspan="2">EXISTING</th> <th colspan="2">DESIGN</th> <th colspan="2">AS BUILT</th> <th colspan="2">EXISTING</th> <th colspan="2">DESIGN</th> <th colspan="2">AS BUILT</th> </tr> <tr> <th>LEVEL</th> <th>OFFSET</th> <th>LEVEL</th> <th>OFFSET</th> <th>LEVEL</th> <th>OFFSET</th> <th>LEVEL</th> <th>OFFSET</th> <th>LEVEL</th> <th>OFFSET</th> <th>LEVEL</th> <th>OFFSET</th> </tr> </thead> <tbody> <tr> <td>393.93</td> <td>-57</td> <td>393.93</td> <td>-57</td> <td>393.93</td> <td>-57</td> <td>393.93</td> <td>-57</td> <td>393.93</td> <td>-57</td> <td>393.93</td> <td>-57</td> </tr> <tr> <td>393.93</td> <td>-46</td> <td>393.93</td> <td>-46</td> <td>393.93</td> <td>-46</td> <td>393.93</td> <td>-46</td> <td>393.93</td> <td>-46</td> <td>393.93</td> <td>-46</td> </tr> <tr> <td>393.93</td> <td>-42</td> <td>393.93</td> <td>-42</td> <td>393.93</td> <td>-42</td> <td>393.93</td> <td>-42</td> <td>393.93</td> <td>-42</td> <td>393.93</td> <td>-42</td> </tr> <tr> <td>393.93</td> <td>-34</td> <td>393.93</td> <td>-34</td> <td>393.93</td> <td>-34</td> <td>393.93</td> <td>-34</td> <td>393.93</td> <td>-34</td> <td>393.93</td> <td>-34</td> </tr> <tr> <td>393.93</td> <td>-29</td> <td>393.93</td> <td>-29</td> <td>393.93</td> <td>-29</td> <td>393.93</td> <td>-29</td> <td>393.93</td> <td>-29</td> <td>393.93</td> <td>-29</td> </tr> <tr> <td>393.93</td> <td>-25</td> <td>393.93</td> <td>-25</td> <td>393.93</td> <td>-25</td> <td>393.93</td> <td>-25</td> <td>393.93</td> <td>-25</td> <td>393.93</td> <td>-25</td> </tr> <tr> <td>393.93</td> <td>-21</td> <td>393.93</td> <td>-21</td> <td>393.93</td> <td>-21</td> <td>393.93</td> <td>-21</td> <td>393.93</td> <td>-21</td> <td>393.93</td> <td>-21</td> </tr> <tr> <td>393.93</td> <td>-17</td> <td>393.93</td> <td>-17</td> <td>393.93</td> <td>-17</td> <td>393.93</td> <td>-17</td> <td>393.93</td> <td>-17</td> <td>393.93</td> <td>-17</td> </tr> <tr> <td>393.93</td> <td>-13</td> <td>393.93</td> <td>-13</td> <td>393.93</td> <td>-13</td> <td>393.93</td> <td>-13</td> <td>393.93</td> <td>-13</td> <td>393.93</td> <td>-13</td> </tr> <tr> <td>393.93</td> <td>-9</td> <td>393.93</td> <td>-9</td> <td>393.93</td> <td>-9</td> <td>393.93</td> <td>-9</td> <td>393.93</td> <td>-9</td> <td>393.93</td> <td>-9</td> </tr> <tr> <td>393.93</td> <td>-5</td> <td>393.93</td> <td>-5</td> <td>393.93</td> <td>-5</td> <td>393.93</td> <td>-5</td> <td>393.93</td> <td>-5</td> <td>393.93</td> <td>-5</td> </tr> <tr> <td>393.93</td> <td>-1</td> <td>393.93</td> <td>-1</td> <td>393.93</td> <td>-1</td> <td>393.93</td> <td>-1</td> <td>393.93</td> <td>-1</td> <td>393.93</td> <td>-1</td> </tr> <tr> <td>393.93</td> <td>3</td> <td>393.93</td> <td>3</td> <td>393.93</td> <td>3</td> <td>393.93</td> <td>3</td> <td>393.93</td> <td>3</td> <td>393.93</td> <td>3</td> </tr> <tr> <td>393.93</td> <td>7</td> <td>393.93</td> <td>7</td> <td>393.93</td> <td>7</td> <td>393.93</td> <td>7</td> <td>393.93</td> <td>7</td> <td>393.93</td> <td>7</td> </tr> <tr> <td>393.93</td> <td>11</td> <td>393.93</td> <td>11</td> <td>393.93</td> <td>11</td> <td>393.93</td> <td>11</td> <td>393.93</td> <td>11</td> <td>393.93</td> <td>11</td> </tr> <tr> <td>393.93</td> <td>15</td> <td>393.93</td> <td>15</td> <td>393.93</td> <td>15</td> <td>393.93</td> <td>15</td> <td>393.93</td> <td>15</td> <td>393.93</td> <td>15</td> </tr> <tr> <td>393.93</td> <td>19</td> <td>393.93</td> <td>19</td> <td>393.93</td> <td>19</td> <td>393.93</td> <td>19</td> <td>393.93</td> <td>19</td> <td>393.93</td> <td>19</td> </tr> <tr> <td>393.93</td> <td>23</td> <td>393.93</td> <td>23</td> <td>393.93</td> <td>23</td> <td>393.93</td> <td>23</td> <td>393.93</td> <td>23</td> <td>393.93</td> <td>23</td> </tr> <tr> <td>393.93</td> <td>27</td> <td>393.93</td> <td>27</td> <td>393.93</td> <td>27</td> <td>393.93</td> <td>27</td> <td>393.93</td> <td>27</td> <td>393.93</td> <td>27</td> </tr> <tr> <td>393.93</td> <td>31</td> <td>393.93</td> <td>31</td> <td>393.93</td> <td>31</td> <td>393.93</td> <td>31</td> <td>393.93</td> <td>31</td> <td>393.93</td> <td>31</td> </tr> <tr> <td>393.93</td> <td>35</td> <td>393.93</td> <td>35</td> <td>393.93</td> <td>35</td> <td>393.93</td> <td>35</td> <td>393.93</td> <td>35</td> <td>393.93</td> <td>35</td> </tr> <tr> <td>393.93</td> <td>39</td> <td>393.93</td> <td>39</td> <td>393.93</td> <td>39</td> <td>393.93</td> <td>39</td> <td>393.93</td> <td>39</td> <td>393.93</td> <td>39</td> </tr> <tr> <td>393.93</td> <td>43</td> <td>393.93</td> <td>43</td> <td>393.93</td> <td>43</td> <td>393.93</td> <td>43</td> <td>393.93</td> <td>43</td> <td>393.93</td> <td>43</td> </tr> <tr> <td>393.93</td> <td>47</td> <td>393.93</td> <td>47</td> <td>393.93</td> <td>47</td> <td>393.93</td> <td>47</td> <td>393.93</td> <td>47</td> <td>393.93</td> <td>47</td> </tr> <tr> <td>393.93</td> <td>51</td> <td>393.93</td> <td>51</td> <td>393.93</td> <td>51</td> <td>393.93</td> <td>51</td> <td>393.93</td> <td>51</td> <td>393.93</td> <td>51</td> </tr> <tr> <td>393.93</td> <td>55</td> <td>393.93</td> <td>55</td> <td>393.93</td> <td>55</td> <td>393.93</td> <td>55</td> <td>393.93</td> <td>55</td> <td>393.93</td> <td>55</td> </tr> </tbody> </table>												EXISTING		DESIGN		AS BUILT		EXISTING		DESIGN		AS BUILT		LEVEL	OFFSET	LEVEL	OFFSET	LEVEL	OFFSET	LEVEL	OFFSET	LEVEL	OFFSET	LEVEL	OFFSET	393.93	-57	393.93	-57	393.93	-57	393.93	-57	393.93	-57	393.93	-57	393.93	-46	393.93	-46	393.93	-46	393.93	-46	393.93	-46	393.93	-46	393.93	-42	393.93	-42	393.93	-42	393.93	-42	393.93	-42	393.93	-42	393.93	-34	393.93	-34	393.93	-34	393.93	-34	393.93	-34	393.93	-34	393.93	-29	393.93	-29	393.93	-29	393.93	-29	393.93	-29	393.93	-29	393.93	-25	393.93	-25	393.93	-25	393.93	-25	393.93	-25	393.93	-25	393.93	-21	393.93	-21	393.93	-21	393.93	-21	393.93	-21	393.93	-21	393.93	-17	393.93	-17	393.93	-17	393.93	-17	393.93	-17	393.93	-17	393.93	-13	393.93	-13	393.93	-13	393.93	-13	393.93	-13	393.93	-13	393.93	-9	393.93	-9	393.93	-9	393.93	-9	393.93	-9	393.93	-9	393.93	-5	393.93	-5	393.93	-5	393.93	-5	393.93	-5	393.93	-5	393.93	-1	393.93	-1	393.93	-1	393.93	-1	393.93	-1	393.93	-1	393.93	3	393.93	3	393.93	3	393.93	3	393.93	3	393.93	3	393.93	7	393.93	7	393.93	7	393.93	7	393.93	7	393.93	7	393.93	11	393.93	11	393.93	11	393.93	11	393.93	11	393.93	11	393.93	15	393.93	15	393.93	15	393.93	15	393.93	15	393.93	15	393.93	19	393.93	19	393.93	19	393.93	19	393.93	19	393.93	19	393.93	23	393.93	23	393.93	23	393.93	23	393.93	23	393.93	23	393.93	27	393.93	27	393.93	27	393.93	27	393.93	27	393.93	27	393.93	31	393.93	31	393.93	31	393.93	31	393.93	31	393.93	31	393.93	35	393.93	35	393.93	35	393.93	35	393.93	35	393.93	35	393.93	39	393.93	39	393.93	39	393.93	39	393.93	39	393.93	39	393.93	43	393.93	43	393.93	43	393.93	43	393.93	43	393.93	43	393.93	47	393.93	47	393.93	47	393.93	47	393.93	47	393.93	47	393.93	51	393.93	51	393.93	51	393.93	51	393.93	51	393.93	51	393.93	55	393.93	55	393.93	55	393.93	55	393.93	55	393.93	55																																																																											
EXISTING		DESIGN		AS BUILT		EXISTING		DESIGN		AS BUILT																																																																																																																																																																																																																																																																																																																																																																																																																												
LEVEL	OFFSET	LEVEL	OFFSET	LEVEL	OFFSET	LEVEL	OFFSET	LEVEL	OFFSET	LEVEL	OFFSET																																																																																																																																																																																																																																																																																																																																																																																																																											
393.93	-57	393.93	-57	393.93	-57	393.93	-57	393.93	-57	393.93	-57																																																																																																																																																																																																																																																																																																																																																																																																																											
393.93	-46	393.93	-46	393.93	-46	393.93	-46	393.93	-46	393.93	-46																																																																																																																																																																																																																																																																																																																																																																																																																											
393.93	-42	393.93	-42	393.93	-42	393.93	-42	393.93	-42	393.93	-42																																																																																																																																																																																																																																																																																																																																																																																																																											
393.93	-34	393.93	-34	393.93	-34	393.93	-34	393.93	-34	393.93	-34																																																																																																																																																																																																																																																																																																																																																																																																																											
393.93	-29	393.93	-29	393.93	-29	393.93	-29	393.93	-29	393.93	-29																																																																																																																																																																																																																																																																																																																																																																																																																											
393.93	-25	393.93	-25	393.93	-25	393.93	-25	393.93	-25	393.93	-25																																																																																																																																																																																																																																																																																																																																																																																																																											
393.93	-21	393.93	-21	393.93	-21	393.93	-21	393.93	-21	393.93	-21																																																																																																																																																																																																																																																																																																																																																																																																																											
393.93	-17	393.93	-17	393.93	-17	393.93	-17	393.93	-17	393.93	-17																																																																																																																																																																																																																																																																																																																																																																																																																											
393.93	-13	393.93	-13	393.93	-13	393.93	-13	393.93	-13	393.93	-13																																																																																																																																																																																																																																																																																																																																																																																																																											
393.93	-9	393.93	-9	393.93	-9	393.93	-9	393.93	-9	393.93	-9																																																																																																																																																																																																																																																																																																																																																																																																																											
393.93	-5	393.93	-5	393.93	-5	393.93	-5	393.93	-5	393.93	-5																																																																																																																																																																																																																																																																																																																																																																																																																											
393.93	-1	393.93	-1	393.93	-1	393.93	-1	393.93	-1	393.93	-1																																																																																																																																																																																																																																																																																																																																																																																																																											
393.93	3	393.93	3	393.93	3	393.93	3	393.93	3	393.93	3																																																																																																																																																																																																																																																																																																																																																																																																																											
393.93	7	393.93	7	393.93	7	393.93	7	393.93	7	393.93	7																																																																																																																																																																																																																																																																																																																																																																																																																											
393.93	11	393.93	11	393.93	11	393.93	11	393.93	11	393.93	11																																																																																																																																																																																																																																																																																																																																																																																																																											
393.93	15	393.93	15	393.93	15	393.93	15	393.93	15	393.93	15																																																																																																																																																																																																																																																																																																																																																																																																																											
393.93	19	393.93	19	393.93	19	393.93	19	393.93	19	393.93	19																																																																																																																																																																																																																																																																																																																																																																																																																											
393.93	23	393.93	23	393.93	23	393.93	23	393.93	23	393.93	23																																																																																																																																																																																																																																																																																																																																																																																																																											
393.93	27	393.93	27	393.93	27	393.93	27	393.93	27	393.93	27																																																																																																																																																																																																																																																																																																																																																																																																																											
393.93	31	393.93	31	393.93	31	393.93	31	393.93	31	393.93	31																																																																																																																																																																																																																																																																																																																																																																																																																											
393.93	35	393.93	35	393.93	35	393.93	35	393.93	35	393.93	35																																																																																																																																																																																																																																																																																																																																																																																																																											
393.93	39	393.93	39	393.93	39	393.93	39	393.93	39	393.93	39																																																																																																																																																																																																																																																																																																																																																																																																																											
393.93	43	393.93	43	393.93	43	393.93	43	393.93	43	393.93	43																																																																																																																																																																																																																																																																																																																																																																																																																											
393.93	47	393.93	47	393.93	47	393.93	47	393.93	47	393.93	47																																																																																																																																																																																																																																																																																																																																																																																																																											
393.93	51	393.93	51	393.93	51	393.93	51	393.93	51	393.93	51																																																																																																																																																																																																																																																																																																																																																																																																																											
393.93	55	393.93	55	393.93	55	393.93	55	393.93	55	393.93	55																																																																																																																																																																																																																																																																																																																																																																																																																											
History of Damages																																																																																																																																																																																																																																																																																																																																																																																																																																						
MM/YYYY	Type of Damage	Description																																																																																																																																																																																																																																																																																																																																																																																																																																				
	Nil																																																																																																																																																																																																																																																																																																																																																																																																																																					
Record of Rehabilitation/ Improvement																																																																																																																																																																																																																																																																																																																																																																																																																																						
MM/YYYY	Project Name and its Description	Cost	Source of Funding																																																																																																																																																																																																																																																																																																																																																																																																																																			
	Nil																																																																																																																																																																																																																																																																																																																																																																																																																																					
Plan for Rehabilitation/ Improvement																																																																																																																																																																																																																																																																																																																																																																																																																																						
MM/YYYY	Project Name and its Description	Cost	Source of Funding																																																																																																																																																																																																																																																																																																																																																																																																																																			
	Nil																																																																																																																																																																																																																																																																																																																																																																																																																																					

Site Photo					
Vulnerable Section	General View of River Side				
	<table border="1"> <tr> <td>Facing Downstream and Side</td> <td>Facing Upstream Side</td> </tr> <tr> <td></td> <td></td> </tr> </table>	Facing Downstream and Side	Facing Upstream Side		
	Facing Downstream and Side	Facing Upstream Side			
					
	General View of Top				
	<table border="1"> <tr> <td>Facing Downstream and Side</td> <td>Facing Upstream Side</td> </tr> <tr> <td></td> <td></td> </tr> </table>	Facing Downstream and Side	Facing Upstream Side		
	Facing Downstream and Side	Facing Upstream Side			
					
	General View of Landside				
	<table border="1"> <tr> <td>Facing Downstream and Side</td> <td>Facing Upstream Side</td> </tr> <tr> <td> <p>29.92028, 70.75556, 66.9m, 176°</p></td> <td></td> </tr> </table>	Facing Downstream and Side	Facing Upstream Side	 <p>29.92028, 70.75556, 66.9m, 176°</p>	
	Facing Downstream and Side	Facing Upstream Side			
	 <p>29.92028, 70.75556, 66.9m, 176°</p>				
Close View of Deformation	(Not Applicable)				
Close View of Damages	(Not Applicable)				

	<p>Photo with 360° angles</p> 	
<p>Typical Section (Adjacent to the Vulnerable Point)</p>	<p>General View of River Side</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
<p>General View of Top</p>		
<p>Facing Downstream and Side</p> 		<p>Facing Upstream Side</p> 
<p>General View of Landside</p>		
<p>Facing Downstream and Side</p> 		<p>Facing Upstream Side</p> 

	<p>Photo with 360° angles</p> 
Downstream End of the Bund	<p>General View</p> <p>(Not Applicable)</p>
	<p>Photo with 360° angles</p> <p>(Not Applicable)</p>
Upstream End of the Bund	<p>General View (In the case that the VP is located near the end)</p> <p>(Not Applicable)</p>
	<p>Photo with 360° angles</p> <p>(Not Applicable)</p>

Observation Record ⁴ (Current status, effect of countermeasure, development of erosion, deformation, deterioration)			
DD/MM/YYYY	Inspection Type	Description and Photo	Damage ⁵
01/3/2024	Visual Inspection	<ul style="list-style-type: none"> • River is situated approximately 2400 feet away from this RD. • Cultivated area is situated on country side and empty canal on the right side of the embankment. • A reserve stock of stones is available on the left bank of Link Number 1, stretching from RD 174+000 to 184+000.  <p>29.91797, 70.75626, 73.6m, 54°</p> <p>Cultivated area on country side</p>  <p>Empty canal on the right side of the embankment</p>	a

⁴ Current Status, Effect of the Existing Structural Countermeasure Such as Spurs/studs, Sheet Piles for Seepage Control etc. and Development of Erosion, Deformation, Deterioration of the Existing Bund

⁵ a: No Deformation, b: No deformations are observed on the bund body, except for gully erosion caused by raindrops or the detachment of the bund's stone pitching, c: The bund or the apron has been damaged, and L: Leakage from the bund has been identified

Evaluation Process					
DD/MM/YYYY	Item		Result	Reason	
	Criteria For Evaluation Flow	Flood Damage		Yes	The inundation analysis indicates that the flood damage is severe
		Bund Damage		NO	There is no significant damage at present.
		Bund Dimension	Bund Height	Fail	Free board height is 5.4 feet.
			Bund Width	Fail	Evaluation is not possible based on the typical cross-section.
			Flood Plain Length	Fail	Floodplain length is about 2400 feet.
		Topographic Feature	Breach Record	No	There is no breach record.
	Flow Impact		NO	It hasn't been affected by strong water flow since before 2010 flood.	
	Category			Proactive Type C	
	For Evaluation Score	Bund Damage		0	There is no significant damage at present.
		Bund Dimension	Bund Height	1	Free board height is 5.4 feet.
			Bund Width	1	Evaluation is not possible based on the typical cross-section.
			Flood Plain Length	1	Floodplain length is about 2400 feet.
	Quality Score			3/9	

Note) HGL: hydraulic gradient line

Left Bank of Link Number 1 RD 185+000

Creation Date: 01/3/2024

Province	Zone	Division	Circle
Punjab	Dera Ghazi Khan Zone	DG Khan Construction Division	Project Circle DG Khan
Sr. No.	River Name	River System	Bank
P-006e	Indus River	Indus River	Right
Bund Name		R.D	GPS Coordinates
Left Bank of Link No. 1		RD 138+000- to 165+000 and 165+000 to 194+000	29°89'95."N, 70°75'5."E
Name of Vulnerable Point	Left Bank of Link No. 1 RD 138+000 to 165+000 and 165+000 to 194+000_5		
Reason for the Vulnerability	<ul style="list-style-type: none"> The said reach is no longer vulnerable, as the river is flowing approximately 5000 feet away from the left bank of link canal number 1 at this RD. There is no breach history of the left bank of link number 1 at this RD. 		
Flow Condition ¹	<ul style="list-style-type: none"> No flow conditions. River flows approximately 5000 feet away from this cross spur. 		
Site Condition in the Country Side ²	<ul style="list-style-type: none"> There is a cultivated lands on country side. There is a village Ghous Abad on either side of the link number 1. 		
Layout Plan (Source of Satellite Image: Google Earth)			
Evaluation ³			
Category	Quality Score		
Proactive Type C	3/9		








¹ Water Flow Direction and Conditions During Floods Around the Listed Vulnerable Points.

² Site Condition Around the Vulnerable Points (Rough Distance Between Main Water Channel and the Bund, Land Use Behind the Point, Important Facility Adjacent to the Point).



³ Emergent Type R: Emergent Phase Requiring Robust Countermeasures, Emergent Type C: Emergent Phase Requiring Common Countermeasures, Proactive Type R: Proactive Phase Requiring Robust Countermeasures, Proactive Type C: Proactive Phase Requiring Common Countermeasures, Monitoring: Monitoring Phase

Basic Information of the Bund																																																																																																																						
Basic Dimensions and Materials	Item	Existing	Proposed																																																																																																																			
	Top Elevation	389.60 feet	Not Applicable																																																																																																																			
	H.F.L	385.14 feet																																																																																																																				
	Free Board Height	4.46 feet																																																																																																																				
	Top Width	25 feet																																																																																																																				
	River Side Slope	1:2																																																																																																																				
	Country Side Slope	Left bank of link number 1																																																																																																																				
	Longitudinal Length	204500 feet																																																																																																																				
	Slope Protection Material	Earthen (Clay)																																																																																																																				
	Covering Material/ Pavement on the Top	Pavement on the top																																																																																																																				
	Embankment Material	Earthen (Clay)																																																																																																																				
Ancillary Structure (Drainage Ditch, and Spurs)	Not Applicable																																																																																																																					
Typical Cross Section																																																																																																																						
	<table border="1"> <thead> <tr> <th colspan="2">L BANK</th> <th>DESIGN</th> <th>AS BUILT</th> <th colspan="2">R BANK</th> <th>DESIGN</th> <th>AS BUILT</th> </tr> </thead> <tbody> <tr> <td>CUT</td> <td>6.49</td> <td></td> <td>0</td> <td>CUT</td> <td>0.42</td> <td></td> <td>0</td> </tr> <tr> <td>FILL</td> <td>15.75</td> <td></td> <td>0</td> <td>FILL</td> <td>0</td> <td></td> <td>0</td> </tr> </tbody> </table> <table border="1"> <thead> <tr> <th colspan="2">DESIGN</th> <th colspan="2">AS BUILT</th> </tr> </thead> <tbody> <tr> <td>LEVEL</td> <td></td> <td></td> <td></td> </tr> <tr> <td>OFFSET</td> <td></td> <td></td> <td></td> </tr> <tr> <td>LEVEL</td> <td>389.60</td> <td>389.60</td> <td>389.60</td> </tr> <tr> <td>OFFSET</td> <td>-57</td> <td>-43</td> <td>-36</td> </tr> <tr> <td>LEVEL</td> <td>388.14</td> <td>387.26</td> <td>384.96</td> </tr> <tr> <td>OFFSET</td> <td></td> <td>-32.45</td> <td>-28.7</td> </tr> <tr> <td>LEVEL</td> <td>385.14</td> <td>384.96</td> <td>384.96</td> </tr> <tr> <td>OFFSET</td> <td></td> <td>-28.7</td> <td>-24.4</td> </tr> <tr> <td>LEVEL</td> <td>382.45</td> <td>382.25</td> <td>381.8</td> </tr> <tr> <td>OFFSET</td> <td></td> <td>-22.25</td> <td>-20</td> </tr> <tr> <td>LEVEL</td> <td>381.22</td> <td>381.22</td> <td>381.22</td> </tr> <tr> <td>OFFSET</td> <td></td> <td>-16</td> <td>-10</td> </tr> <tr> <td>LEVEL</td> <td>379.15</td> <td>379.15</td> <td>379.15</td> </tr> <tr> <td>OFFSET</td> <td></td> <td>0</td> <td>0</td> </tr> <tr> <td>LEVEL</td> <td>380.29</td> <td>382.85</td> <td>381.8</td> </tr> <tr> <td>OFFSET</td> <td></td> <td>15</td> <td>19</td> </tr> <tr> <td>LEVEL</td> <td>381.22</td> <td>382.25</td> <td>381.8</td> </tr> <tr> <td>OFFSET</td> <td></td> <td>21</td> <td>24.4</td> </tr> <tr> <td>LEVEL</td> <td>380.7</td> <td>380.2</td> <td>380.2</td> </tr> <tr> <td>OFFSET</td> <td></td> <td>28.7</td> <td>31</td> </tr> <tr> <td>LEVEL</td> <td>382.45</td> <td>382.45</td> <td>382.45</td> </tr> <tr> <td>OFFSET</td> <td></td> <td>32.45</td> <td>32.45</td> </tr> </tbody> </table>			L BANK		DESIGN	AS BUILT	R BANK		DESIGN	AS BUILT	CUT	6.49		0	CUT	0.42		0	FILL	15.75		0	FILL	0		0	DESIGN		AS BUILT		LEVEL				OFFSET				LEVEL	389.60	389.60	389.60	OFFSET	-57	-43	-36	LEVEL	388.14	387.26	384.96	OFFSET		-32.45	-28.7	LEVEL	385.14	384.96	384.96	OFFSET		-28.7	-24.4	LEVEL	382.45	382.25	381.8	OFFSET		-22.25	-20	LEVEL	381.22	381.22	381.22	OFFSET		-16	-10	LEVEL	379.15	379.15	379.15	OFFSET		0	0	LEVEL	380.29	382.85	381.8	OFFSET		15	19	LEVEL	381.22	382.25	381.8	OFFSET		21	24.4	LEVEL	380.7	380.2	380.2	OFFSET		28.7	31	LEVEL	382.45	382.45	382.45	OFFSET		32.45
L BANK		DESIGN	AS BUILT	R BANK		DESIGN	AS BUILT																																																																																																															
CUT	6.49		0	CUT	0.42		0																																																																																																															
FILL	15.75		0	FILL	0		0																																																																																																															
DESIGN		AS BUILT																																																																																																																				
LEVEL																																																																																																																						
OFFSET																																																																																																																						
LEVEL	389.60	389.60	389.60																																																																																																																			
OFFSET	-57	-43	-36																																																																																																																			
LEVEL	388.14	387.26	384.96																																																																																																																			
OFFSET		-32.45	-28.7																																																																																																																			
LEVEL	385.14	384.96	384.96																																																																																																																			
OFFSET		-28.7	-24.4																																																																																																																			
LEVEL	382.45	382.25	381.8																																																																																																																			
OFFSET		-22.25	-20																																																																																																																			
LEVEL	381.22	381.22	381.22																																																																																																																			
OFFSET		-16	-10																																																																																																																			
LEVEL	379.15	379.15	379.15																																																																																																																			
OFFSET		0	0																																																																																																																			
LEVEL	380.29	382.85	381.8																																																																																																																			
OFFSET		15	19																																																																																																																			
LEVEL	381.22	382.25	381.8																																																																																																																			
OFFSET		21	24.4																																																																																																																			
LEVEL	380.7	380.2	380.2																																																																																																																			
OFFSET		28.7	31																																																																																																																			
LEVEL	382.45	382.45	382.45																																																																																																																			
OFFSET		32.45	32.45																																																																																																																			
History of Damages																																																																																																																						
MM/YYY Y	Type of Damage	Description																																																																																																																				
	Nil																																																																																																																					
Record of Rehabilitation/ Improvement																																																																																																																						
MM/YYY Y	Project Name and its Description	Cost	Source of Funding																																																																																																																			
	Nil																																																																																																																					
Plan for Rehabilitation/ Improvement																																																																																																																						
MM/YYY Y	Project Name and its Description	Cost	Source of Funding																																																																																																																			
	Nil																																																																																																																					

Site Photo		
Vulnerable Section	General View of River Side	
	Facing Downstream and Side	Facing Upstream Side
		
	General View of Top	
	Facing Downstream and Side	Facing Upstream Side
		
	General View of Landside	
	Facing Downstream and Side	Facing Upstream Side
		
	Close View of Deformation	
(Not Applicable)		
Close View of Damages		
(Not Applicable)		

	<p>Photo with 360° angles</p> 	
<p>Typical Section (Adjacent to the Vulnerable Point)</p>	<p>General View of River Side</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
	<p>General View of Top</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
	<p>General View of Landside</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 

	<p>Photo with 360° angles</p> 
<p>Downstream End of the Bund</p>	<p>General View</p> <p>(Not Applicable)</p>
	<p>Photo with 360° angles</p> <p>(Not Applicable)</p>
<p>Upstream End of the Bund</p>	<p>General View (In the case that the VP is located near the end)</p> <p>(Not Applicable)</p>
	<p>Photo with 360° angles</p> <p>(Not Applicable)</p>

Observation Record ⁴ (Current status, effect of countermeasure, development of erosion, deformation, deterioration)			
DD/MM/YYYY	Inspection Type	Description and Photo	Damage ⁵
01/3/2024	Visual Inspection	<ul style="list-style-type: none"> • River is situated approximately 5000 feet away from this RD. • There is a cultivated area on the countryside and an empty canal on the right side of the embankment. Reserve stock of stones on the left bank of link Nnumber 1 from RD 174+000 to 184+000.  <p>Cultivated area on countryside</p>  <p>Empty canal on the right side of the embankment</p>	a

⁴ Current Status, Effect of the Existing Structural Countermeasure Such as Spurs/studs, Sheet Piles for Seepage Control etc. and Development of Erosion, Deformation, Deterioration of the Existing Bund

⁵ a: No Deformation, b: No deformations are observed on the bund body, except for gully erosion caused by raindrops or the detachment of the bund's stone pitching, c: The bund or the apron has been damaged, and L: Leakage from the bund has been identified

Evaluation Process					
DD/MM/YYYY	Item		Result	Reason	
	Criteria For Evaluation Flow	Flood Damage		Yes	The inundation analysis indicates that the flood damage is severe
		Bund Damage		NO	There is no significant damage at present.
		Bund Dimension	Bund Height	Fail	Free board height is 4.5 feet.
			Bund Width	Fail	Evaluation is not possible based on the typical cross-section.
			Flood Plain Length	Fail	Floodplain length is about 5000 feet.
		Topographic Feature	Breach Record	No	There is no breach record.
	Flow Impact		NO	It hasn't been affected by strong water flow since before 2010 flood.	
	Category			Proactive Type C	
	For Evaluation Score	Bund Damage		0	There is no significant damage at present.
		Bund Dimension	Bund Height	1	Free board height is 4.5 feet.
			Bund Width	1	Evaluation is not possible based on the typical cross-section.
			Flood Plain Length	1	Floodplain length is about 5000 feet.
	Quality Score			3/9	


Note) HGL: hydraulic gradient line

Left Bank of Link Number 1 RD 192+000

Creation Date: 01/3/2024

Province	Zone	Division	Circle
Punjab	Dera Ghazi Khan Zone	DG Khan Construction Division	Project Circle DG Khan
Sr. No.	River Name	River System	Bank
P-006f	Indus River	Indus River	Right
Bund Name		R.D	GPS Coordinates
Left Bank of Link No. 1		RD 138+000 to165+000 and 165+000 to 194+000	29°88'18.33"N, 70°75'66.67"E
Name of Vulnerable Point	Left Bank of Link No. 1 RD 138+000 to 165+000 and 165+000 to194+000_6		
Reason for the Vulnerability	<ul style="list-style-type: none"> The said reach is no longer vulnerable, as the river is situated approximately 4700 feet away from the left bank of link canal number 1 at this RD. There is no breach history of the left bank of link number 1 at this RD. 		
Flow Condition ¹	<ul style="list-style-type: none"> No flow conditions. River flows approximately 4700 feet away from this cross spur. 		
Site Condition in the Country Side ²	<ul style="list-style-type: none"> There is a cultivated area on country side. Cross bridge present at RD 192+130 of link number 1 There is a village Udhana Wala on the country side of the right bank of the link number 1. 		

Layout Plan (Source of Satellite Image: Google Earth)



Evaluation³

Category	Quality Score
Proactive Type C	3/9


¹ Water Flow Direction and Conditions During Floods Around the Listed Vulnerable Points.

² Site Condition Around the Vulnerable Points (Rough Distance Between Main Water Channel and the Bund, Land Use Behind the Point, Important Facility Adjacent to the Point).

³ Emergent Type R: Emergent Phase Requiring Robust Countermeasures, Emergent Type C: Emergent Phase Requiring Common Countermeasures, Proactive Type R: Proactive Phase Requiring Robust Countermeasures, Proactive Type C: Proactive Phase Requiring Common Countermeasures, Monitoring: Monitoring Phase

Basic Information of the Bund

Basic Dimensions and Materials	Item	Existing	Proposed
	Top Elevation	389.60 feet	Not Applicable —
	H.F.L	384.17 feet	
	Free Board Height	5.43 feet	
	Top Width	25 feet	
	River Side Slope	1:2	
	Country Side Slope	Left bank of link number 1	
	Longitudinal Length	204500 feet	
	Slope Protection Material	Earthen (Clay)	
	Covering Material/ Pavement on the Top	Pavement on the top	
	Embankment Material	Earthen (Clay)	
Ancillary Structure (Drainage Ditch, and Spurs)	Not Applicable		



History of Damages







MM/YYYY	Type of Damage	Description
	Nil	








Record of Rehabilitation/ Improvement


MM/YYYY	Project Name and its Description	Cost	Source of Funding
	Nil		



Plan for Rehabilitation/ Improvement

MM/YYYY	Project Name and its Description	Cost	Source of Funding
	Nil		

Site Photo		
Vulnerable Section	General View of River Side	
	Facing Downstream and Side	Facing Upstream Side
		
	General View of Top	
	Facing Downstream and Side	Facing Upstream Side
		
	General View of Landside	
	Facing Downstream and Side	Facing Upstream Side
		
	Close View of Deformation (Not Applicable)	
Close View of Damages (Not Applicable)		

	<p>Photo with 360° angles</p> 	
<p>Typical Section (Adjacent to the Vulnerable Point)</p>	<p>General View of River Side</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
	<p>General View of Top</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
	<p>General View of Landside</p>	
	<p>Facing Downstream and Side</p>  <p>29.88587, 70.75727, 76.8m, 183°</p>	<p>Facing Upstream Side</p> 

	<p>Photo with 360° angles</p> 
<p>Downstream End of the Bund</p>	<p>General View</p> <p>(Not Applicable)</p>
	<p>Photo with 360° angles</p> <p>(Not Applicable)</p>
<p>Upstream End of the Bund</p>	<p>General View (In the case that the VP is located near the end)</p> <p>(Not Applicable)</p>
	<p>Photo with 360° angles</p> <p>(Not Applicable)</p>

Observation Record ⁴ (Current status, effect of countermeasure, development of erosion, deformation, deterioration)			
DD/MM/YYYY	Inspection Type	Description and Photo	Damage ⁵
01/3/2024	Visual Inspection	<ul style="list-style-type: none"> • River is situated approximately 4700 feet away from this RD. • Cultivated area is situated on country side and empty canal on the right side of the embankment. • There is a village Udhana Wala on the country side of the right bank of the link number 1.  <p>Cultivated area on country side</p>  <p>An empty canal is located on the right side of the embankment</p>	a

⁴ Current Status, Effect of the Existing Structural Countermeasure Such as Spurs/studs, Sheet Piles for Seepage Control etc. and Development of Erosion, Deformation, Deterioration of the Existing Bund

⁵ a: No Deformation, b: No deformations are observed on the bund body, except for gully erosion caused by raindrops or the detachment of the bund's stone pitching, c: The bund or the apron has been damaged, and L: Leakage from the bund has been identified

Evaluation Process					
DD/MM/YYYY	Item		Result	Reason	
	Criteria For Evaluation Flow	Flood Damage		Yes	The inundation analysis indicates that the flood damage is severe
		Bund Damage		NO	There is no significant damage at present.
		Bund Dimension	Bund Height	Fail	Free board height is 4.4 feet.
			Bund Width	Fail	Evaluation is not possible based on the typical cross-section.
			Flood Plain Length	Fail	Floodplain length is about 4700 feet.
		Topographic Feature	Breach Record	No	There is no breach record.
	Flow Impact		NO	It hasn't been affected by strong water flow since before 2010 flood.	
	Category			Proactive Type C	
	For Evaluation Score	Bund Damage		0	There is no significant damage at present.
		Bund Dimension	Bund Height	1	Free board height is 4.4 feet.
			Bund Width	1	Evaluation is not possible based on the typical cross-section.
			Flood Plain Length	1	Floodplain length is about 4700 feet.
	Quality Score			3/9	


Note) HGL: hydraulic gradient line

Jampur Flood Bund RD 7+000

Creation Date: 01/3/2024

Province	Zone	Division	Circle
Punjab	Dera Ghazi Khan Zone	Jampur Construction Division	Project Circle DG Khan
Sr. No.	River Name	River System	Bank
P-007	Indus River	Indus River	Right
Bund Name		R.D	GPS Coordinates
Jampur Flood Bund		RD 7+500 to 18+000	29°78'27.94"N, 70°71'23.54"E
Name of Vulnerable Point	Jampur Flood Bund at RD 7+500 to 18+000		
Reason for the Vulnerability	<ul style="list-style-type: none"> Jampur Flood Bund at this RD is no longer vulnerable, as the river is situated approximately 6 km away from said reach. 		
Flow Condition ¹	<ul style="list-style-type: none"> No flow conditions. River is situated approximately 6 km away from said reach. 		
Site Condition in the Country Side ²	<ul style="list-style-type: none"> Cultivated area is located on the country side, which is approximately 12 feet below the top level of bund. Village (Basti) Jakhar Imam shah is situated along the country side of the bund. 		

Layout Plan (Source of Satellite Image: Google Earth)



Evaluation³




















Category	Quality Score
Proactive Type C	0/9







¹ Water Flow Direction and Conditions During Floods Around the Listed Vulnerable Points.




² Site Condition Around the Vulnerable Points (Rough Distance Between Main Water Channel and the Bund, Land Use Behind the Point, Important Facility Adjacent to the Point).



³ Emergent Type R: Emergent Phase Requiring Robust Countermeasures, Emergent Type C: Emergent Phase Requiring Common Countermeasures, Proactive Type R: Proactive Phase Requiring Robust Countermeasures, Proactive Type C: Proactive Phase Requiring Common Countermeasures, Monitoring: Monitoring Phase

Basic Information of the Bund			
Basic Dimensions and Materials	Item	Existing	Proposed
	Top Elevation	371.8 feet	Not Applicable -
	H.F.L	358.90 feet	
	Free Board Height	12.90 feet	
	Top Width	25 feet	
	River Side Slope	1:3	
	Country Side Slope	1:2	
	Longitudinal Length	171000 feet	
	Slope Protection Material	Earthen (Silty clay)	
	Covering Material/ Pavement on the Top	Earthen (Silty clay)	
	Embankment Material	Earthen (Silty clay)	
Ancillary Structure (Drainage Ditch, and Spurs)	Not Applicable		
Typical Cross Section			
History of Damages			
MM/YYYY	Type of Damage	Description	
July-August 2010	Breaching/over topping	Maximum flood passed in River Indus along Jampur Flood Bund during the year 2010 (959991 Cs:). This caused main breached between RD 37 to 38 and breached randomly between RD 10 to 24 of Jampur Flood Bund. During the year 2010, flood water of River Indus also entered the city of Jampur and Rajanpur which caused the serious damages to Govt./ public property, schools, graveyard etc.	
Record of Rehabilitation/ Improvement			
MM/YYYY	Project Name and its Description	Cost	Source of Funding
2011	Maintenance and Repair (M&R)	Not provided by PID	Maintenance and repair Works
2012	Annual Development Program (ADP) in which Jampur bypass Jampur Flood Bund restored wholly to save the allied villages and irrigation infrastructure.	Not provided by PID	Annual Development Program 2012 of Punjab Irrigation Department (PID)
Plan for Rehabilitation/ Improvement			
MM/YYYY	Project Name and its Description	Cost	Source of Funding
	Nil		

Site Photo					
Vulnerable Section	General View of River Side				
	<table border="1"> <tr> <td>Facing Downstream and Side</td> <td>Facing Upstream Side</td> </tr> <tr> <td></td> <td></td> </tr> </table>	Facing Downstream and Side	Facing Upstream Side		
	Facing Downstream and Side	Facing Upstream Side			
					
	General View of Top				
	<table border="1"> <tr> <td>Facing Downstream and Side</td> <td>Facing Upstream Side</td> </tr> <tr> <td></td> <td></td> </tr> </table>	Facing Downstream and Side	Facing Upstream Side		
	Facing Downstream and Side	Facing Upstream Side			
					
	General View of Landside				
	<table border="1"> <tr> <td>Facing Downstream and Side</td> <td>Facing Upstream Side</td> </tr> <tr> <td></td> <td></td> </tr> </table>	Facing Downstream and Side	Facing Upstream Side		
Facing Downstream and Side	Facing Upstream Side				
					
Close View of Deformation					
					
Close View of Damages					
(Not Applicable)					

	<p>Photo with 360° angles</p> 	
<p>Typical Section (Adjacent to the Vulnerable Point)</p>	<p>General View of River Side</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
	<p>General View of Top</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
<p>General View of Landside</p>		
<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 	

	<p>Photo with 360° angles</p> 
<p>Downstream End of the Bund</p>	<p>General View</p> <p>(Not Applicable)</p>
	<p>Photo with 360° angles</p> <p>(Not Applicable)</p>
<p>Upstream End of the Bund</p>	<p>General View (In the case that the VP is located near the end)</p> 
	<p>Photo with 360° angles</p> 

Observation Record ⁴ (Current status, effect of countermeasure, development of erosion, deformation, deterioration)			
DD/MM/YYYY	Inspection Type	Description and Photo	Damage ⁵
01/3/2024	Visual Inspection	<ul style="list-style-type: none"> • Cultivated area is located on the country side, which is approximately 13 feet below the top level of bund. • Bast Jakhar Imam Shah is located on the country of the bund. • Design parameters (Top level, top width, and side slopes) of the bund was not well maintained.  <p>Cultivated area on the country side</p>  <p>Design parameters of the bund was not well maintained</p>	a

⁴ Current Status, Effect of the Existing Structural Countermeasure Such as Spurs/studs, Sheet Piles for Seepage Control etc. and Development of Erosion, Deformation, Deterioration of the Existing Bund

⁵ a: No Deformation, b: No deformations are observed on the bund body, except for gully erosion caused by raindrops or the detachment of the bund's stone pitching, c: The bund or the apron has been damaged, and L: Leakage from the bund has been identified

Evaluation Process					
DD/MM/YYYY	Item		Result	Reason	
	Criteria For Evaluation Flow	Flood Damage		No	The inundation analysis indicates that the flood damage is not severe.
		Bund Damage		NO	There is no significant damage at present.
		Bund Dimension	Bund Height	Pass	Free board height is 7 feet.
			Bund Width	Pass	The soil cover thickness over HGL exceeds the guideline value (Soil Depth \geq 2 feet)
			Flood Plain Length	Pass	Floodplain length is about 19700 feet.
		Topographic Feature	Breach Record	Yes	It has breached in the past.
			Flow Impact	NO	It hasn't been affected by strong water flow since before 2010 flood.
	Category			Proactive Type C	
	For Evaluation Score	Bund Damage		0	There is no significant damage at present.
		Bund Dimension	Bund Height	0	Free board height is 7 feet.
			Bund Width	0	The soil cover thickness over HGL exceeds the guideline value (Soil Depth \geq 2 feet)
			Flood Plain Length	0	Floodplain length is about 19700 feet.
	Quality Score			0/9	

Note) HGL: hydraulic gradient line

Jampur Flood Bund RD 107+000 to RD 108+000

Creation Date: 01/3/2024



















Province	Zone	Division	Circle
Punjab	Dera Ghazi Khan Zone	Jampur Construction Division	Project Circle DG Khan
Sr. No.	River Name	River System	Bank
P-008a	Indus River	Indus River	Right
Bund Name		R.D	GPS Coordinates
Jampur Flood Bund		RD 107+000 to 113+000	29°55'64.77"N, 70°61'11.53"E
Name of Vulnerable Point	Jampur Flood Bund at RD 107+000 to 113+000_1		
Reason for the Vulnerability	<ul style="list-style-type: none"> Jampur Flood Bund at this RD is no longer vulnerable due to: <ol style="list-style-type: none"> River is approximately 5 km away from said reach Jampur Flood Bund is 2nd defense line at the right bank of River Indus. 		
Flow Condition ¹	<ul style="list-style-type: none"> No flow conditions. 		
Site Condition in the Country Side ²	<ul style="list-style-type: none"> Cultivated area is present on the country side, which is approximately 15 feet below the top level of bund. Village Bindri Shoar and Kotla Mughlan rest house are situated on the country side of the bund. 		
Layout Plan (Source of Satellite Image: Google Earth)			
Evaluation ³			
Category		Quality Score	
Monitoring		1/9	

¹ Water Flow Direction and Conditions During Floods Around the Listed Vulnerable Points.




² Site Condition Around the Vulnerable Points (Rough Distance Between Main Water Channel and the Bund, Land Use Behind the Point, Important Facility Adjacent to the Point).



³ Emergent Type R: Emergent Phase Requiring Robust Countermeasures, Emergent Type C: Emergent Phase Requiring Common Countermeasures, Proactive Type R: Proactive Phase Requiring Robust Countermeasures, Proactive Type C: Proactive Phase Requiring Common Countermeasures, Monitoring: Monitoring Phase

Basic Information of the Bund			
Basic Dimensions and Materials	Item	Existing	Proposed
	Top Elevation	357.90 feet	Not Applicable —
	H.F.L	351.30 feet	
	Free Board Height	6.60 feet	
	Top Width	25 feet	
	River Side Slope	1:3	
	Country Side Slope	1:2	
	Longitudinal Length	171000 feet	
	Slope Protection Material	Earthen (Silty clay)	
	Covering Material/ Pavement on the Top	Earthen (Silty clay)	
	Embankment Material	Earthen (Silty clay)	
Ancillary Structure (Drainage Ditch, and Spurs)	Not Applicable		
Typical Cross Section *(Prepared by the team, not provided by PID)	JAMPUR FLOOD BUND RD 107+000		
History of Damages			
MM/YYYY	Type of Damage	Description	
July-August 2010	Breaching/over topping	Maximum flood passed in River Indus along Jampur Flood Bund during the year 2010 (959991 Cs:). This caused main breached between RD 37 to 38 and breached randomly between RD 10 to 24 of Jampur Flood Bund. During the year 2010, flood water of mighty River Indus also entered the city of Jampur and Rajanpur which caused the serious damages to Govt./public property, schools, graveyard etc.	
Record of Rehabilitation/ Improvement			
MM/YYYY	Project Name and its Description	Cost	Source of Funding
2011	Maintenance and Repair (M&R)	Not provided by PID	Maintenance and repair Works
2012	The Annual Development Program (ADP) included the full restoration of the Jampur Bypass Flood Bund to protect the surrounding villages and irrigation infrastructure.	Not provided by PID	Annual Development Program 2012 of Punjab Irrigation Department (PID)
Plan for Rehabilitation/ Improvement			
MM/YYYY	Project Name and its Description	Cost	Source of Funding
	Nil		

Site Photo					
Vulnerable Section	General View of River Side				
	<table border="1"> <tr> <td>Facing Downstream and Side</td> <td>Facing Upstream Side</td> </tr> <tr> <td></td> <td></td> </tr> </table>	Facing Downstream and Side	Facing Upstream Side		
	Facing Downstream and Side	Facing Upstream Side			
					
	General View of Top				
	<table border="1"> <tr> <td>Facing Downstream and Side</td> <td>Facing Upstream Side</td> </tr> <tr> <td></td> <td></td> </tr> </table>	Facing Downstream and Side	Facing Upstream Side		
	Facing Downstream and Side	Facing Upstream Side			
					
	General View of Landside				
	<table border="1"> <tr> <td>Facing Downstream and Side</td> <td>Facing Upstream Side</td> </tr> <tr> <td></td> <td></td> </tr> </table>	Facing Downstream and Side	Facing Upstream Side		
	Facing Downstream and Side	Facing Upstream Side			
					
Close View of Deformation	(Not Applicable)				
Close View of Damages	(Not Applicable)				

	<p>Photo with 360⁰ angles</p> 	
<p>Typical Section (Adjacent to the Vulnerable Point)</p>	<p>General View of River Side</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
	<p>General View of Top</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
<p>General View of Landside</p>		
<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 	

	<p>Photo with 360° angles</p> 
<p>Downstream End of the Bund</p>	<p>General View</p> <p>(Not Applicable)</p>
	<p>Photo with 360° angles</p> <p>(Not Applicable)</p>
<p>Upstream End of the Bund</p>	<p>General View (In the case that the VP is located near the end)</p> 
	<p>Photo with 360° angles</p> 

Observation Record ⁴ (Current status, effect of countermeasure, development of erosion, deformation, deterioration)			
DD/MM/YYYY	Inspection Type	Description and Photo	Damage ⁵
01/3/2024	Visual Inspection	<ul style="list-style-type: none"> • Cultivated area is present on the country side, which is approximately 15 feet below the top level of bund. • Village Bindri Shoar and Kot Mughlan rest house are situated on the country side of the bund • Design parameters (Top level, top width, and side slopes) of the bund was not well maintained.  <p>Cultivated area on the country side</p>  <p>Rain cuts observed on side slopes</p>	A

⁴ Current Status, Effect of the Existing Structural Countermeasure Such as Spurs/studs, Sheet Piles for Seepage Control etc. and Development of Erosion, Deformation, Deterioration of the Existing Bund

⁵ a: No Deformation, b: No deformations are observed on the bund body, except for gully erosion caused by raindrops or the detachment of the bund's stone pitching, c: The bund or the apron has been damaged, and L: Leakage from the bund has been identified

Evaluation Process					
DD/MM/YYYY	Item		Result	Reason	
	Criteria For Evaluation Flow	Flood Damage		No	The inundation analysis indicates that the flood damage is not severe.
		Bund Damage		NO	There is no significant damage at present.
		Bund Dimension	Bund Height	Fail	Free board height is 6.6 feet.
			Bund Width	Pass	The soil cover thickness over HGL exceeds the guideline value (Soil Depth \geq 2 feet)
			Flood Plain Length	Pass	Floodplain length is about 16400 feet.
		Topographic Feature	Breach Record	Yes	It has breached in the past.
			Flow Impact	NO	It hasn't been affected by strong water flow since before 2010 flood.
	Category			Monitoring	
	For Evaluation Score	Bund Damage		0	There is no significant damage at present.
		Bund Dimension	Bund Height	1	Free board height is 6.6 feet.
			Bund Width	0	The soil cover thickness over HGL exceeds the guideline value (Soil Depth \geq 2 feet)
			Flood Plain Length	0	Floodplain length is about 16400 feet.
	Quality Score			1/9	


Note) HGL: hydraulic gradient line

Jampur Flood Bund RD 112+000

Creation Date: 01/3/2024

Province	Zone	Division	Circle
Punjab	Dera Ghazi Khan Zone	Jampur Construction Division	Project Circle DG Khan
Sr. No.	River Name	River System	Bank
P-008b	Indus River	Indus River	Right
Bund Name		R.D	GPS Coordinates
Jampur Flood Bund		RD 107+000 to 113+000	29°54'73.17"N, 70°61'72.68"E
Name of Vulnerable Point	Jampur Flood Bund at RD 107+000 to 113+000_2		
Reason for the Vulnerability	<ul style="list-style-type: none"> Jampur Flood Bund at this RD is no longer vulnerable due to: <ol style="list-style-type: none"> The river is located 3.5 km away from the said reach. Jampur Flood Bund is 2nd defense line at the right bank of River Indus. 		
Flow Condition ¹	<ul style="list-style-type: none"> No flow conditions. 		
Site Condition in the Country Side ²	<ul style="list-style-type: none"> Cultivated area is present on the country side, which is approximately 20 feet below the top level of bund. Village kotla Mughlan is situated on the country side of the bund. 		

Layout Plan (Source of Satellite Image: Google Earth)



Evaluation³

Category	Quality Score
Monitoring	1/9








¹ Water Flow Direction and Conditions During Floods Around the Listed Vulnerable Points.


² Site Condition Around the Vulnerable Points (Rough Distance Between Main Water Channel and the Bund, Land Use Behind the Point, Important Facility Adjacent to the Point).



³ Emergent Type R: Emergent Phase Requiring Robust Countermeasures, Emergent Type C: Emergent Phase Requiring Common Countermeasures, Proactive Type R: Proactive Phase Requiring Robust Countermeasures, Proactive Type C: Proactive Phase Requiring Common Countermeasures, Monitoring: Monitoring Phase

Basic Information of the Bund			
Basic Dimensions and Materials	Item	Existing	Proposed
	Top Elevation	357.90 feet	Not Applicable —
	H.F.L	350.90 feet	
	Free Board Height	7.00 feet	
	Top Width	20 feet	
	River Side Slope	1:3	
	Country Side Slope	1:2	
	Longitudinal Length	171000 feet	
	Slope Protection Material	Earthen (Silty clay)	
	Covering Material/ Pavement on the Top	Earthen (Silty clay)	
	Embankment Material	Earthen (Silty clay)	
	Ancillary Structure (Drainage Ditch, and Spurs)	Not Applicable	
Typical Cross Section *(Prepared by the team, not provided by PID)	<p style="text-align: center;">JAMPUR FLOOD BUND RD 112+000</p> <p style="text-align: center;">Top Elevation 357.90 ft 25' Top Width</p> <p style="text-align: center;">1 3 1 2</p> <p style="text-align: right;">NSL 337.90 ft</p>		
History of Damages			
MM/YYYY	Type of Damage	Description	
July-August 2010	Breaching/over topping	Maximum flood passed in River Indus along Jampur Flood Bund during the year 2010 (959991 Cs:). This caused main breached between RD 37 to 38 and breached randomly between RD 10 to 24 of Jampur Flood Bund. During the year 2010, flood water of mighty River Indus also entered the city of Jampur and Rajanpur which caused the serious damages to Govt./public property, schools, graveyard etc.	
Record of Rehabilitation/ Improvement			
MM/YYYY	Project Name and its Description	Cost	Source of Funding
2011	Maintenance and Repair (M&R)	Not provided by PID	Maintenance and Repair Works
2012	Annual Development Program (ADP included the complete restoration of the Jampur Bypass Flood Bund to protect the surrounding villages and irrigation infrastructure.	Not provided by PID	Annual Development Program 2012 of Punjab Irrigation Department (PID)
Plan for Rehabilitation/ Improvement			
MM/YYYY	Project Name and its Description	Cost	Source of Funding
	Nil		

Site Photo		
Vulnerable Section	General View of River Side	
	Facing Downstream and Side	Facing Upstream Side
		
	General View of Top	
	Facing Downstream and Side	Facing Upstream Side
		
	General View of Landside	
	Facing Downstream and Side	Facing Upstream Side
		
	Close View of Deformation	
(Not Applicable)		
Close View of Damages		
(Not Applicable)		

	<p>Photo with 360° angles</p> 	
<p>Typical Section (Adjacent to the Vulnerable Point)</p>	<p>General View of River Side</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
	<p>General View of Top</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
	<p>General View of Landside</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 

	<p>Photo with 360° angles</p> 
<p>Downstream End of the Bund</p>	<p>General View</p> <p>(Not Applicable)</p>
	<p>360 Degrees Photo</p> <p>(Not Applicable)</p>
<p>Upstream End of the Bund</p>	<p>General View (In the case that the VP is located near the end)</p> 
	<p>Photo with 360° angles</p> 

Observation Record ⁴ (Current status, effect of countermeasure, development of erosion, deformation, deterioration)			
DD/MM/YYYY	Inspection Type	Description and Photo	Damage ⁵
01/3/2024	Visual Inspection	<ul style="list-style-type: none"> • Cultivated area is present on the country side, which is approximately 20 feet below the top level of bund. • Village Kotla Mughlan is situated on the country side of the bund • A gauge pillar is observed on the river side at this RD. • In 2010 flood, Jampur Flood Bund was the 1st defense line and was vulnerable. The bund was breached from RD 70+000 to 75+000. • Design parameters (Top level, top width, and side slopes) of the bund was not well maintained.  <p>Cultivated area on the country side</p>  <p>Design parameters of the bund was not well maintained</p>	a

⁴ Current Status, Effect of the Existing Structural Countermeasure Such as Spurs/studs, Sheet Piles for Seepage Control etc. and Development of Erosion, Deformation, Deterioration of the Existing Bund

⁵ a: No Deformation, b: No deformations are observed on the bund body, except for gully erosion caused by raindrops or the detachment of the bund's stone pitching, c: The bund or the apron has been damaged, and L: Leakage from the bund has been identified

Evaluation Process					
DD/MM/YYYY	Item		Result	Reason	
	Criteria For Evaluation Flow	Flood Damage		No	The inundation analysis indicates that the flood damage is not severe.
		Bund Damage		NO	There is no significant damage at present.
		Bund Dimension	Bund Height	Pass	Free board height is 7 feet.
			Bund Width	Fail	The HGL isn't exposed above the ground, but the soil cover thickness over HGL is less than the guideline value (2 feet > Soil Depth \geq 0 feet).
			Flood Plain Length	Pass	Floodplain length is about 11500 feet.
		Topographic Feature	Breach Record	Yes	It has breached in the past.
	Flow Impact		NO	It hasn't been affected by strong water flow since before 2010 flood.	
	Category			Monitoring	
	For Evaluation Score	Bund Damage		0	There is no significant damage at present.
		Bund Dimension	Bund Height	0	Free board height is 7 feet.
			Bund Width	1	The HGL isn't exposed above the ground, but the soil cover thickness over HGL is less than the guideline value (2 feet > Soil Depth \geq 0 feet).
			Flood Plain Length	0	Floodplain length is about 11500 feet.
	Quality Score			1/9	

Note) HGL: hydraulic gradient line

Jampur Flood Bund RD 144+000 to RD 145+000

Creation Date: 01/3/2024







Province	Zone	Division	Circle
Punjab	Dera Ghazi Khan Zone	Jampur Construction Division	Project Circle DG Khan
Sr. No.	River Name	River System	Bank
P-009a	Indus River	Indus River	Right
Bund Name		R.D	GPS Coordinates
Jampur Flood Bund		RD 139+000 to 171+000	29°46'92.99"N, 70°59'48.59"E
Name of Vulnerable Point	Jampur Flood Bund at RD 139+000 to 171+000_1		
Reason for the Vulnerability	<ul style="list-style-type: none"> Jampur Flood Bund at this RD is no longer vulnerable due to: <ol style="list-style-type: none"> River is situated approximately 5 km away from said reach There is no history of breaches at this location of Jampur Flood Bund. 		
Flow Condition ¹	<ul style="list-style-type: none"> No flow conditions 		
Site Condition in the Country Side ²	<ul style="list-style-type: none"> Cultivated area is present on the country side, which is approximately 18 feet below the top level of bund. 		
Layout Plan (Source of Satellite Image: Google Earth)			
Evaluation ³			
Category		Quality Score	
Monitoring		0/9	

¹ Water Flow Direction and Conditions During Floods Around the Listed Vulnerable Points.




² Site Condition Around the Vulnerable Points (Rough Distance Between Main Water Channel and the Bund, Land Use Behind the Point, Important Facility Adjacent to the Point).



³ Emergent Type R: Emergent Phase Requiring Robust Countermeasures, Emergent Type C: Emergent Phase Requiring Common Countermeasures, Proactive Type R: Proactive Phase Requiring Robust Countermeasures, Proactive Type C: Proactive Phase Requiring Common Countermeasures, Monitoring: Monitoring Phase

Basic Information of the Bund				
Basic Dimensions and Materials	Item	Existing	Proposed	
	Top Elevation	350.90 feet	Not Applicable	
	H.F.L	343.90 feet		
	Free Board Height	7.00 feet		
	Top Width	25 feet		
	River Side Slope	1:3		
	Country Side Slope	1:2		
	Longitudinal Length	171000 feet		
	Slope Protection Material	Earthen (Silty clay)		
	Covering Material/ Pavement on the Top	Metaled road on the top		
	Embankment Material	Earthen (Silty clay)		
	Ancillary Structure (Drainage Ditch, and Spurs)	Not Applicable		
	Typical Cross Section *(Prepared by the team, not provided by PID)	<p style="text-align: center;">JAMPUR FLOOD BUND RD 144+000</p>		
<p style="text-align: center;">Top Elevation 350.90 ft 25' Top Width</p> <p style="text-align: center;">1:3 1:2</p> <p style="text-align: right;">NSL 339.90 ft</p>				
History of Damages				
MM/YYYY	Type of Damage	Description		
July-August 2010	Breaching/over topping	Maximum flood passed in River Indus along Jampur Flood Bund during the year 2010 (959991 Cs:). This caused main breached between RD 37 to 38 and breached randomly between RD 10 to 24 of Jampur Flood Bund. During the year 2010, flood water of mighty River Indus also entered the city of Jampur and Rajanpur which caused the serious damages to Govt./public property, schools, graveyard etc.		
Record of Rehabilitation/ Improvement				
MM/YYYY	Project Name and its Description	Cost	Source of Funding	
2011	Maintenance and Repair (M&R)	Not provided by PID	Maintenance and repair works	
2012	Annual Development Program (ADP) included the complete restoration of the Jampur Bypass Flood Bund to protect the surrounding villages and irrigation infrastructure.	Not provided by PID	Annual Development Program 2012 of Punjab Irrigation Department (PID)	
Plan for Rehabilitation/ Improvement				
MM/YYYY	Description/Project Name	Cost	Fund Source	
	Nil			

Site Photo					
Vulnerable Section	General View of River Side				
	<table border="1"> <tr> <td>Facing Downstream and Side</td> <td>Facing Upstream Side</td> </tr> <tr> <td></td> <td></td> </tr> </table>	Facing Downstream and Side	Facing Upstream Side		
	Facing Downstream and Side	Facing Upstream Side			
					
	General View of Top				
	<table border="1"> <tr> <td>Facing Downstream and Side</td> <td>Facing Upstream Side</td> </tr> <tr> <td></td> <td></td> </tr> </table>	Facing Downstream and Side	Facing Upstream Side		
	Facing Downstream and Side	Facing Upstream Side			
					
	General View of Landside				
	<table border="1"> <tr> <td>Facing Downstream and Side</td> <td>Facing Upstream Side</td> </tr> <tr> <td></td> <td></td> </tr> </table>	Facing Downstream and Side	Facing Upstream Side		
Facing Downstream and Side	Facing Upstream Side				
					
Close View of Deformation	(Not Applicable)				
Close View of Damages	(Not Applicable)				

	<p>Photo with 360° angles</p> 	
<p>Typical Section (Adjacent to the Vulnerable Point)</p>	<p>General View of River Side</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
	<p>General View of Top</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
	<p>General View of Landside</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 

	<p>Photo with 360° angles</p> 
<p>Downstream End of the Bund</p>	<p>General View</p> <p>(Not Applicable)</p>
	<p>Photo with 360° angles</p> <p>(Not Applicable)</p>
<p>Upstream End of the Bund</p>	<p>General View (In the case that the VP is located near the end)</p> 
	<p>Photo with 360° angles</p> 

Observation Record ⁴ (Current status, effect of countermeasure, development of erosion, deformation, deterioration)			
DD/MM/YYYY	Inspection Type	Description and Photo	Damage ⁵
01/3/2024	Visual Inspection	<ul style="list-style-type: none"> • Cultivated area is present on the country side, which is approximately 18 feet below the top level of bund. • Design parameters (Top level, top width, and side slopes) of the bund was not well maintained.  <p>Cultivated area on the country side</p>  <p>Design parameters of the bund was not well maintained</p>	a

⁴ Current Status, Effect of the Existing Structural Countermeasure Such as Spurs/studs, Sheet Piles for Seepage Control etc. and Development of Erosion, Deformation, Deterioration of the Existing Bund

⁵ a: No Deformation, b: No deformations are observed on the bund body, except for gully erosion caused by raindrops or the detachment of the bund's stone pitching, c: The bund or the apron has been damaged, and L: Leakage from the bund has been identified

Evaluation Process					
DD/MM/YYYY	Item		Result	Reason	
	Criteria For Evaluation Flow	Flood Damage		No	The inundation analysis indicates that the flood damage is not severe.
		Bund Damage		NO	There is no significant damage at present.
		Bund Dimension	Bund Height	Pass	Free board height is 7 feet.
			Bund Width	Pass	The soil cover thickness over HGL exceeds the guideline value (Soil Depth \geq 2 feet)
			Flood Plain Length	Pass	Floodplain length is about 16400 feet.
		Topographic Feature	Breach Record	Yes	It has breached in the past.
			Flow Impact	NO	It hasn't been affected by strong water flow since before 2010 flood.
	Category			Monitoring	
	For Evaluation Score	Bund Damage		0	There is no significant damage at present.
		Bund Dimension	Bund Height	0	Free board height is 7 feet.
			Bund Width	0	The soil cover thickness over HGL exceeds the guideline value (Soil Depth \geq 2 feet)
			Flood Plain Length	0	Floodplain length is about 16400 feet.
	Quality Score			0/9	

Note) HGL: hydraulic gradient line

Jampur Flood Bund RD 171+000

Creation Date: 01/3/2024

Province	Zone	Division	Circle
Punjab	Dera Ghazi Khan Zone	Jampur Construction Division	Project Circle DG Khan
Sr. No.	River Name	River System	Bank
P-009b	Indus River	Indus River	Right
Bund Name		R.D.	GPS Coordinates
Jampur Flood Bund		RD 139+000 to 171+000	29°40'52.4"N, 70°60'66.55"E
Name of Vulnerable Point	Jampur Flood Bund at RD 139+000 to 171+000_2		
Reason for the Vulnerability	<ul style="list-style-type: none"> Jampur Flood Bund at this RD is no longer vulnerable due to: <ol style="list-style-type: none"> River is approximately 9 km away from said reach There is no breach history at this location of Jampur Flood Bund. 		
Flow Condition ¹	<ul style="list-style-type: none"> No flow conditions. 		
Site Condition in the Country Side ²	<ul style="list-style-type: none"> Cultivated area is present on the country side, which is approximately 10 feet below the top level of bund. 		
Layout Plan (Source of Satellite Image: Google Earth)			
Evaluation ³			
Category		Quality Score	
Monitoring		1/9	








¹ Water Flow Direction and Conditions During Floods Around the Listed Vulnerable Points.




² Site Condition Around the Vulnerable Points (Rough Distance Between Main Water Channel and the Bund, Land Use Behind the Point, Important Facility Adjacent to the Point).



³ Emergent Type R: Emergent Phase Requiring Robust Countermeasures, Emergent Type C: Emergent Phase Requiring Common Countermeasures, Proactive Type R: Proactive Phase Requiring Robust Countermeasures, Proactive Type C: Proactive Phase Requiring Common Countermeasures, Monitoring: Monitoring Phase

Basic Information of the Bund			
Basic Dimensions and Materials	Item	Existing	Proposed
	Top Elevation	344.90 feet	Not Applicable -
	H.F. L	338.70 feet	
	Free Board Height	6.20 feet	
	Top Width	25 feet	
	River Side Slope	1:3	
	Country Side Slope	1:2	
	Longitudinal Length	171000 feet	
	Slope Protection Material	Earthen (Silty clay)	
	Covering Material/ Pavement on the Top	Earthen (Silty clay)	
	Embankment Material	Earthen (Silty clay)	
	Ancillary Structure (Drainage Ditch, and Spurs)	Not Applicable	
Typical Cross Section *(Prepared by the team, not provided by PID)	<p style="text-align: center;">JAMPUR FLOOD BUND RD 171+000</p> <p style="text-align: center;">Top Elevation 344.90 ft 25' Top Width</p> <p style="text-align: center;">1:3 1:2</p> <p style="text-align: right;">NSL 334.90 ft</p>		
History of Damages			
MM/YYYY	Type of Damage	Description	
July-August 2010	Breaching/over topping	Maximum flood passed in River Indus along Jampur Flood Bund during the year 2010 (959991 Cs:). This caused main breached between RD 37 to 38 and breached randomly between RD 10 to 24 of Jampur Flood Bund. During the year 2010, flood water of mighty River Indus also entered the city of Jampur and Rajanpur which caused the serious damages to Govt./public property, schools, graveyard etc.	
Record of Rehabilitation/ Improvement			
MM/YYYY	Project Name with its Description	Cost	Source of Funding
2011	Maintenance and Repair (M&R)	Not provided by PID	Maintenance and repairworks
2012	Annual Development Program (ADP) included the full restoration of the Jampur Bypass Flood Bund to protect the surrounding villages and irrigation infrastructure.	Not provided by PID	Annual Development Program 2012 of Punjab Irrigation Department (PID)
Plan for Rehabilitation/ Improvement			
MM/YYYY	Project Name and its Description	Cost	Source of Funding
	Nil		

Site Photo		
Vulnerable Section	General View of River Side	
	Facing Downstream and Side	Facing Upstream Side
		
	General View of Top	
	Facing Downstream and Side	Facing Upstream Side
		
	General View of Landside	
	Facing Downstream and Side	Facing Upstream Side
		
	Close View of Deformation	
	(Not Applicable)	
	Close View of Damages	
(Not Applicable)		

	<p>Photo with 360° angles</p> 	
<p>Typical Section (Adjacent to the Vulnerable Point)</p>	<p>General View of River Side</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
	<p>General View of Top</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
	<p>General View of Landside</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 

	<p>Photo with 360° angles</p> 
<p>Downstream End of the Bund</p>	<p>General View</p> <p>(Not Applicable)</p>
	<p>Photo with 360° angles</p> <p>(Not Applicable)</p>
<p>Upstream End of the Bund</p>	<p>General View (In the case that the VP is located near the end)</p>  <p>Photo with 360° angles</p> 

Observation Record ⁴ (Current status, effect of countermeasure, development of erosion, deformation, deterioration)			
DD/MM/YYYY	Inspection Type	Description and Photo	Damage ⁵
01/3/2024	Visual Inspection	<ul style="list-style-type: none"> • Cultivated area is present on the country side, which is approximately 10 feet below the top level of bund. • Design parameters (Top level, top width, and side slopes) of the bund was not well maintained.  <p>Cultivated area on the country side</p>  <p>Design parameters of the bund was not well maintained</p>	a

⁴ Current Status, Effect of the Existing Structural Countermeasure Such as Spurs/studs, Sheet Piles for Seepage Control etc. and Development of Erosion, Deformation, Deterioration of the Existing Bund

⁵ a: No Deformation, b: No deformations are observed on the bund body, except for gully erosion caused by raindrops or the detachment of the bund's stone pitching, c: The bund or the apron has been damaged, and L: Leakage from the bund has been identified

Evaluation Process					
DD/MM/YYYY	Item		Result	Reason	
	Criteria For Evaluation Flow	Flood Damage		No	The inundation analysis indicates that the flood damage is not severe.
		Bund Damage		NO	There is no significant damage at present.
		Bund Dimension	Bund Height	Fail	Free board height is 6.2 feet.
			Bund Width	Pass	The soil cover thickness over HGL exceeds the guideline value (Soil Depth \geq 2 feet)
			Flood Plain Length	Pass	Floodplain length is about 16800 feet.
		Topographic Feature	Breach Record	Yes	It has breached in the past.
			Flow Impact	NO	It hasn't been affected by strong water flow since before 2010 flood.
	Category			Monitoring	
	For Evaluation Score	Bund Damage		0	There is no significant damage at present.
		Bund Dimension	Bund Height	1	Free board height is 6.2 feet.
			Bund Width	0	The soil cover thickness over HGL exceeds the guideline value (Soil Depth \geq 2 feet)
			Flood Plain Length	0	Floodplain length is about 16800 feet.
	Quality Score			1/9	

Note) HGL: hydraulic gradient line

Fakhar Flood Bund RD 10+000 to 11+000

Creation Date: 02/3/2024

Province	Zone	Division	Circle
Punjab	Dera Ghazi Khan Zone	Jampur Construction Division	Project Circle DG Khan
Sr. No.	River Name	River System	Bank
P-010a	Indus River	Indus River	Right
Bund Name		R.D	GPS Coordinates
Fakhar Flood bund		RD 10+000 to 24+500	28°95'58.48"N, 70°39'06.66"E
Name of Vulnerable Point	Fakhar flood bund at RD 10+000 to 24+500_1		
Reason for the Vulnerability	<ul style="list-style-type: none"> Fakhar flood bund at this RD was vulnerable in 2010 flood, as the Indus River breached and washed out the entire bund due to overtopping. This reach is no longer vulnerable, as the main creek of the river is now approximately 12 km away from the said reach. The bund was restored in 2020 to the highest flood level recorded during the 2010 flood. 		
Flow Condition ¹	<ul style="list-style-type: none"> No flow conditions. 		
Site Condition in the Country Side ²	<ul style="list-style-type: none"> Cultivated area is present on the country side, which is approximately 18 feet below the top level of bund. 		
Layout Plan (Source of Satellite Image: Google Earth)			
Evaluation ³			
Category		Quality Score	
Proactive Type R		1/9	

¹ Water Flow Direction and Conditions During Floods Around the Listed Vulnerable Points

² Site Condition Around the Vulnerable Points (Rough Distance Between Main Water Channel and the Bund, Land Use Behind the Point, Important Facility Adjacent to the Point)




³ Emergent Type R: Emergent Phase Requiring Robust Countermeasures , Emergent Type C: Emergent Phase Requiring Common Countermeasures, Proactive Type R: Proactive Phase Requiring Robust Countermeasures, Proactive Type C: Proactive Phase Requiring Common Countermeasures, Monitoring: Monitoring Phase

Basic Information of the Bund																																																																																			
Basic Dimensions and Materials	Item	Existing	Proposed																																																																																
	Top Elevation	311.14 feet	Not Applicable —																																																																																
	H.F.L	301.35 feet																																																																																	
	Free Board Height	9.79 feet																																																																																	
	Top Width	25 feet																																																																																	
	River Side Slope	1:2																																																																																	
	Country Side Slope	1:2																																																																																	
	Longitudinal Length	14250 feet																																																																																	
	Slope Protection Material	Stone pitched on river side																																																																																	
	Covering Material/ Pavement on the Top	Shingle on the top																																																																																	
	Embankment Material	Earthen (Clay)																																																																																	
	Ancillary Structure (Drainage Ditch, and Spurs)	Not Applicable																																																																																	
Typical Cross Section																																																																																			
	<p>REHABILITATION AND UP GRADATION OF FAKHAR FLOOD BOND X-SECTION AT RD-10+500</p> <p>Workdone Fill Area : 761.73 Sft Fill Area : 761.73 Sft</p> <table border="1"> <thead> <tr> <th>Station</th> <th>Actual Level</th> <th>Design Level</th> </tr> </thead> <tbody> <tr><td>78+00</td><td>291.00</td><td>291.150</td></tr> <tr><td>78+12</td><td>291.15</td><td>291.15</td></tr> <tr><td>78+24</td><td>291.15</td><td>291.15</td></tr> <tr><td>78+36</td><td>291.15</td><td>291.15</td></tr> <tr><td>78+48</td><td>291.15</td><td>291.15</td></tr> <tr><td>78+60</td><td>291.15</td><td>291.15</td></tr> <tr><td>78+72</td><td>291.15</td><td>291.15</td></tr> <tr><td>78+84</td><td>291.15</td><td>291.15</td></tr> <tr><td>78+96</td><td>291.15</td><td>291.15</td></tr> <tr><td>79+08</td><td>291.15</td><td>291.15</td></tr> <tr><td>79+20</td><td>291.15</td><td>291.15</td></tr> <tr><td>79+32</td><td>291.15</td><td>291.15</td></tr> <tr><td>79+44</td><td>291.15</td><td>291.15</td></tr> <tr><td>79+56</td><td>291.15</td><td>291.15</td></tr> <tr><td>79+68</td><td>291.15</td><td>291.15</td></tr> <tr><td>79+80</td><td>291.15</td><td>291.15</td></tr> <tr><td>79+92</td><td>291.15</td><td>291.15</td></tr> <tr><td>80+04</td><td>291.15</td><td>291.15</td></tr> <tr><td>80+16</td><td>291.15</td><td>291.15</td></tr> <tr><td>80+28</td><td>291.15</td><td>291.15</td></tr> <tr><td>80+40</td><td>291.15</td><td>291.15</td></tr> <tr><td>80+52</td><td>291.15</td><td>291.15</td></tr> <tr><td>80+64</td><td>291.15</td><td>291.15</td></tr> <tr><td>80+76</td><td>291.15</td><td>291.15</td></tr> <tr><td>80+88</td><td>291.15</td><td>291.15</td></tr> <tr><td>81+00</td><td>291.15</td><td>291.15</td></tr> </tbody> </table> <p>CONTRACTOR:- SPARC CONSTRUCTION COMPANY CONSULTANTS:- MM Pakistan (Pvt.) Ltd (PMIC)</p>			Station	Actual Level	Design Level	78+00	291.00	291.150	78+12	291.15	291.15	78+24	291.15	291.15	78+36	291.15	291.15	78+48	291.15	291.15	78+60	291.15	291.15	78+72	291.15	291.15	78+84	291.15	291.15	78+96	291.15	291.15	79+08	291.15	291.15	79+20	291.15	291.15	79+32	291.15	291.15	79+44	291.15	291.15	79+56	291.15	291.15	79+68	291.15	291.15	79+80	291.15	291.15	79+92	291.15	291.15	80+04	291.15	291.15	80+16	291.15	291.15	80+28	291.15	291.15	80+40	291.15	291.15	80+52	291.15	291.15	80+64	291.15	291.15	80+76	291.15	291.15	80+88	291.15	291.15	81+00	291.15
Station	Actual Level	Design Level																																																																																	
78+00	291.00	291.150																																																																																	
78+12	291.15	291.15																																																																																	
78+24	291.15	291.15																																																																																	
78+36	291.15	291.15																																																																																	
78+48	291.15	291.15																																																																																	
78+60	291.15	291.15																																																																																	
78+72	291.15	291.15																																																																																	
78+84	291.15	291.15																																																																																	
78+96	291.15	291.15																																																																																	
79+08	291.15	291.15																																																																																	
79+20	291.15	291.15																																																																																	
79+32	291.15	291.15																																																																																	
79+44	291.15	291.15																																																																																	
79+56	291.15	291.15																																																																																	
79+68	291.15	291.15																																																																																	
79+80	291.15	291.15																																																																																	
79+92	291.15	291.15																																																																																	
80+04	291.15	291.15																																																																																	
80+16	291.15	291.15																																																																																	
80+28	291.15	291.15																																																																																	
80+40	291.15	291.15																																																																																	
80+52	291.15	291.15																																																																																	
80+64	291.15	291.15																																																																																	
80+76	291.15	291.15																																																																																	
80+88	291.15	291.15																																																																																	
81+00	291.15	291.15																																																																																	
History of Damages																																																																																			
MM/YYY Y	Type of Damage	Description																																																																																	
2010	Breach due to overtopping	Fakhar Flood Bund completely breached due to overtopping.																																																																																	
Record of Rehabilitation/ Improvement																																																																																			
MM/YYY Y	Project Name and its Description	Cost	Source of Funding																																																																																
2011	Complete restoration of bund	Rs. 15 Million	Maintenance and repair works by PID																																																																																
2020	Restoration of bund at highest flood level of 2010 flood.	Rs. 67 Million	Project Implementation Unit (PIU)																																																																																
Plan for Rehabilitation/ Improvement																																																																																			
MM/YYY Y	Project Name and its Description	Cost	Source of Funding																																																																																
	Nil																																																																																		

Site Photo					
Vulnerable Section	General View of River Side				
	<table border="1"> <tr> <td>Facing Downstream and Side</td> <td>Facing Upstream Side</td> </tr> <tr> <td></td> <td></td> </tr> </table>	Facing Downstream and Side	Facing Upstream Side		
	Facing Downstream and Side	Facing Upstream Side			
					
	General View of Top				
	<table border="1"> <tr> <td>Facing Downstream and Side</td> <td>Facing Upstream Side</td> </tr> <tr> <td></td> <td></td> </tr> </table>	Facing Downstream and Side	Facing Upstream Side		
	Facing Downstream and Side	Facing Upstream Side			
					
	General View of Landside				
	<table border="1"> <tr> <td>Facing Downstream and Side</td> <td>Facing Upstream Side</td> </tr> <tr> <td></td> <td></td> </tr> </table>	Facing Downstream and Side	Facing Upstream Side		
	Facing Downstream and Side	Facing Upstream Side			
					
Close View of Deformation	(Not Applicable)				
Close View of Damages	(Not Applicable)				

	<p>Photo with 360° angles</p> 	
<p>Typical Section (Adjacent to the Vulnerable Point)</p>	<p>General View of River Side</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
	<p>General View of Top</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
<p>General View of Landside</p>		
<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 	

	<p>Photo with 360° angles</p> 
<p>Downstream End of the Bund</p>	<p>General View</p> <p>(Not Applicable)</p>
	<p>Photo with 360° angles</p> <p>(Not Applicable)</p>
<p>Upstream End of the Bund</p>	<p>General View (In the case that the VP is located near the end)</p> <p>(Not Applicable)</p>
	<p>Photo with 360° angles</p> <p>(Not Applicable)</p>

Observation Record ⁴ (Current status, effect of countermeasure, development of erosion, deformation, deterioration)			
DD/MM/YYYY	Inspection Type	Description and Photo	Damage ⁵
02/3/2024	Visual Inspection	<ul style="list-style-type: none"> • Cultivated area is present on the country side, which is approximately 18feet. below the top level of bund. • Stone pitched on the river side. • There is a Link Road through Benazir bridge from N5 to N55. • Reserve stock of stones is available throughout the length of bund on the river side.  <p>Cultivated area on the country side</p>  <p>Stone pitched on the river side</p>  <p>Reserve stock of stones on the riverside</p>	a

⁴ Current Status, Effect of the Existing Structural Countermeasure Such as Spurs/studs, Sheet Piles for Seepage Control etc. and Development of Erosion, Deformation, Deterioration of the Existing Bund

⁵ a: No Deformation, b: No deformations are observed on the bund body, except for gully erosion caused by raindrops or the detachment of the bund's stone pitching, c: The bund or the apron has been damaged, and L: Leakage from the bund has been identified

Evaluation Process					
DD/MM/YYYY	Item		Result	Reason	
	Criteria For Evaluation Flow	Flood Damage		Yes	The inundation analysis indicates that the flood damage is severe
		Bund Damage		NO	There is no significant damage at present.
		Bund Dimension	Bund Height	Pass	Free board height is 9.8 feet.
			Bund Width	Pass	The soil cover thickness over HGL exceeds the guideline value (Soil Depth \geq 2 feet)
			Flood Plain Length	Fail	Floodplain length is about 4900 feet.
		Topographic Feature	Breach Record	Yes	It has breached in the past.
			Flow Impact	NO	It hasn't been affected by strong water flow since before 2010 flood.
	Category			Proactive Type R	
	For Evaluation Score	Bund Damage		0	There is no significant damage at present.
		Bund Dimension	Bund Height	0	Free board height is 9.8 feet.
			Bund Width	0	The soil cover thickness over HGL exceeds the guideline value (Soil Depth \geq 2 feet)
			Flood Plain Length	1	Floodplain length is about 4900 feet.
	Quality Score			1/9	

Note) HGL: hydraulic gradient line

Fakhar Flood Bund RD 19+000 to 20+000

Creation Date: 02/3/2024













Province	Zone	Division	Circle
Punjab	Dera Ghazi Khan Zone	Jampur Construction Division	Project Circle DG Khan
Sr. No.	River Name	River System	Bank
P-010b	Indus River	Indus River	Right
Bund Name		R.D	GPS Coordinates
Fakhar Flood bund		RD 10+000 to 24+500	28°94'17.81"N, 70°37'24.98"E
Name of Vulnerable Point	Fakhar Flood Bund at RD 10+000 to 24+500_2		
Reason for the Vulnerability	<ul style="list-style-type: none"> Fakhar Flood Bund at this RD was vulnerable in 2010 flood, as the Indus River breached and washed out the entire bund due to overtopping. This reach is no longer vulnerable, as the main creek of the river is now approximately 17 km away from the said reach. The bund is restored in 2020 to the highest flood level recorded during the 2010 flood. 		
Flow Condition ¹	<ul style="list-style-type: none"> No flow conditions. 		
Site Condition in the Country Side ²	<ul style="list-style-type: none"> Cultivated area is present on the country side, which is approximately 18 feet below the top level of bund. The population of Kot Mithon Sharif city is located near the reach on the countryside side. 		
Layout Plan (Source of Satellite Image: Google Earth)			
Evaluation ³			
Category		Quality Score	
Proactive Type R		0/9	

¹ Water Flow Direction and Conditions During Floods Around the Listed Vulnerable Points.


² Site Condition Around the Vulnerable Points (Rough Distance Between Main Water Channel and the Bund, Land Use Behind the Point, Important Facility Adjacent to the Point).




³ Emergent Type R: Emergent Phase Requiring Robust Countermeasures, Emergent Type C: Emergent Phase Requiring Common Countermeasures, Proactive Type R: Proactive Phase Requiring Robust Countermeasures, Proactive Type C: Proactive Phase Requiring Common Countermeasures, Monitoring: Monitoring Phase

Basic Information of the Bund			
Basic Dimensions and Materials	Item	Existing	Proposed
	Top Elevation	310.15 feet	Not Applicable —
	H.F. L	301.35 feet	
	Free Board Height	8.80 feet	
	Top Width	25 feet	
	River Side Slope	1:2	
	Country Side Slope	1:2	
	Longitudinal Length	14250 feet	
	Slope Protection Material	Stone pitched on river side	
	Covering Material/ Pavement on the Top	Shingle on the top	
Embankment Material	Earthen (Clay)		
Ancillary Structure (Drainage Ditch, and Spurs)	Not Applicable		
Typical Cross Section			
History of Damages			
MM/YYYY	Type of Damage	Description	
2010	Breach due to overtopping	Fakhar Flood Bund was completely breached due to overtopping.	
Record of Rehabilitation/ Improvement			
MM/YYYY	Project Name and its Description	Cost	Source of Funding
2011	Complete restoration of bund	Rs. 15 Million	Maintenance and repair works by PID
2020	Restoration of bund at highest flood level of 2010 flood	Rs. 67 Million	Project Implementation Unit (PIU)
Plan for Rehabilitation/ Improvement			
MM/YYYY	Project Name and its Description	Cost	Source of Funding
	Nil		

Site Photo					
Vulnerable Section	General View of River Side				
	<table border="1"> <tr> <td>Facing Downstream and Side</td> <td>Facing Upstream Side</td> </tr> <tr> <td></td> <td></td> </tr> </table>	Facing Downstream and Side	Facing Upstream Side		
	Facing Downstream and Side	Facing Upstream Side			
					
	General View of Top				
	<table border="1"> <tr> <td>Facing Downstream and Side</td> <td>Facing Upstream Side</td> </tr> <tr> <td></td> <td></td> </tr> </table>	Facing Downstream and Side	Facing Upstream Side		
	Facing Downstream and Side	Facing Upstream Side			
					
	General View of Landside				
	<table border="1"> <tr> <td>Facing Downstream and Side</td> <td>Facing Upstream Side</td> </tr> <tr> <td></td> <td></td> </tr> </table>	Facing Downstream and Side	Facing Upstream Side		
Facing Downstream and Side	Facing Upstream Side				
					
Close View of Deformation	(Not Applicable)				
Close View of Damages	(Not Applicable)				

	<p>Photo with 360° angles</p> 	
<p>Typical Section (Adjacent to the Vulnerable Point)</p>	<p>General View of River Side</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
	<p>General View of Top</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
	<p>General View of Landside</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 

	<p>Photo with 360° angles</p> 
<p>Downstream End of the Bund</p>	<p>General View</p> <p>(Not Applicable)</p>
	<p>Photo with 360° angles</p> <p>(Not Applicable)</p>
<p>Upstream End of the Bund</p>	<p>General View (In the case that the VP is located near the end)</p> <p>(Not Applicable)</p>
	<p>Photo with 360° angles</p> <p>(Not Applicable)</p>

Observation Record ⁴ (Current status, effect of countermeasure, development of erosion, deformation, deterioration)			
DD/MM/YYYY	Inspection Type	Description and Photo	Damage ⁵
02/3/2024	Visual Inspection	<ul style="list-style-type: none"> • Cultivated area is present on the country side, which is approximately 18 feet below the top level of bund. • Stone pitched has been applied on the river side. • There is a Link Road through Benazir bridge from N5 to N55. • A reserve stock of stones is present throughout the length of bund on the riverside. • The population of Kot Mithon Sharif city is located near the reach on the countryside side..  <p>Cultivated area on the country side</p>  <p>Stone pitched on the river side</p>  <p>Reserve stock of stones on the river side</p>	a

⁴ Current Status, Effect of the Existing Structural Countermeasure Such as Spurs/studs, Sheet Piles for Seepage Control etc. and Development of Erosion, Deformation, Deterioration of the Existing Bund

⁵ a: No Deformation, b: No deformations are observed on the bund body, except for gully erosion caused by raindrops or the detachment of the bund's stone pitching, c: The bund or the apron has been damaged, and L: Leakage from the bund has been identified

Evaluation Process					
DD/MM/YYYY	Item		Result	Reason	
	Criteria For Evaluation Flow	Flood Damage		Yes	The inundation analysis indicates that the flood damage is severe
		Bund Damage		NO	There is no significant damage at present.
		Bund Dimension	Bund Height	Pass	Free board height is 8.8 feet.
			Bund Width	Pass	The soil cover thickness over HGL exceeds the guideline value (Soil Depth \geq 2 feet)
			Flood Plain Length	Pass	Floodplain length is about 56,000 feet.
		Topographic Feature	Breach Record	Yes	It has breached in the past.
			Flow Impact	NO	It hasn't been affected by strong water flow since before 2010 flood.
	Category			Proactive Type R	
	For Evaluation Score	Bund Damage		0	There is no significant damage at present.
		Bund Dimension	Bund Height	0	Free board height is 8.8 feet.
			Bund Width	0	The soil cover thickness over HGL exceeds the guideline value (Soil Depth \geq 2 feet)
			Flood Plain Length	0	Floodplain length is about 56,000 feet.
	Quality Score			0/9	

Note) HGL: hydraulic gradient line

Rojhan Flood Bund RD 16+000 to 17+000

Creation Date: 02/3/2024

Province	Zone	Division	Circle
Punjab	Dera Ghazi Khan Zone	Jampur Construction Division	Project Circle DG Khan
Sr. No.	River Name	River System	Bank
P-011a	Indus River	Indus River	Right
Bund Name		R.D	GPS Coordinates
Rojhan Flood Bund		RD 10+000 to 25+000	28°68'76.86"N, 69°96'59.07"E
Name of Vulnerable Point	Rojhan Flood Bund RD 10+000 to 25+000_1		
Reason for the Vulnerability	<ul style="list-style-type: none"> • Rojhan Flood Bund at this RD was vulnerable in 2010 flood, the Indus River rose to top level of the bund. • This reach is no longer considered vulnerable, as the main creek of the river is now approximately 2 km away from the said reach. • The site has been restored in 2020 at the highest flood level of 2010 flood. 		
Flow Condition ¹	<ul style="list-style-type: none"> • No flow conditions. 		
Site Condition in the Country Side ²	<ul style="list-style-type: none"> • Adjoining settlement of Rojhan city is present near the reach on either side of the bund from RD 9+000 to RD 16+000. • There is a barren land on the country side. 		
Layout Plan (Source of Satellite Image: Google Earth)			
Evaluation ³			
Category		Quality Score	
Proactive Type C		1/9	

¹ Water Flow Direction and Conditions During Floods Around the Listed Vulnerable Points


² Site Condition Around the Vulnerable Points (Rough Distance Between Main Water Channel and the Bund, Land Use Behind the Point, Important Facility Adjacent to the Point)

³ Emergent Type R: Emergent Phase Requiring Robust Countermeasures, Emergent Type C: Emergent Phase Requiring Common Countermeasures, Proactive Type R: Proactive Phase Requiring Robust Countermeasures, Proactive Type C: Proactive Phase Requiring Common Countermeasures, Monitoring: Monitoring Phase

Basic Information of the Bund

Basic Dimensions and Materials	Item	Existing	Proposed
	Top Elevation	280.66 feet	Not Applicable
	H.F.L	275.40 feet	
	Free Board Height	5.26 feet	
	Top Width	25 feet	
	River Side Slope	1:3	
	Country Side Slope	1:2	
	Longitudinal Length	61250 feet	
	Slope Protection Material	Earthen (clay and sand)	
	Covering Material/ Pavement on the Top	Metaled road	
Embankment Material	Earthen (clay and sand)		
Ancillary Structure (Drainage Ditch, and Spurs)	Nil		

Typical Cross Section



History of Damages







MM/YYY Y	Type of Damage	Description
2010	Side slope and top width disturbed	The Indus River touched the bund up to the top level and disturbed the riverside slope and top width.

Record of Rehabilitation/ Improvement


MM/YYY Y	Project Name with its Description	Cost	Source of Funding
2020	Restoration of bund (River side slope and top width)	RS. 90 Million	Project Implementation Unit (PIU)




Plan for Rehabilitation/ Improvement

MM/YYY Y	Project Name with its Description	Cost	Source of Funding
	Nil		

Site Photo		
Vulnerable Section	General View of River Side	
	Facing Downstream and Side	Facing Upstream Side
		
	General View of Top	
	Facing Downstream and Side	Facing Upstream Side
		
	General View of Landside	
	Facing Downstream and Side	Facing Upstream Side
		
	Close View of Deformation	
	Not Applicable	
	Close View of Damages	
Not Applicable		

	<p>Photo of 360° angles</p> 	
<p>Typical Section (Adjacent to the Vulnerable Point)</p>	<p>General View of River Side</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
	<p>General View of Top</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
	<p>General View of Landside</p>	
	<p>Facing Downstream and Side</p>  <p>28.69064, 69.9686, 49.9m, 267°</p>	<p>Facing Upstream Side</p>  <p>28.69065, 69.96861, 49.5m, 220°</p>

	<p>Photo of 360° angles</p> 
<p>Downstream End of the Bund</p>	<p>General View (Not Applicable)</p>
	<p>Photo of 360° angles (Not Applicable)</p>
<p>Upstream End of the Bund</p>	<p>General View (In the case that the VP is located near the end) (Not Applicable)</p>
	<p>Photo of 360° angles (Not Applicable)</p>

Observation Record ⁴ (Current status, effect of countermeasure, development of erosion, deformation, deterioration)			
DD/MM/YYYY	Inspection Type	Description and Photo	Damage ⁵
02/3/2024	Visual Inspection	<ul style="list-style-type: none"> • Adjoining population of Rojhan city is present on both side of the bund. • Metaled road runs along the top, connecting Rojhan to Miran Pur village. • Cultivated area are present on the river side. • There is a barren land on the country side.  <p>Adjoining population</p>  <p>Metaled road on top</p>  <p>Cropped area on theRiver Side</p>	a

⁴ Current Status, Effect of the Existing Structural Countermeasure Such as Spurs/studs, Sheet Piles for Seepage Control etc. and Development of Erosion, Deformation, Deterioration of the Existing Bund

⁵ a: No Deformation, b: No deformations are observed on the bund body, except for gully erosion caused by raindrops or the detachment of the bund's stone pitching, c: The bund or the apron has been damaged, and L: Leakage from the bund has been identified

Evaluation Process					
DD/MM/YYYY	Item		Result	Reason	
	Criteria For Evaluation Flow	Flood Damage		Yes	The inundation analysis indicates that the flood damage is severe
		Bund Damage		NO	There is no significant damage at present.
		Bund Dimension	Bund Height	Fail	Free board height is 5.3 feet.
			Bund Width	Pass	The soil cover thickness over HGL exceeds the guideline value (Soil Depth \geq 2 feet)
			Flood Plain Length	Pass	Floodplain length is about 6600 feet.
		Topographic Feature	Breach Record	No	There is no breach record.
			Flow Impact	NO	It hasn't been affected by strong water flow since before 2010 flood.
	Category			Proactive Type C	
	For Evaluation Score	Bund Damage		0	There is no significant damage at present.
		Bund Dimension	Bund Height	1	Free board height is 5.3 feet.
			Bund Width	0	The soil cover thickness over HGL exceeds the guideline value (Soil Depth \geq 2 feet)
			Flood Plain Length	0	Floodplain length is about 6600 feet.
	Quality Score			1/9	

Note) HGL: hydraulic gradient line

Rojhan Flood Bund RD 24+000 to 25+000

Creation Date: 02/3/2024



















Province	Zone	Division	Circle
Punjab	Dera Ghazi Khan Zone	Jampur Construction Division	Project Circle DG Khan
Sr. No.	River Name	River System	Bank
P-011b	Indus River	Indus River	Right
Bund Name		R.D	GPS Coordinates
Rojhan Flood Bund		RD 10+000 to 25+000	28°70'44.98"N, 69°98'01.15"E
Name of Vulnerable Point	Rojhan Flood Bund at RD 10+000 to 25+000_2		
Reason for the Vulnerability	<ul style="list-style-type: none"> • Rojhan Flood Bund at this RD was vulnerable in 2010 flood, the Indus River rose to the top level of the bund. • Now this reach is no longer vulnerable, as main creek of river is approximately 12 km away from said reach. • The site has been restored in 2020 at the highest flood level of 2010 flood. 		
Flow Condition ¹	<ul style="list-style-type: none"> • No flow conditions. 		
Site Condition in the Country Side ²	<ul style="list-style-type: none"> • Mud lumps/heaps can be found on both sides of the bund • Adjoining population of Rojhan city is present near the reach towards the river side. 		
Layout Plan (Source of Satellite Image: Google Earth)			
Evaluation ³			
Category		Quality Score	
Proactive Type C		0/9	





¹ Water Flow Direction and Conditions During Floods Around the Listed Vulnerable Points


² Site Condition Around the Vulnerable Points (Rough Distance Between Main Water Channel and the Bund, Land Use Behind the Point, Important Facility Adjacent to the Point)



³ Emergent Type R: Emergent Phase Requiring Robust Countermeasures, Emergent Type C: Emergent Phase Requiring Common Countermeasures, Proactive Type R: Proactive Phase Requiring Robust Countermeasures, Proactive Type C: Proactive Phase Requiring Common Countermeasures, Monitoring: Monitoring Phase

Basic Information of the Bund			
Basic Dimensions and Materials	Item	Existing	Proposed
	Top Elevation	283.75 feet	Not Applicable
	H.F. L	275.40 feet	
	Free Board Height	8.35 feet	
	Top Width	25 feet	
	River Side Slope	1:3	
	Country Side Slope	1:2	
	Longitudinal Length	61250 feet	
	Slope Protection Material	Earthen (Hard clay and sand)	
	Covering Material/ Pavement on the Top	Metaled road	
Embankment Material	Earthen (Hard clay and sand)		
Ancillary Structure (Drainage Ditch, and Spurs)	Nil		
Typical Cross Section	<p>The figure is a technical drawing of a cross-section of a bund at station RD 24+500. It shows a trapezoidal embankment on a grid. The vertical axis represents elevations in feet, ranging from 250 to 300. The horizontal axis represents stationing from -45.00 to 64.13. The drawing includes design levels, existing formation levels, and an area statement table. A legend defines symbols for existing surface level, proposed level, earth work, and materials like shingle and stone pitching. A signature and project details are at the bottom right.</p>		
History of Damages			
MM/YYYY	Type of Damage	Description	
2010	Side slope and top width disturbed	The Indus River reached the top level of the bund, and disrupting the riverside slope and reducing the top width.	
Record of Rehabilitation/ Improvement			
MM/YYYY	Project Name and its Description	Cost	Source of Funding
2020	Restoration of Bund (River side slope and top width)	RS. 90 Million	Project Implementation Unit (PIU)
Plan for Rehabilitation/ Improvement			
MM/YYYY	Project Name and its Description	Cost	Source of Funding
	Nil		

Site Photo					
Vulnerable Section	General View of River Side				
	<table border="1"> <tr> <td>Facing Downstream and Side</td> <td>Facing Upstream Side</td> </tr> <tr> <td></td> <td></td> </tr> </table>	Facing Downstream and Side	Facing Upstream Side		
	Facing Downstream and Side	Facing Upstream Side			
					
	General View of Top				
	<table border="1"> <tr> <td>Facing Downstream and Side</td> <td>Facing Upstream Side</td> </tr> <tr> <td></td> <td></td> </tr> </table>	Facing Downstream and Side	Facing Upstream Side		
	Facing Downstream and Side	Facing Upstream Side			
					
	General View of Landside				
	<table border="1"> <tr> <td>Facing Downstream and Side</td> <td>Facing Upstream Side</td> </tr> <tr> <td></td> <td></td> </tr> </table>	Facing Downstream and Side	Facing Upstream Side		
Facing Downstream and Side	Facing Upstream Side				
					
Close View of Deformation	Not Applicable				
Close View of Damages	Not Applicable				

	<p>Photo with 360° angles</p> 	
<p>Typical Section (Adjacent to the Vulnerable Point)</p>	<p>General View of River Side</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
	<p>General View of Top</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 
	<p>General View of Landside</p>	
	<p>Facing Downstream and Side</p> 	<p>Facing Upstream Side</p> 

	<p>Photo with 360⁰ angles</p> 
<p>Downstream End of the Bund</p>	<p>General View</p> <p>(Not Applicable)</p>
	<p>Photo with 360⁰ angles</p> <p>(Not Applicable)</p>
<p>Upstream End of the Bund</p>	<p>General View (In the case that the VP is located near the end)</p> <p>(Not Applicable)</p>
	<p>Photo with 360⁰ angles</p> <p>(Not Applicable)</p>

Observation Record ⁴ (Current status, effect of countermeasure, development of erosion, deformation, deterioration)			
DD/MM/YYYY	Inspection Type	Description and Photo	Damage ⁵
02/3/2024	Visual Inspection	<ul style="list-style-type: none"> • Mud lumps/heaps can be found on both sides of the bund • Adjoining population of Rojhan city is present near the reach towards the river side. • Metaled road runs on top is towards Rojhan to Miran Pur village.  <p>Mud lumps/heaps on either side of the bund</p>  <p>Metaled road on top</p>	a

⁴ Current Status, Effect of the Existing Structural Countermeasure Such as Spurs/studs, Sheet Piles for Seepage Control etc. and Development of Erosion, Deformation, Deterioration of the Existing Bund

⁵ a: No Deformation, b: No deformations are observed on the bund body, except for gully erosion caused by raindrops or the detachment of the bund's stone pitching, c: The bund or the apron has been damaged, and L: Leakage from the bund has been identified

Evaluation Process					
DD/MM/YYYY	Item		Result	Reason	
	Criteria For Evaluation Flow	Flood Damage		Yes	The inundation analysis indicates that the flood damage is severe
		Bund Damage		NO	There is no significant damage at present.
		Bund Dimension	Bund Height	Pass	Free board height is 8.4 feet.
			Bund Width	Pass	The soil cover thickness over HGL exceeds the guideline value (Soil Depth \geq 2 feet)
			Flood Plain Length	Pass	Floodplain length is about 39400 feet.
		Topographic Feature	Breach Record	No	There is no breach record.
			Flow Impact	NO	It hasn't been affected by strong water flow since before 2010 flood.
	Category			Proactive Type C	
	For Evaluation Score	Bund Damage		0	There is no significant damage at present.
		Bund Dimension	Bund Height	0	Free board height is 8.4 feet.
			Bund Width	0	The soil cover thickness over HGL exceeds the guideline value (Soil Depth \geq 2 feet)
			Flood Plain Length	0	Floodplain length is about 39400 feet.
	Quality Score			0/9	

Note) HGL: hydraulic gradient line

Jampur Flood Bund RD 21+000 to 22+000

Creation Date: 01/3/2024

Province	Zone	Division	Circle
Punjab	Dera Ghazi Khan Zone	Jampur Construction Division	Project Circle DG Khan
Sr. No.	River Name	River System	Bank
P-012	Indus River	Indus River	Right
Bund Name		R.D	GPS Coordinates
Jampur Flood Bund		RD 21+000 to RD 22+000	29°75'11.86"N, 70°69'05.49"E
Name of Vulnerable Point	Jampur Flood Bund RD 21+000 to RD 22+000		
Reason for the Vulnerability	<ul style="list-style-type: none"> Jampur Flood Bund at this RD was vulnerable as in 2010 flood, the Indus River breached the bund at this section. 		
Flow Condition ¹	<ul style="list-style-type: none"> No flow conditions. 		
Site Condition in the Country Side ²	<ul style="list-style-type: none"> Shero Minor is flowing towards country side of the bund. Cultivated area is situated on the country side which is approximately 15 feet below the top level of bund. Village Dulhar is situated on the country side of the bund. 		
Layout Plan (Source of Satellite Image: Google Earth)			
Evaluation ³			
Category		Quality Score	
Proactive Type R		1/9	

¹ Water Flow Direction and Conditions During Floods Around the Listed Vulnerable Points

² Site Condition Around the Vulnerable Points (Rough Distance Between Main Water Channel and the Bund, Land Use Behind the Point, Important Facility Adjacent to the Point)

³ Emergent Type R: Emergent Phase Requiring Robust Countermeasures, Emergent Type C: Emergent Phase Requiring Common Countermeasures, Proactive Type R: Proactive Phase Requiring Robust Countermeasures, Proactive Type C: Proactive Phase Requiring Common Countermeasures, Monitoring: Monitoring Phase

Basic Information of the Bund																													
Basic Dimensions and Materials	Item	Existing	Proposed																										
	Top Elevation	371.80 feet	Not Applicable -																										
	H.F. L	364.80 feet																											
	Free Board Height	7.00 feet																											
	Top Width	25 feet																											
	River Side Slope	1:3																											
	Country Side Slope	1:2																											
	Longitudinal Length	171000 feet																											
	Slope Protection Material	Earthen (Silty clay)																											
	Covering Material/ Pavement on the Top	Earthen (Silty clay)																											
	Embankment Material	Earthen (Silty clay)																											
Ancillary Structure (Drainage Ditch, and Spurs)	Nil																												
Typical Cross Section	<p style="text-align: center;">ESTIMATE FOR STRENGTHENING & RAISING OF JAMPUR FLOOD BUND.</p> <p style="text-align: center;">X-SECTION AT RD : 13+500</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>EXISTING DIST LEVEL</th> <th>-51.000</th> <th>-45.000</th> <th>-38.000</th> <th>-23.472</th> <th>-13.880</th> <th>3.000</th> <th>14.593</th> <th>31.075</th> <th>35.000</th> <th>43.000</th> <th>47.000</th> <th>52.000</th> </tr> </thead> <tbody> <tr> <td></td> <td>357.730</td> <td>359.037</td> <td>363.059</td> <td>366.673</td> <td>369.893</td> <td>370.361</td> <td>369.823</td> <td>365.555</td> <td>363.486</td> <td>355.610</td> <td>355.610</td> <td>353.310</td> </tr> </tbody> </table>			EXISTING DIST LEVEL	-51.000	-45.000	-38.000	-23.472	-13.880	3.000	14.593	31.075	35.000	43.000	47.000	52.000		357.730	359.037	363.059	366.673	369.893	370.361	369.823	365.555	363.486	355.610	355.610	353.310
	EXISTING DIST LEVEL	-51.000	-45.000	-38.000	-23.472	-13.880	3.000	14.593	31.075	35.000	43.000	47.000	52.000																
	357.730	359.037	363.059	366.673	369.893	370.361	369.823	365.555	363.486	355.610	355.610	353.310																	
History of Damages																													
MM/YYYY	Type of Damage	Description																											
2010	Breach due to overtopping	Jampur flood bund breached between RD 21+000 to RD 22+000 due to overtopping.																											
Record of Rehabilitation/ Improvement																													
MM/YYYY	Project Name and its Description	Cost	Source of Funding																										
2010	The bund between RD 21+000 and RD 22+000 has been fully restored.	Not provided by concerned official	Maintenance and Repair works by PID																										
Plan for Rehabilitation/ Improvement																													
MM/YYYY	Project Name and its Description	Cost	Source of Funding																										
	Nil																												