


## FIGURES










Fig. 1-2 (2/2) STUDY PROCEDURE (URGENT PLAN)




Fig. 2-1 LOCATION OF DAMAGED AREA IN GUATEMALA




Fig. 2-2 DAMAGED AREA OF EL PALMAR AND GEOMORPHOLOGICAL CONDITION

## VOLCAND LEGEND Riverbed (Old deposits of debris flow) Volcanic fan Slope of lava flow Debris flow deposits (1982) Gully Streom \_.CHIQUIMULILLA DAMAGED AREA

TECUAMBURRO

Fig. 2-3 DAMAGED AREA OF CHIQUIMULILLA AND GEOMORPHOLOGICAL CONDITION




Fig. 3-1 (1/2) INUNDATION MAP OF THE FLOOD IN SEP. 1969 (ACHIGUATE RIVER)




Fig. 3-1 (2/2) INUNDATION MAP OF THE FLOOD IN SEP. 1969 (PANTALEON RIVER)




Fig. 3-2 (1/2) LAND USE MAP (ACHIGUATE RIVER BASIN)




Fig. 3-2 (2/2) LAND USE MAP (PANTALEON RIVER BASIN)




Fig. 3-3 GEOMORPHOLOGICAL DIVISION OF THE STUDY AREA




Fig. 3-4 (1/2) TRANSITION OF RIVER COURSE (ACHIGUATE RIVER)






Fig. 3-4 (2/2) TRANSITION OF RIVER COURSE (PANTALEON RIVER)

Fig. 3-5 TRANSITION OF RIVER MOUTH IN ACHIGUATE RIVER



TRANSITION OF CROSS-SECTION AT RAILWAY BRIDGE IN ACHIGUATE RIVER



TRANSITION OF CROSS-SECTION AT ROAD BRIDGE IN PANTALEON RIVER Fig. 3-7




Fig. 3-8 (1/2) FEATURES OF RIVER (ACHIGUATE RIVER)




Fig. 3-8 (2/2) FEATURES OF RIVER (PANTALEON RIVER)




Fig. 4-1 LOCATION OF REFERENCE POINTS




Fig. 4-2 SPECIFIC DISCHARGE




Fig. 4-3 (1/2) MODEL HYDROGRAPH (ACHIGUATE RIVER)





Fig. 4-3 (2/2) MODEL HYDROGRAPH (PANTALEON RIVER)



PACIFIC OCEAN

PANTALEON


## ACHIGUATE

NOTE

Unit: m<sup>3</sup>/sec

Figures in parentheses show the discharge added by the tributary at the peak flow time of the main river

Fig. 5-1 (1/2) DESIGN DISCHARGE DISTRIBUTION (30 YEARS)



PACIFIC OCEAN

PANTALEON

**ACHIGUATE** 

NOTE

Unit: m<sup>3</sup>/sec

Figures in parentheses show the discharge added by the tributary at the peak flow time of the main river

Fig. 5-1 (2/2) DESIGN DISCHARGE DISTRIBUTION (10 YEARS)




Fig. 5-2 (1/2) CLASSIFICATION OF ASSETS (ACHIGUATE RIVER BASIN)









Fig. 5-2 (2/2) CLASSIFICATION OF ASSETS (PANTALEON RIVER BASIN)












- 211 -






Fig. 5-5 (1/4) LOCATION OF ALTERNATIVE WORKS (ACHIGUATE RIVER, PROTECTION OF THE BRIDGES)

Fig. 5-5 (2/4) LOCATION OF ALTERNATIVE WORKS (ACHIGUATE RIVER, PROTECTION OF FINCA LA TRINIDAD)




Fig. 5-5 (3/4) LOCATION OF ALTERNATIVE WORKS
(ACHIGUATE RIVER, PROTECTION OF LA BARRITA)





Fig. 5-5 (4/4) LOCATION OF ALTERNATIVE WORKS (PANTALEON RIVER, PROTECTION OF THE BRIDGES)









Fig. 5-6 (1/2) PROPOSED LONG-TERM PLAN (ACHIGUATE RIVER)





(PANTALEON RIVER)

Yr 6th Yr																				
5th Y																,				
4th Yr										_1								~~~		
3rd Yr																				
2nd Yr																				
ist Yr																				
WORK VOLUME	1 F/S	1 1/8	103 000 m3	78 000 m <sup>3</sup>	10 000 m3	1 1/8	202 000 m³	126 000 m³	1 - 000 m <sup>3</sup>	- US	1 140 000 m <sup>3</sup>	160 000 m³	4 600 m	17 Units	5/7 -		s/		4 600 m	47 Units
K STAGE	DETAILED DESIGN	PREPARATION	EXCAVATION	MAIN DAM	SUB DAM	PREPARATION	EXCAVATION	MAIN DAM	SUB DAM	PREPARATION	EXCAVATION	EMBANKMENT	REVETMENT	GROUNDSILL	DRAINAGE FACILITIES	(RING LEVEE)	PREPARATION	EXCAVATION	REVETMENT	GROUNDSILL
WORK	DET	=	ΙŢΑ	กอเ	ΥСН	N	reo	ΑŢΙ	1A9.			31'	∆U.E	HC	) Δ		NO	LE(	ATI	1 <b>4</b> 9
		V	۱AQ	٦٥	NTN	00	ENJ	MIO	ЗS			ΙN	WE	ЭΛE	) ਸ਼ ব	WΙ	Я	3 AI	Я	






Fig. 6-1 (2/4) GENERAL FEATURES OF COMPARATIVE PLANS (A-T)




Fig. 6-1 (3/4) GENERAL FEATURES OF COMPARATIVE PLANS (P-E)




Fig. 6-1 (4/4) GENERAL FEATURES OF COMPARATIVE PLANS (P-T)




Fig. 6-2 COST COMPARISON FOR RIVER IMPROVEMENT METHODS




Fig. 6-3 ECONOMIC COMPARISON FOR PROJECT SCALES

I	[			,		ľ	··· ·· / · · ·	·								
	Frecuency	Year	Year	Year	χ <del>έ</del> στ.	Year	Year	Year	Year	Year	Year	Yedr	Year	Year	Year	Year
	i.	ō	ß	<u>00</u>	Ю	ω.	25	20	ω	8	(1)	თ	50	$\bar{\omega}$	20	Ŋ
	Numbers Occurence	ഗ	N	w	~	ю	~		~		<u></u>	φ		m	_	2
•			•												· • · • ·	
	1980'S			0	0				0	0	0	0	0	. 0	0	:
	2			0	0	0	O		0		0	0			,	٠ ــــــــــــــــــــــــــــــــــــ
	S 77 78				0				:		000					
	2 07 €		·	0		;			ō	<b>.</b>	0					0
	2	· ·				· · ·			0	:	000	0				
	£. 2 8	0	0			· <del>i</del>	0	0	0		0	0				0
·	567.88				0		•				0	0				ol
	1960'S 64:63 66 67		<b>.</b>					···	,					•		0
·	8										i	0		0		:
	80.8				0.											3
	38 59 60 61	0	0			• • •								44.4		
	S 54	: .				:					!					:
	1950'S				0	†			:-							0
	52 53				0	. :				٠,	0					•
	48 48 50 51	· · ·									00					
											:					:
	40'S										. !					! :;
	0 3 4 1	v .			0						į					:
	5 5 5															:
	23					:		***********			·					i
	36 87	0			, O	0										0
	9.00 (8) SE 25 (				-,											- 6-
		0	:		0	0			0		0 0					0
turing and the second s	9 9				<u>·</u> _		<u> </u>				0					0
	River	. ·			. *	e e	at	Viejo	Q)		ıte	inda	9000	soADJ	÷	0
	Name of River	Suchiare	Naranjo	Ocosito	Samala	Sis - Icen	Nahualate	Madre Vieja	Coyolate	Acome	Achiguate	Maria Linda	Paso Hondo	Los Esciavos	Z1	Motagua
	2	್ಗ	ž	ŏ	·ĭ	ν̈			ŭ	٩	Ă	Σ	ď	, ,	Paz	ž

Fig. 6-4 FLOOD DAMAGE FREQUENCIES OF RIVERS IN GUATEMALA



Fig. 6-5 LOCATION OF SEDIMENT CONTROL DAMS
IN THE PROPOSED URGENT PLAN

