

7. "The Bureau of Plant Industry", white colored envelope, including organization chart; staff, functions & objectives; thrusts & strategies; plans & programs; special project and brief description about its services
8. Work Plan and Budgetary Requirements for Studies
 - a. BEF 100: Work Plan
 - b. Budgetary requirements for studies in 1994
 - c. Total cost of R & D activities 1994
 - d. Prioritized list of R & D projects (with their budgetary requirements) in 1994
9. News Paper Articles on Banning of Pesticides
 - a. "Fertilizer body suspends license of big pesticide manufacturer", the Philippine Star, January 14, 1994
 - b. "Government gets tough against Hoechst, judge", The Daily Inquirer, January 25, 1994

PAL-Cebu

1. Study on Pesticide Residue Degradation (on eggplant)

Regional Office in Region 7

1. The Medium-Term Agricultural Development Plan 1993-1998

Agricultural Training Institute

- a. Structure of the Extension System
- b. Organization Chart of the DA
- c. ATI Organization Structure
- d. Map of the National and Regional Training Centers

Fertilizer and Pesticide Authority

1. FPA Organization
 - a. FPA Organization Chart
 - b. Office of the Executive Director
 - c. Office of the Deputy Executive Director (Administration)
 - d. Administrative Division
 - e. Finance Division
 - f. Field Services Division
 - g. Information Services Division
 - h. Office of the Deputy Executive Director (Operations)
 - i. Industry Development Division
 - j. Technical Services Division
 - k. Industry Evaluation Division
 - l. Staffing Modification
2. FPA Annual Report 1993

3. FPA Trainings 1993
 - a. Summary of Agro-chemical Dealers Trainings as of December 31, 1993
 - b. Summary of Agro-medical Trainings 1993
 - c. Trainings, Mango Contractors, 1993
4. Laws on Pesticide Management
 - a. Presidential Decree No. 1144
 - b. FPA Rules and Regulations, No. 1, Series 1977
5. Registered Pesticides
 - a. Agricultural use
 - b. Household use
 - c. Restrictions on availability and usage
6. FPA Pesticide Regulatory Policies and the Implementing Guidelines and Procedures
7. Article on a magazine, "Monitoring Fertilizer and Pesticide Use", Greenfields, May 1993

Asian Development Bank

1. Pesticide Management and Integrated Pest Management in Southeast Asia, edited by P.S. Teng and K.L. Heong, 1988
2. PHI: Crop Protection in the Highland Agricultural Development Project (HADP) area of Northern Luzon - Consultant's Report, Dr. Graham Martin
3. Diamondback Moth and Other Crucifer Pests, Proceedings of the Second International Workshop, Taiwan, 10-14 December 1990, N.S. Talekar (eds.), Asian Vegetable Research and Development Center
4. Pesticide Hazards in the Third World; New evidence from the Philippines, Jennifer A. McCracken and Gordon R. Conway, International Institute for Environment and Development
5. Technical Assistance (JSF-Finances) to the Republic of the Philippines for Integrated Pest Management for Highland Vegetables, ADB, December 1993
6. Project Completion Report of the Highland Agriculture Development Project in the Philippines, July 1994

Food Development Center

1. 1993 Year End Highlights of Accomplishments
2. Questions and Answers about the Food Development Center
3. Schedule of Training Courses/Seminars for 1994

11. SUBSURFACE INVESTIGATION REPORT OF
THE PROJECT SITES (EXCERPT)

(1) PAL-Central

OFFICE: 921-52-41 Loc. 225


921-04-81

921-13-49

LAB. 99-36-02

GEOTECHNICS PHILIPPINES, INC.

800 E. DE LOS SANTOS AVENUE, QUEZON CITY, PHILIPPINES * CABLE ADDRESS: GEOTECH
TELEX NO. 722-27877 FFC PH * FAX NO. 921-0481



FINAL REPORT
SUBSURFACE INVESTIGATION
FOR THE PROPOSED PESTICIDE LABORATORY BUILDING
DILIMAN, QUEZON CITY

INTRODUCTION

This report constitutes the results and final interpretation and evaluation of the subsurface investigation conducted by GEOTECHNICS PHILIPPINES, INC. at the site of the proposed two (2)-storey Pesticide Laboratory Building in Visayas Avenue, Diliman, Quezon City.

As required for the design of the building foundation system, a subsoil investigation program was carried out to establish the geotechnical design parameters. Two (2) borings were drilled at the site as shown in the Borehole Location Plan. A resume of the borings is as follows:

Borehole	Depth (m)	Drilling Period
BH-1	10.00	May 24-26, 1994
BH-2	10.00	May 27, 1994

The boreholes were drilled by a combination of the wash boring technique through unlithified materials and core drilling through rock formations. In the wash boring method of advancing

SUBSURFACE EXPLORATION * LABORATORY TESTING * FIELD LOAD TESTING * EVALUATION &
ENGINEERING REPORTS * FOUNDATION RECOMMENDATIONS * WELL DRILLING * SPECIAL PROBLEMS

the borehole. a chopping bit attached to the bottom end of a string of drilling rods was alternately raised and dropped and, at the same time, the cuttings resulting from the process were continuously pumped out of the hole by pressure controlled water. At regular intervals through soils, representative samples were obtained using a standard 2-inch diameter split-spoon sampler coupled to the bottom end of the string of rods. Standard penetration tests (SPT) were conducted contemporaneous to split-spoon sampling in order to measure the consistencies of the strata encountered. This test was carried out by dropping a standard 63.6 kg (140 lb) hammer through a free fall of 76.2 cm (30 inches) onto a drive head coupled to the top end of the string of rods. The number of blows (drops) for three (3) successive six (6)-inch increments of penetration were recorded and the total number of blows for the last two (2) increments of penetration was taken as the standard penetration value or SPT-N value of the stratum.

At regular intervals through rock formations, core samples were taken using coring bit which was attached to a standard core barrel. In the drilling operation, the bit and core barrel rotate while pressure is applied, thus, grinding a groove around the core. Water under pressure is forced down the barrel and into the bit to carry the rock dust out of the hole as the water is circulated. The core recoveries after each

drilling interval were taken to determine the degree of disturbance of the rock core samples.

Finally, the representative soil samples obtained were subjected to laboratory routine classification and index property tests (grain size analysis, Atterberg limits and natural moisture content tests) while the typical intact rock cores were subjected to unconfined compression test.

The results of all field and laboratory tests undertaken are appended to this report (boring logs, grain size distribution curves and stress-strain curves).

DISCUSSION OF RESULTS

The results of the borings reveal the presence of lithified or rock formations near the beginning of the boreholes. Generally, sedimentary rock formations predominate the foundation of the project site.

A thin soil surficial layer with a thickness of about 1.0-1.5 m and consisting of silty clay overlies the lithified formations. The clay layer has a hard consistency (SPT-N greater than 45) with moisture content of 57-71% and plasticity index of 30-35.

Generally, poor to good core recoveries were

GEOTECHNICS PHILIPPINES, INC.

experienced in the underlying lithified or rock formations consisting of layers of sandstone, siltstone, tuff and claystone. Rock quality based on the rock quality designation (RQD) ranges from very poor to fair. Very poor rock quality, as experienced mostly in both boreholes, signifies intense fracturing and high degree of weathering.

The laboratory unconfined compression tests on upper core samples show that the sedimentary rocks are of medium hard variety. The unconfined compressive strengths of the samples range from 9.10 kg/sq. cm (18,200 psf) to 61.30 kg/sq. cm (122,600 psf). The lowest value was exhibited by the sample taken from a depth of about 3 meters in BH-2 while the sample from a depth of about 2 meters also in BH-2 gave the highest value. The claystone sample taken from a depth of about 7 meters exhibited a very low unconfined compressive strength of 0.30 kg/sq. cm (600 psf).

The depth of the ground water surface measured in both boreholes was about 3.0 meters below the ground surface.

CONCLUSIONS AND RECOMMENDATIONS

The design of the foundation structures of the proposed 2-storey building can be made as shallow foundations resting on the surficial clay layer or on the rock formation. The choice of

the type and design of shallow foundation structure depends on economic considerations and loading conditions.


For the proportioning of footings based on the surficial materials (i.e., based not more than 1.5 meters below present grade), the allowable bearing pressure under full vertical loading should be assumed at 3.0 kg/sq. cm (6,000 psf) net. Under load combinations with wind or earthquake, the allowable overpressure is one third (1/3).

Total settlement should be minimal (less than one inch) using the above allowable soil bearing pressure. It can be expected that foundation settlement will mostly take place during or immediately after the construction of the proposed structure. In the analysis of immediate settlement, the elastic properties modulus of elasticity and Poisson's ratio, may be assumed 2,000 psf and 0.25, respectively. The elastic properties may also be assumed based on the recommended values in most foundation engineering textbooks.

In view of the existing condition of the rock strata wherein the formations are generally of very poor to fair quality based on the values of RQD, the use of not more than fifteen (15) percent of the laboratory unconfined compressive strengths of the core samples tested is recommended to represent the field strength of the rocks. For the proportioning of footings based on

GEOTECHNICS PHILIPPINES, INC.

the upper rock formation, the allowable bearing pressure under full vertical loading should be assumed at 4.0 kg/sq. cm (8,000 lb/sq. ft), taking into account the decreasing strengths of the formations at lower depths and the fractured condition of the rocks. Settlement is expected to be minimal using this recommended allowable bearing pressure. Under load combinations with wind or earthquake, the allowed overpressure is also one third (1/3).




GILBERTO S. REYES
Civil Engineer
Reg. No. 20269

Company	Geotechnics Phil., Inc.		Borehole	BH-1
Project	Prop.Pesticide Laboratory Bldg.	Start	May 24, 1994	
Location	Diliman, Quezon City	Finish	May 26, 1994	
Equipment	LY-24	Groundlevel	42.67 m	
Method	Waashiboring & Coring	Hammer Wt.	63.6 Kg	
Watertable	3.00 m	Hammer Fall	76.2 cm	
E	20,004.50		N	20,052.00

Depth Metres	Samp no	Type test	Recovery cm.	Blow Count (NV)		RQD %	Legend	Description	Level m
				Core Recovery (%)					
42.67								(CH) Silty CLAY with few sand; yellowish brown; we NMC=71%; LL=66 PL=31 PI=35; No. of Blows = (5)(19)(30) HARD	42.67
1.00	S-1	SPT	45	49					
	S-2	SPT	10		60/10			(SM) Silty SAND with gravel; dark brown; very moist NMC=51%; AL=NP; No. of Blows = (60/10) HARD	41.12 41.02
2.00	C-1	CRG	31	31		0		SILTSTONE with thin layer of sandstone; light brown; highly fractured; moist HARD	
3.00	C-2	CRG	42	31		0		SANDSTONE; light brown to dark gray; highly fractured VERY DENSE	39.80
4.00	C-3	CRG	70	47		0		TUFF; gray; gray; weathered; highly fractured; weakly fractured HARD	38.51
5.00	C-4	CRG	43	29		53		CLAYSTONE; yellowish brown; moderately fractured HARD	36.99
6.00	C-5	CRG	76	76		76			
7.00	C-6	CRG	41	41		0		... highly fractured	
8.00	C-7	CRG	54	54		52		SILTSTONE; dark brown; moderately fractured HARD	33.67
9.00								End of hole at 10.00 metres.	32.67
10.00									
11.00									


Remarks:	CRG = CORING	Drilled by	V. Oliva
		Logged by	O.P.Mercado
		Prepared by	E.G.Mercado
		APPROVED	A.P.Arcilla
Descr. of strata according to USC Classifications		Scale:	1:75




Company	Geotechnics Phil., Inc.		Borehole	BH-2
Project	Prop. Pesticide Laboratory Bldg.	Start	May 27, 1994	
Location	Diliman, Quezon City	Finish	May 27, 1994	
Equipment	LY-24	Groundlevel	42.69 m	
Method	Washboring & Coring		Hammer Wt.	63.6 Kg
Watertable	3.00 m	Hammer Fall	76.2 cm	
E	19,938.00		N	20,086.50

Depth Metres	Samp no	Type test	Recovery cm.	Blow Count (NV)		ROD %	Legend	Description	Level m
				Core Recovery (%)	0 100 1				
1.00	S-1	SPT	25	11	60/15		(CH) Silty CLAY with sand; brown; very moist; NMC=57%; LL=60 PL=30 PI=30; No. of Blows = 11(60/15) HARD	42.69	
2.00	C-1	CRG	54	47	●	0	Tuffaceous SILTSTONE with thin layer of sandstone; brown to gray; HARD	41.84	
3.00	C-2	CRG	107	71	●	41	Tuffaceous SANDSTONE, fine to coarse grained; dark gray; weakly cemented VERY DENSE	40.69	
4.00	C-3	CRG	80	53	●	20	SANDSTONE, fine to coarse grained; dark gray; weakly cemented; highly fractured VERY DENSE	39.19	
5.00	C-4	CRG	60	40	●	23			
6.00	C-5	CRG	145	97	●	22	TUFF; dark gray; weathered HARD	35.50	
7.00								35.24	
8.00	C-6	CRG	92	92	●	50	CLAYSTONE; dark gray to yellowish brown; highly fractured HARD	34.61	
9.00	C-7	CRG	99	99	●	29	SILTSTONE; dark brown; moderately fractured HARD		
10.00							Tuffaceous SANDSTONE, dark brown to dark gray; weakly jointed; moderately fractured VERY DENSE	32.29	
11.00							End of hole at 10.00 metres.	32.69	

Remarks:	Washboring & Coring	Drilled by	V. Oliva
		Logged by	O.P. Mercado
		Prepared by	E.G. Mercado
		APPROVED	A.P. Arcilla
Descr. of strata according to USC Classifications		Scale:	1:75




SECTION A-A :




SOIL PROFILE

VERTICAL SCALE
HORIZONTAL SCALE

100 MTS.
250 MTS.



PROPOSED PESTICIDE LABORATORY BLDG.
DILIMAN QUEZON CITY



(2) PAL-Davao

OFFICE 921-1349
921-0481
921-5241 loc. 2
LABORATORY: 99-36-02

GEOTECHNICS PHILIPPINES, INC.

800 E. DE LOS SANTOS AVENUE, QUEZON CITY, PHILIPPINES * CABLE ADDRESS: GEOTECH
TELEX NO. 722-27877 FFC PH FAX NO. 921-12-23

FINAL REPORT ON THE SUB-SURFACE INVESTIGATION CONDUCTED AT THE SITE OF THE PROPOSED PESTICIDE LABORATORY BUILDING LOCATED IN BAGO OSHIRO, DAVAO CITY

I. INTRODUCTION

This report presents the geotechnical study conducted on the site of the Proposed One-Storey Pesticide Laboratory Building located in Bago Oshiro, Davao City

GEOTECHNICS PHILIPPINES, INC. was commissioned by YOKOGAWA ENGINEERS & ARCHITECTS of Japan to conduct the soil investigation and topographic survey of the proposed project.

The site is located in Davao National Crop Research and Development Center, about 17 Km. from the city proper and the area are planted by fruit bearing trees of different variety.

We acknowledged the presence of Yokogawa architect and staff of Bureau of Plant and Industry in facilitating our undertakings.

II. SUB-SURFACE INVESTIGATION

2.1 General

The program of investigation work was designated by the Client consisting of two (2) holes with a total meterage of 20.00 meters and an area of 40m. x 50m. for topographic survey. A slight variations were made to suit actual field conditions.

2.2 Method of Sampling and Drilling

A motorized cathead was employed initially, then a hydraulic feed rotary drilling machine was reinforced to advance the drill holes on boulder formations. Washboring technique was used to penetrate ordinary soil while rotary drilling was used to advanced through rock formation.

Standard penetration testing (SPT) was carried-out in soil at depth intervals of not more than 1.0m. This test was performed using procedures and equipment conforming to ASTM D1586.

Core drilling was achieved by means of NQ size double tube core barrels fitted with diamond bits. After each drilling run of 1.5m. the core barrel is withdrawn from the drill hole and the core sample recovered is examined.

2.3 Drilling Investigation

As schedule our team mobilize ahead on site to comply the May 30, 1994, date of actual boring test. No prior inspection were made on the site and only light equipment was mobilized to carry-out the investigation. The following resume of boring test are as follows:

- BH-1 - May 30 - 31, 1994 - 2.0 meters deep
Hit boulders at 2.30 m.
confirm by offset holes
BH-1A and BH-1B
- BH-2 - June 1, 1994 - 0.65 meters deep
Confirm by test pit and
two offset hole BH-2A
and BH-2B
- BH-3 - June 2, 1994 - 3.0 meters deep
Hit boulder at 3.30 meters
offset holes BH-3A and BH-3B
shallower boulder
- BH-4 - June 3, 1994 - 1.0 meter deep
Hit boulder at 1.30 meters
- BH-1 - June 24-26, 1994 - 10.00 meters deep


The area is said to be underlain by an alluvial deposit of big boulders from the slope of Mount Apo and the topmost soil are residual soil of high plasticity. Refusal or boulder formation was hit at various depth ranging from 0.65 meters to 3.30 meters from the ground level. Water table was observed at level -5.15 from ground on BH-1.

III. FINDINGS AND RECOMMENDATION

Based on the results of investigation on the proposed building, the area has two interface, the clay formation on the top layer (0.65 to 3.30) and the boulders and cobbles formation down to 10.00 meters deep. These boulders formation are believed to have CLAY-SILT matrix. For the purpose of construction design the footings may be founded at surficial layer (0.70-1.00m.) using the allowable bearing pressure of 1500 psf. A footing tie beam is recommended to counteract the effect of differential settlement as some footings may rest on boulders while some may embed on soil. The settlements are expected to be minimal (less than 25mm.) using the above bearing capacity. Under load combinations with wind or earthquake, the allowed over pressure is 33%.

During construction, the foundation bed should be compacted and or a well compacted gravel bedding should be placed to develop a better contact between the concrete and the soil.

The above recommendation were based on the borings done on site and should any major changes in soil strata be discovered during construction the under-signed should be informed so that necessary recommendations be made.



DIOSDADO A. URENA
Civil Engineer
PTR No. 1404257
Issued on July 29, 1993
Quezon City, Metro Manila


GEOTECHNICS PHIL., INC.			Borehole BH-1	
Project	PROP. PESTICIDE LABORATORY BLDG.	Start	May 30, 1994	Sheet 1 of 1.
Location	Bago Oshiro, Davao City	Finish	June 26, 1994	0.00 to 10.00 metres
Equipment	CATHEAD / ACKER ACE	Groundlevel 110.54 m		
Method	Washboring / Coring	Hammer Wt. 63.6 Kg		
Watertable	5.15 m	Hammer Fall 76.2 cm		

Depth Metres	Samp no	Type test	NMC	LL %	PI %	NV	NV 0	NV 100	1	Rec	Legend	Description	Level m
1.00	S-1	SPT	38	70	38	9				30	(CH) Silty CLAY with little sand and some fibrous matter; dark brown; very moist STIFF NV: (2)(3)(6)	110.5	
2.00	S-2	SPT	46	88	56	15				30	... with few gravel. VERY STIFF NV: (5)(6)(9)	109.5	
3.00											Basaltic BOULDER, gray NV:	108.5	
4.00	C-1	CRG								38	MH Clayey SILT with few coarse gravel, light brown; very moist VERY STIFF NV: (11) (14) (15)	106.5	
5.00	S-3	SPT	46	55	22	29				40	Sub-rounded to angular COBBLES, gray RQD = 0 NV:	106.0	
6.00	C-2	CRG								30	Basaltic BOULDER, gray RQD = 0 NV:	105.0	
7.00	C-3	CRG								17	RQD = 17 NV:	104.0	
8.00	C-4	CRG								28	...with some semi-rounded gravel RQD = 16 NV:	103.0	
9.00	C-5	CRG								25	Basaltic COBBLES with few semi-rounded gravel NV:	102.0	
10.00	C-6	CRG								15	Basaltic BOULDER, gray RQD = 45 NV:	101.0	
11.00	C-7	CRG								33	End of hole at 10.00 metres.	100.5	




Remarks: Hit BOULDER at 2.30 mts. Confirm by offset holes, BH-1A and BH-1B	Drilled by W. Mosqueda
Additional depth between June 24-26, 1994	Logged by C.L. Arcilla
NV = No. of Blows	Checked E.G. Mercado
Descr. of strata according to ASTM Classifications	APPROVED A.P. Arcilla
	Scale: 1:100

GEOTECHNICS PHIL., INC.										Borehole BH-1			
Project		PROP. PESTICIDE LABORATORY BLDG.			Start		May 30, 1994			Sheet 1 of 1.			
Location		Bago Oshiro, Davao City			Finish		May 31, 1994			0.00 to 2.00 metres			
Equipment		CATHEAD			Groundlevel		110.54 m						
Method		Washboring			Hammer Wt.		63.6 Kg						
Wetertable		Nil m			Hammer Fall		76.2 cm						
Depth Metres	Samp no	Type test	NMC	LL %	PI %	NV	NV - 0	100	1	Reo	Legend	Description	Level m
												(CH) Silty CLAY with little sand and some fibrous matter; dark brown; very moist STIFF NV: (2)(3)(6)	110.5
1.00	S-1	SPT	38	70	38	9	0			30		... with few gravel VERY STIFF NV: (5)(6)(9)	
2.00	S-2	SPT	46	88	56	15	0			30		End of hole at 2.00 metres.	108.5
3.00													
Remarks: Hit BOULDER at 2.30 mts. Confirm by offset holes, BH-1A and BH-1B										Drilled by		W. Mosqueda	
										Logged by		A.P. Arcilla	
										Checked		E.G. Mercado	
NV = No. of Blows										APPROVED		A.P. Arcilla	
Descr. of strata according to ASTM Classifications												Scale: 1:25	



GEOTECHNICS PHIL., INC.			Borehole BH-2	
Project	PROP.PESTICIDE LABORATORY BLDG.	Start	June 1, 1994	
Location	Bago Oshiro, Davao City	Finish	June 1, 1994	
Equipment	CATHEAD	Groundlevel		111.21 m
Method	Washboring	Hammer Wt.		63.6 Kg
Watertable	Nil	Hammer Fall		76.2 cm

Depth Metres	Samp no	Type test	NMC	LL %	PI %	NV	NV 0 100 1	Rec	Legend	Description	Level m
										(CH) Silty CLAY with little sand, few gravel and some fibrous matter; dark brown; very moist STIFF NV: (2)(4)(7)	111.2
	S-1	SPT	52	78	46	11	10			End of hole at 0.65 metres.	110.5
1.00											
2.00											
3.00											




Remarks: Hit BOULDER at 0.65mts. Confirm by test pit hole and two offset hole BH-2A & BH-2B.	Drilled by W. Mosqueda
	Logged by A.P.Arcilla
	Checked E.G.Mercado
NV = No. of Blows	APPROVED A.P.Arcilla
Descr. of strata according to ASTM Classifications	Scale: 1:25

GEOTECHNICS PHIL., INC.										Borehole	BH-3	
Project		PROP. PESTICIDE LABORATORY BLDG.			Start	June 2, 1994 <th colspan="3">Sheet 1 of 1.</th>			Sheet 1 of 1.			
Location		Bago Oshiro, Davao City			Finish	June 2, 1994			0.00 to 3.00 metres			
Equipment		CATHEAD			Groundlevel			111.80 m				
Method		Washboring			Hammer Wt.			63.6 Kg				
Watertable		Nil			Hammer Fall			76.2 cm				
Depth Metres	Samp no	Type test	NMC	LL %	PI %	NV	NV - 0	100	1	Legend	Description	Level m
											(CH) Silty CLAY with little sand and some fibrous matter; dark brown; very moist FIRM NV: (3)(4)(5)	111.8
1.00	S-1	SPT	47	81	49	9	0		40		... with few sand STIFF NV: (5)(4)(6)	
2.00	S-2	SPT	53	95	62	10	0		40		... with little sand NV: (6)(5)(7)	
3.00	S-3	SPT	56	80	48	12	0		40		End of hole at 3.00 metres.	108.8
Remarks: Hit BOULDER at 3.30mts. Offset holes BH-3A & BH-3B show a shallower hard stratum.										Drilled by		W. Mosqueda
										Logged by		A.P. Arcilla
										Checked		E.G. Mercado
NV = No. of Blows										APPROVED		A.P. Arcilla
Descr. of strata according to ASTM Classifications												Scale: 1:25

GEOTECHNICS PHIL., INC.			Borehole	BH-4
Project	PROP. PESTICIDE LABORATORY BLDG.	Start	June 3, 1994	Sheet 1 of 1.
Location	Bago Oshiro, Davao City	Finish	June 3, 1994	0.00 to 1.00 metres
Equipment	CATHEAD			Groundlevel 110.96 m
Method	Washboring			Hammer Wt. 63.6 Kg
Watertable	Nil			Hammer Fall 76.2 cm


Depth Metres	Samp no	Type test	NMC	LL %	PI %	NV	NV 0 100 1	Rec	Legend	Description	Level m
										(CH) Silty CLAY with little sand and some fibrous matter; dark brown; very moist FIRM NV: (2)(2)(4)	110.9
	S-1	SPT	52	93	60	6	0	40			
1.00										End of hole at 1.00 metres.	109.9
2.00											
3.00											



Remarks: Hit BOULDER at 1.30mts.	Drilled by	W. Mosqueda
	Logged by	A.P. Arcilla
	Checked	E.G. Mercado
NV = No. of Blows	APPROVED	A.P. Arcilla
Descr. of strata according to ASTM Classifications		Scale: 1:25

SECTION A-A


SECTION B-B




SOIL PROFILE

VERTICAL SCALE 1: 100 MTS.
HORIZONTAL SCALE 1: 50 MTS.

PROPOSED PESTICIDE LABORATORY BLDG.
BAGO OSHIRO DAVAO CITY




BASIC DESIGN DRAWINGS



PLOT PLAN 1/1,000


PROJECT SITE : BPI NURSERY



VICINITY MAP



FLOOR AREAS

BUILDING	FLOOR AREA (m ²)
MAIN BUILDING	2,270.38
ANNEX	286.72
GREEN HOUSE	81.00
TOTAL FLOOR AREA	2,638.10




MAIN BUILDING GROUND FLOOR PLAN 1/300


PAL-CENTRAL: MAIN BUILDING GROUND FLOOR PLAN





MAIN BUILDING SECOND FLOOR PLAN 1/300




SIDE A ELEVATION 1/300




SIDE B ELEVATION 1/300




SIDE C ELEVATION 1/300




SIDE D ELEVATION 1/300




SIDE E ELEVATION 1/300







ANNEX FLOOR PLAN 1/300



GREEN HOUSE FLOOR PLAN 1/300




NORTH ELEVATION 1/300




NORTH & SOUTH ELEVATION 1/300




EAST & WEST ELEVATION 1/300




SOUTH ELEVATION 1/300




SECTION 1/300



WEST ELEVATION 1/300



SECTION 1/300




EXISTING BUILDINGS

- ① FRUITS COMMODITY SECTION
- ② PLANT PEST & DISEASE LABORATORY
- ③ PLANT TISSUE CULTURE LABORATORY
- ④ SEED QUALITY CONTROL LABORATORY
- ⑤ PRODUCTION SECTION
- ⑥ S M A P
- ⑦ PAVILLION
- ⑧ ADMINISTRATIVE OFFICE (BPI)
- ⑨ RESEARCH
- ⑩ PESTICIDE ANALYTICAL LABORATORY (EXISTING)


PAL-DAVAO
TOTAL FLOOR AREA : 437.93m²

PAL-DAVAO PLOT PLAN 1/1,000


FROM DAVAO CITY




PLAN 1/300




WEST ELEVATION 1/300




EAST ELEVATION 1/300



SOUTH ELEVATION 1/300



NORTH ELEVATION 1/300



SECTION 1/300

JICA