

LOCAL GOVERNMENT ENGINEERING DEPARTMENT,
MINISTRY OF LOCAL GOVERNMENT, RURAL DEVELOPMENT
AND COOPERATIVES
THE PEOPLE'S REPUBLIC OF BANGLADESH

BASIC DESIGN STUDY REPORT
ON
THE PROJECT FOR THE CONSTRUCTION OF
MULTIPURPOSE CYCLONE SHELTERS (II)
IN
THE PEOPLE'S REPUBLIC OF BANGLADESH

(APPENDIX 9. RESULTS OF SITE CONDITIONS SURVEY
APPENDIX 10. RESULTS OF NATURAL CONDITIONS SURVEY)



OCTOBER, 1995


JAPAN INTERNATIONAL COOPERATION AGENCY
JAPAN ENGINEERING CONSULTANTS CO., LTD.

G R S
C R (2)
95-240-2

BASIC DESIGN STUDY REPORT ON THE PROJECT FOR THE CONSTRUCTION OF
MULTIPURPOSE CYCLONE SHELTERS (II) IN THE PEOPLE'S REPUBLIC OF BANGLADESH

(APPENDIX 9.
APPENDIX 10.)

OCTOBER, 1995



95-240-2



1125568 [4]

**LOCAL GOVERNMENT ENGINEERING DEPARTMENT,
MINISTRY OF LOCAL GOVERNMENT, RURAL DEVELOPMENT
AND COOPERATIVES
THE PEOPLE'S REPUBLIC OF BANGLADESH**

**BASIC DESIGN STUDY REPORT
ON
THE PROJECT FOR THE CONSTRUCTION OF
MULTIPURPOSE CYCLONE SHELTERS (III)
IN
THE PEOPLE'S REPUBLIC OF BANGLADESH**

**(APPENDIX 9. RESULTS OF SITE CONDITIONS SURVEY
APPENDIX 10. RESULTS OF NATURAL CONDITIONS SURVEY)**

OCTOBER, 1995

**JAPAN INTERNATIONAL COOPERATION AGENCY
JAPAN ENGINEERING CONSULTANTS CO., LTD.**

CONTENTS

Appendix 9. Results of Site Conditions Survey	A9-1
Appendix 10. Results of Natural Conditions Survey	A10-1
10-1 Topographic Survey.....	A10-1
10-2 Geological Survey.....	A10-33
10-2-1 Locations of Boring Holes	A10-35
10-2-2 Boring Log.....	A10-51
10-2-3 Summary of Laboratory Tests.....	A10-67
10-2-4 Grain Size Distribution.....	A10-83
10-2-5 Unconfined Compression Tests.....	A10-99

APPENDIX 9.

RESULTS OF SITE CONDITIONS SURVEY

APPENDIX 9. RESULTS OF SITE CONDITIONS SURVEY

(1) Site Conditions Survey

The Government of Bangladesh initially put forward 63 candidate sites for the Project (III). Having examined and discussed the list of candidate sites in view of the actual implementation period of the construction work under the grant aid scheme of the Government of Japan, the local distribution of the listed candidate sites, the types of existing schools, the envisaged period for the basic design study and the findings of the preliminary study at Thana Mirsharai, the Japanese government organizations related to the Project (III) decided to select 25 sites located in the Chittagong, Laxmipur and Noakhali Districts, in turn situated inside the HRA. The site conditions survey would then be conducted and, based on the findings of this survey, 18 sites would be identified as high priority sites. The number would finally be reduced to 15 based on the results of the natural conditions survey and the basic plan regarding the actual construction of cyclone shelters would address these 15 high priority sites.

In short, 25 sites located in the Chittagong, Laxmipur and Noakhali Districts were selected (see Table A-9-1) out of the originally requested 63 sites for the survey to confirm the site conditions.

The site conditions survey was conducted at the 25 selected sites. In view of the fact that all the selected sites were primary school premises, the survey tried to identify the following details.

(1) Locational Conditions

- Site access
- Land ownership
- Site area

(2) Items Related to School Education

- State of building(s)
- Number of pupils and teachers
- State of drop-out
- Available educational fittings
- Auxiliary facilities
- Maintenance system

(3) Items Related to Cyclones


- Population within a 1.5 km radius
- Distance to nearest cyclone shelter
- Actual cyclone damage in the past (number of casualties, damage to housing, damage to farming and storm surge height, etc.)
- Cyclone warning system in the neighbourhood
- Availability of killa(s) in the neighbourhood

(4) Others

- Items to be confirmed should the Project be implemented
 - * Necessity for demolition of existing school building(s)
 - * Construction body for temporary school building to be used during the construction of planned facilities
 - * Neighboring inhabitants' participation in operation and maintenance
- Job capabilities of possible sub-contractors based near the sites
- Availability of procuring construction materials and equipment, etc. near the sites

The findings of the site conditions survey at each site are shown in the following check lists, photographs, etc.

Fig. A-9-1 Locations of 25 Sites Selected for Site Conditions Survey



SITE SURVEY CHECK LIST

(Date: 1995/3/25)

1. Site No. 9
 2. Name of School: *Tingharia Tola Abu Taher GPS*
 3. Site Location : District: *Chittagong* Thana : *Mirsharai*
 Union : *Moshandia* Village: *Tingharia Tola*
 4. Interviewee : Name : *Mr. Profulla* Position: *Headmaster*
 5. Accessibility *Kumar Nath*
 - 1) Nearest Station, Port, Main Road *Dhaka - Chittagong* Distance: *7.5* km
 - 2) Road Conditions *1 Km Road*
 - Kind of Pavement: Earth, Gravel, Brick, Asphalt, Concrete.
 - Condition of Pavement: Good, Not so good, Bad
 - Road Width : *2.5 to 3.0 m* *Road gets muddy in rainy seasons*
 - Passable Vehicle: Motor cycle, Rikisha, Sedan, Jeep, Truck (*2.0 ton*)
only in dry seasons
 - Necessity for Repair of Road: Yes, No
 - Necessity for Repair of Bridges or Culverts: Yes, No
 6. Conditions of School
 - 1) Name of Landowner : *Government*
 - 2) Area of School Site : *1.482* m² (including Playground of *722* m²)
 - 3) School Building : *1* no(s) (Floor Area: *15.2 m x 5.3 m = 80.56* m²)
 - 4) Type of Building : RC, Brick, Wooden
 - 5) Building conditions : Good, Not so good, Bad (*7* years after built)
 - 6) Layout of Building : Class Room : *3* nos (*4.13 m x 5.3 m*)
 Teacher's Room: *1* no(s) (*2.8 m x 5.3 m*)
 Other : *-* no(s) (*- m x - m*)
 - 7) Number of Pupils : *386* nos (Single education, Two shift education)
 (Class-1: *90* nos, Class-2: *85* nos, Class-3: *84* nos)
 (Class-4: *60* nos, Class-5: *47* nos)
 - 8) Number of Drop-outs : Class-1: nos, Class-2: nos, Class-3: nos
 Class-4: nos, Class-5: nos.
 - 9) Reasons of Drop-outs: ① *Economic*, ②, ③
 - 10) Countermeasures for 9): ① *Income Increase*, ② *Making guardians*, ③
 - 11) Number of Teachers : *7* nos $\frac{M-5}{F-2}$ *understand the necessity of education*
 - 12) Ancillary Facility: Well (Yes) No, if yes, Depth of Well: *15* m
 with pump or not)
 Present Conditions: Good, Not so bad, Bad
 Toilet (Yes) No, if yes, Common or separate)
 Present Conditions: Good, Not so bad, Bad
 Electric Facility (Yes, No) ** 220V line within the site.*
 - 13) Material of Fixtures: Desk (*Wooden*), Chair (*Wooden*)
 Locker ()
 - 14) Number of School Aged Children
 within School Attendance Area: *460* nos (Radius: *1* km)
 - 15) Maintenance of Building: Place: Roof (Leaking of rain?), Pillar (Exfoliate
 of concrete?), Wall (Color painting?),
 Window (Window/door fitting?),
 Method: Name of organization, Organizational
 unit for maintenance (*PMED (LAFD) through Tola Education
 (H.Q. District. Committee
 Thana or school)*), Procedure for repair
 (Requesting, Patrol by engineer=when)
by School Management Committee (SMC)
- No maintenance has been done since 1991.*
- Present wooden school building was constructed by public donation.*

7. Surrounding Conditions

- 1) Population within a 1.5km Radius: 7,000 nos
- 2) Distance to Neighbouring Primary School : 1.0 km
- 3) Distance to Neighbouring Cyclone shelter : 1.6 km
- 4) Neighbouring Killa : Distance from the School: _____ m
 Size(Top) : _____ m x _____ m. Height: _____ m
~~Progress Ratio: _____ %~~
- 5) Topographic Conditions Nearby : *Non-existing*
 (Obstruction for School Attendance or Evacuation at Cyclone Time) : *Pond is near the site, but no objection for school attendance, etc*
- 6) Normal Flood Level in Site : *0.3m above the existing ground level*
- 7) Neighbouring Warning System : Warning organization: *BDRCS*
 for Cyclone Measure of warning: *Hand-mike*
 Kind of signal: *Flag; Lavel 1 ~ 10..*
- 8) Maximum Damage by Cyclone in the Past : Year of Hitting: *1963*
 Casualties; nos (Why so many died?) : *700 persons.*
 (How to solve?) : *by climbing up trees or roof.*
 Surge Height: *3.0 m*
 Houses Brokened: *50% nos*
 Damage of Crops: *50% ha*
 Damage of Livestock: Cow - nos. } *90%*
 Goat - nos. }
 Sheep - nos. }

8. Item to Be Confirmed in Case of the Project Being Executed

- 1) Necessity for Demolition of : Yes (If yes: Executing Body _____). (No)
 the Existing School Building
- 2) Construction Body for Temporary School Building during the Construction of New school. : *A Temporary school building is not necessary to be constructed.*
- 3) Management and Maintenance System for Planned Facilities (Shelter-cum-school) : *PMED, SMC, Local people.*
- 4) Neighbouring Inhabitants' Participation in Management and Maintenance for the Planned Facilities : *To be participated through donation.*

9. Capability of Sub-Contractor near the Site

- 1) ~~Name~~ of Sub-Contractor : *3 nos.*
- 2) No. of Engineers : *None*
- 3) Past Experience and Construction Records : *- N.A. -*


10. Availability of Procuring Construction Equipment and Materials

- 1) Equipment:) *Not available*
- 2) Materials:)

11. Other Remarks

Location Map of the Site


Site No.: 9



Sketch of the Site


Site No. : 9

Name of School : Tingharia Tola Abu
Tahur GPS





View of the School Building



Current Conditions of A Classroom




Auxiliary Facilities of the School Building



Auxiliary Facilities of
the School Building

Current Conditions
near the Site
(including topographic
features)



Road Conditions
near the Site

SITE SURVEY CHECK LIST

(Date: 5/19/95 / 3 / 24)

1. Site No. 11
2. Name of School: West Hailkandi GPS
3. Site Location : District: Chittagong Thana : Mirsharai
Union : Hailkandi Village: West Hailkandi
4. Interviewee : Name : Mr. Md. Khurshid Position: Headmaster
5. Accessibility
Alam
 - 1) Nearest Station, Port, Main Road: Distance: 2.5 km
 - 2) Road Conditions
 - Kind of Pavement: Earth, Gravel, Brick, Asphalt, Concrete,
 - Condition of Pavement: Good, Not so good, Bad
 - Road Width : 2.0 m *Road gets muddy in rainy season*
 - Passable Vehicle: Motor cycle, Rikisha, Sedan, Jeep, Truck (2 ton) *only in dry season*
 - Necessity for Repair of Road: Yes No,
 - Necessity for Repair of Bridges or Culverts: Yes, No
6. Conditions of School
 - 1) Name of Landowner : Government
 - 2) Area of School Site : 997.5 m² (including Playground of 594 m²)
 - 3) School Building : 1 no(s) (Floor Area: 7.9 m x 23 m = 181.7 m²)
 - 4) Type of Building : RC, Brick Wooden
 - 5) Building conditions : Good, Not so good, Bad (30 years after built)
 - 6) Layout of Building : Class Room : 3 nos (2.5/5.0/2.5m x 5.6 m)
Teacher's Room: 1 no(s) (2.0 m x 5.6 m)
Other : - no(s) (- m x - m)
 - 7) Number of Pupils : 236 nos (Single education, Two shift education)
(Class-1: 66 nos, Class-2: 52 nos, Class-3: 45 nos)
(Class-4: 40 nos, Class-5: 43 nos)
 - 8) Number of Drop-outs : Class-1: nos, Class-2: nos, Class-3: nos
0% Class-4: nos, Class-5: nos.
 - 9) Reasons of Drop-outs: ①, ②, ③
 - 10) Countermeasures for 9): ①, ②, ③
 - 11) Number of Teachers : 5 nos
 - 12) Ancillary Facility: Well (Yes, No, if yes, Depth of Well; 22.5 m with pump or not)
Present Conditions: Good, Not so bad Bad,
Toilet (Yes, No, if yes, common or separate)
Present Conditions: Good, Not so bad, Bad out of use
Electric Facility (Yes, No) * 220V line within 20m.
 - 13) Material of Fixtures: Desk(Wooden), Chair(Wooden)
Locker(Wooden)
 - 14) Number of School Aged Children within School Attendance Area: 400 nos (Radius: 0.5 km)
 - 15) Maintenance of Building: Place: Roof (Leaking of rain?), Piller (Exfoliate of concrete?), Wall (Color painting?), Window (Window door fitting?).
Method; Name of organization, Organizational unit for maintenance (PMED/USED through Thana H.Q., District Education Committee), Procedure for repair (Requesting, Patrol by engineer when) *by School Management Committee (SMC)*

7. Surrounding Conditions

- 1) Population within a 1.5km Radius: *7,500* nos
- 2) Distance to Neighbouring Primary School : *1.5* km
- 3) Distance to Neighbouring Cyclone shelter : *2.5* km
- 4) Neighbouring Killa : Distance from the School: _____ m
 Size (Top) : _____ m x _____ m, Height: _____ m
none-existing Progress Ratio: _____ %
- 5) Topographic Conditions Nearby :
 (Obstruction for School Attendance or Evacuation at Cyclone Time) *No objection*
- 6) Normal Flood Level in Site *0.6 m above the existing ground level.*
- 7) Neighbouring Warning System : Warning organization: *BDRCS*
 for Cyclone Measure of warning: *Hand-siren*
 Kind of signal: *none*
- 8) Maximum Damage by Cyclone in the Past : Year of Hitting: *1963*
 Casualties; nos (Why so many died?) *1,000 persons*
 (How to solve?) *by climbing trees or roofs*
 Surge Height: *2.5* m
 Houses Brokened: *100% nos*
 Damage of Crops: *100% ha*
 Damage of Livestock: Cow nos. }
 Goat nos. } *20%*
 Sheep nos. }

8. Item to Be Confirmed in Case of the Project Being Executed

- 1) Necessity for Demolition of : Yes (If yes; Executing Body _____). No.
 the Existing School Building
- 2) Construction Body for Temporary School Building during the Construction of New school. : *Temporary school building is not necessary to be constructed.*
- 3) Management and Maintenance System for Planned Facilities (Shelter-cum-school) : *PMED, SMC*
- 4) Neighbouring Inhabitants' Participation in Management and Maintenance for the Planned Facilities : *Local people will try.*

9. Capability of Sub-Contractor near the Site

- 1) ~~Name~~ ^{No.} of Sub-Contractor *None*
- 2) No. of Engineers *-*
- 3) Past Experience and Construction Records *-*


10. Availability of Procuring Construction Equipment and Materials

- 1) Equipment:)
- 2) Materials:) *Not available.*

11. Other Remarks

Location Map of the Site


Site No. : //




Sketch of the Site

Site No. : 11

Name of School : West Haitkandi GPS





Overall View of
the School Site



View of the School
Building



Current Conditions
of A Classroom



Auxiliary Facilities of
the School Building



Auxiliary Facilities
of the School Building



Road Conditions
near the Site

SITE SURVEY CHECK LIST

(Date: 1995/3/25)

1. Site No. 12
2. Name of School: *Alia Pathan GPS (East Isakhali Ali Khan)*
3. Site Location : District: *Chittagong* Thana : *Minsharai*
 Union : *Isakhali* Village: *East Isakhali*
4. Interviewee : Name : *Mr. Md. Nurul Haque Khan* Position: *Headmaster*
5. Accessibility
 - 1) Nearest Station, Port, Main Road: Distance: *8.50* km
 - 2) Road Conditions
 - Kind of Pavement: Earth, Gravel, Brick, Asphalt, Concrete.
 - Condition of Pavement: Good, Not so good, Bad
 - Road Width : *2.5* m
 - Passable Vehicle: Motor cycle, Rikisha, Sedan, Jeep Truck (*2.0* ton)
 - Necessity for Repair of Road: Yes No,
 - Necessity for Repair of Bridges or Culverts: Yes, No
6. Conditions of School *Newly proposed site*
 - 1) Name of Landowner : Government
 - 2) Area of School Site : *1.150* m² (including Playground of - m²)
 - 3) School Building : *1* no(s) (Floor Area: *15.5* m × *5.8* m = *89.9* m²)
 - 4) Type of Building : RC, Brick, Wooden
 - 5) Building conditions : Good, Not so good, Bad (*14* years after built)
 - 6) Layout of Building : Class Room : *1* nos (*12.8* m × *5.8* m)
 Teacher's Room: *1* no(s) (*2.7* m × *5.8* m)
 Other - : - no(s) (- m × - m)
 - 7) Number of Pupils : *38* nos (Single education, Two shift education)
 (Class-1: *88* nos, Class-2: *76* nos, Class-3: *64* nos)
 (Class-4: *55* nos, Class-5: *35* nos)
 - 8) Number of Drop-outs : Class-1: nos, Class-2: nos, Class-3: nos
 5% Class-4: nos, Class-5: nos.
 - 9) Reasons of Drop-outs: ① *Economic Condition*, ② *Going to other*, ③
 - 10) Countermeasures for 9): ① *Income Increase*, ② *GPS*, ③
 - 11) Number of Teachers : *3* nos
 - 12) Ancillary Facility: Well (Yes No, if yes, Depth of Well; *15* m with pump or not)
 Present Conditions: Good, Not so bad, Bad
 Toilet (Yes, No if yes, common or separate)
 Present Conditions: Good, Not so bad, Bad
 Electric Facility (Yes, No) *Power line is installed 1.8 km away*
 - 13) Material of Fixtures: Desk (Wooden), Chair (Wooden)
 Locker (-)
 - 14) Number of School Aged Children within School Attendance Area: *1.000* nos (Radius: *1.0* km)
 - 15) Maintenance of Building: Place: Roof (Leaking of rain?), Piller (Exfoliate of concrete?), Wall (Color painting?), *Repaired in 1992*
 Window (Window door fitting?).
 Method: Name of organization, Organizational unit for maintenance *PMED / LGED through Thana Education Committee* (Thana or school), Procedure for repair (Requesting, Patrol by engineer=when)
by School Management Committee (SMC)

7. Surrounding Conditions

- 1) Population within a 1.5km Radius: *10,000 nos*
- 2) Distance to Neighbouring Primary School : *1.0 km*
- 3) Distance to Neighbouring Cyclone shelter : *3.0 km*
- 4) Neighbouring Killa : Distance from the School: _____ m
 Size (Top) : _____ m x _____ m. Height: _____ m
Non-existing Progress Ratio: _____ %
- 5) Topographic Conditions Nearby : _____
 (Obstruction for School Attendance or Evacuation at Cyclone Time) *Plain Land*
No objection
- 6) Normal Flood Level in Site *Access road gets muddy in rainy season.*
- 7) Neighbouring Warning System : Warning organization *Police, Radio*
 for Cyclone Measure of warning: _____
 Kind of signal: _____
- 8) Maximum Damage by Cyclone in the Past : Year of Hitting: *1963*
 Casualties; nos (Why so many died? *100 persons*)
 (How to solve? *by climbing up trees or roof*)
 Surge Height: *2.7 m*
 Houses Brokened; *100%* nos
 Damage of Crops: *100%* ha
 Damage of Livestock: Cow - nos. } *damaged.*
 Goat - nos. } *25%*
 Sheep - nos

8. Item to Be Confirmed in Case of the Project Being Executed

- 1) Necessity for Demolition of : Yes (If yes; Executing Body _____). *No*
 the Existing School Building
- 2) Construction Body for Temporary School : _____
 Building during the Construction of New school. *No need.*
- 3) Management and Maintenance System for Planned Facilities (Shelter-cum-school) : *PMED + Local People*
- 4) Neighbouring Inhabitants' Participation : _____
 in Management and Maintenance for the Planned Facilities *Local people will try to support the management and maintenance.*

9. Capability of Sub-Contractor near the Site

- 1) ~~Name~~ of Sub-Contractor *Few*
- 2) No. of Engineers _____
- 3) Past Experience and Construction Records *Culvert construction, etc.*


10. Availability of Procuring Construction

- Equipment and Materials
- 1) Equipment: _____
- 2) Materials: _____) *Not available*

11. Other Remarks

Location Map of the Site


Site No.: 12




Sketch of the Site


Site No. : 12

Name of School : Alia Pathan G.P.S
(East Isakhali Oli Khan)





Overall View of
the School Site



Overall View of
the School Building



Current Conditions
of A Classroom



Auxiliary Facilities of
the School Building



Newly Proposed Site
for Construction of
Cyclone Shelter-cum
-Primary School



Road Conditions
near the Site

SITE SURVEY CHECK LIST

(Date: 1995/ 3 / 26)

1. Site No. 13
2. Name of School: East Tetoiya GPS
3. Site Location : District: Chittagong Thana : Mirsharai
Union : Katachara Village: East Tetoiya
4. Interviewee : Name : Mr. Sulalit Kumar Position: Headmaster
Biswas
5. Accessibility
 - 1) Nearest Station, Port, Main Road: Distance: 5.0 km
 - 2) Road Conditions
 - Kind of Pavement: Earth, Gravel, Brick, Asphalt, Concrete.
 - Condition of Pavement: Good, Not so good, Bad
 - Road Width : 2.0 m Road gets muddy in rainy season
 - Passable Vehicle: Motor cycle, Rikisha, Sedan, Jeep Truck (only in dry season)
 - Necessity for Repair of Road: Yes, No.
 - Necessity for Repair of Bridges or Culverts: Yes, No
6. Conditions of School
 - 1) Name of Landowner : Government
 - 2) Area of School Site : 2,259 m² (including Playground of 1,200 m²)
 - 3) School Building : 2 no(s) (Floor Area: 10.3 m x 3.25 m = 33.5 m²)
 - 4) Type of Building : RC, Brick, Wooden
 - 5) Building conditions : Good, Not so good, Bad (4 years after built)
 - 6) Layout of Building : Class Room : 2 nos (3.92 m x 3.25 m)
Teacher's Room: 1 no(s) (2.93 m x 3.25 m)
Other : - no(s) (- m x - m)
 - 7) Number of Pupils : 23 nos (Single education, Two shift education)
(Class-1; 73 nos, Class-2; 46 nos, Class-3; 44 nos)
(Class-4; 37 nos, Class-5; 31 nos)
 - 8) Number of Drop-outs : Class-1: nos, Class-2: nos, Class-3: nos
20% Class-4: nos, Class-5: nos.
 - 9) Reasons of Drop-outs: ① Economic, ② Accommodation, ③ Condition
 - 10) Countermeasures for 9): ① Income Increase, ② Food for Education, ③
 - 11) Number of Teachers : 4 nos
 - 12) Ancillary Facility: Well (Yes, No, if yes, Depth of Well; 15 m with pump or not)
Present Conditions: Good, Not so bad, Bad Broken.
Toilet (Yes, No, if yes, common or separate)
Present Conditions: Good, Not so bad, Bad.
Electric Facility (Yes, No) 220V line (50m away)
- 13) Material of Fixtures: Desk(Wooden), Chair(Wooden)
Locker(-)
- 14) Number of School Aged Children within School Attendance Area: 200 nos (Radius; 1.0 km)
- 15) Maintenance of Building: Place: Roof (Leaking of rain?), Piller (Exfoliate of concrete?), Wall (Color painting?), Window (Window door fitting?).
Method: Name of organization, Organizational unit for maintenance PMED / LGED / Mirsharai Thana Education Committee (H. Q., District, Thana or school). Procedure for repair (Requesting, Patrol by engineer-when) by School Management Committee (SMC).

Minor repair has been done by local people.

7. Surrounding Conditions

- 1) Population within a 1.5km Radius: *12,000 nos*
- 2) Distance to Neighbouring Primary School : *1.0 km*
- 3) Distance to Neighbouring Cyclone shelter : *3.5 km*
- 4) Neighbouring Killa : Distance from the School; _____ m
 Size(Top) : _____ m x _____ m. Height: _____ m
~~Progress Ratio: _____ %~~
Non-existing
- 5) Topographic Conditions Nearby : *Pond is next to the site, but no objection for School Attendance, etc.*
 (Obstruction for School Attendance or Evacuation at Cyclone Time)
- 6) Normal Flood Level in Site : *0.3 m above the existing ground level,*
- 7) Neighbouring Warning System : Warning organization; *BDRCS, Radio*
 for Cyclone Measure of warning; *Hand-mike*
 Kind of signal: *Flag; Level 1-10.*
- 8) Maximum Damage by Cyclone in the Past : Year of Hitting: *1963*
 Casualties; nos (Why so many died? *400 people*)
 (How to solve? *To construct a cyclone shelter*)
 Surge Height; *2.0 m*
 Houses Brokened; *100% nos*
 Damage of Crops; *100% ha*
 Damage of Livestock: Cow nos. } *65%*
 Goat nos. }
 Sheep nos. }

8. Item to Be Confirmed in Case of the Project Being Executed

- 1) Necessity for Demolition of : Yes (If yes; Executing Body _____). *(No)*
 the Existing School Building
- 2) Construction Body for Temporary School Building during the Construction of New school. : *No need.*
- 3) Management and Maintenance System for Planned Facilities (Shelter-cum-school) : *PMED, SMC.*
- 4) Neighbouring Inhabitants' Participation in Management and Maintenance for the Planned Facilities : *Minor maintenance work will be done by local people.*

9. Capability of Sub-Contractor near the Site

- 1) ~~Name~~ ^{*NA*} of Sub-Contractor : *3 Nos.*
- 2) No. of Engineers : _____
- 3) Past Experience and Construction Records : *N.A.*


10. Availability of Procuring Construction Equipment and Materials :

- 1) Equipment;)
- 2) Materials;) *Not available.*

11. Other Remarks

Location Map of the Site


Site No. : 13



Sketch of the Site

Site No. : 13

Name of School : East Totoiya GPS





Overall View of
the School Site



Overall View of
the School Building



Current Conditions
of a Classroom



Auxiliary Facilities
of the School Building



Road Conditions
near the Site

SITE SURVEY CHECK LIST

(Date: 1995/ 3/26)

1. Site No. 15
2. Name of School: Isakhali Kazigram GPS
3. Site Location : District: Chittagong Thana : Mirsharai
Union : Katachara 7 Village: Kazigram
4. Interviewee : Name : Md. Hai Nizami Position: Headmaster
5. Accessibility
 - 1) Nearest Station, Port, Main Road: Distance: 7.5 km
 - 2) Road Conditions
 - Kind of Pavement: Earth, Gravel, Brick, Asphalt, Concrete,
 - Condition of Pavement: Good, Not so good, Bad
 - Road Width : 2.5 m
 - Passable Vehicle: Motor cycle, Riksha, Sedan, Jeep, Truck (ton)
 - Necessity for Repair of Road: Yes, No.
 - Necessity for Repair of Bridges or Culverts: Yes, No
6. Conditions of School *Newly propose site.*
 - 1) Name of Landowner : Government
 - 2) Area of School Site: 782 m² (including Playground of - m²)
 - 3) School Building : 7 no(s) (Floor Area: 13.9 m x 4.4 m = 61.2 m²)
 - 4) Type of Building : RC, Brick, Wooden
 - 5) Building conditions : Good, Not so good, Bad (19 years after built)
 - 6) Layout of Building : Class Room : 2 nos (5.15 m x 4.6 m) x 2
Teacher's Room: 1 no(s) (3.6 m x 2.9 m)
Other : - no(s) (- m x - m)
 - 7) Number of Pupils : 265 nos (Single education, two shift education)
(Class-1: 67 nos, Class-2: 56 nos, Class-3: 49 nos)
(Class-4: 44 nos, Class-5: 45 nos)
 - 8) Number of Drop-outs : Class-1: nos, Class-2: nos, Class-3: nos
5% Class-4: nos, Class-5: nos.
 - 9) Reasons of Drop-outs: ① Economic, ② Going to other schools, ③
 - 10) Countermeasures for 9): ① Food for Education, ② Monthly Meeting of SMC, ③
 - 11) Number of Teachers : 5 nos
 - 12) Ancillary Facility: Well (Yes, No if yes, Depth of Well: m
with pump or not)
Present Conditions: Good, Not so bad, Bad.
Toilet (Yes, No if yes, common or separate)
Present Conditions: Good, Not so bad, Bad.
Electric Facility (Yes, No) * 220V line (7.1 km away)
- 13) Material of Fixtures: Desk(Wooden), Chair(Wooden)
Locker(Wooden)
- 14) Number of School Aged Children within School Attendance Area: 360 nos (Radius: 1.0 km)
- 15) Maintenance of Building: Place; Roof(Leaking of rain?), Piller(Exfoliate of concrete?), Wall(Color painting?), Window(Window door fitting?).
Method: Name of organization, Organizational unit for maintenance (H.Q., District, Thana or school), Procedure for repair (Requesting, Patrol by engineer=when)

Maintenance work has been done by local people only.

7. Surrounding Conditions

- 1) Population within a 1.5km Radius: 10,000 nos
- 2) Distance to Neighbouring Primary School : 2.0 km
- 3) Distance to Neighbouring Cyclone shelter : 0.3 km
- 4) Neighbouring Killa : Distance from the School: _____ m
~~Size(Top) : _____ m X _____ m. Height: _____ m~~
Now-existing Progres Ratio: %
- 5) Topographic Conditions Nearby : *Canal (500m away west)*
 (Obstruction for School Attendance or Evacuation at Cyclone Time) *no-bridge to cross it.*
- 6) Normal Flood Level in Site *0.4 m above the existing ground level.*
- 7) Neighbouring Warning System : Warning organization: *BDRCS.*
 for Cyclone Measure of warning: *Hand-mike*
 Kind of signal: *Flag; Level 1-10*
- 8) Maximum Damage by Cyclone in the Past : Year of Hitting: *1963*
 Casualties:nos(Why so many died?)
400 persons

(How to solve?)
to climbing up trees or roof.
 Surge Height: *2.0 m*
 Houses Brokened: *80% nos*
 Damage of Crops: *100% ha*
 Damage of Livestock: Cow -nos.)
 Goat -nos.) *25%*
 Sheep -nos.)

8. Item to Be Confirmed in Case of the Project Being Executed

- 1)Necessity for Demolition of : Yes (If yes;Executing Body) *No*
 the Existing School Building
- 2) Construction Body for Temporary School : *No need.*
 Building during the Construction of New school.
- 3) Management and Maintenance System for : *PMED, SMC.*
 Planned Facilities(Shelter-cum-school)
- 4) Neighbouring Inhabitants' Participation : *Minor maintenance will be done*
 in Management and Maintenance for the *by local people.*
 Planned Facilities

9. Capability of Sub-Contractor near the Site

- 1) ~~Name~~ ^{No.} of Sub-Contractor *2 or 3 Nos.*
- 2) No. of Engineers _____
- 3) Past Experience and Construction Records *culvert, road etc.*

10. Availability of Procuring Construction


Equipment and Materials
 1) Equipment:)
 2) Materials:) *Not available*

11. Other Remarks


Neighbouring shelter is located about 0.3 km away from the Site No. 15.

Location Map of the Site

Site No. : 15




Sketch of the Site



Site No. : 15

Name of School : Isokhali Kazigram G.P.S






Overall View of
the School Site



View of the School
Building



Current Conditions
of A Classroom



Existing Cyclone Shelter
located about 0.3km away
from the School Site



Road Conditions
near the Site

SITE SURVEY CHECK LIST

(Date: 1995/3/24)

1. Site No. 17

2. Name of School: South Saherkhali GPS.

3. Site Location : District: Chittagong Thana : Mirsharai
Union : Saherkhali 16 Village: Gozatia

4. Interviewee : Name : Mr. Ismail Position: Headmaster

5. Accessibility

1) Nearest Station, Port, Main Road Distance: 6.5 km

2) Road Conditions

- Kind of Pavement: Earth, Gravel, Brick, Asphalt, Concrete,

- Condition of Pavement: Good, Not so good, Bad.

- Road Width : 2.5 m

- Passable Vehicle: Motor cycle, Rikisha, Sedan, Jeep, Truck (2.0 ton) →

- Necessity for Repair of Road: Yes No. only in dry season.

- Necessity for Repair of Bridges or Culverts: Yes. No.

6. Conditions of School

1) Name of Landowner : Government

2) Area of School Site : 1,695.9 m² (including Playground of 200 m²)

3) School Building : 1 no(s) (Floor Area: 18 m × 6.50 m = 117.0 m²)

4) Type of Building : RC Brick, Wooden 133 m × 2.0 m = 266 m²

5) Building conditions : Good, Not so good, Bad (7 years after built 143.6 m²)

6) Layout of Building : Class Room : 3 nos (5.5 m × 6.50 m) × 3
Teacher's Room: 1 no(s) (3.0 m × 6.50 m)
Other : — no(s) (— m × — m)

7) Number of Pupils : 77 nos (Single education, Two shift education)
(Class-1: 90 nos, Class-2: 72 nos, Class-3: 40 nos)
(Class-4: 44 nos, Class-5: 32 nos)

8) Number of Drop-outs : Class-1: nos, Class-2: nos, Class-3: nos
Class-4: nos, Class-5: nos.

9) Reasons of Drop-outs: ① Economic ② ③

10) Countermeasures for 9): ① Making guardians, ② Food for Education ③

11) Number of Teachers : 5 nos understand the necessity of education

12) Ancillary Facility: Well (Yes, No, if yes, Depth of Well: 7.5 m with pump or not)

Present Conditions: Good, Not so bad, Bad,

Toilet (Yes, No, if yes, common or separate)

Present Conditions: Good, Not so bad, Bad,

Electric Facility (Yes, No) Near by 220V.

13) Material of Fixtures: Desk (Wooden), Chair (Wooden), Locker (steel)

14) Number of School Aged Children

within School Attendance Area: 425 nos (Radius: 1.5 km)

15) Maintenance of Building: Place: Roof (Leaking of rain?), Piller (Exfoliate of concrete?), Wall (Color painting?), Window (Window door fitting?).

No need to repair

Method: Name of organization, Organizational unit for maintenance (H. Q. District, Thana or school), Procedure for repair (Requesting, Patrol by engineer=when)

by School Management Committee (SMC)

7. Surrounding Conditions

- 1) Population within a 1.5km Radius: 4,500 nos
- 2) Distance to Neighbouring Primary School : 2.0 km
- 3) Distance to Neighbouring Cyclone shelter : 6.0 km
- 4) Neighbouring Killa : Distance from the School: m
~~Non - Existing~~ Size(Top) : m x m Height: m
 Progres Ratio: %

- 5) Topographic Conditions Nearby :
 (Obstruction for School Attendance or Evacuation at Cyclone Time) Canal 500m away south.
- 6) Normal Flood Level in Site 0.5 m above the existing ground level.
- 7) Neighbouring Warning System : Warning organization: BDRCS
 for Cyclone Measure of warning: Hard-mike
 Kind of signal: None
- 8) Maximum Damage by Cyclone in the Past : Year of Hitting: 1963

Casualties;nos(Why so many died?
 350 persons)
 (How to solve?
 no plan.)
 Surge Height: 3.5 m
 Houses Brokened: 100% nos
 Damage of Crops: 100% ha
 Damage of Livestock: Cow - nos. } 95%
 Goat - nos. }
 Sheep - nos }

8. Item to Be Confirmed in Case of the Project Being Executed

- 1)Necessity for Demolition of : Yes (If yes;Executing Body) (No)
- 2) Construction Body for Temporary School Building during the Construction of New school. : No need.
- 3)Management and Maintenance System for Planned Facilities(Shelter-cum-school) : PMED, SMC
- 4)Neighbouring Inhabitants' Participation in Management and Maintenance for the Planned Facilities : ^{repair} Minor work will be done by local people.

9. Capability of Sub-Contractor near the Site

- 1) ~~Name~~^{No.} of Sub-Contractor 2-3
- 2)No. of Engineers 2/sub-contractor
- 3)Past Experience and Construction Records Road, culvert construction

10. Availability of Procuring Construction Equipment and Materials


- 1) Equipment:)
- 2) Materials:) Not available.

11. Other Remarks

There is one abandoned existing school building at the site. It should be demolished for constructing a new shelter.

Location Map of the Site


Site No.: 17




Sketch of the Site


Site No. : 17

Name of School : South Sakarkhali GPS





View of the School Building



Abandoned Building to be demolished at the School Site



Current Conditions of a Classroom



Auxiliary Facilities of
the School Building

Current Conditions
near the Site
(including topographic
features)



Road Conditions
near the Site

7. Surrounding Conditions

- 1) Population within a 1.5km Radius: 25,000 nos
- 2) Distance to Neighbouring Primary School : 1.0 km
- 3) Distance to Neighbouring Cyclone shelter : 4.5 km
- 4) Neighbouring Killa : Distance from the School: _____ m
 Size(Top) : _____ m x _____ m, Height: _____ m
~~Non-Existing~~ Progress Ratio: _____ %
- 5) Topographic Conditions Nearby : Pond is near to the site, but
 (Obstruction for School Attendance or Evacuation at Cyclone Time) no objection for school attendance, etc.
- 6) Normal Flood Level in Site : 0.6m above the existing ground level.
- 7) Neighbouring Warning System : Warning organization: BDRCS
 for Cyclone Measure of warning: hand-mike
 Kind of signal: Flag; Level 1 or 10.
- 8) Maximum Damage by Cyclone in the Past : Year of Hitting: 1963
 Casualties: nos (Why so many died? 1,000 persons)
 (How to solve? by climbing up trees or roofs)
 Surge Height: 2.0 m
 Houses Brokened: 100% nos
 Damage of Crops: 100% ha
 Damage of Livestock: Cow - nos. } 50%
 Goat - nos. }
 Sheep - nos. }

8. Item to Be Confirmed in Case of the Project Being Executed

- 1) Necessity for Demolition of : Yes (If yes; Executing Body _____). (No)
- 2) Construction Body for Temporary School Building during the Construction of New school. : No need.
- 3) Management and Maintenance System for Planned Facilities (Shelter-cum-school) : PMED, SMC.
- 4) Neighbouring Inhabitants' Participation in Management and Maintenance for the Planned Facilities : No need.

9. Capability of Sub-Contractor near the Site

- 1) ~~Name~~ ^{No.} of Sub-Contractor : 30 nos.
- 2) No. of Engineers : 2-3 nos / sub-contractor
- 3) Past Experience and Construction Records : Building / Bridge / Road construction


10. Availability of Procuring Construction

- Equipment and Materials
- 1) Equipment: Mixer / Vibrator / Truck
 - 2) Materials: Bricks / Local Sand

11. Other Remarks

Location Map of the Site


Site No.: 18



Sketch of the Site

Site No. : 18

Name of School : Kabir Memorial GPS






Overall View of
the School Site



View of the School
Building



Current Conditions
of A Classroom



Auxiliary Facilities of
the School Building

Current Conditions
near the Site
(including topographic
features)



Road Conditions
near the Site

SITE SURVEY CHECK LIST

(Date: 1995/ 3/24)

1. Site No. 19
2. Name of School: West Saherkhali GPS
3. Site Location : District: Chittagong Thana : Mirsharai
 Union : Saherkhali Village: Saherkhali
4. Interviewee : Name : Mr. Shamsuddha Position: Asst. Headmaster
5. Accessibility
 - 1) Nearest Station. Port. Main Road Distance: 6.0 km
 - 2) Road Conditions
 - Kind of Pavement: Earth Gravel, Brick, Asphalt, Concrete.
 - Condition of Pavement: Good, Not so good, Bad
 - Road Width : 2.5 m
 - Passable Vehicle: Motor cycle, Rikisha, Sedan, Jeep, Truck (2.0 ton)
 - Necessity for Repair of Road: Yes No. (only in dry season)
 - Necessity for Repair of Bridges or Culverts: Yes. No
6. Conditions of School
 - 1) Name of Landowner : Government
 - 2) Area of School Site : 3,513.9 m² (including Playground of 602. m²)
 - 3) School Building : 1 no(s) (Floor Area: 18 m x 6.7 m = 120.6 m²)
 - 4) Type of Building : RC, Brick Wooden 13 m x 1.8 m = 23.4 m²
 - 5) Building conditions : Good, Not so good, Bad (5 years after built)
 - 6) Layout of Building : Class Room : 3 nos (5-15 m x 6.7 m) x 3
 Teacher's Room: 1 no(s) (2.5 m x 6.7 m)
 Other : — no(s) (— m x — m)
 - 7) Number of Pupils : 364 nos (Single education, Two shift education)
 (Class-1: 64 nos, Class-2: 75 nos, Class-3: 70 nos)
 (Class-4: 65 nos, Class-5: 72 nos)
 - 8) Number of Drop-outs : Class-1: nos, Class-2: nos, Class-3: nos
 % Class-4: nos, Class-5: nos,
 - 9) Reasons of Drop-outs: ① Economic , ② , ③
 - 10) Countermeasures for 9): ① Meeting with guardians, ② , ③
 - 11) Number of Teachers : 6 nos
 - 12) Ancillary Facility: Well (Yes) No, if yes, Depth of Well: m
 with pump or not)
 Present Conditions: Good, Not so bad, Bad
 Toilet (Yes) No, if yes, common or separate)
 Present Conditions: Good, Not so bad, Bad.
 Electric Facility (Yes, No.) 220V line, within 100m
 - 13) Material of Fixtures: Desk(Steel), Chair(Steel)
 Locker(Steel)
 - 14) Number of School Aged Children
 within School Attendance Area: 525 nos (Radius: 1.5 km)
 - 15) Maintenance of Building: Place: Roof (Leaking of rain?), Piller(Exfoliate
 of concrete?), Wall(Color painting?),
 Window(Window door fitting?),
 Method: Name of organization, Organizational
 unit for maintenance (H.O., District, Education
 Thana or school), Procedure for repair Committee,
 (Requesting, Patrol by engineer=when)
 by School Management Committee(SMC)

7. Surrounding Conditions

- 1) Population within a 1.5km Radius: 9,000 nos.
- 2) Distance to Neighbouring Primary School : 1.0 km
- 3) Distance to Neighbouring Cyclone shelter : 2.0 km
- 4) Neighbouring Killa : Distance from the School: _____ m
 Size(Top) : _____ m x _____ m. Height: _____ m
~~Progres Ratio: _____ %~~
Not - Existing
- 5) Topographic Conditions Nearby :
 (Obstruction for School Attendance or Evacuation at Cyclone Time) *No objection*
- 6) Normal Flood Level in Site *0.5 m above the existing ground level.*
- 7) Neighbouring Warning System : Warning organization: BDRCS
 for Cyclone Measure of warning: *Hand-Mike*
 Kind of signal: *Flag, Level 1 ~ 10.*
- 8) Maximum Damage by Cyclone in the Past : Year of Hitting: 1963
 Casualties; nos (Why so many died?) *2,500 persons*
 (How to solve?) *by climbing up trees or roof.*
 Surge Height: 2.2 m
 Houses Brokened: 100% nos
 Damage of Crops: 100% ha
 Damage of Livestock: Cow -nos. } 95%
 Goat -nos. }
 Sheep -nos. }

8. Item to Be Confirmed in Case of the Project Being Executed

- 1) Necessity for Demolition of : Yes (If yes; Executing Body _____). No
 the Existing School Building
- 2) Construction Body for Temporary School Building during the Construction of New school. : *No need.*
- 3) Management and Maintenance System for Planned Facilities (Shelter-cum-school) : *PMED + ^{SMC} (Local People)*
- 4) Neighbouring Inhabitants' Participation in Management and Maintenance for the Planned Facilities : *Participation in repairing facilities.*

9. Capability of Sub-Contractor near the Site

- 1) Name of Sub-Contractor, *5*
- 2) No. of Engineers *2 or 3 / sub-contractor*
- 3) Past Experience and Construction Records *Culvert, Small Bridge*

10. Availability of Procuring Construction


Equipment and Materials

- 1) Equipment;
- 2) Materials;) *None (to be procured from Mirstarai)*

11. Other Remarks

Location Map of the Site


Site No.: 19



Sketch of the Site

Site No. : 19

Name of School : West Saherkhali GPS





Overall View of
the School Site



Overall View of
the School Building



Current Conditions
of A Classroom



Auxiliary Facilities of
the School Building



Auxiliary facilities
of the School Building



Current Conditions
near the Site
(including topographic
features)

SITE SURVEY CHECK LIST

(Date: 1995/3/24)

1. Site No. 20
2. Name of School: Saherkhali Jamalsafi GPS
3. Site Location : District: Chittagong Thana : Mirsharai
Union : Saherkhali Village: Saherkhali
4. Interviewee : Name : Mr. Md. Abdul Hai Position: Headmaster
5. Accessibility
 - 1) Nearest Station, Port, Main Road: Distance: 7.0 km
 - 2) Road Conditions
 - Kind of Pavement: Earth, Gravel, Brick, Asphalt, Concrete,
 - Condition of Pavement: Good, Not so good, Bad
 - Road Width : 2.5 m
 - Passable Vehicle: Motor cycle, Rikisha, Sedan, Jeep, Truck (≥ ton)
 - Necessity for Repair of Road: Yes No.
 - Necessity for Repair of Bridges or Culverts: Yes, No (only dry season)
6. Conditions of School
 - 1) Name of Landowner : Government
 - 2) Area of School Site : 1,768.3 m² (including Playground of 1172 m²)
 - 3) School Building : / no(s) (Floor Area: 12.14 m × 5.1 m = 61.9 m²)
 - 4) Type of Building : RC, Brick, Wooden
 - 5) Building conditions : Good, Not so good, Bad (13 years after built)
 - 6) Layout of Building : Class Room : / nos (8.14 m × 5.1 m)
Teacher's Room: / no(s) (4. m × 5.1 m)
Other : - no(s) (- m × - m)
 - 7) Number of Pupils : 175 nos (Single education, Two shift education)
(Class-1; 60 nos, Class-2; 50 nos, Class-3; 30 nos)
(Class-4; 19 nos, Class-5; 16 nos)
 - 8) Number of Drop-outs : Class-1; nos, Class-2; nos, Class-3; nos
6% Class-4; nos, Class-5; nos.
 - 9) Reasons of Drop-outs: ① Economic, ②, ③
 - 10) Countermeasures for 9): ① Talking to guardians, ② Food for education, ③
 - 11) Number of Teachers : 4 nos
 - 12) Ancillary Facility: Well (Yes No, if yes, Depth of Well: 10 m
with pump or not)
Present Conditions: Good, Not so bad, Bad, Broken
Toilet (Yes, No if yes, common or separate)
Present Conditions: Good, Not so bad, Bad,
Electric Facility (Yes, No) Power line is installed 2 km away
- 13) Material of Fixtures: Desk(Wooden), Chair(Wooden)
Locker(Wooden)
- 14) Number of School Aged Children
within School Attendance Area: 525 nos (Radius: 10 km)
- 15) Maintenance of Building: Place; Roof(Leaking of rain?), Pillar(Exfoliate of concrete?), Wall(Color painting?),
Window(Window door fitting?), by local people.
Method: Name of organization, Organizational unit for maintenance (H.Q., District, Thana or school), Procedure for repair (Requesting, Patrol by engineer=when)
PHED/CEP District Thana Education Committee

7. Surrounding Conditions

- 1) Population within a 1.5km Radius: 4,000 nos
- 2) Distance to Neighbouring Primary School : 2.0 km
- 3) Distance to Neighbouring Cyclone shelter : 4.0 km
- 4) Neighbouring Killa : Distance from the School: _____ m
 Size(Top) : _____ m x _____ m. Height: _____ m
~~Progress-Ratio: _____ %~~
Non-Existing
- 5) Topographic Conditions Nearby :
 (Obstruction for School Attendance or Evacuation at Cyclone Time) *No objection*
- 6) Normal Flood Level in Site *0.3 m above the existing ground level.*
- 7) Neighbouring Warning System : Warning organization; *BDRCS*
 for Cyclone Measure of warning; *Hand-speaker*
 Kind of signal; *none*
- 8) Maximum Damage by Cyclone in the Past : Year of Hitting: *1963*
 Casualties;nos(Why so many died?
1,200 persons)
 (How to solve?
 _____)

Surge Height: 3.0 m
 Houses Brokened; 100% nos
 Damage of Crops; 100% ha
 Damage of Livestock: Cow nos. }
 Goat nos. } 90%
 Sheep nos. }

8. Item to Be Confirmed in Case of the Project Being Executed

- 1) Necessity for Demolition of : Yes (If yes; Executing Body _____). *(No)*
 the Existing School Building
- 2) Construction Body for Temporary School : *No need.*
 Building during the Construction of New school.
- 3) Management and Maintenance System for : *PMED, SMC*
 Planned Facilities (Shelter-cum-school)
- 4) Neighbouring Inhabitants' Participation : *Local people will try to*
 in Management and Maintenance for the *support the repair of facilities.*
 Planned Facilities

9. Capability of Sub-Contractor near the Site

- 1) Name of Sub-Contractor *4 n 5*
- 2) No. of Engineers *none*
- 3) Past Experience and Construction Records


10. Availability of Procuring Construction Equipment and Materials :

- 1) Equipment:)
- 2) Materials:) *Not available*

11. Other Remarks

Location Map of the Site


Site No.: 20



Sketch of the Site

Site No. : 20

Name of School : Seberkhali Jama/safi
GPS.





Overall View of
the School Site



Current Conditions
of A Classroom



Auxiliary Facilities of
the School Building



Current Conditions
near the Site
(including topographic
features)



Road Conditions
near the Site

SITE SURVEY CHECK LIST

(Date: 1995/ 3/23)

1. Site No. 22
2. Name of School: South-West Char Alekjangar Registered N.G.P.S.
3. Site Location : District: Laxmipur Thana : Ramgati
Union : Char Alekjangar Village: Alekjangar (Asal Para)
4. Interviewee : Name : Mr. Md. Fakhrul Islam Position: Headmaster
5. Accessibility

1) Nearest Station, Port, Main Road: ^{Ramgati Thana H.Q.} Distance: 4.6 km

2) Road Conditions

- Kind of Pavement: Earth, Gravel, Brick, Asphalt, Concrete.
- Condition of Pavement: Good, Not so good, Bad, partially very bad
- Road Width : 2 ~ 2.5 m ^{Earth} ← road gets muddy in rainy season.
- Passable Vehicle: Motor cycle, Rikisha, Sedan, Jeep, Truck (ton) only in dry season.
- Necessity for Repair of Road: Yes, No.
- Necessity for Repair of Bridges or Culverts: Yes, No

6. Conditions of School

- 1) Name of Landowner : School Management Committee
- 2) Area of School Site : 1.632 m² (including Playground of - m²)
- 3) School Building : / no(s) (Floor Area: 9.8 m × 4.2 m = 41.16 m²)
- 4) Type of Building : RC, Brick, Wooden
- 5) Building conditions : Good, Not so good, Bad (8 years after built)
- 6) Layout of Building : Class Room : / nos (9.8 m × 4.2 m)
Teacher's Room: - no(s) (- m × - m)
Other : - no(s) (- m × - m)
- 7) Number of Pupils : 37 nos (Single education, Two shift education)
(Class-1: 17 nos, Class-2: 5 nos, Class-3: 5 nos)
(Class-4: 3 nos, Class-5: 7 nos)
- 8) Number of Drop-outs : Class-1: nos, Class-2: nos, Class-3: nos
16% Class-4: nos, Class-5: nos.
- 9) Reasons of Drop-outs: ① Economic, ② - , ③ -
- 10) Countermeasures for 9): ① Income Increase, ② Food for Education, ③
- 11) Number of Teachers : 4 nos ^{M-3, F-1}
- 12) Ancillary Facility: Well (Yes, No, if yes, Depth of Well: m
with pump or not)

Present Conditions: Good, Not so bad, Bad.

Toilet (Yes, No, if yes, common or separate)

Present Conditions: Good, Not so bad, Bad.

Electric Facility (Yes, No, ^{Power line is installed 1.5 km away.})

- 13) Material of Fixtures: Desk (Wooden), Chair (Wooden)
Locker (-)

14) Number of School Aged Children

within School Attendance Area: 2,000 nos (Radius: 1.5 km)

- 15) Maintenance of Building: Place; Roof (Leaking of rain?), Piller (Exfoliate of concrete?), Wall (Color painting?),
Window (Window door fitting?),

No repair has been done.

Method: Name of organization, Organizational unit for maintenance (H.Q., District, Thana or school), Procedure for repair (Requesting, Patrol by engineer-when)

School Management Committee (SMC)

7. Surrounding Conditions

- 1) Population within a 1.5km Radius: 6,000 nos
- 2) Distance to Neighbouring Primary School : 2.0 km
- 3) Distance to Neighbouring Cyclone shelter : 2.0 km
- 4) Neighbouring Killa : Distance from the School: _____ m
~~Size (Top) : _____ m x _____ m. Height: _____ m~~
None-existing Progress Ratio: %
- 5) Topographic Conditions Nearby :
 (Obstruction for School Attendance or Evacuation at Cyclone Time) *Deep canal along the access road to the site.*
- 6) Normal Flood Level in Site *0.6m above the existing ground level.*
- 7) Neighbouring Warning System : Warning organization: *BARCS*
 for Cyclone Measure of warning: *Hand-mike*
 Kind of signal: *Flag; Level 1-10.*
- 8) Maximum Damage by Cyclone in the Past : Year of Hitting: *1970*
 Casualties; nos (Why so many died?
2,000)
 (How to solve?
by climbing up roof/trees
 Surge Height: *6.0* m
 Houses Brokened; *100%* nos
 Damage of Crops: *100%* ha
 Damage of Livestock: Cow nos. }
 Goat nos. } *100%*
 Sheep nos }

8. Item to Be Confirmed in Case of the Project Being Executed

- 1) Necessity for Demolition of : Yes (If yes: Executing Body _____), No
 the Existing School Building
- 2) Construction Body for Temporary School : *No need.*
 Building during the Construction of New school.
- 3) Management and Maintenance System for : *SMC*
 Planned Facilities (Shelter-cum-school)
- 4) Neighbouring Inhabitants' Participation : *No participation*
 in Management and Maintenance for the Planned Facilities

9. Capability of Sub-Contractor near the Site

- 1) ~~Name~~ ^{No.} of Sub-Contractor) *none.*
- 2) No. of Engineers
- 3) Past Experience and Construction Records

10. Availability of Procuring Construction Equipment and Materials

- 1) Equipment:
- 2) Materials:) *Not available*


11. Other Remarks

Deep canal exists the access road to the site.

Sketch of the Site

Site No. : 22

Name of School : South-West Char
Alekjandar Registered NAPS.





Overall View of
the School Site



Overall View of
the School Building



Current Conditions
of A Classroom



Deep Canal along the
Access Road to the
School Site



Road Conditions
near the Site

SITE SURVEY CHECK LIST

(Date: 1995/ 3 / 23)

1. Site No. 23
2. Name of School: Sabagram GPS.
3. Site Location : District: Laxmipur Thana : Rangati
Union : Char Alekjangar Village: Alekjangar/Sabagram
4. Interviewee : Name : Md. Salehuddin Position: Asst. Teacher
5. Accessibility *Rangati Thana H.Q.*
 - 1) ~~Nearest Station, Port, Main Road:~~ Distance: 0.2 km
 - 2) Road Conditions
 - Kind of Pavement: Earth Gravel, Brick, Asphalt, Concrete,
 - Condition of Pavement: Good, Not so good, Bad
 - Road Width : 2 or 4 m
 - Passable Vehicle: Motor cycle, Rikisha, Sedan, Jeep, Truck (— ton)
 - Necessity for Repair of Road: Yes, No. (*muddy in rainy season*)
 - Necessity for Repair of Bridges or Culverts: Yes, No
6. Conditions of School *Newly proposed site*
 - 1) Name of Landowner : Government
 - 2) Area of School Site : 1,020.5 m² (including Playground of — m²)
 - 3) School Building : 1 no(s) (Floor Area: 15.5 m x 6.38 m = 98.89 m²)
 - 4) Type of Building : RC, Brick, Wooden
 - 5) Building conditions : Good, Not so good, Bad (5 years after built)
 - 6) Layout of Building : Class Room : 4 nos (m x m)
Teacher's Room: ; no(s) (m x m)
Other : — no(s) (m x m)
 - 7) Number of Pupils : 47 nos (Single education, Two shift education)
(Class-1: 120 nos, Class-2: 140 nos, Class-3: 90 nos)
(Class-4: 44 nos, Class-5: 25 nos)
 - 8) Number of Drop-outs : Class-1: nos, Class-2: nos, Class-3: nos
None Class-4: nos, Class-5: nos.
 - 9) Reasons of Drop-outs: ① , ② , ③
 - 10) Countermeasures for 9): ① , ② , ③
 - 11) Number of Teachers : 6 nos *M-4, F-2*
 - 12) Ancillary Facility: Well (Yes, No if yes, Depth of Well: m
with pump or not)
Present Conditions: Good, Not so bad, Bad,
Toilet (Yes, No, if yes, common or separate)
Present Conditions: Good, Not so bad, Bad, out of order
Electric Facility (Yes, No.)
 - 13) Material of Fixtures: Desk (Wooden), Chair (Wooden)
Locker (Steel)
 - 14) Number of School Aged Children
within School Attendance Area: 1500 nos (Radius: 1.5 km)
 - 15) Maintenance of Building: Place: Roof (Leaking of rain?), Piller (Exfoliate
of concrete?), Wall (Color painting?),
by LGED in 1990. Window (Window door fitting?).
Method: Name of organization, Organizational
unit for maintenance *PMED/LGED through Thana
Educational* (H.Q., District, *Education*
Thana or school), Procedure for repair *Committee*
(Requesting, Patrol by engineer=when)
by School Management Committee (SMC)

7. Surrounding Conditions

- 1) Population within a 1.5km Radius: 5,000 nos
- 2) Distance to Neighbouring Primary School : 1.5 km
- 3) Distance to Neighbouring Cyclone shelter : 6.0 km
- 4) Neighbouring Killa : Distance from the School: _____ m
 Size(Top) : _____ m x _____ m, Height: _____ m
~~Progress Ratio: _____ %~~
Now - Existing
- 5) Topographic Conditions Nearby :
 (Obstruction for School Attendance or Evacuation at Cyclone Time) *No objection*
- 6) Normal Flood Level in Site *Same level of the existing ground.*
- 7) Neighbouring Warning System : Warning organization; *BDRCS*
 for Cyclone Measure of warning; *Hand-Mike*
 Kind of signal; *Flag ; Level 12/10.*
- 8) Maximum Damage by Cyclone in the Past : Year of Hitting: *1970*

Casualties; nos (Why so many died?)
700 persons
 (How to solve?)
by evacuating to Thana H.Q. by Government office
 Surge Height: *2.1*
 Houses Broken: *90% nos*
 Damage of Crops: *100% ha*
 Damage of Livestock: Cow nos. *500*
 Goat nos. *700 or 800*
 Sheep nos.

8. Item to Be Confirmed in Case of the Project Being Executed

- 1) Necessity for Demolition of : Yes (If yes; Executing Body _____). *No.*
 the Existing School Building
- 2) Construction Body for Temporary School Building during the Construction of New school. : *No. need.*
- 3) Management and Maintenance System for Planned Facilities (Shelter-cum-school) : *PMED, SMC*
- 4) Neighbouring Inhabitants' Participation in Management and Maintenance for the Planned Facilities : *No. participation*

9. Capability of Sub-Contractor near the Site

- 1) ~~Name~~ ^{No.} of Sub-Contractor : *5* eg. *one sub-contractor consists of*
- 2) No. of Engineers : _____
- 3) Past Experience and Construction Records : *Culvert, small bridge, etc.*

10. Availability of Procuring Construction

Equipment and Materials

- 1) Equipment: _____
- 2) Materials: *) not available* * *Brick is available; but its quality is very low*



11. Other Remarks

2-story dormitory and Thana H.Q. Buildings, which have sufficient sheltering capacity, are located next to the Site.

Sketch of the Site


Site No. : 23

Name of School : Sabagram G.P.S.






Overall View of
The School Site



View of the School
Building



Current Conditions
of A Classroom



Auxiliary Facilities
(toilet) of the School
Building



Thana Office
adjacent to the School
Site



Road Conditions
of A Classroom

SITE SURVEY CHECK LIST

(Date: 1995/3/24)

1. Site No. 25
2. Name of School: Azadnagar GPS.
3. Site Location : District: Laxmipur Thana : Rangati
Union : Char Badam Village: Char Kolokopa
4. Interviewee : Name : Mr. Abdul Mazed Position: Headmaster
5. Accessibility Rangati Thana H.Q.
1) Nearest Station, Port, Main Road: Distance: 12.5 km
2) Road Conditions
- Kind of Pavement: Earth, Gravel, Brick, Asphalt, Concrete,
- Condition of Pavement: Good, Not so good, Bad
- Road Width : 4.0 m Road gets muddy in rainy season.
- Passable Vehicle: Motor cycle, Rikisha, Sedan, Jeep, Truck (4 ton)
- Necessity for Repair of Road: Yes, No, (only in dry season)
- Necessity for Repair of Bridges or Culverts: Yes, No
6. Conditions of School
1) Name of Landowner : Government
2) Area of School Site : 5,068 m² (including Playground of - m²)
3) School Building : 2 no(s) (Floor Area: 12.7 m \times 1.85 m = 148.79 m²)
4) Type of Building : RC, Brick, Wooden
5) Building conditions : Good, Not so good, Bad (15 years after built)
6) Layout of Building : Class Room : 3 nos (- m \times - m)
Teacher's Room: 1 no(s) (- m \times - m)
Other : - no(s) (- m \times - m)
7) Number of Pupils : 460 nos (Single education, Two shift education)
(Class-1; 90 nos, Class-2; 100 nos, Class-3; 70 nos)
(Class-4; 68 nos, Class-5; 32 nos)
8) Number of Drop-outs : Class-1: none nos, Class-2: none nos, Class-3: none nos
Class-4: none nos, Class-5: none nos.
9) Reasons of Drop-outs: ①, ②, ③
10) Countermeasures for 9): ①, ②, ③
11) Number of Teachers : 2 nos
12) Ancillary Facility: Well (Yes, No, if yes, Depth of Well: 10 m
with pump or not)
Present Conditions; Good, Not so bad, Bad, out of order
Toilet (Yes, No, if yes, common or separate)
Present Conditions; Good, Not so bad, Bad,
Electric Facility (Yes, No) Power line is installed 3km away
13) Material of Fixtures: Desk(Steel), Chair(Steel)
Locker(Steel)
14) Number of School Aged Children
within School Attendance Area: 800 nos (Radius: 1.5 km)
15) Maintenance of Building: Place: Roof(Leaking of rain?), Piller(Exfoliate
of concrete?), Wall(Color painting?),
No maintenance
Window(Window door fitting?).
Method: Name of organization, Organizational
unit for maintenance PMED/ED through Thana
Thana or school), Procedure for repair Education Committee
(Requesting, Patrol by engineer=when)
School Management Committee (SMC)

7. Surrounding Conditions

- 1) Population within a 1.5km Radius: 10,000 nos
- 2) Distance to Neighbouring Primary School : 3 km
- 3) Distance to Neighbouring Cyclone shelter : in the same premises
- 4) Neighbouring Killa : Distance from the School; _____ m
 Size(Top) : _____ m x _____ m. Height: _____ m
 Progres Ratio: _____ %
None
- 5) Topographic Conditions Nearby :
 (Obstruction for School Attendance or Evacuation at Cyclone Time) *No objection*
- 6) Normal Flood Level in Site *the existing ground level*
- 7) Neighbouring Warning System : Warning organization: *None*
 Measure of warning: _____
 Kind of signal: _____
- 8) Maximum Damage by Cyclone in the Past : Year of Hitting: 1970
 Casualities:nos(Why so many died?)
 200)
 (How to solve?)
 _____)

Surge Height: *0* m
 Houses Brokened: 100% nos
 Damage of Crops: 100% ha
 Damage of Livestock: Cow nos. }
 Goat nos. } 100%
 Sheep nos. }

8. Item to Be Confirmed in Case of the Project Being Executed

- 1)Necessity for Demolition of : Yes (If yes;Executing Body _____) No. the Existing School Building
- 2)Construction Body for Temporary School : _____ Building during the Construction of New school.
- 3)Management and Maintenance System for : _____ Planned Facilities (Shelter-cum-school)
- 4)Neighbouring Inhabitants' Participation : _____ in Management and Maintenance for the Planned Facilities

9. Capability of Sub-Contractor near the Site

- 1) ~~Name~~ ^{No.} of Sub-Contractor
- 2) No. of Engineers
- 3) Past Experience and Construction Records


10. Availability of Procuring Construction :

- Equipment and Materials
- 1) Equipment;
- 2) Materials;


11. Other Remarks

A shelter is now being constructed within the Site.

Location Map of the Site




Site No.: 25



Sketch of the Site


Site No. : 25

Name of School : Azadnagar GPS






Overall View of
the School Site



Overall View of
the School Building



Current Conditions
of A Classroom