5. Cost Estimation Borne by the Receipient Country

and VND		Grand total	QXA	2, 402	2 683	12 353	277.8	3,869	4, 365	7.717	00% F	2,030	707	0 796	9, 150	21, 553	2, 479	11,841	14, 701			11 846	C . C . S	0,040	2,514	4,114	138, 177
Unit: Thousand VND	, T . 1	Total Gr	O.Y.	2 400	2 683	2,002	2000 0	869	783	677	008	0,030	2,707	1, 477		1, 489	2, 479	7, 741	6.541	2 477	1 396	182	400	0, 545	1,220		57. 284
	Other *	Quantity	XOX	0 630	0.100	1, 036, U	7 240 2	1 281 8	270 5	307 6	0.577	2,011.2	7, 100 0	7.770		620.5	885.5	2, 764, 7	0 336 0	1 448 6	. 1	-1	6.132	2, 726. 2	554. 7		
		Unit cost	WOS/UNA	0 0	0 0	2.0	- 1	2.8		0 0	7.7	7.7	7.7		2.4	2.4	2.8	2.8			1 2		-1	2.4	2.2	2.2	
		Total		7,										- 1	3211.0			1901 2	7		_ _					4114.0	9226. 2
	Farm	Quantity	, MOS	200											321. 1			3 3 5 5	יוססי					2	2	7 1111.9	
٠ .	,	Unit cost Quantity	אוסט/ כבער	VAN ZAM	16.6	12.5	12.0	16.6	16.6	12.0	12.0	12.0	10.5	10.0	10.0	14.0			3	, ,	0.0		3.	က်	က်	60	
Acquisition		70+21	:	VNU	_		11,549			ကြ	7,040				6,515	<u> </u>	ļ	-	\\ \frac{1}{2} \cdot	8, 160		-	1 11,265		0 1,294		71,667
Land Ac	Doddy.	Thom:		NO.	2	7	0 721.8	2	2	0 223.9	0 440.0	0	-	0	0 542.9	9 11 045 0	1 -	7	2 114.	8 832.7	∞	65	3 1, 788.	5	5 -199.	 	N · ·
		1.0		VOS/OVV	19.	18.	16.	19.	19.	16.	16.	16.	12.	12.	12.			73.	19.	6	6	_	6.	9	9	50	
		£	Name of bridge bill costanding		Duc Khe	Chuoc	Dong Dinh	Tu O	Hau	Ben The	Lac	Vu Ban	Ky Phu	Luong Nha	Suons	Vor Tho	011	Hoann I ruc	Dong Quach	Nao Hoa	Quang	Pho Tra Linh	Trong Panh	Knoi Nieng	Kioi Kiens	Va Sano-2	P. CHARLES DAY
-					Tav		Ha Bac	 50		Hoa Binh			Sac Thai		_	4.50	ייווען סיוועו		Thai Binh	Lang Song	Tuyen Qung	- :		- 6		104 (40)	_
			Province		Ha		Ha	Hai		Hoa	 -		Sac	V.12			N I II		Thai	Lang	Tuye	Cao	S	7.2	110		רמו
		Bridge	ġ			3	r.	9	00	თ	=	12	13	V.	2 0	ָבן י	7	18	50	22	23	27	\ 		3 6	7 6	10

Note:

* : Forestry, Wasteland, Vacant-land etc. Source of unit cost: PMU-18

A2-1 Bridge Construction (3/3) Cost Estimation Borne By Viet Nam

Unit: Thousand VVD	÷ .	Grand total	CNA	50.920	10,800	35, 200	32, 680	40, 280	41, 600	17, 280	41.600	10.320	24.960	008 61	48.640	55.860	72,960	33, 500	23, 760	24, 640	26,000	6.880	26,000	17, 600	661, 280	
i i		Lease Period	(Year)	2	2	3	2	2	2	-	2		2	2	2	က	3	2	2	2	2	2	2	2		
		Total	QNA	0	5, 400	0	0	0	0	0	0	0	0	0	0	.0	0	0	0	0	0	3,440	0	0	8.840	
	Other *	uantity	Ē	0	5,400	0	0	0	0	0	0	0	0	0	ō	0	0	0	0	0	0	4,300	0	0	:	
	0t)	Unit cost Quantity	VND/m · year	1 0	1.0	0.8	1.0	1,0	1.0	1.0	1.0	0.8	8.0	0.8	1.2	1.2	1.2	8.0	1.0	1.0	8 0	0.8	0.8	0.8		
		Total	V.D	0	0	0	0	0	0	0	0	0	0	9,900	0	0	0	0	11.880	0	0	0	0	8,800	30,580	
	Farm	Quantity	Έ	0	0	0	0	0	0	0	0	0	0	4,500	0	0	0	0	5, 400	0	0	0	0	4.400	 -	
for Construction Yard		Unit cost (VND/m' · year	3.0	3.0	3.0	2.8	2.8	2.5	2.5	2.5	2.2	2.2	2.2	3.0	3.0	3.0	2.0	2.2	2.5	2.0	2.2	2.2	2.0		
or constr		Total	GNA	25, 460	0	17, 600	16.340	20, 140	20,800	17, 280	20,800	10,320	12, 480	0	24, 320	18, 620	24, 320	16,750	0	12, 320	13,000	0	13,000	0	283, 550	
껡	Packy	Quantity	. E	6.700	0	5,500	4, 300	5,300	6,500	5.400	6.500	4, 300	5, 200	0	8.400	4.900	6,400	8,700	0	4, 400	5, 200	0	5, 200	0		
rease ranc co	23.	Unit cost (VND/m' · year	3.8	3.8	3.2	က တ	တ	3.2	3.2	3.2	2.4	2.4	2.4	3.8	3.0	: 60 (0)	2.5	3.0	2.8	2.5	2.5	2.5	2.5		
	. J	Province Name of Bridge		Duc Khe	Chuoc	Dong Dinh	Tu 0	Hau	Ben The	Ľac	Vu San	Ky Phu	Luong Wha	Suons	Yen Tho	Hoanh Truc	Dong Quach	Nao Boa	Quang	Pho Tra Linh	Trong Panh	Kuoi Nieng	Kuoi Kieng	Va Sang-2		
		Province \		Ha Tay		Ha Bac	Hai Bung	}	Hoa Binh	·	_	Sac Thai	Vinh Phu		Ninh Binh		Thai Binhi	Lang Song	Tuyen Qung	Cao Bang	Son La	Ha Giang	:	Lai Chou	Total	
	Bridge	No.			3	ĵ.	9		63		12	13	15	1.6	17	- S	8	22	23	12	31	33	34	37,		

te:

* : Forestry, Wasteland, Vacant land etc.

Source of unit cost: PMU-i8 ...

A2-1 Bridge Construction (2/3) Cost Estimation Borne by Viet Nam

		Сощреп	ensation of removal	removal				0.11 6 7	and proceeding to the
Bridge	: ;		Pe	Permanent House	0)	Ter	Temporary House	9	
)	Province	Name of Bridge	Unit cost	Quantity	Total	Unit cost	Quantity	Total	Grand total
			WOS/GNA	SOM	QNA	WDS/GNA	SQM	QNA	QNA
	Ha Tav	Duc Khe	559	506.9	283, 357	292			283, 357
		Chuoc	559			292			
ی اد	Ha Bac	Dong Dinh	566	120.9	68, 429	296			68, 429
ی		Tu 0	689	160.9	110,860	336			110,860
·α	C	Han	548	503.6	275, 972	302	37.0	11, 174	287, 146
o	Hos Binh	Ben The	404			228	26.4	6,019	6,019
, -		36	351			220			
12		Vr. Ban	420			245	105, 6	25, 872	25, 872
2 00	Rac Thai	Kv Phu	526	109.7	57, 702	281			57, 702
Š Č	Vinh Phu	Luong Nha	477	199.5	95, 161	265			95, 161
16		Suong	388			216			-
2-	Nich Rich	Ven Tho	498	68.7	34,212	234			34, 212
۲		Hoanh True	457			258	187.5	48, 375	48, 375
2	That Rinh	Dong Ousch	520	186.8	97, 136	279	101.0	28, 179	125, 315
3 %	Sac Sac I	Nac Hoa	477	15.4	7,345	265	60.1	15,926	
23 66	Trivon Oring	Onano	526			281	147.3	41, 391	41,391
2.2	Cao Pang	Pho Tra Linh	640	174.8	111,872	310	20.0	6, 200	118,072
2 ~	Son La	Trong Panh	310			218	29.6	6, 452	6, 452
33	Ha Giano	Knot Nienz	477			265	20.3	5, 379	5, 379
34	0	Kuoi Kieng	477	-		265	33, 7	8, 930	8, 930
37	Lai Chou	Na Sang-2	310			218			
	Total				1, 142, 046	:		203, 897	1,345,943

Note: Source of unit cost : PMU-18

A2-2 Steel Girder Supply (1/2)

5	מספר מפרומת ססותב חל זובר ועשת	ומון שמו ווהן	א זבר ואמם								Unit : B	Billion VND
Bridge	Province	Province Name of	3	Cost of Subs	Substructure(A	,	Cost	of Suppe	Cost of Supperstructure(B)		Cost of	Total
No.		Bridge	Abutment	Pier	Foundation Sub-Total	Sub-Total	Erection	Slab	Accesories	Accesories Sub-Total Ap.	Road (C)	(A+B+C)
T.	На Вас	Ha Bac Dong Vuong	0.342	0.110	0.143	0, 595	0.324	1.029	0.195	1.548	0.184	2, 327
01	Hoa Binh	Tinh	0.240	1	0.070	0.310	0.170	0.540	0.100	0.810	0.100	1, 220
21	Lang Son	Dong Mo	0.630		0.200	0.830	0.450	1.440	0.270	2,160	0, 260	3,250
25	Yen Bai	Lanh	0.251		0.080	0.331	0.170	0.550	0.120	0,840	0.120	1.291
58		Vai	0.210		0.071	0.281	0.160	0.490	0.090	0.740	0.090	1, 111
29	Son La	Ban Ai	0.110		0.032	0.142	0.081	0.250	0.050	0.381	0.040	0.563
30		Ban Hinh	0, 133		0.040	0.173	0.000	0.290	0.050	0.430	0.050	0,653
35	Lao Cai	Lao Cai Ban Vuoc	0.710	0.125	0.115	0,950	0.373	0.429	0.981	1. 783	0.126	2.859
	Total		2. 626	0.235	0.751	3.612	1,818	5.018	1.856	8.692	0.970	13.274
٠												

,,

· Construction Cost of Bridge : 12,304 Billion VND

· Construction Cost of Approach Road : 0.970 Billion VND

- Sourse of Cost : PMU-18

A2-2 Steel Girder Supply (2/2) Cost Estimation Borde by Viet Nam

	Total	Million VND	100	80	0	50	09	0	0	0	290
Land Aquisition and Compensation	Name of Bridge	, , , , , , , , , , , , , , , , , , ,	Dong Vuong	Tinh	Dong Mo	Lanh	Vai	Ban Ai	Ban Hinh	Ban Vuoc	
Land Aquisition a	Province		Ha Bac	Hoa Binh	Lang Son	Yen Bai		Son La		Lao Cai	Total
	Bridge No.)	4	10	21	25	26	29	30	35	

Notes: Source of Cost; PMU-18



6. Request Letter

'BỘ GIAO THỐNG VẬN TẢI CỘNG HÒA XÃ HỘI CHỦ NGHIA VIỆT NAM MINISTRY OF TRANSPORT AND COMMUNICATIONS OF SRV

80 Tran Hung Dao Hanoi Tel: 252 079 Fax: 84 4 267 291

Telex: 412242 BGTVT VT

To: Mr. Kazuchica Sato

Team Leader

Basic Design Study Team

JICA

Subject: List of Bridges in the Project for Reconstruction of Bridges in the Northern Districts.

Dear Mr. Sato,

We would like to express our thank to you and to all members of the JICA Study Team for the support and assistance in the preparation for the Project.

Regarding the list of bridges to be included into the Project, we would like to make some proposals as follows:

1. Replacement of two bridges Pa Mo (No.37) and Nam Bun (No.38) by two other bridges Na Sang and Nam Thanh by name (in the same Lai Chau Province).

As you know bridges at Pa Mo and Nam Bun are located rather far from the existing road network which will bring a lot of difficulties when we come to the stage of construction.

These two other proposed bridges (Na Sang and Nam Thanh) are in the priority list for investment of the Province. We would like to provide you with some more information:

al Na Sang Bridge:

Located at Km16 on the Pom Lot - Sulu Road, 38 km from Dien Bien Town. It is on the way leading to ten mountainous populated communes, Dien Bien District (area of 121,800 ha, population of 35,000 people). Production here is mainly from agriculture and forestry. Average traffic volume is between 15 and 50 vehicles/day. Estimated length of the Bridge is 80 m. Now there is no bridge at all.

- b/ Nam Thanh Bridge: Located on the District road Dien Bien, 12 km from Dien Bien Town. It is on the way leading to 3 mountainous communes, Dien Bien District (area of 50,000 ha, population of 12,000 people). Production here is mainly from agriculture and forestry. Average traffic volume is about 12 vehicles/day. Estimated length of the bridge is 60 m. There exists now an old suspended bridge (built in 1968). It needs to be urgently replaced.
- 2. Thong Nhat Bridge (No.19) Ninh Binh Province
 This Bridge is very important for the socio-economic development in rural and
 coastal area of Ninh Binh Province. It is on the way leading to a riverport,
 providing good condition for combined transports between road and inlandwaterway. If it will be constructed; it would bring benefits to about 50,000 people
 living along.


Because of above mentioned reasons we propose that Thong Nhat Bridge shall be kept in the list of bridges with the category 2 (provision of steel girder).

We hope that our proposal will be accepted. Thank you once again.

Yours Sincerely,


Hanoi, 23 rd, August 1995

TRAN DOAN THO
Deputy Director General
Planning & Investment Department
Ministry of Transport





7. Overview of Bridge Site Survey Results


Br. No.	Bridge Name	Province	County	Village	Village Population	Road Jurisdiction	Area Land Use	Main Products	Purpose of Bridge Construction	Remarks
1	Duc Khe	На Тау	l ·	Huong Son			Agriculture/Tourisin	Agricultural	Improved welfare, Economic advancement	Access Road to famous temple; traffic increases during lunar New Year
2	Chua Ngoi		Ha Dong	(Ha Dong)	-	County Road	Urban	Agricultural	Improved welfare, Economic advancement	
4 .	Chuoc		Ba Vi	Ba Trai		County Road	Agriculture	Agricultural		Bamboo bridge for pedestrians, breyeles, motorcycles (privately operated for toll)
4	Dong Vuong	Ha Bac	Yen The	Dong Vuong	30,000	County Road	Agriculture	Agricultural		Bamboo bridge and small ferry for pedestrians, bicycles, motorcycles (privately operated for toll)
5	Dong Dinh		Luc Nam	Luc Son/Binh Son	17,200	County Road	Agriculture	Agricultural	Improved welfare, Economic advancement	i ·
6	Tu O	Hai Hung	Ninh Thank	Tan Trao	8,000	Provincial Road	Agriculture	Agricultural	Improved welfare, Economic advancement	
7	Do Day		Tu Loc	Le Loi	9,800	Provincial Road	Agriculture	Agricultural		Pontoon bridge for pedestrians, bicycles, motorcycle
8	Hau		Van Giang	Trung Hoa	10,000	Provincial Road	Agriculture	Agricultural	Improved welfare, Economic advancement	
9	Ben The	Hoa Binh	Tan Lac	Quy My	2,000	Provincial Road	Agriculture	Agricultural		Temporary wooden bridge for pedestrians, bicycles, motorcycle
	Tinh		Da Bac	Tu Ly	10,000	County Road	Agriculture	Agricultural	Improved welfare, Economic advancement	•
11	Lac		Mai Chau	Chieng Chau	3,200	County Road	Agriculture	Agricultural	Improved welfare, Economic advancement	· · · · · · · · · · · · · · · · · · ·
12	Vu Ban		Lac Son	Vu Ban	4,000	Provincial Road	Agriculture/Village	Agricultural	1	Deteriorated suspension bridge for pedestrians, bicycles, motorcycle. Automobile use submorged bridge.
13	Ky Phu	Bac Thai	Dai Tu	Ky Phu	27,000	County Road	Agriculture	Agricultural	3	Bridge destroyed: temporary bridge for pedestrians, bicycles, motorcycle. Market held in vicinity
14	Phu Son 4		Phu Luong	Son Cam		County Road	Agriculture	Agricultural	Improved welfare, Economic advancement	l
	~ !	Vinh Phu	Thanh Son	Luong Nha	3,842	County Road	Agriculture	Agricultural		Bridge ruined in 1995 flood; previously used by 3800 villagers.
	Suong		Song Thao	Huong Lung	14,900	Provincial Road	Agriculture	Agricultural		Bamboo bridge for pedestrians, bicycles, motorcycle; school in vicinity.
	i i	Ninh Binh	Yen Mo	Yen Hoa	7,158	County Road	Agriculture	Agricultural		Deteriorated concrete bridge crossable by pedestrians, bicycles, motorcycle
	Hoanh Truc		Kim Son	Van Hai	6,200	County Road	Agriculture	Agricultural		Bamboo bridge for pedestrians, bicycles, motorcycles.
	Thong Nhat		Kim Son	Phat Diem	5,000	County Road	Urban	Agricultural	Improved welfare, Economic advancement	
	Dong Quach	Thai Binh	Tien Hai	Tay Phong	104,000	County Road	Agriculture	Agricultural	Improved welfare. Economic advancement	
	Dong Mo	Lang Son	Chi Lang	Dong Mo	5,000	Provincial Road	Agriculture/Village	Agricultural	Improved welfare, Economic advancement	la companya di mangantan di mang
	Nao Hoa		_	Son Ha/Ho Son	8,500	Provincial Road	Agriculture	Agricultural	Improved welfare, Economic advancement	Manpowered ferry (vehicles up to 13 tons)
			1	Xuan Quang	29,747	County Road	Agriculture	Agricultural	Improved welfare. Economic advancement	Ferry for small vehicles
	Yen Hoa		Na Hang	Yen Hoa	11,363	County Road	Agriculture	Agricultural	Improved welfare, Economic advancement	No access road; access in rainy season difficult (approx. 40km)
	i	Yen Bai	Luc Yen	Lien Do	5,000	County Road	Agriculture	Agricultural	Improved welfare, Economic advancement	Automobile crossing in dry season only.
	Vai		Van Yen	Dong Cuong	7,000	Provincial Road	Agriculture	Agricultural	Improved welfare, Economic advancement	Automobile crossing in dry season only.
	Pho Tra Linh		Tra Linh	Hung Quoc	- '	County Road	Agriculture/Village	Agricultural	Improved welfare, Economic advancement	Deteriorated bridge for pedestrians, bicycles, motorcycles.
	Mo Sat			Dan Chu	-	Provincial Road	Agriculture	Agricultural	Improved welfare. Economic advancement	Manpowered ferry (rainy season only)
	. 1	Son La		Chieng Xam	-	Provincial Road	Agriculture	Agricultural	Improved welfare, Economic advancement	Deteriorated bridge, 8-ton limit
	Ban Hinh		Thuan Chau	_	•	Provincial Road	Agriculture	Agricultural	Improved welfare, Economic advancement	Small vehicles crossable; subgrade deteriorated
	Tong Panh			Chieng An	-	County Road	Agriculture	Agricultural	Improved welfare, Economic advancement	Destroyed by flood: temporary Bridge for pedestrians, bicycles, motorcycles.
				Bang Hanh	t l	County Road	Agriculture	Agricultural	Improved welfare, Economic advancement	Extremely poor access: construction difficult
	Khuoi Nieng		Bac Quang			County Road	Agriculture	Agricultural	Improved welfare. Economic advancement	Submerged bridge passable only during dry season.
	Khuoi Kieng		Bac Quang	l ` . **		County Road	Agriculture	Agricultural	Improved welfare, Economic advancement	Bamboo raft crossing : automobile crossable only in dry season
		7		Ban Vuoc		County Road	Agriculture	Agricultural	Improved welfare. Economic advancement	Suspension bridge for pedestrians, bicycles, motorcycles: Automobile crossable only in dry season.
	Khe Chan			Son Thuy	6,570	County Road	-	Agricultural	Improved welfare, Economic advancement	Manpowered ferry
		Lai Chau	Muong Te		-	Provincial Road	_	Agricultural	Improved welfare, Economic advancement	Road flooded; unsurveyable due to landslide
	Nam Bun		Muong Te		-	Provincial Road		Agricultural	Improved welfare, Economic advancement	Rood flooded ; unsurveyable due to landslide
	Na Sang - 2		Dien Bien				, '		Improved welfare, Economic advancement	Former bridge carried away by flood; automobiles crossable in low water, pedestrians use raft.
. 8	Nam Thanh		Dien Bien	Noang Luong	4,839	County Road	Agriculture/Porestry	Produce/Lumber	Improved welfare, Economic advancement	Suspension bridge passable by small vehicles; no major problems




No. 1 DUC KHE BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Present Bridge Condition

Ha Tay Province My Duc District Huong Son County Super Structure: Temporary Pontoon Bridge & Steel Plate

Sub Structure

Bridge Flow Out 71.0 m

Bridge Length Width of Bridge

Main Traffic

Pedestrians, Bicycle, Motorbike, Light

Vehicle

Access Road : Good (No Pavement)

Other Information

Access road is in good condition.

River width is 70 m to 80 m therefore 300 ton class ships are navigable.

Currently a temporary pontoon bridge is used, therefore only pedestrians

can pass over the bridge.


This temporary pontoon bridge has been in use since 1970.


No problem in ship navigation to bridge site. Floating crane would be useful for construction of bridge.

Depth of water is around 3 m and velocity of flow is around 0.5 m/sec. High water level is 1.0 m from current water level.


Coarse and fine aggregates are carried by dump truck from Hoa, Vinh Province.

No. 3 CHUOC BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Present Bridge Condition

Ha Tay Province Ba Vi District Can Linh County Super Structure : Pedestrian Bamboo Bridge (Private

Enterprise) Temporary Bamboo Bridge 50.0 m

Sub Structure : Bridge Length : Width of Bridge : Main Traffic :

2.0 m Bicycle, Motorbike only Non-Paved Road

Access Road

- Bridge site is tocated 50 km from Ha Noi. This bridge is a pedestrian
- Bridge site is located 50 km from tra two. This ortuge is a processimal bamboo bridge.


 This bridge is located in 1 km downstream from Suoi Hai Dam. (It is necessary to make arrangements before construction).

 Access road is in good condition. The nature of the soil in the area is mixed cobble stone. There is no hindrance for construction.


 Coarse and line aggregates are carried from Chuong My (about 70 km).

No. 4 DONG VUONG BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Present Bridge Condition

Ha Bac Province Yen The District Dong Vuong County Super Structure : Temporary Bamboo Bridge (Dry Season) Perry Boal (Rainy Season)

Sub Structure Bridge Length Width of Bridge

River Width 30 m

Main Traffic Access Road

Bicycle, Motorbike, Pedestrians Good (No Pavement)

Other Information

Three hours by car from Ha Noi to bridge site.


The Vehicle impossible pass through on the bridge during dry season cause by brook (L=20 m) before 500 m from proposed bridge point.


Local government had bridge plan and started construction, therefore only right bank abutment was constructed. Construction was suspended due to financial difficulties.


Pedestrians use bamboo bridge as detour road during dry season Ferry boat used during rainy season.
No problem for temporary yard. The nature of the soil is terrace deposit and in good condition (gravelly soil).
Existing road height is around 10 m from river bed.

No. 5 DONG DINH BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Present Bridge Condition

Ha Bac Province Luc Nam District Luc Son/Binh Son

Country Super Structure

Sub Structure

River Width 60 m

Bridge Length Width of Bridge Main Traffic


People, Motorbike, Light Vehicle Poor (No Pavement)


Access Road


- About two hours from Bac Giang to the bridge site.
 On the way Luc Nam river is crossed by ferry boat.
 On the way there are around 2 km of poor road. Difficulty in vehicle irrespective of season.
 There is no bridge on site


- There is no bridge on site
 Vehicles possible across the river bed only in dry season.
 People cross a weir upstream in rainy season. Closed to all traffic during flood season. Bridge site is located in mountain valley.
 River bed is saindy gravel (alluvium).
 Site area is of hard terrace deposit.
 No problem for temporary yard.

NO. 6 TU O BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Present Bridge Condition

P: Hai Hung D: Ninh Thanh C: Tan Trao

Super Structure : Destroyed Sub Structure : -

Bridge Length Width of Bridge Main Traffic

: Pedestrians, Bicycle, Motorbike : Gravel Road (W = 3 m)

Access Road

Other Information

Ferry is available in place of bridge crossing.

Access road to the site is in bad conditin, in particular after rain fall.

During the dry season, truck (max. 5 ton) access is possible to the site.

Equipment and materials for bridge construction can be transported by canal.


Boat with weight of 100 ton can cruise the river.


Aggregate and sand for concrete are available from Kin Mon and Chin Ling districts, respectively.

NO. 8 HAU BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Present Bridge Condition

P: Hai Hung D: Van Giang C: Trung Hoa Super Structure : -Sub Structure : -Bridge Length Width of Bridge

Main Traffic Access Road : Pedestrians, Bicycle : Dirt Road (W = 5 m)

- Local residents have a ferry service.

 The width of river is about 60 m.

 Boat with weight up to 100 ton emises the river.


 Access road to bridge site is in bad condition, only land cruiser can reach the site by land (12 km from My Van).


 Local government has already studied about the feasibility of bridge construction (bridge length = 71 m).


 Access road has an improvement plan starting at the end of 1995.

NO. 9 BEN THE BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Present Bridge Condition

P: Hoa Binh D: Tan Lac C: Phong Phu Super Structure : -Sub Structure : -

Bridge Length Width of Bridge

Main Traffic Access Road : Pedestrians, Bicycle, Motorbike : Gravel Road


- Temporary bridge is for pedestrians, bicycle and Motorbike, automobiles cross the river bed only in dry season.


 Rocks are exposed on river bed. Spread foundation can be applied.


 District road 12 C will be improved from 1996 to 1998.

NO. 10 TINH BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Present Bridge Condition

P: Hoa Binh D: Da Bac C: Tu Ly Super Structure : -Sub Structure : -

Bridge Length : Width of Bridge :

Pedestrians, Bicycle, Motorbike Gravel Road (W = 4.5 m) Main Traffic Access Road

- When water level is high, most traffic makes a detour at 3 km upstream. The traffic is open to pedestrians and to heavy vehicles at present, in the dry season.


 Traffic to three communities is blocked by the river.


 Rocks are exposed on river bed. Spread foundation is likely to be applicable.

NO. 11 LAC BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Present Bridge Condition


P: Hoa Binh D: Lac Son C: Tong Dau Super Structure : Wooden Bridge Sub Structure : Stone Masonry


Bridge Length : Width of Bridge : Main Traffic : Access Road : 23.5 m 1.5 m


Pedestrians, Bicycle Dirt Road


- A minority community is located along the access road.
 The river bends at the bridge site.
 Sub-soil is likely to be clay sediment.
 Access road will be improved soon after completion of a proposed bridge.

NO. 12 VU BAN BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Present Bridge Condition

P: Hoa Binh D: Lac Son C: Lien Vu Super Structure : Steel Suspension Bridge Sub Structure : Stone Masonry

Bridge Length

Width of Bridge

104 m

Main Traffic

Access Road

2.7 m Pedestrians, bicycle, Motorbike Paved with Macadam (Minh Binh Side) Gravel Road (Rt. 6 side)

Other Information

27 km from the junction with Rt. 27.

New bridge is proposed upstream of existing bridge.

New bridge requires approach roads with the total length of 230 m.


Existing bridge is a suspension bridge built at approximately 20 m above the surface of the river.


At present, passage is only open to Motorbike riders and pedestrians.


Construction material, such as crushed stones and sand can be procured within a range of 2 km.


Depth of cover soil is expected to be less than a few meters. Spread foundation is applicable.

NO. 13 KY PHU BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Present Bridge Condition

Bac Thai Province Dal Tu District Ky Phu County Super Structure: Half Damaged Temporary Wooden

Bridge Stone Masonry 26.5 m Sub Structure

Bridge Length : 26.5 n Width of Bridge : 1.5 m Main Traffic : Pedest

Access Road

: Pedestrians, Bicycle : 5 m Width Road (No Pavement)

- Around 8 km from Dai Tu to the bridge site, via Song Doung and Dai Tu. No problem for access road.

 Concrete bridge was destroyed due to scouring.

 Only pedestrians and motorbikes can cross the bamboo bridge.

 Vehicles cross the river bed around 1 km downstream.

 A market is held 5 days a week.


 Site area is a farming village.


 River bed is sandy soit mixed with cobble stone.

NO. 15 LUONG NHA BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Present Bridge Condition

Vinh Phu Province Thanh Son District Luong Nha/fu Vu

County
Super Structure: Plate Girder (Concrete Slab)
Sub Structure: Pilebent (H Steel Girder)
Bridge Length: 41.5 in (70 in When Log Bridge is Included)

Width of Bridge:

Main Traffic

Pedestrians, Bicycle, Light Vehicle Good (No Pavement)

Access Road

Other Information

4 hours via Viet Thi from Ha Noi to bridge site.

4 hours via Viet Thi from Ha Noi to bridge site.
Access road to the site is one lane and unpaved road.
Substructure of existing bridge has bad damage and Log Bridge is connected to both sides of river, therefore only pedestrians and motorbikes can pass over the bridge. Site is located along DA river.
DA river is tributary of Red river therefore equipment and materials for bridge will be transported by boat.
The nature of the soil is deposit from DA river (clay soil).
High water level is near deck slab during flood season.
Difference of water levels in flood season and in dry season is abou 5 m.

Difference of water levels in flood season and in dry season is abou 5 m.


Superstructure was washed out by flood in August.

NO. 16 SUONG BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Present Bridge Condition

Vinh Phu Province Songu Thao District Puong Lung County Super Structure: Temporary Bamboo Bridge

Sub Structure

42.5 m

Bridge Length Width of Bridge

1.5 m

Pedestrians, Bicycle Good (No Pavement) Main Traffic Access Road

Other Information

Access road to the site is in poor condition during rainy season. However, 10 ton trucks are accessible to the site.

Former bridge was destroyed by bombing of U.S. military.

Existing bridge is made from bamboo therefore only pedestrians and motorcycle can pass over the bridge. However deposit bridge is closed during rainy season.

The nature of the soil is clay soil deposit.


Rocks are exposed upstream, therefore spread foundation can be applied.


New bridge is proposed upstream of the former bridge point.

NO. 17 THEN THO BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Present Bridge Condition

P: Ninh Binh D: Yen Mo C: Yen Hoa Super Structure : Concrete (Heavily Damaged) Sub Structure : Pilebent

Bridge Length Width of Bridge 28 m 2.6 m

Main Traffic

Pedestrians, Bicycle, Motorbike
Good for 59B, Access Road for 59B is
Gravel Road (W = 2.6 m) Access Road

- The route is among paddy fields in a deltaic region.


- The width of the road is about 3 m.
 The length from the access road to the bridge site is approximately 200 m.
 Existing bridge has been heavily damaged and automobile traffic is injussible.
 At the time of flooding in 1994, the access road was inundate.

NO. 18 HONAH TRUC BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Present Bridge Condition

P: Ninh Binh D: Kim Son C: Van Hai Super Structure : Temporary Bamboo Bridge Sub Structure : Stone Masonry

Bridge Length

27.7 m

Width of Bridge

0.6 m

Main Traffic

Access Road

: Pedestrians, Bicycle : Gravel Road (Good Condition)

Other Information


The route is among puddy fields in a deltaic region.


The condition of access road is not good but provides sufficient access to the site.


The road will be improved in 1996.
Bridge length is expected to be 45 m.
Water depth of the canal is around 1.5 m.
Equipment and materials for bridge construction will be transported by


After completion of the bridge, three provinces will be connected along the coast.

NO. 20 DONG QUACH BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Present Bridge Condition


P: Thai Binh D: Tien Hai C: Nam Ha
Super Structure : Concrete Deck, H-Beam Girder
Sub Structure : Pilebent
Bridge Length : 70.5 in
Width of Bridge : 4.1 in
Main Traction

Main Traffic Access Road Grow People to Truck (5 t)
Gravel Road (Tien Hai Side)
Paved Road with Macadam (Opposite


Other Information


The surface of access road is in good condition.
Two bridges on access road have the load limit of 5 tons.
Deck slab and girder of the bridge are severely damaged.
The bridge site is accessible by boat (20 ~ 25 ton).
Sub-soil is presumed to be the sediment of the Red River.
Proposed bridge crosses as teh river downstream of existing bridge by

NO. 21 DONG MO BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Present Bridge Condition

Lang Son Province Chi Lang District Dong Mo County

Super Structure Sub Structure : RC Bridge Stone Masonry


64.3 m 5.0 m Bridge Length Width of Bridge

Main Traffic Access Road


: Good (Temporary Asphalt Pavement)


- The bridge is located in a town of Dong Mo district on the way to Land Son by National Highway No. 1
 This bridge is made of concrete. However, it is severely damaged due to
- flooding. Existing bridge was improved but bridge has been heavily damaged and vehicle traffic is interrupted.
 Fields are flooded every year (around 5 m up).
 River bed is gravely sand.
 Possible difficulty in obtaining temporary yard.

NO. 22 NAO HOA BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Present Bridge Condition

Lang Son Province Chi Lang District Son Ha/Ho Son County Super Structure : Manpowered - Perry Boat Sub Structure :

Bridge Length Width of Bridge

Main Traffic

: Pedestrians, Bicycle, Vehicle (Max.

Access Road


13 ton)
: Good (No Pavement)


- 13 km from National Highway No. 1 to the bridge site.
 Access road to the site is in good condition.
 Actually no bridge on site, crossers use manpowered ferry boat.
 There are sand pits in the river near site.
 No problem for temporary yard. New bridge is proposed 50 m downstream from ferry boat landing.
 Approach road will be required (around 400 m length).

NO. 23 QUANG BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Present Bridge Condition

Tuyen Quang Province Chiem Hoa District Xuan Quang

Ferry Boat Flow Out 60.0 m

County Super Structure Sub Structure Bridge Length Width of Bridge Main Traffic

Pedestrians, Bicycle, Motorbike, Light

Access Road

Vehicle : Normal

- One and a half hours from National Road No. 2 to the site.

- One and a hall hours from National Road No. 2 to the site.

 Access road is mountain road in good condition.

 This road will be improved by 1997.

 River bed is said with cobble stone.


 There are said pits in the river.

 Proposed bridges site is located 6 km from province capital Chiem Hoa.


 High water level is 3 m up from normal water level during flood season.
- Yehicles use ferry boat.


 The nature of the soil is gravel, sand and clay.
- Terrace is sand and hard clay.

NO. 25 LANH BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Present Bridge Condition

P: Yen Bai D: Luc Yen C: Lieu De Super Structure : -Sub Structure : -Bridge Length : -

Width of Bridge:

Pedestrians, Bicycle, Motorbike Dirt Road Main Traffic

Access Road

- The distance between Luc Yen and bridge site is 5 km.
 Access road to the site is narrow and in bad condition, in particular, after rainfall.
- Proposed bridge crosses the river with the length of 15 m.


 The site is among the paddy fiels.


 Spread foundation is expected to be acceptable.


 When river depth is shallow, people cross the river bed.

NO. 26 BAL BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Present Bridge Condition

P: Yen Bai D: Van Yen C: Mau Dong

Super Structure
Sub Structure

Bridge Length: Width of Bridge: Main Traffic: Access Road

Pedestrians, Bicycle, Motorbike Dirt Road (W = 3.5 m)

- Access road from Yen Bai to the site is narrow and in bad condition, in particular, after rain fall.


 Distance from Yen Bai to the site is 47 km.


 Subsoil is supposedly sand with boulders.


 When the water level is not high, pedestrians and vehicles cross the river on advertised.


- e river bed. Flood level rises 3 m from teh present river stage.

NO. 27 PHO TRA LINH BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Present Bridge Condition

Cao Bang Province, Tra Linh District, Hung Quoc Village Super Structure : Wooden Bridge and Submerged Bridge Sub Structure : Stone Masonry

29.7 m

Bridge Length Width of Bridge

1.5 m


Pedestrians, Bicycle, Motorbike Gravel Road Main Traffic

Access Road


- From Cao Bang city to the site in Tra Linh it takes about one hour and a half by car.
 Site is located in the town.
 Border of China is located about 3 km from the town.
 Vehicles can submerged bridge except during flood season.


- Pedestrians and motor-cycle cross use temporary bridge in all seasons.
 Old bridge was destroyed in 1979 during the war.
 Lowest temperature is around 4 °C during winter season.

NO. 29 BAN AI BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Present Bridge Condition

P: Son La D: Son La C: Chieng Xom Super Structure : II-Beam, Wooden Deck Sub Structure : Stone Masonty

Bridge Length
Width of Bridge
Main Traffic

10.5 m 4.0 m


Access Road


form Pedestrians to Heavy Vehicle Gravel Road (W = 5 m)


- Bridge site is 8 km distant from Son La through Rt. 106. Flood level rises up to the surface of bridge. Load limit for Rt. 106 is 8 tons.


- Existing abutment is in good condition and can support new giders.

NO. 30 BAN HINH BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Present Bridge Condition

P: Son La D: Thuang Chau C: Super Structure : 11-Beam, Wooden Deck Sub Structure : Stone Masonry

Bridge Length : Width of Bridge :

13.2 m 2.9 m

Main Traffic


form Pedestrians to Heavy Vehicle
Gravel Road (W = 5 m)


Access Road


Other Information

Bridge site is 2 km distant from the junction with Ntional Rd. 6. Site is located among mountains.
Rocks are exposed on the river bed and spread foundation is likely to be applicable.
Existing abutments can be reused after renovation.
Surface condition of access road is fair.

NO. 31 TONG PANH BRIDGE







LOCATION MAP

BRIDGE SITE MAP

Present Bridge Condition

P: Son La D: Son La C: Chieng An


Super Structure : 11-Beam Sub Structure : Concrete Bridge Length : 23.8 m Width of Bridge : 3.7 m Main Traffic : Pedestrian


: Pedestrians, Bicycle : Soil Road (W = 5 m) Access Road


- The bridge collapsed due to a flood in 1991 which scoured abutment backfill.
- This route is the only access road to 6 communities.
 In new bridge construction, abutment and pier need to be carefully protected from flood flow.

NO. 33 KHUOI NIENG BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Present Bridge Condition

Ha Giang Province Bac Quang District Vinh Bao County Super Structure : Submerged Bridge

Sub Structure Bridge Length : 43.0 m Width of Bridge : 4.5 m

43.0 m

: Pedestrians, Bicycle, Motorbike, Light Main Traffic

Vehicle
: Good (No Pavement) Access Road


- 13 km from Khuoi Kieng via National Road No. 2 to the site. 10 minutes by
- Access road is in good condition.


 Presently a submerged bridge but up until 5 years ago a suspension bridge was used.
- Rocks are exposed in surrounding area.


 Rocks are exposed in river bed. However, spread foundation is likely to be applicable because deposit soil is thin.


 No problem for temporary yard.

NO. 34 KHUOI KIENG BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Present Bridge Condition

Ha Giang Province Bac Quang District Dong Yen County Super Structure : Bamboo Raft Sub Structure : -

Bridge Length : Width of Bridge : Main Traffic :

Pedestrians, Bicycle, Motorbike, Light

Vehicle
: Bad (No Payement) Access Road

- One hour by car from Khuoi Nieng bridge to the bridge site. On the way five mountain streams are crossed.

- Trucks cannot pass the access road.


 Vehicles can cross the river only during dry season.


 Pedestrians, bicycle and motorbike use bamboo raft during rainy season.


 Water level is 2.5 in up during flood season and reaches road level of left river bank.
- The nature of the soil is terrace deposit and hard layer is presumed in shallow layer.

NO. 35 BAN VUOC BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Present Bridge Condition

P: Lao Cai D: Bat Xat, C: Coc My Super Structure : Suspension Bridge Sub Structure : Stone Masonry

42 m 2.2 m

Bridge Length Width of Bridge Main Traffic Access Road 2.2 m : Pedestrians, Bicycle, Motorbike : Paved with Macadam (W = 6 m)

- The distance from Lao Cai to bridge site is around 18 km.


 No problem in transportation of equipment and materials.


 Former bridge was damaged during the war between Vietnam and China.


 Existing abutments and pier are likely to be reusable after some repair work.


 Aggregate and sand for concrete can be procured in the vicinity.

No. 37' NA SANG-2 BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Present Bridge Condition

Lai Chau Province, Dien Bien District, Nua Ngan Village
Super Structure: No Bridge
Sub Structure:
Bridge Length:
Width of Bridge: River Width is about 60 m

River Width is about 60 m Pedestrians, Bicycle, Truck Earth Road

Main Traffic Access Road

- From Dien Bien City to the site it takes one hour by jeep.
 Old bridge was washed away in 1993.
 Condition of access road is very poor, especially in rainy season.
 Improvement of the road will be completed by 1998.
 Vehicles can pass the river in dry season only.
 Alignment of new bridge crossing is limited by the topographic conditions.

8. Basic Design Criteria

Basic Design Study

0n

The Project for Reconstruction of Bridges in the Northern District

[n

The Socialist Republic of Viet Nam

DESIGN CRITERIA (DRAFT)

AUGUST

1995

13-9-4055.

Cane

Based on Design Criteria of Highway TCVN 4054-85 Victnamese Bridge Design Code 22 TCN 018-79 Winistry of Transport and Communication No2057QD/K14 1979

1. Typical Cross Section


1-1. Bridge

a. Classification of the Road


Class	Design Traffic Volume (Yeh. /day)
N	300 ~ 1000
γ	50 ~ 300
Ŋ	Less than 50

b. Recommended Width for Each Bridge

Case 1	Clear Width 4.5m	Bri. Construction No. 9 11 13 15 17 18 24 31 33 34	Girder Supply No. 10 25	Total 12
2	5.5m	No. 3 5 6 8 16 23	No. 4 7 21 26 28 29 30 35 36	15
3	7. Om	No.1 12 20 22 27	No. 19	6
	Total	2j Brt.	12 Bri.	33 Bri.



1-2. Approach Road



2. Live Load Vietnamese standard II 13 -X60

3. Coefficient of Earthquake

Kh(Horizontal Acceleration Ratio) = 0.05 (by Seismic Intensity Scale 1992)

1. Clearance

-Road Clearance for the Bridge | II= 4.50m

-Flood Clearance for the Bridge | H= 0.50m

-Navigation Clearance for the Bridge

Ship	lloriz	ontal	Vertical
	River	Channe 1	
300tons	40m	25m	6m
100tons	25m	20m	3.5m
40tons	15m	10m	2.5 ₁₀


5. Standard Span Length (3.0m Interval)

- -1. 15m
- -2. 21m
- -3. 24m
- -4. 30m
- -5. Specified length

6. Structural Type of Bridge

- 6-1. Super Structure
 - -1. Bridge Construction


Post Tentioned - Prestressed Concrete T Beam (Case-1)



-2. Girder Supply

Composite H-beam Girder (Case-2)


Composite Built-up Steel Glrder (Case-3)





6-2. Sub Structure

- -1. Spread Foundation Type (Case-1)
- -2. Pile Foundation Type (Case-2)



Item	Unit	Design S	tandard	
Design Speed	km/h	60	40	25
HORIZONTAL ALIGNMENT				
Min. radius	m	130	60	25
Min. curve length	n	100*	70*	45*
Min. transition curve len	gth m	50*	35*	25*
Superelevation runoff		1/125*	1/100*	1/65*
Min. stopping sight dista	nce m	150	80	40
VERTICAL ALIGNMENT	: : :			
Max. gradient	*	7	8	9
Min. vertical curve lengt	h			• •
Crest	m	2500(1400*)	1000 (450*)	600(175+)
Sag	. п	1500(1000*)	1000 (450*)	250(175+)
Min. vertical curve lengt	h n	50#	30*	25*
CROSS SECTION				
Cross fall	*	3	3	3
Max superelevation	*	10*	10*	10+

Notes: * Based on Japanese Code Applied 40,25km/h Design Speed