




Corrosion on main beams



Rating 4




Rating 4




Rating 3
4-15


Painting




Rating 4




Rating 3






Rating 3



Rating 2




Rating 2





Rating 1

Corrosion





Rating 3



Rusting





Rating 2



Bearing




Rating 4



Rating 3




Rating 2





Rating 1

Expansion joint






Rating 4






Rating 3



Rating 2




Drainage





Rating 3

Too small



Rating 2





Choking up with mud




Rating 1






Substructure




Rating 4



Rating 3




Rating 2



Rating 1


4-21



Substructure(RSJ)




Very corroded



Inclined

Rating 4




Rating 4




Rating 3

Huge opening




Rating 2



Rating 2



Foundation




Major scoring




Rating 4




Rating 4



Settled substructure



Rating 3




Scoring






4-23

Substructure



Rating 2




Rating 1


1-24



Wingwall






Huge void




Huge opening



Rating 4











Rating 3





Rating 2




Wingwall, Revetment






Structural defect






Very corroded




Corroded beam ends






Structural defect



- Upper Flang of Main Beam corroded.
- Lower Flang of Main Beam corroded.



Redecking.



Structural defect

