




INVENTORY OF PAVEMENT SURFACE CONDITION




Date: 11-6-95

Sheet No: 1/3


Km. 1472+000



To Carmen
Proper



Undulating Pavt.










INVENTORY OF PAVEMENT SURFACE CONDITION

Date : 11-6-95

Km. 1472+000

Sheet No : 2/3








INVENTORY OF PAVEMENT SURFACE CONDITION

Date: 11-6-95

Sheet No: 1/3

Km. 1473+000










INVENTORY OF PAVEMENT SURFACE CONDITION

Date: 11-6-95

Sheet No: 1/2

Km. 1474+000










INVENTORY OF PAVEMENT SURFACE CONDITION

Km. 1474+000

Date: 11-6-95

Sheet No: 2/2










INVENTORY OF PAVEMENT SURFACE CONDITION

Date: 11 - 6 - 95

Km. 1475 + 000 - 1477 + 000

Sheet No: 1/6










INVENTORY OF PAVEMENT SURFACE CONDITION

Date: 11 - 6 - 95

Km. 1475 + 000 - 1477 + 000

Sheet No: 2/6










INVENTORY OF PAVEMENT SURFACE CONDITION

Date: 11 - 7 - 95

Km. 1475 + 000 - 1477 + 000

Sheet No: 5/6



INVENTORY OF PAVEMENT SURFACE CONDITION

Km. 1475 + 000 - 1477 + 000

Date: 11-7-95

Sheet No: 6/6

Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc
Sc (Po)	Sc	Sc	Sc (Po)	Sc (Po)	Sc	Sc	Sc	Sc	Sc	Sc (Po)	Po	Sc	Sc	Sc	Sc

Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc
Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc

Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc
Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc

Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc
Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Po	Po	Po	Sc	Po	Po	Po	Sc

Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc
Sc	Po	Po	Po	Po	Po	Po	Po	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc

Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc
Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc

Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc
Sc	Sc	Sc	Sc	Sc	Sc	Sc	Sc (Po)	Sc	8.54						

X

4.35

1.80255 -8.43








⊗ KP. 1478 + 000

INVENTORY OF PAVEMENT SURFACE CONDITION

Date: 11-7-95

Km. 1478+000

Sheet No: 1/3









INVENTORY OF PAVEMENT SURFACE CONDITION

Date: 11-7-95

Km. 1478+000

Sheet No: 2/3




INVENTORY OF PAVEMENT SURFACE CONDITION

Date: 11-7-95

Sheet No: 1/2

Km. 1479+000










INVENTORY OF PAVEMENT SURFACE CONDITION

Km. 1479+000

Date: 11-7-95

Sheet No: 2/2










INVENTORY OF PAVEMENT SURFACE CONDITION

Date: 11-7-95

Sheet No: 1/2

Km. 1480+000










INVENTORY OF PAVEMENT SURFACE CONDITION

Km. 1480+000

Date: 11-7-95

Sheet No: 2/2










1.0 3.60 2.50
 KP 1481+000

INVENTORY OF PAVEMENT SURFACE CONDITION

Date: 11-7-95

Sheet No: 1/2

Km. 1481+000









INVENTORY OF PAVEMENT SURFACE CONDITION

Date: 11 - 8 - 95

Sheet No: 1/3

Km. 1482 + 000



INVENTORY OF PAVEMENT SURFACE CONDITION

Date : 11 - 8 - 95

Km. 1482 + 000

Sheet No : 2/3

