Japan International Copperation Agency
Ministry of Works and Supply, Republic of Zambia
Ministry of Transport and Energy, Republic of Limitations

The Feasibility Study on the Proposed New Bridge Over the Zambezi River at Chicanda Border Post

Ketwech

the Republic of Zambia and the Peral lic of Kinds lave

> Pimal Report (Drawing)

Manch 1998

J 1142086 [6]

Cherolin Con, Filel.

S S F CR (3)







Japan International Cooperation Agency Ministry of Works and Supply, Republic of Zambia Ministry of Transport and Energy, Republic of Zimbabwe

The Feasibility Study on the Proposed New Bridge Over the Zambezi River at Chirundu Border Post

Between

the Republic of Zambia and the Republic of Zimbabwe

Final Report (Drawings)


March 1998


Chodai Co., Ltd.


1142086[6]


Contents


- 1 GENERAL PLAN OF THE PROJECT
- 2 GEOLOGICAL SECTION
- 3 TOPOGRAPHICAL MAP 1
- 4 TOPOGRAPHICAL MAP 2
- 5 TOPOGRAPHICAL MAP 3
- 6 LONGITUDINAL PROFILE 1
- 7 LONGITUDINAL PROFILE 2
- 8 LONGITUDINAL PROFILE 3
- 9 CHIRUNDU BRIDGE GENERAL VIEW
- 10 SUPERSTRUCTURAL PLAN 1
- 11 SUPERSTRUCTURAL PLAN 2
- 12 SUBSTRUCTURAL PLAN 1
- 13 SUBSTRUCTURAL PLAN2
- 14 ROAD PLAN AND PROFILE 1 (ZAMBIA SIDE)
- 15 ROAD PLAN AND PROFILE 2 (ZIMBABWE SIDE)
- 16 CUSTOMS AND IMMIGRATION FACILITIES IMPROVEMENT PLAN AT ZAMBIA SIDE
- 17 LAYOUT OF BORDER FACILITIES ZAMBIA SIDE 1
- 18 LAYOUT OF BORDER FACILITIES ZAMBIA SIDE 2
- 19 CUSTOMS AND IMMIGRATION FACILITIES IMPROVEMENT PLAN AT ZIMBABWE SIDE
- 20 LAYOUT OF BORDER FACILITIES ZIMBABWE SIDE 1
- 21 LAYOUT OF BORDER FACILITIES ZIMBABWE SIDE 2
- 22 LAYOUT OF BORDER FACILITIES ZIMBABWE SIDE 3
- 23 PASSENGER CONTROL BUILDING 1
- 24 PASSENGER CONTROL BUILDING 2
- 25 FREIGHT TERMINAL BUILDING 1
- 26 FREIGHT TERMINAL BUILDING 2
- 27 FREIGHT TERMINAL BUILDING 3
- 28 FREIGHT INSPECTION TERMINAL BUILDING 1
- 29 FREIGHT INSPECTION TERMINAL BUILDING 2
- 30 VEHICLE THEFT UNIT
- 31 VID BUILDING + WEIGH BREIDGE
- 32 DEC OFFICES + SNIFFER DOG KENNELS







































SUPERSTRUCTURAL PLAN 2

Section View 5-1:50










SUBSTRUCTURAL PLAN 1

(1:500)


Α1

A2


FRONT VIEW




FRONT VIEW




SIDE VIEW



PLAN VIEW





PLAN VIEW



SUBSTRUCTURAL PLAN 2


(1:500)








ROAD PLAN AND PROFILE 2 (ZIMBABWE SIDE)


PLAN \$ = 1:1000


















CUSTOMS AND IMMIGRATION FACILITIES IMPROVEMENT PLAN AT ZIMBABWE SIDE












PASSENGER CONTROL BUILDING 1



MAIN ENTRANCE ELEVATION









SIDE ELEVATION


PASSENGER CONTROL BUILDING 2

OUT - GOING PASSENGERS








MAIN ENTRANCE ELEVATION - IMPORT SIDE 1:200




SECTION THRO ASYCUDA SYSTEM











VEHICLE THEFT UNIT 02(03)(04)(05)(06)(07)(08)(09)(10)(11)(12)(13)(14)(15)(G)(F) (E)(D)(C)(B)(A)ELEVATION SIDE ELEVATION (05)(06)(07)(08)(09)(10)(11)(12)(13)(14)(15)H(G)(F)(E)(D)(C)(B)(A)28 000 GENERAL STORE)(B)(C INSPECTION HOIST GENERAL STORE OFFICER IN - CHARGE 13000 SECTION AA CORRIDOR LOCK-UP GARAGE)(E)(F)(G)(H ADMIN. 8 OPEN-PLAN COMPUTER OFFICE ROOM INVESTIGATORS PUBLIC RECEPTION RAMP RAMP

PLAN





		,



