No. 2

JAPAN INTERNATIONAL COOPERATION AGENCY (JICA)

MINISTRY OF COMMUNICATIONS, THE ROYAL GOVERNMENT OF BHUTAN

THE STUDY


ON

NATIONAL HIGHWAY BRIDGE CONSTRUCTION

IN

THE KINGDOM OF BHUTAN

FINAL REPORT
VOLUME 3
APPENDIX



JULY 1998



PACIFIC CONSULTANTS INTERNATIONAL HOKKAIDO ENGINEERING CONSULTANTS Co., Ltd.

SSF

CR (5)

98-080





JAPAN INTERNATIONAL COOPERATION AGENCY (JICA)

MINISTRY OF COMMUNICATIONS, THE ROYAL GOVERNMENT OF BHUTAN

THE STUDY

ON

NATIONAL HIGHWAY BRIDGE CONSTRUCTION

IN

THE KINGDOM OF BHUTAN

FINAL REPORT
VOLUME 3
APPENDIX

JULY 1998


PACIFIC CONSULTANTS INTERNATIONAL HOKKAIDO ENGINEERING CONSULTANTS Co., Ltd.



NOTE

The following exchange rate was adopted through this report.

US\$ 1.00 = Nu. 38.6 (March 1998)



Location Map of Bridges for the Study



TABLE OF CONTENTS

VOLUME 3

APPENDIX


Appendix - A	Outline of 22 Bridges
Appendix - B	Photographs of Site Conditions (5 Bridges)
Appendix - C	Bridges Survey Results (22 Bridges)
Appendix - D	List of Permanent Bridges on National Highways in Bhutan
Appendix - E	Standard Specifications and Code of Practice for Road Bridges Section II Loads and Stresses The Indian Roads Congress 1990
Appendix - F	Geological Survey Results
Appendix - G	List of Totally Protected Wild Animals and Plants in Bhutan
Appendix - H	Tables of Initial Environmental Evaluation
Appendix - I	TOR for EIA for the National Highway Bridge Construction
Appendix - J	Construction Plan/Cost Estimate
Appendix - K	Economic Analysis - Cost & Benefit Flow


APPENDIX


Appendix-A
Outline of 22 Bridges


그 가는 아님, 그는 회를 선택하게 되는 것을 바람을 하는 것이 하지 않는 하는 것은 것 같아. 그가 그 있다.
그는 앞에 하는 말한 후에는 보이 없었다. 하라니다. 이 원리가 되는 것이 많은 그는 말이 되어 있는 것은 말했다. 이 사람들은 사람들이 되었다.
경험이 가는 이렇게 하고요요요요요요. 그렇게 하는 경우 나이를 눈이 들어 먹는 사람이 되었습니다. 하다 나라는
그리다 그 이 일반에 가장하는 말 없는 이 전에 가는 사람이 하는 사람이 많은 사람들이 다른 사람이다.
그는 하는 하는 한 병장 이를 살았다. 그런 그는 이를 하는 것은 것은 사람들이 없는 사람들이 살 살아 있다.
그리고 회의 그 보는 하는 사람들이 되는 사람들이 되는 사람들이 되는 사람들이 되었다. 그 사람들이 모양하는 것이다.

BRIDGE NO. 1 KURIZAMPA BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Existing Conditions

1.Location: Kurichu River, Mongar Dzongkhag

National Highway Route No.1 2.Class of road:

Bailey TSR 3. Superstructure:

Masonry abutments on natural rock 4. Substructure:

Sealed macadam paved 4 m wide 5. Approach roads:

42.7 m 6.Bridge length:

3.36 m (carriageway) 7.Bridge width:

8. Maintenance, especially repainting manner, is not

satisfactory.

Other Information


Completed in 1971

Original load capacity: Present limited load capacity: 5 ton


18 ton


In down stream, Kurichu Hydro Power Plant is under construction. However there is no influence to water level at the bridge site.

BRIDGE NO. 2 CHAMKAR ZAM BRIDGE









LOCATION MAP

BRIDGE SITE MAP

	٠.		/· •	
ŀλ	ıst	mg	Cond	litions

1.Location: Chamkarchu River, Bumthang

Dzongkhag

2.Class of road: National Highway Route No.1

3. Superstructure: Bailey DS

4.Substructure: Masonry abutments on natural rock

5. Approach roads: Sealed macadam paved 4 m wide

6.Bridge length: 33.7 m

7.Bridge width: 3.22 m (carriageway)

1.8 Maintenance, especially on the underside of superstructure, is not satisfactory. The rust has gone into steel members.

superstructure is not satisfactory. The rust has gone into steel members.


Other Information


 Completed in 1973
 Original load capacity: 18 ton Present limited load capacity: 5 ton


3. Near bridge site a space for construction materials and


equipment is available.

BRIDGE NO. 3 BJEE BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Existing Conditions

1.Location: Mangdichu River, Trongsa Dzongkhag

2.Class of road: National Highway Route No.1

3. Superstructure: Bailey TSR

4.Substructure: Masonry abutments on natural rock 5.Approach roads: Sealed macadam paved 4 m wide

6.Bridge length: 42.7 m


7.Bridge width: 3.36 m (carriageway)


8. The underside of the superstructure is very rusty and there is no sign of past maintenance. A turn-buckle doesn't work as shown in the photo, pins are missing, and main beams are crushed by vehicles and left bent severely at 24 locations.


Other Information


 Completed in 1971
 Original load capacity: 18 ton Present limited load capacity: 9 ton

BRIDGE NO. 4 WACHY ZAM BRIDGE









LOCATION MAP

BRIDGE SITE MAP

		89.3	
t.xist	mg C	onditions	

1.Location:

Dangehu River, Wongdue Dzongkhag

2. Class of road:

National Highway Route No.1

3.Superstructure:

Bailey DSR

4.Substructure:

Masonry abutments on natural rock

5. Approach roads:

Sealed macadam paved 4 m wide

6.Bridge length:

33.7 m

7.Bridge width:

3.15 m (carriageway)

8. Main steel members are seriously got rusted into

the mother materials.

Other Information

1. Completed in

1969


2. Original load capacity:

18 ton


Present foad capacity:


18 ton

BRIDGE NO. 5 MANGDICHU BRIDGE











LOCATION MAP


BRIDGE SITE MAP


Existing Conditions		8. Some wires of main cables were damaged. It is very	
1.Location:	Mangdichu River, Zhemgang Dzongkhag	dangerous. Other Information	
2.Class of road: 3.Superstructure:	National Highway Route No.4 Bailey Suspension	Completed in Original load capacity:	1965 18 ton
4. Substructure: 5. Approach roads: 6. Bridge length:	Masonry abutments on Sealed macadam paved 4 m wide 97.4 m	Present limited load capacity: 3. Near bridge site a space for construct equipment is available.	4 ton tion materials and
7.Bridge width:	3.20 m (carriageway)	единисти із ачапаме.	

BRIDGE NO. 6 WANGDIGANG BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Existing (Condi	tions
1 Location	n.	

Location: Wangdigangchu River, Zhenigang

Dzongkhag

2. Class of road: National Highway Route No.4

3.Superstructure:

Bailey DS

4.Substructure: Masonry abutments on natural rocks

5. Approach roads: Sealed macadam paved 4 m wide

6.Bridge length:

30.5 m

7.Bridge width: 3.35 m (carriageway)

8.One pin on the end post is missing, and main frames were crushed and bent at 3 locations.


Other Information


 Completed in 1969
 Original load capacity: 15 ton Present load capacity: 15 ton

BRIDGE NO. 7 PANJURMANI BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Existin	e Co	ndit	ions

1.Location:

Kartigangchu River, Trongsa

Dzongkhag

2.Class of road:

National Highway Route No.4

3. Superstructure:

Steel I girder with timber deck

4.Substructure:

Masonry abutments

5. Approach roads:

Sealed macadam paved 4 m wide

6.Bridge length:

Sealed macadam j

7.Bridge width:

4.0 m (carriageway)

8. Former Bailey bridge was damaged by flood and falling trees.

Existing steel girder with log deck is a temporary one. Heavy trucks are crossing the river bed at upper stream.

Other Information

1. Completed in

1995


2. Original load capacity:

unknown


Present limited food capacity:


7 ton

BRIDGE NO. 8 ISHIGANGCHU BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Existing Conditions

1.Location: Ishigangchu River, Trongsa

Dzongkhag

2.Class of road: National Highway Route No.4

3. Superstructure: Bailey DS

4. Substructure: Masonry abutments on natural rock

5. Approach roads:

Sealed macadam paved 4 m wide

6.Bridge length: 36.6 m


7.Bridge width: 3.34 m (carriageway)


8.This is a temporary bridge.


Other Information


 Completed in 1992
 Original load capacity: 18 ton Present limited load capacity: 15 ton

BRIDGE NO. 9 HESOTHANGKHA BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Existing Conditions

1.Location:

Hesothangkhachu River, Wangdue

Dzongkhag

2.Class of road:

National Highway Route No.5

3. Superstructure:

Bailey SS

4. Substructure:

Masonry abutments on natural rock

5. Approach roads:

Sealed macadam paved 4 m wide

6.Bridge length:

9.2 m

7. Bridge width:

3.34 m (carriageway)

8. totally very good condition

Other Information

1. Completed in

1985

24 ton

2. Original load capacity:


18ton


Present limited load capacity:


3. Near bridge site a space for construction materials


and equipment is available.

BRIDGE NO. 10 LAWAKHA BRIDGE











LOCATION MAP

BRIDGE SITE MAP


Existing Conditions		0	ther Information	
1.Location: 2.Class of road: 3.Superstructure: 4.Substructure: 5.Approach roads: 6.Bridge length: 7.Bridge width:	Lawakhachu River, Wangdue Dzongkhag National Highway Route No.5 Bailey DSR Masonry abutments on natural rocks Scaled macadam paved 4 m wide 30.5 m 3.37 m (carriageway)	1. 2. 3.	Completed in	1988 24 ton 18 ton struction materials and
8.Deck timber is det	eriorated.			

BRIDGE NO. 11 BASOCHU BRIDGE









LOCATION MAP

BRIDGE SITE MAP

1.Location:	Basochu River, Wangdue
	Dzongkhag
2.Class of road:	National Highway Route No.5
3.Superstructure:	Bailey SSR

4.Substructure: Masonry abutments on natural rock 5.Approach roads: Sealed macadam paved 4 m wide

6.Bridge length: 18.3 m


Existing Conditions

7.Bridge width: 3.34 m (carriageway)


Other Information


1. Completed in 1985
2. Original load capacity: 18 ton
Present limited load capacity: 15 ton

BRIDGE NO. 12 RURICHU BRIDGE









LOCATION MAP

BRIDGE SITE MAP

ľ	AIST	ıng י	Conamons

Rurichu River, Wangdue 1.Location:

Dzongkhag

2.Class of road:

National Highway Route No.5

3. Superstructure:

Bailey SS

4. Substructure:

Masonry abutments on natural rock

5. Approach roads:

Sealed macadam paved 4 m wide

6.Bridge length:

15.3 m

7.Bridge width:

3.34 m (carriageway)

8. Very good condition, except bearings.

Other Information

1. Completed in

1987

Original load capacity:


18 ton


Present load capacity: 3. Near bridge site a space for construction materials


18 ton


and equipment is available.

BRIDGE NO. 13 BAYCHU BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Existing	Conditions
----------	------------

1.Location:

Baychu River, Wangdue

Dzongkhag

2.Class of road:

National Highway Route No.5

3. Superstructure:

Bailey SS

4. Substructore:

Masonry abutments on natural rock

5. Approach roads:

Scaled macadam paved 4 m wide

6.Bridge length:

15.3 m

7.Bridge width:

3.34 m (carriageway)

8. Very good condition

Other Information

1. Completed in

1985


Original load capacity:

18 ton


Present limited load capacity:


17 ton

BRIDGE NO.14 KAMICHU BRIDGE











LOCATION MAP


BRIDGE SITE MAP


Existing Conditions		Other Information	
1.Location: 2.Class of road: 3.Superstructure: 4.Substructure: 5.Approach roads: 6.Bridge length: 7.Bridge width:	Kamichu River, Wangdue Dzongkhag National Highway Route No.5 Bailey SS Masonry abutments on natural rocks Sealed macadam paved 4 m wide 18.3 m 3.34 m (carriageway)	1. Completed in 2. Original load capacity: Present limited load capacity: 3. Near bridge site a space for consequipment is available.	1986 24ton 15 ton struction materials and

BRIDGE NO. 15 NARACHU BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Existing Conditions

1.Location: Narachu River, Daga Dzongkhag 2.Class of road: National Highway Route No.5

3. Superstructure: Bailey DS

4. Substructure: Masonry abutments on natural rock

5. Approach roads: Sealed macadam paved 4 m wide 6. Bridge length: 30.5 m


7.Bridge width: 3.31 m (carriageway)

8. Very good condition


Other Information


 Completed in 1991
 Original load capacity: 24 ton Present load capacity: 24 ton

BRIDGE NO. 16 WAKLEYTAR BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Existing Conditions

1.Location: Sunkosh River, Tsirang Dzongkhag

2. Class of road: National Highway Route No.5

3. Superstructure: Bailey Suspension

4.Substructure: Masonry abutments on natural rock

5. Approach roads: Sealed macadam paved 4 m wide

6.Bridge length: 73.2 m


7.Bridge width: 3.37 m (carriageway)

8. Members underside of superstructure is very rusty. The above photo shows one example of very rusty turn-buckles,


Other Information


 Completed in 1987
 Original load capacity: 24 ton Present limited load capacity: 12 ton

BRIDGE NO. 17 MECHIKHOLA BRIDGE









LOCATION MAP

BRIDGE SITE MAP

EXISTING CONTINUES	Exi	isting	Conditions
--------------------	-----	--------	------------

1. Location: Mechikhola River, Tsirang Dzongkhag

2.Class of road: National Highway Route No.5

3. Superstructure: Timber Truss

4.Substructure: Masonry abutments on natural rock

5. Approach roads: Sealed macadam paved 4 m wide

6.Bridge length: 18.0 m


7.Bridge width: 3.69 m (carriageway)


8. Very good condition. However in PWD's classification, this is a temporary bridge


Other Information


Completed in
 Original load capacity:
 Present limited load capacity:
 8 ton

BRIDGE NO. 18 BURICHU BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Existing Conditions

1.Location: Burichu River, Tsirang Dzongkhag

2.Class of road: National Highway Route No.5

3.Superstructure: Bailey DS

4. Substructure: Masonry abutments on natural rocks

5. Approach roads: Sealed macadam paved 4 m wide

6.Bridge length: 27.5 m


7.Bridge width: 3.37 m (carriageway)


8. Very good condition


Other Information


 Completed in 1985
 Original load capacity: 24 ton Present limited load capacity: 18 ton

BRIDGE NO. 19 CHANCHY BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Existing Conditions	
1.Location;	Chancheychu River, Tsirang
	Dzongkhag

National Highway Route No.5 2.Class of road:

Bailey TS 3. Superstructure:

Masonry abutments on natural rock 4.Substructure: Scaled macadam paved 4 m wide 5. Approach roads:

6.Bridge length: 39.7 m


7.Bridge width: 3.31 m (carriageway)


8. Very good condition


Other	Inf	ormat	ion
-------	-----	-------	-----


1986 1. Completed in 24 ton Original load capacity: 18 ton Present limited load capacity:

BRIDGE NO. 20 LORINGKHOLA BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Existing Conditions

1.Location: Loringkhola River, Sarpang Dzongkhag

National Highway Route No.5 2.Class of road:

3. Superstructure: Bailey DDR

4.Substructure: Masonry abutments on natural rock 5. Approach roads: Sealed macadam paved 4 m wide

6.Bridge length: 48.8 m


7.Bridge width: 3.30 m (carriageway)


8. Environment the bridge site is very wet by the high waterfall at the upper stream side.


Other Information


1. Completed in 1992 2. Original load capacity: 24 ton Present limited load capacity: 18 ton

BRIDGE NO. 21 TANGMACHU BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Existing Conditions

1.Location: Kurichu River, Lhuentse Dzongkhag 2.Class of road: District Road Monga-Lhuentse

3. Superstructure: Bailey Suspension

4. Substructure: Masonry abutments on natural rock
5. Approach roads: Sealed macadam paved 4 m wide


6.Bridge length: 85.4 m


7.Bridge width: 3.30 m (carriageway)


Other Information


 Completed in 1982
 Original load capacity: 24 ton Present limited load capacity: 12 ton

BRIDGE NO.22 SUNKOSH BRIDGE









LOCATION MAP

BRIDGE SITE MAP

Existi	no (Con	dit	ions
1.31311			U 11	10 12.7

1.Location: Sunkosh River, Daga Dzongkhag 2.Class of road: National Highway Route No.5

3. Superstructure: Bailey Suspension

4.Substructure: Masonry abutments on natural rocks
5.Approach roads: Sealed macadam paved 4 m wide

6.Bridge length:

85.4m

7.Bridge width:

3.30 m (carriageway)

Other Information

Completed in
 Original load capacity:

1982 24 ton

Original load capacity:

Present limited load capacity:

12 ton