

BUILDING SURVEY DETAILS

BUILDING NUMBER	BUILDING NAME	STRUCTURE	COMPLETION YEAR	BUILDING AREA	TOTAL FLOOR AREA	CONCRETE DESIGN COMPRESSIVE STRESS	CONCRETE ACTUAL COMPRESSIVE STRESS	RENEWAL DATA	COPING	CAULKING	OTHERS
20	POWER STATION	REINFORCED CONCRETE COLUMN/WALL BRICK		565.86m <sup>2</sup>	565.86m <sup>2</sup>	300KG/cm <sup>2</sup>					
EXTERIOR NORTH	COLUMN BEAM	⊙ WALL(BRICK)	⊙	DOOR	X	METAL	EXTERIOR FINISH	X	WATER PROOF	X	OTHERS
		NORMAL	✓	NORMAL		NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	AT THE PRESENT MOMENT (JULY 22, 1999), REPAIRING WORK AT THE ROOF OF THE GENERATOR ROOM IS IN PROGRESS.
EVALUATION ITEM	DAMAGE	BROKEN		CORROSION	✓	CORROSION	DIRTY	✓	LEAKAGE	BROKEN	✓
		BROKEN		CORROSION	✓	CORROSION	DIRTY	✓	DAMAGE	NONE	
INVESTIGATION METHOD	VISUAL INSPECTION	BULLET MARKS		MISSING	✓	NONE	WORK OUT	✓			
		VISUAL INSPECTION		MISSING	✓	VISUAL INSPECTION	VISUAL INSPECTION	✓	VISUAL INSPECTION	VISUAL INSPECTION	
PHOTO NUMBERS	30-1			20-1			20-1				20-1
RECOMMENDATION	C	C		A			A		A	A	
EXTERIOR EAST	COLUMN BEAM	⊙ WALL(BRICK)	⊙	DOOR	X	METAL	EXTERIOR FINISH	X	WATER PROOF	X	OTHERS
		NORMAL	✓	NORMAL		NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	
EVALUATION ITEM	DAMAGE	BROKEN		CORROSION	✓	CORROSION	DIRTY	✓	LEAKAGE	BROKEN	✓
		BROKEN		CORROSION	✓	CORROSION	DIRTY	✓	DAMAGE	NONE	
INVESTIGATION METHOD	VISUAL INSPECTION	BULLET MARKS		MISSING	✓	NONE	WORK OUT	✓			
		VISUAL INSPECTION		MISSING	✓	VISUAL INSPECTION	VISUAL INSPECTION	✓	VISUAL INSPECTION	VISUAL INSPECTION	
PHOTO NUMBERS	30-2			20-2			20-2				
RECOMMENDATION	C	C		A			A		A	A	
EXTERIOR SOUTH	COLUMN BEAM	⊙ WALL(BRICK)	X	DOOR	X	METAL	EXTERIOR FINISH	X	WATER PROOF	X	OTHERS
		NORMAL	✓	NORMAL		NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	
EVALUATION ITEM	DAMAGE	BROKEN	✓	CORROSION	✓	CORROSION	DIRTY	✓	LEAKAGE	BROKEN	✓
		BROKEN	✓	CORROSION	✓	CORROSION	DIRTY	✓	DAMAGE	NONE	
INVESTIGATION METHOD	VISUAL INSPECTION	BULLET MARKS		MISSING	✓	NONE	WORK OUT	✓			
		VISUAL INSPECTION		MISSING	✓	VISUAL INSPECTION	VISUAL INSPECTION	✓	VISUAL INSPECTION	VISUAL INSPECTION	
PHOTO NUMBERS	20-3			20-3			20-3				
RECOMMENDATION	C	B		A			A		A	A	
EXTERIOR WEST	COLUMN BEAM	⊙ WALL(BRICK)	⊙	DOOR	W	METAL	EXTERIOR FINISH	X	WATER PROOF	X	OTHERS
		NORMAL	✓	NORMAL		NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	
EVALUATION ITEM	DAMAGE	BROKEN		CORROSION	✓	CORROSION	DIRTY	✓	LEAKAGE	BROKEN	✓
		BROKEN		CORROSION	✓	CORROSION	DIRTY	✓	DAMAGE	NONE	
INVESTIGATION METHOD	VISUAL INSPECTION	BULLET MARKS		MISSING	✓	NONE	WORK OUT	✓			
		VISUAL INSPECTION		MISSING	✓	VISUAL INSPECTION	VISUAL INSPECTION	✓	VISUAL INSPECTION	VISUAL INSPECTION	
PHOTO NUMBERS	20-1			20-1							
RECOMMENDATION	C	C		A			A		A	A	

EVALUATION ⊙-GOOD Δ-AVERAGE X-BAD  
 RECOMMENDATION A-TOTAL REFURBISHMENT B-PARTIAL REFURBISHMENT C-NOT NECESSARY



BUILDING NUMBER-20 POWER STATION

TOILET	FLOOR	WALL	CEILING	METAL	STAIR	LIGHTING	VENTILATION	HEATING	WATER EQUIPMENT	FIRE EXTINGUISHER	OTHERS
PARTICULAR	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	
EVALUATION ITEM	DIRTY	DIRTY	DIRTY	RUSTY	DIRTY	RUSTY	CORROSION	BROKEN	BROKEN	CORROSION	
	SAG	SAG	SAG	CORROSION	UNEVEN	BROKEN	BROKEN	MISSING	MISSING	BROKEN	
	BROKEN	BROKEN	BROKEN	BROKEN	BROKEN	MISSING	MISSING			MISSING	
INVESTIGATION METHOD	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	
PHOTO NUMBERS											
RECOMMENDATION	A	A	A			A		A	A		
STORAGE											
PARTICULAR	FLOOR	WALL	CEILING	METAL	STAIR	LIGHTING	VENTILATION	HEATING	WATER EQUIPMENT	FIRE EXTINGUISHER	OTHERS
	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	
EVALUATION ITEM	DIRTY	DIRTY	DIRTY	RUSTY	DIRTY	RUSTY	CORROSION	BROKEN	BROKEN	CORROSION	
	SAG	SAG	SAG	CORROSION	UNEVEN	BROKEN	BROKEN	MISSING	MISSING	BROKEN	
	BROKEN	BROKEN	BROKEN	BROKEN	BROKEN	MISSING	MISSING			MISSING	
INVESTIGATION METHOD	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	
PHOTO NUMBERS											
RECOMMENDATION	A	A	A			A					
PARTICULAR	FLOOR	WALL	CEILING	METAL	STAIR	LIGHTING	VENTILATION	HEATING	WATER EQUIPMENT	FIRE EXTINGUISHER	OTHERS
	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	
EVALUATION ITEM	DIRTY	DIRTY	DIRTY	RUSTY	DIRTY	RUSTY	CORROSION	BROKEN	BROKEN	CORROSION	
	SAG	SAG	SAG	CORROSION	UNEVEN	BROKEN	BROKEN	MISSING	MISSING	BROKEN	
	BROKEN	BROKEN	BROKEN	BROKEN	BROKEN	MISSING	MISSING			MISSING	
INVESTIGATION METHOD	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	
PHOTO NUMBERS											
RECOMMENDATION	A	A	A			A					

RECOMMENDATION A-TOTAL REFURBISHMENT  
 B-PARTIAL REFURBISHMENT  
 C-NOT NECESSARY

EVALUATION  
 ⊕-GOOD  
 Δ-AVERAGE  
 x-BAD

# BUILDING SURVEY PHOTO

BUILDING NUMBER	20	BUILDING NAME	POWER STATION
-----------------	----	---------------	---------------

PLAN AND DIRECTION FROM WHICH PHOTO WAS TAKEN




PHOTO NUMBER 20-1



# BUILDING SURVEY PHOTO

BUILDING NUMBER	20	BUILDING NAME	POWER STATION
-----------------	----	---------------	---------------

PHOTO NUMBER	20-2
--------------	------





PHOTO NUMBER	20-3
--------------	------



# BUILDING SURVEY PHOTO

BUILDING NUMBER	20	BUILDING NAME	POWER STATION
-----------------	----	---------------	---------------

PHOTO NUMBER	20-4
--------------	------




PHOTO NUMBER	20-10
--------------	-------



# BUILDING SURVEY PHOTO

BUILDING NUMBER	20	BUILDING NAME	POWER STATION
-----------------	----	---------------	---------------

PHOTO NUMBER	20-11
--------------	-------





PHOTO NUMBER	20-12
--------------	-------



**BUILDING SURVEY PHOTO**

BUILDING NUMBER	20	BUILDING NAME	POWER STATION
-----------------	----	---------------	---------------

PHOTO NUMBER	20-13
--------------	-------




PHOTO NUMBER	20-14
--------------	-------





BUILDING SURVEY DETAILS

BUILDING NUMBER	BUILDING NAME	STRUCTURE	COMPLETION YEAR	BUILDING AREA	TOTAL FLOOR AREA	CONCRETE DESIGN COMPRESSIVE STRESS	CONCRETE ACTUAL COMPRESSIVE STRESS	RENEWAL DATA	OTHERS
21	SUBSTATION	REINFORCED CONCRETE (COLUMN,BEAM), WALL BRICK		60.84m <sup>2</sup>	60.84m <sup>2</sup>	300KG/cm <sup>2</sup>			
EXTERIOR NORTH	COLUMN BEAM	⊙ WALL(BRICK)	⊙	DOOR	X WINDOW	METAL	EXTERIOR FINISH	X COPING	X CAULKING
EVALUATION ITEM	NORMAL	✓	✓	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL
	DAMAGE			RUSTY	RUSTY	RUSTY	DIRTY	RUSTY	BROKEN
	BROKEN			CORROSION	CORROSION	CORROSION	WORN OUT	CORROSION	NONE
INVESTIGATION METHOD	VISUAL INSPECTION			MISSING	MISSING	NONE		NONE	
PHOTO NUMBERS	VISUAL INSPECTION	21-1		VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION
RECOMMENDATION	C	C		A		A	A	A	A
EXTERIOR EAST	COLUMN BEAM	⊙ WALL(BRICK)	⊙	DOOR	X WINDOW	METAL	EXTERIOR FINISH	X COPING	X CAULKING
EVALUATION ITEM	NORMAL	✓	✓	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL
	DAMAGE			RUSTY	RUSTY	RUSTY	DIRTY	RUSTY	BROKEN
	BROKEN			CORROSION	CORROSION	CORROSION	WORN OUT	CORROSION	NONE
INVESTIGATION METHOD	VISUAL INSPECTION			MISSING	MISSING	NONE		NONE	
PHOTO NUMBERS	VISUAL INSPECTION	21-1		VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION
RECOMMENDATION	C	C		A		A	A	A	A
EXTERIOR SOUTH	COLUMN BEAM	⊙ WALL(BRICK)	⊙	DOOR	X WINDOW	METAL	EXTERIOR FINISH	X COPING	X CAULKING
EVALUATION ITEM	NORMAL	✓	✓	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL
	DAMAGE			RUSTY	RUSTY	RUSTY	DIRTY	RUSTY	BROKEN
	BROKEN			CORROSION	CORROSION	CORROSION	WORN OUT	CORROSION	NONE
INVESTIGATION METHOD	VISUAL INSPECTION			MISSING	MISSING	NONE		NONE	
PHOTO NUMBERS	VISUAL INSPECTION	21-2		VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION
RECOMMENDATION	C	C		A		A	A	A	A
EXTERIOR WEST	COLUMN BEAM	⊙ WALL(BRICK)	⊙	DOOR	X WINDOW	METAL	EXTERIOR FINISH	X COPING	X CAULKING
EVALUATION ITEM	NORMAL	✓	✓	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL
	DAMAGE			RUSTY	RUSTY	RUSTY	DIRTY	RUSTY	BROKEN
	BROKEN			CORROSION	CORROSION	CORROSION	WORN OUT	CORROSION	NONE
INVESTIGATION METHOD	VISUAL INSPECTION			MISSING	MISSING	NONE		NONE	
PHOTO NUMBERS	VISUAL INSPECTION	21-2		VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION
RECOMMENDATION	C	C		A		A	A	A	A
EXTERIOR OTHERS									
EVALUATION ITEM									
INVESTIGATION METHOD									
PHOTO NUMBERS									
RECOMMENDATION									

RECOMMENDATION A-TOTAL REFURBISHMENT  
 B-PARTIAL REFURBISHMENT  
 C-NOT NECESSARY

⊙-GOOD  
 ⊕-AVERAGE  
 X-BAD

ELECTRIC ROOM	FLOOR	WALL	CEILING	METAL	STAIR	LIGHTING	VENTILATION	HEATING	WATER EQUIPMENT	FIRE EXTINGUISHER	OTHERS
PARTICULAR	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	SCARES OF THE FLOOD ON THE WALL
EVALUATION ITEM	DIRTY	DIRTY	DIRTY	RUSTY	DIRTY	RUSTY	CORROSION	BROKEN	BROKEN	CORROSION	
	SAG	SAG	SAG	CORROSION	UNEVEN	BROKEN	BROKEN	MISSING	MISSING	BROKEN	
	BROKEN	BROKEN	BROKEN	BROKEN	BROKEN	MISSING	MISSING			MISSING	
INVESTIGATION METHOD	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	
PHOTO NUMBERS											
RECOMMENDATION	A	A	A			A					
TRANSFORMER ROOM											
PARTICULAR	FLOOR	WALL	CEILING	METAL	STAIR	LIGHTING	VENTILATION	HEATING	WATER EQUIPMENT	FIRE EXTINGUISHER	OTHERS
EVALUATION ITEM	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	
	DIRTY	DIRTY	DIRTY	RUSTY	DIRTY	RUSTY	CORROSION	BROKEN	BROKEN	CORROSION	
	SAG	SAG	SAG	CORROSION	UNEVEN	BROKEN	BROKEN	MISSING	MISSING	BROKEN	
	BROKEN	BROKEN	BROKEN	BROKEN	BROKEN	MISSING	MISSING			MISSING	
INVESTIGATION METHOD	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	
PHOTO NUMBERS	21-10	21-10	21-10			21-10					
RECOMMENDATION	A	A	A			A					
PARTICULAR	FLOOR	WALL	CEILING	METAL	STAIR	LIGHTING	VENTILATION	HEATING	WATER EQUIPMENT	FIRE EXTINGUISHER	OTHERS
EVALUATION ITEM	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	
	DIRTY	DIRTY	DIRTY	RUSTY	DIRTY	RUSTY	CORROSION	BROKEN	BROKEN	CORROSION	
	SAG	SAG	SAG	CORROSION	UNEVEN	BROKEN	BROKEN	MISSING	MISSING	BROKEN	
	BROKEN	BROKEN	BROKEN	BROKEN	BROKEN	MISSING	MISSING			MISSING	
INVESTIGATION METHOD	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	
PHOTO NUMBERS											
RECOMMENDATION											

RECOMMENDATION A-TOTAL REFURBISHMENT  
B-PARTIAL REFURBISHMENT  
C-NOT NECESSARY

⊕-GOOD  
Δ-AVERAGE  
x-BAD

# BUILDING SURVEY PHOTO

BUILDING NUMBER	21	BUILDING NAME	SUBSTATION
-----------------	----	---------------	------------

PLAN AND DIRECTION FROM WHICH PHOTO WAS TAKEN





PHOTO NUMBER	21-1
--------------	------



# BUILDING SURVEY PHOTO

BUILDING NUMBER	21	BUILDING NAME	SUBSTATION
-----------------	----	---------------	------------

PHOTO NUMBER	21-2
--------------	------






PHOTO NUMBER	21-3
--------------	------



# BUILDING SURVEY PHOTO

BUILDING NUMBER	21	BUILDING NAME	SUBSTATION
PHOTO NUMBER	21-10		
			
PHOTO NUMBER	21-		

BUILDING SURVEY DETAILS

BUILDING NUMBER	BUILDING NAME	STRUCTURE	COMPLETION YEAR	BUILDING AREA	TOTAL FLOOR AREA	CONCRETE DESIGN COMPRESSIVE STRESS	CONCRETE ACTUAL COMPRESSIVE STRESS	RENEWAL DATA	OTHERS
22	RECEPTION	REINFORCED CONCRETE (COLUMN/BEAM), WALL BRICK		49.96m <sup>2</sup>	49.96m <sup>2</sup>	30NKG/cm <sup>2</sup>		REPAIRED	
EXTERIOR NORTH	COLUMN BEAM	WALL(BRICK)	⊙	DOOR	WINDOW	METAL	EXTERIOR FINISH	⊙	⊙
EVALUATION ITEM	NORMAL	NORMAL	✓	NORMAL	NORMAL	NORMAL	NORMAL	✓	✓
	DAMAGE	DAMAGE		RUSTY	RUSTY	RUSTY	DIRTY		
		BROKEN		CORROSION	CORROSION	CORROSION	WORN OUT		
		BULLET MARKS		MISSING	MISSING	NONE			
INVESTIGATION METHOD	VISUAL INSPECTION	VISUAL INSPECTION		VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION		
PHOTO NUMBERS	22-1	22-1		22-1	22-1	22-1	22-1	22-4	22-4
RECOMMENDATION	C	C		C	C	C	C	C	C
EXTERIOR EAST	COLUMN BEAM	WALL(BRICK)	⊙	DOOR	WINDOW	METAL	EXTERIOR FINISH	⊙	⊙
EVALUATION ITEM	NORMAL	NORMAL	✓	NORMAL	NORMAL	NORMAL	NORMAL	✓	✓
	DAMAGE	DAMAGE		RUSTY	RUSTY	RUSTY	DIRTY		
		BROKEN		CORROSION	CORROSION	CORROSION	WORN OUT		
		BULLET MARKS		MISSING	MISSING	NONE			
INVESTIGATION METHOD	VISUAL INSPECTION	VISUAL INSPECTION		VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION		
PHOTO NUMBERS	22-2	22-2		22-2	22-2	22-2	22-2	22-4	22-4
RECOMMENDATION	C	C		C	C	C	C	C	C
EXTERIOR SOUTH	COLUMN BEAM	WALL(BRICK)	⊙	DOOR	WINDOW	METAL	EXTERIOR FINISH	⊙	⊙
EVALUATION ITEM	NORMAL	NORMAL	✓	NORMAL	NORMAL	NORMAL	NORMAL	✓	✓
	DAMAGE	DAMAGE		RUSTY	RUSTY	RUSTY	DIRTY		
		BROKEN		CORROSION	CORROSION	CORROSION	WORN OUT		
		BULLET MARKS		MISSING	MISSING	NONE			
INVESTIGATION METHOD	VISUAL INSPECTION	VISUAL INSPECTION		VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION		
PHOTO NUMBERS	22-3	22-3		22-3	22-3	22-3	22-3	22-4	22-4
RECOMMENDATION	C	C		C	C	C	C	C	C
EXTERIOR WEST	COLUMN BEAM	WALL(BRICK)	⊙	DOOR	WINDOW	METAL	EXTERIOR FINISH	⊙	⊙
EVALUATION ITEM	NORMAL	NORMAL	✓	NORMAL	NORMAL	NORMAL	NORMAL	✓	✓
	DAMAGE	DAMAGE		RUSTY	RUSTY	RUSTY	DIRTY		
		BROKEN		CORROSION	CORROSION	CORROSION	WORN OUT		
		BULLET MARKS		MISSING	MISSING	NONE			
INVESTIGATION METHOD	VISUAL INSPECTION	VISUAL INSPECTION		VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION		
PHOTO NUMBERS	22-1	22-1		22-1	22-1	22-1	22-1	22-4	22-4
RECOMMENDATION	C	C		C	C	C	C	C	C

RECOMMENDATION A-TOTAL REFURBISHMENT  
 B-PARTIAL REFURBISHMENT  
 C-NOT NECESSARY

EVALUATION ⊙-GOOD  
 Δ-AVERAGE  
 X-BAD

BUILDING NUMBER-22 RECEPTION

RECEPTION	FLOOR	WALL	CEILING	METAL	STAIR	LIGHTING	VENTILATION	HEATING	WATER EQUIPMENT	FIRE EXTINGUISHER	OTHERS
PARTICULAR	NORMAL	⊙	⊙	⊙	NORMAL	NORMAL	⊙	NORMAL	NORMAL	NORMAL	⊙
EVALUATION ITEM	DIRTY	DIRTY	DIRTY	RUSTY	DIRTY	RUSTY	CORROSION	BROKEN	BROKEN	CORROSION	⊙
	SAG	SAG	SAG	CORROSION	UNEVEN	BROKEN	MISSING	MISSING	MISSING	BROKEN	⊙
	BROKEN	BROKEN	BROKEN	BROKEN	BROKEN	MISSING	MISSING	MISSING	MISSING	MISSING	⊙
INVESTIGATION METHOD	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	⊙
PHOTO NUMBERS		22-10									⊙
RECOMMENDATION	C	C	C			C		A		C	⊙
OFFICE											
PARTICULAR	FLOOR	⊙	⊙	⊙	STAIR	LIGHTING	⊙	HEATING	WATER EQUIPMENT	FIRE EXTINGUISHER	⊙
EVALUATION ITEM	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	⊙	NORMAL	NORMAL	NORMAL	⊙
	DIRTY	DIRTY	DIRTY	DIRTY	DIRTY	RUSTY	CORROSION	BROKEN	BROKEN	CORROSION	⊙
	SAG	SAG	SAG	CORROSION	UNEVEN	BROKEN	MISSING	MISSING	MISSING	BROKEN	⊙
	BROKEN	BROKEN	BROKEN	BROKEN	BROKEN	MISSING	MISSING	MISSING	MISSING	MISSING	⊙
INVESTIGATION METHOD	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	⊙
PHOTO NUMBERS		22-11									⊙
RECOMMENDATION	C	C	C			C		A		C	⊙
TOILET											
PARTICULAR	FLOOR	⊙	⊙	⊙	STAIR	LIGHTING	⊙	HEATING	WATER EQUIPMENT	FIRE EXTINGUISHER	⊙
EVALUATION ITEM	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	⊙	NORMAL	NORMAL	NORMAL	⊙
	DIRTY	DIRTY	DIRTY	RUSTY	DIRTY	RUSTY	CORROSION	BROKEN	BROKEN	CORROSION	⊙
	SAG	SAG	SAG	CORROSION	UNEVEN	BROKEN	MISSING	MISSING	MISSING	BROKEN	⊙
	BROKEN	BROKEN	BROKEN	BROKEN	BROKEN	MISSING	MISSING	MISSING	MISSING	MISSING	⊙
INVESTIGATION METHOD	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	⊙
PHOTO NUMBERS											⊙
RECOMMENDATION	C	C	C			C		A	C		⊙

EVALUATION ⊙-GOOD Δ-AVERAGE X-BAD  
 RECOMMENDATION A-TOTAL REFURBISHMENT B-PARTIAL REFURBISHMENT C-NOT NECESSARY

# BUILDING SURVEY PHOTO





PHOTO NUMBER 22-1





# BUILDING SURVEY PHOTO

BUILDING NUMBER	22	BUILDING NAME	RECEPTION
PHOTO NUMBER	22-2		




PHOTO NUMBER	22-3		
--------------	------	--	--



# BUILDING SURVEY PHOTO

BUILDING NUMBER	22	BUILDING NAME	RECEPTION
-----------------	----	---------------	-----------

PHOTO NUMBER	22-4
--------------	------





PHOTO NUMBER	22-10
--------------	-------



# BUILDING SURVEY PHOTO

BUILDING NUMBER	22	BUILDING NAME	RECEPTION
PHOTO NUMBER	22-11		
			
PHOTO NUMBER	22-		

BUILDING SURVEY DETAILS

BUILDING NUMBER	BUILDING NAME	STRUCTURE	COMPLETION YEAR	BUILDING AREA	TOTAL FLOOR AREA	CONCRETE DESIGN COMPRESSIVE STRESS	CONCRETE ACTUAL COMPRESSIVE STRESS	RENEWAL DATA	OTHERS
23-A	ADMINISTRATION BUILDING (A) BLOCK	REINFORCED CONCRETE (COLUMN-BEAM), WALL		892.68m <sup>2</sup>	1326.39m <sup>2</sup>	300KG/cm <sup>2</sup>	565KG/cm <sup>2</sup>		
EXTERIOR NORTH	COLUMN BEAM	⊙ WALL(BRICK)	⊙	⊙ DOOR	⊙ WINDOW	⊙ METAL	⊙ EXTERIOR FINISH	⊙ COPING	⊙ CAULKING
EVALUATION ITEM	NORMAL	NORMAL	✓	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL
	DAMAGE	DAMAGE		RUSTY	RUSTY	RUSTY	DIRTY	RUSTY	BROKEN
	BROKEN	BROKEN		CORROSION	CORROSION	CORROSION	WORN OUT	CORROSION	NONE
	BULLET MARKS	BULLET MARKS		MISSING	MISSING	NONE		NONE	
INVESTIGATION METHOD	VISUAL INSPECTION	VISUAL INSPECTION		VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION
PHOTO NUMBERS	23A-1,2	23A-1,2		23A-2	23A-1,2		23A-1,2		
RECOMMENDATION	C	C		C	A	C	A	C	C
EXTERIOR EAST	COLUMN BEAM	⊙ WALL(BRICK)	⊙	⊙ DOOR	⊙ WINDOW	⊙ METAL	⊙ EXTERIOR FINISH	⊙ COPING	⊙ CAULKING
EVALUATION ITEM	NORMAL	NORMAL	✓	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL
	DAMAGE	DAMAGE		RUSTY	RUSTY	RUSTY	DIRTY	RUSTY	BROKEN
	BROKEN	BROKEN		CORROSION	CORROSION	CORROSION	WORN OUT	CORROSION	NONE
	BULLET MARKS	BULLET MARKS		MISSING	MISSING	NONE		NONE	
INVESTIGATION METHOD	VISUAL INSPECTION	VISUAL INSPECTION		VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION
PHOTO NUMBERS	23A-3,4	23A-3,4		23A-3,4	23A-3,4		23A-3,4		
RECOMMENDATION	C	C		C	C	A	A	C	C
EXTERIOR SOUTH	COLUMN BEAM	⊙ WALL(BRICK)	⊙	⊙ DOOR	⊙ WINDOW	⊙ METAL	⊙ EXTERIOR FINISH	⊙ COPING	⊙ CAULKING
EVALUATION ITEM	NORMAL	NORMAL	✓	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL
	DAMAGE	DAMAGE		RUSTY	RUSTY	RUSTY	DIRTY	RUSTY	BROKEN
	BROKEN	BROKEN		CORROSION	CORROSION	CORROSION	WORN OUT	CORROSION	NONE
	BULLET MARKS	BULLET MARKS		MISSING	MISSING	NONE		NONE	
INVESTIGATION METHOD	VISUAL INSPECTION	VISUAL INSPECTION		VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION
PHOTO NUMBERS	23A-1	23A-1				23A-8			
RECOMMENDATION	C	C		C	C	C	A	C	C
EXTERIOR WEST	COLUMN BEAM	⊙ WALL(BRICK)	⊙	⊙ DOOR	⊙ WINDOW	⊙ METAL	⊙ EXTERIOR FINISH	⊙ COPING	⊙ CAULKING
EVALUATION ITEM	NORMAL	NORMAL	✓	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL
	DAMAGE	DAMAGE		RUSTY	RUSTY	RUSTY	DIRTY	RUSTY	BROKEN
	BROKEN	BROKEN		CORROSION	CORROSION	CORROSION	WORN OUT	CORROSION	NONE
	BULLET MARKS	BULLET MARKS		MISSING	MISSING	NONE		NONE	
INVESTIGATION METHOD	VISUAL INSPECTION	VISUAL INSPECTION		VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION
PHOTO NUMBERS	23A-5,6	23A-5,6		23A-5,6	23A-5,6		23A-5,6		
RECOMMENDATION	C	C		C	C	A	A	C	C

RECOMMENDATION A-TOTAL REFURBISHMENT  
 B-PARTIAL REFURBISHMENT  
 C-NOT NECESSARY

⊙-GOOD  
 △-AVERAGE  
 x-BAD

BUILDING ADMINISTRATION BUILDING  
NUMBER-23A (A)BLOCK

1-HALL	FLOOR	WALL	CEILING	METAL	STAIR	LIGHTING	VENTILATION	HEATING	WATER EQUIPMENT	FIRE EXTINGUISHER	OTHERS
PARTICULAR	⊙	⊙	⊙	⊙	⊙	⊙	⊙	⊙	⊙	⊙	⊙
EVALUATION ITEM	NORMAL	DIRTY	DIRTY	RUSTY	DIRTY	RUSTY	CORROSION	BROKEN	BROKEN	CORROSION	*NO HANDRAILS IN STAIRS.
INVESTIGATION METHOD	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	
PHOTO NUMBERS	23A-10.11	23A-10.11	23A-10.11			23A-10.11					
RECOMMENDATION	C	C	C		B	C		A		A	
2-OFFICE FOR ECONOMIC											
PARTICULAR	⊙	⊙	⊙	⊙	⊙	⊙	⊙	⊙	⊙	⊙	⊙
EVALUATION ITEM	FLOOR	WALL	CEILING	METAL	STAIR	LIGHTING	VENTILATION	HEATING	WATER EQUIPMENT	FIRE EXTINGUISHER	OTHERS
INVESTIGATION METHOD	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	
PHOTO NUMBERS	DIRTY	DIRTY	DIRTY	RUSTY	DIRTY	RUSTY	CORROSION	BROKEN	BROKEN	CORROSION	
RECOMMENDATION	SAG	SAG	SAG	CORROSION	UNEVEN	BROKEN	MISSING	MISSING	MISSING	BROKEN	
INVESTIGATION METHOD	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	
PHOTO NUMBERS											
RECOMMENDATION	A	A	A			A		A			
3-CONFERENCE ROOM (LARGE)											
PARTICULAR	⊙	⊙	⊙	⊙	⊙	⊙	⊙	⊙	⊙	⊙	⊙
EVALUATION ITEM	FLOOR	WALL	CEILING	METAL	STAIR	LIGHTING	VENTILATION	HEATING	WATER EQUIPMENT	FIRE EXTINGUISHER	OTHERS
INVESTIGATION METHOD	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	
PHOTO NUMBERS	DIRTY	DIRTY	DIRTY	RUSTY	DIRTY	RUSTY	CORROSION	BROKEN	BROKEN	CORROSION	
RECOMMENDATION	SAG	SAG	SAG	CORROSION	UNEVEN	BROKEN	MISSING	MISSING	MISSING	BROKEN	
INVESTIGATION METHOD	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	
PHOTO NUMBERS	23A-12	23A-12	23A-12			23A-12		23A-12			
RECOMMENDATION	C	C	C			A		A		A	

⊙-GOOD  
Δ-AVERAGE  
x-BAD

RECOMMENDATION A-TOTAL REFURBISHMENT  
B-PARTIAL REFURBISHMENT  
C-NOT NECESSARY

BUILDING NUMBER-23A ADMINISTRATION BUILDING A-BLOCK

4-CONFERENCE ROOM(S)WALL	FLOOR	WALL	CEILING	METAL	STAIR	LIGHTING	VENTILATION	HEATING	WATER EQUIPMENT	FIRE EXTINGUISHER	OTHERS
	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	*NO SLIDING WALL IN A SPACE BETWEEN THE HALL
EVALUATION ITEM	DIRTY	DIRTY	DIRTY	RUSTY	DIRTY	RUSTY	CORROSION	BROKEN	BROKEN	CORROSION	
	SAG	SAG	SAG	CORROSION	UNEVEN	BROKEN	BROKEN	MISSING	MISSING	BROKEN	
	BROKEN	BROKEN	BROKEN	BROKEN	BROKEN	MISSING	MISSING			MISSING	
INVESTIGATION METHOD	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	
PHOTO NUMBERS	23A-13	23A-13	23A-13			23A-13					23A-13
RECOMMENDATION	C	A	C			A		A		A	
5-LIBRARY											
PARTICULAR	FLOOR	WALL	CEILING	METAL	STAIR	LIGHTING	VENTILATION	HEATING	WATER EQUIPMENT	FIRE EXTINGUISHER	OTHERS
	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	
EVALUATION ITEM	DIRTY	DIRTY	DIRTY	RUSTY	DIRTY	RUSTY	CORROSION	BROKEN	BROKEN	CORROSION	
	SAG	SAG	SAG	CORROSION	UNEVEN	BROKEN	BROKEN	MISSING	MISSING	BROKEN	
	BROKEN	BROKEN	BROKEN	BROKEN	BROKEN	MISSING	MISSING			MISSING	
INVESTIGATION METHOD	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	
PHOTO NUMBERS											
RECOMMENDATION	C	C	C			C		A			
6-TOILET											
PARTICULAR	FLOOR	WALL	CEILING	METAL	STAIR	LIGHTING	VENTILATION	HEATING	WATER EQUIPMENT	FIRE EXTINGUISHER	OTHERS
	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	
EVALUATION ITEM	DIRTY	DIRTY	DIRTY	RUSTY	DIRTY	RUSTY	CORROSION	BROKEN	BROKEN	CORROSION	
	SAG	SAG	SAG	CORROSION	UNEVEN	BROKEN	BROKEN	MISSING	MISSING	BROKEN	
	BROKEN	BROKEN	BROKEN	BROKEN	BROKEN	MISSING	MISSING			MISSING	
INVESTIGATION METHOD	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	
PHOTO NUMBERS	23A-14	23A-14							23A-14		
RECOMMENDATION	A	A	A			A		A	A		

EVALUATION  
 @-GOOD  
 Δ-AVERAGE  
 X-BAD  
 RECOMMENDATION A-TOTAL REFURBISHMENT  
 B-PARTIAL REFURBISHMENT  
 C-NOT NECESSARY

BUILDING NUMBER-23A ADMINISTRATION BUILDING A-BLOCK

7-TELEPHONE	FLOOR	WALL	CEILING	METAL	STAIR	LIGHTING	VENTILATION	HEATING	FIRE EXTINGUISHER	OTHERS
PARTICULAR	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	
EVALUATION ITEM	DIRTY	DIRTY	DIRTY	RUSTY	DIRTY	RUSTY	CORROSION	BROKEN	CORROSION	
	SAG	SAG	SAG	CORROSION	UNEVEN	BROKEN	BROKEN	MISSING	BROKEN	
	BROKEN	BROKEN	BROKEN	BROKEN	BROKEN	MISSING	MISSING		MISSING	
INVESTIGATION METHOD	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	
PHOTO NUMBERS										
RECOMMENDATION	A	A	A			A		A		
8-PUBLIC OFFICE										
PARTICULAR	FLOOR	WALL	CEILING	METAL	STAIR	LIGHTING	VENTILATION	HEATING	WATER EQUIPMENT	OTHERS
EVALUATION ITEM	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	
	DIRTY	DIRTY	DIRTY	RUSTY	DIRTY	RUSTY	CORROSION	BROKEN	CORROSION	
	SAG	SAG	SAG	CORROSION	UNEVEN	BROKEN	BROKEN	MISSING	BROKEN	
	BROKEN	BROKEN	BROKEN	BROKEN	BROKEN	MISSING	MISSING		MISSING	
INVESTIGATION METHOD	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	
PHOTO NUMBERS										
RECOMMENDATION	C	A	C			C		A		
9-DINING ROOM										
PARTICULAR	FLOOR	WALL	CEILING	METAL	STAIR	LIGHTING	VENTILATION	HEATING	WATER EQUIPMENT	OTHERS
EVALUATION ITEM	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	
	DIRTY	DIRTY	DIRTY	RUSTY	DIRTY	RUSTY	CORROSION	BROKEN	CORROSION	
	SAG	SAG	SAG	CORROSION	UNEVEN	BROKEN	BROKEN	MISSING	BROKEN	
	BROKEN	BROKEN	BROKEN	BROKEN	BROKEN	MISSING	MISSING		MISSING	
INVESTIGATION METHOD	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	
PHOTO NUMBERS	23A-15	23A-15	23A-15	23A-15	23A-15	23A-15	23A-15	23A-15	23A-15	
RECOMMENDATION	C	C	C			C		A		

EVALUATION  
 @-GOOD  
 Δ-AVERAGE  
 x-BAD  
 RECOMMENDATION A-TOTAL REFURBISHMENT  
 B-PARTIAL REFURBISHMENT  
 C-NOT NECESSARY

BUILDING NUMBER-23A

ADMINISTRATION BUILDING  
A-BLOCK

10-STORAGE	FLOOR	x	WALL	x	CEILING	x	METAL	STAIR	LIGHTING	x	VENTILATION	HEATING	x	WATER EQUIPMENT	FIRE EXTINGUISHER	OTHERS
PARTICULAR	NORMAL		NORMAL		NORMAL		NORMAL	NORMAL	NORMAL		NORMAL	NORMAL		NORMAL	NORMAL	
EVALUATION ITEM	DIRTY	✓	DIRTY	✓	DIRTY	✓	DIRTY	DIRTY	RUSTY	✓	CORROSION	BROKEN	✓	BROKEN	CORROSION	
	SAG		SAG		SAG		UNEVEN	UNEVEN	BROKEN		BROKEN	MISSING		MISSING	BROKEN	
	BROKEN		BROKEN		BROKEN		BROKEN	BROKEN	MISSING		MISSING				MISSING	
INVESTIGATION METHOD	VISUAL INSPECTION		VISUAL INSPECTION		VISUAL INSPECTION		VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION		VISUAL INSPECTION	VISUAL INSPECTION		VISUAL INSPECTION	VISUAL INSPECTION	
PHOTO NUMBERS																
RECOMMENDATION	A		A		A				A			A				
11-LOCKER ROOM																
PARTICULAR	FLOOR	⊙	WALL	⊙	CEILING	⊙	METAL	STAIR	LIGHTING	Δ	VENTILATION	HEATING	x	WATER EQUIPMENT	FIRE EXTINGUISHER	OTHERS
	NORMAL		NORMAL	✓	NORMAL	✓	NORMAL	NORMAL	NORMAL		NORMAL	NORMAL		NORMAL	NORMAL	
EVALUATION ITEM	DIRTY		DIRTY		DIRTY		RUSTY	DIRTY	RUSTY	✓	CORROSION	BROKEN		BROKEN	CORROSION	
	SAG		SAG		SAG		CORROSION	UNEVEN	BROKEN		BROKEN	MISSING	✓	MISSING	BROKEN	
	BROKEN		BROKEN		BROKEN		BROKEN	BROKEN	MISSING		MISSING				MISSING	
INVESTIGATION METHOD	VISUAL INSPECTION		VISUAL INSPECTION		VISUAL INSPECTION		VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION		VISUAL INSPECTION	VISUAL INSPECTION		VISUAL INSPECTION	VISUAL INSPECTION	
PHOTO NUMBERS																
RECOMMENDATION	C		C		C				B			A				
12-KITCHIN																
PARTICULAR	FLOOR	⊙	WALL	⊙	CEILING	⊙	METAL	STAIR	LIGHTING	Δ	VENTILATION	HEATING	x	WATER EQUIPMENT	FIRE EXTINGUISHER	OTHERS
	NORMAL		NORMAL	✓	NORMAL	✓	NORMAL	NORMAL	NORMAL		NORMAL	NORMAL		NORMAL	NORMAL	
EVALUATION ITEM	DIRTY		DIRTY		DIRTY		RUSTY	DIRTY	RUSTY	✓	CORROSION	BROKEN		BROKEN	CORROSION	
	SAG		SAG		SAG		CORROSION	UNEVEN	BROKEN		BROKEN	MISSING	✓	MISSING	BROKEN	
	BROKEN		BROKEN		BROKEN		BROKEN	BROKEN	MISSING		MISSING				MISSING	
INVESTIGATION METHOD	VISUAL INSPECTION		VISUAL INSPECTION		VISUAL INSPECTION		VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION		VISUAL INSPECTION	VISUAL INSPECTION		VISUAL INSPECTION	VISUAL INSPECTION	
PHOTO NUMBERS	23A-16		23A-16		23A-16											
RECOMMENDATION	C		C		C				B			A				

RECOMMENDATION A-TOTAL REFURBISHMENT  
B-PARTIAL REFURBISHMENT  
C-NOT NECESSARY

EVALUATION ⊙-GOOD  
Δ-AVERAGE  
x-BAD



BUILDING NUMBER-23A ADMINISTRATION BUILDING A-BLOCK

13-CONTROL ROOM		FLOOR		WALL		CEILING		METAL		STAIR		LIGHTING		VENTILATION		HEATING		WATER EQUIPMENT		FIRE EXTINGUISHER		OTHERS			
PARTICULAR	EVALUATION ITEM	NORMAL	DIRTY	NORMAL	DIRTY	NORMAL	DIRTY	NORMAL	RUSTY	NORMAL	DIRTY	NORMAL	RUSTY	NORMAL	CORROSION	BROKEN	MISSING	NORMAL	BROKEN	MISSING	NORMAL	CORROSION	BROKEN	MISSING	
		VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION
PHOTO NUMBERS				23A-17;18				23A-17				23A-17													
RECOMMENDATION	A	A	A	A	A	A	A	A	A	A	A	A	A	A	A	A	A	A	A	A	A	A	A	A	
14-OFFICE(1)																									
PARTICULAR	EVALUATION ITEM	NORMAL	DIRTY	NORMAL	DIRTY	NORMAL	DIRTY	NORMAL	RUSTY	NORMAL	DIRTY	NORMAL	RUSTY	NORMAL	CORROSION	BROKEN	MISSING	NORMAL	BROKEN	MISSING	NORMAL	CORROSION	BROKEN	MISSING	
		VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION
PHOTO NUMBERS																									
RECOMMENDATION	C	C	C	C	C	C	C	C	C	C	C	C	C	C	C	C	C	C	C	C	C	C	C	C	
15-OFFICE(2)																									
PARTICULAR	EVALUATION ITEM	NORMAL	DIRTY	NORMAL	DIRTY	NORMAL	DIRTY	NORMAL	RUSTY	NORMAL	DIRTY	NORMAL	RUSTY	NORMAL	CORROSION	BROKEN	MISSING	NORMAL	BROKEN	MISSING	NORMAL	CORROSION	BROKEN	MISSING	
		VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION
PHOTO NUMBERS																									
RECOMMENDATION	C	C	C	C	C	C	C	C	C	C	C	C	C	C	C	C	C	C	C	C	C	C	C	C	
EVALUATION																									

RECOMMENDATION A-TOTAL REFURBISHMENT  
B-PARTIAL REFURBISHMENT  
C-NOT NECESSARY

⊙-GOOD  
Δ-AVERAGE  
x-BAD

BUILDING NUMBER-23A

ADMINISTRATION BUILDING  
A-BLOCK

16-OFFICE(3)	FLOOR	WALL	CEILING	METAL	STAIR	LIGHTING	VENTILATION	HEATING	WATER EQUIPMENT	FIRE EXTINGUISHER	OTHERS
PARTICULAR	NORMAL	⊙	⊙	⊙	NORMAL	NORMAL	⊙	NORMAL	NORMAL	NORMAL	
EVALUATION ITEM	DIRTY	DIRTY	DIRTY	RUSTY	DIRTY	RUSTY	CORROSION	BROKEN	BROKEN	CORROSION	
	SAG	SAG	SAG	BROKEN	UNEVEN	BROKEN	BROKEN	MISSING	MISSING	BROKEN	
	BROKEN	BROKEN	BROKEN	BROKEN	BROKEN	MISSING	MISSING			MISSING	
INVESTIGATION METHOD	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	MISSING	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	
PHOTO NUMBERS											
RECOMMENDATION	C	C	C					A			
17-OFFICE(4)											
PARTICULAR	FLOOR	WALL	CEILING	⊙	STAIR	LIGHTING	VENTILATION	HEATING	WATER EQUIPMENT	FIRE EXTINGUISHER	OTHERS
EVALUATION ITEM	NORMAL	⊙	⊙	⊙	NORMAL	NORMAL	⊙	NORMAL	NORMAL	NORMAL	
	DIRTY	DIRTY	DIRTY	RUSTY	DIRTY	RUSTY	CORROSION	BROKEN	BROKEN	CORROSION	
	SAG	SAG	SAG	CORROSION	UNEVEN	BROKEN	BROKEN	MISSING	MISSING	BROKEN	
	BROKEN	BROKEN	BROKEN	BROKEN	BROKEN	MISSING	MISSING			MISSING	
INVESTIGATION METHOD	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	MISSING	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	
PHOTO NUMBERS											
RECOMMENDATION	C	C	C			C		A			
18-GALLERY											
PARTICULAR	FLOOR	WALL	CEILING	⊙	STAIR	LIGHTING	VENTILATION	HEATING	WATER EQUIPMENT	FIRE EXTINGUISHER	OTHERS
EVALUATION ITEM	NORMAL	⊙	⊙	⊙	NORMAL	NORMAL	⊙	NORMAL	NORMAL	NORMAL	
	DIRTY	DIRTY	DIRTY	RUSTY	DIRTY	RUSTY	CORROSION	BROKEN	BROKEN	CORROSION	
	SAG	SAG	SAG	CORROSION	UNEVEN	BROKEN	BROKEN	MISSING	MISSING	BROKEN	
	BROKEN	BROKEN	BROKEN	BROKEN	BROKEN	MISSING	MISSING			MISSING	
INVESTIGATION METHOD	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	MISSING	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	
PHOTO NUMBERS	23A-11	23A-11	23A-11			23A-11					
RECOMMENDATION	C	C	C			C		A		A	

RECOMMENDATION A-TOTAL REFURBISHMENT  
B-PARTIAL REFURBISHMENT  
C-NOT NECESSARY

⊙-GOOD  
Δ-AVERAGE  
x-BAD

BUILDING NUMBER-23A ADMINISTRATION BUILDING A-BLOCK

19-OFFICE(5)	FLOOR	WALL	CEILING	METAL	STAIR	LIGHTING	VENTILATION	HEATING	WATER EQUIPMENT	FIRE EXTINGUISHER	OTHERS
	NORMAL	⊙	⊙	⊙	NORMAL	NORMAL	⊙	NORMAL	NORMAL	NORMAL	
	DIRTY	✓	✓	✓	DIRTY	RUSTY	✓	BROKEN	BROKEN	CORROSION	
	SAG		SAG	BROKEN	UNEVEN	BROKEN	BROKEN	MISSING	MISSING	BROKEN	
	BROKEN		BROKEN	BROKEN	BROKEN	MISSING	MISSING			MISSING	
	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	MISSING	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	
PHOTO NUMBERS											
RECOMMENDATION	C	C	C			C		A			
20-OFFICE(6)											
	FLOOR	⊙	⊙	⊙	STAIR	LIGHTING	⊙	HEATING	WATER EQUIPMENT	FIRE EXTINGUISHER	OTHERS
	NORMAL	✓	✓	✓	NORMAL	NORMAL	✓	NORMAL	NORMAL	NORMAL	
	DIRTY		DIRTY	RUSTY	DIRTY	RUSTY	✓	BROKEN	BROKEN	CORROSION	
	SAG		SAG	CORROSION	UNEVEN	BROKEN	MISSING	MISSING	MISSING	BROKEN	
	BROKEN		BROKEN	BROKEN	BROKEN	MISSING	MISSING			MISSING	
	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	MISSING	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	
PHOTO NUMBERS											
RECOMMENDATION	C	C	C			C		A			
21-OFFICE(7)											
	FLOOR	⊙	⊙	⊙	STAIR	LIGHTING	⊙	HEATING	WATER EQUIPMENT	FIRE EXTINGUISHER	OTHERS
	NORMAL	✓	✓	✓	NORMAL	NORMAL	✓	NORMAL	NORMAL	NORMAL	
	DIRTY		DIRTY	RUSTY	DIRTY	RUSTY	✓	BROKEN	BROKEN	CORROSION	
	SAG		SAG	CORROSION	UNEVEN	BROKEN	MISSING	MISSING	MISSING	BROKEN	
	BROKEN		BROKEN	BROKEN	BROKEN	MISSING	MISSING			MISSING	
	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	MISSING	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	
PHOTO NUMBERS											
RECOMMENDATION	C	C	C			C		A			

EVALUATION ⊙-GOOD Δ-AVERAGE x-BAD  
 RECOMMENDATION A-TOTAL REFURBISHMENT B-PARTIAL REFURBISHMENT C-NOT NECESSARY

BUILDING NUMBER-23A  
ADMINISTRATION BUILDING  
A-BLOCK

22-MEETING ROOM	FLOOR	WALL	CEILING	METAL	STAIR	LIGHTING	VENTILATION	HEATING	WATER EQUIPMENT	FIRE EXTINGUISHER	OTHERS
PARTICULAR	NORMAL	⊙	⊙	⊙	NORMAL	NORMAL	⊙	NORMAL	NORMAL	NORMAL	
EVALUATION ITEM	DIRTY	DIRTY	DIRTY	RUSTY	DIRTY	RUSTY	CORROSION	BROKEN	BROKEN	CORROSION	
	SAG	SAG	SAG	CORROSION	UNEVEN	BROKEN	BROKEN	MISSING	MISSING	BROKEN	
	BROKEN	BROKEN	BROKEN	BROKEN	BROKEN	MISSING	MISSING			MISSING	
				MISSING							
INVESTIGATION METHOD	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	
PHOTO NUMBERS	23A-19	23A-19	23A-19	23A-19	23A-19	23A-19					
RECOMMENDATION	C	C	C			C		A			
23-TOILET											
PARTICULAR	FLOOR	⊙	⊙	⊙	STAIR	LIGHTING	VENTILATION	HEATING	WATER EQUIPMENT	⊙	FIRE EXTINGUISHER
EVALUATION ITEM	NORMAL	⊙	⊙	⊙	NORMAL	NORMAL	⊙	NORMAL	NORMAL	⊙	NORMAL
	DIRTY	DIRTY	DIRTY	RUSTY	DIRTY	RUSTY	CORROSION	BROKEN	BROKEN	⊙	CORROSION
	SAG	SAG	SAG	CORROSION	UNEVEN	BROKEN	BROKEN	MISSING	MISSING	⊙	BROKEN
	BROKEN	BROKEN	BROKEN	BROKEN	BROKEN	MISSING	MISSING			⊙	MISSING
INVESTIGATION METHOD	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION
PHOTO NUMBERS	23A-20	23A-20	23A-20	23A-20	23A-20	23A-20			23A-20		
RECOMMENDATION	C	C	C			C		A	C		
24-CENTRAL LABORATORY											
PARTICULAR	FLOOR	△	⊙	⊙	STAIR	LIGHTING	VENTILATION	HEATING	WATER EQUIPMENT	⊙	FIRE EXTINGUISHER
EVALUATION ITEM	NORMAL	⊙	⊙	⊙	NORMAL	NORMAL	⊙	NORMAL	NORMAL	⊙	NORMAL
	DIRTY	DIRTY	DIRTY	RUSTY	DIRTY	RUSTY	CORROSION	BROKEN	BROKEN	⊙	CORROSION
	SAG	SAG	SAG	CORROSION	UNEVEN	BROKEN	BROKEN	MISSING	MISSING	⊙	BROKEN
	BROKEN	BROKEN	BROKEN	BROKEN	BROKEN	MISSING	MISSING			⊙	MISSING
INVESTIGATION METHOD	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION
PHOTO NUMBERS	23-A21	23-A21	23-A21	23-A21	23-A21	23-A21					
RECOMMENDATION	B	C	C			C		A			

RECOMMENDATION A-TOTAL REFURBISHMENT  
B-PARTIAL REFURBISHMENT  
C-NOT NECESSARY

BUILDING NUMBER-23A ADMINISTRATION BUILDING A-BLOCK

25-LABORATORY(1)	FLOOR	WALL	CEILING	METAL	STAIR	LIGHTING	VENTILATION	HEATING	WATER EQUIPMENT	FIRE EXTINGUISHER	OTHERS
PARTICULAR	⊙	⊙	⊙	⊙	⊙	⊙	⊙	⊙	⊙	⊙	
EVALUATION ITEM	NORMAL	DIRTY	DIRTY	RUSTY	DIRTY	RUSTY	CORROSION	BROKEN	BROKEN	CORROSION	
	SAG	SAG	SAG	BROKEN	UNEVEN	BROKEN	MISSING		MISSING	BROKEN	
	BROKEN			MISSING	BROKEN	MISSING				MISSING	
INVESTIGATION METHOD	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	
PHOTO NUMBERS	23A-22	23A-22	23A-22			23A-22					
RECOMMENDATION	C	C	C			C		A	C		
26-LABORATORY(2)											
PARTICULAR	⊙	⊙	⊙	⊙	⊙	⊙	⊙	⊙	⊙	⊙	
EVALUATION ITEM	FLOOR	WALL	CEILING	METAL	STAIR	LIGHTING	VENTILATION	HEATING	WATER EQUIPMENT	FIRE EXTINGUISHER	OTHERS
	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	
	DIRTY	DIRTY	DIRTY	RUSTY	DIRTY	RUSTY	CORROSION	BROKEN	BROKEN	CORROSION	
	SAG	SAG	SAG	CORROSION	UNEVEN	BROKEN	MISSING		MISSING	BROKEN	
	BROKEN			BROKEN	BROKEN	MISSING				MISSING	
INVESTIGATION METHOD	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	
PHOTO NUMBERS											
RECOMMENDATION	C	C	C			C		A	C		
27-PREPARING ROOM											
PARTICULAR	⊙	⊙	⊙	⊙	⊙	⊙	⊙	⊙	⊙	⊙	
EVALUATION ITEM	FLOOR	WALL	CEILING	METAL	STAIR	LIGHTING	VENTILATION	HEATING	WATER EQUIPMENT	FIRE EXTINGUISHER	OTHERS
	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	
	DIRTY	DIRTY	DIRTY	RUSTY	DIRTY	RUSTY	CORROSION	BROKEN	BROKEN	CORROSION	
	SAG	SAG	SAG	CORROSION	UNEVEN	BROKEN	MISSING		MISSING	BROKEN	
	BROKEN			BROKEN	BROKEN	MISSING				MISSING	
INVESTIGATION METHOD	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	
PHOTO NUMBERS											
RECOMMENDATION	C	C	C			C		A	C		

RECOMMENDATION A-TOTAL REFURBISHMENT  
 B-PARTIAL REFURBISHMENT  
 C-NOT NECESSARY

⊙-GOOD  
 Δ-AVERAGE  
 x-BAD

BUILDING NUMBER-23A

ADMINISTRATION BUILDING

A-BLOCK

28-THERMOSTAT AREA	FLOOR	WALL	CEILING	METAL	STAIR	LIGHTING	VENTILATION	HEATING	WATER EQUIPMENT	FIRE EXTINGUISHER	OTHERS
PARTICULAR	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	
EVALUATION ITEM	DIRTY	DIRTY	DIRTY	RUSTY	DIRTY	RUSTY	CORROSION	BROKEN	BROKEN	CORROSION	
	SAG	SAG	SAG	CORROSION	UNEVEN	BROKEN	BROKEN	MISSING	MISSING	BROKEN	
	BROKEN	BROKEN	BROKEN	BROKEN	BROKEN	MISSING	MISSING			MISSING	
INVESTIGATION METHOD	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	
PHOTO NUMBERS											
RECOMMENDATION	C	C	C			C		A			
29-MICROBIOLOGIC											
PARTICULAR	FLOOR	WALL	CEILING	METAL	STAIR	LIGHTING	VENTILATION	HEATING	WATER EQUIPMENT	FIRE EXTINGUISHER	OTHERS
EVALUATION ITEM	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	
	DIRTY	DIRTY	DIRTY	RUSTY	DIRTY	RUSTY	CORROSION	BROKEN	BROKEN	CORROSION	
	SAG	SAG	SAG	CORROSION	UNEVEN	BROKEN	BROKEN	MISSING	MISSING	BROKEN	
	BROKEN	BROKEN	BROKEN	BROKEN	BROKEN	MISSING	MISSING			MISSING	
INVESTIGATION METHOD	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	
PHOTO NUMBERS	23A-23	23A-23							23A-23		
RECOMMENDATION	C	C	C			C		A	C		
PARTICULAR	FLOOR	WALL	CEILING	METAL	STAIR	LIGHTING	VENTILATION	HEATING	WATER EQUIPMENT	FIRE EXTINGUISHER	OTHERS
EVALUATION ITEM	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	NORMAL	
	DIRTY	DIRTY	DIRTY	RUSTY	DIRTY	RUSTY	CORROSION	BROKEN	BROKEN	CORROSION	
	SAG	SAG	SAG	CORROSION	UNEVEN	BROKEN	BROKEN	MISSING	MISSING	BROKEN	
	BROKEN	BROKEN	BROKEN	BROKEN	BROKEN	MISSING	MISSING			MISSING	
INVESTIGATION METHOD	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	VISUAL INSPECTION	
PHOTO NUMBERS											
RECOMMENDATION											

EVALUATION  
 ⊕-GOOD  
 △-AVERAGE  
 x-BAD  
 RECOMMENDATION A-TOTAL REFURBISHMENT  
 B-PARTIAL REFURBISHMENT  
 C-NOT NECESSARY

# BUILDING SURVEY PHOTO

BUILDING NUMBER	23A	BUILDING NAME	ADMINISTRATION
-----------------	-----	---------------	----------------

## PLAN AND DIRECTION FROM WHICH PHOTO WAS TAKEN





PHOTO NUMBER	23A-1
--------------	-------




# BUILDING SURVEY PHOTO

BUILDING NUMBER	23A	BUILDING NAME	ADMINISTRATION
-----------------	-----	---------------	----------------

PHOTO NUMBER	23A-2
--------------	-------



PHOTO NUMBER	23A-3
--------------	-------





# BUILDING SURVEY PHOTO

BUILDING NUMBER	23A	BUILDING NAME	ADMINISTRATION
PHOTO NUMBER	23A-4		




PHOTO NUMBER 23A-5



# BUILDING SURVEY PHOTO

BUILDING NUMBER	23A	BUILDING NAME	ADMINISTRATION
PHOTO NUMBER	23A-6		




PHOTO NUMBER	23A-10		
--------------	--------	--	--



**BUILDING SURVEY PHOTO**

BUILDING NUMBER	23A	BUILDING NAME	ADMINISTRATION
-----------------	-----	---------------	----------------

PHOTO NUMBER	23A-11
--------------	--------





PHOTO NUMBER	23A-12
--------------	--------



**BUILDING SURVEY PHOTO**

BUILDING NUMBER	23A	BUILDING NAME	ADMINISTRATION
-----------------	-----	---------------	----------------

PHOTO NUMBER	23A-13
--------------	--------




PHOTO NUMBER	23A-14
--------------	--------



**BUILDING SURVEY PHOTO**

BUILDING NUMBER	23A	BUILDING NAME	ADMINISTRATION
-----------------	-----	---------------	----------------

PHOTO NUMBER	23A-15
--------------	--------






PHOTO NUMBER	23A-16
--------------	--------



# BUILDING SURVEY PHOTO


BUILDING NUMBER	23A	BUILDING NAME	ADMINISTRATION
-----------------	-----	---------------	----------------

PLAN AND DIRECTION FROM WHICH PHOTO WAS TAKEN





2ND FLOOR  
 A=802.68M<sup>2</sup>

PHOTO NUMBER 23A-17



# BUILDING SURVEY PHOTO

BUILDING NUMBER	23A	BUILDING NAME	ADMINISTRATION
PHOTO NUMBER	23A-18		
			
PHOTO NUMBER	23A-19		
			


# BUILDING SURVEY PHOTO

BUILDING NUMBER	23A	BUILDING NAME	ADMINISTRATION
-----------------	-----	---------------	----------------

PHOTO NUMBER	23A-20
--------------	--------




PHOTO NUMBER	23A-21
--------------	--------





# BUILDING SURVEY PHOTO

BUILDING NUMBER	23A	BUILDING NAME	ADMINISTRATION
PHOTO NUMBER	23A-22		
			
PHOTO NUMBER	23A-23		
