




Retention Ponds in Sungai Petani No. 7

| | | | |
|----------------------------------|---|----------------------|--------|
| Name of Development | Taman Sutera | | |
| Developed Area | 9.9 ha | Year of Construction | |
| Area of Pond | 840 m ² | Depth of Pond | 2.5 m |
| Storage Capacity | 1,600 m ³ | Catchment Area | 9.9 ha |
| Additional Function | Oxidation for Domestic Wastewater | | |
| Drainage System | Sg. Petani | | |
| Outlet Structure and Maintenance | <ul style="list-style-type: none"> •difficult to measure the structure due to being submerged in impounding water (plugged with sludge or rubbish) | | |
| Environmental Condition | <ul style="list-style-type: none"> •growth of kangkung, floating rubbish and offensive odor | | |
| Overview of Pond |  | | |
| Outlet Structure | <p>(difficult to find out the structure)</p> | | |



Retention Ponds in Sungai Petani No. 8

| | | | |
|----------------------------------|---|----------------------|---------|
| Name of Development | Taman Arked | | |
| Developed Area | 45.0 ha | Year of Construction | |
| Area of Pond | 3,450 m ² | Depth of Pond | 2.5 m |
| Storage Capacity | 6,560 m ³ | Catchment Area | 29.9 ha |
| Additional Function | Oxidation | | |
| Drainage System | Sg. Bakar Arang, Sg. Petani | | |
| Outlet Structure and Maintenance | <ul style="list-style-type: none"> •difficult to enter and measure due to thick growth of weeds •poor maintenance (weeding work is necessary) | | |
| Environmental Condition | <ul style="list-style-type: none"> •difficult to enter and evaluate due to thick growth of weeds | | |
| Overview of Pond |  | | |
| Outlet Structure | | | |



Taman Arked

