

CHANNEL CONDITION (1/2)



PHOTO - 13

The **Manamo Gate** at 188 km upstream, constructed in 1960's for flood control and agricultural development in Tucupita area.

PHOTO - 14

The **Downstream of Manamo Gate** with a maintenance discharge of 130 - 200 m³/s throughout the year.



PHOTO - 15

The **Macareo - Manamo Bifurcation** at 174 km upstream of Macareo, with sand bars formation due to high sedimentation.