


## CHANNEL CONDITION (2/2)

---



**PHOTO - 16**

The view of **Orinoco - Caroni River Confluence** at 339 km upstream of Rio Grande, with a discharge of black, dissolved carbon and low sedimentation from Caroni river.

**PHOTO - 17**

The vertically collapsed eroded **left bank of Guargopo - Barrancas section** at 270km upstream, composed of silt and clay.



**PHOTO - 18**

The **Macareo Channel Condition** at 270km upstream with a mild slope, fine sand and erodible banks.