


Fig.7-3-2 GRADING CURVES OF BED MATERIAL (1999 JICA SURVEY)








Fig.7-3- 4 RECENT BANK LINE CHANGE



Longitudinal Profile of Main Branches(1/2)

Fig.7-3-5



Longitudinal Profile of Main Branches(2/2)

Fig.7-3-5





Fig.7-3-6(2/3) Channel Bed Elevation Variation (Right Side)



250 -1997/11/24-1998/11/28**★** 1999/10/25 **--** 1999/1/27 **--** 1998/2/27 **-\***-1998/6/30 <del>--- 1998/9/20</del> \_\_\_1998/10/1 **→** 1999/1/23 **★**-1998/3/8 €/6/8/6/1 <del>-4</del> 1999/3/8 255 Ya Ya Section Fig.7-3-6(3/3) Channel Bed Elevation Variation (Left Side) 260 Barrancas Section Chainage (km) 265 270 Guarguapo Section 275 280

Depth below LWL in meter

15.0

20.0

25.0

10.0

5.0

0.0

