


No.10 Hoi (Ha Tinh Prov.)


Other Information

- It is alternative bridge (metal I girder 60m) in 150m of the upstream. The bridge is situated in a 100m place from national highway No. 1.
- 2) It is flooded on dyke in flood. Therefore, they want right-bank residents to move to the left bank.
- 3) According to DOT, it is the bridge which requires emergency most. But there is no bridge now.
- 4) A left-bank access road (about 2km to national highway No. 1) is due to upgrade around March, 2002.











Pic. 2: The present bridge

No.13 Truc (Ha Tinh Prov.)


Other Information

- The old bridge was built over the branch. (1978 outflow)
 The proposed position is a downstream of a river side.
- 2) It is a railroad bridge to the branch upstream. (w=0.8m footbridge juxtaposition)
- 3) Plan to upgrade road by WB fund from around May, 2002.
- 4) There is a ferry boat.





from the right bank



from upstream


Pic. 1: The present bridge


Pic. 2: The present bridge

No.14 Ha Rong (Ha Tinh Prov.)

Other Information

- 1) the amount of flowing water in flood: $5000\sim7000 \text{m}3/\text{sec}$ the amount of flowing water in dry season: about 10 m3/sec, Driftwood
- 2) There is a gate to an access road left-bank side. The residents have managed.
- 3) There is no water in the dry season and passing waterway by vehicle is possible.
- 4) Submerged bridge is better.







from the left bank



the left bank from the right bank

Pic. 2: The present bridge