

No. 1 Nam Khe (Tanh Hoa Prov.)

Other	Information
1)	War breaks and only left-bank abutments of a bridge remain.
2)	Now, a ferryboat is not functioning, either.
,	No crossing trace of people.
2)	200m of the upstream, shore protection of both banks are repaird.
	300m of the downstream, shore protection of the left bank are constructing.






Pic. 1: The present bridge


Pic. 2: The present bridge

No.3 Phuc Hung (Tanh Hoa Prov.)

Other Information

- 1) Especially damage of the slab is remarkable.
- 2) A school and a hospital, is situated in the left bank. Right-bank residents' life road
- 3) In the case of the yard reservation for left-bank construction, lot purchase is needed.
- 4) Navigation restrictions are not required.
- 5) The water level of a flood is a left-bank attachment road side.









axis direction from the right bank


Pic. 1: The present bridge

Pic. 2: The present bridge


No.8 Dien Van (Nghe An Prov.)

Other Information

- The access road from national highway No. 1 is narrow, and it is bad. Penetration of a track is impossible. It can be passed only through a small vehicle. There is a bridge (10t limit)on an access road.
- 2) It is a ferryboat (10 person) For 800 persons, a child and 200 persons are a laborer.
- 3) The clearance of a bridge is required more than MWL 5.0m.
- 4) It is flooded 0.5m from an attachment road side in flood.
- 5) It is difficult to purchase a lot, because a residential section is in the near left-bank side. (being parallel with a river)
 - It is thought that a footbridge is suitable with judging from the number of users.









downstream from the left bank

Pic. 1: The present bridge

Pic. 2: The present bridge