


MASASI, MTWARA REGION

Village Name : *Namkungwi*

Region	Mtwara	District	<i>Masasi</i>		Ward	
Coordination	E :		N :		GPS ☐	Point Deitail ☐
Elevation	GPS ☐	m	Altimeter ☐	m	Contour ☐	m ft
Topographical feature	☐		☐		☐	
Geology	Surface : <i>Redish silty sand</i>		Underground :			
Geological Structure	Lineaments : <i>weak</i>		Direction : <i>N35 E</i>		Strike/Dip / of	
River Basin	<i>Mbangala</i>					
Reference	Spring Name					Discharge m
	Bore hole No	Drill Depth	m	SWL	m	Discharge m
	Bore hole No	Drill Depth	m	SWL	m	Discharge m



Vertical Electric Survey Result Value range - Sequence -
Horizontal Electric Survey Result *HES P+160*

Comments
*HES 1 (468 006 E May hit clear water.
8812 667 N 414*

Groundwater Development Plan		Type				
Source No.	Coordination	EL (m)	SWL (estimation)	Drilling Depth	Hydrogeological Classification of the Site	
<i>NW1</i>	N: <i>8812 667</i>	E: <i>468 006</i>	<i>414</i>	<i>10</i> m	<i>100</i> m	<i>E (1~3 m³/h)</i>
	N:	E:		m	m	
	N:	E:		m	m	
	N:	E:		m	m	
	N:	E:		m	m	
	N:	E:		m	m	

Remarks *Rain collector, dug wells.*

Legend New hole ● Existing hole ○ Spring ♀