

13. Condition of the Relevant Facilities

Appendix 13 Condition of the Relevant Facilities



(Photo-1) Site View from South East



1 (Photo-2) South Side of PHC Building







1 (Photo-4) Main Gate to Mansourah PC




1 (Photo-5) Drainage Pit



1 (Photo-6) Geological Survey




1 (Photo-7) Electrical Sub-Station





National Tuberculosis Institute (NTI) 1 1 1 1 2 3 States ģ. 1 (Photo-17) Corridor (Photo-16) Exterior 的问题 (MAG) Â (Photo-18) Reference Lab. 1 (Photo-19) Meeting Room ↑ (Photo-21) Bed Room (Photo-20) Lecture Room 1 (Photo-22) Laboratory


1 (Photo-23) Preparation Room

Λ-100









1 (Photo-59) DOTS Room

1 (Photo-60) Medical Storage

