

Figure B4.3 Geological Condition around the Agos Dam Site




Figure B4.4 Geological Profile of the Agos Damsite (1)





Figure B4.5 Geological Profile of the Agos Damsite (2)



LEGEND

	: River Deposit	Alluvium Quaternary
	: Talus Deposit	


	: Assumed fault
	: Bottom of potential landslide block

Lugeon-value

	: $5 \leq Lu$
	: $1 \leq Lu < 5$
	: $Lu < 1$

SCALE 0 100m 200m

Figure B4.6 Permeable Profile of the Agos Damsite






Figure B4.8 Result of Electric Prospecting
(Two-dimensional resistivity profiling)