



Figure B4.9 Suspected Landslide Areas around Agos Damsite





PROFILE ALONG THE AXIS OF AGOS AFTERBAY WEIR
(A-A')

LEGEND

	Riverbed deposit
	Conglomerate
	Decomposed rock or residual soil
	Weathered rock, cracky
	Geological boundary

Geotechnical investigations carried out in this study

	Core drilling site (BD-1 to BD-3)
--	--------------------------------------

SCALE 0 100m

Figure 4.11 Geological Profile of the Agos Afterbay Weir Site