


GENERAL PLAN (ALTERNATIVE-1)



TYPICAL CROSS SECTION OF DIKE HEIGHTENING


THE GOVERNMENT OF THE PHILIPPINES  
THE DEPARTMENT OF PUBLIC WORKS AND HIGHWAYS

The Study on Sabo and Flood Control for  
Western River Basins of Mount Pinatubo in  
the Republic of the Philippines


JAPAN INTERNATIONAL COOPERATION AGENCY

Figure 1.5.5

General Layout of Proposed Structural  
Measures (Alternative-1) in the Bucao River



GENERAL PLAN (ALTERNATIVE-2)



TYPICAL CROSS SECTION OF CONSOLIDATION DAM (OVERFLOW SECTION)


THE GOVERNMENT OF THE PHILIPPINES  
THE DEPARTMENT OF PUBLIC WORKS AND HIGHWAYS

The Study on Sabo and Flood Control for  
Western River Basins of Mount Pinatubo in  
the Republic of the Philippines

JAPAN INTERNATIONAL COOPERATION AGENCY

Figure 1.5.6

General Layout of Proposed Structural  
Measures (Alternative-2) in the Bucao River




THE GOVERNMENT OF THE PHILIPPINES  
 THE DEPARTMENT OF PUBLIC WORKS AND HIGHWAYS


**The Study on Sabo and Flood Control for  
 Western River Basins of Mount Pinatubo in  
 the Republic of the Philippines**

JAPAN INTERNATIONAL COOPERATION AGENCY

**Figure 1.5.7**  
**Longitudinal Profile of Proposed Structural  
 Measures (Alternative-2) in the Bucao River**



GENERAL PLAN (ALTERNATIVE-3)



TYPICAL CROSS SECTION OF CONSOLIDATION DAM (OVERFLOW SECTION)

THE GOVERNMENT OF THE PHILIPPINES  
THE DEPARTMENT OF PUBLIC WORKS AND HIGHWAYS

The Study on Sabo and Flood Control for  
Western River Basins of Mount Pinatubo in  
the Republic of the Philippines

JAPAN INTERNATIONAL COOPERATION AGENCY

Figure 1.5.8

General Layout of Proposed Structural  
Measures (Alternative-3) in the Bucao River