


Notice : Not all the Area inside cell is inundated.



**THE STUDY ON COMPREHENSIVE WATER
MANAGEMENT OF MUSI RIVER BASIN**

Annex G6. 5. 3(1)

**CTI Engineering
International Co., Ltd.**

**NIKKEN
Consultants, Inc.**

Flood Map (Buah, 15 Year)