

Deteriorated Hypo Solution Tank







Hypo Dosing Point by Gravity Flow at the Clear Water Reservoir due to Malfunctioned Feeding Pumps

Power Sub-Station Constructed in 1964

