

Table A3-13 (2) Rehabilitation and Improvement Cost of Irrigation and Drainage Facilities (Pumping Station)

NO.	Region	NIS	Pumping Station Name	Intake Gate												Suction Sump											
				Rust				Damaged				Leak				Condition			Damaged, Leak, Scoured								
				Cond.	Type	Unit	Qty	Unit Cost	Amount	Cond.	Type	Unit	Qty	Unit Cost	Amount	Cond.	Type	Unit	Qty	Unit Cost	Amount	Damaged	Leak	Scoured	Type	Unit	Qty
1	CAR	Upper Chico	DIS																								
2		Hapid																									
3		West Apayao Abulog																									
4	Region I	Bonga PIS-1	Bonga Pump # 1	N/A																	N/A	N/A	N/A				
5		Bonga PIS-2	Bonga Pump # 2	Modc.																	Modc.	Modc.	Good				
6		Bonga PIS-3	Bonga Pump # 3	Modc.																	Modc.	Modc.	Good				
7		Laosa Vintar	DIS																								
8		Nmc Pasuquin	DIS																								
9		Dingras	Intake																								
10		Bolo	DIS																								
11		Cura	Intake																								
12		Nueva Era	DIS																								
13		Madongan Area	DIS																								
14		Solsoua Area	DIS																								
15		Labugan Area	DIS																								
16		Papa Area	DIS																								
17		Sta. Maria-Burgos	DIS																								
18		Sta. Lucia-Candon	DIS																								
19		Tagudin	DIS																								
20		Amburayan																									
21		Ambuyan	Intake																								
22		Ambuyan-Extension																									
23		Dipalo	DIS																								
24		Masalip	DIS																								
25		Lower Agno	Intake																								
26		San Fabian	DIS																								
27		Dumoloc	DIS																								
28		Agno	DIS																								
29		Sinolacan	DIS																								
30	Region II	Visitacion																									
31		Baua	DIS																								
32		Banurbar Creek	DIS																								
33		Magapit PIS	Magapit Pump																		Good	Good	Good				
34		Apayao-Abulog	DIS																								
35		Pamplona																									
36		Dummun	Intake																								
37		Zinundangan	DIS																								
38		Baggao	DIS																								
39		Iguig-Alcala-Amulong PIS	Iguig	N/A																	N/A	N/A	N/A				
40		Lower Chico	DIS																								
41		Solana PIS	Solana Pump	Good																	Good	Good	Good				
42		Pinacanauan	Intake																								
43		San Pablo Cabagan	Dalena Dam																								
44		Tumauini																									
45		Mallig	DIS																								
46		Bagabag	DIS																								
47	MRIS	MRIS Distric I	DIS																								
48		MRIS Distric II	DIS																								
49		MRIS Distric III	Pump Sta. # 2	Modc.																	Modc.	Modc.	Modc.				
			Pump Sta. # 3	Modc.																	Modc.	Modc.	Modc.				
			Camaal	Modc.																	Modc.	Modc.	Modc.				
			Cabaruan	Modc.																	Modc.	Modc.	Modc.				
50		MRIS Distric IV	Pump Sta. No.1	Severe	Medium	lot	1	20,090	20,090	Modc.	Medium	lot	1	25,850	25,850	Modc.	Medium	lot	1	1,090	1,090	Modc.	Modc.	Good			
51	Region III	Mayon																									
52		Bayo																									
53		Camiling																									
54		Tarlac	DIS																								
55		San Miguel																									
56		Bucay	Intake																								
57		NEPIS	Nueva Ecija PS	N/A																	N/A	N/A	N/A				
58		Pampanga Delta																									
59		Porac	DIS																								
60		Gumain	DIS																								
61		Colo																									
62		Caulaman																									
63		Angat	DIS																								

A-199

