

## **Pakistan Transport Plan Study in the Islamic Republic of Pakistan (Implementation)**

### **Technical Assistance for Reconstruction of Five Bridges Damaged by the 8 October 2005 Earthquake**

#### **Table of Contents**

<b>1. Introduction.....</b>	<b>1-1</b>
1.1 History of the Study .....	1-1
1.2 Scope of the Study .....	1-2
1.3 Schedule of the Study .....	1-4
1.4 Organization and Assignment of the Study Team .....	1-4
<b>2. Implementation of Reconstruction of Five Bridges .....</b>	<b>2-1</b>
2.1 Contents of the Bridges to be Reconstructed .....	2-1
2.2 Modification of the Approach Road Design of No.3 Bridge (Slope Protection Work) .....	2-2
2.3 Contractual Administration.....	2-3
2.4 Progress of the Works .....	2-7
2.4.1 Construction progress.....	2-7
2.4.2 Progress Photos .....	2-14
<b>3. Landslide Disaster Management .....</b>	<b>3-1</b>
3.1 General.....	3-1
3.2 Geomorphological Outline of Northern Pakistan .....	3-2
3.3 Geological outline of northern Pakistan.....	3-16
3.4 The 2005 Northern Pakistan Earthquake .....	3-19
3.5 Landslides and slope failures triggered by the 2005 Northern Pakistan Earthquake .....	3-26
3.6 Hazard assessment of landslides along the Jhelum River .....	3-44
3.7 Hazard assessment on slope failures along the Jhelum River.....	3-50
3.8 Assessment of debris flow hazard after the Northern Pakistan Earthquake.....	3-59
3.9 Geological hazard assessment of the candidate sites of satellite towns of Muzaffarabad .....	3-63
3.9.1 Introduction .....	3-63
3.9.2 Concerning points and suggestions .....	3-65
3.9.3 Concluding remarks .....	3-70
3.10 Seminar and workshop.....	3-72
3.11 Preparation of a Guide of Slope Inspection for Road Maintenance.....	3-78
3.11.1 Recommendation for Steady Recovery of Road System from 2005 Earthquake Damage .....	3-78

---

3.11.2	Necessary of Preparation of Slope Inspection Guide .....	3-79
3.11.3	Purpose of the Guide of Slope Inspection .....	3-79
3.11.4	Outline of the Guide of Slope Inspection .....	3-79
<b>4.</b>	<b>Recommendation .....</b>	<b>4-1</b>
4.1	Recommendation about mitigation measures against landslide hazards along the national highway near the Jhelum River .....	4-1
4.1.1	Characteristics of landslides and basic approaches to countermeasure planning .....	4-1
4.1.2	Effective countermeasures against landslides in steep slopes .....	4-4
4.1.3	Design procedures and priorities of countermeasures against various types of landslides .....	4-8
4.1.4	Recommendation of countermeasures for typical slope failures .....	4-10
4.2	Application of the slope inspection guideline prepared by the Study Team for rehabilitation of the roadside slope damaged by the earthquake .....	4-22
4.3	Effective use of the five bridges reconstructed .....	4-23

## **Appendix**

### Appendix – A

- A-1 A Guideline of Slope Inspection for Maintenance of Roadside Slope in the Islamic Republic of Pakistan
- A-2 Agendas of the Seminar

### Appendix – B

- B-1 As Build Drawings (Summary) of the Five Bridges
- B-2 Justifications of the Change in the No.3 Bridge Slope Protection Design
- B-3 Minute of Meeting for Revision of the No.3 Bridge Design
- B-4 Contract Agreements
- B-5 Bill of Quantities (Final)

### Appendix – C

- C Minute of Meeting for Handing Over of the Facilities
-