




Based on the geological condition, Ilog No.2 and Hilabangan No.2 were eliminated. Among remaining possible dam site, Ilog No.1 Lower Site was selected as the most suitable dam site.


Source: 2002 F/S

| THE PREPARATORY STUDY FOR SECTOR LOAN ON DISASTER RISK MANAGEMENT | Figure 2.1 Location Map of Dam Site in Ilog-Hilabangan River | |
|---|--|--|
| CTI Engineering International Co., Ltd. Nippon Koei Co., Ltd | | |









Hourly Rate to 48-hour Rainfall


| Time Hour | Rate % | Time Hour | Rate % | Time Hour | Rate % |
|--------------|-----------|--------------|--------|--------------|--------|
| 1 | 0.97 | 17 | 1.23 | 33 | 1.23 |
| 2 | 0.97 | 18 | 1.23 | 34 | 1.23 |
| 3 | 0.97 | 19 | 1.92 | 35 | 1.23 |
| 4 | 0.97 | 20 | 2.3 | 36 | 1.07 |
| 5 | 0.97 | 21 | 3.45 | 37 | 0.98 |
| 6 | 0.97 | 22 | 4.22 | 38 | 0.97 |
| 7 | 0.97 | 23 | 6.14 | 39 | 0.97 |
| 8 | 0.97 | 24 | 18.87 | 40 | 0.97 |
| 9 | 0.97 | 25 | 9.51 | 41 | 0.97 |
| 10 | 0.97 | 26 | 4.99 | 42 | 0.97 |
| 11 | 0.97 | 27 | 3.84 | 43 | 0.97 |
| 12 | 0.98 | 28 | 2.68 | 44 | 0.97 |
| 13 | 1.23 | 29 | 2.3 | 45 | 0.97 |
| 14 | 1.23 | 30 | 1.92 | 46 | 0.97 |
| 15 | 1.23 | 31 | 1.23 | 47 | 0.97 |
| 16 | 1.23 | 32 | 1.23 | 48 | 0.97 |

| THE PREPARATORY STUDY FOR | | |
|---------------------------|--|--|
| SECTOR LOAN ON | | |
| DISASTER RISK MANAGEMENT | | |
| | | |


Figure 5.1

Model Hyetograph

of Ilog-Hilabangan River Basin



F - 5 - 2





THE PREPARATORY STUDY FOR SECTOR LOAN ON DISASTER RISK MANAGEMENT


Figure 5.3

River System Model for Flood Runoff Analysis

of Ilog-Hilabangan River Basin








THE PREPARATORY STUDY FOR SECTOR LOAN FOR DISASTER RISK MANAGEMENT

CTI Engineering International Co., Ltd. Nippon Koei Co., Ltd

Figure 7.1


Ilog-Hilabangan River Improvement Plan (Alternative I-1: Full Improvement)



THE PREPARATORY STUDY FOR SECTOR LOAN FOR DISASTER RISK MANAGEMENT

Figure 7.2


Ilog-Hilabangan River Improvement Plan (Alternative I-2: Construction of Dike)




THE PREPARATORY STUDY FOR SECTOR LOAN FOR DISASTER RISK MANAGEMENT

Figure 7.3

Ilog-Hilabangan River Improvement Plan (Alternative I-3: Dike and Dredging)



Alternative I-4_1




Alternative I-4_2

THE PREPARATORY STUDY FOR SECTOR LOAN FOR DISASTER RISK MANAGEMENT

Figure 7.4

Ilog-Hilabangan River Improvement Plan
(Alternative I-4: Dike and Dredging:
Partial Protection)




THE PREPARATORY STUDY FOR SECTOR LOAN ON DISASTER RISK MANAGEMENT

Figure 7.5 (1/6)

Result of Flood Inundation Analysis

(Without Project)




THE PREPARATORY STUDY FOR SECTOR LOAN ON DISASTER RISK MANAGEMENT

Figure 7.5 (5 yr)

Result of Flood Inundation Analysis

(Without Project)




THE PREPARATORY STUDY FOR SECTOR LOAN ON DISASTER RISK MANAGEMENT

Figure 7.5 (10 yr)

Result of Flood Inundation Analysis

(Without Project)




THE PREPARATORY STUDY FOR SECTOR LOAN ON DISASTER RISK MANAGEMENT

Figure 7.5 (25 yr)

Result of Flood Inundation Analysis

(Without Project)




THE PREPARATORY STUDY FOR SECTOR LOAN ON DISASTER RISK MANAGEMENT

Figure 7.5 (50 yr)

Result of Flood Inundation Analysis

(Without Project)





THE PREPARATORY STUDY FOR SECTOR LOAN ON DISASTER RISK MANAGEMENT


Figure 7.5 (100 yr)


Result of Flood Inundation Analysis

(Without Project)









THE PREPARATORY STUDY FOR SECTOR LOAN FOR DISASTER RISK MANAGEMENT

CTI Engineering International Co., Ltd. Nippon Koei Co., Ltd Figure 7.9

Typical Cross Sections of Flood Protection Dikes Proposed for Ilog-Hilabangan River Improvement Plan